

CC4/AIG1601

4109 / Aeb352

LKK:  
IDAC:

INS. CASE OWNER:

## ASSIGNMENT

Surveyor:

Adrian

DOI:

21/7/10

Date / Time:

28/7/10

Registered in Merimen:

29/7/10

Pre-assign / CCU / FTE



Insured Vehicle No.:

SEV 8910 A

Name of Insured:

LIM HAN LIEOM

Insured Tel No.:

HP:

93064433

Excess Sec II :S\$

D.O.A.:

21/7/10

Is driver the owner?

(YES) / NO

Nature of Accident:

Claim No.:

15576387526

Policy No.:

XDD432356-00000

Make / Model:

NISSAN

Place of Accident:

PIE TWDS LIANBI MYPORT

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SFY 6748K



INSRS:

WSP:

Tel:

Liability:

RMKS:

TWINCAR



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

| Date / Time | STAGE                             | DATE / PIC |
|-------------|-----------------------------------|------------|
| 1/8/16      | Non-Reporting ltr (1st):          |            |
| 1/8/16      | Non-Reporting ltr (2nd):          |            |
| 1/8/16      | Non-Reporting ltr (Final):        |            |
| 1/8/16      | Notification ltr (if non-pickup): |            |
| 1/8/16      | Call OI:                          |            |
| 1/8/16      | After call ltr to OI:             |            |
| 1/8/16      | Documentation Check List:         |            |
| 1/8/16      | Notification ltr (if non-pickup)  |            |
| 1/8/16      | After call ltr to OI:             |            |
| 1/8/16      | Authorisation To Act:             |            |
| 1/8/16      | Release Voucher:                  |            |
| 1/8/16      | Final Repair Bill:                |            |
| 1/8/16      | Car Rental Invoice:               |            |
| 1/8/16      | Towing Invoice:                   |            |
| 1/8/16      | LTA / GIA:                        |            |
| 1/8/16      | Medical Bill:                     |            |
| 1/8/16      | PIR:                              |            |
| 1/8/16      | Mandate/Reject Instruction:       |            |
| 1/8/16      | LOD                               |            |
| 1/8/16      | Payment Breakdown Form:           |            |
| 1/8/16      | Post-Repair Photos:               |            |
| 1/8/16      | Others:                           |            |

PRELIMINARY ADVICE Date/Time:

Sent By:

## FINALIZATION

Date/Time: 24.4.18

Confirm with: SABRINA

Confirm by: LWP

Repair Cost:

45 S\$10,000

(14 days)

Reduction:

61 %

## FINAL SETTLEMENT

Date/Time: 01.05.19

Confirm with: SABRINA

Email ☒ Call ☐

Final Liability:

100 %

(Agreed / Assessed) BOLA S/N No.:

28

If NO or B 28, Ass. Lia: 100%

Repair Cost:

10/16

S\$11,556.00

(8 days)

x 100

3 YEH C.C. OI LAST

Loss of Rental (LOR):

S\$ 800.00

(8 days)

x 100

Loss of Use (LOU):

S\$ -

(\$ x days)

Loss of Income (LOI):

S\$ -

(\$ x days)

LOR only ☒LOU only ☐LOR + LOU ☐LOR + LOI ☐

(Tick only one)

GIA/LTA Search

S\$5.35

Medical:

S\$ -

Disbursement:

S\$150

(e.g. Tow/Independent)

Legal Cost

S\$ -

Total:

S\$12,511.35

Global Sum S\$: 12,350 (MANDATE APPROVAL)

Email ☒ Call ☐

## FINAL PAYMENT

Date/Time: 01.05.19

Confirm with: SABRINA

Email ☒ Call ☐

Payee 1:

S\$12,350.00

Name 1:

TWINCAR AUTOMOTIVE PTE LTD.

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format: TP

3) Survey fee: 4320

COPY SENT

ASS. REC. BY: Adrian Ling

REF:

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

|     |     |
|-----|-----|
|     |     |
| N/S | O/S |
|     |     |

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 14 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SF462481C Yr Regn: 2005, Sept.Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Vios c.c. 1497Colour: white A/C: Insured / Std / NI / NASp. Reading: 390015 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: MR0531474204151350Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/55 R15R: 195/55 R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Silverstone

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. \_\_\_\_\_ D.O.I. 29/07/16Survey held at Twin Car.Des. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

| Date / Time | Action / Instruction                    |
|-------------|-----------------------------------------|
|             | <u>TP A16.</u>                          |
|             | <u>45: 10,800 (RSD: 17,210.74 6.1%)</u> |
|             | <u>COE Expiry 20/01/2020</u>            |
|             |                                         |
|             | <u>MV: +</u>                            |
|             | <u>LTA: + 24,550</u>                    |
|             | <u>NET: +</u>                           |

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Report Format : \_\_\_\_\_

Lump Sum / I.B.I: (\$ \_\_\_\_\_)

84825151Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)☐ : Interview (\$ \_\_\_\_\_)☐ : Tech. Invs (\$ \_\_\_\_\_)☐ : Weekend (\$ \_\_\_\_\_)

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

Photos

Others

TOTAL



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                         |                                                                                                   |                            |            |                                                                                     |
|-------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------|----------------------------|------------|-------------------------------------------------------------------------------------|
| AIG ASIA PACIFIC INSURANCE PTE LTD                                                                                                        |                                                                                                   | Ref : CC4/AIG16014109/Aeb3 |            |                                                                                     |
| 78 SHENTON WAY #08-16<br>CHARTIS BUILDING<br>SINGAPORE 079120                                                                             |                                                                                                   | Date : 29-07-2016          |            |  |
|                                                                                                                                           |                                                                                                   | Code : AIG                 |            |                                                                                     |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                         |                                                                                                   |                            |            |                                                                                     |
| Insured Veh.                                                                                                                              | SKV 8910A                                                                                         | Veh. Inspected             | SFY 6248K  |                                                                                     |
| Policy No.                                                                                                                                |                                                                                                   | Coverage (\$)              | 0.00       |                                                                                     |
| Claim No.                                                                                                                                 |                                                                                                   | Excess (\$)                | 0.00       |                                                                                     |
| Assign From                                                                                                                               |                                                                                                   | Assign Date                | 29/07/2016 |                                                                                     |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                             |                                                                                                   |                            |            |                                                                                     |
| Make & Model                                                                                                                              |                                                                                                   | c.c                        | 0          |                                                                                     |
| Engine No.                                                                                                                                | HIDDEN                                                                                            | Year of Reg.               |            |                                                                                     |
| Chassis No.                                                                                                                               |                                                                                                   | Colour                     |            |                                                                                     |
| Odometer                                                                                                                                  | -                                                                                                 | Steering                   |            |                                                                                     |
| Brakes                                                                                                                                    |                                                                                                   | Modification               |            |                                                                                     |
| General                                                                                                                                   |                                                                                                   |                            |            |                                                                                     |
| <b>3. Conditions of Tyres</b>                                                                                                             |                                                                                                   |                            |            |                                                                                     |
|                                                                                                                                           | Size                                                                                              | Make                       | Balance    |                                                                                     |
| R/H Front Tyre                                                                                                                            |                                                                                                   |                            | mm         |                                                                                     |
| L/H Front Tyre                                                                                                                            |                                                                                                   |                            | mm         |                                                                                     |
| R/H Rear Tyre                                                                                                                             |                                                                                                   |                            | mm         |                                                                                     |
| L/H Rear Tyre                                                                                                                             |                                                                                                   |                            | mm         |                                                                                     |
| <b>4. Description of Damages</b>                                                                                                          |                                                                                                   |                            |            |                                                                                     |
|                                                                                                                                           |                                                                                                   |                            |            |                                                                                     |
| <b>5. General Information</b>                                                                                                             |                                                                                                   |                            |            |                                                                                     |
| Accident Date                                                                                                                             | 27/07/2016                                                                                        | Inspection Date            | 29/07/2016 |                                                                                     |
| Survey held at                                                                                                                            | TWINCAR AUTOMOTIVE PTE LTD<br>2 KAKI BUKIT AVE 2<br>#01-17 KAKI BUKIT AUTOHUB<br>SINGAPORE 417921 |                            |            |                                                                                     |
| <b>5a. Remarks</b>                                                                                                                        |                                                                                                   |                            |            |                                                                                     |
| A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.<br>B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                                                   |                            |            |                                                                                     |

# TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200714616M

GST Registration No. : 200714616M

ASIA ICE MANUFACTURING (1991) PTE LTD

BLK 28 CASSIA CRESCENT #03-24

SINGAPORE 391028

Contact : 97566868

TP A16.

Asher.

2005 Sept

COE Expiry 20/09/20.

## ESTIMATE

Repair Code : CLM13393

Date in : 27/07/2016

Vehicle Num. : SFY6248K

Model : TOYOTA VIOS 1.5E A

Chassis/Eng# : MR053HY4204151350/1NZX317045

### Parts and Labour Assesment

| Description of part                                  | Qty | Unit Price | Amount   |
|------------------------------------------------------|-----|------------|----------|
| AIRCON CONDENSER <i>Bent</i>                         | 1   | 845.00     | 845.00 ✓ |
| AIRCON CONDENSER LOWER RUBBER BUSH L/R <i>new</i>    | 2   | 25.10      | 50.20 ✓  |
| AIRCON CONDENSER TOP BRACKET L/R <i>Not New</i>      | 2   | 35.00      | 70.00 ✗  |
| AIRCON CONDENSER TOP RUBBER BUSH L/R <i>new</i>      | 2   | 23.10      | 46.20 ✓  |
| AIRCON COOLING PIPE                                  | 1   | 271.80     | 271.80 ✗ |
| AIRCON DISCHARGE PIPE                                | 1   | 260.00     | 260.00 ✗ |
| AIRCON FAN BLADE                                     | 1   | 105.10     | 105.10 ✗ |
| AIRCON FAN COWLING                                   | 1   | 123.10     | 123.10 ✗ |
| AIRCON FAN MOTOR                                     | 1   | 163.10     | 163.10 ✗ |
| AIRCON SUCTION PIPE                                  | 1   | 207.90     | 207.90 ✗ |
| FRONT BONNET <i>Buckled</i>                          | 1   | 561.45     | 561.45 ✓ |
| FRONT BONNET HINGES L/R <i>Not New</i>               | 2   | 40.00      | 80.00 ✗  |
| FRONT BONNET MECHANISM LOCK                          | 1   | 131.20     | 131.20 ✗ |
| FRONT BONNET RUBBER GUIDE STOPPER L/R <i>Not New</i> | 4   | 25.00      | 100.00 ✗ |
| FRONT BONNET STAND                                   | 1   | 61.00      | 61.00 ✗  |
| FRONT BONNET STAND HOLDER CLIPS                      | 1   | 6.50       | 6.50 ✗   |
| FRONT BONNET WEATHER STRIP                           | 1   | 131.20     | 131.20 ✗ |
| FRONT BONNET WIPER NOZZLE                            | 1   | 21.56      | 21.56 ✗  |

\*\*\* This is a computer-generated document which requires no signature.\*\*\*

# TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200714616M

GST Registration No. : 200714616M

ASIA ICE MANUFACTURING (1991) PTE LTD

BLK 28 CASSIA CRESCENT #03-24

SINGAPORE 391028

## ESTIMATE

Repair Code : CLM13393

Date in : 27/07/2016

Vehicle Num. : SFY6248K

Model : TOYOTA VIOS 1.5E A

Chassis/Eng# : MR053HY4204151350/1NZX317045

Contact : 97566868

|                                        |                    |   |        |                        |   |
|----------------------------------------|--------------------|---|--------|------------------------|---|
| FRONT BONNET WIPER NOZZLE HOSE         | <i>Not Nec</i>     | 1 | 19.21  | 19.21                  | + |
| FRONT BRACE PANEL                      | <i>Bent</i>        | 1 | 128.30 | 128.30                 | ✓ |
| FRONT BUMPER                           | <i>2nd</i>         | 1 | 298.00 | 298.00                 | ✓ |
| FRONT BUMPER FOGLAMP COVER L/R         | <i>R/L Missing</i> | 2 | 43.20  | <del>86.40</del> 43.20 | + |
| FRONT BUMPER REINFORCEMENT             | <i>Bent</i>        | 1 | 207.00 | 207.00                 | ✓ |
| FRONT BUMPER REINFORCEMENT BRACKET L/R | <i>Bent</i>        | 2 | 55.70  | 111.40                 | ✓ |
| FRONT BUMPER SIDE RETAINER L/R         | <i>new</i>         | 2 | 53.70  | 107.40                 | ✓ |
| FRONT GRILLE                           | <i>cracked</i>     | 1 | 287.10 | 287.10                 | ✓ |
| FRONT GRILLE 'LOGO' EMBLEM             | <i>new</i>         | 1 | 65.80  | 65.80                  | ✓ |
| FRONT GRILLE CLIPS                     |                    | 4 | 6.50   | 26.00                  | ✓ |
| FRONT GRILLE SCREW CLIPS L/R           | <i>Not Nec</i>     | 2 | 12.50  | 25.00                  | x |
| FRONT HEADLAMP CLIPS L/R               | <i>new</i>         | 4 | 6.50   | 26.00                  | ✓ |
| FRONT HEADLAMP L/R                     | <i>cracked</i>     | 2 | 287.40 | 574.80                 | ✓ |
| FRONT LH FENDER                        | <i>Repair</i>      | 1 | 179.00 | 179.00                 | + |
| FRONT LH FENDER INNER PANEL            | <i>Not Nec</i>     | 1 | 131.25 | 131.25                 | x |
| FRONT LH FENDER INNER SHIELD           | <i>Not Nec</i>     | 1 | 39.60  | 39.60                  | + |
| FRONT LH FENDER QUATER GARNISH         |                    | 1 | 39.60  | 39.60                  | + |
| FRONT LH FENDER QUATER GARNISH CLIPS   |                    | 2 | 6.50   | 13.00                  | + |

\*\*\* This is a computer-generated document which requires no signature.\*\*\*

page 2

1831-80

# TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200714616M

GST Registration No. : 200714616M

ASIA ICE MANUFACTURING (1991) PTE LTD

BLK 28 CASSIA CRESCENT #03-24

SINGAPORE 391028

## ESTIMATE

Repair Code : CLM13393

Date in : 27/07/2016

Vehicle Num. : SFY6248K

Model : TOYOTA VIOS 1.5E A

Chassis/Eng# : MR053HY4204151350/1NZX317045

Contact : 97566868

|                                                        |    |         |                    |
|--------------------------------------------------------|----|---------|--------------------|
| FRONT LH FENDER SIGNAL LAMP <i>nt new</i>              | 1  | 33.70   | 33.70 <i>+</i>     |
| FRONT LH SUB CHASSIS FRAME <i>Repair</i>               | 1  | 321.30  | 321.30 <i>+</i>    |
| FRONT RH FENDER <i>Repair</i>                          | 1  | 189.25  | 189.25 <i>+</i>    |
| FRONT RH FENDER INNER PANEL <i>nt new</i>              | 1  | 175.00  | 175.00 <i>+</i>    |
| FRONT RH FENDER INNER SHIELD <i>nt new</i>             | 1  | 53.70   | 53.70 <i>+</i>     |
| FRONT RH FENDER QUATER GARNISH <i>nt new</i>           | 1  | 39.60   | 39.60 <i>+</i>     |
| FRONT RH FENDER QUATER GARNISH CLIPS <i>nt new</i>     | 2  | 6.50    | 13.00 <i>+</i>     |
| FRONT RH FENDER SIGNAL LAMP <i>nt new</i>              | 1  | 56.60   | 56.60 <i>+</i>     |
| FRONT RH SUB CHASSIS FRAME <i>Repair</i>               | 1  | 321.30  | 321.30 <i>+</i>    |
| FRONT SUPPORT PANEL <i>Buckled</i>                     | 1  | 681.35  | 681.35 <i>✓</i>    |
| FRONT WINDSCREEN <i>moulding</i> <i>New</i>            | 1  | 131.80  | 131.80 <i>✓</i>    |
| FRONT WINDSCREEN INNER GARNISH CLIPS L/R <i>nt new</i> | 10 | 6.50    | 65.00 <i>✓</i>     |
| FRONT WINDSCREEN INNER GARNISH L/R                     | 2  | 95.10   | 190.20 <i>+</i>    |
| FRONT WINDSCREEN <del>MOULDING</del> <i>could</i>      | 1  | 321.30  | 321.30 <i>✓</i>    |
| HORN L/R <i>nt</i>                                     | 2  | 90.70   | 181.40 <i>+</i>    |
| RADIATOR (A) <i>Bent</i>                               | 1  | 1383.40 | 1383.40 <i>972</i> |
| RADIATOR FAN BLADE <i>nt new</i>                       | 1  | 131.20  | 131.20 <i>+</i>    |
| RADIATOR FAN COWLING <i>nt new</i>                     | 1  | 1653.35 | 181.75 <i>+</i>    |

\*\*\* This is a computer-generated document which requires no signature.\*\*\*

# TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200714616M

GST Registration No. : 200714616M

ASIA ICE MANUFACTURING (1991) PTE LTD

BLK 28 CASSIA CRESCENT #03-24

SINGAPORE 391028

Contact : 97566868

## ESTIMATE

Repair Code : CLM13393

Date in : 27/07/2016

Vehicle Num. : SFY6248K

Model : TOYOTA VIOS 1.5E A

Chassis/Eng# : MR053HY4204151350/1NZX317045

|                                       |                |   |        |        |   |
|---------------------------------------|----------------|---|--------|--------|---|
| RADIATOR FAN MOTOR                    | <i>2 new</i>   | 1 | 201.00 | 201.00 | ✓ |
| RADIATOR LOWER HOSE                   | <i>1 new</i>   | 1 | 47.80  | 47.80  | ✓ |
| RADIATOR LOWER RUBBER BUSH L/R        | <i>new</i>     | 2 | 42.70  | 85.40  | ✓ |
| RADIATOR SPARE TANK                   | <i>2 new</i>   | 1 | 65.00  | 65.00  | ✓ |
| RADIATOR SPARE TANK HOSE              |                | 1 | 48.60  | 48.60  | ✓ |
| RADIATOR TOP BRACKET L/R              | <i>Best</i>    | 2 | 35.00  | 70.00  | ✓ |
| RADIATOR TOP HOSE                     | <i>1 new</i>   | 1 | 43.20  | 43.20  | ✓ |
| RADIATOR TOP RUBBER BUSH L/R          | <i>new</i>     | 2 | 43.20  | 86.40  | ✓ |
| REAR BOOTLID                          | <i>Bushed</i>  | 1 | 657.70 | 657.70 | ✓ |
| REAR BOOTLID 'LOGO' EMBLEM            | <i>new</i>     | 1 | 35.70  | 35.70  | ✓ |
| REAR BOOTLID HINGES L/R               | <i>Best</i>    | 2 | 76.20  | 152.40 | ✓ |
| REAR BOOTLID MECHANISM LOCK           | <i>Damaged</i> | 1 | 78.00  | 78.00  | ✓ |
| REAR BOOTLID NUMBER PLATE LAMP L/R    | <i>new</i>     | 2 | 61.50  | 123.00 | ✓ |
| REAR BOOTLID OUTER GARNISH            | <i>new</i>     | 1 | 125.00 | 125.00 | ✓ |
| REAR BOOTLID OUTER GARNISH CLIPS      | <i>new</i>     | 4 | 6.50   | 26.00  | ✓ |
| REAR BOOTLID OUTER KEY LOCK           | <i>new</i>     | 1 | 69.00  | 69.00  | ✓ |
| REAR BOOTLID RUBBER GUIDE STOPPER L/R | <i>new</i>     | 2 | 18.90  | 37.80  | ✓ |
| REAR BOOTLID WEATHER STRIP            | <i>new</i>     | 1 | 83.90  | 83.90  | ✓ |

124950

\*\*\* This is a computer-generated document which requires no signature.\*\*\*

# TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200714616M

GST Registration No. : 200714616M

ASIA ICE MANUFACTURING (1991) PTE LTD

BLK 28 CASSIA CRESCENT #03-24

SINGAPORE 391028

## ESTIMATE

Repair Code : CLM13393

Date in : 27/07/2016

Vehicle Num. : SFY6248K

Model : TOYOTA VIOS 1.5E A

Chassis/Eng# : MR053HY4204151350/1NZX317045

Contact : 97566868

|                                         |                         |   |        |                         |
|-----------------------------------------|-------------------------|---|--------|-------------------------|
| REAR BUMPER                             | Distorted.              | 1 | 298.45 | 298.45 ✓                |
| REAR BUMPER INNER SIDE SHIELD CLIPS L/R | } <del>new</del><br>New | 6 | 6.50   | 39.00 ✓                 |
| REAR BUMPER INNER SIDE SHIELD L/R       |                         | 2 | 151.25 | 302.50 ✓                |
| REAR BUMPER SIDE RETAINER L/R           | new                     | 2 | 50.20  | 100.40 ✓                |
| REAR END PANEL                          | Dented                  | 1 | 791.55 | 791.55 <sup>666</sup> ✓ |
| REAR END PANEL INNER TOP GARNISH        | Deformed                | 1 | 101.30 | 101.30 ✓                |
| REAR END PANEL INNER TOP GARNISH CLIPS  | New                     | 4 | 6.50   | 26.00 <sup>10</sup> ✓   |
| REAR END PANEL LOCK STRIKER             | new New                 | 1 | 43.20  | 43.20 ✓                 |
| REAR EXHAUST GASKET                     | } Not New               | 1 | 27.00  | 27.00 ✓                 |
| REAR EXHAUST RUBBER MOUNTING            |                         | 3 | 25.10  | 75.30 ✓                 |
| REAR EXHAUST SILENCER BOX               | Bent                    | 1 | 791.20 | 791.20 <sup>451</sup> ✓ |
| REAR LH FENDER                          | Buckled.                | 1 | 781.40 | 781.40 ✓                |
| REAR LH FENDER INNER AIR VENT           | the new                 | 1 | 65.00  | 65.00 ✓                 |
| REAR LH FENDER INNER PANEL              | Repair                  | 1 | 145.90 | 145.90 ✓                |
| REAR LH FENDER INNER UPHOLSTERY TRIM    | torn                    | 1 | 179.00 | 179.00 ✓                |
| REAR LH FENDER PETROL LID COVER         | } the new               | 1 | 121.25 | 121.25 ✓                |
| REAR LH FENDER PETROL LID COVER RIVET   |                         | 2 | 12.50  | 25.00 ✓                 |
| REAR LH SUB CHASSIS FRAME               | Repair                  | 1 | 387.40 | 387.40 ✓                |

2587.55

\*\*\* This is a computer-generated document which requires no signature.\*\*\*

# TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200714616M

GST Registration No. : 200714616M

ASIA ICE MANUFACTURING (1991) PTE LTD

BLK 28 CASSIA CRESCENT #03-24

SINGAPORE 391028

Contact : 97566868

## ESTIMATE

Repair Code : CLM13393

Date in : 27/07/2016

Vehicle Num. : SFY6248K

Model : TOYOTA VIOS 1.5E A

Chassis/Eng# : MR053HY4204151350/1NZX317045

|                                                 |   |        |                   |
|-------------------------------------------------|---|--------|-------------------|
| REAR RH FENDER <i>Repair</i>                    | 1 | 981.25 | 981.25 <i>+</i>   |
| REAR RH FENDER INNER PANEL <i>Repair</i>        | 1 | 145.90 | 145.90 <i>+</i>   |
| REAR RH FENDER INNER UPHOLSTERY TRIM <i>new</i> | 1 | 179.00 | 179.00 <i>+</i>   |
| REAR RH SUB CHASSIS FRAME <i>Repair</i>         | 1 | 351.20 | 351.20 <i>+</i>   |
| REAR TAILLAMP BACK RUBBER GASKET L/R <i>new</i> | 2 | 53.90  | 107.80 <i>40</i>  |
| REAR TAILLAMP CLIPS L/R <i>new</i>              | 6 | 6.50   | 39.00 <i>20</i>   |
| REAR TAILLAMP INNER PANEL L/R <i>LH Bent</i>    | 2 | 110.00 | 220.00 <i>110</i> |
| REAR TAILLAMP L/R <i>cracked</i>                | 2 | 251.60 | 503.20 <i>✓</i>   |
| REAR WHEEL HOUSE PANEL ASSY L/R <i>Repair</i>   | 2 | 263.50 | 527.00 <i>+</i>   |
| REAR WINDSCREEN MOULDING <i>new</i>             | 1 | 89.00  | 89.00 <i>✓</i>    |
| SPARE TYRE PANEL <i>Repair</i>                  | 1 | 881.90 | 881.90 <i>+</i>   |
| SPARE TYRE PANEL INNER TOP CARBOARD <i>tear</i> | 1 | 131.35 | 131.35 <i>✓</i>   |
| SPARE TYRE RETAINER LOCK <i>new</i>             | 1 | 70.20  | 70.20 <i>+</i>    |
| SPARE TYRE SIDE PANEL L/R <i>Repair</i>         | 2 | 166.70 | 333.40 <i>+</i>   |
| WASHER TANK                                     | 1 | 65.00  | 65.00 <i>+</i>    |
| WASHER TANK CAP                                 | 1 | 18.50  | 18.50 <i>+</i>    |
| WASHER TANK MOTOR <i>new</i>                    | 1 | 110.35 | 110.35 <i>+</i>   |
| WASHER TANK NECK <i>new</i>                     | 1 | 28.50  | 28.50 <i>+</i>    |

893.55

\*\*\* This is a computer-generated document which requires no signature.\*\*\*

# TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200714616M

GST Registration No. : 200714616M

ASIA ICE MANUFACTURING (1991) PTE LTD

BLK 28 CASSIA CRESCENT #03-24

SINGAPORE 391028

## ESTIMATE

Repair Code : CLM13393

Date in : 27/07/2016

Vehicle Num. : SFY6248K

Model : TOYOTA VIOS 1.5E A

Chassis/Eng# : MR053HY4204151350/1NZX317045

Contact : 97566868

|                                          |                          |        |                  |
|------------------------------------------|--------------------------|--------|------------------|
|                                          | Subtotal before discount |        | 21,190.32        |
| Percentage discount 25%                  |                          |        | 5,297.58         |
|                                          | <b>Sub-total 1</b>       |        | <b>15,892.74</b> |
| FRONT BONNET INSULATOR MAT               | 1                        | 350.00 | 350.00 +         |
| FRONT BONNET INSULATOR MAT CLIPS - SET   | 1                        | 30.00  | 30.00 +          |
| FRONT BUMPER CLIPS - SET                 | 1                        | 30.00  | 30.00 ✓          |
| FRONT BUMPER NUMBER PLATE                | 1                        | 25.00  | 25.00 ✓          |
| FRONT BUMPER NUMBER PLATE HOLDER         | 1                        | 50.00  | 50.00 30         |
| FRONT HEADLAMP 'LAMP' BULB               | 2                        | 40.00  | 80.00 +          |
| FRONT HEADLAMP 'PARKING' BULB L/R        | 2                        | 15.00  | 30.00 +          |
| FRONT HEADLAMP 'SIGNAL' BULB L/R         | 2                        | 15.00  | 30.00 +          |
| FRONT LH FENDER INNER SHIELD CLIPS - SET | 1                        | 30.00  | 30.00 +          |
| FRONT RH FENDER INNER SHIELD CLIPS - SET | 1                        | 30.00  | 30.00 +          |
| FRONT WINDSCREEN 3M SOLAR FILM           | 1                        | 380.00 | 380.00 +         |
| FRONT WINDSCREEN E.R.P. BRACKET          | 1                        | 50.00  | 50.00 +          |
| FRONT WINDSCREEN SEALANT                 | 1                        | 100.00 | 100.00 +         |
| RADIATOR COOLANT - 1BOT                  | 1                        | 80.00  | 80.00 40         |
| REAR BOOTLID NUMBER PLATE                | 1                        | 25.00  | 25.00 ✓          |

\*\*\* This is a computer-generated document which requires no signature.\*\*\*

# TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200714616M

GST Registration No. : 200714616M

ASIA ICE MANUFACTURING (1991) PTE LTD

BLK 28 CASSIA CRESCENT #03-24

SINGAPORE 391028

Contact : 97566868

## ESTIMATE

Repair Code : CLM13393

Date in : 27/07/2016

Vehicle Num. : SFY6248K

Model : TOYOTA VIOS 1.5E A

Chassis/Eng# : MR053HY4204151350/1NZX317045

|                                                                 |   |         |                       |
|-----------------------------------------------------------------|---|---------|-----------------------|
| REAR BUMPER CLIPS - SET <i>new</i>                              | 1 | 30.00   | 30.00 ✓               |
| REAR BUMPER REVERSE SENSOR - SET <i>Donkeyed</i>                | 1 | 350.00  | <del>350.00</del> 200 |
| REAR LH FENDER INNER UPHOLSTERY TRIM CLIPS - SET <i>new</i>     | 1 | 30.00   | 30.00 ✓               |
| REAR LH FENDER INSULATOR MAT <i>not new</i>                     | 1 | 180.00  | 180.00 ✗              |
| REAR RH FENDER INNER UPHOLSTERY TRIM CLIPS - SET <i>Not new</i> | 1 | 30.00   | 30.00 ✗               |
| REAR RH FENDER INSULATOR MAT <i>not new</i>                     | 1 | 180.00  | 180.00 ✗              |
| REAR SUB WOOFER WITH UPHOLSTERY BOX <i>Not Nec</i>              | 1 | 2400.00 | 2,400.00 ✗            |
| REAR TAILLAMP 'BRAKE' BULB L/R                                  | 2 | 12.00   | 24.00 ✗               |
| REAR TAILLAMP 'REVERSE' BULB L/R                                | 2 | 12.00   | 24.00 ✗               |
| REAR TAILLAMP 'SIGNAL' BULB L/R                                 | 2 | 15.00   | 30.00 ✗               |
| REAR WINDSCREEN SEALANT <i>new</i>                              | 1 | 100.00  | <del>100.00</del> 60  |
| SPARE TYRE <i>Not Nec</i>                                       | 1 | 280.00  | 280.00 ✗              |
| SPARE TYRE PANEL INNER BREAK DOWN SIGN                          | 1 | 150.00  | 150.00 ✓              |
| SPARE TYRE PANEL INNER JACKING TOOL                             | 1 | 180.00  | 180.00 ✗              |
| Subtotal before discount                                        |   |         | 5,308.00              |
| Percentage discount 0%                                          |   |         | 0.00                  |
| Sub-total 2                                                     |   |         | 5,308.00              |
| Parts-total                                                     |   |         | 21,200.74             |

\*\*\* This is a computer-generated document which requires no signature. \*\*\*

# TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200714616M

GST Registration No. : 200714616M

ASIA ICE MANUFACTURING (1991) PTE LTD

BLK 28 CASSIA CRESCENT #03-24

SINGAPORE 391028

## ESTIMATE

Repair Code : CLM13393

Date in : 27/07/2016

Vehicle Num. : SFY6248K

Model : TOYOTA VIOS 1.5E A

Chassis/Eng# : MR053HY4204151350/1NZX317045

Contact : 97566868

## LABOUR

To remove, change air con parts, vacuums, refill air con gas.

~~180.00~~ 120

To remove, reinstall electrical wiring harness, check lighting, resetting headlamp focussing and rewire for parking sensor.

~~180.00~~ 100

To remove, change windscreen. (Front)

~~150.00~~ 120

To remove and refit rear windscreen(to FR)

~~150.00~~ 120

To remove, reinstall petrol tank. (to FR)

~~80.00~~ ✓

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

~~140.00~~ 80

To re-spray painting on the rear bootlid, rear end panel, rear fender (L/R), spare tyre panel and rear bumper.

~~1,500.00~~ 1400

To re-spray painting on the front bonnet, front support panel, front fender (L/R) and front bumper.

~~1,250.00~~ 800

To remove and change exhaust silencer box with pipe, re-align where necessary consistent to the accident.

~~160.00~~ 80

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

~~2,500.00~~ 2400

To mount vehicle on to Car 'O' Liner.

~~400.00~~ ✓

To apply anti-rust chemical on repaired and replaced panel.

~~120.00~~ 60

Labour Total

6,810.00

Parts & Labour Total

28,010.74

\*\*\* This is a computer-generated document which requires no signature.\*\*\*

page 9

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total 134 91.17

6/3, 10.8K

14 Days.

10.8K



Logout

- Pre repair inspection request - SFY6248K VS SKV8910A (OI) DOA 27/07/2016

From: BernardJiQian.Ler@aig.com

To: admin-a@lkkauto.com, assignments@lkkauto.com

Cc: Kristelli.Lopez@chartisinsurance.com, Andy-SY.Fong@aig.com, Lily.Tan@aig.com, KahYin.Leong@aig.com, Kunaseelan.Deivaseelan@aig.com, MingYao.Lee@aig.com, Baljit.i

Sent: Thursday, 28 July, 2016 2:40:12 PM

Attachments: 28072016120538-0001.pdf 28072016120538-0001.pdf

Hi,

Please refer to the enclosed request from **TwinCar Automotive Pte Ltd**

Kindly carry out Policy coverage verification first before conducting the pre-repair inspection within 48 hours

If you have any queries/concerns, please let us know.

Kindly assist to assign **Adrian Ling** as Single Joint Expert as requested.

Thank you.

Best Regards,

Bernard Ler

AIG

Express Claims Adjuster II

Claims Operations | AIG Shared Services

Level 7, Menara Worldwide, 198 Jalan Bukit Bintang, 55100 Kuala Lumpur, Malaysia.

[BernardJiQian.Ler@aig.com](mailto:BernardJiQian.Ler@aig.com) | [www.AIG.com](http://www.AIG.com)

28-07-2016 @ 2:51pm  
Hui Xin veh in  
Adrian

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

# TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit Autohub

2 Kaki Bukit Ave 2, #01-17

Singapore 417921

Tel No. : +65 6744 0510 / 6842 0051 Fax No. : +65 6741 0510

Company Reg. No. : 200714616M

GST Registration No. : 200714616M

Our Ref: **SFY 6248 K**

Your ref: **SKV 8910 A**

28 July 2016

**AIG ASIA PACIFIC INSURANCE PTE. LTD.**

NO: 78 SHENTON WAY

#07-16 CHARTIS BUILDING

SINGAPORE 079120

Attn: Motor Claims Department

BY FAX 6835-7416 & EMAIL :

[AIGSGP\\_ClaimsSurvey@aig.com](mailto:AIGSGP_ClaimsSurvey@aig.com)

Dear Sir/Madam,

DATE OF ACCIDENT: 27 July 2016

NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 3 WORKING DAYS

PURSUANT TO PARAGRAPH 2.2 OF PRE-ACTION PROTOCOL FOR NIMA CASES

We are instructed by **ASIA ICE MANUFACTURING (1991) PTE LTD** to notify you of a road traffic accident on **27 July 2016** at about **18:00 HOURS** At **PIE TOWARDS CHANGI AFTER ENG NEO EXIT** involving our client's vehicle **SFY 6248 K & SKV 8910 A** driven by you/your insured at the material time.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Please be inform that we don't excess to Merimen System and kindly reply to us by Email / Fax.

Yours faithfully,



Twincar Automotive Pte Ltd

## Asher Sng (LKKAuto)

---

**From:** Asher Sng (LKKAuto)  
**Sent:** Tuesday, 2 August, 2016 10:34 AM  
**To:** sales@n51.com.sg  
**Cc:** CS A Team  
**Subject:** Your Ref: SFY 6248K, Our Ref: CC4/AIG16014109/Aeb3, Accident Involving SFY 6248K & SFV 8910A on 27/07/2016

WITHOUT PREJUDICE

Your Ref: SFY 6248K  
Our Ref: CC4/AIG16014109/Aeb3

Dear Sir/Madam,

### **Accident Involving SFY 6248K & SFV 8910A on 27/07/2016**

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident. And the days of LOU/ LOR will base on the number of days of repair as recommended by our surveyor.

Kindly take note that the case handler in-charge is Asher and she can be contacted at her DID 6841 6051

Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants

phone: 6841-6051 | email: [ashersng@lkkauto.com](mailto:ashersng@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

## Asher Sng (LKKAuto)

---

**From:** Asher Sng (LKKAuto)  
**Sent:** Monday, 25 March 2019 2:42 PM  
**To:** 'Tan, Bennie-WZ'  
**Subject:** [MANDATE REQUEST] Your ref : 1557638752SG, ACCIDENT ON 27/07/2016 INVOLVING SKV 8910A (OI) & SFY 6248K (TP)

Your ref : 1557638752SG  
Our ref : CC4/AIG16014109/Aeb3

Dear Sirs,

### **ACCIDENT ON 27/07/2016 INVOLVING SKV 8910A (OI) & SFY 6248K (TP)**

We refer to the above matter.

The said chain collision involved 3 vehicles whereby our insured was the last vehicle.

In accordance to the MCF guideline for chain collision, we have to settle the front vehicle's claim at 100%.

We did clarify with insured the nature of the accident and he's aware that NCD (if any) maybe affected.

We seek your approval to offer repairer " **TWINCAR AUTOMOTIVE PTE LTD**" at **\$ 12,511.35 (all-in)**.

The summary is as follows: -

|                                   | Amount Claimed | Amount Revised            |
|-----------------------------------|----------------|---------------------------|
| 1. Cost of Repairs (with GST)     | \$ 29,971.49   | \$ 11,556.00              |
| 2. Loss of Rental (8days x \$120) | \$ 960.00      | \$ 800.00 (8days x \$100) |
| 3. LTA Search Fee                 | \$ 5.35        | \$ 5.35                   |
| 4. Towing Fee                     | \$ 150.00      | \$ 150.00                 |
| Total                             | \$ 31,086.84   | \$ 12,511.35              |

**For your approval in merimen please.**

Thank You.

Best Regards,

**Asher Sng** | Case Handler

**LKK Auto Consultants Pte Ltd**

phone: 6841-6051 | email: [ashersng@lkkauto.com](mailto:ashersng@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

## Print Received Message

This mail is associated with :

**\*SFY6248K (1557638752SG)**  
**[SKV8910A]**

TP  
M/S ASIA ICE MANUFACTURING(1991)PTE LTD  
Jul 27 2016 6:00PM  
[LIM HAN CHEONG]  
Twincar Automotive Pte Ltd

**From** AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG\_SG\_EXPRESS), sent on 28/03/2019 22:34 PM.  
**To** LKK\_HQ  
**Subject** Alert - Adj Mandate Approved (S\$12350.00) - SFY6248K - Claim Handler: Tan, Bennie-WZ

Approved:12350.00:Please do your utmost to negotiate settlement from: \$12,000-12,350 (All-in)

# TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit Autohub  
2 Kaki Bukit Ave 2  
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
Singapore 417921  
Tel No: +65 6842 0051 Fax No: +65 6741 0510  
E-Mail: sales@n51.com.sg  
Company reg. No. : 200714616M  
GST Registration No. : 200714616M

10 January 2019

Our Ref: CLM13393 /SFY6248K / JULY-32/2016

**AIG ASIA PACIFIC INSURANCE PTE LTD**  
NO. 78 SHENTON WAY  
#07-16 CHARTIS BUILDING  
SINGAPORE 079120

**ATTN: MOTOR CLAIMS DEPARTMENT**

Dear Sir @ Mdm,

**Re: Accident involving SFY6248K & SKV8910A on 27/07/2016**  
**Along PIE towards Changi after Eng Neo exit**

We refer to the above accident which was caused due to the negligence of your insured driver of vehicle No: **SKV8910A** whose vehicle was insured with you at the material date of the accident.

We are proposing for a direct settlement on the claims as following exclude personal injury in respect of claim arising out of the abovementioned accident.

|                 |                               |
|-----------------|-------------------------------|
| Cost of Repairs | \$ 11,556.00 (Include 7% GST) |
| Loss of rental  | \$ 960.00 (\$120.00 X 8 days) |
| LTA Search      | \$ 5.35                       |
| Towing Fee      | \$ 150.00                     |
|                 | <u>S \$ 12,671.35</u>         |

We enclosed herein the following documents for your necessary attention.

- 1) Our Final Repair Bill No: CLM13393
- 2) Hock Chuan Heng Car Rental & Trading Pte Ltd - No: 14121
- 3) LTA Search Fee
- 4) Autobay Towing - SFY6248K (receipt attached)
- 5) GIA report of SFY6248K
- 6) Letter of Authorisation To Act
- 7) Release Voucher (AIG Express Third Party Claim)

If you have any queries, please contact Sabrina at 6842 0051 or email at [sabrina@n51.com.sg](mailto:sabrina@n51.com.sg)

We look forward to your prompt reply.

Yours faithfully,



.....  
**TwinCar Automotive Pte Ltd**  
S.Y. NEO  
Managing Director

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

### CLAIM SUBFOLDER TRACKING

| Case | Notified                                | Est. Submitted | Adj. Assigned                                     | Adj. Rpt                                              | Adj. Submitted                                  | Ins. Auth'd | Status                                                          |
|------|-----------------------------------------|----------------|---------------------------------------------------|-------------------------------------------------------|-------------------------------------------------|-------------|-----------------------------------------------------------------|
| Main | 29 Jul 2016<br><a href="#">Edit Reg</a> |                | 28 Jul 2016 00:00<br><a href="#">Edit Adj Rpt</a> | <b>S\$10,800.00</b><br><a href="#">Edit Estimates</a> | <b>S\$10,800.00</b><br><a href="#">View Rpt</a> |             | <b>Pending for Survey Report</b><br><a href="#">Cancel Case</a> |

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

[Created by adjuster]

|                             |                                                                                                                        |                        |                                                                              |
|-----------------------------|------------------------------------------------------------------------------------------------------------------------|------------------------|------------------------------------------------------------------------------|
| Insured:                    | LIM HAN CHEONG, ID: S1164842H                                                                                          |                        |                                                                              |
| Main Claimant:              | M/S ASIA ICE MANUFACTURING(1991)PTE LTD, Co. Reg. No.: 198902288C                                                      |                        |                                                                              |
| Vehicle Reg. No.:           | SFY6248K                                                                                                               | Date of Loss:          | 27/07/2016 18:00 - :59<br>[130 Months and 6 Days From LTA Reg Date (Man Yr)] |
| Claim Type:                 | TP / 1557638752SG                                                                                                      | Policy/Cover Note No.: | 2100432356                                                                   |
| Vehicle Reg. No. (Insured): | SKV8910A                                                                                                               | Policy No. (Claimant): | DMPCSN3065561500                                                             |
|                             |                                                                                                                        | Excess:                |                                                                              |
| Repairer:                   | Twincar Automotive Pte Ltd (Kaki Bukit) BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB, 417921 Kaki Bukit - Tel:       |                        |                                                                              |
| Handling Insurer:           | AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Tan, Bennie-WZ - 6419 1718] Bennie- |                        |                                                                              |
| Claimant's Insurer:         | China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111                                                    |                        |                                                                              |
| Adjuster:                   | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 10/08/2016]         |                        |                                                                              |

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG\_SG\_EXPRESS (25/04/2019): Alert - Adj Mandate Maintained - SFY6248K - Claim Handler: Tan, Bennie-WZ
- AIG\_SG\_EXPRESS (28/03/2019): Alert - Adj Mandate Approved (S\$12350.00) - SFY6248K - Claim Handler: Tan, Benni...

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

| Due Date    | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
|-------------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|
| No results. |          |      |            |         |         |             |              |            |       |



## Claim Documents

\*SFY6248K (1557638752SG)  
[SKV8910A]

TP

M/S ASIA ICE MANUFACTURING(1991)PTE LTD

Jul 27 2016 6:00PM

[LIM HAN CHEONG]

Twincar Automotive Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[Upload Video](#)
[Upload Audio](#)

**View** View in Browser ▼

---

**Letters/Correspondences**

1 per page ▼ ☒

| No | Finalized On |                                                                                                | Thumbnail | Print |
|----|--------------|------------------------------------------------------------------------------------------------|-----------|-------|
| 1  | (Draft)      | LKK Auto Consultants Pte Ltd (HQ)<br><b>Third Party Express Settlement – Payment Breakdown</b> | Edit      |       |

---

**Assessment Reports**

1 per page ▼ ☒

| No | Finalized On   |                                                                                                                                                 | Thumbnail | Print |
|----|----------------|-------------------------------------------------------------------------------------------------------------------------------------------------|-----------|-------|
| 1  | 01/08/16 11:20 | AIG Asia Pacific Insurance Pte. Ltd. (SG)<br><b>Accident Statement</b><br><small>From: SC - Reg. No: SKV8910A, Claimant: LIM HAN CHEONG</small> | Load HTM  |       |

---

**Photos/Images**

3 per page ▼ ☒

| No | Relabel/Reorder |                                                          | Thumbnail                                    | Print |
|----|-----------------|----------------------------------------------------------|----------------------------------------------|-------|
| 1  | 23/04/18 19:26  | LKK Auto Consultants Pte Ltd (HQ)<br><b>General View</b> | Load JPG <input checked="" type="checkbox"/> |       |
| 2  | 23/04/18 19:26  | <b>General View</b>                                      | Load JPG <input checked="" type="checkbox"/> |       |
| 3  | 23/04/18 19:26  | <b>General View</b>                                      | Load JPG <input checked="" type="checkbox"/> |       |
| 4  | 23/04/18 19:26  | <b>General View</b>                                      | Load JPG <input checked="" type="checkbox"/> |       |
| 5  | 23/04/18 19:26  | <b>General View</b>                                      | Load JPG <input checked="" type="checkbox"/> |       |
| 6  | 23/04/18 19:26  | <b>General View</b>                                      | Load JPG <input checked="" type="checkbox"/> |       |
| 7  | 23/04/18 19:26  | <b>General View</b>                                      | Load JPG <input checked="" type="checkbox"/> |       |
| 8  | 23/04/18 19:26  | <b>General View</b>                                      | Load JPG <input checked="" type="checkbox"/> |       |
| 9  | 23/04/18 19:26  | <b>General View</b>                                      | Load JPG <input checked="" type="checkbox"/> |       |
| 10 | 23/04/18 19:26  | <b>General View</b>                                      | Load JPG <input checked="" type="checkbox"/> |       |
| 11 | 23/04/18 19:26  | <b>General View</b>                                      | Load JPG <input checked="" type="checkbox"/> |       |
| 12 | 23/04/18 19:26  | <b>General View</b>                                      | Load JPG <input checked="" type="checkbox"/> |       |
| 13 | 23/04/18 19:26  | <b>General View</b>                                      | Load JPG <input checked="" type="checkbox"/> |       |
| 14 | 23/04/18 19:26  | <b>General View</b>                                      | Load JPG <input checked="" type="checkbox"/> |       |
| 15 | 23/04/18 19:26  | <b>General View</b>                                      | Load JPG <input checked="" type="checkbox"/> |       |
| 16 | 23/04/18 19:26  | <b>General View</b>                                      | Load JPG <input checked="" type="checkbox"/> |       |
| 17 | 23/04/18 19:26  | <b>General View</b>                                      | Load JPG <input checked="" type="checkbox"/> |       |
| 18 | 23/04/18 19:26  | <b>General View</b>                                      | Load JPG <input checked="" type="checkbox"/> |       |
| 19 | 23/04/18 19:26  | <b>General View</b>                                      | Load JPG <input checked="" type="checkbox"/> |       |
| 20 | 23/04/18 19:26  | <b>General View</b>                                      | Load JPG <input checked="" type="checkbox"/> |       |
| 21 | 23/04/18 19:26  | <b>General View</b>                                      | Load JPG <input checked="" type="checkbox"/> |       |
| 22 | 23/04/18 19:26  | <b>General View</b>                                      | Load JPG <input checked="" type="checkbox"/> |       |
| 23 | 23/04/18 19:26  | <b>General View</b>                                      | Load JPG <input checked="" type="checkbox"/> |       |
| 24 | 23/04/18 19:26  | <b>General View</b>                                      | Load JPG <input checked="" type="checkbox"/> |       |
| 25 | 23/04/18 19:26  | <b>General View</b>                                      | Load JPG <input checked="" type="checkbox"/> |       |
| 26 | 23/04/18 19:26  | <b>General View</b>                                      | Load JPG <input checked="" type="checkbox"/> |       |
| 27 | 23/04/18 19:26  | <b>General View</b>                                      | Load JPG <input checked="" type="checkbox"/> |       |
| 28 | 23/04/18 19:26  | <b>General View</b>                                      | Load JPG <input checked="" type="checkbox"/> |       |

| Letters/Correspondences |                |                                   | 1 per page ▼                                                                                   | <input checked="" type="checkbox"/> |
|-------------------------|----------------|-----------------------------------|------------------------------------------------------------------------------------------------|-------------------------------------|
| No                      | Finalized On   | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail                                                                                      | Print                               |
| 29                      | 23/04/18 19:26 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 30                      | 23/04/18 19:26 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 31                      | 23/04/18 19:26 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 32                      | 23/04/18 19:26 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 33                      | 23/04/18 19:26 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 34                      | 23/04/18 19:26 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 35                      | 23/04/18 19:26 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 36                      | 23/04/18 19:26 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 37                      | 23/04/18 19:26 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 38                      | 23/04/18 19:26 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 39                      | 23/04/18 19:26 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 40                      | 23/04/18 19:26 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 41                      | 23/04/18 19:26 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 42                      | 23/04/18 19:26 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 43                      | 23/04/18 19:26 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 44                      | 23/04/18 19:26 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 45                      | 23/04/18 19:26 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 46                      | 23/04/18 19:26 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 47                      | 23/04/18 19:26 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 48                      | 23/04/18 19:26 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 49                      | 23/04/18 19:26 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 50                      | 23/04/18 19:26 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 51                      | 23/04/18 19:26 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 52                      | 23/04/18 19:26 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 53                      | 23/04/18 19:26 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 54                      | 23/04/18 19:26 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 55                      | 23/04/18 19:26 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 56                      | 23/04/18 19:26 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 57                      | 23/04/18 19:26 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 58                      | 23/04/18 19:26 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 59                      | 23/04/18 19:26 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 60                      | 23/04/18 19:26 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 61                      | 23/04/18 19:26 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 62                      | 23/04/18 19:26 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 63                      | 23/04/18 19:26 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 64                      | 23/04/18 19:26 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 65                      | 23/04/18 19:26 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 66                      | 23/04/18 19:26 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 67                      | 23/04/18 19:26 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 68                      | 23/04/18 19:26 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 69                      | 23/04/18 19:26 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 70                      | 23/04/18 19:26 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 71                      | 23/04/18 19:26 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 72                      | 23/04/18 19:26 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 73                      | 23/04/18 19:26 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 74                      | 23/04/18 19:26 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 75                      | 23/04/18 19:26 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 76                      | 23/04/18 19:26 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |

| Letters/Correspondences |                |                                   | 1 per page ▼                                                                                   | <input checked="" type="checkbox"/> |
|-------------------------|----------------|-----------------------------------|------------------------------------------------------------------------------------------------|-------------------------------------|
| No                      | Finalized On   | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail                                                                                      | Print                               |
| 77                      | 23/04/18 19:26 | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 78                      | 23/04/18 19:26 | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 79                      | 23/04/18 19:26 | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 80                      | 23/04/18 19:26 | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 81                      | 23/04/18 19:26 | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 82                      | 23/04/18 19:26 | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 83                      | 23/04/18 19:26 | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 84                      | 23/04/18 19:26 | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 85                      | 23/04/18 19:26 | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 86                      | 23/04/18 19:26 | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 87                      | 23/04/18 19:26 | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 88                      | 23/04/18 19:26 | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 89                      | 23/04/18 19:26 | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 90                      | 23/04/18 19:26 | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 91                      | 23/04/18 19:26 | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 92                      | 23/04/18 19:26 | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 93                      | 23/04/18 19:26 | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 94                      | 23/04/18 19:26 | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 95                      | 23/04/18 19:26 | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 96                      | 23/04/18 19:26 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 97                      | 23/04/18 19:26 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 98                      | 23/04/18 19:26 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 99                      | 23/04/18 19:26 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 100                     | 23/04/18 19:26 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 101                     | 23/04/18 19:26 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 102                     | 23/04/18 19:26 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 103                     | 23/04/18 19:26 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 104                     | 23/04/18 19:26 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 105                     | 23/04/18 19:26 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 106                     | 23/04/18 19:26 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 107                     | 23/04/18 19:26 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 108                     | 23/04/18 19:26 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 109                     | 23/04/18 19:26 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 110                     | 23/04/18 19:26 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 111                     | 23/04/18 19:26 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 112                     | 23/04/18 19:26 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 113                     | 23/04/18 19:26 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 114                     | 23/04/18 19:26 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 115                     | 23/04/18 19:26 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 116                     | 23/04/18 19:26 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 117                     | 23/04/18 19:26 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 118                     | 23/04/18 19:26 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 119                     | 23/04/18 19:26 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 120                     | 23/04/18 19:26 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 121                     | 23/04/18 19:26 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 122                     | 23/04/18 19:26 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 123                     | 23/04/18 19:26 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 124                     | 23/04/18 19:26 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |

| Letters/Correspondences |                |                                   | 1 per page ▼                                                                                   | ✓     |
|-------------------------|----------------|-----------------------------------|------------------------------------------------------------------------------------------------|-------|
| No                      | Finalized On   | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail                                                                                      | Print |
| 125                     | 23/04/18 19:26 | Reinspection Photo                |  Load JPG   | ✓     |
| 126                     | 23/04/18 19:26 | Reinspection Photo                |  Load JPG   | ✓     |
| 127                     | 23/04/18 19:26 | Reinspection Photo                |  Load JPG   | ✓     |
| 128                     | 23/04/18 19:26 | Reinspection Photo                |  Load JPG   | ✓     |
| 129                     | 23/04/18 19:26 | Reinspection Photo                |  Load JPG   | ✓     |
| 130                     | 23/04/18 19:26 | Reinspection Photo                |  Load JPG   | ✓     |
| 131                     | 23/04/18 19:26 | Reinspection Photo                |  Load JPG   | ✓     |
| 132                     | 23/04/18 19:26 | Reinspection Photo                |  Load JPG   | ✓     |
| 133                     | 23/04/18 19:26 | Reinspection Photo                |  Load JPG   | ✓     |
| 134                     | 23/04/18 19:26 | Reinspection Photo                |  Load JPG   | ✓     |
| 135                     | 23/04/18 19:26 | Reinspection Photo                |  Load JPG   | ✓     |
| 136                     | 23/04/18 19:26 | Reinspection Photo                |  Load JPG   | ✓     |
| 137                     | 23/04/18 19:26 | Reinspection Photo                |  Load JPG   | ✓     |
| 138                     | 23/04/18 19:26 | Reinspection Photo                |  Load JPG   | ✓     |
| 139                     | 23/04/18 19:26 | Reinspection Photo                |  Load JPG   | ✓     |
| 140                     | 23/04/18 19:26 | Reinspection Photo                |  Load JPG   | ✓     |
| 141                     | 23/04/18 19:26 | Reinspection Photo                |  Load JPG   | ✓     |
| 142                     | 23/04/18 19:26 | Reinspection Photo                |  Load JPG   | ✓     |
| 143                     | 23/04/18 19:26 | Reinspection Photo                |  Load JPG  | ✓     |
| 144                     | 23/04/18 19:26 | Reinspection Photo                |  Load JPG | ✓     |
| 145                     | 23/04/18 19:26 | Reinspection Photo                |  Load JPG | ✓     |
| 146                     | 23/04/18 19:26 | Reinspection Photo                |  Load JPG | ✓     |
| 147                     | 23/04/18 19:26 | Reinspection Photo                |  Load JPG | ✓     |
| 148                     | 23/04/18 19:26 | Reinspection Photo                |  Load JPG | ✓     |
| 149                     | 23/04/18 19:26 | Reinspection Photo                |  Load JPG | ✓     |
| 150                     | 23/04/18 19:26 | Reinspection Photo                |  Load JPG | ✓     |
| 151                     | 23/04/18 19:26 | Reinspection Photo                |  Load JPG | ✓     |
| 152                     | 23/04/18 19:26 | Reinspection Photo                |  Load JPG | ✓     |
| 153                     | 23/04/18 19:26 | Reinspection Photo                |  Load JPG | ✓     |
| 154                     | 23/04/18 19:26 | Reinspection Photo                |  Load JPG | ✓     |
| 155                     | 23/04/18 19:26 | Reinspection Photo                |  Load JPG | ✓     |
| 156                     | 23/04/18 19:26 | Reinspection Photo                |  Load JPG | ✓     |
| 157                     | 23/04/18 19:26 | Reinspection Photo                |  Load JPG | ✓     |
| 158                     | 23/04/18 19:26 | Reinspection Photo                |  Load JPG | ✓     |
| 159                     | 23/04/18 19:26 | Reinspection Photo                |  Load JPG | ✓     |
| 160                     | 23/04/18 19:26 | Reinspection Photo                |  Load JPG | ✓     |
| 161                     | 23/04/18 19:26 | Reinspection Photo                |  Load JPG | ✓     |
| 162                     | 23/04/18 19:26 | Reinspection Photo                |  Load JPG | ✓     |
| 163                     | 23/04/18 19:26 | Reinspection Photo                |  Load JPG | ✓     |
| 164                     | 23/04/18 19:26 | Reinspection Photo                |  Load JPG | ✓     |
| 165                     | 23/04/18 19:26 | Reinspection Photo                |  Load JPG | ✓     |
| 166                     | 23/04/18 19:26 | Reinspection Photo                |  Load JPG | ✓     |
| 167                     | 23/04/18 19:26 | Reinspection Photo                |  Load JPG | ✓     |
| 168                     | 23/04/18 19:26 | Reinspection Photo                |  Load JPG | ✓     |
| 169                     | 23/04/18 19:26 | Reinspection Photo                |  Load JPG | ✓     |
| 170                     | 23/04/18 19:26 | Reinspection Photo                |  Load JPG | ✓     |
| 171                     | 23/04/18 19:26 | Reinspection Photo                |  Load JPG | ✓     |
| 172                     | 23/04/18 19:26 | Reinspection Photo                |  Load JPG | ✓     |

| Letters/Correspondences |                 |                                   | 1 per page ▼                                                                                   | <input checked="" type="checkbox"/> |
|-------------------------|-----------------|-----------------------------------|------------------------------------------------------------------------------------------------|-------------------------------------|
| No                      | Finalized On    | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail                                                                                      | Print                               |
| 173                     | 23/04/18 19:26  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 174                     | 23/04/18 19:26  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 175                     | 23/04/18 19:26  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 176                     | 23/04/18 19:26  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 177                     | 23/04/18 19:26  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 178                     | 23/04/18 19:26  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 179                     | 23/04/18 19:26  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 180                     | 23/04/18 19:26  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 181                     | 23/04/18 19:26  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 182                     | 23/04/18 19:26  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 183                     | 23/04/18 19:26  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 184                     | 23/04/18 19:26  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 185                     | 23/04/18 19:26  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 186                     | 23/04/18 19:26  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 187                     | 23/04/18 19:26  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 188                     | 23/04/18 19:26  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 189                     | 23/04/18 19:26  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 190                     | 23/04/18 19:26  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 191                     | 23/04/18 19:26  | Reinspection Photo                |  Load JPG  | <input checked="" type="checkbox"/> |
| 192                     | 23/04/18 19:26  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 193                     | 23/04/18 19:26  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 194                     | 23/04/18 19:26  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 195                     | 23/04/18 19:26  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 196                     | 23/04/18 19:26  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 197                     | 23/04/18 19:26  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| Documentation           |                 |                                   | 1 per page ▼                                                                                   | <input checked="" type="checkbox"/> |
| No                      | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail                                                                                      | Print                               |
| 1                       | 29/07/16 14:37  | EMAIL FROM AIG DD 28072016        |  Load PDF |                                     |
| 2                       | 29/07/16 14:37  | TP GIA REPORT                     |  Load PDF |                                     |
| 3                       | 29/07/16 14:37  | NOTICE & GIA REPORT               |  Load PDF |                                     |
| 4                       | 20/03/19 09:01  | LETTER TO OI                      |  Load PDF |                                     |
| 5                       | 20/03/19 09:01  | LTA SEARCH                        |  Load PDF |                                     |
| 6                       | 20/03/19 09:01  | RENTAL RECEIPT                    |  Load PDF |                                     |
| 7                       | 20/03/19 09:01  | TOWING FEE                        |  Load PDF |                                     |
| 8                       | 24/04/19 17:42  | EMAIL FROM WSP DD 160419          |  Load PDF |                                     |
| 9                       | 14/05/19 08:37  | AUTHORISATION TO ACT              |  Load PDF |                                     |
| 10                      | 14/05/19 08:37  | RELEASE VOUCHER                   |  Load PDF |                                     |
| 11                      | 14/05/19 08:37  | WORKSHOP INVOICE                  |  Load PDF |                                     |

## Documents Checklist

### DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

### Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.



NOTE: TO BE COMPLETED BY SURVEYOR

TEAM \_\_\_\_\_

### THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

|                   |                     |        |                       |
|-------------------|---------------------|--------|-----------------------|
| Vehicle No:       | SKV8910A (Insd veh) | Model: | TOYOTA VIOS 1.5 E (A) |
|                   | SFY6248K (TP veh)   |        |                       |
| Date of Accident: | 27/07/2016          |        |                       |

|                                   |   |                                         |                             |                        |
|-----------------------------------|---|-----------------------------------------|-----------------------------|------------------------|
| Global Sum Settlement             | : | <input checked="" type="checkbox"/> Yes | <input type="checkbox"/> No |                        |
| Repair Estimate                   | : | \$                                      |                             | 29,971.49              |
| Final Repair Cost                 | : | \$                                      |                             | 12,350.00              |
| Loss of Use                       | : | \$                                      |                             | days at \$0.00 per day |
| Rental (if any)                   | : | \$                                      |                             | 8 days                 |
| LTA / GIA Search Fee              | : | \$                                      |                             |                        |
| Others:                           | : | \$                                      |                             |                        |
|                                   | : | \$                                      |                             |                        |
| Final Settlement Sum (GLOBAL SUM) | : | \$                                      |                             | 12,350.00              |

|                                                                                                      |  |                                                     |                                        |                         |
|------------------------------------------------------------------------------------------------------|--|-----------------------------------------------------|----------------------------------------|-------------------------|
| Is Third Party Workshop GIA Registered?                                                              |  | <input type="checkbox"/> YES                        | <input checked="" type="checkbox"/> NO | (Kindly indicate below) |
| A) For <b>Non GIA Registered Workshop:</b>                                                           |  | Agreed Liability _____ 100 _____ (%)                |                                        |                         |
| B) For <b>GIA Registered Workshop:</b>                                                               |  | BOLA Applicable: Yes/ No    BOLA Scenario No: _____ |                                        |                         |
| BOLA Liability: _____ (%)                                                                            |  | Assessed Liability (*): _____ 100 _____ (%)         |                                        |                         |
| * Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply. |  |                                                     |                                        |                         |
| Remarks _____                                                                                        |  |                                                     |                                        |                         |

| Payment Instruction: Payee's Breakdown |                            |   |           |
|----------------------------------------|----------------------------|---|-----------|
| 1)                                     | TwinCar Automotive Pte Ltd | : | 12,350.00 |
| 2)                                     |                            | : | \$        |
| 3)                                     |                            | : | \$        |
| 4)                                     |                            | : | \$        |

NUR SHAQILAH BTE ABDOL WAHAB

LKK Auto Consultants Pte Ltd

14 May  
2019

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG16014109/AEB3S2  
Date: 14/05/2019

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100432356  
Claimant Vehicle No: SFY6248K Insured Vehicle No: SKV8910A  
Date of Loss: 27/07/2016 Nature of Claim: TP Claim No: 1557638752SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SFY6248K**  
Make & Model: TOYOTA VIOS, 1.5 E (A) Engine No: 1NZX317045  
Reg. Date: 21/09/2005 (Man. Year: 2005) Chassis No: MR053HY4204151350  
Colour: White Odometer: 390015 km  
Engine Capacity: 1497 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 195/55R15 Rear Tyre Size: 195/55R15  
Front Left Side: Silverstone 6 mm Rear Left Side: Silverstone 6 mm  
Front Right Side: Silverstone 6 mm Rear Right Side: Silverstone 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS                                  | Repairer's       | Adjuster's       | Difference       | Diff %       |
|-------------------------------------------------|------------------|------------------|------------------|--------------|
| Parts                                           | 21,200.74        | 8,131.17         | 13,069.57        | 61.65        |
| Miscellaneous Items                             | 0.00             | 0.00             | 0.00             |              |
| Labour                                          | 6,810.00         | 5,360.00         | 1,450.00         | 21.29        |
| Paintwork Labour                                | 0.00             | 0.00             | 0.00             |              |
| Towing                                          | 0.00             | 0.00             | 0.00             |              |
| <b>Calculated Gross Total (S\$)</b>             | <b>28,010.74</b> | <b>13,491.17</b> | <b>14,519.57</b> | <b>51.84</b> |
| <b>Approved Total (Overridden) (S\$)</b>        |                  | <b>10,800.00</b> |                  |              |
| (S\$)                                           | 28,010.74        | 10,800.00        | 17,210.74        | 61.44        |
| <b>+ GST 7.00/7.00% (S\$)</b>                   | 1,960.75         | 756.00           | 1,204.75         | 61.44        |
| <b>Nett Amount (S\$)</b>                        | <b>29,971.49</b> | <b>11,556.00</b> | <b>18,415.49</b> | <b>61.44</b> |
| <b>+ Car Rental (8.0 x S\$100.00/day) (S\$)</b> |                  | 800.00           |                  |              |
| <b>+ Doc/Search Fee (S\$)</b>                   |                  | 5.35             |                  |              |
| <b>+ Other Costs (S\$)</b>                      |                  | 150.00           |                  |              |
| <b>Nett Liability (S\$)</b>                     |                  | <b>12,511.35</b> |                  |              |
| <b>Global Sum Settlement (S\$)</b>              |                  | <b>12,350.00</b> |                  |              |

### INSPECTION

Date of Assignment: 28/07/2016  
Date Inspected: 29/07/2016 Inspected At:

Twincar Automotive Pte Ltd (Kaki Bukit)  
BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB  
Singapore 417921

Estimated Period of Repair: 14.0 days

---

**Adjuster:** ADRIAN LING

**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

| No. | Qty | Part No. | Particulars                               | Condition     | Repairer's | Amount     |
|-----|-----|----------|-------------------------------------------|---------------|------------|------------|
| 1   | 1   |          | *AIRCON CONDENSER                         | Bent          | 845.00 FL  | *845.00 FL |
| 2   | 2   |          | *AIRCON CONDENSER LOWER RUBBER BUSH L/R   | Necessary     | 50.20 FL   | *50.20 FL  |
| 3   | 2   |          | *AIRCON CONDENSER TOP BRACKET L/R         | Not Necessary | 70.00 FL   | *- FL      |
| 4   | 2   |          | *AIRCON CONDENSER TOP RUBBER BUSH L/R     | Necessary     | 46.20 FL   | *46.20 FL  |
| 5   | 1   |          | *AIRCON COOLING PIPE                      | Not Necessary | 271.80 FL  | *- FL      |
| 6   | 1   |          | *AIRCON DISCHARGE PIPE                    | Not Necessary | 260.00 FL  | *- FL      |
| 7   | 1   |          | *AIRCON FAN BLADE                         | Not Necessary | 105.10 FL  | *- FL      |
| 8   | 1   |          | *AIRCON FAN COWLING                       | Not Necessary | 123.10 FL  | *- FL      |
| 9   | 1   |          | *AIRCON FAN MOTOR                         | Not Necessary | 163.10 FL  | *- FL      |
| 10  | 1   |          | *AIRCON SUCTION PIPE                      | Not Necessary | 207.90 FL  | *- FL      |
| 11  | 1   |          | *FRONT BONNET                             | Buckled       | 561.45 FL  | *561.45 FL |
| 12  | 2   |          | *FRONT BONNET HINGE L/R                   | Not Necessary | 80.00 FL   | *- FL      |
| 13  | 1   |          | *FRONT BONNET MECHANISM LOCK              | Not Necessary | 131.20 FL  | *- FL      |
| 14  | 4   |          | *FRONT BONNET RUBBER GUIDE STOPPER L/R    | Not Necessary | 100.00 FL  | *- FL      |
| 15  | 1   |          | *FRONT BONNET STAND                       | Not Necessary | 61.00 FL   | *- FL      |
| 16  | 1   |          | *FRONT BONNET STAND HOLDER CLIPS          | Not Necessary | 6.50 FL    | *- FL      |
| 17  | 1   |          | *FRONT BONNET WEATHER STRIP               | Not Necessary | 131.20 FL  | *- FL      |
| 18  | 1   |          | *FRONT BONNET WIPER NOZZLE                | Not Necessary | 21.56 FL   | *- FL      |
| 19  | 1   |          | *FRONT BONNET WIPER NOZZLE HOSE           | Not Necessary | 19.21 FL   | *- FL      |
| 20  | 1   |          | *FRONT BRACE PANEL                        | Bent          | 128.30 FL  | *128.30 FL |
| 21  | 1   |          | *FRONT BUMPER                             | Deformed      | 298.00 FL  | *298.00 FL |
| 22  | 1   |          | *FRONT BUMPER FOGLAMP COVER L/R           | O/s Missing   | 86.40 FL   | *43.20 FL  |
| 23  | 1   |          | *FRONT BUMPER REINFORCEMENT               | Bent          | 207.00 FL  | *207.00 FL |
| 24  | 2   |          | *FRONT BUMPER REINFORCEMENT BRACKET L/R   | Bent          | 111.40 FL  | *111.40 FL |
| 25  | 2   |          | *FRONT BUMPER SIDE RETAINER L/R           | Necessary     | 107.40 FL  | *107.40 FL |
| 26  | 1   |          | *FRONT GRILLE                             | Cracked       | 287.10 FL  | *287.10 FL |
| 27  | 1   |          | *FRONT GRILLE LOGO EMBLEM                 | Necessary     | 65.80 FL   | *65.80 FL  |
| 28  | 4   |          | *FRONT GRILLE CLIPS                       | Necessary     | 26.00 FL   | *26.00 FL  |
| 29  | 2   |          | *FRONT GRILLE SCREW CLIPS L/R             | Not Necessary | 25.00 FL   | *- FL      |
| 30  | 4   |          | *FRONT HEADLAMP CLIPS L/R                 | Necessary     | 26.00 FL   | *26.00 FL  |
| 31  | 2   |          | *FRONT HEADLAMP L/R                       | Cracked       | 574.80 FL  | *574.80 FL |
| 32  | 1   |          | *FRONT LH FENDER                          | Repair        | 179.00 FL  | *- FL      |
| 33  | 1   |          | *FRONT LH FENDER INNER PANEL              | Not Necessary | 131.25 FL  | *- FL      |
| 34  | 1   |          | *FRONT LH FENDER INNER SHIELD             | Not Necessary | 39.60 FL   | *- FL      |
| 35  | 1   |          | *FRONT LH FENDER QUARTER GARNISH          | Not Necessary | 39.60 FL   | *- FL      |
| 36  | 2   |          | *FRONT LH FENDER QUARTER GARNISH CLIPS    | Not Necessary | 13.00 FL   | *- FL      |
| 37  | 1   |          | *FRONT LH FENDER SIGNAL LAMP              | Not Necessary | 33.70 FL   | *- FL      |
| 38  | 1   |          | *FRONT LH SUB CHASSIS FRAME               | Repair        | 321.30 FL  | *- FL      |
| 39  | 1   |          | *FRONT RH FENDER                          | Repair        | 189.25 FL  | *- FL      |
| 40  | 1   |          | *FRONT RH FENDER INNER PANEL              | Not Necessary | 175.00 FL  | *- FL      |
| 41  | 1   |          | *FRONT RH FENDER INNER SHIELD             | Not Necessary | 53.70 FL   | *- FL      |
| 42  | 1   |          | *FRONT RH FENDER QUARTER GARNISH          | Not Necessary | 39.60 FL   | *- FL      |
| 43  | 2   |          | *FRONT RH FENDER QUARTER GARNISH CLIPS    | Not Necessary | 13.00 FL   | *- FL      |
| 44  | 1   |          | *FRONT RH FENDER SIGNAL LAMP              | Not Necessary | 56.60 FL   | *- FL      |
| 45  | 1   |          | *FRONT RH SUB CHASSIS FRAME               | Repair        | 321.30 FL  | *- FL      |
| 46  | 1   |          | *FRONT SUPPORT PANEL                      | Buckled       | 681.35 FL  | *681.35 FL |
| 47  | 1   |          | *FRONT WINDSCREEN MOULDING                | Necessary     | 131.80 FL  | *131.80 FL |
| 48  | 10  |          | *FRONT WINDSCREEN INNER GARNISH CLIPS L/R | Not Necessary | 65.00 FL   | *- FL      |
| 49  | 2   |          | *FRONT WINDSCREEN INNER GARNISH L/R       | Not Necessary | 190.20 FL  | *- FL      |
| 50  | 1   |          | *FRONT WINDSCREEN                         | Cracked       | 321.30 FL  | *321.30 FL |
| 51  | 2   |          | *HORN L/R                                 | Not Necessary | 181.40 FL  | *- FL      |

Report was unsubmitted during this print-out.

| No. | Qty | Part No. | Particulars                              | Condition     | Repairer's  | Amount     |
|-----|-----|----------|------------------------------------------|---------------|-------------|------------|
| 52  | 1   |          | *RADIATOR (A)                            | Bent          | 1,383.40 FL | *972.00 FL |
| 53  | 1   |          | *RADIATOR FAN BLADE                      | Not Necessary | 131.20 FL   | *- FL      |
| 54  | 1   |          | *RADIATOR FAN COWLING                    | Not Necessary | 181.75 FL   | *- FL      |
| 55  | 1   |          | *RADIATOR FAN MOTOR                      | Not Necessary | 201.00 FL   | *- FL      |
| 56  | 1   |          | *RADIATOR LOWER HOSE                     | Not Necessary | 47.80 FL    | *- FL      |
| 57  | 2   |          | *RADIATOR LOWER RUBBER BUSH L/R          | Necessary     | 85.40 FL    | *85.40 FL  |
| 58  | 1   |          | *RADIATOR SPARE TANK                     | Not Necessary | 65.00 FL    | *- FL      |
| 59  | 1   |          | *RADIATOR SPARE TANK HOSE                | Not Necessary | 48.60 FL    | *- FL      |
| 60  | 2   |          | *RADIATOR TOP BRACKET L/R                | Bent          | 70.00 FL    | *70.00 FL  |
| 61  | 1   |          | *RADIATOR TOP HOSE                       | Not Necessary | 43.20 FL    | *- FL      |
| 62  | 2   |          | *RADIATOR TOP RUBBER BUSH L/R            | Necessary     | 86.40 FL    | *86.40 FL  |
| 63  | 1   |          | *REAR BOOTLID                            | Buckled       | 657.70 FL   | *657.70 FL |
| 64  | 1   |          | *REAR BOOTLID LOGO EMBLEM                | Necessary     | 35.70 FL    | *35.70 FL  |
| 65  | 2   |          | *REAR BOOTLID HINGES L/R                 | Bent          | 152.40 FL   | *152.40 FL |
| 66  | 1   |          | *REAR BOOTLID MECHANISM LOCK             | Damaged       | 78.00 FL    | *78.00 FL  |
| 67  | 2   |          | *REAR BOOTLID NUMBER PLATE LAMP L/R      | Not Necessary | 123.00 FL   | *- FL      |
| 68  | 1   |          | *REAR BOOTLID OUTER GARNISH              | Not Necessary | 125.00 FL   | *- FL      |
| 69  | 4   |          | *REAR BOOTLID OUTER GARNISH CLIPS        | Not Necessary | 26.00 FL    | *- FL      |
| 70  | 1   |          | *REAR BOOTLID OUTER KEY LOCK             | Not Necessary | 69.00 FL    | *- FL      |
| 71  | 2   |          | *REAR BOOTLID RUBBER GUIDE STOPPER L/R   | Not Necessary | 37.80 FL    | *- FL      |
| 72  | 1   |          | *REAR BOOTLID WEATHER STRIP              | Cut           | 83.90 FL    | *83.90 FL  |
| 73  | 1   |          | *REAR BUMPER                             | Distorted     | 298.45 FL   | *298.45 FL |
| 74  | 6   |          | *REAR BUMPER INNER SIDE SHIELD CLIPS L/R | Not Necessary | 39.00 FL    | *- FL      |
| 75  | 2   |          | *REAR BUMPER INNER SIDE SHIELD L/R       | Not Necessary | 302.50 FL   | *- FL      |
| 76  | 2   |          | *REAR BUMPER SIDE RETAINER L/R           | Necessary     | 100.40 FL   | *100.40 FL |
| 77  | 1   |          | *REAR END PANEL                          | Dented        | 791.55 FL   | *666.00 FL |
| 78  | 1   |          | *REAR END PANEL INNER TOP GARNISH        | Deformed      | 101.30 FL   | *101.30 FL |
| 79  | 4   |          | *REAR END PANEL INNER TOP GARNISH CLIPS  | Necessary     | 26.00 FL    | *10.00 FL  |
| 80  | 1   |          | *REAR END PANEL LOCK STRIKER             | Not Necessary | 43.20 FL    | *- FL      |
| 81  | 1   |          | *REAR EXHAUST GASKET                     | Not Necessary | 27.00 FL    | *- FL      |
| 82  | 3   |          | *REAR EXHAUST RUBBER MOUNTING            | Not Necessary | 75.30 FL    | *- FL      |
| 83  | 1   |          | *REAR EXHAUST SILENCER BOX               | Bent          | 791.20 FL   | *451.00 FL |
| 84  | 1   |          | *REAR LH FENDER                          | Buckled       | 781.40 FL   | *781.40 FL |
| 85  | 1   |          | *REAR LH FENDER INNER AIR VENT           | Not Necessary | 65.00 FL    | *- FL      |
| 86  | 1   |          | *REAR LH FENDER INNER PANEL              | Repair        | 145.90 FL   | *- FL      |
| 87  | 1   |          | *REAR LH FENDER INNER UPHOLSTERY TRIM    | Torn          | 179.00 FL   | *179.00 FL |
| 88  | 1   |          | *REAR LH FENDER PETROL LID COVER         | Not Necessary | 121.25 FL   | *- FL      |
| 89  | 2   |          | *REAR LH FENDER PETROL LID COVER RIVET   | Not Necessary | 25.00 FL    | *- FL      |
| 90  | 1   |          | *REAR LH SUB CHASSIS FRAME               | Repair        | 387.40 FL   | *- FL      |
| 91  | 1   |          | *REAR RH FENDER                          | Repair        | 981.25 FL   | *- FL      |
| 92  | 1   |          | *REAR RH FENDER INNER PANEL              | Repair        | 145.90 FL   | *- FL      |
| 93  | 1   |          | *REAR RH FENDER INNER UPHOLSTERY TRIM    | Not Necessary | 179.00 FL   | *- FL      |
| 94  | 1   |          | *REAR RH SUB CHASSIS FRAME               | Repair        | 351.20 FL   | *- FL      |
| 95  | 2   |          | *REAR TAILLAMP BACK RUBBER GASKET L/R    | Necessary     | 107.80 FL   | *40.00 FL  |
| 96  | 1   |          | *REAR TAILLAMP CLIPS L/R                 | Necessary     | 39.00 FL    | *20.00 FL  |
|     |     |          | 6pcs                                     |               |             |            |
| 97  | 1   |          | *REAR TAILLAMP INNER PANEL L/R           | N/s Dented    | 220.00 FL   | *110.00 FL |
| 98  | 2   |          | *REAR TAILLAMP L/R                       | Cracked       | 503.20 FL   | *503.20 FL |
| 99  | 2   |          | *REAR WHEEL HOUSE PANEL ASSY L/R         | Repair        | 527.00 FL   | *- FL      |
| 100 | 1   |          | *REAR WINDSCREEN MOULDING                | Necessary     | 89.00 FL    | *89.00 FL  |
| 101 | 1   |          | *SPARE TYRE PANEL                        | Repair        | 881.90 FL   | *- FL      |
| 102 | 1   |          | *SPARE TYRE PANEL INNER TOP CARDBOARD    | Torn          | 131.35 FL   | *131.35 FL |
| 103 | 1   |          | *SPARE TYRE RETAINER LOCK                | Not Necessary | 70.20 FL    | *- FL      |
| 104 | 2   |          | *SPARE TYRE SIDE PANEL L/R               | Repair        | 333.40 FL   | *- FL      |
| 105 | 1   |          | *WASHER TANK                             | Not Necessary | 65.00 FL    | *- FL      |
| 106 | 1   |          | *WASHER TANK CAP                         | Not Necessary | 18.50 FL    | *- FL      |

Report was unsubmitted during this print-out.

| No. | Qty | Part No. | Particulars                                     | Condition     | Repairer's  | Amount     |
|-----|-----|----------|-------------------------------------------------|---------------|-------------|------------|
| 107 | 1   |          | *WASHER TANK MOTOR                              | Not Necessary | 110.35 FL   | *- FL      |
| 108 | 1   |          | *WASHER TANK NECK                               | Not Necessary | 28.50 FL    | *- FL      |
| 109 | 1   |          | *FRONT BONNET INSULATOR MAT                     | Not Necessary | 350.00 FS   | *- FS      |
| 110 | 1   |          | *SET FRONT BONNET INSULATOR MAT CLIPS           | Not Necessary | 30.00 FS    | *- FS      |
| 111 | 1   |          | *SET FRONT BUMPER CLIPS                         | Necessary     | 30.00 FS    | *30.00 FS  |
| 112 | 1   |          | *FRONT BUMPER NUMBER PLATE                      | Cracked       | 25.00 FS    | *25.00 FS  |
| 113 | 1   |          | *FRONT BUMPER NUMBER PLATE HOLDER               | Cracked       | 50.00 FS    | *30.00 FS  |
| 114 | 2   |          | *FRONT HEADLAMP LAMP BULB                       | Not Necessary | 80.00 FS    | *- FS      |
| 115 | 2   |          | *FRONT HEADLAMP PARKING BULB L/R                | Not Necessary | 30.00 FS    | *- FS      |
| 116 | 2   |          | *FRONT HEADLAMP SIGNAL BULB L/R                 | Not Necessary | 30.00 FS    | *- FS      |
| 117 | 1   |          | *SET FRONT LH FENDER INNER SHIELD CLIPS         | Not Necessary | 30.00 FS    | *- FS      |
| 118 | 1   |          | *SET FRONT RH FENDER INNER SHIELD CLIPS         | Not Necessary | 30.00 FS    | *- FS      |
| 119 | 1   |          | *FRONT WINDSCREEN 3M SOLAR FILM                 | Not Necessary | 380.00 FS   | *- FS      |
| 120 | 1   |          | *FRONT WINDSCREEN E.R.P. BRACKET                | Not Necessary | 50.00 FS    | *- FS      |
| 121 | 1   |          | *FRONT WINDSCREEN SEALANT                       | Not Necessary | 100.00 FS   | *- FS      |
| 122 | 1   |          | *BOT RADIATOR COOLANT                           | Necessary     | 80.00 FS    | *40.00 FS  |
| 123 | 1   |          | *REAR BOOTLID NUMBER PLATE                      | Cut           | 25.00 FS    | *25.00 FS  |
| 124 | 1   |          | *SET REAR BUMPER CLIPS                          | Necessary     | 30.00 FS    | *30.00 FS  |
| 125 | 1   |          | *SET REAR BUMPER REVERSE SENSOR                 | Damaged       | 350.00 FS   | *200.00 FS |
| 126 | 1   |          | *SET REAR LH FENDER INNER UPHOLSTERY TRIM CLIPS | Necessary     | 30.00 FS    | *30.00 FS  |
| 127 | 1   |          | *REAR LH FENDER INSULATOR MAT                   | Not Necessary | 180.00 FS   | *- FS      |
| 128 | 1   |          | *SET REAR RH FENDER INNER UPHOLSTERY TRIM CLIPS | Not Necessary | 30.00 FS    | *- FS      |
| 129 | 1   |          | *REAR RH FENDER INSULATOR MAT                   | Not Necessary | 180.00 FS   | *- FS      |
| 130 | 1   |          | *REAR SUB WOOFER WITH UPHOLSTERY BOX            | Not Necessary | 2,400.00 FS | *- FS      |
| 131 | 2   |          | *REAR TAILLAMP BRAKE BULB L/R                   | Not Necessary | 24.00 FS    | *- FS      |
| 132 | 2   |          | *REAR TAILLAMP REVERSE BULB L/R                 | Not Necessary | 24.00 FS    | *- FS      |
| 133 | 2   |          | *REAR TAILLAMP SIGNAL BULB L/R                  | Not Necessary | 30.00 FS    | *- FS      |
| 134 | 1   |          | *REAR WINDSCREEN SEALANT                        | Necessary     | 100.00 FS   | *60.00 FS  |
| 135 | 1   |          | *SPARE TYRE                                     | Not Necessary | 280.00 FS   | *- FS      |
| 136 | 1   |          | *SPARE TYRE PANEL INNER BRAKE DOWN SIGN         | Not Necessary | 150.00 FS   | *- FS      |
| 137 | 1   |          | *SPARE TYRE PANEL INNER JACKING TOOL            | Not Necessary | 180.00 FS   | *- FS      |

F=Franchise part, S=SpcNett, L=ListItemDisc.

|                                                            |                  |                  |
|------------------------------------------------------------|------------------|------------------|
| <b>Sub Total (\$\$)</b>                                    | <b>26,498.32</b> | <b>10,684.90</b> |
| <b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b> | <b>5,297.58</b>  | <b>2,553.73</b>  |
| <b>Total Parts (\$\$)</b>                                  | <b>21,200.74</b> | <b>8,131.17</b>  |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                             | Particulars                                                                                                                                                                     | Lab.Type | Repairer's      | Amount          |
|--------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------|-----------------|-----------------|
| <b>Labour Items</b>            |                                                                                                                                                                                 |          |                 |                 |
| 1                              | TO REMOVE, CHANGE AIR CON PARTS, VACUUMS, REFILL AIR CON GAS.                                                                                                                   | New      | 180.00          | 120.00          |
| 2                              | TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING, RESETTNG HEADLAMP FOCUSING AND REWIRE FOR PARKING SENSOR.                                                       | New      | 180.00          | 100.00          |
| 3                              | TO REMOVE, CHANGE WINDSCREEN. (FRONT)                                                                                                                                           | New      | 150.00          | 120.00          |
| 4                              | TO REMOVE AND REFIT REAR WINDSCREEN (TO FR)                                                                                                                                     | New      | 150.00          | 120.00          |
| 5                              | TO REMOVE, REINSTALL PETROL TANK.                                                                                                                                               | New      | 80.00           | 80.00           |
| 6                              | TO REMOVE, REINSTALL ROOF TOP TRIM UPHOLSTERY, CUSHION SEAT, TRIM GARNISH, TRIM LINER CARPET. (TO FR)                                                                           | New      | 140.00          | 80.00           |
| 7                              | TO RE-SPRAY PAINTING ON THE REAR BOOTLID, REAR END PANEL, REAR FENDER (L/R), SPARE TYRE PANEL AND REAR BUMPER.                                                                  | New      | 1,500.00        | 1,400.00        |
| 8                              | TO RE-SPRAY PAINTING ON THE FRONT BONNET, FRONT SUPPORT PANEL, FRONT FENDER (L/R) AND FRONT BUMPER.                                                                             | New      | 1,250.00        | 800.00          |
| 9                              | TO REMOVE AND CHANGE EXHAUST SILENCER BOX WITH PIPE, RE-ALIGN WHERE NECESSARY CONSISTENT TO THE ACCIDENT.                                                                       | New      | 160.00          | 80.00           |
| 10                             | TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT. | New      | 2,500.00        | 2,400.00        |
| 11                             | TO MOUNT VEHICLE ON TO CAR O LINER.                                                                                                                                             | New      | 400.00          | 0.00            |
| 12                             | TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL.                                                                                                                     | New      | 120.00          | 60.00           |
| <b>Gross Labour Cost (S\$)</b> |                                                                                                                                                                                 |          | <b>6,810.00</b> | <b>5,360.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >