

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC3/III16016052/KPA3Q2

**Date:** 09/02/2021

### REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	M482553
<b>Claimant</b>		
<b>Vehicle No :</b> SHC5113P	<b>Insured Vehicle No :</b>	SKM687U
Date of Loss: 24/08/2016	Nature of Claim: TP	Claim No: MC20163002

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC5113P		
Make & Model:	RENAULT LATITUDE, 2.0 D dCi (A)	Engine No:	M9R8839C000795
Reg. Date:	27/12/2013 (Man. Year: 2013)	Chassis No:	VF1ABL15AUC276214
Colour:	Metallic White/Red	Odometer:	434689 km
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Linglong 9 mm	Rear Left Side:	Falken 8 mm
Front Right Side:	Linglong 9 mm	Rear Right Side:	Falken 8 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	35,659.95	7,991.88	27,668.07	77.59
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,330.00	950.00	7,380.00	88.60
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>43,989.95</b>	<b>8,941.88</b>	<b>35,048.07</b>	<b>79.67</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>7,150.00</b>		
<b>(\$\$)</b>	43,989.95	7,150.00	36,839.95	83.75
<b>+ GST 7.00/7.00% (\$\$)</b>	3,079.30	500.50	2,578.80	83.75
<b>Nett Amount (\$\$)</b>	<b>47,069.25</b>	<b>7,650.50</b>	<b>39,418.75</b>	<b>83.75</b>
<b>Global Sum Settlement (\$\$)</b>		<b>0.00</b>		

### INSPECTION

Date of Assignment:	24/08/2016	
Date Inspected:	24/08/2016	Inspected At:
		Trans-cab Auto Services Pte Ltd
		NO. 2ANG MO KIO, ST 63
		Singapore 569111
Estimated Period of Repair:	5.0 days	

**Adjuster:** KENNETH KONG

**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 09 Feb 2021)
<b>Parts:</b>	143	RENAULT LATITUDE 2.0 D dCi (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SHC5113P)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER FRT	Buckled/Cracked	968.79 FL	*968.79 FL
2	1		*BUMPER SPOILER FRT	Serviceable	139.81 FL	*- FL
3	1		*BUMPER ABSORBER FRT	Cracked	303.60 FL	*303.60 FL
4	1		*BUMPER RETAINER FRT LH	Distorted	116.47 FL	*116.47 FL
5	1		*BUMPER SUPPORT FRT LH (HEADLAMP LOWER)	Serviceable	18.37 FL	*- FL
6	1		*BUMPER RETAINER FRT RH	Distorted	115.98 FL	*115.98 FL
7	1		*BUMPER SUPPORT FRT RH (HEADLAMP LOWER)	Serviceable	18.37 FL	*- FL
8	1		*BUMPER UNDERTRAY FRT	Serviceable	363.71 FL	*- FL
9	1		*BUMPER GRILLE LOWER FRT	Serviceable	205.23 FL	*- FL
10	1		*BUMPER FOG LAMP GRILLE LH	Serviceable	159.39 FL	*- FL
11	1		*BUMPER BEAM FRT	*Check	703.14 FL	*- FL
12	1		*RADIATOR GRILLE	Mtg Cracked	1,313.68 FL	*1,313.68 FL
13	1		*RADIATOR GRILLE BADGE RENAULT	Necessary	173.36 FL	*173.36 FL
14	1		*RADIATOR GRILLE FRAME	Cracked	1,041.35 FL	*1,041.35 FL
15	1		*FRAME FULL SUPPORT PANEL	Cracked	473.77 FL	*473.77 FL
16	1		*HEADLAMP LH	Cracked	911.10 FL	*911.10 FL
17	1		*HEADLAMP RH	Mtg Cracked	911.10 FL	*911.10 FL
18	1		*BONNET	Bent	1,493.56 FL	*1,493.56 FL
19	1		*FENDER PANEL FRT LH	Repair	602.95 FL	*- FL
20	1		*FENDER PANEL FRT RH	Repair	602.95 FL	*- FL
21	1		*FENDER WHEELARCH FRT LH (LINER)	Serviceable	107.32 FL	*- FL
22	1		*FENDER WHEELARCH FRT RH (LINER)	Serviceable	214.49 FL	*- FL
23	1		*RADIATOR	Serviceable	924.77 FL	*- FL
24	1		*AIR CLEANER HOSE	Serviceable	58.57 FL	*- FL
25	1		*AIR CLEANER LOWER	Serviceable	311.95 FL	*- FL
26	1		*ENGINE UNDERTRAY	Serviceable	434.60 FL	*- FL
27	1		*A/C CONDENSER	Serviceable	1,554.13 FL	*- FL
28	1		*TRANSMISSION COOLER	Serviceable	852.66 FL	*- FL
29	1		*STEERING PUMP ELECTRIC	Serviceable	1,543.08 FL	*- FL
30	1		*BUMPER COVER REAR	Buckled	852.66 FL	*852.66 FL
31	1		*BUMPER BRACKET CTR REAR	Serviceable	87.29 FL	*- FL
32	1		*BUMPER BRACKET SIDE LH REAR (TAILLAMP LOWER)	Serviceable	34.61 FL	*- FL
33	1		*BUMPER RETAINER LH REAR	Serviceable	104.59 FL	*- FL
34	1		*BUMPER BRACKET SIDE LH REAR (TAILLAMP LOWER)	Serviceable	34.61 FL	*- FL
35	1		*BUMPER RETAINER RH REAR	Serviceable	104.59 FL	*- FL
36	1		*BUMPER LOWER REAR	Serviceable	591.41 FL	*- FL
37	1		*BUMPER BEAM REAR	Repair	598.08 FL	*- FL
38	1		*BUMPER BEAM BRACKET LH REAR	Repair	173.81 FL	*- FL
39	1		*BUMPER BEAM BRACKET RH REAR	Repair	173.81 FL	*- FL
40	1		*BUMPER REFLECTOR LH	Serviceable	33.55 FL	*- FL
41	1		*BUMPER REFLECTOR RH	Serviceable	33.55 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
42	1		*BOOT REAR	Repair	2,209.75 FL	*- FL
43	1		*BOOT FINISHER (MOULDING)	Serviceable	361.58 FL	*- FL
44	1		*BOOT LOCK	Repair	155.90 FL	*- FL
45	1		*BOOT LOCK CATCH	Repair	57.23 FL	*- FL
46	1		*BOOT WEATHERSTRIP	Serviceable	248.50 FL	*- FL
47	1		*BOOT REFLECTOR LAMP LH	Serviceable	379.50 FL	*- FL
48	1		*BOOT REFLECTOR LAMP RH	Serviceable	379.50 FL	*- FL
49	1		*BOOT BADGE RENAULT	Not Necessary	173.35 FL	*- FL
50	1		*BOOT BADGE	Not Necessary	173.35 FL	*- FL
51	2		*LICENCE PLATE LAMP	Serviceable	84.00 FL	*- FL
52	2		*BOOT RUBBER PLUG	Serviceable	170.63 FL	*- FL
53	1		*TAILLAMP LH	Serviceable	425.04 FL	*- FL
54	1		*TAILLAMP RH	Serviceable	425.04 FL	*- FL
55	1		*FENDER PANEL REAR LH	Repair	2,537.80 FL	*- FL
56	1		*FENDER PANEL REAR RH	Repair	2,537.80 FL	*- FL
57	1		*FENDER WHEELARCH REAR LH (LINNER)	Serviceable	418.06 FL	*- FL
58	1		*FENDER WHEELARCH REAR RH (LINNER)	Serviceable	418.06 FL	*- FL
59	1		*OUTER PANEL REAR (END PANEL)	Repair	1,132.13 FL	*- FL
60	1		*OUTER PANEL REAR (END PANEL) TRIM	Serviceable	308.48 FL	*- FL
61	1		*EXHAUST REAR	Repair	5,760.00 FL	*- FL
62	1		*EXHAUST CAP REAR	Repair	177.30 FL	*- FL
63	1		*SET RADIATOR GRILLE FRAME CLIP	Necessary	52.00 FS	*52.00 FS
64	1		*SET BUMPER CLIP FRT	Necessary	66.00 FS	*66.00 FS
65	1		*BUMPER BRACKET CLIP FRT LH	Not Necessary	12.00 FS	*- FS
66	1		*BUMPER SUPPORT CLIP FRT LH	Not Necessary	10.50 FS	*- FS
67	1		*BUMPER BRACKET CLIP FRT RH	Not Necessary	12.00 FS	*- FS
68	1		*BUMPER SUPPORT CLIP FRT RH	Not Necessary	10.50 FS	*- FS
69	1		*TOW COVER FRT	Serviceable	14.50 FS	*- FS
70	1		*SET BUMPER GRILLE LOWER CLIP	Not Necessary	69.00 FS	*- FS
71	1		*SET FRAME FULL SUPPORT PANEL CLIP	Not Necessary	70.00 FS	*- FS
72	2		*FRAME FULL SUPPORT PANEL NUT	Not Necessary	20.00 FS	*- FS
73	2		*FRAME FULL SUPPORT PANEL STUD	Not Necessary	30.00 FS	*- FS
74	1		*SET WHEELARCH CLIP FRT LH	Not Necessary	30.50 FS	*- FS
75	1		*SET WHEELARCH CLIP FRT RH	Not Necessary	29.40 FS	*- FS
76	1		*SET BUMPER RR RIVET	Not Necessary	28.60 FS	*- FS
77	1		*SET BUMPER RR CLIP	Necessary	66.00 FS	*66.00 FS
78	1		*SET BUMPER BEAM BOLT	Serviceable	22.22 FS	*- FS
79	1		*SET REFLECTOR SCREW LH	Not Necessary	25.00 FS	*- FS
80	1		*SET PARKING AID	Serviceable	600.00 FS	*- FS
81	1		*BUMPER BRACKET CLIP CTR REAR	Not Necessary	15.00 FS	*- FS
82	1		*BUMPER BRACKET SIDE CLIP LH REAR	Not Necessary	12.00 FS	*- FS
83	1		*BUMPER RETAINER CLIP LH REAR	Not Necessary	10.40 FS	*- FS
84	1		*BUMPER BRACKET SIDE CLIP RH REAR	Not Necessary	12.00 FS	*- FS
85	1		*BUMPER RETAINER CLIP RH REAR	Not Necessary	10.40 FS	*- FS
86	1		*SET WHEELARCH CLIP LH RR	Not Necessary	32.34 FS	*- FS
87	1		*SET WHEELARCH CLIP RH RR	Not Necessary	32.34 FS	*- FS
88	1		*SET BOOT FINISHER CLIP	Not Necessary	25.10 FS	*- FS
89	1		*REAR BOOTS STICKER TRANS-CAB	Not Necessary	30.00 FS	*- FS
90	1		*REAR BOOTS STICKER 6555-3333	Not Necessary	30.00 FS	*- FS
91	1		*EXHAUST MOUNTING REAR	Serviceable	65.50 FS	*- FS
92	1		*EXHAUST BRACKET REAR	Serviceable	22.22 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

**Sub Total (\$\$) 39,459.33 8,859.42**  
**- List Item Discount on L Items 10.00/10.00% (\$\$) 3,799.38 867.54**

**Total Parts (\$\$) 35,659.95 7,991.88**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	2,800.00	800.00
2	TO APPLY PAINT PROTECTION SYSTEM (PPS) MAINTAIN AND ENHANCEMENT	New	380.00	0.00
3	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	2,700.00	30.00
4	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	30.00
5	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH, FITTINGS AND OTHER,TO ENABLE REPAIR	New	380.00	0.00
6	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
7	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING	New	170.00	0.00
8	TO CHECK ABS BRAKE EFFICIENCY,FINAL CHECKING AND TESTING	New	380.00	0.00
9	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	30.00
10	TO TRANSFER OF REAR END PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
11	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	60.00
12	TO DROP REAR EXHAUST BOX,RENEW THE SAME,TO REPAIR AND REALIGN CENTRE EXHAUST PIPE	New	280.00	0.00
13	TO REPAIR AND REALIGN REAR EXHAUST PIPE	New	170.00	0.00
14	TO TRANSFER OF BOOTLID FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>8,330.00</b>	<b>950.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >