

RESTRICTED

HQ Transport
Kranji Camp III
151 Choa Chu Kang Way
Block 822 #01-04
Singapore 688248

Tel : 6307 4511
Fax : 6307 4520

Date: 07 / 09 / 17

To: LKK Auto Consultants Pte Ltd
Attn: Zayer / Chew Hsiao Tong (Ms)

Our Ref: FY 16 / 17 / 0038

Forwarding of Outstanding Document(s)

Accident involving MID 41533 & YP 876J on 18 / 08 / 16 .
and SCA 1677E

We are faxing over / dispatching document(s) with regards to the above matter.

Kindly acknowledge upon receiving the below mentioned document(s) and revert back to us.

Acknowledgement from LKK Auto			
S/N	Documents	Received On	Received By
1	SAF 1201		
2	SAF 1202		
3	Police Report	/	ms
4	Original Photographs		
5	Final Bill	/	ms.

Thank You

S721957BG
1WO SIVAJI RAJAH
TA INVESEN WO
HQ TRANSPORT

M. 814
070917.



14/9/17
Zayer (LKK)
received by post.

RESTRICTED



**SINGAPORE
POLICE FORCE**



T/20160819/2035

1 of 4

Police Station Of Origin:
Yishun North N.P.C
31 Yishun Central SINGAPORE 768827
Tel No: 1800-8529999

Report No: T/20160819/2035

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 19/08/2016 10:32	Vide Report No.:	Station Diary No.: 56
--	------------------	--------------------------

Informant's Particulars

Name of Informant: MUHAMMAD DANIAL BIN ROSLAN		Address: APT BLK 123 BUKIT MERAH VIEW #03-290 SINGAPORE 151123	
ID Type / ID No.: NRIC NO / S9448590H		Contact No.: Home/Office: Mobile: 86615129	
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 21	Date of Birth: 26/12/1994	Type of Informant: Driver
Race: Malay		Language: English	Institution / School Name:
Occupation: FULL TIME NS		Driving Licence Information: Class: 3,4 Date of Expiry:	

General Information of the Accident

Type of Accident:	Non-Injury Government Vehicle	Drink Drive: No	Date/Time of Accident: 18/08/2016 15:40	Type of Location: Straight Road
Location: Along Road 1 UPPER THOMSON ROAD towards Ang Mo Kio direction, near to Thomson Plaza				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: Dual Carriage Way		Traffic Control: Not Controlled	Traffic Volume: Heavy	
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: No	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of
MID41533	Car	FORD		Green	Slightly Damaged	1
SKA1677E	Car	SUZUKI	Swift	White	No Damage	0
YP876J	Lorry	MITSUBISHI		White	No Damage	0



**SINGAPORE
POLICE FORCE**



T/20160819/2035

2 of 4

Police Station Of Origin:
Yishun North N.P.C.
31 Yishun Central SINGAPORE 768827
Tel No: 1800-8529999

Report No. T/20160819/2035

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	MUHAMMAD DANIAL BIN ROSLAN	ID No.	S9448590H
Related Vehicle	MID41533 (Car)	Contact No.	86615129
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3,4 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Name	Oh Chee Ann	ID No.	S7316971B
Related Vehicle	YP876J (Lorry)	Contact No.	90691782
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 18/08/16 at 1542hrs, I was driving a MINDEF vehicle along Upper Thomson Road towards Ang Mo Kio direction, next to Thomson Plaza. There were road works and the road was reduced from 3 to 2 lanes. Traffic was congested and slow moving. I was driving on the extreme right lane, with a 20-foot lorry in front of my car. The lorry started to move and resumed normal speed. After 2 seconds, I also started to move off when suddenly the lorry jam braked. I tried to jam brake as well, but the close proximity of my car and the lorry meant I did not have enough reaction time. The front of my lorry hit onto the rear of the lorry, resulting in damages to the front bumper and hood area of my car. There was no visible damage to the lorry. No one was injured in the accident. Based on our transponder records, the speed of my car was 25 km/hour at the time of the accident impact.

After the accident, both myself and the lorry driver alighted and exchanged particulars. The driver then showed me the in-vehicle camera footage and it showed there was a white car in front of the lorry who make an illegal left turn to the entrance of Thomson Plaza car park, it was done across a double white line. I have a footage of the white car that caused the accident. I wish to say that the drive of the white car was the cause of the accident, and even after the accident, it did not stop and continue to drive off.



SINGAPORE
POLICE FORCE



T/20160819/2035

3 of 4

Report No. T/20160819/2035

Police Station Of Origin:
Yishun North N.P.C
31 Yishun Central SINGAPORE 768827
Tel No: 1800-8529999

CONTINUATION OF REPORT



T/20160819/2035

4 of 4

Report No. T/20160819/2035

Resolution Of Origin:
North N.P.C
Central SINGAPORE 768827
No. 1800-8529999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report

F /

Staff Sgt MOHAMMED ZUFARHAN BIN
BOHART *Claudia Hsing Wah*

Signature Of Interpreter:

Not applicable

Signature Of Informant:

Date/Time:

19/08/2016 10:32

Officer In Charge Of Case:

TP / GIA /

Sr Staff Sgt ESTHER CHONG

Contact No.: 65476368

Classification Of Case:

BN 035





Authentication Stamp

NP168



Signature: *[Signature]*

Singapore Police Force



Front Left Bumper Scratched
Front Bumper Dented

1. Front Bumper Dented
2. Front Left Headlight Cracked
3. Front Left Headlight Cracked
4. Front Bumper Scratched
5. Front Bumper Scratched
6. Front Bumper Scratched
7. Front Bumper Scratched
8. Top Air Deflector Cracked
9. Front Bumper Scratched
10. Radiator Fan Dented
11. Radiator Fan Dented
12. Radiator Fan Dented
13. Radiator Fan Dented
14. Radiator Fan Dented
15. Radiator Fan Dented



MT Staff Rank & Name:

M86 871116

Signature & Unit Stamp:

[Signature]

Date & Time: 220616

1645

Unit / Camp: X62 5000 Camp

SMRT Staff Signature: *[Signature]*

chip (km long)

Date & Time: 22/8/16

1645

Mileage: 71910 km



Defects: Broken / Cracked / Damaged / Dented / Misaligned / Missing

Vehicle No: 1410 4553

Make / Model: Ford Focus

Received on 23/8/16 @ 1027
GENERAL ADMIN VEHICLE MAINTENANCE CONTRACT
(CN: 8013100564)

Attention: REGZORN (Fax: 64819221)

Contacted: ASUKA (Hotline: 93227386)

Date: 220816


Requestor's Info	
Vehicle No.	MID 41533
Unit:	TPT HUB EAST / NEE 300N
Rank & Name:	MSG STARK
Contact No.	8100 2579
Activated Time (24hr Format):	1020 HRS
<u>Joh Requests</u>	
01	MID 41533 - ACCIDENT QUOTATION VEH ASSESSMENT

Approved By: *M/S STEVEN*

Signature :

(Park & Natick)

RESTRICTED



SMRT AUTOMOTIVE SERVICES PTE LTD
 3 ANG MO KIO STREET #2
 SINGAPORE 689140

Quotation Ref No.: MAV/Aug16/Y3Q302
 Quotation Request Date: 22.08.2016
 Date of Quotation: 24.08.2016
 Date Quotation Submitted to HQ MES: 24.08.2016

HQ Maintenance Engineering Support
 151 Choa Chu Kang Way, Singapore 688248
 #02-14, Kranji Camp 3

Dear Sir,

Type of Repair: Accident / Damaged / Mod
 Vehicle No.: MID 41533
 Vehicle Model: FORD FOCUS 1.6A
 Vehicle Grouping: A / B
 Contract Ref No.: 8013100564

We hereby submit the quote for repair for the above-mentioned vehicle in accordance to the job description attached.

Job carried out by SMRT Automotive Services Pte Ltd

Total Repair Labour Cost: \$ 1,319.43 44.5 hrs @ \$ 29.65 per hr
 Spares Cost: \$ 14,682.00
 Transportation Cost: \$ 121.34
 Grand Total Cost: \$ 16,122.77

Delivery Period: 21 Days from date of Purchase Order (PO) Approval
 Validity Period: 90 Days from the date of quotation

Spares purchased by Vendor's Name are subjected to mark-up for both local and overseas items based on CIF price. The grand total repair cost of labour and spare(s)/ material(s) used are subjected to Goods and Services Tax.

Yours Faithfully,
 SMRT Automotive Services Pte Ltd

Name: Brijesh
 Appointment: Executive

For Authority Use Only:

Description of Reports	Ref No.	Date Created	Date Released	Released By: (Rank & Name)	Signed:
Purchase Request (PR) No.:					
Purchase Order (PO) No.:					



SMRT AUTOMOTIVE SERVICES PTE LTD
 8 ANG MO KIO STREET #2
 SINGAPORE 606140

Job Scope/ Inspection Report

Particulars of Vehicle

Type of Repair: Accident / Damaged / Mod
 Contract Ref No: S013100584
 Vehicle No.: MID 41533
 Vehicle Model: FORD FOCUS 1.6A
 Vehicle Grouping: A / B
 Chassis Number: WFDWXXGC6W7U77941
 Engine Number: -
 Odometer Reading: 77910

Quotation Ref. No.:
 Vendor's Coy Job No.:
 TPT HUB:
 Unit:

MAV/AUG16/Y3/Q107

East Hub

Nee Soon Camp

Quotation Req Date:

22.08.2016

Inspected By:

Robin Koh

Date Inspected:

22.08.2016

Date quotation Submitted:

24.08.2016

The scope of work and total labour manhours are agreed by customer.

Total Labour Manhours: 44.5

Delivery Period:

21

Sub Contractor Cost:

Transportation/ Towing Service: 2

S/No.	Task ID	Job Description	Work Done	Quoted Hrs	Remarks
		Trade Jobs			
1	10	Front bumper damaged	RPL	4	
1.1	-	Remove & install front bumper	-	-	
2	20	Front RH & LH head lamp cracked	RPL	1	
2.1	-	Remove, install front RH & LH head lamp assembly & connect wiring	-	-	
3	30	Front grille & emblem damaged	RPL	1	
3.1	-	Remove, install front grille, emblem, front grille finisher	-	-	
4	40	Front bonnet dented & bonnet lock broken	RPL	2	
4.1	-	Remove, install front bonnet & bonnet lock mechanism	-	-	
5	50	Front bumper reinforcement damaged	RPL	1	
5.1	-	Remove & install front bumper reinforcement	-	-	
6	60	Aircon condensor dented	RPL	2	
6.1	-	Remove & install aircon condensor	-	-	
7	70	Radiator assembly dented	RPL	1	
7.1	-	Remove, install radiator assembly & top up coolant	-	-	
8	80	Radiator cowling and fan assy cracked	RPL	2	
8.1	-	Remove, install radiator cowling & fan assy	-	-	
9	90	Transmission oil cooler dented	RPL	2	
9.1	-	Remove, install transmission oil cooler	-	-	
10	100	Engine intake manifold cracked	RPL	4	
10.1	-	Remove, install engine intake manifold	-	-	
11	110	Air cleaner intake assembly cracked	RPL	2	
11.1	-	Remove, install air cleaner intake assembly	-	-	
12	120	Aircon dryer damaged	RPL	0.5	
12.1	-	Remove & install aircon dryer	-	-	
13	130	Front support panel	RPL	2	
13.1	-	Remove & install front support panel	-	-	
14	140	Spray paint on repaired areas body	RPL & REP	20	

14.1		Putty, respray on front bonnet, front LH fender, front bumper, front grille & front support panel			
			Total Hrs	44.5	
		Towing Service			
1	150	To provide towing service for above vehicle from Nee Soon Camp to SMRT Workshop.		\$ 60.67	
2	160	To provide towing service for above vehicle from SMRT Workshop to Nee Soon Camp		\$ 60.67	
			Total	\$ 121.34	

Legend: REP- Repair, RPL - Replace, INFO - Information Only

FR-AS-CWD-24 Rev 0



SMRT AUTOMOTIVE SERVICES PTE LTD
 8 AND NO 10 STREET #2
 SINGAPORE 481100

Job Scope/ Inspection Report

Particulars of Vehicle

Type of Repair: Accident / Damaged / Mod
 Contract Ref No: 8013100566
 Vehicle No.: MD 41533
 Vehicle Model: FORD FOCUS 1.6A
 Vehicle Grouping: A / B
 Chassis Number: WF0WXXGCDW7U77941
 Engine Number: -
 Odometer Reading: 77910

Mark Up Rate:

10%

S/No	Part Number	Parts Description	Qty	UM	Unit Price	Mark-Up Price	Total Mark-Up Price	Unit Selling Price	Total Price
1	4M52-2757-CAXWAA	Front bumper	1	EA	\$ 850.00	\$ 85.00	\$ 85.00	\$ 935.00	\$ 935.00
2	4M51-13099-BD	Front RH head lamp assembly	1	EA	\$ 400.00	\$ 40.00	\$ 40.00	\$ 440.00	\$ 440.00
3	4M51-13101-BD	Front LH head lamp assembly	1	EA	\$ 400.00	\$ 40.00	\$ 40.00	\$ 440.00	\$ 440.00
4	4M51-8200-GA	Front grille	1	EA	\$ 953.80	\$ 95.38	\$ 95.38	\$ 1,053.80	\$ 1,053.80
5	4M51-8116-AA	Front emblem (Ford logo)	1	EA	\$ 144.40	\$ 14.44	\$ 14.44	\$ 158.40	\$ 158.40
6	4M518C436AAXWAA	Front grille Finisher	1	EA	\$ 248.80	\$ 24.88	\$ 24.88	\$ 272.80	\$ 272.80
7	4M51-A10610-AL	Front bonnet	1	EA	\$ 990.00	\$ 99.00	\$ 99.00	\$ 1,089.00	\$ 1,089.00
8	3M51-16700-BC	Front bonnet lock mechanism	1	EA	\$ 338.80	\$ 33.88	\$ 33.88	\$ 371.80	\$ 371.80
9	8V41510922AD	Front bumper reinforcement	1	EA	\$ 750.00	\$ 75.00	\$ 75.00	\$ 825.00	\$ 825.00
10	3M5H-19710CC	Alcon condensor	1	EA	\$ 736.60	\$ 73.66	\$ 73.66	\$ 809.60	\$ 809.60
11	3M5H-8005AK	Radiator assembly	1	EA	\$ 872.20	\$ 87.22	\$ 87.22	\$ 959.20	\$ 959.20
12	3M53-8C607EC	Radiator cowl and fan assy	1	EA	\$ 1,481.10	\$ 148.11	\$ 148.11	\$ 1,629.10	\$ 1,629.10
13	4M5P7A095	Transmission oil cooler	1	EA	\$ 1,264.40	\$ 126.44	\$ 126.44	\$ 1,390.40	\$ 1,390.40
14	256G9424	Engine intake manifold	1	EA	\$ 2,085.50	\$ 208.55	\$ 208.55	\$ 2,293.50	\$ 2,293.50
15	7M5G00	Air cleaner intake assembly	1	EA	\$ 566.60	\$ 56.66	\$ 56.66	\$ 622.60	\$ 622.60
16	3M5H19E647	Alcon dryer	1	EA	\$ 650.00	\$ 65.00	\$ 65.00	\$ 715.00	\$ 715.00
17	8M518B043CC	Front support panel	1	EA	\$ 870.00	\$ 87.00	\$ 87.00	\$ 957.00	\$ 957.00
18	NA	Paint material	2	EA	\$ 140.00	\$ 14.00	\$ 28.00	\$ 154.00	\$ 308.00
Total:							\$ 1,388.20		\$ 15,270.20

Total Spare Price: \$ 15,270.20

Total Mark Up Price: \$ 1,388.20

Max Allowable Mark Up: \$ 800.00

Total Spare Price including allowable Mark Up Price: \$ 14,682.00

FR-AS-CWD-24 Rev 0