

15/5/2016

INS. CASE OWNER:

CC AXA160

16456, MI Wg 37

LKK:
IDAC:

Surveyor:

DOI:

ASSIGNMENT

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II :SS

Is driver the owner?

(YES) / (NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: %

Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

1/9/16
Vian

7/9/16

18/1/17
18/1/17SIB6335P - (83/1116016357) Y53 047 29/10/16.
YE 2888U - XConfirm accident details. Inform TP claim.
Q2 involved in Acc 0213 the last veh. agree to
settle and aware NCD will be affected. Letter
send out.File pass to typist type report
See K mandale via Merimen.

Email From DoCA to submit w/p report.

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No. : 28

Repair Cost:

S\$

40660.00

Loss of Rental (LOR):

S\$

3263.50 (25 days) x 130.54

Loss of Use (LOU):

S\$

1150.00 (\$ 50 x 23 days)

Loss of Income (LOI):

S\$

(\$ x days)

LOR only ☐ LOU only ☐

LOR + LOU

☐

LOR + LOI

☐

[Tick only one]

GIA/LTA Search

S\$

2.00

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost

S\$

Total:

S\$

45075.50

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

ee 1:

S\$

Name 1:

2: (Strike if N.A.)

S\$

Name 2:

3: (Strike if N.A.)

S\$

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

COPY SENT

(08/11/13)

Surveyor:

REF:

AXA 16016456/M/wg3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s CHUNNI

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 20 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SHB6335P Yr Regn: SEP 12Type: M.Car / M.Cycle / Bus / Van / Lorry / ☒ Prime Mover /

Truck / Trailer or

Make: HYUNDAI C.C. 1685Colour: Blue A/C: Insured / Std / NI / NASp. Reading: 475307 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KMHLBHIUMDU 039869Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ Inorder / Jammed / Leaked / Burnt orBrake: ☒ Inorder / Jammed / Leaked / Burnt orModi: ☒ Nil / S/Rim / STD A/Rim orTyre Size: F: 205/60R16R: 2☒ BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /TOYO / YOKO or BlueFront 8 mm Rear 8 mmR/Bal. 8 mm R/Bal. 8 mmL/Bal. 8 mm L/Bal. 8 mmD.O.A. 29/8/2016 D.O.I. 2/9/2016

Survey held at _____

Des. of Damages: ☒ Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
17/1/17	Confirm L/S \$38000.00 with 20 working days
	MV - \$6475.63
	LTA - \$44875.00
	NV - \$19850.63
	(Red: \$43217.31 53%)

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS \$ _____

Photos

Others

TOTAL

Report Format : _____

Lump Sum / I.B.I. (\$) _____



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE SINGAPORE PTE LTD		Ref : CC4/AXA16016456/wg3		
8 SHENTON WAY #27-01 SINGAPORE 068811		Date : 01-09-2016		
		Code : AXA2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YE 2888U	Veh. Inspected	SHB 6335P	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	01/09/2016	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	29/08/2016	Inspection Date		
Survey held at	CHUNNI MOTOR WORK PTE LTD BLK 10 ANG MO KIO IND. PARK 2A, #03-19 AMK AUTOPOINT SINGAPORE 568047.			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

...CLAIM SUBFOLDER...(New Assignment)

Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	01 Sep 2016		01 Sep 2016 12:44 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	CHAN, CHEN CHYE, NRIC: S1447962G, Tel: +6596322227								
Main Claimant:	COMFORT TRANSPORTATION PTE LTD								
Vehicle Reg. No.:	SHB6335P	Date of Loss:	29/08/2016 06:00 - :59						
Claim Type:	TP / C0398006	Policy/Cover Note No.:	P1693215 (Comprehensive)						
Vehicle Reg. No. (Insured):	YE2888U	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	Chunni Motor Work Pte Ltd (HQ) Blk 10 Ang Mo Kio Industrial Park 2A, #03-19 AMK Autopoint, 568047 Ang Mo Kio - Tel: 6542 7162								
Handling Insurer:	AXA Insurance Singapore Pte Ltd (HQ) - Tel: 6338 7288 ... [Handled by Chen Xinyou - 6880 4269]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 13/09/2016]								
Driver/Custodian (Insured):	CHAN, CHEN CHYE (), NRIC: S1447962G, Tel: +6596322227								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
• AXA_SG (01/09/2016): New TP Assignment - C0398006/P1693215									
ALL ASSOCIATED TASKS		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

01-09-2016 @ 1:18pm

Isrene veh not in

CHUNNI MOTOR WORK PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHB 6335P

MAKE :

MODEL : HYUNDAI i40

DATE : 31.08.2016

TEL : 6542 5119

FAX : 6542 6039

4x4

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Bonnet		mc/s	1,526.00
	Bonnet Lock		bt/s	50.90
	Bonnet Insulator		dis/s	243.00
	Bonnet Insulator Clips		mc/s	8.40
	Radiator Grille		dis/s	1,480.00
	Radiator Grille H Emblem		mc/s	290.80
	Radiator Grille Chrome Moulding		dis/s	395.50
	Front Bumper Cover		dis/s	1,052.20
	Front Bumper Sponge		term/s	142.20
	Front Bumper Reinforcement		bt/s	526.10
	Front Bumper Reinforcement Bar		bt/s	258.50
	Front Bumper Grille (LH)		dis/s	285.50
	Front Bumper Grille Airduct (LH)		dis/s	155.00
	Front Bumper Bracket Top (LH)		dis/s	22.40
	Front Bumper Bracket (LH)		dis/s	24.60
	Front Bumper Retainer Mounting		dis/s	9.20
	Headlamp Support Top Cover		dis/s	398.00
	Headlamp Support Panel Assy		bt/s	1,067.50
	Headlamp (LH/RH)	cvq	S 1,388.00	S 2,776.00
	Radiator		bt/s	S 850.20
	Radiator Fan Blade,Cowling,Motor Assy		dis/s	S 792.95
	Radiator Bracket (RH/LH)	S	dis 6.50	S 13.00
	Radiator Hose Upper		dis/s	S 47.40
	Radiator Hose Lower		mc/s	S x 47.40
	Radiator Expansion Tank		mc/s	S x 48.00
	Radiator Guard	S	dis 35.00	S 70.00
	Horn Unit (LH/RH)	S	dis 86.75	S 173.50
	Horn Wire		mc/s	S x 156.50
	Front Fender (LH)		mc/s	S 619.00
	Front Fender Apron Panel (LH)		bt/s	S 1,575.50
	Front Fender Shield (LH)		dis/s	S 169.80
	Front Fender Retainer		dis/s	S 9.20
	Air Cleaner Assy		dis/s	S 128.40
	Air Duct		dis/s	S 206.05
	Air Cleaner Body		mc/s	S x 106.20
	Aircon Condenser		bt/s	S 1,137.35
	Front Windscreen Glass		cvq/s	S 1,059.25
	Front Windscreen Moulding		mc/s	S 60.00
	Front Wheel Rim (LH)		mc/s	S x 351.90
	Front Wheel Hub Cap (LH)		mc/s	S x 158.90
	Front Wheel Bearing		mc/s	S 258.50
	Front Shock Absorber (Assy) (LH)		mc/s	S 342.20
	Front Shock Absorber Mounting (LH)		mc/s	S 75.10
	Front Drive Shaft (LH)		mc/s	S 1,069.55
	Rack & Pinion Assy		mc/s	S 2,184.00
	STG Tie Rod		mc/s	S 162.00
	STG Tie End		mc/s	S 69.50

SHB 6335P

[illegible]

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Labour Charge			
	Panel Beating			\$ 2,000.00 1200
	Spray Painting Charge			\$ 1,000.00 720
	Wiring Charge			\$ 100.00 30
	Tuff Kote			\$ 100.00 60
	Towing Charge			\$ 50.00
	Remove/Refix Undercarriage (FRT)			\$ 400.00 180 ✓
	FRT Wheel Alignment			\$ 120.00 80
	Remove/Refix Aircon & Refill Gas			\$ 150.00 100
	Remove/Refix Gearbox			\$ 450.00 350 ✓
	Remove/Refix Dashboard			\$ 450.00 280 ✓
	Remove/Refix Fuse Box			\$ 180.00 120
	Remove/Refix Front Windscreen Glass			\$ 120.00 100
	Remove/Refix Cushion & Upholstery Front			\$ 90.00 60
	Re-programme Air Bag & Safety Belt System			\$ 550.00 350
	TOTAL LABOUR			\$ 5,760.00
	Boot Lid	LA	\$ 1,681.40	—
	Boot Lid Rubber	dis	\$ 115.80	—
	Boot Lid Lock Upper	LA	\$ 137.90	—
	Boot Lid Lock Lower	LA	\$ 31.70	—
	Boot Lid 'H' Emblem	LA	\$ 27.20	—
	Boot Lid CRDI Plate	LA	\$ 41.00	—
	Boot Lid Lamp (LH/RH)	S 29556.80	\$ 1,113.60	—
	Licence Lamp (LH/RH)	S 29533.95	\$ 67.90	—
	Boot Lid Trimboard	dis	\$ 172.70	—
	Boot Lid Trimboard Clips (11pcs)	LA	\$ 11.00	—
	Bootlid Moulding	dis	\$ 85.00	—
	Bootlid i40 Emblem	LA	\$ 41.00	—
	Bootlid Lower Garnish	dis	\$ 398.00	—
	Rear Bumper	LA	\$ 33.96	—
	Rear Bumper Reinforcement	LA	\$ 504.35	—
	Rear Bumper Reinforcement Bracket	S 180.00	\$ 360.00	—
	Rear Bumper Side Bracket	S 549.00	\$ 98.00	—
	Rear Bumper Sponge	LA	\$ 143.40	—
	Rear Bumper Under Cover	dis	\$ 225.80	—
	Rear Bumper Reflector Lamp (LH/RH)	LA NS 29532.00	\$ 64.00	✓
	Tail Lamp (LH/RH)	S 295565.60	\$ 1,131.20	✓
	Tail Lamp Quarter Panel (LH/RH)	S 29549.90	\$ 195.80	✓
	Rear Panel	LA	\$ 592.30	—
	Rear Panel Garnish	dis	\$ 57.70	—
	Rear Panel Lower Panel	LA	\$ 495.50	—
	Spare Tyre Holder	LA	\$ 143.40	✓
	Tail Lamp Panel Top (LH)	LA	\$ 545.90	—
	Spare Tyre Panel	LA	\$ 900.50	—
	Spare Tyre Panel Cushion	LA	\$ 209.05	✓
	Rear Towing Hook	dis	\$ 94.60	✓
	Member Assy- Rear Floor Centre	LA	\$ 170.75	✓

SHB 6335P

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Exhaust Pipe Insulator	W	S 58.55	S 117.10	X SJC
	Exhaust Silencer <i>os ? as on</i>		S X 954.00	S X 1,908.00	X SJC
	Exhaust Pipe Hanger		S W 58.55	S X 117.10	
	Exhaust Pipe Centre			S X 1,150.30	SJC
	Rear Fender With Housing (LH)			S X 4,736.80	bt
	Rear Fender Inner Lining (LH)			S X 164.40	
	Rear Fender Air-Duct			S X 225.60	
	Rear Fender Trim Board (LH)			S 188.75	
	Rear Windscreen Glass			S X 985.50	
	Rear Windscreen Moulding			S 62.15	
	SUB TOTAL			S 19,546.11	
	LESS 20%			S 3,909.22	
	DISCOUNTED TOTAL			S 15,636.89	
	Boot Lid Comfort Logo & Tel No. Sticker			S 30.00	Nett
	Rear No. Plate			S 25.00	Nett
	Rear Bumper Reverse Sensor			S 135.70	Nett
	Rear Windscreen Sealant			S 46.00	Nett
				S 236.70	
	Labour Charge				
	Panel Beating			S 2,000.00	1600
	Spray Painting Charge			S 1,200.00	1200
	Wiring Charge			S 50.00	30
	Tuff Kote			S 50.00	1
	Remove/Refix Cushion & Upholstery Rear			S 150.00	80
	Remove/Refix Rear Windscreen Glass			S 120.00	100
	Remove/Refix Reverse Sensor			S 120.00	60
	Remove/Refix Fuel Tank			S 150.00	X
	Remove/Refix Exhaust Pipe			S 150.00	100
	TOTAL LABOUR			S 3,990.00	
	ESTIMATE TOTAL			S 81,217.31	
				82910.51	
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					

Ab Mene

FAX : 6542 6039

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

CHUNNI MOTOR WORK PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHB 6335P

DATE : 31.08.2016

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI i40

FAX : 6542 6039

AXA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Bonnet		ucl \$	1,526.00
	Bonnet Lock		bt \$	50.90
	Bonnet Insulator		dis \$	243.00
	Bonnet Insulator Clips		ucl \$	8.40
	Radiator Grille		dis \$	1,480.00
	Radiator Grille H Emblem		ucl \$	290.80
	Radiator Grille Chrome Moulding		dis \$	395.50
	Front Bumper Cover		dis \$	1,052.20
	Front Bumper Sponge		term \$	142.20
	Front Bumper Reinforcement		bt \$	526.10
	Front Bumper Reinforcement Bar		bt \$	258.50
	Front Bumper Grille (LH)		dis \$	285.50
	Front Bumper Grille Airduct (LH)		dis \$	155.00
	Front Bumper Bracket Top (LH)		dis \$	22.40
	Front Bumper Bracket (LH)		dis \$	24.60
	Front Bumper Retainer Mounting		dis \$	9.20
	Headlamp Support Top Cover		dis \$	398.00
	Headlamp Support Panel Assy		bt \$	1,067.50
	Headlamp (LH/RH)	cvr	\$ 1,388.00	\$ 2,776.00
	Radiator		bt \$	850.20
	Radiator Fan Blade,Cowling,Motor Assy		dis \$	792.95
	Radiator Bracket (RH/LH)		\$ dis 6.50	\$ 13.00
	Radiator Hose Upper		dis \$	47.40
	Radiator Hose Lower		mc \$	47.40
	Radiator Expansion Tank		mc \$	48.00
	Radiator Guard		\$ dis 35.00	\$ 70.00
	Horn Unit (LH/RH)		\$ dis 86.75	\$ 173.50
	Horn Wire		mc \$	156.50
	Front Fender (LH)		ucl \$	619.00
	Front Fender Apron Panel (LH)		bt \$	1,575.50
	Front Fender Shield (LH)		dis \$	169.80
	Front Fender Retainer		dis \$	9.20
	Air Cleaner Assy		dis \$	128.40
	Air Duct		dis \$	206.05
	Air Cleaner Body		R \$	106.20
	Aircon Condenser		bt \$	1,137.35
	Front Windscreen Glass		cvr \$	1,059.25
	Front Windscreen Moulding		ucl \$	60.00
	Front Wheel Rim (LH)		mc \$	351.90
	Front Wheel Hub Cap (LH)		mc \$	158.90
	Front Wheel Bearing		7 \$	258.50
	Front Shock Absorber (Assy) (LH)		7 \$	342.20
	Front Shock Absorber Mounting (LH)		7 \$	75.10
	Front Drive Shaft (LH)		X \$	1,069.55
	Rack & Pinion Assy		mc { X \$	2,184.00
	STG Tie Rod		X \$	162.00
	STG Tie End		X \$	69.50

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Stabilizer Bar			\$ 252.30
	Stabilizer Bar Bush (LH)			\$ 14.20
	Stabilizer Bar Link			\$ 81.70
	Stabilizer Bracket			\$ 24.00
	Front Suspension Lower Arm (LH)			\$ 715.10
	Knuckle Arm (LH)			\$ 582.95
	Engine Mounting			\$ 481.90
	Engine Under Cover			\$ 343.10
	Engine Crossmember			\$ 2,236.90
	Front Cushion Seat (RH)			\$ 5,992.00
	Engine Mtg (Front)			\$ 235.30
	Engine Mtg (Rear)			\$ 279.60
	Gearbox			\$ 14,808.00
	Gearbox Mounting			\$ 342.50
	Inter Cooler			\$ 921.90
	Inter Cooler Mounting (2 PCS)			\$ 25.90
	Hose B To Inter Cooler			\$ 229.70
	Hose C To Inter Cooler Inlet			\$ 113.30
	ABS Sensor			\$ 261.50
	Wiring-Engine			\$ 3,326.00
	Wiring-Front			\$ 1,960.80
	Airbag Complete			\$ 2,948.50
	Airbag Control Module			\$ 1,894.00
	Steering Angle Assy			\$ 1,150.60
	Sensor Assy Impact -Frt Impact			\$ 1,180.50
	Airbag Sensor		\$ 580.00	\$ 1,160.00
	Electric Power Steering			\$ 4,880.50
	SUB TOTAL			\$ 69,095.90
	LESS 20%			\$ 13,819.18
	DISCOUNTED TOTAL			\$ 55,276.72
	Front Number Plate			\$ 25.00
	Front No Plate Trim Cover			\$ 30.00
	Front Tyre (LH)			\$ 216.00
	Front Windscreen Sealant			\$ 46.00
				\$ 317.00

1500814

Nett

Nett

Nett 80%

Nett

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Labour Charge			
	Panel Beating			\$ 2,000.00 1200
	Spray Painting Charge			\$ 1,000.00 720
	Wiring Charge			\$ 100.00 30
	Tuff Kote			\$ 100.00 60
	Towing Charge			\$ 50.00 1
	Remove/Refix Undercarriage (FRT)			\$ 400.00 180?
	FRT Wheel Alignment			\$ 120.00 80
	Remove/Refix Aircon & Refill Gas			\$ 150.00 100
	Remove/Refix Gearbox			\$ 450.00 350?
	Remove/Refix Dashboard			\$ 450.00 280?
	Remove/Refix Fuse Box			\$ 180.00 120
	Remove/Refix Front Windscreen Glass			\$ 120.00 100
	Remove/Refix Cushion & Upholstery Front			\$ 90.00 60
	Re-programme Air Bag & Safety Belt System			\$ 550.00 350-
	TOTAL LABOUR			\$ 5,760.00
	Boot Lid		LA \$ 1,681.40	—
	Boot Lid Rubber		dis \$ 115.80	—
	Boot Lid Lock Upper		LT \$ 137.90	—
	Boot Lid Lock Lower		LT \$ 31.70	—
	Boot Lid 'H' Emblem		LT \$ 27.20	—
	Boot Lid CRDI Plate		LT \$ 41.00	—
	Boot Lid Lamp (LH/RH)		\$ avg 556.80 \$ 1,113.60	—
	Licence Lamp (LH/RH)		\$ avg 33.95 \$ 67.90	—
	Boot Lid Trimboard		dis \$ 172.70	—
	Boot Lid Trimboard Clips (11pcs)		LT \$ 11.00	—
	Bootlid Moulding		dis \$ 85.00	—
	Bootlid i40 Emblem		LT \$ 41.00	—
	Bootlid Lower Garnish		dis \$ 398.00	—
	Rear Bumper		LT \$ 33.96	—
	Rear Bumper Reinforcement		LT \$ 504.35	—
	Rear Bumper Reinforcement Bracket		\$ LT 180.00 \$ 360.00	—
	Rear Bumper Side Bracket		\$ dis 49.00 \$ 98.00	—
	Rear Bumper Sponge		LT \$ 143.40	—
	Rear Bumper Under Cover		dis \$ 225.80	—
	Rear Bumper Reflector Lamp (LH/RH)	LT NS avg	\$ 32.00 \$ 64.00	✓
	Tail Lamp (LH/RH)		\$ avg 565.60 \$ 1,131.20	✓
	Tail Lamp Quarter Panel (LH/RH)	NS LT OSR	\$ 97.90 \$ 195.80	✓
	Rear Panel		LT \$ 592.30	—
	Rear Panel Garnish		dis \$ 57.70	—
	Rear Panel Lower Panel		LT \$ 495.50	—
	Spare Tyre Holder		LT \$ 143.40	✓
	Tail Lamp Panel Top (LH)		LT \$ 545.90	—
	Spare Tyre Panel		LT \$ 900.50	—
	Spare Tyre Panel Cushion		LT \$ 209.05	✓
	Rear Towing Hook		\$ 94.60	✓
	Member Assy- Rear Floor Centre		\$ 170.75	✓

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Exhaust Pipe Insulator	W	\$ 58.55	\$ 117.10	X
	Exhaust Silencer <i>of 2 used</i>		\$ 7954.00	\$ 1,908.00	
	Exhaust Pipe Hanger	W	\$ 58.55	\$ 117.10	
	Exhaust Pipe Centre			\$ 1,150.30	
	Rear Fender With Housing (LH)			\$ 4,736.80	
	Rear Fender Inner Lining (LH)	W		\$ 164.40	
	Rear Fender Air-Duct	W		\$ 225.60	
	Rear Fender Trim Board (LH)	W		\$ 188.75	
	Rear Windscreen Glass	W		\$ 985.50	
	Rear Windscreen Moulding	W		\$ 62.15	
	SUB TOTAL			\$ 19,546.11	
	LESS 20%			\$ 3,909.22	
	DISCOUNTED TOTAL			\$ 15,636.89	
	Boot Lid Comfort Logo & Tel No. Sticker	W	\$ 30.00	\$ 30.00	Nett
	Rear No. Plate	W	\$ 25.00	\$ 25.00	Nett
	Rear Bumper Reverse Sensor	W	\$ 135.70	\$ 135.70	Nett
	Rear Windscreen Sealant	W	\$ 46.00	\$ 46.00	Nett
				\$ 236.70	
	Labour Charge				
	Panel Beating			\$ 2,000.00	1600
	Spray Painting Charge			\$ 1,200.00	1200
	Wiring Charge			\$ 50.00	30
	Tuff Kote			\$ 50.00	1
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00	80
	Remove/Refix Rear Windscreen Glass			\$ 120.00	100
	Remove/Refix Reverse Sensor			\$ 120.00	60
	Remove/Refix Fuel Tank			\$ 150.00	X
	Remove/Refix Exhaust Pipe			\$ 150.00	100
	TOTAL LABOUR			\$ 3,990.00	
	ESTIMATE TOTAL			\$ 81,217.31	
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	01 Sep 2016		01 Sep 2016 12:44 Edit Adj Rpt	S\$38,000.00 Edit Estimates	S\$38,000.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by Insurer]

Insured:	CHAN, CHEN CHYE, ID: S1447962G, Tel: +6596322227		
Main Claimant:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R		
Vehicle Reg. No.:	SHB6335P	Date of Loss:	29/08/2016 06:00 - :59 [34 Months and 30 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / C0398006	Policy/Cover Note No.:	P1693215 (Comprehensive)
Vehicle Reg. No. (Insured):	YE2888U	Policy No. (Claimant):	MCOM0016
		Excess:	S\$0.00
Repairer:	Chunni Motor Work Pte Ltd (HQ) Blk 10 Ang Mo Kio Industrial Park 2A, #03-19 AMK Autopoint, 568047 Ang Mo Kio - Tel: 6542 7162		
Handling Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288 ... [Handled by Chan Kian Chuan - 6880 4269]		
Claimant's Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MA CHIN FOOK] ... [Final Rpt due 13/09/2016]		
Driver/Custodian (Insured):	CHAN, CHEN CHYE (), NRIC: S1447962G, Tel: +6596322227 Email:		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AXA_SG (12/01/2019): Re: Direct Settlement - Accident Involving YE2888U (OI : AXA - C0398006) and SHB...
- AXA_SG (08/08/2017): Re: Direct Settlement - Accident Involving YE2888U (OI : AXA - C0398006) and SHB...
- AXA_SG (26/01/2017): Alert - Adj Mandate Maintained - SHB6335P - Claim Handler: Chen Xinyou
- AXA_SG (05/01/2017): Re: Direct Settlement - Accident Involving YE2888U (OI : AXA - C0398006) and SHB...
- AXA_SG (21/11/2016): Re: Direct Settlement - Accident Involving YE2888U (OI : AXA - C0398006) and SHB...
- AXA_SG (12/10/2016): Fw: Re: Direct Settlement - Accident Involving YE2888U (OI : AXA - C0398006) and...
- AXA_SG (05/09/2016): Re: Direct Settlement - Accident Involving YE2888U (OI : AXA - C0398006) and SHB...
- AXA_SG (01/09/2016): New TP Assignment - C0398006/P1693215

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SHB6335P (C0398006)
[YE2888U]
TP
COMFORT TRANSPORTATION PTE LTD
Aug 29 2016 6:00AM
[CHAN, CHEN CHYE]
Chunni Motor Work Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Letters/Correspondences															1 per page		☒			
No	Finalized On	AXA Insurance Pte Ltd (HQ)													Thumbnail	Print				
1	01/09/16 12:45	Email correspondence with TP workshop (PRS)												1	Load PDF					
Assessment Reports															1 per page		☒			
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail	Print				
1	05/09/16 11:27	Adjuster Immediate Advice												1	Load HTM					
Photos/Images															3 per page		☒			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail	Print				
1	05/09/16 11:33	LKK PHOTOS INSPECTION												1	Load PDF					
2	18/01/17 11:26	LKK Reinspection Photo												1	Load PDF					
Documentation															1 per page		☒			
No	Finalized On	AXA Insurance Pte Ltd (HQ)													Thumbnail	Print				
1	01/09/16 08:45	YE2888U INS GIA_ABS												1	Load PDF					
2	01/09/16 08:45	SLD8139T GIA_ABS												1	Load PDF					
3	01/09/16 08:45	SJC4308C GIA_ABS												1	Load PDF					
4	01/09/16 08:45	ESTIMATE & SHB6335P TP GIA_ABS												1	Load PDF					
5	01/09/16 08:45	EMAIL_ABS												1	Load PDF					
6	01/09/16 11:48	CI												1	Load PDF					
7	01/09/16 11:48	Policy Schedule												1	Load PDF					
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail	Print				
1	05/09/16 11:31	TP ESTIMATE - MARKED												1	Load PDF					
2	18/01/17 11:03	GIA SEARCH												1	Load PDF					
3	18/01/17 11:03	LETTER TO OI												1	Load PDF					
4	18/01/17 11:03	RENTAL RECEIPT												1	Load PDF					
5	06/05/19 08:57	EMAIL												1	Load PDF					

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AXA16016456/M1WB3S2

Date: 06/05/2019

REFERENCE

Handling Insurer:	AXA Insurance Pte Ltd	Policy No:	P1693215
Claimant Vehicle No :	SHB6335P	Insured Vehicle No :	YE2888U
Date of Loss:	29/08/2016	Nature of Claim:	TP
		Claim No:	C0398006

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHB6335P	Engine No:	D4FDDU349515
Make & Model:	HYUNDAI I40, 1.7 D CRDi (A)	Chassis No:	KMHLB41UMDU039869
Reg. Date:	30/09/2013 (Man. Year: 2013)	Odometer:	475307 km
Colour:	Blue		
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	Bridgestone 8 mm	Rear Left Side:	Bridgestone 8 mm
Front Right Side:	Bridgestone 8 mm	Rear Right Side:	Bridgestone 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	73,160.51	52,886.91	20,273.60	27.71
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,750.00	6,900.00	2,850.00	29.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	82,910.51	59,786.91	23,123.60	27.89
Approved Total (Overridden) (S\$)		38,000.00		
(S\$)	82,910.51	38,000.00	44,910.51	54.17
+ GST 7.00/7.00% (S\$)	5,803.74	2,660.00	3,143.74	54.17
Nett Amount (S\$)	88,714.25	40,660.00	48,054.25	54.17

INSPECTION

Date of Assignment:	01/09/2016	Chunni Motor Work Pte Ltd (HQ) Blk 10 Ang Mo Kio Industrial Park 2A, #03-19 AMK Autopoint Singapore 568047
Date Inspected:	02/09/2016 Inspected At:	
Estimated Period of Repair:	20.0 days	

Adjuster: MA CHIN FOOK

Manager: VIVIAN LAU PEI FENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 May 2019)
Parts:	143	HYUNDAI I40 1.7 D CRDi (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHB6335P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET (CONSISTENT)	Buckled	1,526.00 FL	*1,526.00 FL
2	1		*BONNET LOCK (CONSISTENT)	Bent	50.90 FL	*50.90 FL
3	1		*BONNET INSULATOR (CONSISTENT)	Distorted	243.00 FL	*243.00 FL
4	1		*BONNET INSULATOR CLIPS (CONSISTENT)	Necessary	8.40 FL	*8.40 FL
5	1		*RADIATOR GRILLE (CONSISTENT)	Distorted	1,480.00 FL	*1,480.00 FL
6	1		*RADIATOR GRILLE H EMBLEM (CONSISTENT)	Necessary	290.80 FL	*290.80 FL
7	1		*RADIATOR GRILLE CHROME MOULDING (CONSISTENT)	Distorted	395.50 FL	*395.50 FL
8	1		*FRONT BUMPER COVER (CONSISTENT)	Deformed	1,052.20 FL	*1,052.20 FL
9	1		*FRONT BUMPER SPONGE (CONSISTENT)	Torn	142.20 FL	*142.20 FL
10	1		*FRONT BUMPER REINFORCEMENT (CONSISTENT)	Bent	526.10 FL	*526.10 FL
11	1		*FRONT BUMPER REINFORCEMENT BAR (CONSISTENT)	Bent	258.50 FL	*258.50 FL
12	1		*FRONT BUMPER GRILLE (LH) (CONSISTENT)	Distorted	285.50 FL	*285.50 FL
13	1		*FRONT BUMPER GRILLE AIRDUCT (LH) (CONSISTENT)	Distorted	155.00 FL	*155.00 FL
14	1		*FRONT BUMPER BRACKET TOP (LH) (CONSISTENT)	Distorted	22.40 FL	*22.40 FL
15	1		*FRONT BUMPER BRACKET (LH) (CONSISTENT)	Distorted	24.60 FL	*24.60 FL
16	1		*FRONT BUMPER RETAINER MOUNTING (CONSISTENT)	Distorted	9.20 FL	*9.20 FL
17	1		*HEADLAMP SUPPORT TOP COVER (CONSISTENT)	Distorted	398.00 FL	*398.00 FL
18	1		*HEADLAMP SUPPORT PANEL ASSY (CONSISTENT)	Bent	1,067.50 FL	*1,067.50 FL
19	2		*HEADLAMP (LH/RH) (CONSISTENT)	Cracked	2,776.00 FL	*2,776.00 FL
20	1		*RADIATOR (CONSISTENT)	Bent	850.20 FL	*850.20 FL
21	1		*RADIATOR FAN BLADE, COWLING, MOTOR ASSY (CONSISTENT)	Distorted	792.95 FL	*792.95 FL
22	2		*RADIATOR BRACKET (RH/LH) (CONSISTENT)	Distorted	13.00 FL	*13.00 FL
23	1		*RADIATOR HOSE UPPER (CONSISTENT)	Distorted	47.40 FL	*47.40 FL
24	1		*RADIATOR HOSE LOWER (CONSISTENT)	Serviceable	47.40 FL	*- FL
25	1		*RADIATOR EXPANSION TANK (CONSISTENT)	Serviceable	48.00 FL	*- FL
26	2		*RADIATOR GUARD (CONSISTENT)	Distorted	70.00 FL	*70.00 FL
27	2		*HORN UNIT (LH/RH) (CONSISTENT)	Distorted	173.50 FL	*173.50 FL
28	1		*HORN WIRE (CONSISTENT)	Serviceable	156.50 FL	*- FL
29	1		*FRONT FENDER (LH) (CONSISTENT)	Buckled	619.00 FL	*619.00 FL
30	1		*FRONT FENDER APRON PANEL (LH) (CONSISTENT)	Bent	1,575.50 FL	*1,575.50 FL
31	1		*FRONT FENDER SHIELD (LH) (CONSISTENT)	Distorted	169.80 FL	*169.80 FL
32	1		*FRONT FENDER RETAINER (CONSISTENT)	Distorted	9.20 FL	*9.20 FL
33	1		*AIR CLEANER ASSY (CONSISTENT)	Distorted	128.40 FL	*128.40 FL
34	1		*AIR DUCT (CONSISTENT)	Distorted	206.05 FL	*206.05 FL
35	1		*AIR CLEANER BODY (CONSISTENT)	Repair	106.20 FL	*- FL
36	1		*AIRCON CONDENSER (CONSISTENT)	Bent	1,137.35 FL	*1,137.35 FL
37	1		*FRONT WINDSCREEN GALSS (CONSISTENT)	Cracked	1,059.25 FL	*1,059.25 FL
38	1		*FRONT WINDSCREEN MOULDING (CONSISTENT)	Necessary	60.00 FL	*60.00 FL
39	1		*FRONT WHEEL RIM (LH) (CONSISTENT)	Serviceable	351.90 FL	*- FL
40	1		*FRONT WHEEL HUB CAP (LH) (CONSISTENT)	Serviceable	158.90 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
41	1		*FRONT WHEEL BEARING (CONSISTENT)	Serviceable	258.50 FL	*- FL
42	1		*FRONT SHOCK ABSORBER (ASSY) (LH) (CONSISTENT)	Serviceable	342.20 FL	*- FL
43	1		*FRONT SHOCK ABSORBER MOUNTING (LH) (CONSISTENT)	Serviceable	75.10 FL	*- FL
44	1		*FRONT DRIVE SHAFT (LH) (CONSISTENT)	Serviceable	1,069.55 FL	*- FL
45	1		*RACK & PINION ASSY (CONSISTENT)	Serviceable	2,184.00 FL	*- FL
46	1		*STG TIE ROD (CONSISTENT)	Serviceable	162.00 FL	*- FL
47	1		*STG TIE END (CONSISTENT)	Serviceable	69.50 FL	*- FL
48	1		*STABILIZER BAR (CONSISTENT)	Serviceable	252.30 FL	*- FL
49	1		*STABILIZER BAR BUSH (LH) (CONSISTENT)	Serviceable	14.20 FL	*- FL
50	1		*STABILIZER BAR LINK (CONSISTENT)	Serviceable	81.70 FL	*- FL
51	1		*STABILIZER BRACKET (CONSISTENT)	Serviceable	24.00 FL	*- FL
52	1		*FRONT SUSPENSION LOWER ARM (LH) (CONSISTENT)	Bent	715.10 FL	*715.10 FL
53	1		*KNUCKLE ARM (LH) (CONSISTENT)	Bent	582.95 FL	*582.95 FL
54	1		*ENGINE MOUNTING (CONSISTENT)	Serviceable	481.90 FL	*- FL
55	1		*ENGINE UNDER COVER (CONSISTENT)	Serviceable	343.10 FL	*- FL
56	1		*ENGINE CROSSMEMBER (CONSISTENT)	Serviceable	2,236.90 FL	*- FL
57	1		*ENGINE MTG (FRONT) (CONSISTENT)	Serviceable	235.30 FL	*- FL
58	1		*ENGINE MTG (REAR) (CONSISTENT)	Serviceable	279.60 FL	*- FL
59	1		*GEARBOX (CONSISTENT)	Jammed	14,808.00 FL	*14,808.00 FL
60	1		*GEARBOX MOUNTING (CONSISTENT)	Serviceable	342.50 FL	*- FL
61	1		*INTER COOLER (CONSISTENT)	Bent	921.90 FL	*921.90 FL
62	2		*INTER COOLER MOUNTING (CONSISTENT)	Distorted	25.90 FL	*25.90 FL
63	1		*HOSE B TO INTER COOLER (CONSISTENT)	Distorted	229.70 FL	*229.70 FL
64	1		*HOSE C TO INTER COOLER INLET (CONSISTENT)	Serviceable	113.30 FL	*- FL
65	1		*ABS SENSOR (CONSISTENT)	Serviceable	261.50 FL	*- FL
66	1		*WIRING-ENGINE (CONSISTENT)	Distorted	3,326.00 FL	*3,326.00 FL
67	1		*WIRING-FRONT (CONSISTENT)	Distorted	1,960.80 FL	*1,960.80 FL
68	1		*AIRBAG COMPLETE (CONSISTENT)	Activated	2,948.50 FL	*2,948.50 FL
69	1		*AIRBAG CONTROL MODULE (CONSISTENT)	Activated	1,894.00 FL	*1,894.00 FL
70	1		*STEERING ANGLE ASSY (CONSISTENT)	Activated	1,150.60 FL	*1,150.60 FL
71	1		*SENSOR ASSY IMPACT - FRT INPACT (CONSISTENT)	Necessary	1,180.50 FL	*1,180.50 FL
72	2		*AIRBAG SENSOR (CONSISTENT)	Serviceable	1,160.00 FL	*- FL
73	1		*ELECTRIC POWER STEERING (CONSISTENT)	Serviceable	4,880.50 FL	*- FL
74	1		*FRONT CUSHION SEAT (RH) (CONSISTENT)	Bent	4,793.60 FS	*1,500.00 FS
75	1		*FRONT NUMBER PLATE (CONSISTENT) }	Distorted	25.00 FS	*40.00 FS
76	1		*FRONT NO PLATE TRIM COVER (CONSISTENT) }		30.00 FS	*- FS
77	1		*FRONT TYRE (LH) (80%) (CONSISTENT)	Punctured	216.00 FS	*172.80 FS
78	1		*FRONT WINDSCREEN SEALANT (CONSISTENT)	Necessary	46.00 FS	*46.00 FS
79	1		*BOOT LID (CONSISTENT)	Bent	1,681.40 FL	*1,681.40 FL
80	1		*BOOT LID RUBBER (CONSISTENT)	Distorted	115.80 FL	*115.80 FL
81	1		*BOOT LID LOCK UPPER (CONSISTENT)	Bent	137.90 FL	*137.90 FL
82	1		*BOOT LID LOCK LOWER (CONSISTENT)	Bent	31.70 FL	*31.70 FL
83	1		*BOOT LID H EMBLEM (CONSISTENT)	Necessary	27.20 FL	*27.20 FL
84	1		*BOOT LID CRDI PLATE (CONSISTENT)	Necessary	41.00 FL	*41.00 FL
85	2		*BOOT LID LAMP (LH/RH) (CONSISTENT)	Cracked	1,113.60 FL	*1,113.60 FL
86	2		*LICENCE LAMP (LH/RH) (CONSISTENT)	Cracked	67.90 FL	*67.90 FL
87	1		*BOOT LID TRIMBOARD (CONSISTENT)	Distorted	172.70 FL	*172.70 FL
88	11		*BOOT LID TRIMBOARD CLIPS (CONSISTENT)	Necessary	11.00 FL	*11.00 FL
89	1		*BOOTLID MOULDING (CONSISTENT)	Distorted	85.00 FL	*85.00 FL
90	1		*BOOTLID I40 EMBLEM (CONSISTENT)	Necessary	41.00 FL	*41.00 FL
91	1		*BOOTLID LOWER GARNISH (CONSISTENT)	Distorted	398.00 FL	*398.00 FL
92	1		*REAR BUMPER (CONSISTENT)	Deformed	33.96 FL	*33.96 FL
93	1		*REAR BUMPER REINFORCEMENT (CONSISTENT)	Bent	504.35 FL	*504.35 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
94	2		*REAR BUMPER REINFORCEMENT BRACKET (CONSISTENT)	Bent	360.00 FL	*360.00 FL
95	2		*REAR BUMPER SIDE BRACKET (CONSISTENT)	Distorted	98.00 FL	*98.00 FL
96	1		*REAR BUMPER SPONGE (CONSISTENT)	Torn	143.40 FL	*143.40 FL
97	1		*REAR BUMPER UNDER COVER (CONSISTENT)	Distorted	225.80 FL	*225.80 FL
98	1		*REAR BUMPER REFLECTOR LAMP (LH/RH) (CONSISTENT)	O/s Serviceable / N/s Cracked	64.00 FL	*32.00 FL
99	2		*TAIL LAMP (LH/RH) (CONSISTENT)	Cracked	1,131.20 FL	*1,131.20 FL
100	1		*TAIL LAMP QUARTER PANEL (LH/RH) (CONSISTENT)	N/s Bent / O/s Repair	195.80 FL	*97.90 FL
101	1		*REAR PANEL (CONSISTENT)	Bent	592.30 FL	*592.30 FL
102	1		*REAR PANEL GARNISH (CONSISTENT)	Distorted	57.70 FL	*57.70 FL
103	1		*REAR PANEL LOWER PANEL (CONSISTENT)	Bent	495.50 FL	*495.50 FL
104	1		*SPARE TYRE HOLDER (CONSISTENT)	Serviceable	143.40 FL	*- FL
105	1		*TAIL LAMP PANEL TOP (LH) (CONSISTENT)	Bent	545.90 FL	*545.90 FL
106	1		*SPARE TYRE PANEL (CONSISTENT)	Bent	900.50 FL	*900.50 FL
107	1		*SPARE TYRE PANEL CUSHION (CONSISTENT)	Serviceable	209.05 FL	*- FL
108	1		*REAR TOWING HOOK (CONSISTENT)	Serviceable	94.60 FL	*- FL
109	1		*MEMBER ASSY - REAR FLOOR CENTRE (CONSISTENT)	Repair	170.75 FL	*- FL
110	2		*EXHAUST PIPE INSULATOR (CONSISTENT)	Serviceable	117.10 FL	*- FL
111	2		*EXHAUST SILENCER (CONSISTENT)	Serviceable	1,908.00 FL	*- FL
112	1		*EXHAUST PIPE HANGER (CONSISTENT)	Serviceable	117.10 FL	*- FL
113	1		*EXHAUST PIPE CENTRE (CONSISTENT)	Serviceable	1,150.30 FL	*- FL
114	1		*REAR FENDER WITH HOUSING (LH) (CONSISTENT)	Bent	4,736.80 FL	*4,736.80 FL
115	1		*REAR FENDER INNER LINING (LH) (CONSISTENT)	Serviceable	164.40 FL	*- FL
116	1		*REAR FENDER AIR-DUCT (CONSISTENT)	Serviceable	225.60 FL	*- FL
117	1		*REAR FENDER TRIM BOARD (LH) (CONSISTENT)	Distorted	188.75 FL	*188.75 FL
118	1		*REAR WINDSCREEN GLASS (CONSISTENT)	Serviceable	985.50 FL	*- FL
119	1		*REAR WINDSCREEN MOULDING (CONSISTENT)	Necessary	62.15 FL	*62.15 FL
120	1		*BOOT LID COMFORT LOGO & TEL NO. STICKER (CONSISTENT)	Necessary	30.00 FS	*30.00 FS
121	1		*REAR NO. PLATE (CONSISTENT)	Distorted	25.00 FS	*25.00 FS
122	1		*REAR BUMPER REVERSE SENSOR (CONSISTENT)	Shorted	135.70 FS	*135.70 FS
123	1		*REAR WINDSCREEN SEALANT (CONSISTENT)	Necessary	46.00 FS	*46.00 FS
124	2		*FRT SAFETY BELT (ASSY) (LH/RH) (CONSISTENT)	Activated	1,145.30 FL	*1,145.30 FL
125	2		*FRT SEAT BELT ADJUSTER (LH/RH) (CONSISTENT)	Bent	971.20 FL	*971.20 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	90,113.81	65,609.76
- List Item Discount on L Items 20.00/20.00% (S\$)	16,953.30	12,722.85
Total Parts (S\$)	73,160.51	52,886.91

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING.	New	4,000.00	2,800.00
2	SPRAY PAINTING CHARGE.	New	2,200.00	1,920.00
3	WIRING CHARGE.	New	150.00	60.00
4	TUFF KOTE.	New	150.00	110.00
5	TOWING CHARGE.	New	50.00	50.00
6	REMOVE / REFIX UNDERCARRIAGE (FRT)	New	400.00	180.00
7	FRT WHEEL ALIGNMENT.	New	120.00	80.00
8	REMOVE / REFIX AIRCON & REFILL GAS.	New	150.00	100.00
9	REMOVE / REFIX GEARBOX.	New	450.00	350.00
10	REMOVE / REFIX DASHBOARD.	New	450.00	280.00
11	REMOVE / REFIX FUSE BOX.	New	180.00	120.00
12	REMOVE / REFIX FRONT WINDSCREEN GLASS.	New	120.00	100.00
13	REMOVE / REFIX CUSHION & UPHOLSTERY FRONT.	New	90.00	60.00
14	RE-PROGRAMME AIR BAG & SAFETY BELT SYSTEM.	New	550.00	350.00
15	REMOVE / REFIX CUSHION & UPHOLSTERY REAR.	New	150.00	80.00
16	REMOVE / REFIX REAR WINDSCREEN GLASS.	New	120.00	100.00
17	REMOVE / REFIX REVERSE SENSOR.	New	120.00	60.00
18	REMOVE / REFIX FUEL TANK.	New	150.00	0.00
19	REMOVE / REFIX EXHAUST PIPE.	New	150.00	100.00
Gross Labour Cost (S\$)			9,750.00	6,900.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >