

CC7/CTI1601 8248, K263

LKK:
IDAC:

P.S. CASE OWNER:

Surveyor:

Kenneth

DOI:

27/9/16

Date / Time:

27/9/16

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SJF 5973J

Name of Insured:

ZHANG CHUNHUA

Insured Tel No.:

HP: 97591848

Excess Sec II :S\$

D.O.A: 27/9/16

Is driver the owner?

(YES) / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

SNM160946301/3/4405

Policy No.:

DMP1SM114471605

Make / Model:

HONDA

Place of Accident:

91M AVE & BEYKANG LOR 1 THM

OI GIA REPORT (YES) / NO ; TP GIA REPORT (YES) / NO

Insured Liability: % Final ? Yes / No

SHDSSSLC



INSRS:
WSP:
Tel:
Liability:
RMKS:

Transcab



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date / Time	STAGE	DATE / PIC
27/9/16	SHDSSSLC	SJF 5973J - X
3/11/16	Rep. CCTV footage	
3/11/16	Called OI - No Response	
4/11/16	OI contacted. Confirmed accident details. Informed TP claim. OI disputed claim. Will send in CCTV footage.	
08/11/16	CCTV - Saved in VIC/SSP89A3 VIDEO Folder	
12-04-18	TO CHASE OI TO SUBMIT CCTV IN ORDER TO DETERMINE Responsible party SO AS TO PROCEED FURTHER.	
	TP beat the Traffic light.	
	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup)	
	After call ltr to OI:	
	Authorisation To Act:	
	Release Voucher:	
	Final Repair Bill:	
	Car Rental Invoice:	
	Towing Invoice:	
	LTA / GIA:	
	Medical Bill:	
	PIR:	
	Mandate/Reject Instruction:	
	LOD:	
	Payment Breakdown Form:	
	Post-Repair Photos:	
	Others:	

PRELIMINARY ADVICE Date/Time:		Sent By:		Reclaim Case	
FINALIZATION Date/Time:		Confirm with:		Approved by: Yuy	
Repair Cost:	S\$	() days	Reduction:	% 20/11/18	
FINAL SETTLEMENT Date/Time:		Confirm with:		Email ☐ Call ☐	
Final Liability:	% 50	(Agreed / Assessed) BOLA S/N No.:		If NO or B 28, Ass. Lia:	
Repair Cost:	S\$			Conflicting Versions	
Loss of Rental (LOR):	S\$	() days		COPY SENT	
Loss of Use (LOU):	S\$	(\$ x days)			
Loss of Income (LOI):	S\$	(\$ x days)			
LOR only ☐ LOU only ☐ LOR + LOU ☐ LOR + LOI ☐	[Tick only one]				
GIA/LTA Search	S\$			1) Claim status: Normal/Reject/Private Settle	
Medical:	S\$			2) Report Format:	
Disbursement:	S\$	(e.g. Tow/ Independent)		3) Survey fee: \$400.00	
Legal Cost	S\$				
Total:	S\$	Global Sum S\$:		Email ☐ Call ☐	
FINAL PAYMENT Date/Time:		Confirm with:			
Payee 1:	S\$	Name 1:			
Payee 2: (Strike if N.A.)	S\$	Name 2:			
Payee 3: (Strike if N.A.)	S\$	Name 3:			

ASS. REC. BY:

REF:

CAZ

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 18 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SHD5551C Yr Regn: 08, 10

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy Wsh C.C. 1987Colour White / Red A/C: Insured / Std / NI / NASp. Reading 890347 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTD GT20W405002526Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Falken

Front

R/Bal. 4 mmL/Bal. 4 mmD.O.A. 22/9/16

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
23/9	GIA & E11 not ready
28/9	Report to Corburn
	UNCONFIRMED COR U/S \$15,260.00
	CHECK ITEMS: \$16,269.14

Date/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

S + RS _____ \$

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$) _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD			Ref : CC3/CTI16018248/Kzb3	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909			Date : 28-09-2016	
			Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJF 5973J		Veh. Inspected	SHD 5551C
Policy No.			Coverage (\$)	0.00
Claim No.			Excess (\$)	0.00
Assign From			Assign Date	28/09/2016
2. Vehicle Particulars & Condition				
Make & Model			c.c	0
Engine No.	HIDDEN		Year of Reg.	
Chassis No.			Colour	
Odometer			Steering	
Brakes			Modification	
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	22/09/2016		Inspection Date	23/09/2016
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC3/CTH16018248/Kzb3

Date: 28.09.2016

The Motor Claims Department
M/s CHINA TAIPING INSURANCE (S) PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SHD5551C


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 23.09.2016 at the premises of M/s Trans-cab Auto Services Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	95,088.95
Revised Estimate Amount	: S\$	19,090.08
"Check" Items Amount	: S\$	16,269.14
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the Front Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 18 days

Yours faithfully,

KENNETH KONG
Licensed Appraiser

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO.6287 6666 FAX NO.6257 1330

CO/GST REG NO.201019626G

SHD 5551C - CHINA TAIPING**CANDY**

Not Authorized Done 22/10/10
11 Sep 08
Back Valve ??

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD 5551C - CANDY

JTDGJ20W405002526

TOYOTA

WISH 2.0 BI-FUEL

22.09.2016

CHINA TAIPING**PART****LIST**

1	1	Front Bumper	\$	<i>BL/CM</i> 585.36	—
2	1	Front Bumper Lower Absorber	\$	<i>ML</i> 130.00	—
3	1	Front Bumper Reinforcement	\$	<i>B</i> 318.11	—
4	1	Front Bumper Side Support LH	\$	<i>ML</i> 76.20	—
5	1	Front Bumper Side Support RH	\$	<i>ML</i> 76.20	—
6	1	Front Bumper Retainer RH	\$	<i>CM</i> 102.00	—
7	1	Front Bumper Retainer LH	\$	<i>CM</i> 102.00	—
8	1	Front Bumper Bracket RH	\$	<i>B</i> 108.00	—
9	1	Front Bumper Bracket LH	\$	<i>B</i> 108.00	—
10	1	Front Bumper Fog Lamp RH	\$	<i>ML</i> 208.00	—
11	1	Front Bumper Fog Lamp Outer Chrome RH	\$	<i>DL</i> 190.00	—
12	1	Front Bumper Fog Lamp Grille RH	\$	<i>DL</i> 150.00	—
13	1	Front Bumper Fog Lamp LH	\$	<i>ML</i> 208.00	—
14	1	Front Bumper Fog Lamp Outer Chrome LH	\$	<i>ML</i> 190.00	—
15	1	Front Bumper Fog Lamp Grille LH	\$	<i>ML</i> 150.00	—
16	1	Front Bumper Fog Lamp Protector Grille	\$	<i>ML</i> 100.00	—
17	1	Front Headlamp RH	\$	<i>BL</i> 672.00	—
18	1	Headlamp RH inner panel	\$	<i>NN</i> 732.00	X
19	1	Front Headlamp LH	\$	<i>BL</i> 672.00	—
20	1	Headlamp LH inner panel	\$	<i>NN</i> 732.00	X
21	1	Front Support Panel Assy	\$	<i>B</i> 1,222.32	—
22	1	Front Brace Panel	\$	<i>B</i> 95.49	—
23	1	Horn unit	\$	<i>DL</i> 125.00	—
24	1	Horn high pitch / low pitch	\$	<i>DL</i> 150.00	—
25	1	Bonnet	\$	<i>B</i> 1,019.16	—
26	1	Bonnet Under Weatherstrip Seal	\$	<i>GL</i> 71.99	—
27	1	Bonnet Hinge RH	\$	<i>B</i> 81.60	—
28	1	Bonnet Hinge LH	\$	<i>B</i> 81.60	—
29	1	Bonnet Moulding	\$	<i>NSP</i> 194.36	X
30	1	Bonnet Lock	\$	<i>B</i> 90.02	—
31	1	Bonnet Centre 'TOYOTA' Logo Badge	\$	<i>ML</i> 115.44	—
32	1	Bonnet Insulator	\$	<i>Q2671077</i> 524.06	<i>solon</i>
33	1	Bonnet Damper Stay	\$	<i>NSP</i> 239.05	X
34	1	Front Fender RH	\$	<i>BL</i> 837.60	—
35	1	Front Fender Liner RH	\$	<i>CM</i> 369.14	—
36	1	Front Fender Indicator Lamp RH	\$	<i>SLC</i> 95.80	X

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO.6287 6666 FAX NO.6257 1330

CO/GST REG NO.201019626G

SHD 5551C - CHINA TAIPING**CANDY**

37	1	Front Fender Inner Wheel House Panel RH	\$	B ₁	714.86	✓
38	1	Front Fender LH	\$	B ₁	369.14	✓
39	1	Front Fender Liner LH	\$	CM	369.14	✓
40	1	Front Fender Indicator Lamp LH	\$	S _u	95.80	X
41	1	Front Fender Inner Wheel House Panel LH	\$	B ₁	714.86	✓
42	1	Front Windscreen	\$	CM	1,406.64	✓
43	1	Front Windscreen Moulding	\$	ru	86.40	✓
44	1	Radiator Assembly	\$	B ₁	2,268.24	✓
45	1	Radiator Grille	\$	mi	462.48	✓
46	1	Radiator Fan Blade	\$	Di	223.95	✓
47	1	Aircon Fan Blade	\$	asp	223.95	X
48	1	Radiator Cowling	\$	CM	221.73	✓
49	1	Radiator Fan Motor	\$	tu	372.76	✓
50	1	Aircon Fan Motor	\$	asp	372.76	X
51	1	Radiator Expansion Tank	\$	mg CM	180.76	✓
52	1	Radiator Y - Pipe	\$	S _u	98.50	X
53	1	Aircon Condenser	\$	B ₁	1,375.50	✓
54	1	Aircon hose - condenser to compressor	\$		389.51	?
55	1	Aircon hose - compressor to evaporator	\$		521.93	?
56	1	Aircon hose - condenser to evaporator	\$		216.00	?
57	1	Aircon compressor - pump	\$		3,200.00	?
58	1	Windscreen Washer Tank - Filler Neck	\$	nd	120.76	✓
59	1	Windscreen Washer Tank	\$	nd	166.00	✓
60	1	Windscreen Washer Tank Motor	\$		266.86	?
61	1	Fuse Box Top (Cover)	\$		88.44	?
62	1	Fuse Box Lower	\$		84.24	?
63	1	Fuse Box Centre	\$		254.04	?
64	1	Fuse Box Centre Cover	\$		238.32	?
65	1	Engine Cover (Top)	\$	S _u	250.60	X
66	1	Intake Manifold	\$	S _u	1,500.08	X
67	1	Air Cleaner Assembly	\$		1,036.44	?
68	1	Air-Cleaner Intake Duct	\$	CM	101.57	✓
69	1	Air-cleaner intake hose	\$	CM	199.42	✓
70	1	V-belt	\$		146.40	?
71	1	Front shock absorber assy LH	\$		558.00	?
72	1	Front shock absorber top mounting LH	\$		159.16	?
73	1	Front shock absorber assy RH	\$		558.00	?
74	1	Front shock absorber top mounting RH	\$		159.16	?
75	1	Front lower arm RH	\$	S _u	620.57	X
76	1	Front lower arm LH	\$	S _u	620.57	X
77	1	Front knuckle arm RH	\$	B ₁	490.74	X
78	1	Front knuckle arm LH	\$	S _u	490.74	X
79	1	Steering rack & pinion assy	\$	S _u	3,167.33	X
80	1	Steering rack end	\$	S _u	246.50	X
81	1	Steering rack & pinion bushing	\$	S _u	30.00	X

TRANS-CAB AUTO SERVICES PTE LTD**CANDY**

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO.6287 6666 FAX NO.6257 1330

CO/GST REG NO.201019626G

SHD 5551C - CHINA TAIPING

82	1	Bracket-strg rack no 1 (s10/12)	\$	55.14 X
83	1	Bracket-strg rack no 2 (s10/12)	\$	37.42 X
84	1	Steering tie-rod end	\$	127.44 X
85	1	Power steering pump	\$	5,664.96 X
86	1	Power steering belt	\$	251.33 X
87	1	Power steering reservoir tank	\$	394.62 X
88	1	Power steering inlet / outlet pipe	\$	518.04 X
89	1	Power steering pump pulley	\$	235.68 X
90	1	Power steering hose - pressure	\$	361.68 X
91	1	Power steering hose - non pressure	\$	494.28 X
92	1	Engine block	\$	9,512.81 X
93	1	Engine main harness wire	\$	1,947.93 X
94	1	Engine splash cover RH	\$	178.20 —
95	1	Engine splash cover LH	\$	178.20 —
96	1	Engine oil sump	\$	350.04 X
97	1	Engine oil sump strainer	\$	115.68 X
98	1	ECU assy	\$	4,584.24 ?
99	1	ABS pump	\$	5,679.60 ?
100	1	ABS pump pipe	\$	82.08 X
101	1	Alternator assembly	\$	2,657.64 X
102	1	Gear box assy	\$	16,629.60 X
103	1	Gear box cross member	\$	1,454.28 ?
104	1	Gear box cross member Center	\$	539.76 ?
105	1	Gear box mountingRR	\$	349.68 ?
106	1	Gear box mounting FRT	\$	189.60 ?
107	1	Engine mounting side LH	\$	209.58 ?
108	1	Engine mounting RH	\$	254.28 ?
109	1	Front Seat Belt RH	\$	862.20 X
110	1	Front safety belt cover garnish RH	\$	253.68 X
111	1	Front Seat Belt tension RH	\$	126.01 X
112	1	Front Seat Belt LH	\$	862.20 X
113	1	Front safety belt cover garnish LH	\$	253.68 X
114	1	Front Seat Belt tension LH	\$	126.01 X
115	1	Battery	\$	240.00 50% @ 170% R
116	1	Battery fastener bracket	\$	37.26 X
117	1	Driver's seat	\$	1,454.28 X
118	1	Drivers seat reclining mechanism	\$	3,599.76 X
119	1	Longitudinal FRT LH	\$	556.33 X
120	1	Longitudinal FRT RH	\$	554.33 X
121	1	Front door LH	\$	1,554.00 X
122	1	Front side view mirror LH	\$	874.43 X
123	1	Front door RH	\$	1,554.00 X
124	1	Front side view mirror RH	\$	874.43 X

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO.6287 6666 FAX NO.6257 1330

CO/GST REG NO.201019626G

SHD 5551C - CHINA TAIPING**CANDY**

TOTAL	\$	103,197.74
25%	\$	25,799.44
	\$	77,398.30

Special Nett

1 Set Front Bumper Fastener Clip	\$	<i>Me</i> 40.00 —
1 CNG Sticker	\$	<i>Me</i> 30.00 <i>15sn</i>
1 Set Front Fender Liner Clip LH	\$	<i>Me</i> 30.00 —
1 Set Front Fender Liner Clip RH	\$	<i>Me</i> 30.00 —
2 Bonnet Stopper	\$	<i>Me</i> 9.60 —
1 Set Bonnet Under Weatherstrip Seal Clips	\$	<i>Me</i> 21.60 —
1 Set Bonnet Insulator Clip	\$	<i>Me</i> 42.00 —
1 Set Bonnet Damper Stay Clip	\$	<i>nn</i> 10.00 X
1 Set Horn High pitch / Low Pitch	\$	<i>Replaced</i> 100.00 X
1 Set Front Wiper Garnish / Wiper Grille Clips	\$	<i>nn</i> 18.50 X
1 Set Front Wiper Clip	\$	<i>nn</i> 10.68 X
1 Set Radiator Grille Clip	\$	<i>Me</i> 18.00 —
2 Can Radiator Coolant	\$	<i>Me</i> 40.00 <i>20sn</i>
2 Radiator Top Bracket Mounting	\$	<i>R</i> 33.84 X
2 Radiator Lower Mounting Bushing	\$	<i>R</i> 18.43 X
1 Front Licence Plate	\$	<i>Mis</i> 50.00 <i>25sn</i>
1 Front Door Sticker 'Trans-Cab' LH	\$	<i>nn</i> 60.00 X
1 Front Door Sticker 'Trans-Cab' RH	\$	<i>nn</i> 60.00 X
1 Set Front Side Rocker Panel Garnish Clips	\$	<i>nn</i> 18.00 X
1 Front Windscreen Sealant	\$	<i>Me</i> 80.00 <i>40sn</i>
1 Front Windscreen Inner Sponge Seal	\$	<i>Me</i> 60.00 <i>30sn</i>
1 Front ERP Bracket	\$	<i>Me</i> 50.00 <i>26sn</i>
1 Front ERP Unit	\$	<i>Sn</i> 200.00 X
2 ERP Sticker	\$	<i>Me</i> 10.00 —
1 Air Filter	\$	36.00 ?
1 Set Engine splash cover clip RH	\$	<i>Me</i> 12.00 —
1 Set Engine splash cover clip LH	\$	<i>Me</i> 12.00 —
1 Front tyre LH	\$	<i>Sn</i> 190.00 X
1 Front wheel rim LH	\$	<i>Sn</i> 150.00 X
1 Front tyre RH	\$	<i>Sn</i> 190.00 X
1 Front wheel rim RH	\$	<i>Sn</i> 150.00 X

TOTAL	\$	1,780.65
TOTAL PARTS	\$	79,178.95

Panel Beating, Knocking And Straightening The
Necessary Portion, Remove And Renewal Of
Parts, Adjust And Realign The Same @

\$ 5,400.00 *200d*

To Check Electrical Lighting Concerned.

\$ 120.00 *40d*

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO.6287 6666 FAX NO.6257 1330

CO/GST REG NO.201019626G

SHD 5551C - CHINA TAIPING**CANDY**

To Rust-Proofing Of The Affected Areas.	\$	200.00	180/
Putty And Spray Painting Of The Affected	\$	5,350.00	1400/
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00	250/
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	380.00	280/
To remove and renew engine and gear box mounting.	\$	380.00	250/
To dismantle and refit engine cross-member and engine mounting.	\$	380.00	?
To lift-up engine with gear box and refit.	\$	440.00	Repair X
To remove and renew power steering pump, oil cooler pipe and final checking and testing.	\$	440.00	nn X
To check ABS brake efficiency, final checking and testing.	\$	380.00	} 80/
To remove and refit ABS pump relay to enable repair.	\$	380.00	
To Check Steering Geometry And Computer Wheel Alignment.	\$	200.00	60/
To Transfer Of Tire, Rim And On Wheel	\$	150.00	nn X
Towing Fees.	\$	120.00	50/
To Vacuum, Replace, Refix And Recharge Air Condenser	\$	350.00	100/
To Transfer Of Door Fittings, Attachments And Perform Water Seepage Test.	\$	170.00	nn X
To Replace, Refix And Top Up Coolant For Radiator	\$	170.00	50/
To Dismantle And Refit Aircon Assy And Attachment, Vacuum And Charge-In-Gas.	\$	350.00	Repair X

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO.6287 6666 FAX NO.6257 1330

CO/GST REG NO.201019626G

SHD 5551C - CHINA TAIPING**CANDY**

To Transfer Of Fender Fittings, Attachments
And Perform Water Seepage Test.

\$ *nn* 170.00 *X*

TOTAL \$ 15,910.00

Over All Total \$ 95,088.95

Total Repair Days *30 DAYS*

18 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Shu Pei (LKKAUTO)

From: Angie Foo <angie.foo@sg.cntaiping.com>
Sent: Thursday, 29 September, 2016 10:04 AM
To: Shu Pei (LKKAUTO)
Cc: Alfred Toh; KKLau; Admin A; Zayyer (LKKAUTO); Hsiao Tong (LKKAUTO); Vivian Lau (LKKAUTO); Chee So Chow
Subject: RE: Direct Settlement - Accident Involving SJF5973J (OI : CTI - TBA) and SHD5551C (TP : LKK REF -CC3/CTI16018248/Kzb3) on 22.09.2016
Attachments: SNM16D04463C02 20160929 INSURED SAS REPORT SJF5973J.pdf; SNM16D04463C02 20160929 To Insured -LKK Assignment Ltr.pdf

OUR REF: SNM16D04463C02/3/LKKDS
YR REF: (TP : LKK REF -CC3/CTI16018248/Kzb3)

Dear Shu Pei/Zayyer,

We refer to your email of 28th September 2016.

We attached our Insured's SAS Report and Assignment Letter for your necessary action.

Please take note our Insured had reported TAXI driver beat red light, request video from our Insured and from Trans-Cab.

Thank you.

Regards,
Angie Foo
Executive
Motor Division
Claims Department
China Taiping Insurance (Singapore) Pte Ltd
3 Anson Road #16-00
Springleaf Tower
Singapore 079909
Co.Reg.No.200208384E
DID: 6389 6186
Fax: 6224 7478 /6224 7175
Email: angie.foo@sg.cntaiping.com
Email: claimsdept@sg.cntaiping.com
Website: www.sg.cntaiping.com

Disclaimer:

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Shu Pei (LKKAUTO) [<mailto:shupeil@lkkauto.com>]
Sent: Wednesday, 28 September, 2016 3:32 PM
To: Claims Dept of CTI
Cc: Alfred Toh; Hwang Shiang Yi; Angie Foo; KKLau; Admin A; Zayyer (LKKAUTO); Hsiao Tong (LKKAUTO); Vivian Lau (LKKAUTO)

Subject: Direct Settlement - Accident Involving SJF5973J (OI : CTI - TBA) and SHD5551C (TP : LKK REF - CC3/CTI16018248/Kzb3) on 22.09.2016

WITHOUT PREJUDICE

Dear Angie,

We refer to the above matter.

This is a TP direct settlement case.

We had inspected TP vehicle SHD 5551C at M/s Trans-cab Auto Services Pte Ltd - Ang Mo Kio.

Enclosed for your perusal is:

- TP GIA report
- Police report
- TP estimated cost of repair
- Preliminary advice

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Zayyer and he can be contacted at DID: 6841 2409.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupej@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>



中国太平
CHINA TAIPING

中国太平保险(新加坡)有限公司

CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

3 Anson Road #16-00 Springleaf Tower Singapore 079909

Tel: 6389 6111 Fax: 6222 1033

Website: www.sg.cntaiping.com

Co. Reg. No. 200208384E

Our Reference: **SNM16D04463/C01/3**

Date : **29 SEPTEMBER 2016**

via Ordinary & Registered Mail

**ZHANG CHUNHUA
BLK 220B BEDOK CENTRAL
#06-42
SINGAPORE 462220**

Dear Sir / Madam

**ACCIDENT INVOLVING SJF5973J AND SHD5551C ON 22 SEPTEMBER 2016
ALONG SIM AVE & GEYLANG LORONG 1 JUNCTION**

We refer to the abovementioned accident.

Please be advised that the third party vehicle, **SHD5551C**, is filing a third party property claim against your vehicle.

We have appointed **LKK Auto Consultants Pte Ltd**, to administer the said claim on our behalf and they will contact you for more information about the accident.

Kindly render your assistance and co-operation accordingly.

Yours truly,

Claims Department

(This is a computer generated letter and no signature is required.)

CC : LKK Auto Consultants Pte Ltd

Attn : ZAYYER

Ref : CC3/CT116018248/KZB3)

Contact No : 6841 2409

via Email : zayyer@lkkauto.com

CC : Agent - (BR0075A) - FINEXIS ADVISORY PTE LTD

F01/LKKDS-2013

Vasanthi Rengiyan (LKKAUTO)

To: ZCHA001@YAHOO.COM
Cc: Vic (LKKAUTO); Zayyer (LKKAUTO); Vasanthi Rengiyan (LKKAUTO)
Subject: YOUR REF : SJF 5973J _ACCIDENT INVOLVING SJF 5973 AND SHD 5551C ON 22/09/2016

Our Ref: CC3/CTI16018248/Kzb3

04 NOVEMBER 2016

ZHANG CHUNHUA
220B BEDOK CENTRAL
#06-42
SINGAPORE 462220

Dear Sir/Madam,

ACCIDENT INVOLVING SJF 5973 AND SHD 5551C ON 22/09/2016

We refer to the above accident where we are acting for China Taiping Insurance (Singapore) Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Kindly note that we have reviewed this matter and would like to advise that you and/or your authorized driver may not be absolved from blame for this accident.

If you have evidence/information to prove that we should not settle the third party claim, kindly let us have them in writing within the next 10 days i.e. by **14/11/2016**, after we shall proceed with negotiation with Third Party claimant on the **without prejudice basis** and any settlement should not bind any claims whatsoever by you/your driver against the other party's insurer arising from this particular accident.

Please call us if you have further queries.

Best Regards,

R.Vasanthi (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2132 | email: Vasanthi@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC3/CTI16018248/Kjb3s2

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 12-12-2018



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJF 5973J	Veh. Inspected	SHD 5551C
Policy No.	DMPCSN1114471605	Coverage (\$)	0.00
Claim No.	SNM16D04463C02/3	Excess (\$)	0.00
Assign From		Assign Date	23/09/2016

2. Vehicle Particulars & Condition

Make & Model	TOYOTA WISH (A)	c.c	1987
Engine No.	HIDDEN	Year of Reg.	2010
Chassis No.	JTDGJ20W405002526	Colour	WHITE / RED
Odometer	890347	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65R15	FALKEN	4 mm
L/H Front Tyre	195/65R15	FALKEN	4 mm
R/H Rear Tyre	195/65R15	FALKEN	7 mm
L/H Rear Tyre	195/65R15	FALKEN	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	22/09/2016	Inspection Date	23/09/2016
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	18 Working Days
-------------------------------------	-----------------

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 7

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 5551C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	BENT / CRACKED	585.36	585.36
1	FRONT BUMPER LOWER ABSORBER	MISSING	130.00	130.00
1	FRONT BUMPER REINFORCEMENT	BENT	318.11	318.11
1	FRONT BUMPER SIDE SUPPORT LH	MISSING	76.20	76.20
1	FRONT BUMPER SIDE SUPPORT RH	MISSING	76.20	76.20
1	FRONT BUMPER RETAINER RH	CRACKED	102.00	102.00
1	FRONT BUMPER RETAINER LH	CRACKED	102.00	102.00
1	FRONT BUMPER BRACKET RH	BENT	108.00	108.00
1	FRONT BUMPER BRACKET LH	BENT	108.00	108.00
1	FRONT BUMPER FOG LAMP RH	MISSING	208.00	208.00
1	FRONT BUMPER FOG LAMP OUTER CHROME RH	DISTORTED	190.00	190.00
1	FRONT BUMPER FOG LAMP GRILLE RH	DISTORTED	150.00	150.00
1	FRONT BUMPER FOG LAMP LH	MISSING	208.00	208.00
1	FRONT BUMPER FOG LAMP OUTER CHROME LH	MISSING	190.00	190.00
1	FRONT BUMPER FOG LAMP GRILLE LH	MISSING	150.00	150.00
1	FRONT BUMPER FOG LAMP PROTECTOR GRILLE	MISSING	100.00	100.00
1	FRONT HEADLAMP RH	BROKEN	672.00	672.00
1	HEADLAMP RH INNER PANEL	NOT NECESSARY	732.00	-
1	FRONT HEADLAMP LH	BROKEN	672.00	672.00
1	HEADLAMP LH INNER PANEL	NOT NECESSARY	732.00	-
1	FRONT SUPPORT PANEL ASSY	BENT	1,222.32	1,222.32
1	FRONT BRACE PANEL	BENT	95.49	95.49
1	HORN UNIT	DENTED	125.00	125.00
1	HORN HIGH PITCH / LOW PITCH	DENTED	150.00	150.00
1	BONNET	BENT	1,019.16	1,019.16
1	BONNET UNDER WEATHERSTRIP SEAL	CUT	71.99	71.99
1	BONNET HINGE RH	BENT	81.60	81.60
1	BONNET HINGE LH	BENT	81.60	81.60
1	BONNET MOULDING	NO SUCH PARTS	194.36	-
1	BONNET LOCK	BENT	90.02	90.02
1	BONNET CENTRE 'TOYOTA' LOGO BADGE	NECESSARY	115.44	115.44

Report Ref No. CC3/CTI16018248/Kjb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 7

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BONNET DAMPER STAY	NO SUCH PARTS	239.05	-
1	FRONT FENDER RH	BUCKLED	837.60	837.60
1	FRONT FENDER LINER RH	CRACKED	369.14	369.14
1	FRONT FENDER INDICATOR LAMP RH	SERVICEABLE	95.80	-
1	FRONT FENDER INNER WHEEL HOUSE PANEL RH	BENT	714.86	714.86
1	FRONT FENDER LH	BENT	369.14	369.14
1	FRONT FENDER LINER LH	CRACKED	369.14	369.14
1	FRONT FENDER INDICATOR LAMP LH	SERVICEABLE	95.80	-
1	FRONT FENDER INNER WHEEL HOUSE PANEL LH	BENT	714.86	714.86
1	FRONT WINDSCREEN	CRACKED	1,406.64	1,406.64
1	FRONT WINDSCREEN MOULDING	NECESSARY	86.40	86.40
1	RADIATOR ASSEMBLY	BROKEN	2,268.24	2,268.24
1	RADIATOR GRILLE	MISSING	462.48	462.48
1	RADIATOR FAN BLADE	DISTORTED	223.95	223.95
1	AIRCON FAN BLADE	NO SUCH PARTS	223.95	-
1	RADIATOR COWLING	CRACKED	221.73	221.73
1	RADIATOR FAN MOTOR	JAMMED	372.76	372.76
1	AIRCON FAN MOTOR	NO SUCH PARTS	372.76	-
1	RADIATOR EXPANSION TANK	MTG CRACKED	180.76	180.76
1	RADIATOR Y - PIPE	SERVICEABLE	98.50	-
1	AIRCON CONDENSER	BENT	1,375.50	1,375.50
1	AIRCON HOSE - CONDENSER TO COMPRESSOR	* CHECK	389.51	-
1	AIRCON HOSE - COMPRESSOR TO EVAPORATOR	* CHECK	521.93	-
1	AIRCON HOSE - CONDENSER TO EVAPORATOR	* CHECK	216.00	-
1	AIRCON COMPRESSOR - PUMP	* CHECK	3,200.00	-
1	WINDSCREEN WASHER TANK - FILLER NECK	DENTED	120.76	120.76
1	WINDSCREEN WASHER TANK	DENTED	166.00	166.00
1	WINDSCREEN WASHER TANK MOTOR	* CHECK	266.86	-
1	FUSE BOX TOP (COVER)	* CHECK	88.44	-
1	FUSE BOX LOWER	* CHECK	84.24	-
1	FUSE BOX CENTRE	* CHECK	254.04	-
1	FUSE BOX CENTRE COVER	* CHECK	238.32	-
1	ENGINE COVER (TOP)	SERVICEABLE	250.60	-

Report Ref No. CC3/CTI16018248/Kjb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 7

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	INTAKE MANIFOLD	SERVICEABLE	1,500.08	-
1	AIR CLEANER ASSEMBLY	* CHECK	1,036.44	-
1	AIR-CLEANER INTAKE DUCT	CRACKED	101.57	101.57
1	AIR-CLEANER INTAKE HOSE	CRACKED	199.42	199.42
1	V-BELT	* CHECK	146.40	-
1	FRONT SHOCK ABSORBER ASSY LH	* CHECK	558.00	-
1	FRONT SHOCK ABSORBER TOP MOUNTING LH	* CHECK	159.16	-
1	FRONT SHOCK ABSORBER ASSY RH	* CHECK	558.00	-
1	FRONT SHOCK ABSORBER TOP MOUNTING RH	* CHECK	159.16	-
1	FRONT LOWER ARM RH	SERVICEABLE	620.57	-
1	FRONT LOWER ARM LH	SERVICEABLE	620.57	-
1	FRONT KNUCKLE ARM RH	SERVICEABLE	490.74	-
1	FRONT KNUCKLE ARM LH	SERVICEABLE	490.74	-
1	STEERING RACK & PINION ASSY	SERVICEABLE	3,167.33	-
1	STEERING RACK END	SERVICEABLE	246.50	-
1	STEERING RACK & PINION BUSHING	SERVICEABLE	30.00	-
1	BRACKET-STRG RACK NO 1 (S10/12)	SERVICEABLE	55.14	-
1	BRACKET-STRG RACK NO 2 (S10/12)	SERVICEABLE	37.42	-
1	STEERING TIE-ROD END	SERVICEABLE	127.44	-
1	POWER STEERING PUMP	NO SUCH PARTS	5,664.96	-
1	POWER STEERING BELT	NO SUCH PARTS	251.33	-
1	POWER STEERING RESERVOIR TANK	NO SUCH PARTS	394.62	-
1	POWER STEERING INLET / OULET PIPE	NO SUCH PARTS	518.04	-
1	POWER STEERING PUMP PULLEY	NO SUCH PARTS	235.68	-
1	POWER STEERING HOSE - PRESSURE	NO SUCH PARTS	361.68	-
1	POWER STEERING HOSE - NON PRESSURE	NO SUCH PARTS	494.28	-
1	ENGINE BLOCK	SERVICEABLE	9,512.81	-
1	ENGINE MAIN HARNESS WIRE	TO REPAIR SEE LABOUR	1,947.93	-
1	ENGINE SPLASH COVER RH	CRACKED	178.20	178.20
1	ENGINE SPLASH COVER LH	CRACKED	178.20	178.20
1	ENGINE OIL SUMP	SERVICEABLE	350.04	-
1	ENGINE OIL SUMP STRAINER	SERVICEABLE	115.68	-

Report Ref No. CC3/CTI16018248/Kjb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 7

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	ECU ASSY	* CHECK	4,584.24	-
1	ABS PUMP	* CHECK	5,679.60	-
1	ABS PUMP PIPE	SERVICEABLE	82.08	-
1	ALTERNATOR ASSEMBLY	SERVICEABLE	2,657.64	-
1	GEAR BOX ASSY	SERVICEABLE	16,629.60	-
1	GEAR BOX CROSS MEMBER	* CHECK	1,454.28	-
1	GEAR BOX CROSS MEMBER CENTER	* CHECK	539.76	-
1	GEAR BOX MOUNTING RR	* CHECK	349.68	-
1	GEAR BOX MOUNTING FRT	* CHECK	189.60	-
1	ENGINE MOUNTING SIDE LH	* CHECK	209.58	-
1	ENGINE MOUNTING RH	* CHECK	254.28	-
1	FRONT SEAT BELT RH	SERVICEABLE	862.20	-
1	FRONT SAFETY BELT COVER GARNISH RH	SERVICEABLE	253.68	-
1	FRONTSEAT BELT TENSION RH	SERVICEABLE	126.01	-
1	FRONT SEAT BELT LH	SERVICEABLE	862.20	-
1	FRONT SAFETY BELT COVER GARNISH LH	SERVICEABLE	253.68	-
1	FRONT SEAT BELT TENSION LH	SERVICEABLE	126.01	-
1	BATTERY FASTENER BRACKET	TO REPAIR SEE LABOUR	37.26	-
1	DRIVER'S SEAT	TO REPAIR SEE LABOUR	1,454.28	-
1	DRIVERS SEAT RECLINING MECHANISM	TO REPAIR SEE LABOUR	3,599.76	-
1	LONGITUDINAL FRT LH	SERVICEABLE	556.33	-
1	LONGITUDINAL FRT RH	SERVICEABLE	554.33	-
1	FRONT DOOR LH	TO REPAIR SEE LABOUR	1,554.00	-
1	FRONT SIDE VIEW MIRROR LH	SERVICEABLE	874.43	-
1	FRONT DOOR RH	TO REPAIR SEE LABOUR	1,554.00	-
1	FRONT SIDE VIEW MIRROR RH	SERVICEABLE	874.43	-
	LESS 25% DISCOUNT		-25,608.42	-4,528.96
			76,825.26	13,586.88

Report Ref No. CC3/CTI16018248/Kjb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:5 of 7

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BONNET INSULATOR (50%) (SN)	TORN	524.06	262.03
1	BATTERY (50%) (SN)	DENTED	240.00	120.00
	LESS 25% DISCOUNT		-191.02	-
			573.04	382.03
	SPECIAL NETT ITEMS			
1	SET FRONT BUMPER FASTENER CLIP (SN)	NECESSARY	40.00	40.00
1	CNG STICKER (SN)	NECESSARY	30.00	15.00
1	SET FRONT FENDER LINER CLIP LH (SN)	NECESSARY	30.00	30.00
1	SET FRONT FENDER LINER CLIP RH (SN)	NECESSARY	30.00	30.00
2	BONNET STOPPER (SN)	NECESSARY	9.60	9.60
1	SET BONNET UNDER WEATHERSTRIP SEAL CLIP (SN)	NECESSARY	21.60	21.60
1	SET BONNET INSULATOR CLIP (SN)	NECESSARY	42.00	42.00
1	SET BONNET DAMPER STAY CLIP (SN)	NOT NECESSARY	10.00	-
1	SET HORN HIGH PITCH / LOW PITCH (SN)	REPEATED	100.00	-
1	SET FRONT WIPER GARNISH / WIPER GRILLE CLIPS (SN)	NOT NECESSARY	18.50	-
1	SET FRONT WIPER CLIP (SN)	NOT NECESSARY	10.68	-
1	SET RADIATOR GRILLE CLIP (SN)	NECESSARY	18.00	18.00
2	CAN RADIATOR COOLANT (SN)	NECESSARY	40.00	20.00
2	RADIATOR TOP BRACKET MOUNTING (SN)	TO REPAIR SEE LABOUR	33.84	-
2	RADIATOR LOWER MOUNTING BUSHING (SN)	TO REPAIR SEE LABOUR	18.43	-
1	FRONT LICENCE PLATE (SN)	MISSING	50.00	25.00
1	FRONT DOOR STICKER 'TRANS-CAB' LH (SN)	NOT NECESSARY	60.00	-
1	FRONT DOOR STICKER 'TRANS-CAB' RH (SN)	NOT NECESSARY	60.00	-
1	SET FRONT SIDE ROCKER PANEL GARNISH CLIPS (SN)	NOT NECESSARY	18.00	-
1	FRONT WINDSCREEN SEALANT (SN)	NECESSARY	80.00	40.00
1	FRONT WINDSCREEN INNER SPONGE SEAL (SN)	NECESSARY	60.00	30.00
1	FRONT ERP BRACKET (SN)	NECESSARY	50.00	26.00
1	FRONT ERP UNIT (SN)	SERVICEABLE	200.00	-
2	ERP STICKER (SN)	NECESSARY	10.00	10.00
1	AIR FILTER (SN)	* CHECK	36.00	-

Report Ref No. CC3/CTI16018248/Kjb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:6 of 7

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET ENGINE SPLASH COVER CLIP RH (SN)	NECESSARY	12.00	12.00
1	SET ENGINE SPLASH COVER CLIP LH (SN)	NECESSARY	12.00	12.00
1	FRONT TYRE LH (SN)	SERVICEABLE	190.00	-
1	FRONT WHEEL RIM LH (SN)	SERVICEABLE	150.00	-
1	FRONT TYRE RH (SN)	SERVICEABLE	190.00	-
1	FRONT WHEEL RIM RH (SN)	SERVICEABLE	150.00	-
			1,780.65	381.20
	LABOUR			
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME, INCLUSIVE OF THE REPAIR OF ENGINE MAIN HARNESS WIRE, BATTERY FASTENER BRACKET, DRIVER'S SEAT, DRIVERS SEAT RECLINING MECHANISM, FRONT DOOR LH, FRONT DOOR RH, RADIATOR TOP BRACKET MOUNTING AND RADIATOR LOWER MOUNTING BUSHING.		5,400.00	2,000.00
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		120.00	40.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		200.00	180.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED.		5,350.00	1,400.00
	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH, TO FACILITATE REPAIR.		380.00	250.00
	TO DISMANTLE AND REFIT FRONT END SUSPENSION, UNDERCARRIAGE PARTS, FINAL CHECKING AND TESTING.		380.00	280.00
	TO REMOVE AND RENEW ENGINE AND GEAR BOX MOUNTING.		380.00	250.00
	TO DISMANTLE AND REFIT ENGINE CROSS-MEMBER AND ENGINE MOUNTING.	* CHECK	380.00	-
	TO LIFT-UP ENGINE WITH GEAR BOX AND REFIT.	REPEATED	440.00	-
	TO REMOVE AND RENEW POWER STEERING PUMP, OIL COOLER PIPE AND FINAL CHECKING AND TESTING.	NOT NECESSARY	440.00	-
	TO CHECK ABS BRACKE EFFICIENCY, FINAL CHECKING AND TESTING. }		380.00	80.00
	TO REMOVE AND REFIT ABS PUMP RELAY TO ENABLE REPAIR. }		380.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.		200.00	60.00

Report Ref No. CC3/CT116018248/Kjb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:7 of 7

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO TRANSFER OF TIRE, RIM AND ON WHEEL.	NOT NECESSARY	150.00	-
	TOWING FEES.		120.00	50.00
	TO VACUUM, REPLACE, REFIX AND RECHARGE AIR CONDENSER.		350.00	100.00
	TO TRANSFER OF DOOR FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO REPLACE, REFIX AND TOP UP COOLANT FOR RADIATOR.		170.00	50.00
	TO DISMANTLE AND REFIT AIRCON ASSY AND ATTACHMENT, VACUUM AND CHARGE-IN-GAS.	REPEATED	350.00	-
	TO TRANSFER OF FENDER FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
			15,910.00	4,740.00
GRAND TOTAL			95,088.95	19,090.11

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS S\$16,269.14NETT) (UNCONFIRMED)				15,250.00
--	--	--	--	-----------

Report Ref No. CC3/CT116018248/Kjb3s2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.