



Pte Ltd

Teamwork Garage Pte Ltd
53 Ubi Avenue 1 #01-23/24 Spore 408934
Paya Ubi Industrial Park
Tel : 6844 2475 Fax : 6844 2474
E-mail : claims@teamworkgarage.com
ROC number : 201015366H

~~QBE Insurance (International) Limited~~
~~60 Anson Road~~
~~#11-01 Mapletree~~
~~Singapore 079914~~

3RD PARTY CLAIM ESTIMATION

Vehicle number : SKJ9849B
Make / Model : Jaguar XJ
Chassis number : SAJAC0564DDS87089
Accident date : 04 October 2016
Reference : 1610-05

Qty	Particulars	Unit Price - SGD \$
<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1	Rear bumper <i>cut</i>	2268.90 ✓
1	Rear bumper under cover <i>cut</i>	890.30 ✓
1	Rear tow cover <i>NF</i>	173.80 X
1	Rear bumper bracket <i>broken</i>	250.20 ✓
1	Rear bumper retainer <i>crack N/S</i>	140.80 ✓
1	Rear bootlid <i>sign</i>	2063.45 X
1	Rear boot rubber <i>N/C</i>	371.20 ✓
1	Rear bootlid lock <i>SVC</i>	465.90 X
2	Rear bootlid hinge @ \$90.20 <i>NH</i>	180.40 X
1	Rear bootlid logo <i>N/C</i>	201.65 ✓
1	Rear bootlid logo 'XF' <i>N/C</i>	170.62 ✓
2	Rear bootlid lamp <i>NH</i>	1389.40 X
1	Rear bootlid chrome <i>NH</i>	378.20 X
1	Rear lock sensor <i>broken</i>	470.00 ✓
1	Rear bumper reinforcement <i>Dentail</i>	795.50 ✓
1	Rear bumper sponge <i>NF</i>	398.30 X
1	Rear bumper moulding <i>NF</i>	378.90 X
1	Rear bumper center garnish <i>NH</i>	548.89 X
1	Rear spare tyre compartment cover <i>NH</i>	320.00 X
1	Rear bumper reflector <i>NF</i>	420.20 X
1	Rear bumper parking sensor <i>Dem</i>	941.60 ✓
1	Rear bumper parking sensor holder <i>N/C</i>	268.00 ✓
1	Rear end panel <i>Dentail</i>	1498.00 ✓
1	Rear end panel top garnish <i>SVC</i>	432.70 X
1	Rear taillamp <i>NH</i>	2289.40 X
1	Rear bootlid insulator <i>NH</i>	278.90 X
1	Rear fender inner trim <i>NH</i>	880.40 X
1	Rear exhaust pipe <i>NH</i>	2870.65 ✓
Subtotal		21736.26
Balance C/F		21736.26

Vehicle number : SKJ9849B

Make / Model : Jaguar XJ

Reference : 1610-05

Qty Particulars		Unit Price - SGD \$
<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>		
	Balance B/F	21736.26
1	Rear bumper clips <i>nlc</i>	80.00 30/-
1	Bootlid insulator clips <i>src</i>	60.00 x
1	Rear fender inner trim clips <i>nl</i>	60.00 x
1	Joint sealant <i>nlc</i>	120.00 40/-
1	Reverse camera <i>Dan</i>	400.00 300/-
	Subtotal	720.00
	Balance C/F	22456.26
<u>LABOUR AND MISCELLANEOUS CHARGES</u>		
S/No	Balance B/F	22456.26
1	Check front and rear wiring and lighting system	150.00 <i>nl</i>
2	Remove and refit rear lining, garnish and trim for repair	250.00 100/-
3	Remove and renew rear reverse sensor	150.00 40/-
4	Diagnosis, check and clear fault code	250.00 <i>nl</i>
5	Transfer parts, attachment from old bootlid to new	200.00 <i>nl</i>
6	Remove and renew rear exhaust pipe	200.00 60/-
7	Panel beating on affected area	1500.00 800/-
8	Spray painting on affected area	1500.00 700/-
9	Apply anti rust on affected area	150.00 40/-
	Subtotal	4350.00
	Grand total	26806.26
11/10/2016 @ 1200h <i>nlc Andrew</i> <i>2/5m</i> <i>Bygn 5 dgs.</i> <i>2 KIC And</i> <i>8</i>		check part prices. Photo given <i>nlc</i>