

Surveyor: KANNTA DOI: 12/10/16 Date/Time: 12/10/16

Pre-assign / CCU / FTE



Insured Vehicle No. : SKK 5879K
 Name of Insured : Lim Wei Yong (Lim Weirong)
 Insured Tel No. : HP: 93630377
 Excess Sec II :SS D.O.A: 13/10/16

Claim No. : _____
 Policy No. : Dmpcsw304921600
 Make / Model : Mitsubishi A200
 Place of Accident : ECR (Haruh)

Is driver the owner? (YES / NO) Nature of Accident : _____
 If NO, Driver Name / Age : _____ OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO
 Driver Tel No. : _____ (V/L: YES / NO) Insured Liability : _____ % Final ? Yes / No



INSRS:
WSP: Trans. Cab
Tel :
Liability :
RMKS:



INSRS:
WSP:
Tel :
Liability :
RMKS:



INSRS:
WSP:
Tel :
Liability :
RMKS:



INSRS:
WSP:
Tel :
Liability :
RMKS:

Date/Time	STAGE	DATE / PIC
<u>11/11/16</u> <u>CH</u>	Non-Reporting ltr (1st): Non-Reporting ltr (2nd): Non-Reporting ltr (Final): Notification ltr (if non-pickup): Cal. C.I. <u>M/S galery 14/11/16.</u> After call ltr to OI:	
<u>14/11/16 @ 10.55am</u>	called OI, Ms Lim. Confirm 7cc. OI wear the 5th car. Inform TP claim. Agreed to settle & aware NRS issue.	
<u>9/5/19</u>	BTM	
<u>2/10/19</u>	File → type mandae	

PRELIMINARY ADVICE	Date/Time:	Sent By:	Confirm by: <u>KSC</u>
FINALIZATION	Date/Time:	Confirm with:	Confirm by: <u>KSC</u>
Repair Cost: <u>46</u> SS <u>15,600</u>	(<u>21</u> days) Reduction: <u>78</u> %	Email <input checked="" type="checkbox"/> Call <input type="checkbox"/>	
FINAL SETTLEMENT	Date/Time: <u>25.03.20</u>	Confirm with: <u>Wai Yin</u>	Email <input type="checkbox"/> Call <input type="checkbox"/>
Final Liability: % <u>100</u>	(Agreed / Assessed) BOLA S/N No. : <u>20(j)</u>	If NO or B 28, Ass. Lia : <u>01.</u>	
Repair Cost: <u>W/L 51</u> SS <u>16,692.00</u>			
Loss of Rental (LOR): SS <u>2,713.44</u>	(<u>21</u> days) x <u>102.12</u>		
Loss of Use (LOU): SS <u>-</u>	(\$ x <u>-</u> days)		
Loss of Income (LOI): SS <u>1,350.00</u>	(\$ <u>50</u> x <u>27</u> days)		
LOR only <input type="checkbox"/> LOU only <input type="checkbox"/> LOR + LOU <input type="checkbox"/> LOR + LOI <input checked="" type="checkbox"/>	[Tick only one]		
GIA/LTA Search: SS <u>6.00</u>			
Medical: SS <u>-</u>		1) Claim status: Normal/Reject/Private Settle	
Disbursement: SS <u>-</u>	(e.g. Tow/ Independent)	2) Report Format: <u>TP</u>	
Legal Cost: SS <u>-</u>		3) Survey fee: <u>7400</u>	
Total: SS <u>20,821.44</u>	Global Sum SS:		
FINAL PAYMENT	Date/Time: <u>25.03.20</u>	Confirm with: <u>Wai Yin</u>	Email <input type="checkbox"/> Call <input type="checkbox"/>
Payee 1: SS <u>20,821.44</u>	Name 1: <u>TRANS-CAB AUTO SERVICES PTE LTD</u>		
Payee 2: (Strike if N.A.) SS <u>-</u>	Name 2: _____		
Payee 3: (Strike if N.A.) SS <u>-</u>	Name 3: _____		

COPY SENT 21/11/2020

REF: CAZ/

ASS. REC. BY:

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Tans Cab

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 21 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SHD 9543A Yr Regn: 06, 12

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Chrysler A) Epic c.c. 1991

Colour: White Red A/C: Insured / Std / NI / NA

Sp.Reading: 572173 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KL1LA 63RTBB . 089142

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: Cremax 195/65R.5

R: Falken

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 13/10/16

Survey held at ✓

Rear

R/Bal. 7 mm

L/Bal. 7 mm

D.O.I. 17/10/16

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
17/10	GIA not ready
18/10	File pass to Catherine
9/11/16	11 Rpt @ 15,600. Cabinal Taintine (21+6 X 102.72 + 1350)
	CPed \$ 545P2.05 / 789A

Date/Time, File Pass to?

: Preli. Report

1)

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation: _____

S + RS. \$ _____

Photos

Others

TOTAL

Add Fee: : Site Insp (\$ _____)

: Interview (\$ _____)

: Tech. Invs (\$ _____)

: Weekend (\$ _____)

Report Format :

Lump Sum / I.B.I: (\$ _____)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CC3/CTI16019744/Kpa3	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909		Date : 18-10-2016	
		Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SKK 5879K	Veh. Inspected	SHD 9543A
Policy No.	DMPCSN3049921600	Coverage (\$)	0.00
Claim No.	SNM16D04822/C02/9	Excess (\$)	0.00
Assign From		Assign Date	18/10/2016
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	13/10/2016	Inspection Date	17/10/2016
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO.6287 6666 FAX NO.6257 1330

CO/GST REG NO.201019626G

SHD 9543A - CHINA

Candy

*Not Ashenik
Proposed 11 Sep @ 15,600*

Vehicle No.:
Chassis No.:
Vehicle Make: *P-Drive*
Vehicle Model: *(X) RS photos*
Date of Accider: *Est Next value*
Third Party Ins: *~ \$15600.00*

SHD 9543A - Candy
KL1LA69RJBB089142
CHEVROLET
EPICA 2.0
13.10.16
CHINA

PAKI

LIST

QTY	UNIT	DESCRIPTION	PRICE	REMARKS	STATUS
1	1	Front Bumper	\$	B1	1,202.00 ✓
2	1	Front Bumper Reinforcement	\$	B1	295.25 ✓
3	1	Front Bumper Lower Absorber	\$	CM	180.00 ✓
4	1	Front Bumper Lower Grille	\$	M11	78.00 ✓
5	1	Front Bumper Retainer RH	\$	SN	102.00 X
6	1	Front Bumper Retainer LH	\$	SN	102.00 X
7	1	Front Bumper Lower Stiffener	\$	R	134.37 X
8	1	Front Headlamp RH	\$	M31M	816.00 ✓
9	1	Front Headlamp LH	\$	M3B2	816.00 ✓
10	1	Front Bumper Fog Lamp Outer Cover LH	\$	SN	32.40 X
11	1	Front Bumper Fog Lamp Outer Cover RH	\$	SN	32.40 X
12	1	Front Support Panel Assy (Panel A-Frt)	\$	B1	1,222.32 ✓
13	1	Bonnet (Panel A-Hood)	\$	B1	1,250.00 ✓
14	1	Centre 'CHEVROLET' Logo Badge	\$	M	144.30 ✓
15	1	Bonnet Moulding	\$	Del	257.00 ✓
16	1	Bonnet Insulator	\$	SN	84.63 X
17	1	Bonnet hinge RH	\$	R	36.00 X
18	1	Bonnet hinge LH	\$	R	36.00 X
19	1	Bonnet cable	\$	SN	150.00 X
20	1	Bonnet lock	\$	B1	200.00 ✓
21	2	HORN LH	\$	SN	320.00 7X
22	1	Radiator Grille (Grille A-Rad)	\$	CM	367.00 ✓
23	1	Radiator Assembly (Radiator A)	\$	1 hrs B1	618.00 ✓
24	1	Radiator upper hose	\$	SN	30.00 7X
25	1	Radiator lower hose	\$	SN	120.00 7X
26	1	Aircon Condenser (Condenser A)	\$	B1	600.00 ✓
27	1	Aircon hose - condenser to compressor	\$	SN	215.40 7X
28	1	Aircon hose - compressor to evaporator	\$	SN	316.20 7X
29	1	Aircon hose - condenser to evaporator	\$	SN	332.10 7X
30	1	Aircon compressor - pump	\$	SN	1,847.95 7X
31	1	Aircon compressor bracket	\$	R	245.30 7X
32	1	Front Centre Member	\$	SN	265.63 X
33	1	Air Intercooler	\$	B1/P2	652.00 ✓

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO.6287 6666 FAX NO.6257 1330

CO/GST REG NO.201019626G

SHD 9543A - CHINA

Candy

34	1	Fan Blade (Small)	\$	CM	536.00	✓
35	1	Fan Blade (Big)	\$	Sm	634.00	✓
36	1	Front Fender LH	\$	Bu	837.60	✓
37	1	Front Fender RH	\$	Bu	837.60	✓
38	1	Fender Insulation RH	\$	Sm	39.00	X
39	1	Front Fender Liner RH	\$	Sm	47.00	X
40	1	Front Fender Liner LH	\$	Sm	47.00	X
41	1	Rear Bumper	\$	Bu	1,202.00	✓
42	1	Rear Bumper Beam	\$	Bu	239.94	✓
43	1	Rear Bumper Centre Absorber	\$	CM	260.00	✓
44	1	Rear Bumper Side Retainer RH	\$	CM	68.76	✓
45	1	Rear Bumper side support RH	\$	Sm	25.00	X
46	1	Rear Bumper Reflectors RH	\$	CM	119.74	✓
47	1	Rear Bumper stay RH	\$	Sm	35.00	X
48	1	Rear Bumper Tow Hook Cover	\$	Sm	93.00	X
49	1	Rear End Panel Inner	\$	Bu	336.84	✓
50	1	Rear End Panel Outer	\$	Bu	623.76	✓
51	1	Rear End Panel Inner Trim	\$	Dis	263.84	✓
52	1	Bootlid	\$	Bu	973.00	✓
53	1	Bootlid inner trim board	\$	Sm	400.00	X
54	1	Bootlid Weatherstrip	\$	1224x 1121x 508 Sm	344.28	508 Sm
55	1	Bootlid Lock - Top	\$	Dis	466.56	✓
56	1	Bootlid lock - bottom	\$	Bu	39.40	✓
57	1	Bootlid 'CHEVROLET' Badge	\$	Bu	120.62	✓
58	1	Bootlid Logo	\$	Bu	138.84	✓
59	1	Bootlid 'EPICA LT' Badge	\$	Bu	119.84	✓
60	1	Bootlid inner handle	\$	Sm	45.55	X
61	1	Bootlid Reflector Centre	\$	Sm	217.97	X
62	1	Bootlid Reflector RH	\$	CM	128.40	✓
63	1	Bootlid Reflector LH	\$	CM	128.40	✓
64	1	Bootlid Hinge RH	\$	K	120.00	X
65	1	Bootlid Hinge LH	\$	K	120.00	X
66	1	Rear Gas T/Gate Spring RH	\$	Sm	286.90	X
67	1	Rear Gas T/Gate Spring LH	\$	Sm	286.90	X
68	1	Rear number plate lamp RH	\$	Sm	25.00	X
69	1	Rear number plate lamp LH	\$	Sm	25.00	X
70	1	Rear Tail Lamp RH	\$	Bu	479.30	✓
71	1	Rear Tail Lamp Panel RH	\$	Bu	359.00	✓
72	1	Rear Tail Lamp LH	\$	Bu	479.30	✓
73	1	Rear Tail Lamp Panel LH	\$	Bu	359.00	✓

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO.6287 6666 FAX NO.6257 1330

CO/GST REG NO.201019626G

SHD 9543A - CHINA**Candy**

74	1	Rear Exhaust Box (Muffler A-EXH,RR)	\$	Bu 1,110.00 ✓
75	1	Centre Exhaust Pipe	\$	R 403.00 ?
76	1	Rear Fender RH	\$	Bu 1,145.00 ✓
77	1	Rear Fender Inner Cowling RH	\$	Sn 298.00 X
78	1	Rear Fender Inner Trim RH	\$	De form 418.44 ✓
79	1	Rear Fender Inner Wheel House Panel RH	\$	R 2,556.35 X
80	1	Rear Fender LH	\$	Bu 1,145.00 ✓
81	1	Rear Fender Inner Cowling LH	\$	Sn 298.00 X
82	1	Rear Fender Inner Trim LH	\$	De form 418.44 ✓
83	1	Rear Fender Inner Wheel House Panel LH	\$	R 2,556.35 X
84	1	Rear Door RH (Panel A-RR DR RH)	\$	R 1,133.00 X
85	1	Rear Door weatherstrip - Inner RH	\$	Sn 41.40 ✓

TOTAL	\$	36,532.57
10%	\$	3,653.26
	\$	32,879.31

Special Nett

1	1Set	Front Bumper Fastener Clip	\$	Ma 24.00 ✓
2	1Set	Front Licence Plate With Holder	\$	De 192.00 2 Sn
6	1Set	Bonnet Insulator Clip	\$	nn 40.00 X
7	1Set	Radiator Grille Clip	\$	nn 18.00 ✓
8	1Set	Radiator Grille Top Cover Clip	\$	nn 10.00 ✓
9	1Set	Front Fender Liner Clip LH	\$	nn 40.00 X
10	1Set	Front Fender Liner Clip RH	\$	nn 40.00 X
11	1Set	Engine Splash Cover Clip RH	\$	nn 12.00 X
12	1Set	Rear Bumper Parking Sensor	\$	De 300.00 ✓
13	1Set	Rear Bumper Fastener Clip	\$	nn 30.00 ✓
14	1Set	Rear Fender inner cowling clip RH	\$	nn 30.00 X
15	1	Rear Boot Sticker 'Trans-cab'	\$	nn 30.00 ✓
16	1	Rear Boot Sticker '6555-3333'	\$	nn 30.00 ✓
18	1	Rear Door Sticker '6555-3333' RH	\$	nn 30.00 X
18	1	Rear Door Sticker '6555-3333' LH	\$	nn 30.00 X
22	1	Spare Tyre RH	\$	Sn 180.00 X
23	1	Spare Wheel Rim RH	\$	Sn 126.74 X
24	2	Rear Windscreen Sealant	\$	nn 80.00 40 Sn
25	1	Rear Windscreen Inner Sponge Seal	\$	nn 100.00 30 Sn

TOTAL	\$	1,342.74
TOTAL PARTS	\$	34,222.05

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO.6287 6666 FAX NO.6257 1330

CO/GST REG NO.201019626G

SHD 9543A - CHINA**Candy**

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	16,800.00 ²⁸⁰⁰
To Check Electrical Lighting Concerned.	\$	170.00 ⁴⁰⁰
To Rust-Proofing Of The Affected Areas.	\$	170.00 ✓
Putty And Spray Painting Of The Affected Portion.	\$	16,200.00 ²²⁰⁰
To dismantle and refit rear undercarriage parts, final checking and testing.	\$	380.00 ²²⁰
To reinstall rear bumper parking sensor.	\$	170.00 ⁶⁰⁰
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	380.00 ²⁵⁰
To transfer of Fender fittings, attachments and perform water seepage test.	\$	170.00 ¹⁰⁰
Towing Fees.	\$	120.00 ⁵⁰
To check steering geometry and computer wheel alignment	\$	220.00 ⁶⁰
To transfer of tire, rim and on wheel balancing.	\$	~ 170.00 X
To Remove And Refit Rear W/Screen Glass To Facilitate Bodywork Repair.	\$	170.00 ¹²⁰
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	~ 120.00 X
To check ABS brake efficiency, final checking and testing.	\$	~ 380.00 X

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO.6287 6666 FAX NO.6257 1330

CO/GST REG NO.201019626G

SHD 9543A - CHINA

Candy

To replace, refix and top up coolant for radiator	\$	170.00	<i>500</i>
To vacuum, replace, refix and recharge Air Intercooler	\$	170.00	<i>500</i>
		<hr/>	
	\$	35,960.00	
TOTAL	\$	70,182.05	

Repair Days

~~60 Days~~

21 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

DOA	13.10.2016
COE Expiry Date	14.06.2020

\$

(I) Estimated Book Value

Unit Cost	30,000.00
Import Duty	2,879.00
Registration Fee	140.00
PQP Paid	46,401.00
ARF Paid	14,395.00
Estimated Per Taxi Purchase Price	93,815.00
Estimated Per Taxi Purchase Price	93,815.00
Less 60% of ARF Paid	8,637.00
Estimated Full Lifespan Depreciation	85,178.00
Estimated Full Lifespan Depreciation	85,178.00
Times Balance Life (44/96 months)	39,039.92
Add 60% of ARF Paid	8,637.00
Estimated Book Value	47,676.92

(II) Adjusted LTA Rebate

PARF Rebate	
PQP Paid	
Times Balance Life (69/96 months)	
Adjusted COE Rebate	
PARF Rebate	
Add Adjusted COE Rebate	
Adjusted LTA Rebate	32,063.00

(Summary) Estimated Nett Value

Estimated Book Value	47,676.92
Less Adjusted LTA Rebate	32,063.00
Estimated Net Value	15,613.92



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: TBA
Our ref: CC3/CTI16019744/Kpa3

Date: 21.10.2016

The Motor Claims Department
M/s CHINA TAIPING INSURANCE (S) PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SHD 9543A


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 17/10/2016 at the premises of M/s Trans-cab Auto Services Pte Ltd - Ang Mo Kio and have the following to report:-

Workshop Estimate Amount	: S\$	70,182.05
Revised Estimate Amount	: S\$	26,726.38
"Check" Items Amount	: S\$	4,017.56
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the Front & Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 21 days

Yours faithfully,

KENNETH KONG
Licensed Appraiser

**ONE MOTORING**
Your Fast Track To Complete Motoring

Text size + -

Enquire PARF/COE Rebate for Registered Vehicle**Vehicle Owner Particulars**

Owner ID Type: Company

Owner ID: 3878K

Vehicle Details

Vehicle No.: SHD9543A

Vehicle to be Exported: Yes

Intended De-registration Date: 14 Oct 2016

Vehicle Make: CHEVROLET

Vehicle Model: EPICA 2.0DSL AT ABS D/AB 2WD 4DR TURBO

Primary Colour: Red

Manufacturing Year: 2011

Engine No.: Z20S1450887K

Chassis No.: KL1LA69RJBB089142

Maximum Power Output: 110.0 kW (147 bhp)

Open Market Value: \$14,395.00

Original Registration Date: 15 Jun 2012

First Registration Date: 15 Jun 2012

Transfer Count: 0

Actual ARF Paid: \$14,395.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 14 Jun 2020

PARF Rebate Amount: \$10,796.00

Intended COE Rebate Details

COE Expiry Date: 14 Jun 2020

COE Category: A - Car (1600cc & below)

COE Period (Years): 8

QP Paid: \$46,401.00

COE Rebate Amount: \$21,267.00

Total Rebate Amount: \$32,063.00**Message**

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 14 Oct 2016

OK

Land Transport Authority

Please read through the Privacy Statement, Terms of Use and Disclaimer.

Mei Kwan (LKKAuto)

From: Jowyn Tay <jowyn.tay@sg.cntaiping.com>
Sent: Friday, 21 October, 2016 3:57 PM
To: Mei Kwan (LKKAuto); Hsiao Tong (LKKAuto)
Cc: Alfred Toh; Zayyer (LKKAuto); Vivian Lau (LKKAuto); Admin A; Jowyn Tay
Subject: RE: Direct Settlement - Accident Involving SKK5879K (REF: SNM16D04822/C02/9) and SHD9543A (TP : LKK REF - CC3/CTI16019744/Kpa3) on 13.10.2016
Attachments: SNM16D04822C02 20161021-TO INSD-APPT LKK AS SETTLEMENT AGENT.pdf; MNA116129524-SKK5879K.pdf
Importance: High

Dear Hsiao Tong &/or Mei Kwan,

We refer to your email on even date.

We attached herewith our insured's accident report and letter for your immediate attention.

Thank you.

Regards,

Jowyn Tay

Assistant Claims Executive
Motor Division
Claims Department
China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00
Springleaf Tower
Singapore 079909
Co. Reg. No. 200208384E
DID: 6389 6174
Fax: 6224 7175 / 6224 7478
Email: claimsdept@sg.cntaiping.com
jowyn.tay@sg.cntaiping.com
Website: www.sg.cntaiping.com

Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Mei Kwan (LKKAuto) [<mailto:Meikwan@lkkauto.com>]
Sent: Friday, 21 October, 2016 9:45 AM
To: Claims Dept of CTI
Cc: Jowyn Tay; Alfred Toh; Hwang Shiang Yi; Hsiao Tong (LKKAuto); Zayyer (LKKAuto); Vivian Lau (LKKAuto); Admin A



中国太平
CHINA TAIPING

中国太平保险(新加坡)有限公司
CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
Tel: 6389 6111 Fax: 6222 1033
Website: www.sg.taiping.com
Co. Reg. No. 200206384E

Our Reference: **SNM16D04822/C02/9**

Date : **21 OCTOBER 2016**

via Ordinary & Registered Mail

**LIM WEI YONG (LIN WEIRONG)
BLK 431 BUKIT PANJANG RING ROAD
#11-689
SINGAPORE 670431**

Dear Sir / Madam

**ACCIDENT INVOLVING SKK5879K AND SHD9543A ON 13 OCTOBER 2016
ALONG ECP TOWARDS CHANGI BESIDE EXIT OF 10A (MARINE PARADE FLYOVER)**

We refer to the abovementioned accident.

Please be advised that the third party vehicle, **SHD9543A** , is filing a third party property claim against your vehicle.

We have appointed **LKK Auto Consultants Pte Ltd**, to administer the said claim on our behalf and they will contact you for more information about the accident.

Kindly render your assistance and co-operation accordingly.

Yours truly,
Claims Department

(This is a computer generated letter and no signature is required.)

CC : LKK Auto Consultants Pte Ltd
Attn : HSHAO TONG
Ref : CC3/CTI16019744/KPA3
Contact No : 67423197
via Email : chewht@lkkauto.com

CC : Agent - (AN0166A) - LQ BUSINESS SERVICES

F01/LKKDS-2013



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CC3/CTI16019744/Kea3s2	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909		Date : 06-04-2020	
		Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SKK 5879K	Veh. Inspected	SHD 9543A
Policy No.	DMPCSN3049921600	Coverage (\$)	0.00
Claim No.	SNM16D04822/C02/9	Excess (\$)	0.00
Assign From		Assign Date	17/10/2016
2. Vehicle Particulars & Condition			
Make & Model	CHEVROLET EPICA (A)	c.c	1991
Engine No.	HIDDEN	Year of Reg.	2012
Chassis No.	KL1LA69RJBB089142	Colour	WHITE / RED
Odometer	572173	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/65R15	GREMAX	6 mm
L/H Front Tyre	195/65R15	GREMAX	6 mm
R/H Rear Tyre	195/65R15	FALKEN	7 mm
L/H Rear Tyre	195/65R15	FALKEN	7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	13/10/2016	Inspection Date	17/10/2016
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		21 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 5

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 9543A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER	BENT	1,202.00	1,202.00
1	FRONT BUMPER REINFORCEMENT	BENT	295.25	295.25
1	FRONT BUMPER LOWER ABSORBER	CRACKED	180.00	180.00
1	FRONT BUMPER LOWER GRILLE	MISSING	78.00	78.00
1	FRONT BUMPER RETAINER RH	SERVICEABLE	102.00	-
1	FRONT BUMPER RETAINER LH	SERVICEABLE	102.00	-
1	FRONT BUMPER LOWER STIFFENER	TO REPAIR SEE LABOUR	134.37	-
1	FRONT HEADLAMP RH	MTG CRACKED	816.00	816.00
1	FRONT HEADLAMP LH	MTG BROKEN	816.00	816.00
1	FRONT BUMPER FOG LAMP OUTER COVER LH	SERVICEABLE	32.40	-
1	FRONT BUMPER FOG LAMP OUTER COVER RH	SERVICEABLE	32.40	-
1	FRONT SUPPORT PANEL ASSY (PANEL A-FRT)	BENT	1,222.32	1,222.32
1	BONNET (PANEL A-HOOD)	BENT	1,250.00	1,250.00
1	CENTRE 'CHEVROLET' LOGO BADGE	NECESSARY	144.30	144.30
1	BONNET MOULDING	DENTED	257.00	257.00
1	BONNET INSULATOR	SERVICEABLE	84.63	-
1	BONNET HINGE RH	TO REPAIR SEE LABOUR	36.00	-
1	BONNET HINGE LH	TO REPAIR SEE LABOUR	36.00	-
1	BONNET CABLE	SERVICEABLE	150.00	-
1	BONNET LOCK	BENT	200.00	200.00
2	HORN LH	SERVICEABLE	320.00	-
1	RADIATOR GRILLE (GRILLE A-RAD)	CRACKED	367.00	367.00
1	RADIATOR ASSEMBLY (RADIATOR A)	HOUSING BROKEN	618.00	618.00
1	RADIATOR UPPER HOSE	SERVICEABLE	30.00	-
1	RADIATOR LOWER HOSE	SERVICEABLE	120.00	-
1	AIRCON CONDENSER (CONDENSER A)	BENT	600.00	600.00
1	AIRCON HOSE - CONDENSER TO COMPRESSOR	SERVICEABLE	215.40	-
1	AIRCON HOSE - COMPRESSOR TO EVAPORATOR	SERVICEABLE	316.20	-
1	AIRCON HOSE - CONDENSER TO EVAPORATOR	SERVICEABLE	332.10	-

Report Ref No. CC3/CTI16019744/Kea3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	AIRCON COMPRESSOR - PUMP	SERVICEABLE	1,847.95	-
1	AIRCON COMPRESSOR BRACKET	TO REPAIR SEE LABOUR	245.30	-
1	FRONT CENTRE MEMBER	SERVICEABLE	265.63	-
1	AIR INTERCOOLER	BENT / PUNCTURE	652.00	652.00
1	FAN BLADE (SMALL)	CRACKED	536.00	536.00
1	FAN BLADE (BIG)	SERVICEABLE	634.00	-
1	FRONT FENDER LH	BUCKLED	837.60	837.60
1	FRONT FENDER RH	BUCKLED	837.60	837.60
1	FENDER INSULATION RH	SERVICEABLE	39.00	-
1	FRONT FENDER LINER RH	SERVICEABLE	47.00	-
1	FRONT FENDER LINER LH	SERVICEABLE	47.00	-
1	REAR BUMPER	BENT	1,202.00	1,202.00
1	REAR BUMPER BEAM	BENT	239.94	239.94
1	REAR BUMPER CENTRE ABSORBER	CRACKED	260.00	260.00
1	REAR BUMPER SIDE RETAINER RH	CRACKED	68.76	68.76
1	REAR BUMPER SIDE SUPPORT RH	SERVICEABLE	25.00	-
1	REAR BUMPER REFLECTORS RH	CRACKED	119.74	119.74
1	REAR BUMPER STAY RH	SERVICEABLE	35.00	-
1	REAR BUMPER TOW HOOK COVER	SERVICEABLE	93.00	-
1	REAR END PANEL INNER	BENT	336.84	336.84
1	REAR END PANEL OUTER	BENT	623.76	623.76
1	REAR END PANEL INNER TRIM	DISTORTED	263.84	263.84
1	BOOTLID	BENT	973.00	973.00
1	BOOTLID INNER TRIM BOARD	SERVICEABLE	400.00	-
1	BOOTLID LOCK - TOP	DENTED	466.56	466.56
1	BOOTLID LOCK - BOTTOM	BENT	39.40	39.40
1	BOOTLID 'CHEVROLET' BADGE	NECESSARY	120.62	120.62
1	BOOTLID LOGO	NECESSARY	138.84	138.84
1	BOOTLID 'EPICA LT' BADGE	NECESSARY	119.84	119.84
1	BOOTLID INNER HANDLE	SERVICEABLE	45.55	-
1	BOOTLID REFLECTOR CENTRE	SERVICEABLE	217.97	-
1	BOOTLID REFLECTOR RH	CUT	128.40	128.40

Report Ref No. CC3/CTI16019744/Kea3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BOOTLID REFLECTOR LH	CRACKED	128.40	128.40
1	BOOTLID HINGE RH	TO REPAIR SEE LABOUR	120.00	-
1	BOOTLID HINGE LH	TO REPAIR SEE LABOUR	120.00	-
1	REAR GAS T/GATE SPRING RH	SERVICEABLE	286.90	-
1	REAR GAS T/GATE SPRING LH	SERVICEABLE	286.90	-
1	REAR NUMBER PLATE LAMP RH	SERVICEABLE	25.00	-
1	REAR NUMBER PLATE LAMP LH	SERVICEABLE	25.00	-
1	REAR TAIL LAMP RH	BROKEN	479.30	479.30
1	REAR TAIL LAMP PANEL RH	BENT	359.00	359.00
1	REAR TAIL LAMP LH	BROKEN	479.30	479.30
1	REAR TAIL LAMP PANEL LH	BENT	359.00	359.00
1	REAR EXHAUST BOX (MUFFLER A-EXH,RR)	BENT	1,110.00	1,110.00
1	CENTRE EXHAUST PIPE	TO REPAIR SEE LABOUR	403.00	-
1	REAR FENDER RH	BUCKLED	1,145.00	1,145.00
1	REAR FENDER INNER COWLING RH	SERVICEABLE	298.00	-
1	REAR FENDER INNER TRIM RH	DEFORMED	418.44	418.44
1	REAR FENDER INNER WHEEL HOUSE PANEL RH	TO REPAIR SEE LABOUR	2,556.35	-
1	REAR FENDER LH	BUCKLED	1,145.00	1,145.00
1	REAR FENDER INNER COWLING LH	SERVICEABLE	298.00	-
1	REAR FENDER INNER TRIM LH	DEFORMED	418.44	418.44
1	REAR FENDER INNER WHEEL HOUSE PANEL LH	TO REPAIR SEE LABOUR	2,556.35	-
1	REAR DOOR RH (PANEL A-RR DR RH)	TO REPAIR SEE LABOUR	1,133.00	-
1	REAR DOOR WEATHERSTRIP - INNER RH	SERVICEABLE	41.40	-
	LESS 10% DISCOUNT		-3,618.83	-2,205.25
			32,569.46	19,847.24
1	BOOTLID WEATHERSTRIP (50%) (SN)	DENTED / CUT	344.28	172.14
	LESS 10% DISCOUNT		-34.43	-
			309.85	172.14

Report Ref No. CC3/CTI16019744/Kea3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
SPECIAL NETT ITEMS				
1	SET FRONT BUMPER FASTENER CLIP (SN)	NECESSARY	24.00	24.00
1	SET FRONT LICENCE PLATE WITH HOLDER (SN)	DENTED	192.00	25.00
1	SET BONNET INSULATOR CLIP (SN)	NOT NECESSARY	40.00	-
1	SET RADIATOR GRILLE CLIP (SN)	NECESSARY	18.00	18.00
1	SET RADIATOR GRILLE TOP COVER CLIP (SN)	NECESSARY	10.00	10.00
1	SET FRONT FENDER LINER CLIP LH (SN)	NOT NECESSARY	40.00	-
1	SET FRONT FENDER LINER CLIP RH (SN)	NOT NECESSARY	40.00	-
1	SET ENGINE SPLASH COVER CLIP RH (SN)	NOT NECESSARY	12.00	-
1	SET REAR BUMPER PARKING SENSOR (SN)	DENTED	300.00	300.00
1	SET REAR BUMPER FASTENER CLIP (SN)	NECESSARY	30.00	30.00
1	SET REAR FASTENER INNER COWLING CLIP RH (SN)	NOT NECESSARY	30.00	-
1	REAR BOOT STICKER 'TRANS-CAB' (SN)	NECESSARY	30.00	30.00
1	REAR BOOT STICKER '6555-3333' (SN)	NECESSARY	30.00	30.00
1	REAR DOOR STICKER '6555-3333' RH (SN)	NOT NECESSARY	30.00	-
1	REAR DOOR STICKER '6555-3333' LH (SN)	NOT NECESSARY	30.00	-
1	SPARE TYRE RH (SN)	SERVICEABLE	180.00	-
1	SPARE WHEEL RIM RH (SN)	SERVICEABLE	126.74	-
2	REAR WINDSCREEN SEALANT (SN)	NECESSARY	80.00	40.00
1	REAR WINDSCREEN INNER SPONGE SEAL (SN)	NECESSARY	100.00	30.00
			1,342.74	537.00
LABOUR				
PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND RELIGN THE SAME. INCLUSIVE OF THE REPAIR OF FRONT BUMPER LOWER STIFFENER, BONNET HINGE RH, BONNET HINGE LH, AIRCON COMPRESSOR BRACKET, BOOTLID HINGE RH, BOOTLID HINGE LH, CENTRE EXHAUST PIPE, REAR FENDER INNER WHEEL HOUSE PANEL RH, REAR FENDER INNER WHEEL HOUSE PANEL LH AND REAR DOOR RH (PANEL A-RR DR RH).			16,800.00	2,800.00
TO CHECK ELECTRICAL LIGHTING CONCERNED.			170.00	40.00
TO RUST-PROOFING OF THE AFFECTED AREAS.			170.00	170.00
PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.			16,200.00	2,200.00

Report Ref No. CC3/CT116019744/Kea3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:5 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO DISMANTLE AND REFIT REAR UNDERCARRIAGE PARTS, FINAL CHECKING AND TESTING.		380.00	220.00
	TO REINSTALL REAR BUMPER PARKING SENSOR.		170.00	60.00
	TO PULL AND JACK OUT CHASSIS FRAME AND CORRECT IT TO SYMMETRICAL POSITION WITH THE AID OF HYDRAULIC PNEUMATIC JACK.		380.00	250.00
	TO TRANSFER OF FENDER FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.		170.00	100.00
	TOWING FEES.		120.00	50.00
	TO CHECK STEERING GEOMETRY AND COMOUTER WHEEL ALIGNMENT.		220.00	60.00
	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
	TO REMOVE AND REFIT REAR W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR.		170.00	120.00
	TO DISMANTLE AND REFIT FRONT END SUSPENSION, UNDERCARRIAGE PARTS, FINAL CHECKING AND TESTING.	NOT NECESSARY	120.00	-
	TO CHECK ABS BRAKE EFFICIENCY, FINAL CHECKING AND TESTING.	NOT NECESSARY	380.00	-
	TO REPLACE, REFIX AND TOP UP COOLANT FOR RADIATOR.		170.00	50.00
	TO VACUUM, REPLACE, REFIX AND RECHARGE AIR INTERCOOLER.		170.00	50.00
			35,960.00	6,170.00
	GRAND TOTAL		70,182.05	26,726.38
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			15,600.00

Report Ref No. CC3/CT116019744/Kea3s2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.