

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/III16020059/T1PS3Q2
Date: 19/07/2021**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	MC0M0016
Claimant Vehicle No :	SKM4327H	Insured Vehicle No :	SHD4364H
Date of Loss:	19/10/2016	Nature of Claim:	TP
		Claim No:	MCT16100872

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKM4327H		
Make & Model:	JAGUAR XF, 2.0 GTDI Luxury (A)	Engine No:	181013134907204PT
Reg. Date:	28/02/2014 (Man. Year: 2014)	Chassis No:	SAJAC05M9EPU17026
Colour:	Silver	Odometer:	0 km
Engine Capacity:	1999 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	245/45 R18	Rear Tyre Size:	245/45 R18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,924.70	15,238.40	686.30	4.31
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,650.00	8,104.00	4,546.00	35.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	28,574.70	23,342.40	5,232.30	18.31
+ GST 7.00/7.00% (S\$)	2,000.23	1,633.97	366.26	18.31

Nett Amount (S\$)	30,574.93	24,976.37	5,598.56	18.31
+ Car Rental (5.0 x S\$130.00/day + 7.00% GST) (S\$)		695.50		
Nett Liability (S\$)		25,671.87		

INSPECTION

Date of Assignment: 28/10/2016

Date Inspected: 28/10/2016

Estimated Period of Repair: 5.0 days

Inspected At: Wearnes Automotive Pte Ltd (Leng Kee)
45 Leng Kee Road,
159103 Leng Kee

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 13 Dec 2019)
Parts:	143	JAGUAR XF 2.0 GTDI Luxury (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKM4327H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FENDER PANEL FRT RH	Bent	1,551.10 FS	*1,551.10 FS
2	1		*FENDER BAFFLE FRT RH	Not Necessary	49.20 FS	*- FS
3	1		*FENDER BRACKET FRT R	Not Necessary	47.80 FS	*- FS
4	1		*FINISHER -VEN	Cut	310.30 FS	*310.30 FS
5	1		*BUMPER BRACKET FRT R	Not Necessary	52.40 FS	*- FS
6	1		*FENDER BRACKET RH XF	Not Necessary	138.30 FS	*- FS
7	1		*WHEELARCH FRT RH XF	Not Necessary	398.60 FS	*- FS
8	10		*WHEELARCH PLASTIC NU	Necessary	37.00 FS	*37.00 FS
9	1		*STEERING RACK XF	Bent	5,348.70 FS	*5,348.70 FS
10	1		*ALLOY RIM 18 VELA XF	Cut	1,681.70 FS	*1,681.70 FS
11	1		*SHOCK ABSORBER FRT R	Bent	823.40 FS	*823.40 FS
12	2		*ABSORBER SPRING INSU	Bent	156.80 FS	*156.80 FS
13	1		*VERTICAL LINK RH XF	Bent	587.30 FS	*587.30 FS
14	1		*JC2D38989/HUB & REAR	Bent	518.50 FS	*518.50 FS
15	1		*LATERAL LOWER ARM RH	Bent	1,799.90 FS	*1,799.90 FS
16	1		*WISHBONE ARM FRT RH	Bent	1,293.20 FS	*1,293.20 FS
17	1		*STABILIZER BAR FRT X	Bent	881.70 FS	*881.70 FS
18	1		*STABILIZER LINK FRT	Bent	107.60 FS	*107.60 FS
19	2		*STABILIZER BUSH FRT	Necessary	55.20 FS	*55.20 FS
20	2		*STEERING OIL 1L XF S	Necessary	86.00 FS	*86.00 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **15,924.70** **15,238.40**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPLACE FRT RH FENDER AND REPAIR ON FRT BUMPER	New	3,400.00	1,700.00
2	TO SPRAY PAINT ON FRONT BUMPER ,FRONT RH FENDER FENDER INNER PANEL	New	3,000.00	1,500.00
3	TO REPLACE FRT RH AFFECTED UNDERCARRIAGES	New	5,184.00	3,888.00
4	TO CHECK WIRING INCLUSIVE OF RESETTING ALL ELECTRICAL MODULES	New	486.00	486.00
5	COMPUTERIZED 4 WHEEL ALIGNMENT	New	280.00	280.00
6	TO REPLACE FRT RH RIM	New	50.00	0.00
7	TOWING DUE TO ACCIDENT	New	250.00	250.00
Gross Labour Cost (S\$)			12,650.00	8,104.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >