

ASS. C.BY:

REF:

CS/GA116022726/Atb02

Special Instruction:

Surveyor:

Purnan

ASSIGNMENT (Office)

From (Person):

Stella Goh

of

GML

Date/Time:

29.11.2016 3.32pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

YN 5610L

Insured:

YP 3851K

at Workshop m/s

Torque 5

Tel:

9182 8432

of

8 Kaki Bukit Ave 4 #01-49

Policy No:

Claim No:

YP 3851K

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

26.11.2016

CA / REV / REP. / REV 24 HRS WP

30.11.2016

H.O.D. Endorsement:

Date/Time:

29.11.2016 3.37pm

Person Contacted:

May

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	YN 5610L - CC3 / AXA 16011224 / Kw3
	YP 3851K - X
	lump sum \$8200/- 14 days (Red: 2939.48 : 26%)

DOA: 130616

Surveyor:

ASSIGNMENT

From: _____ Date: 30-11-2016

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: YN 5610L

at Workshop m/s Torque 5

of 8 Kuki Bukit Ave 4 # 01-49

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: YN 5610L Yr Regn: 2014 / July

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Isuzu NPR c.c 2999

Colour: white A/C: Insured / Std / NI / NA

Sp. Reading: 136966 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JAANPR85HE7100380

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or _____

Brake: Inorder / Jammed / Leaked / Burnt or _____

Modi: Nil / S/Rim / STD A/Rim or _____

Tyre Size: F: 205/85 R16

R: 205/85 R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Chao Yang

Front

Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. _____ D.O.I. 30/11/16

Survey held at Torque 5

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP Great American

RECEIVED 13 DEC 2017

Date/Time, File Pass to?

1) BID TYPIST

Date/Time, File Return to?

2)

☐ : Preli. Report☒ : Final Report

Days Of Repair: 14

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

350

Report Format: TP

Lump Sum / I.B.I: (\$ 2200)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

GREAT AMERICAN INSURANCE COMPANY

Ref : CS/GAI16022726/Atb

3 TEMASEK AVENUE
#16-01 CENTENNIAL TOWER
SINGAPORE 039190

Date : 29-11-2016



Code : GAI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YP 3851K	Veh. Inspected	YN 5610L
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	STELLA GOH	Assign Date	29/11/2016

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	26/11/2016	Inspection Date	30/11/2016
Survey held at	TORQUE 5 PTE LTD 8 KAKI BUKIT AVENUE 4 #01-50 PREMIER @ KAKI BUKIT SINGAPORE 415875		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

Catherine Chong (LKK Auto)

From: Goh, Stella <Stella.Goh@sg.gaig.com>
Sent: Tuesday, 29 November, 2016 3:32 PM
To: Reporting @ Torque 5
Cc: sam.chang@torque5.com; may.ng@torque5.com; 'KKLau'; 'Admin A'; assignments@lkkauto.com
Subject: RE: Accident Involving YP 3851 K (Your Ref) & YN 5610 L (Our Ref) on 26/11/2016 at 0800hrs along Woodlands Loop
Attachments: 20161129103458397.pdf; List of LKK Surveyors.pdf

WITHOUT PREJUDICE

Dear May,

We refer to your email on even date.

We will appoint LKK to conduct the PRS.

Enclosed a list of surveyors.

By copy to Catherine, please assist.

Thank you.

Stella Goh, Senior Executive | P. 65 6804 6059 | F. 65 6235 3354 | stella.goh@sg.gaig.com



Claims | 3 Temasek Avenue #16-01 Centennial Tower Singapore 039190



Moody's
A1 (Good)
Affirmed June 15, 2015

Standard & Poor's
A+ (Strong)
Affirmed March 2, 2016

For more information on our financial ratings, visit GAIG.com/FinancialStrength.

From: Reporting @ Torque 5 [mailto:reporting@torque5.com]
Sent: Tuesday, November 29, 2016 10:27 AM
To: Goh, Stella <Stella.Goh@sg.gaig.com>
Cc: sam.chang@torque5.com; may.ng@torque5.com
Subject: Accident Involving YP 3851 K (Your Ref) & YN 5610 L (Our Ref) on 26/11/2016 at 0800hrs along Woodlands Loop

Attn: Motor Claims Department

Dear Sir/Mdm,

Refer to the above mentioned.

We represent our client, Toh Thy San Farm to notify you of the aforesaid accident involving YN 5610 L our client's vehicle and your insured's vehicle YP 3851 K. Attached a copy of the GIA Report.

This serves as a **NOTICE** that we are claiming against YP 3851 K for damages, costs and disbursements.

Please let us know within **2 working days** from today, your client's and your intention to conduct a pre-repair survey of our client's vehicle, along with your list of at least **ten (10) motor surveyors**.

If we do not receive any reply from you within the stipulated timeline, we shall proceed to appoint our own surveyor and proceed with the necessary repair for our client's vehicle without further reference to your insured or you.

Premises for the Pre-repair inspection: 8 Kaki Bukit Ave 4 #01-49, Premier @ Kaki Bukit Singapore 415875

Contact Person: May Ng (9182 8732)

Contact Email: may.ng@torque5.com / reporting@torque5.com



Kindly cc a copy of this letter to your insured for his/her acknowledgement.

Look forward to your reply soon.

Warmest Regards,

May Ng

Assessor | Motor Claims Department

Hotline (65) 6385 0475 DID 106 | Fax (65) 6452 4584

Mobile (65) 9182 8732

Email may.ng@torque5.com

Address 8 Kaki Bukit Ave 4, #01-49/50/51/52/53/54
Premier @ KB, Singapore 415875

www.torque5.com



Email: sm@idac.com.sg

Tel no: 6555 6888 Fax no: 6454 3279

Personal Particulars of Owner & Driver (Vehicle A)

Date of Accident: 26/11/2016 (dd/mm/yy) Time of Accident: 08:00 (24-HR-FORMAT)

Vehicle No.: YN5610L Vehicle Make & Model: ISUZU

Exact location of Accident: Along Woodlands Loop

Policyholder's Name / IC No.: Toh Thye San Farm

Driver's Name / IC No.: Chong Kein How 46562603P (As Above) ☐

Driver's Contact No.: 8266 4433 Company Contact No.: 6283 3800

Driver's Address: 684 Hougang Ave 8 #02-967 S/530684

Insurance Company: AXA

Email address (if any):

Relationship between Owner & Driver: (Please CIRCLE one only)

Owner / Spouse / Children / Friend / Parents / Sibling / Relative / Employee / Hirer or Others specify: _____

What do you wish to claim? (Please TICK one only)

☐ Own Insurance / ☒ Other Vehicle (The one you want to claim against) / ☐ Reporting (For Record Purpose)

Exact purpose for which the vehicle was being used at time of accident?

☐ Private use / ☒ Work purpose

Occupation (nature of job) ☐ Indoor / ☒ Outdoor

No. of Passengers (Including Driver): 02

Weather condition & Road conditions? (On the day of accident)

☒ Clear & Dry / ☐ Raining & Wet / ☐ After-Rain & Wet / ☐ Drizzling & Wet / Others: _____

Was there any video captured by your Car Camera? ☐ Yes / ☒ No

Any Injuries: ☒ Yes / ☐ No (If YES) Injured Person's Name: _____

Injuries Sustain: _____ Injured Person in Which Vehicle: _____

Police Report filed: ☒ Yes / ☐ No (If YES) Which Police Station: _____

The Other Party(s) Details:

1. Driver's Name / IC No: _____ Vehicle No: YP3851K

Driver's Contact No: _____ Insurance Company (If any): _____

2. Driver's Name / IC No: _____ Vehicle No: _____

Driver's Contact No: _____ Insurance Company (If any): _____

*Independent Witness (If Any): _____ Contact No: _____

Preferred Workshop Name: _____ Contact No: _____

*If no proper documents are produced, IDAC should not file the report. Information will be discarded after one week.

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Policy for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Center established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the center and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
I understand, acknowledge, agree and consent that:
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or processed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims; the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.




Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Center Personnel

Sketch Plan

Vehicle A: YN5610L
Vehicle B: YP3851K



Describe Circumstances of the Accident

On the stated date & time, I, Vehicle 'A', YN5610L, was travelling along the stated route. Suddenly, Vehicle 'B', YP3B51K, cut through from the opposite direction and hit into my vehicle's front portion.

Declaration

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Center Personnel



Torque 5 Pte Ltd
No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Estimation No. : E16110086

Vehicle No : YN5610L
Make & Model : ISUZU, NPR85UH5A
Year of : 2014
Manufacture

No	Description	Qty	U/P	Amt
<u>Section: List Items</u>				
1	RH door <i>Buckled</i>	1.00	0.00 882.00	0.00 ✓
2	RH door hinge top <i>But</i>	1.00	0.00 98.00	0.00 ✓
3	RH door hinge bottom <i>But</i>	1.00	0.00 98.00	0.00 ✓
4	RH door lock <i>Do d</i>	1.00	0.00 145.00	0.00 ✓
5	RH door trim <i>Comb</i>	1.00	0.00 239.00	0.00 ✓
6	RH door trim clips <i>m</i>	1.00	0.00 50.00	0.00 ✓
7	RH door weatherstrip <i>ht</i>	1.00	0.00 182.00	0.00 ✓
8	RH door regulator <i>Do d</i>	1.00	0.00 295.00	0.00 ✓
9	RH door power window motor <i>Do d</i>	1.00	0.00 234.00	0.00 ✓
10	RH pillar <i>Buckled</i>	1.00	0.00 279.00	0.00 ✓
11	RH door glass <i>shattered</i>	1.00	0.00 245.00	0.00 ✓
12	RH side mirror assy <i>misang</i>	1.00	0.00 72.00	0.00 ✓
13	RH door step <i>ht</i>	1.00	0.00 138.00	0.00 ✓
14	RH door signal lamp <i>ht</i>	1.00	0.00 96.00	0.00 ✓
15	Front windscreen <i>shattered</i>	1.00	0.00 1600.00	0.00 ✓
16	Front windscreen rubber <i>ht</i>	1.00	0.00 143.00	0.00 ✓
17	Wiper panel <i>Do d</i>	1.00	0.00 158.00	0.00 ✓
18	Wiper nozzle LH <i>m</i>	1.00	0.00 49.90	0.00 ✓
19	Wiper nozzle RH <i>Do d</i>	1.00	0.00 49.90	0.00 ✓
20	Wiper arm LH <i>m</i>	1.00	0.00 27.00	0.00 ✓
21	Wiper arm RH <i>ht</i>	1.00	0.00 27.00	0.00 ✓
22	Front bumper <i>Dislod</i>	1.00	0.00 513.00	0.00 ✓
23	Front crossmember <i>But</i>	1.00	0.00 535.00	0.00 ✓
24	Front panel <i>Dislod</i>	1.00	0.00 673.00	0.00 ✓
25	Front panel "Isuzu" <i>m</i>	1.00	0.00 143.00	0.00 ✓

Continue on next page...



Torque 5 Pte Ltd
No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Estimation No. : E16110086

Vehicle No : YN5610L
Make & Model : ISUZU, NPR85UH5A
Year of : 2014
Manufacture :

No	Description	Qty	U/P	Amt
26	Front grille assy <i>Ambed</i>	1.00	0.00	414.00 0.00 ✓
27	Headlamp RH assy <i>Ambed</i>	1.00	0.00	7991.90 0.00 ✓
28	RH corner panel <i>Ambed</i>	1.00	0.00	6793.11 0.00 ✓
				Amt S\$ 0.00 3128.80
				Discount (0.00%) S\$ 0.00
				Subtotal S\$ 0.00 6909.48

Section: Special Nett Items

29	Front number plate <i>Bnt</i>	1.00	50.00	50.00 ✓
				Amt S\$ 50.00
				Discount (0.00%) S\$ 0.00
				Subtotal S\$ 50.00

Section: Labour Items

30	To knock & straighten on accident area, to remove & refit damage parts.	1.00	1,800.00	1,800.00 1450
31	To putty & respray on accident affected area.	1.00	1,600.00	1,600.00 1400
32	To rust proof accident affected area.	1.00	160.00	160.00 80
33	To check wiring layout and headlamp focus	1.00	50.00	50.00 30
34	To remove & refit front windscreen.	1.00	150.00	150.00 120
35	To remove & refit dashboard to assist work load.	1.00	300.00	300.00 220
36	To remove & refit door trim, door glass, window regulator, door lock to assist work load.	1.00	120.00	120.00 100
				Amt S\$ 4,180.00
				Discount (0.00%) S\$ 0.00
				Subtotal S\$ 4,180.00

P- 7991.90
+ 151.1198.78
6793.11

L/S Admin Lin

30/11/16.

14 Day

96893735.

total: 10243.11

L/S: 8.21C

12358.80

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey 7 days after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

List Items Subtotal S\$ 0.00
Special Nett Items S\$ 50.00
Subtotal
Labour Items Subtotal S\$ 4,180.00

11139.48 Total S\$ 4,230.00

07/12/2016 13:16



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

GREAT AMERICAN INSURANCE COMPANY

Ref : CS/GAI16022726/Atbn2

3 TEMASEK AVENUE
#16-01 CENTENNIAL TOWER
SINGAPORE 039190

Date : 19-12-2017



Code : GAI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YP 3851K	Veh. Inspected	YN 5610L
Policy No.		Coverage (\$)	0.00
Claim No.	YP3851K	Excess (\$)	0.00
Assign From	STELLA GOH	Assign Date	29/11/2016

2. Vehicle Particulars & Condition

Make & Model	ISUZU NPR	c.c	2999
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	JAANPR85HE7100380	Colour	WHITE
Odometer	136966	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/85 R16	CHAO YANG	6 mm
L/H Front Tyre	205/85 R16	CHAO YANG	6 mm
R/H Rear Tyre	205/85 R16	CHAO YANG	6 mm
L/H Rear Tyre	205/85 R16	CHAO YANG	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	26/11/2016	Inspection Date	30/11/2016
Survey held at	TORQUE 5 PTE LTD 8 KAKI BUKIT AVENUE 4 #01-50 PREMIER @ KAKI BUKIT SINGAPORE 415875		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	14 Working Days
-------------------------------------	-----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YN 5610L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	RH DOOR	BUCKLED	882.00	882.00
1	RH DOOR HINGE TOP	BENT	98.00	98.00
1	RH DOOR HINGE BOTTOM	BENT	98.00	98.00
1	RH DOOR LOCK	DAMAGED	145.00	145.00
1	RH DOOR TRIM	CRACKED	279.00	279.00
1	RH DOOR TRIM CLIPS	NECESSARY	50.00	50.00
1	RH DOOR WEATHERSTRIP	CUT	182.00	182.00
1	RH DOOR REGULATOR	DAMAGED	295.00	295.00
1	RH DOOR POWER WINDOW MOTOR	DAMAGED	234.00	234.00
1	RH PILLAR	BUCKLED	279.00	279.00
1	RH DOOR GLASS	SHATTERED	295.00	295.00
1	RH SIDE MIRROR ASSY	MISSING	72.00	72.00
1	RH DOOR STEP	CUT	138.00	138.00
1	RH DOOR SIGNAL LAMP	CUT	95.00	95.00
1	FRONT WINDSCREEN	SHATTERED	1,600.00	1,600.00
1	FRONT WINDSCREEN RUBBER	NECESSARY	143.00	143.00
1	WIPER PANEL	DISTORTED	158.00	158.00
1	WIPER NOZZLE LH	NOT NECESSARY	49.90	-
1	WIPER NOZZLE RH	DAMAGED	49.90	49.90
1	WIPER ARM LH	NOT NECESSARY	87.00	-
1	WIPER ARM RH	CUT	87.00	87.00
1	FRONT BUMPER	DISTORTED	513.00	513.00
1	FRONT CROSSMEMBER	BENT	535.00	535.00
1	FRONT PANEL	DISTORTED	673.00	673.00
1	FRONT PANEL "ISUZU"	NECESSARY	143.00	143.00
1	FRONT GRILLE ASSY	CRACKED	414.00	414.00
1	HEADLAMP RH ASSY	CRACKED	298.00	298.00
1	RH CORNER PANEL	CRACKED	236.00	236.00
	LESS 15% DISCOUNT		-	-1,198.79
			8,128.80	6,793.11
<u>SPECIAL NETT ITEMS</u>				
1	FRONT NUMBER PLATE (SN)	BENT	50.00	50.00
			50.00	50.00

Report Ref No. CS/GAI16022726/Atbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO KNOCK & STRAIGHTEN ON ACCIDENT AREA,TO REMOVE & REFIT DAMAGE PARTS.		1,800.00	1,450.00
	TO PUTTY & RESPRAY ON ACCIDENT AFFECTED AREA.		1,600.00	1,400.00
	TO RUST PROOF ACCIDENT AFFECTED AREA.		160.00	80.00
	TO CHECK WIRING LAYOUT AND HEADLAMP FOCUS.		50.00	30.00
	TO REMOVE & REFIT FRONT WINDSCREEN.		150.00	120.00
	TO REMOVE & REFIT DASHBOARD TO ASSIST WORK LOAD.		300.00	220.00
	TO REMOVE & REFIT DOOR TRIM,DOOR GLASS,WINDOW REGULATOR,DOOR LOCK TO ASSIST WORK LOAD.		120.00	100.00
			4,180.00	3,400.00
	GRAND TOTAL		12,358.80	10,243.11
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			8,200.00

Report Ref No. CS/GAI16022726/Atbn2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.