

22/03/2002

ASS REC. BY:

REF: CS/C116022993/R1cd3

Special Instruction:

Surveyor:

ASSIGNMENT (Office,

From (Person):

Angie Foo

of

CIL

Date/Time: 02.12.2016 4.01pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKW 8873T

Insured:

SFL 8011H

at Workshop m/s

Hwa Peng Auto

Tel:

9688 5655 / 6365 6100

of

Blk 70 Woodlands Ind Park E

May

Policy No: DMCVSN30114621601

Claim No:

SNM16D05708C03/3

Sum Insured:

Excess:

Make of Veh:

D.O.A.

30.11.2016

(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp'

05.12.2016

H.O.D. Endorsement:

Date/Time: 02.12.2016 4.15pm

Person Contacted:

Francis

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SKW 8873T - NEA / C116022990 / Y
	SFL 8011H - CCS / A1A03806102 / KDN

DA: 30.11.16

DA: 15.01.2008

Surveyor: Tauhid Rabbu

**ASSIGNMENT**

From: \_\_\_\_\_ Date: 05.12.2016

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKW 8873T

at Workshop m/s Hwa Peng Auto  
of Blk 70 Woodlands Ind Park E

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_


Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS Wp

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SKW 8873T Yr Regn: Oct / 15

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: TOYOTA C.C. 1986

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 34368 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: 18U600038331

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 235/55R18

R: 22

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. \_\_\_\_\_ D.O.I. 05/12/16

Survey held at Hwa Peng

Des. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>24/19</u>	<u>Paul Kh confirmed 12 @ 16,800; 12 days with Franke thru phone. (Ref 24, 187, 40, 592)</u>

RECEIVED 03 APR 2019

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 12

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S + RS \$ 250

Photos

Others

TOTAL

Report Format : TP

Lump Sum / I.B.I: (\$16,800)

Add Fee: ☐ : Site Insp (\$ )

☐ : Interview (\$ )

☐ : Tech. Invs (\$ )

☐ : Weekend (\$ )

Signature

Taylor

REF:

CT1

# ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT  
Francis

Veh No

SKW 8873T

Yr Regn

2015, Oct.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Harrier.

C.C 1986

Colour:

Black

A/C

Insured / Std / NI / NA

Sp. Reading

34368

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

ZSY 600038331

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / SRim / STD A/Rim or

Tyre Size:

F:

235/55R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

5/12/16

Survey held at

Hua Peng

Des. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

24/19

confirm with Francis 1/5/16 800, 12 days time phone.

Date/Time: File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time: File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

Add Fee:

☐

Site Insp (\$

) - \$ + RS. \$

☐

Interview (\$

) Photos

☐

Tech Invs (\$

) Others

☐

Weekend (\$

)

Report Format :

Lump Sum / I.B.I: (\$

TOTAL




## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CS/CTI16022993/R1gb	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 02-12-2016	
		Code : CTI	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	SFG 8011H	Veh. Inspected	SKW 8873T
Policy No.		Coverage (\$)	0.00
Claim No.	SNM16D05708C02/3	Excess (\$)	0.00
Assign From	ANGIE FOO	Assign Date	02/12/2016
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
<b>4. Description of Damages</b>			
<b>5. General Information</b>			
Accident Date	30/11/2016	Inspection Date	05/12/2016
Survey held at	HWA PENG AUTO SERVICE (1996) 70 WOODLAND INDUSTRIAL PARK E SINGAPORE 757836		
<b>5a. Remarks</b>			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

**Catherine Chong (LKK Auto)**

---

**From:** Veron Chen (LKKAuto) <veronchen@lkkauto.com>  
**Sent:** Friday, 2 December, 2016 4:01 PM  
**To:** assignments  
**Subject:** FW: OUR REF: SNM16D05708C02/3 & YR REF: LCH.MY/W1HP-60899.16- TO CONDUCT PRE REPAR SURVEY - SKW8873T  
**Attachments:** 60899 (Nominated 3P's surveyor).pdf

Dear Assignment Team,

FYNA

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Angie Foo [mailto:angie.foo@sg.cntaiping.com]  
**Sent:** Friday, 2 December, 2016 3:42 PM  
**To:** Cheonghoh Law <mail@cheonghoh.sg>  
**Cc:** Chee So Chow <sochow.chee@sg.cntaiping.com>; Alfred Toh <alfred.toh@sg.cntaiping.com>; Admin A <admin-a@lkkauto.com>; Veron Chen (LKKAuto) <veronchen@lkkauto.com>; Denise Tay (LKKAuto) <denisetay@lkkauto.com>  
**Subject:** FW: OUR REF: SNM16D05708C02/3 & YR REF: LCH.MY/W1HP-60899.16- TO CONDUCT PRE REPAR SURVEY -SKW8873T

WITHOUT PREJUDICE  
SAVE AS TO COSTS

Dear Melody,

We refer to your email on even date.

We had appointed Mohd Taufikh –M/S LKK Auto Consultants Pte Ltd to conduct survey on your client's vehicle.

Please ensure that your client's vehicle is available for survey within 2 working days.

REMARKS:

Dear Taufikh,

Please conduct survey, check consistency of the damages on without prejudice.

Thank you.

Regards,  
Angie Foo  
Executive  
Motor Division  
Claims Department  
China Taiping Insurance (Singapore) Pte Ltd  
3 Anson Road #16-00  
Springleaf Tower  
Singapore 079909  
Co.Reg.No.200208384E  
DID: 6389 6186  
Fax: 6224 7478 /6224 7175  
Email: [angie.foo@sg.cntaiping.com](mailto:angie.foo@sg.cntaiping.com)  
Email: [claimsdept@sg.cntaiping.com](mailto:claimsdept@sg.cntaiping.com)  
Website: [www.sg.cntaiping.com](http://www.sg.cntaiping.com)

*Disclaimer*

*This message is confidential, its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.*

**From:** Cheong Hoh Lee [<mailto:mail@cheonghoh.sg>]  
**Sent:** Friday, 2 December, 2016 3:11 PM  
**To:** Angie Foo  
**Cc:** Chee So Chow; Alfred Toh; Claims Dept of CTI  
**Subject:** Re: OUR REF: SNM16D05708C02/3 & YR REF: LCH.MY/W1HP-60899.16- TO CONDUCT PRE REPAR SURVEY -SKW8873T

Dear Angie,

Please see attached letter for your attention and arrangement.

Regards,  
Melody  
Cheonghoh Law Corporation  
Blk 53 Chin Swee Road #03-05  
Singapore 160053  
Tel: 6337 8700  
Fax: 6337 3700

\* With effect from 7 December 2015, our office is located at Blk 53 Chin Swee Road #03-05  
Singapore 160053

## **Cheonghoh Law Corporation**

(Incorporated with limited liability) Blk 53 Chin Swee Road #03-05 Singapore 160053  
Co. Reg No.201108070G Tel: 63378700 Fax: 63373700 E-mail: mail@cheonghoh.sg

---

In reply, please quote our Reference Number

Our Ref: LCH.my/W1HP-60899.16  
Your Ref: PRS/SNM16D05708

2 December 2016

**URGENT ATTENTION**

China Taiping Insurance (Singapore) Pte Ltd  
3 Anson Road #15-00  
Springleaf Tower  
Singapore 079909  
Attn: Angie Foo

**BY FAX & EMAIL**  
Fax No: 6224 7478

Dear Sirs

**ACCIDENT INVOLVING VEHICLES NO SKW 8873 T AND GBA 1833 C / SFG 8011 H ON 30 NOVEMBER 2016 AT/ALONG THE CTE TOWARDS THE SLE -**

We refer to the above matter and to our tele- conversation this afternoon.

As spoken, Our client hereby nominate Mohamad Taufikh from LKK Auto Consultants Pte Ltd to conduct the pre-repair survey of the damages to our client's vehicle arising out of the above mentioned accident.

Please be informed that our client's vehicle, SKW 8873 T is currently laying at our client's workshop, Hwa Peng Auto Service (1996), Blk 70 Woodlands Industrial Park E Singapore 757836.

Kindly proceed to do the needful.

Yours faithfully



Lee Cheong Hoh  
**CHEONGHOH LAW CORPORATION**

cc: client - via fax only (SKW 8873 T)

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type	Singapore NRIC
Owner ID	5169D
<b>Vehicle Details</b>	
Vehicle No.	SKW8873T
Vehicle to be Exported	No
Intended De-registration Date	04 Dec 2017
Vehicle Make	TOYOTA
Vehicle Model	HARRIER 2.0 PREMIUM CVT 2WD SR
Primary Colour	Black
Manufacturing Year	2015
Engine No.	3ZRB514180
Chassis No.	ZSU600038331
Maximum Power Output	111.0 kW (148 bhp)
Open Market Value	\$29,366.00
Original Registration Date	13 Oct 2015
First Registration Date	13 Oct 2015
Transfer Count	0
Actual ARF Paid	\$28,113.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility	Yes
PARF Eligibility Expiry Date	12 Oct 2025
PARF Rebate Amount	\$21,084.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date	12 Oct 2025
COE Category	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years)	10
QP Paid	\$58,190.00
COE Rebate Amount	\$45,707.00
<b>Total Rebate Amount</b>	<b>\$66,791.00</b>

The information contained herein is correct as at 04 Dec 2017

OK



> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	5169D
<b>Vehicle Details</b>	
Vehicle No.:	SKW8873T
Vehicle to be Exported:	No
Intended Deregistration Date:	03 Apr 2019
Vehicle Make:	TOYOTA
Vehicle Model:	HARRIER 2.0 PREMIUM CVT 2WD SR
Primary Colour:	Black
Manufacturing Year:	2015
Engine No.:	3ZRB514180
Chassis No.:	ZSU600038331
Maximum Power Output:	111.0 kW (148 bhp)
Open Market Value:	\$29,366.00
Original Registration Date:	13 Oct 2015
First Registration Date:	13 Oct 2015
Transfer Count:	0
Actual ARF Paid:	\$28,113.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	12 Oct 2025
PARF Rebate Amount:	\$21,084.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	12 Oct 2025
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$58,190.00
COE Rebate Amount:	\$37,964.00
<b>Total Rebate Amount:</b>	<b>\$59,048.00</b>

The information contained herein is correct as at 03 Apr 2019

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	01/12/2016 17:08
Date Of Accident	30/11/2016 16:15
Exact Location Of Accident	CTE TOWARDS AYE
Country/State of Loss	Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKW8873T
<b>Insured/Policyholder</b>	
Name Of Registered Owner	BOO CHOON CHIK (WU JUNJIE)
Co Reg No	S7315169D
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	Office-93882048

### Vehicle Particulars

Manufacturer	TOYOTA
Model	HARRIER-2.0 (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	No
If No, Please state action to be taken	Third Party
Vehicle Category	Private Car

### Insurance Company

Name of Insurance Company	NTUC Income Insurance Co-operative Ltd
Type Of Coverage	Comprehensive
Fleet Policy	No
Policy Number	5084377252
Cover Note Number	

### Driver

Name of Driver	JACLYN CHUA
NRIC No	S7328714F
Date Of Birth	08/08/1973
Occupation	Indoor
Date Of Driving Pass	03/01/1996
Driving Experience	20 Years And 10 Months
Gender	Female
Mobile Number	(Local) +65-93882048
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	89 YISHUN AVE 1 #01-07 SINGAPORE
Postcode	769134
Was driver an employee of the Insured's Company	No
If No, Relationship of the Driver with the Insured	Spouse
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	Collision- Chain Collision
Weather Conditions	Clear
Road Surface	Dry

#### Other Information

Was any foreign vehicle involved in this accident?	No
Was any body injured in the Accident?	No
Was any other material or property damaged?	Yes
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	No
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	No
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	No
If Yes, against whom?	

#### Circumstances of Accident

REFER ATTACHED

#### Attachment(s)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBA1833C
Vehicle Make/Model/Colour	
Details Of Properties	
Name of Driver	LIM SIEW HEE
NRIC/Passport Number	S1420193I
Contact Number	97124264
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

#### Details of Witness

Name	
Phone Number	
Email Address	

#### DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SFG8011H
Vehicle Make/Model/Colour	
Details Of Properties	

Name of Driver	TAN BENG HUAT
NRIC/Passport Number	S0219695F
Contact Number	93876729
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

**Details of Witness**

Name	
Phone Number	
Email Address	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)  
I understand, acknowledge, agree and consent that :  
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :  
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;  
(ii) investigating the accident and/or my claims;  
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;  
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or  
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.  
(collectively the "Purposes")  
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and  
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

A: SKW 8873T

B: GBA 1833C

C: SFG 8011H

☒ B ☒ A ☒ C

## Describe Circumstances of the Accident

On mentioned date and time, I was driving along CTE towards SKE on the extreme LH lane. Vehicle (C) which was ahead of me suddenly brake and I could stop in time. Vehicle (B) which was travelling behind me, couldn't stop in time and collided against my vehicle. Due to the heavy impact, my vehicle was thrown forward / surge forward and collided against vehicle (C). My vehicle front and rear section were very badly damaged. At the time of accident, no one injured and No Ambulance to the accident scene.


## Declaration

We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel



# 華平汽車服務 HWA PENG AUTO SERVICE (1996)

70 Woodlands Industrial Park E9 Singapore 757836

TEL: 6365 6100 FAX: 6365 6101

Spray Painting • Panel Beating • Body Repair • Engine Tuning • Towing Service • Insurance Claim • L.T.A. Inspection Service  
Co. Reg 52823719E

## ESTIMATE REPORT

Mr Boo Choon Chik  
C/o 70 Woodlands Industrial Park E9  
Singapore 757836

Vehicle Number : SKW 8873T  
Mark And Model : Toyota Harrier 2.0(A)  
Date of Accident : 30 Nov 2016

S/No	Parts	QTY	Unit Price	List Price
1	Front Bumper Cover 1465	1		\$ 1,455.90 de✓
2	Front Bumper Lower Gasnish	1		\$ 298.80 de✓
3	Front Bumper Fog Lamp	2	\$ 284.50	\$ 569.00 xnn
4	Front Bumper Fog Lamp Garnish	2	\$ 82.90	\$ 165.80 xnn
5	Front Bumper Lower Grille	1		\$ 238.30 de✓
6	Front Bumper Side Retainer	2	\$ 92.00	\$ 184.00 ne✓
7	Front Bumper Side Holder	2	\$ 101.90	\$ 203.80 ne✓
8	Front Bumper foam - Centre	1		\$ 101.90 de✓
9	Front Bumper foam - Side	2	\$ 66.95	\$ 133.90 de✓
10	Front Bumper Inner Air Guide	2	\$ 102.30	\$ 204.60 xnn
11	Front Bumper Clip	1 set		\$ 42.60 ne✓
8	Front Bumper Tow Hook Cover	2	\$ 26.90	\$ 53.80 de✓
9	Front Bumper Upper Grille 689.50	1		\$ 555.90 cut✓
10	Front Bumper Upper Grille Logo	1		\$ 82.10 ne✓
11	Front Bumper Upper Grille Clip	1 set		\$ 19.20 ne✓
12	Front Bumper Lower Air Guide	1		\$ 189.65 xnn
13	Headlamp @3305	2	\$ 3,221.90	\$ 6,443.80 cre✓
14	Radiator Top Panel Garnish	1		\$ 224.10 de✓
15	Radiator Top Panel Garnish Clip	1 set		\$ 18.90 ne✓
16	Bonnet	1		\$ 1,378.90 RX✓
17	Bonnet Outer Moulding	1		\$ 289.70 cut✓
18	Bonnet Insulator	1		\$ 608.50 xnn
19	Bonnet Insulator Clip	1 set		\$ 31.20 xnn
20	Bonnet Lock	1		\$ 142.30 bt✓
21	Bonnet Lock Panel	1		\$ 220.60 bt✓
22	Air Con Condenser 1447.80	1		\$ 1,449.60 bt✓
23	Air Con Hose - Short	1		\$ 489.30 x
24	Air Con Hose - Long	1		\$ 386.10 x
25	Air Con Pipe - High Pressure	1		\$ 567.90 x
26	Air Con Pipe - Low Pressure	1		\$ 1,013.80 x
27	Radiator	1		\$ 2,068.30 x
28	Radiator Upper Hose	1		\$ 45.80 x

To be continued next page 2





# 華平汽車服務 HWA PENG AUTO SERVICE (1996)

70 Woodlands Industrial Park E9 Singapore 757836

TEL: 6365 6100 FAX: 6365 6101

Spray Painting • Panel Beating • Body Repair • Engine Tuning • Towing Service • Insurance Claim • L.T.A. Inspection Service  
Co. Reg 52823719E

Page 2

S/No	Parts	QTY	Unit Price	List Price
29	Radiator Lower Hose	1		\$ 55.40x
30	Electric Fan Shroud	1		\$ 291.60x
31	Radiator Fan Blade	1		\$ 180.60x
32	Radiator Fan Blade Motor	1		\$ 510.60x
33	Air Con Fan Blade	1		\$ 185.60x
34	Air Con Fan Blade Motor	1		\$ 548.90x
35	Sensor Assy. Millimeter Wave Radar	1		\$ 2,255.10x
36	Sensor Assy. Millimeter Wave Radar Bracket	1		\$ 42.10nd
37	Headlamp Upper Panel	2	\$ 780.90	\$ 1,561.80bt
38	Front Fender Inner Top Garnish	2	\$ 161.80	\$ 323.60xnn
39	Rear Bumper 1395.40	1		\$ 1,395.90de
40	Rear Bumper Lower Garnish	1		\$ 57.60nd
41	Rear Bumper Reflector	2	\$ 58.60	\$ 117.20xnn
42	Rear Bumper Side Retainer	2	\$ 65.10	\$ 130.20nd
43	Rear Bumper Side Holder	2	\$ 85.60	\$ 171.20nd
44	Rear Bumper Reinforcement	1		\$ 190.85x
45	Rear Bumper Foam	1		\$ 106.20x
46	Rear Bumper Clip	1 set		\$ 16.80nd
47	Tail Gate 1813.40	1		\$ 1,762.00bt
48	Tail Gate Weatherstrip	1		\$ 367.90de
49	Tail Gate Lock Mechanism	1		\$ 981.40bt
50	Tail Gate Side Rubber Moulding	2	\$ 102.30	\$ 204.60nd
51	Tail Gate Side Rubber Moulding Clip	2 set	\$ 16.20	\$ 32.40nd
52	Tail Gate Badge - HARRIER	1		\$ 58.60nd
53	Tail Gate Lamp @488.53	2	\$ 466.20	\$ 932.40LH, RH x
54	Tail Gate Wiper Motor	1		\$ 633.90xnn
55	Tail Gate Outer Garnish 1135.50			\$ 1,135.90nd
56	Tail Gate Outer Garnish Clip	1 set		\$ 22.10nd
57	Tail Gate Outer Garnish Logo	1		\$ 85.95nd
58	Tail Gate Rubber Stopper	2	\$ 19.20	\$ 38.40nd
59	Taillamp	2	\$ 510.60	\$ 1,021.20xnn
60	Rear End Panel 781.10	1		\$ 731.95bt
61	Rear End Panel Top Garnish	1 set		\$ 369.90de
62	Rear End Panel Top Garnish Clip	1		\$ 18.50nd
63	Spare Tyre Panel	1		\$ 766.90Ry

To be continued next page 3





# 華平汽車服務 HWA PENG AUTO SERVICE (1996)

70 Woodlands Industrial Park E9 Singapore 757836

TEL: 6365 6100 FAX: 6365 6101

Spray Painting • Panel Beating • Body Repair • Engine Tuning • Towing Service • Insurance Claim • L.T.A. Inspection Service  
Co. Reg 52823716E

Page 3

S/No	Parts	QTY	Unit Price	List Price
64	Spare Tyre Panel Board	1		\$ 549.90
65	Spare Tyre Panel Side Compartment - R/H	1		\$ 507.30
66	Spare Tyre Panel Side Compartment - L/H	1		\$ 510.20
67	Spare Tyre Panel Inner Compartment - L/H	1		\$ 561.90
68	Spare Tyre Panel Inner Board	1		\$ 510.60
69	Sapre Tyre Panel Side Board - R/H	1		\$ 155.20
70	Sapre Tyre Panel Side Board - L/H	1		\$ 157.10

25%  
Less 20%  
\$ 40,135.50  
\$ (8,027.10)  
21810.60  
16357.95

Total : \$ 32,108.40

## Special Nett Item

71	Front Number Plate	1		\$ 60.00 cur ✓
72	Rear Number Plate	1		\$ 60.00 Xnn ✓
73	Radiator Coolant	1		\$ 34.00 nei ✓
74	Rear End Panel Sealant	1		\$ 100.00 6onei ✓
75	Rear Windscreen Sealant	1		\$ 100.00 nei ✓
76	Front Bumper Sensor	1		\$ 300.00 250mm ✓
77	Rear Bumper Sensor	1		\$ 320.00 250mm ✓
78	Sun-roof Motor	1		\$ 1,605.00 Xnn ✓

Total : \$ 2,579.00 739

## Labour & Misc Charges

To provide towing	\$ 100.00 Xnn.
To check wiring	\$ 100.00 50
To remove and replace air con components.	\$ 150.00 100
To remove and replace damaged parts(rear section)	\$ 1,620.00 1000
To remove and replace damaged parts(front section)	\$ 1,100.00 700
To respray replaced and affected panels (rear section)	\$ 1,400.00 1200
To respray replaced and affected panels (front section)	\$ 1,000.00 600
To insatl both bumper sensors.	\$ 150.00 60.
To remove & install rear compartment fittings.	\$ 180.00 60.
To remove & replace radiator assembly.	\$ 100.00 Xnn
To check wiring for proper functions.	\$ 100.00 Xnn.
To replace rear windscreen glass	\$ 200.00 120.
To trafer boot mechanism & trimming.	\$ 100.00 60

\$ 6,300.00 3950.

Grand Total : \$ 40,987.40

16357.15  
739  
4050  
21046.95  
15\$16800\* 12 days

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI16022993/R1CD3N2

Date: 03/04/2019

## REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN3014621601	
Claimant Vehicle No :	SKW8873T	Insured Vehicle No :	GBA1833C	
Date of Loss:	30/11/2016	Nature of Claim:	TP	Claim No: SNM16D05708C02

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SKW8873T	Engine No:	3ZRB514180
Make & Model:	TOYOTA HARRIER, 2.0 (A)	Chassis No:	ZSU600038331
Reg. Date:	13/10/2015 (Man. Year: 2015)	Odometer:	34368 km
Colour:	Black		
Engine Capacity:	1986 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	235/55R18	Rear Tyre Size:	235/55R18
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

## COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	34,687.40	17,096.95	17,590.45	50.71
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,300.00	3,950.00	2,350.00	37.30
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>40,987.40</b>	<b>21,046.95</b>	<b>19,940.45</b>	<b>48.65</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>16,800.00</b>		
<b>Nett Amount (\$\$)</b>	<b>40,987.40</b>	<b>16,800.00</b>	<b>24,187.40</b>	<b>59.01</b>

## INSPECTION

Date of Assignment:	13/12/2016	
Date Inspected:	05/12/2016 Inspected At:	Hwa Peng Auto Service (HQ) 70 WOODLANDS INDUSTRIAL PARK E9 SINGAPORE 757836 Singapore 757836
Estimated Period of Repair:	12.0 days	

Adjuster: MOHD RASUL

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

## Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 03 Apr 2019)
<b>Parts:</b>	M1-SUV	TOYOTA HARRIER 2.0 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SKW8873T)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER COVER	Deformed	1,455.90 FL	*1,455.90 FL
2	1		*FRONT BUMPER LOWER GARNISH	Deformed	298.80 FL	*298.80 FL
3	2		*FRONT BUMPER FOG LAMP	Not Necessary	569.00 FL	*- FL
4	2		*FRONT BUMPER FOG LAMP GARNISH	Not Necessary	165.80 FL	*- FL
5	1		*FRONT BUMPER LOWER GRILLE	Deformed	238.30 FL	*238.30 FL
6	2		*FRONT BUMPER SIDE RETAINER	Necessary	184.00 FL	*184.00 FL
7	2		*FRONT BUMPER SIDE HOLDER	Necessary	203.80 FL	*203.80 FL
8	1		*FRONT BUMPER FOAM-CENTRE	Deformed	101.90 FL	*101.90 FL
9	2		*FRONT BUMPER FOAM-SIDE	Deformed	133.90 FL	*133.90 FL
10	2		*FRONT BUMPER INNER AIR GUIDE	Not Necessary	204.60 FL	*- FL
11	1		*SET FRONT BUMPER CLIP	Necessary	42.60 FL	*42.60 FL
12	2		*FRONT BUMPER TOW HOOK COVER	Deformed	53.80 FL	*53.80 FL
13	1		*FRONT BUMPER UPPER GRILLE	Cut	555.90 FL	*555.90 FL
14	1		*FRONT BUMPER UPPER GRILLE LOGO	Necessary	82.10 FL	*82.10 FL
15	1		*SET FRONT BUMPER UPPER GRILLE CLIP	Necessary	19.20 FL	*19.20 FL
16	1		*FRONT BUMPER LOWER AIR GUIDE	Not Necessary	189.65 FL	*- FL
17	2		*HEADLAMP	Cracked	6,443.80 FL	*6,443.80 FL
18	1		*RADIATOR TOP PANEL GARNISH	Deformed	224.10 FL	*224.10 FL
19	1		*SET RADIATOR TOP PANEL GARNISH CLIP	Necessary	18.90 FL	*18.90 FL
20	1		*BONNET	Repair	1,378.90 FL	*- FL
21	1		*BONNET OUTER MOULDING	Cut	289.70 FL	*289.70 FL
22	1		*BONNET INSULATOR	Not Necessary	608.50 FL	*- FL
23	1		*SET BONNET INSULATOR CLIP	Not Necessary	31.20 FL	*- FL
24	1		*BONNET LOCK	Bent	142.30 FL	*142.30 FL
25	1		*BONNET LOCK PANEL	Bent	220.60 FL	*220.60 FL
26	1		*AIR CON CONDENSER	Bent	1,449.60 FL	*1,449.60 FL
27	1		*AIR CON HOSE-SHORT	Not Necessary	489.30 FL	*- FL
28	1		*AIR CON HOSE-LONG	Not Necessary	386.10 FL	*- FL
29	1		*AIR CON PIPE-HIGH PRESSURE	Not Necessary	567.90 FL	*- FL
30	1		*AIR CON PIPE-LOW PRESSURE	Not Necessary	1,013.80 FL	*- FL
31	1		*RADIATOR	Not Necessary	2,068.30 FL	*- FL
32	1		*RADIATOR UPPER HOSE	Not Necessary	45.80 FL	*- FL
33	1		*RADIATOR LOWER HOSE	Not Necessary	55.40 FL	*- FL
34	1		*ELECTRIC FAN SHROUD	Not Necessary	291.60 FL	*- FL
35	1		*ELECTRIC FAN BLADE	Not Necessary	180.60 FL	*- FL
36	1		*ELECTRIC FAN BLADE MOTOR	Not Necessary	510.60 FL	*- FL
37	1		*AIR CON FAN BLADE	Not Necessary	185.60 FL	*- FL
38	1		*AIR CON FAN BLADE MOTOR	Not Necessary	548.90 FL	*- FL
39	1		*SENSOR ASSY MILLIMETER WAVE RADAR	Not Necessary	2,255.10 FL	*- FL
40	1		*SENSOR ASSY MILLIMETER WAVE RADAR BRACKET	Necessary	42.10 FL	*42.10 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
41	2		*HEADLAMP UPPER PANEL	Bent	1,561.80 FL	*1,561.80 FL
42	2		*FRONT FENDER INNER TOP GARNISH	Not Necessary	323.60 FL	*- FL
43	1		*REAR BUMPER	Deformed	1,395.90 FL	*1,395.90 FL
44	1		*REAR BUMPER LOWER GARNISH	Cut	57.60 FL	*57.60 FL
45	2		*REAR BUMPER REFLECTOR	Not Necessary	117.20 FL	*- FL
46	2		*REAR BUMPER SIDE RETAINER	Necessary	130.20 FL	*130.20 FL
47	2		*REAR BUMPER SIDE HOLDER	Necessary	171.20 FL	*171.20 FL
48	1		*REAR BUMPER REINFORCEMENT	Not Necessary	190.85 FL	*- FL
49	1		*REAR BUMPER FOAM	Not Necessary	106.20 FL	*- FL
50	1		*SET REAR BUMPER CLIP	Necessary	16.80 FL	*16.80 FL
51	1		*TAIL GATE	Bent	1,762.00 FL	*1,762.00 FL
52	1		*TAIL GATE WEATHERSTRIP	Deformed	367.90 FL	*367.90 FL
53	1		*TAIL GATE LOCK MECHANISM	Bent	981.40 FL	*981.40 FL
54	2		*TAIL GATE SIDE RUBBER MOULDING	Necessary	204.60 FL	*204.60 FL
55	2		*SET TAIL GATE SIDE RUBBER MOULDING CLIP	Necessary	32.40 FL	*32.40 FL
56	1		*TAIL GATE BADGE-HARRIER	Necessary	58.60 FL	*58.60 FL
57	1		*TAIL GATE LAMP	N/s Cracked/O/s Not Necessary	932.40 FL	*466.20 FL
58	1		*TAIL GATE WIPER MOTOR	Not Necessary	633.90 FL	*- FL
59	1		*TAIL GATE OUTER GARNISH	Cut	1,135.90 FL	*1,135.90 FL
60	1		*SET TAIL GATE OUTER GARNISH CLIP	Necessary	22.10 FL	*22.10 FL
61	1		*TAIL GATE OUTER GARNISH LOGO	Necessary	85.95 FL	*85.95 FL
62	2		*TAIL GATE RUBBER STOPPER	Necessary	38.40 FL	*38.40 FL
63	2		*TAILLAMP	Not Necessary	1,021.20 FL	*- FL
64	1		*REAR END PANEL	Bent	731.95 FL	*731.95 FL
65	1		*SET REAR END PANEL TOP GARNISH	Deformed	369.90 FL	*369.90 FL
66	1		*REAR END PANEL TOP GARNISH CLIP	Necessary	18.50 FL	*18.50 FL
67	1		*SPARE TYRE PANEL	Repair	766.90 FL	*- FL
68	1		*SPARE TYRE PANEL BOARD	Not Necessary	549.90 FL	*- FL
69	1		*SPARE TYRE PANEL SIDE COMPARTMENT-R/H	Not Necessary	507.30 FL	*- FL
70	1		*SPARE TYRE PANEL SIDE COMPARTMENT-L/H	Not Necessary	510.20 FL	*- FL
71	1		*SPARE TYRE PANEL INNER COMPARTMENT-L/H	Not Necessary	561.90 FL	*- FL
72	1		*SPARE TYRE PANEL INNER BOARD	Not Necessary	510.60 FL	*- FL
73	1		*SPARE TYRE PANEL SIDE BOARD-R/H	Not Necessary	155.20 FL	*- FL
74	1		*SPARE TYRE PANEL SIDE BOARD-L/H	Not Necessary	157.10 FL	*- FL
75	1		*FRONT NUMBER PLATE	Cracked	60.00 FS	*45.00 FS
76	1		*REAR NUMBER PLATE	Not Necessary	60.00 FS	*- FS
77	1		*RADIATOR COOLANT	Necessary	34.00 FS	*34.00 FS
78	1		*REAR END PANEL SEALANT	Necessary	100.00 FS	*60.00 FS
79	1		*REAR WINDSCREEN SEALANT	Necessary	100.00 FS	*100.00 FS
80	1		*FRONT BUMPER SENSOR	Not Working	300.00 FS	*250.00 FS
81	1		*REAR BUMPER SENSOR	Not Working	320.00 FS	*250.00 FS
82	1		*SUN-ROOF MOTOR	Not Necessary	1,605.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	42,714.50	22,549.60
- List Item Discount on L Items 20.00/25.00% (\$\$)	8,027.10	5,452.65
Total Parts (\$\$)	34,687.40	17,096.95

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO PROVIDE TOWING	New	100.00	0.00
2	TO CHECK WIRING	New	100.00	50.00
3	TO REMOVE AND REPLACE AIR CON COMPONENTS	New	150.00	100.00
4	TO REMOVE AND REPLACE DAMAGED PARTS (REAR SECTION)	New	1,620.00	1,000.00
5	TO REMOVE AND REPLACE DAMAGED PARTS (FRONT SECTION)	New	1,100.00	700.00
6	TO RESPRAY REPLACED AND AFFECTED PANELS (REAR SECTION)	New	1,400.00	1,200.00
7	TO RESPRAY REPLACED AND AFFECTED PANELS (FRONT SECTION)	New	1,000.00	600.00
8	TO INSTALL BOTH BUMPER SENSORS	New	150.00	60.00
9	TO REMOVE & INSTALL REAR COMPARTMENT FITTINGS	New	180.00	60.00
10	TO REMOVE & REPLACE RADIATOR ASSEMBLY	New	100.00	0.00
11	TO CHECK WIRING FOR PROPER FUNCTIONS	New	100.00	0.00
12	TO REPLACE REAR WINDSCREEN GLASS	New	200.00	120.00
13	TO TRAHER BOOT MECHANISM & TRIMMING	New	100.00	60.00
Gross Labour Cost (\$\$)			<b>6,300.00</b>	<b>3,950.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >