

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AXA17000133/APA3Q2
Date: 29/12/2021

REFERENCE

Handling Insurer:	AXA Insurance Pte Ltd	Policy No:	GA113129
Claimant Vehicle No :	SLF6788Y	Insured Vehicle No :	SDS297M
Date of Loss:	31/12/2016	Nature of Claim:	TP
		Claim No:	C0415064

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLF6788Y		
Make & Model:	BMW 318I, 2.0 L ABS D/AIRBAG 2WD 4DR SR (A)	Engine No:	B626I700N46B20BZ
Reg. Date:	29/06/2010 (Man. Year: 2010)	Chassis No:	WBAPF72000A793830
Colour:	Silver	Odometer:	75872 km
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/40 R18	Rear Tyre Size:	225/40 R18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,709.95	3,554.00	3,155.95	47.03
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,130.00	550.00	1,580.00	74.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,839.95	4,104.00	4,735.95	53.57
Approved Total (Overridden) (S\$)		2,100.00		

Nett Amount (S\$)	8,839.95	2,100.00	6,739.95	76.24
+ Loss of Use (4.0 x S\$100.00/day) (S\$)		400.00		
+ Doc/Search Fee (S\$)		5.35		
Nett Liability (S\$)		2,505.35		
Global Sum Settlement (S\$)		2,500.00		

INSPECTION

Date of Assignment: 04/01/2017

Date Inspected: 04/01/2017

Estimated Period of Repair: 4.0 days

Inspected At:

New Hock Teck Motor Workshop (HQ)
 Blk 1, Kaki Bukit Avenue 6 #01-43, AutoBay @ Kaki Bukit
 Singapore 417883

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 04 May 2021)
Parts:	143	BMW 318I 2.0 L ABS D/AIRBAG 2WD 4DR SR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLF6788Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET (CONSISTENT)	Not Necessary	1,166.55 F	*- FL
2	1		*FRONT BONNET EMBLEM (CONSISTENT)	Not Necessary	66.15 F	*- FL
3	2		*FRONT HEAD LAMP (CONSISTENT)	Cracked	2,110.50 F	*2,110.50 FL
4	2		*FRONT HEAD LAMP LOWER BRACKET (CONSISTENT)	Cracked	137.00 F	*137.00 FL
5	2		*FRONT GRILLE (CONSISTENT)	Cracked	269.20 F	*269.20 FL
6	8		*FRONT GRILLE CLIP (CONSISTENT)	Not Necessary	52.00 F	*- FL
7	1		*FRONT BUMPER (CONSISTENT)	Deformed	998.00 F	*998.00 FL
8	8		*FRONT BUMPER CLIP (CONSISTENT)	Necessary	52.00 F	*52.00 FL
9	2		*FRONT BUMPER SIDE RETAINER (CONSISTENT)	Necessary	57.80 F	*57.80 FL
10	2		*FRONT BUMPER FOG LAMP (CONSISTENT)	Not Necessary	491.40 F	*- FL
11	2		*FRONT BUMPER FOG LAMP COVER (CONSISTENT)	Not Necessary	137.90 F	*- FL
12	1		*FRONT BUMPER LOWER GRILLE (CONSISTENT)	Deformed	66.55 F	*66.55 FL
13	1		*FRONT BUMPER REINFORCEMENT (CONSISTENT)	Not Necessary	523.75 F	*- FL
14	1		*FRONT BUMPER NUMBER PLATE (CONSISTENT)	Bent	50.00 F	*50.00 FL
15	1		*FRONT SUPPORT PANEL (CONSISTENT)	Not Necessary	531.15 F	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	6,709.95	3,741.05
- List Item Discount on L Items 0.00/5.00% (\$\$)	0.00	187.05
Total Parts (\$\$)	6,709.95	3,554.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE & REFIT AIR-CON CONDENSER ,RADIATOR ,FAN MOTOR & TOP UP GAS	New	280.00	0.00
2	TO CHECK WIRING	New	100.00	50.00
3	TUFF KOTE	New	150.00	0.00
4	PANEL BEATING	New	800.00	250.00
5	SPRAY PAINTING	New	800.00	250.00
Gross Labour Cost (S\$)			2,130.00	550.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >