

2/2/2017

S.S. REC. BY:

REF: CSMCH 17003724 / R 1rb 9

Special Instruction:

Surveyor

Rusu

ASSIGNMENT (Office)

From (Person):

Mg Chen Hui

of

MSECH

Date/Time:

22/2/2017 5:29pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SUC 1863J

Insured:

SKX 6360P

at Workshop m/s

chunni Motor

Tel:

65425119 / 64836016 (William)

of

Blk 10 AME Ind Park #03-19 Antapoint

Policy No:

80422270@my

Claim No:

505399

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A

21/2/2017

CA / REV / REP. / REV 24 HRS (w/p)

H.O.D. Endorsement:

Date/Time:

23/1/2017

Person Contacted:

Lynn

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SUC 1863J
	SKX 6360P
27/2/17	Sent poli through Menimen
20/7/2017 @ 3:15pm	Lynn said pending firelice with PCSI.

ASSIGNMENT

From: Date: 23/2/2017

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SHC 1863J
at Workshop m/s Churni Motor

of

Insured:

Policy No.

Claims No.


Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

WPI

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SHC 1863J Yr Regn: 2012 / APR

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai Sonata 2.0 c.c 1991

Colour: BLUE A/C: Insured / Std / NI / NA

Sp. Reading: 814319 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: KM HET 41 VM C48 24546

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: N/S / S/Rim / STD A/Rim or

Tyre Size: F: 216/60R16

R: 22

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or MAXX

Front

Rear

R/Bal: 5 mm R/Bal: 5 mm

L/Bal: 5 mm L/Bal: 5 mm

D.O.A: 21/02/17 D.O.I: 23/02/17

Survey held at Churni

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

30/10

Elaine call up to submit report because they have reject the claim.

2/5

Submit preli report.

RECEIVED 02 MAY 2018

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: 8

1)

☐ : Final Report

Resurvey No. of Trip: -

Date/Time, File Return to?

Survey Fee:

2)

Add Fee: ☐ Site Insp (\$

) \$ + RS \$

Report Format : TP

Lump Sum / I.B.I: (\$ Preli report:)

☐ Interview (\$

) Photos

☐ Tech. Invs (\$

) Others

☐ Weekend (\$

)

TOTAL

Survey Department Check List (Case Handler)

Reference No. : CE/MEG/17003724/R1rb
Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (Catherine): Case handler to make sure all Information created by the assignment team are ACCURATE.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code	✓			
N	Assign From	✓			
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (Rasul): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount				
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded				
---	-------------------------	--	--	--	--

Check By:

Catherine 2/5/18

Case Handler

Date

*C: Critical *N: Non-Critical

21/05/20



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG17003724/R1gh3		
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 22-02-2017		
		Code : MSG		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKX 6360P	Veh. Inspected	SHC 1863J	
Policy No.	80422270QMY	Coverage (\$)	0.00	
Claim No.	505399	Excess (\$)	0.00	
Assign From	MERIMEN (NG CHEN HOW)	Assign Date	22/02/2017	
2. Vehicle Particulars & Condition				
Make & Model	c.c		0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	21/02/2017	Inspection Date	23/02/2017	
Survey held at	CHUNNI MOTOR WORK PTE LTD BLK 10 ANG MO KIO IND. PARK 2A, #03-19 AMK AUTOPOINT SINGAPORE 568047.			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: NG CHEN HOW

Date: 27 Feb 2017

Preliminary Advice

Insured Vehicle No	: SKX6360P	Accident Date	: 21/02/2017
TP Vehicle No	: SHC1863J	Assignment Date	: 22/02/2017
Make	: HYUNDAI SONATA	Est. Duration of Repair	: 8.00
Date of Inspection	: 23/02/2017		
Inspection At	: Chunni Motor Work Pte Ltd (HQ) Blk 10 Ang Mo Kio Industrial Park 2A, #03-19 AMK Autopoint Singapore 568047		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	19,611.72
Revised Amount	:S\$	10,324.52
Check Items (Estimated)	:S\$	2,476.24
Total	:S\$	12,800.76

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 3821R

Vehicle Details

Vehicle No.: SHC1863J

Vehicle to be Exported: No

Intended De-registration Date: 02 May 2018

Vehicle Make: HYUNDAI

Vehicle Model: SONATA NF 2.0 CRDI AT ABS 2WD 4DR TURBO

Primary Colour: Blue

Manufacturing Year: 2012

Engine No.: D4EAC084659

Chassis No.: KMHET41VMCA824546

Maximum Power Output: 110.0 kW (147 bhp)

Open Market Value: \$14,560.00

Original Registration Date: 30 Apr 2012

First Registration Date: 30 Apr 2012

Transfer Count: 0

Actual ARF Paid: \$14,560.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 29 Apr 2020

PARF Rebate Amount: \$9,464.00

Intended COE Rebate Details

COE Expiry Date: 29 Apr 2020

COE Category: A - Car (1600cc & below)

COE Period(Years): 8

PQP Paid: \$42,384.00

COE Rebate Amount: \$10,551.00

Total Rebate Amount: \$20,015.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 02 May 2018

OK

MCOM0016 / ComfortDelGro Engineering Pte Ltd - Linyang
ENF TRATE & TIME: 22/02/2017 15:21

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. After the reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available also.

ACCIDENT STATEMENT

Date Of Report 22/02/2017 15:21
Date Of Accident 21/02/2017 14:05
Exact Location Of Accident RANGOON RD RIGHT TURN > TESSENSOHN RD
County/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SHC1863J
Insured/Policyholder
Name Of Registered Owner COMFORT TRANSPORTATION PTE LTD
Co Reg No 199303821R
Email Address fleetsafety@cdgtaxi.com.sg
Mobile Phone No
Alternative Phone No Office-65508768
Vehicle Particulars
Manufacturer HYUNDAI
Model SONATA
Exact Purpose for which vehicle was being used at time of accident
Are you claiming under your own insurance policy for repair to your vehicle? No
If No, Please state action to be taken Third Party
Vehicle Category Taxi
Insurance Company
Name of Insurance Company India International Insurance Pte Ltd
Type Of Coverage Third Party Fire and/or Theft
Fleet Policy Yes
Policy Number MCOM0016
Cover Note Number
Driver
Name of Driver YEO BOON SING (YANG WENSHENG)
NRIC No S7426074H
Date Of Birth 09/08/1974
Occupation Outdoor
Date Of Driving Pass 22/05/1995
Driving Experience 21 Years And 8 Months
Gender Male
Mobile Number
Fax Number
Contact Number
Email Address SOUTHEASTMARINE101@YAHOO.COM

Address 109C #10-131 EDGEDALE PLAINS
 Postcode 823109
 Was driver an employee of the Insured's Company No
 If No Relationship of the Driver with the Insured Other - TAXI DRIVER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type of Accident Collision- Head to Rear (Insured Hit TP)
 Weather Conditions Raining
 Road Surface Wet

Other Information

Was any foreign vehicle Involved in this accident? No
 Was any body injured in the Accident? No
 Was any other material or property damaged? Yes
 Have been approached by unknown person(s) soiling/offering accident claims assistance. No
 Number of Passengers (Including Driver) 3

Details of Police Action

Was the accident reported to the police? No
 If Yes, Please state which Police Station
 Was notice of Intended Prosecution given? No
 If Yes, against whom?

Circumstances of Accident

PLS SEE ATTACH.

Attachment(s)

Are accident photos available for attachment? Yes
 Was there any video captured by Car Camera? Yes
 Remarks/ Reasons: -
 Was there any audio recorded? No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SKX6360P
 Vehicle Make/Model/Colour
 Details Of Properties
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage NO CONTACT
 No. Of Passenger (Including Driver)

Details of Witness

Name
 Phone Number
 Email Address

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SHC6260R

Vehicle Make/Model/Colour

Details Of Properties

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Name Of Damage

REAR

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

SKETCH PLAN**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time


Witnessed by Reporting Centre Personnel

Sketch Plan

A = SHC1863J →

B = SKX 6360P →

C = PNC 6360A (P) ←



Describe Circumstances of the Accident

On 21.02.2017 @ 14:05 Hrs,I was driving along from Rangoon Rd.

With 1 male and 1 female passenger on board.

While approaching near to the junction of Tessensohn Rd,the traffic light turned red and the green arrow show,thus the front veh (C) making a right turn towards Tessensohn Rd,as my taxi followed suit.However,there was a Veh (B) from opposite direction,dashed through the red light and made a left turn towards Tessensohn Rd with a reckless manner,and cut into our lane in front of veh (C),forced it jammed a brake and halted.I applied e-brake too but too late,my taxi hit onto veh (C)rear portion,caused the badly damage to my taxi and Veh (C) had moderate damage.After the accident,the culprit Veh (B) did not stop and just simply drove away.

I had CCTV fixed in the taxi and it captured the accident clearly.

No injury at the point of accident.

A-SHC 1863J.

B-SKX 6360P.

C-SHC 6260R (SC).

Declaration

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R



Anikka

Policyholder's Signature/Date &
Time

Driver's Signature(If driver is not the policyholder)/Date
& Time 21.02.2017 @17:45Hrs

Witnessed by Reporting
Centre Personnel

CHUNNI MOTOR WORK PTE LTD

REPAIR ESTIMATE*

To survey by Utk

VEHICLE NO : SHC 1863J

DATE : 22.02.2017

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI SONATA

FAX : 6542 6039

MSIG

QTY	Parts Description/ Labour	Type	Unit Price	Amount
	Bonnet			\$ 1,151.80
	Bonnet Hinge (LH/RH)	\$	87.50	\$ 175.00
	Bonnet Moulding			\$ 120.90
	Bonnet Lock			\$ 48.80
	Bonnet Insulator			\$ 232.80
	Bonnet Insulator Clips			\$ 10.00
	Radiator Grille			\$ 282.10
	Radiator Grille U Moulding			\$ 108.90
	Front Bumper Cover			\$ 538.80
	Front Bumper Sponge			\$ 136.30
	Front Bumper Reinforcement			\$ 504.10
	Front Bumper Bracket Top (LH/RH)	\$	22.40	\$ 44.80
	Front Bumper Protector (LH/RH)	\$	29.20	\$ 58.40
	Front Bumper Bracket (LH/RH)	\$	20.10	\$ 40.20
	Front Bumper Side Bracket	\$	14.30	\$ 28.60
	Front Bumper Clips 10 pcs			\$ 22.00
	Headlamp Support Panel Assy			\$ 1,023.00
	Headlamp (LH/RH)	\$	797.90	\$ 1,595.80
	Radiator			\$ 814.80
	Radiator Fan Blade, Cowling, Motor Assy			\$ 651.30
	Radiator Bracket	\$	6.20	\$ 12.40
	Radiator Hose Upper			\$ 45.40
	Radiator Hose Lower			\$ 45.40
	Radiator Expansion Tank			\$ 46.00
	Horn Unit (RH)			\$ 83.10
	Horn Wire			\$ 150.00
	Front Fender (RH)			\$ 593.00
	Front Fender Shield (RH)			\$ 86.00
	Front Fender Retainer			\$ 9.20
	Aircon Condenser			\$ 1,089.90
	Aircon Suction & Liquid Hose			\$ 631.40
	Aircon Discharge Hose			\$ 223.50
	Battery Tray			\$ 53.00
	Wiper Container			\$ 59.00
	Power Steering Pressure Hose Assy			\$ 588.60
	Power Steering Outlet Hose & Bracket			\$ 73.20
	Inter Cooler			\$ 771.50
	Inter Cooler Mounting (2 PCS)			\$ 24.80
	Hose B To Inter Cooler			\$ 220.10
	Hose C To Inter Cooler Inlet			\$ 108.50
	Pipe To Inter Cooler			\$ 160.00
	Pipe To Inter Cooler Outlet			\$ 234.30
	Wiring-Engine			\$ 3,187.40
	Wiring-Front			\$ 1,879.00
	Wiring-ECM			\$ 3,107.80

only depend on
used part
28/2

SHC 1863J

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	SUB TOTAL			\$ 21,070.90
	LESS 20%			\$ 4,214.18
	DISCOUNTED TOTAL			\$ 16,856.72
	Front Number Plate			\$ 25.00
	Front No Plate Trim Cover			\$ 30.00
				\$ 55.00
	Labour Charge			
	Panel Beating			\$ 1,000.00
	Spray Painting Charge			\$ 600.00
	Wiring Charge			\$ 50.00
	Tuff Kote			\$ 100.00
	Towing Charge			\$ 50.00
	Remove/Refix Aircon & Refill Gas			\$ 150.00
	Remove/Refix Dashboard — photo			\$ 450.00
	Remove/Refix Fuse Box			\$ 180.00
	Remove/Refix Power Steering Pump			\$ 120.00
	TOTAL LABOUR			\$ 2,700.00
	ESTIMATE TOTAL			\$ 19,611.72

Nett CHA ✓

Nett X ✓

720

480

30

50

? rent

150

250

80

X

Rasul

Hp 90010068

8 days

45

23/02/17 @ 1710

28/2/17

Rasul after repair

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.



































...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	22 Feb 2017		22 Feb 2017 17:29 Edit Adj Rpt	S\$10,324.52 Edit Estimates	S\$10,324.52 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured:	ONG CHEE HOCK , ID: S1247276E								
Main Claimant:	COMFORT TRANSPORTATION PTE LTD , Co. Reg. No.: 199303821R								
Vehicle Reg. No.:	SHC1863J	Date of Loss:	21/02/2017 00:00 - :59 [57 Months and 22 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 505399	Policy/Cover Note No.:	B0422270QMY (Third Party Only) Coverage: 21/12/2016 - 20/12/2017						
Vehicle Reg. No. (Insured):	SKX6360P	Policy No. (Claimant):							
		Excess:							
Repairer:	Chunni Motor Work Pte Ltd (HQ) Blk 10 Ang Mo Kio Industrial Park 2A, #03-19 AMK Autopoint, 568047 Ang Mo Kio - Tel: 6542 7162								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by NG CHEN HOW - 6643 1391]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 24/03/2017]								
Adj Asg. Remarks:	ON WP								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> MSIG_SG (30/04/2018): Survey Invoice 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SHC1863J (505399)
 [SKX6360P]
 TP
 COMFORT TRANSPORTATION PTE LTD
 Feb 21 2017 12:00AM
 [ONG CHEE HOCK]
 Chunni Motor Work Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	02/03/17 14:48	Accident Statement <small>From: SC - Reg. No: SKX6360P, Claimant: ONG CHEE HOCK</small>	 Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	27/02/17 12:34	Adjuster Immediate Advice	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	30/04/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
2	30/04/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
3	30/04/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
4	30/04/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
5	30/04/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
6	30/04/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
7	30/04/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
8	30/04/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
9	30/04/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
10	30/04/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
11	30/04/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
12	30/04/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
13	30/04/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
14	30/04/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
15	30/04/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
16	30/04/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
17	30/04/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
18	30/04/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
19	30/04/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
20	30/04/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
21	30/04/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
22	30/04/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
23	30/04/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
24	30/04/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
25	30/04/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
26	30/04/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
27	30/04/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
28	30/04/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
29	30/04/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
30	30/04/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
31	30/04/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
32	30/04/18 17:03	General View	 Load JPG	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
33	30/04/18 17:03	General View	Load JPG	<input checked="" type="checkbox"/>
34	30/04/18 17:03	General View	Load JPG	<input checked="" type="checkbox"/>
35	30/04/18 17:03	General View	Load JPG	<input checked="" type="checkbox"/>
36	30/04/18 17:03	General View	Load JPG	<input checked="" type="checkbox"/>
37	30/04/18 17:03	General View	Load JPG	<input checked="" type="checkbox"/>
38	30/04/18 17:03	General View	Load JPG	<input checked="" type="checkbox"/>
39	30/04/18 17:03	General View	Load JPG	<input checked="" type="checkbox"/>
40	30/04/18 17:03	General View	Load JPG	<input checked="" type="checkbox"/>
41	30/04/18 17:03	General View	Load JPG	<input checked="" type="checkbox"/>
42	30/04/18 17:03	General View	Load JPG	<input checked="" type="checkbox"/>
43	30/04/18 17:03	General View	Load JPG	<input checked="" type="checkbox"/>
44	30/04/18 17:03	General View	Load JPG	<input checked="" type="checkbox"/>
45	30/04/18 17:03	General View	Load JPG	<input checked="" type="checkbox"/>
46	30/04/18 17:03	General View	Load JPG	<input checked="" type="checkbox"/>
47	30/04/18 17:03	General View	Load JPG	<input checked="" type="checkbox"/>
48	30/04/18 17:03	General View	Load JPG	<input checked="" type="checkbox"/>
49	30/04/18 17:03	General View	Load JPG	<input checked="" type="checkbox"/>
50	30/04/18 17:03	General View	Load JPG	<input checked="" type="checkbox"/>
51	30/04/18 17:03	General View	Load JPG	<input checked="" type="checkbox"/>
52	30/04/18 17:03	General View	Load JPG	<input checked="" type="checkbox"/>
53	30/04/18 17:03	General View	Load JPG	<input checked="" type="checkbox"/>
54	30/04/18 17:03	General View	Load JPG	<input checked="" type="checkbox"/>
55	30/04/18 17:03	General View	Load JPG	<input checked="" type="checkbox"/>
56	30/04/18 17:03	General View	Load JPG	<input checked="" type="checkbox"/>
57	30/04/18 17:03	General View	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	22/02/17 17:13	TP EST BILL & ACCDT REPORT	Load PDF	
2	02/03/17 14:48	TP SHC18633 GIA REPORT From: SC - Reg. No: SKK6380P, Claimant: ONG CHEE HOCK	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)				
<div style="border: 1px solid black; height: 100px; width: 100%;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG17003724/R1GH3Q2

Date: 09/05/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 80422270QMY

Claimant Vehicle No: SHC1863J

Insured Vehicle No: SKX6360P

Date of Loss: 21/02/2017

Nature of Claim: TP

Claim No: 505399

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHC1863J

Make & Model: HYUNDAI SONATA, 2.0 D CRDi Turbo (NF) (A)

Engine No: D4EAC084659

Reg. Date: 30/04/2012 (Man. Year: 2012)

Chassis No: KMHET41VMCA824546

Colour: Blue

Odometer: 814319 km

Engine Capacity: 1991 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 216/60 R16

Rear Tyre Size: 216/60 R16

Front Left Side: Maxxis 5 mm

Rear Left Side: Maxxis 5 mm

Front Right Side: Maxxis 5 mm

Rear Right Side: Maxxis 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,911.72	8,614.52	8,297.20	49.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,700.00	1,710.00	990.00	36.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	19,611.72	10,324.52	9,287.20	47.36
+ GST 7.00/7.00% (S\$)	1,372.82	722.72	650.10	47.36
Nett Amount (S\$)	20,984.54	11,047.24	9,937.30	47.36

INSPECTION

Date of Assignment: 22/02/2017

Date Inspected: 23/02/2017 Inspected At:

Chunni Motor Work Pte Ltd (HQ)
Blk 10 Ang Mo Kio Industrial Park 2A, #03-19
AMK Autopoint
Singapore 568047

Estimated Period of Repair: 8.0 days

Adjuster: MOHD RASUL

Manager: LOW AI PHING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$2,476.24 NETT)

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 09 May 2018)
Parts:	143	HYUNDAI SONATA 2.0 D CRDi Turbo (NF) (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHC1863J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Bent	1,151.80 FL	*1,151.80 FL
2	2		*BONNET HINGE (LH/RH)	Serviceable	175.00 FL	*- FL
3	1		*BONNET MOULDING	Cut	120.90 FL	*120.90 FL
4	1		*BONNET LOCK	Bent	48.80 FL	*48.80 FL
5	1		*BONNET INSULATOR	Serviceable	232.80 FL	*- FL
6	1		*BONNET INSULATOR CLIPS	Necessary	10.00 FL	*10.00 FL
7	1		*RADIATOR GRILLE	Broken	282.10 FL	*282.10 FL
8	1		*RADIATOR GRILLE U MOULDING	Cracked	108.90 FL	*108.90 FL
9	1		*FRONT BUMPER COVER	Torn	538.80 FL	*538.80 FL
10	1		*FRONT BUMPER SPONGE	*Check	136.30 FL	*- FL
11	1		*FRONT BUMPER REINFORCEMENT	*Check	504.10 FL	*- FL
12	2		*FRONT BUMPER BRACKET TOP (LH/RH)	Necessary	44.80 FL	*44.80 FL
13	2		*FRONT BUMPER PROTECTOR (LH/RH)	Repair	58.40 FL	*- FL
14	2		*FRONT BUMPER BRACKET (LH/RH)	Necessary	40.20 FL	*40.20 FL
15	2		*FRONT BUMPER SIDE BRACKET	Necessary	28.60 FL	*28.60 FL
16	10		*FRONT BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
17	1		*HEADLAMP SUPPORT PANEL ASSY	Bent	1,023.00 FL	*1,023.00 FL
18	2		*HEADLAMP (LH/RH)	Cracked	1,595.80 FL	*1,595.80 FL
19	1		*RADIATOR	*Check	814.80 FL	*- FL
20	1		*RADIATOR FAN BLADE ,COWLING ,MOTOR ASSY	*Check	651.30 FL	*- FL
21	2		*RADIATOR BRACKET	*Check	12.40 FL	*- FL
22	1		*RADIATOR HOSE UPPER	Torn	45.40 FL	*45.40 FL
23	1		*RADIATOR HOSE LOWER	Serviceable	45.40 FL	*- FL
24	1		*RADIATOR EXPANSION TANK	Serviceable	46.00 FL	*- FL
25	1		*HORN UNIT (RH)	Serviceable	83.10 FL	*- FL
26	1		*HORN WIRE	Serviceable	150.00 FL	*- FL
27	1		*FRONT FENDER (RH)	Bent	593.00 FL	*593.00 FL
28	1		*FRONT FENDER SHIELD (RH)	Serviceable	86.00 FL	*- FL
29	1		*FRONT FENDER RETAINER	Necessary	9.20 FL	*9.20 FL
30	1		*AIRCON CONDENSER	Bent	1,089.90 FL	*1,089.90 FL
31	1		*AIRCON SUCTION & LIQUID HOSE	*Check	631.40 FL	*- FL
32	1		*AIRCON DISCHARGE HOSE	*Check	223.50 FL	*- FL
33	1		*BATTERY TRAY	Serviceable	53.00 FL	*- FL
34	1		*WIPER CONTAINER	*Check	59.00 FL	*- FL
35	1		*POWER STEERING PRESSURE HOSE ASSY	Serviceable	588.60 FL	*- FL
36	1		*POWER STEERING OUTLET HOSE & BRACKET	Serviceable	73.20 FL	*- FL
37	1		*INTER COOLER	Bent	771.50 FL	*771.50 FL
38	2		*INTER COOLER MOUNTING	Cracked	24.80 FL	*24.80 FL
39	1		*HOSE B TO INTER COOLER	Serviceable	220.10 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*HOSE C TO INTER COOLER INLET	Serviceable	108.50 FL	*- FL
41	1		*PIPE TO INTER COOLER	Serviceable	160.00 FL	*- FL
42	1		*PIPE TO INTER COOLER OUTLET	Serviceable	234.30 FL	*- FL
43	1		*WIRING -ENGINE	Cracked	3,187.40 FL	*3,187.40 FL
44	1		*WIRING -FRONT	Serviceable	1,879.00 FL	*- FL
45	1		*WIRING -ECM	Serviceable	3,107.80 FL	*- FL
46	1		*FRONT NUMBER PLATE	Cracked	25.00 FS	*25.00 FS
47	1		*FRONT NO PLATE TRIM COVER	Serviceable	30.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	21,125.90	10,761.90
- List Item Discount on L Items 20.00/20.00% (\$\$)	4,214.18	2,147.38
Total Parts (\$\$)	16,911.72	8,614.52

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,000.00	720.00
2	SPRAY PAINTING CHARGE	New	600.00	480.00
3	WIRING CHARGE	New	50.00	30.00
4	TUFF KOTE	New	100.00	50.00
5	TOWING CHARGE	New	50.00	0.00
6	REMOVE/REFIX AIRCON & REFILL GAS	New	150.00	100.00
7	REMOVE/REFIX DASHBOARD	New	450.00	250.00
8	REMOVE/REFIX FUSE BOX	New	180.00	80.00
9	REMOVE/REFIX POWER STEERING PUMP	New	120.00	0.00
Gross Labour Cost (\$\$)			2,700.00	1,710.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >