



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD  
3 ANSON ROAD #16-00  
SPRINGLEAF TOWER  
SINGAPORE 079909

INV No. AC2003610  
INV Date 04/05/2020  
Reference CC3/CTI17003784/K1ha3q2  
Code CTI



#### PROFESSIONAL SERVICE FEE

Vehicle No. SHB 429S  
Insured Veh. YP 2835P  
Claim No. SNM17D01054C02/5  
Policy No. DMCVSN3056761600  
Accident Date 16/02/2017  
Inspection Date 22/02/2017

Description	Total
Third Party Express Settlement	400.00
<b>Subtotal</b>	<b>400.00</b>
<b>GST (7%)</b>	<b>28.00</b>
<b>Grand Total</b>	<b>428.00</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC3/CTI17003784/K1ha3q2

3 ANSON ROAD #16-00  
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 04-05-2020



Code : CTI

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	YP 2835P	<b>Veh. Inspected</b>	SHB 429S
<b>Policy No.</b>	DMCVSN3056761600	<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	SNM17D01054C02/5	<b>Excess (\$)</b>	0.00
<b>Assign From</b>		<b>Assign Date</b>	22/02/2017

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	TOYOTA PRIUS	<b>c.c</b>	1798
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2015
<b>Chassis No.</b>	JTDKN36U305758052	<b>Colour</b>	MAROON
<b>Odometer</b>	284918	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	STANDARD ALLOY RIM
<b>General</b>	FAIR		

### 3. Conditions of Tyres

	<b>Size</b>	<b>Make</b>	<b>Balance</b>
<b>R/H Front Tyre</b>	195/65 R15	FALKEN	7 mm
<b>L/H Front Tyre</b>	195/65 R15	FALKEN	7 mm
<b>R/H Rear Tyre</b>	195/65 R15	FALKEN	7 mm
<b>L/H Rear Tyre</b>	195/65 R15	FALKEN	7 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.
--

### 5. General Information

<b>Accident Date</b>	16/02/2017	<b>Inspection Date</b>	22/02/2017
<b>Survey held at</b>	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
---

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	<b>2 Working Days</b>
-------------------------------------	-----------------------



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 429S

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
2	PIXEL STICKER @\$60.00 (SN)	NECESSARY	120.00	120.00
1	SMRT LOGO (SN)	NECESSARY	7.80	7.80
1	STICKER DECAL 6555 8888 (SN)	NECESSARY	21.60	21.60
10	BUMPER CLIPS 1.61	NOT NECESSARY	16.10	-
1	BUMPER LIP COVER RR/RH	NOT NECESSARY	118.10	-
1	BUMPER SEA, RR RH	NOT NECESSARY	65.70	-
1	BUMPER SIDE RETAINER RR/RH	NOT NECESSARY	94.80	-
1	SENSOR REVERSE	NOT NECESSARY	180.00	-
1	TAIL LAMP BRACKET ,RH	NOT NECESSARY	30.70	-
1	TAIL LAMP RH	NOT NECESSARY	557.80	-
1	FENDER LINER RR/RH	NOT NECESSARY	141.30	-
1	TYRE	NOT NECESSARY	126.74	-
1	WHEEL DISC	NOT NECESSARY	1,490.20	-
1	QUARTER GLASS RR/RH	NOT NECESSARY	846.50	-
1	SEALANT W/SCREEN	NOT NECESSARY	37.00	-
1	SOLAR FILM	NOT NECESSARY	125.00	-
1	BUMPER REAR	TO REPAIR SEE LABOUR	458.60	-
1	FENDER RR/RH	TO REPAIR SEE LABOUR	766.80	-
			5,204.74	149.40
<b><u>LABOUR</u></b>				
PANEL BEATING & BODY WORK.INCLUSIVE OF THE REPAIR OF BUMPER REAR AND FENDER RR/RH.			845.00	200.00
SPRAY PAINT.			936.00	400.00
TO CHECK WIRING AND SYSTEM FUNCTION .			80.00	20.00
TO APPLY RUST-PROOFING ON AFFECTED AREA.		NOT NECESSARY	100.00	-
TO REMOVE & REFIT REAR QUARTER GLASS RH .		NOT NECESSARY	120.00	-
TO TEST AND REFIX REVERSE SENSOR SYSTEM.		NOT NECESSARY	120.00	-
TO DO WHEEL ALIGNMENT /TYRE BALANCING .		NOT NECESSARY	120.00	-

Report Ref No. CC3/CTI17003784/K1ha3q2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE).	NOT NECESSARY	120.00	-
			2,441.00	620.00
GRAND TOTAL			7,645.74	769.40
RECOMMENDED COST OF REPAIRS				769.40

Report Ref No. CC3/CT117003784/K1ha3q2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHB 429S

INSPECTION









## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

