

SS REC BY:

REF: CS / MS61700 3854 / RIGBER

Special Instruction:

SURVIVOR:

MEOW

ASSIGNMENT (Office)

From (Person):

Vammala

of

MS16

Date/Time:

24/02/2017 11:01am

Estimated Cost:

Bill to:

☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

XE 6006J

Insured:

at Workshop m/s

Goldbell

Tel:

9755 7336

of

10 Tuas Ave 18

Policy No:

A28712860MKC

Claim No:

505605

Sum Insured:

Excess:

\$ 3000.00

Make of Veh:

(Client's Record)

D.O.A.

13-07-2017

CA / BEV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

24/02/2017 11:12am

Person Contacted:

William

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	XE 6006J - X
27/2/17 @ 5:30pm	revert to Vammala via Meimen.
27/2/17 @ 3:55pm	Huey Ni informed C/A via Meimen
28/2/17 @ 5:11pm	informed William & Mei Yen C/A & EX: \$3000 by email.
28/11/17 @ 2:05pm	2nd revert to Vammala via Meimen. (supplementary).
14/2/18 @ 9:11a	Ng Chen Hwa informed C/A at 8/4/2015 11:00am via Meimen.

08/11/13 wef
ASS REC BY *Rasul*

REF:

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
☒ OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: *XE 60063*
at Workshop m/s: *GOLDEN*
of: *10, TUN RUG 18*
Insured: *MSH / 00*
Policy No: _____
Claims No: _____
Sum Insured: _____ Excess: *3000*
(Client's Record) _____
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: *130K*
IDAC Accident Report: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: *12* days Res: Yes or No
Lum Sum: _____ % 3 Val: Yes or No

CA / ☒ REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: *XE 60063* Yr Regn: *2016* *more*
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

☒ Truck / Trailer or

Make: *McBentley H1 Fuso FFS150* cc *1967*

Colour: *Brown* A/C: Insured / Std / NI / NA

Sp. Reading: *-* T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: *FP 51 SDA 20027*

Gen. Cond: Good / ☒ Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modi: ☒ Nil / S/Rim / STD A/Rim or

Tyre Size: F: *295/80R 22X*

R: *-*

☒ BZ / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or *alp*

Front: _____ Rear: _____

R/Bal: *8* mm R/Bal: *8/8* mm

L/Bal: *8* mm L/Bal: *8/8* mm

D.O.A: *13/02/17* D.O.I: *24/2/17*

Survey held at: *GOLDEN*

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Far

The U/C / Chassis frame / Body Structure affected due to collision.

N/S	O/S

Date / Time Action / Instruction
28/3/15 @ 10.24m confirmed with written final fig B42015.11, 12 days.
(Per \$9092.51, 18%)

-Rasul,

See my remarks (7 items w/out photos)

RECEIVED 07 MAY 2018

Date/Time: File Pass to? ☐ Prel. Report

11/5/15 ☐ Final Report

Date/Time: File Return to?

2

Days Of Repair: *12*

Resurvey No. of Trip: *1*

Survey Fee:

Transportation:

Add Fee: ☐ Site Insp (\$) \$ + RS \$

☐ Interview (\$) Photos

☐ Tech. Invs (\$) Others

☐ Weekend (\$)

TOTAL

Report Format: *WEEK-07*

Lump Sum / I.B.I: (\$ *42015.11*)

<i>1150</i>
<i>10</i>
<i>460</i>

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG17003854/R1qb	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 24-02-2017	
		Code : MSG	
1. Policy Particulars :- OWN DAMAGE			
Insured Veh.		Veh. Inspected	XE 6006J
Policy No.	A28712860MKC	Coverage (\$)	0.00
Claim No.	505605	Excess (\$)	3,000.00
Assign From	MERIMEN (VIMMALA)	Assign Date	24/02/2017
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	13/02/2017	Inspection Date	24/02/2017
Survey held at	GOLDBELL ENGINEERING PTE LTD NO. 10 TUAS AVE 18 SINGAPORE 638894		
5a. Remarks			
A) THE MARKET VALUE IS S\$----- (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 Feb 2017		24 Feb 2017 11:01 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	PAN OCEAN INTERNATIONAL PTE LTD, Co. Reg. No.: 199004645C
Vehicle Reg. No.:	XE6006J
Claim Type:	OD / 505605
Repairer:	Goldbell Engineering Pte Ltd (Tuas) 10, Tuas Avenue 18, 638894 Tuas - Tel: 6864 0695
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Vimmala D/O Raja Singam - 65942471]
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 25/02/2017]
Driver/Custodian:	HAN ZHAOHUI (43 / Male), NRIC: G8351765X, Tel: +6598077618
Adj Asg. Remarks:	Please revert. Vehicle is in workshop now. Please survey by today

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shiau Chan (LKKAuto)

From: William Go Shaw Chan <WilliamGoSC@goldbell.com.sg>
Sent: Tuesday, 27 March 2018 10:24 AM
To: Shiau Chan (LKKAuto); SUR; Rasul (LKKAuto)
Cc: Ashlyn Chng
Subject: RE: XE 6006 J

Dear Shiau Chan,

The amount is confirmed.

Thanks & Best Regards,



William Go Shaw Chan | Goldbell Engineering Pte Ltd
Customer Service Advisor, Motor Claims

DID: +65 6864 0637 | Tel: +65 6861 0007 | Fax: +65 6863 0425 |
Mobile: +65 9755 7336 | Web: <http://www.goldbell.com.sg>
Address: Goldbell Engineering Pte Ltd (Tanjong Penjuru)
29 Tanjong Penjuru Singapore 609026



From: Shiau Chan (LKKAuto) [mailto:siewsc@lkkauto.com]
Sent: Tuesday, March 27, 2018 10:22 AM
To: William Go Shaw Chan <WilliamGoSC@goldbell.com.sg>; SUR <sur@lkkauto.com>; Rasul (LKKAuto) <Rasul@lkkauto.com>
Cc: Ashlyn Chng <AshlynChng@goldbell.com.sg>
Subject: RE: XE 6006 J

Dear William,

Offer final fig \$42,015.11 before excess \$3,000.00 & GST and 12 repair days.
Kindly confirm.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Claim Audit

AUDIT TRAIL					By
No.	On	Audit	Remarks		[I]
1	24 Feb 2017 09:12	Clim Veh Model Changed	(204674) MITSUBISHI FP51SDR3VDEA 12.0 D (M).		Vimmala D/O Raja Singam
2	24 Feb 2017 09:12	Clim Created	Reg No: XE6006J, Policy No: A28712860MKC, Acct Date: 2017/02/13, Claim Type: OD, Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ), Ins.Status => Incoming Claim, Created from SAS:MGE117019935-01		[I] Vimmala D/O Raja Singam
3	24 Feb 2017 09:13	Clim Registration Modified	Rep:1137->200248.		[I] Vimmala D/O Raja Singam
4	24 Feb 2017 09:13	Adj Co Assigned	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor):Please revert.		[I] Vimmala D/O Raja Singam
5	24 Feb 2017 09:13	Adj Next Rpt Changed	Next Rpt:Im. Advice.Due Date:2017/02/25		[I] Vimmala D/O Raja Singam
6	24 Feb 2017 09:13	Adj Mandate Set	Approved:25000.00.Reinsp:Adj decides.		[I] Vimmala D/O Raja Singam
7	24 Feb 2017 09:14	Adj Assignment Cancelled	NEED TO UPDATE DETAILS		[I] Vimmala D/O Raja Singam
8	24 Feb 2017 09:14	Adj Est Details Deleted	Deleting Est Details For Cancelling Adjuster Assignment		[I] Vimmala D/O Raja Singam
9	24 Feb 2017 09:47	Adj Co Assigned	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor):Please revert.		[I] Vimmala D/O Raja Singam
10	24 Feb 2017 09:47	Adj Next Rpt Changed	Next Rpt:Im. Advice.Due Date:2017/02/25		[I] Vimmala D/O Raja Singam
11	24 Feb 2017 09:47	Adj Mandate Set	Approved:25000.00.Reinsp:Adj decides.		[I] Vimmala D/O Raja Singam
12	24 Feb 2017 10:45	Assignment 1st Accessed			[A] Ho Pei Fang
13	24 Feb 2017 10:59	Adj Assignment Cancelled	IHS APPT FULL		[I] Vimmala D/O Raja Singam
14	24 Feb 2017 10:59	Adj Est Details Deleted	Deleting Est Details For Cancelling Adjuster Assignment		[I] Vimmala D/O Raja Singam
15	24 Feb 2017 11:01	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):Please revert, Vehicle is in workshop now, Please survey by today		[I] Vimmala D/O Raja Singam
16	24 Feb 2017 11:01	Adj Next Rpt Changed	Next Rpt:Im. Advice.Due Date:2017/02/25		[I] Vimmala D/O Raja Singam
17	24 Feb 2017 11:01	Adj Mandate Set	Approved:25000.00.Reinsp:Adj decides.		[I] Vimmala D/O Raja Singam
18	24 Feb 2017 11:08	Assignment 1st Accessed			[A] CATHERINE CHONG KAI LING
19	24 Feb 2017 12:10	Adj Adjuster Assigned	[None] -> MOHD RASUL		[A] CATHERINE CHONG KAI LING
20	27 Feb 2017 14:05	Adj Rpt Initiated			[A] SHIAU CHAN
21	27 Feb 2017 14:50	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2017/03/26		[A] SHIAU CHAN
22	27 Feb 2017 14:50	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2017/03/26		[A] SHIAU CHAN
23	27 Feb 2017 14:52	Adj Mandate Request	Cur,Req:40353.19:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL.		[A] SHIAU CHAN

AUDIT TRAIL				
No.	On	Audit	Remarks	By
24	27 Feb 2017 15:55	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2017/03/26	[I] Eng Huey Ni
25	27 Feb 2017 15:55	Adj Mandate Set	Approved:40353.19.	[I] Eng Huey Ni
26	28 Nov 2017 14:04	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2017/03/26	[A] SHIAU CHAN
27	28 Nov 2017 14:05	Adj Mandate Request	Cur.Req:42015.11:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. KINDLY APPROV E ON CHECK ITEMS AND SUPPLEMENTARY.	[A] SHIAU CHAN
28	30 Nov 2017 09:18	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2017/03/26. Mandate Remarks: Hi Surveyor at LKK, please let us have more photos showing damages to steering shaft, combination clock spring sw itch, rear quarter panel outer RHS, front wheelhousing liner RHS, dashboard and the u	[I] Eng Huey Ni
29	30 Nov 2017 09:18	Adj Mandate Set	Maintained:Hi Surveyor at LKK, please let us have more photos showing damages to steer ing shaft, combination clock spring switch, rear quarter panel outer RHS, front wheelho using liner RHS, dashboard and the undercarriage parts. Thanks.	[I] Eng Huey Ni
30	30 Nov 2017 09:34	Adj Mandate Request	Cur.Req:42015.11:THE PHOTOGRAPHS HAD UPLOADED.	[A] SHIAU CHAN
31	01 Dec 2017 16:08	Adj Next Rpt Changed	Cur Rpt:Final Rpt. Cur Due Date:2017/03/26. Mandate Remarks: Hi Surveyor at LKK. Th anks for the re-inspection photos. We have two more questions: 1) How do you determin e the steering shaft was damaged? Were there any photos taken before dismantling the	[I] Eng Huey Ni
32	01 Dec 2017 16:08	Adj Mandate Set	Maintained:Hi Surveyor at LKK. Thanks for the re-inspection photos. We have two more questions: 1) How do you determine the steering shaft was damaged? Were there any ph otos taken before dismantling the steering shaft? 2) What do photos number 45	[I] Eng Huey Ni
33	13 Feb 2018 16:49	Adj Mandate Request	Cur.Req:42015.11:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. KINDLY APPROV E ON CHECK ITEMS AND SUPPLEMENTARY.	[A] SHIAU CHAN
34	14 Feb 2018 09:11	Adj Next Rpt Changed	Cur Rpt:Final Rpt. Cur Due Date:2017/03/26. Mandate Remarks: Hi Surveyor at LKK. Th anks for the re-inspection photos. We have two more questions: 1) How do you determin e the steering shaft was damaged? Were there any photos taken before dismantling the	[I] NG CHEN HOW
35	14 Feb 2018 09:11	Adj Mandate Set	Approved:42015.11:Hi Surveyor at LKK. Thanks for the re-inspection photos. We have t wo more questions: 1) How do you determine the steering shaft was damaged? Were the re any photos taken before dismantling the steering shaft? 2) What do photos num	[I] NG CHEN HOW

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1392755	27/02/2017 14:05	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	XE6006J		10.70

Shiau Chan (LKKAUTO)

From: Eng Huey Ni <HueyNi_Eng@sg.msig-asia.com>
Sent: Thursday, 25 January 2018 8:48 AM
To: Shiau Chan (LKKAUTO); Vimmala D/O Raja Singam
Cc: SUR
Subject: RE: XE6006J (505605)

Hi Shiau Chan,

Thank you for your email.

There are a few photos shown by Mr Lau on Monday (22/1/18) which were not forwarded to us earlier. Could you please let us have those photos? (eg. The photos showing the new steering shaft)

Thanks
Huey Ni

From: Shiau Chan (LKKAUTO) [mailto:siewsc@lkkauto.com]
Sent: Tuesday, 23 January 2018 6:15 PM
To: Vimmala D/O Raja Singam <vimmala_rajasingam@sg.msig-asia.com>
Cc: SUR <sur@lkkauto.com>; Eng Huey Ni <HueyNi_Eng@sg.msig-asia.com>
Subject: RE: XE6006J (505605)

Dear Vimmala,

Thank you for the email.

We referred to Mr K.K.Lau explanation at your good office yesterday afternoon, the damages to the steering shaft and related were due to the "induced damaged" as a result of impact at the cabin & floor board panel, from the third party vehicle.

Best Regards,
Shiau Chan (Ms) | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Vimmala D/O Raja Singam [mailto:vimmala_rajasingam@sg.msig-asia.com]
Sent: Wednesday, 10 January 2018 7:17 AM
To: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Cc: SUR <sur@lkkauto.com>; Eng Huey Ni <HueyNi_Eng@sg.msig-asia.com>
Subject: RE: XE6006J (505605)

Hi Shiau Chan,

Thank you for the email.

We will review the photographs.

Mala (Ms)
Senior Admin Officer, Claims Services (Motor)
Direct line +65 6594 2471 | Direct fax +65 6225 7402 | vimmala_rajasingam@sg.msig-asia.com

Shiau Chan (LKKAUTO)

To: Vimmala D/O Raja Singam
Cc: SUR; Eng Huey Ni
Subject: RE: XE6006J (505605)

Dear Vimmala,

Thank you for the email.

We referred to Mr K.K.Lau explanation at your good office yesterday afternoon, the damages to the steering shaft and related were due to the "induced damaged" as a result of impact at the cabin & floor board panel,

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

from the third party vehicle.

From: Vimmala D/O Raja Singam [mailto:vimmala_rajasingam@sg.msig-asia.com]
Sent: Wednesday, 10 January 2018 7:17 AM
To: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Cc: SUR <sur@lkkauto.com>; Eng Huey Ni <HueyNi_Eng@sg.msig-asia.com>
Subject: RE: XE6006J (505605)

Hi Shiau Chan,

Thank you for the email.

We will review the photographs.

Mala (Ms)

Senior Admin Officer, Claims Services (Motor)

Direct line +65 6594 2471 | Direct fax +65 6225 7402 | vimmala_rajasingam@sg.msig-asia.com



Insurer Claims
Team of the Year
2016

MSIG Insurance (Singapore) Pte. Ltd. 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | Tel +65 6220 9644 | Fax +65 6225 6371 | Co. Reg. No. 200412212G | <http://www.msig.com.sg/> | Follow us

on :    

A member of **MS&AD** INSURANCE GROUP

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

Thank you for the email.

We refered to Mr K. K. Lau
explanation at your good office this
afternoon. The damages to the
steering shaft and related were
due to the "induced damage"
as the a results of impact at
the cabin & floor board panel.

XE6006J - Submitted by: LKK Auto Consultants Pte Ltd (HQ)



88/94: Reinspection Photo



89/94: Reinspection Photo



90/94: Reinspection Photo





Photo 92 to 94 - Steering Shaft bent, during re-inspection checked.

View Received Message

This mail is associated with :

*XE6006J (505605)

OD

Feb 13 2017 8:00AM

[PAN OCEAN INTERNATIONAL PTE LTD]
Goldbell Engineering Pte Ltd

Reply	Reply All	Mark as Unread	Print Message	Delete Message	Forward
-------	-----------	----------------	---------------	----------------	---------

From MSIG Insurance (Singapore) Pte. Ltd. (MSIG_SG) sent on 01/12/2017 16:08 PM.
To LKK_HQ
Subject Alert - Adj Mandate Maintained - XE6006J - Claim Handler: Vimmala D/O Raja Singam

Maintained: Hi Surveyor at LKK. Thanks for the re-inspection photos. We have two more questions: 1) How do you determine the steering shaft was damaged? Were there any photos taken before dismantling the steering shaft? 2) What do photos number 45—

45
46

49

DOCUMENTS SUMMARY

There are no documents.

47

48

1) The damage was on the front RH portion. The damages was on the steering linkages side near to the driver side. Due to the impact, possibility the steering shaft will bend.

2) No photos were taken before dismantling the steering shaft.

3)

Sorry for the late reply, due to further checked with the engineer after reading the accident report

2) During the physical inspection, I observed the steering wheel by turning it left or right, found irregular movements, ± for the checked & looked at the underneath it was damaged,

View Received Message

This mail is associated with :

***XE6006J (505605)**

OD

Feb 13 2017 8:00AM

[PAN OCEAN INTERNATIONAL PTE LTD]

Goldbell Engineering Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From MSIG Insurance (Singapore) Pte. Ltd. (MSIG_SG), sent on 30/11/2017 09:18 AM.
To LKK_HQ
Subject Alert - Adj Mandate Maintained - XE6006J - Claim Handler: Vimmala D/O Raja Singam

Maintained: Hi Surveyor at LKK, please let us have more photos showing damages to steering shaft, combination clock spring switch, rear quarter panel outer RHS, front wheelhousing liner RHS, dashboard and the undercarriage parts. Thanks,

DOCUMENTS SUMMARY

There are no documents.

Shoot picture
unable to get a close-up due to
blockage. (See photos 66)
However, during the reinspection confirmed
it was bent & beyond repair.

Adjuster Letter/DV not verified.
This claim is to be authorized on the insurer's behalf.
Submissions will not be allowed until the Letter of Offer/DV is VERIFIED.
Click on 'View Letter/DV' to verify the offer.

Insurer's Mandate Remarks

Hi Surveyor at LKK. Thanks for the re-inspection photos. We have two more questions: 1) How do you determine the steering shaft was damaged? Were there any photos taken before dismantling the steering shaft? 2) What do photos number 45 to 49 trying to indicate/show? Please advise. Thanks.

You cannot authorize this offer because
Adjuster Letter/DV not verified..
File to be authorized by your superior.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/MSG1700385/R1QB
Date: 01/12/2017

REFERENCE

Insured/Claimant:	PAN OCEAN INTERNATIONAL PTE LTD	Policy No:	A28712860MKC	Claim No:	505605
Date of Loss:	13/02/2017	Nature of Claim:	OD		

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	XE6006J	Engine No:	OM457319642
Make & Model:	MITSUBISHI FP51SDR3VDEA, 12.0 D (M)	Chassis No:	FP51SDA20027
Reg. Date:	22/03/2016 (Man. Year: 2015)	Odometer:	0 km
Colour:	Brown		
Engine Capacity:	11967 cc		
Market Value/New Car Price:	S\$130,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	295/80 R22.5	Rear Tyre Size:	295/80 R22.5 (D)
Front Left Side:	Bridgestone 8 mm	Rear Left Side:	Bridgestone 8/8 mm
Front Right Side:	Bridgestone 8 mm	Rear Right Side:	Bridgestone 8/8 mm

The above values represent the remaining tyre tread's depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	0.00	0.00	0.00	
- Excess (\$\$)	3,000.00	3,000.00	0.00	0.00
(\$\$)	-3,000.00	-3,000.00	0.00	0.00
+ GST 7.00/7.00% (\$\$)	-210.00	-210.00	0.00	0.00
Nett Amount (\$\$)	-3,210.00	-3,210.00	0.00	0.00

INSPECTION

Date of Assignment:	24/02/2017	Inspected At:	Goldbell Engineering Pte Ltd (Tuas)
Date Inspected:	24/02/2017		10, Tuas Avenue 18
			Singapore 638894
Estimated Period of Repair:	12.0 days		

Adjuster: MOHD RASUL

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Monday, 27 February, 2017 5:11 PM
To: William Go Shaw Chan; NgMeiYen@goldbell.com.sg
Cc: SUR
Subject: VEHICLE XE 6006J DOA: 13/02/2017

Dear William & Mei Yen,

As instructed by our client MSIG Insurance Company, please proceed to repair the insured vehicle XE 6006J (excess \$3,000.00).

If there are any check items or supplementary items please inform our office's Assignment Team at : 6741 8434 to arrange our surveyor for inspection.

Any supplementary items are subjected to further approval from our client.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

***XE6006J (505605)**

OD

Feb 13 2017 8:00AM

[PAN OCEAN INTERNATIONAL PTE LTD]

Goldbell Engineering Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From MSIG Insurance (Singapore) Pte. Ltd. (MSIG_SG), sent on 27/02/2017 15:55 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$40353.19) - XE6006J - Claim Handler: Vimmala D/O Raja Singam

Approved:40353.19.

DOCUMENTS SUMMARY

There are no documents.

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Vimmaia D/O Raja Singam

Date: 28 Nov 2017

Preliminary Advice

Vehicle No	: XE6006J	Accident Date	: 13/02/2017
Make	: MITSUBISHI FP51SDR3VDEA	Policy No.	: A28712860MKC
Assignment Date	: 24/02/2017	Excess	: S\$3,000.00
Date of Inspection	: 24/02/2017	Est. Duration of Repair	: 12.00
Inspection At	: GOLDBELL ENGINEERING PTE LTD (TUAS) 10, TUAS AVENUE 18 SINGAPORE 638894		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	51,107.62	(ESTIMATE \$47,023.42 + SUPPLEMENTARY \$4,084.20)
Revised Amount	:S\$	42,015.11	(INCLUSIVE OF SUPPLEMENTARY)
Check Items (Estimated)	:S\$	0.00	
Total	:S\$	42,015.11	
Lump Sum Repair	:S\$		

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	130,000.00
COE / PARF Rebate	:S\$	30,403.00
Salvage Value	:S\$	
Margin for Repair	:S\$	99,597.00

Remarks

- (X) The vehicle is economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis. KINDLY APPROVE ON SUPPLEMENTARY.

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Vimimala D/O Raja Singam

Date: 27 Feb 2017

Preliminary Advice

Vehicle No	: XE6006J	Accident Date	: 13/02/2017
Make	: MITSUBISHI FP51SDR3VDEA	Policy No.	: A28712860MKC
Assignment Date	: 24/02/2017	Excess	: S\$3,000.00
Date of Inspection	: 24/02/2017	Est. Duration of Repair	: 12.00
Inspection At	: GOLDBELL ENGINEERING PTE LTD (TUAS) 10, TUAS AVENUE 18 SINGAPORE 638894		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	47,023.42
Revised Amount	:S\$	30,933.10
Check Items (Estimated)	:S\$	9,420.09
Total	:S\$	40,353.19

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	130,000.00
COE / PARF Rebate	:S\$	30,403.00
Salvage Value	:S\$	
Margin for Repair	:S\$	99,597.00

Remarks

(X) The vehicle is economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis. WE HAVE NOT AUTHORISE REPAIR.

Text size + -

Enquire PARF/COE Rebate for Registered Vehicle**Vehicle Owner Particulars**

Owner ID Type: Company

Owner ID: 4645C

Vehicle Details

Vehicle No.: XE6006J

Vehicle to be Exported: No

Intended De-registration
Date: 27 Feb 2017

Vehicle Make: MITSUBISHI

Vehicle Model: FUSO FP51SDR3VDEA

Primary Colour: White

Manufacturing Year: 2015

Engine No.: OM457319642

Chassis No.: FP51SDA20027

Maximum Power Output:-

Open Market Value: \$78,091.00

Original Registration
Date: 22 Mar 2016

First Registration Date: 22 Mar 2016

Transfer Count: 0

Actual ARF Paid: \$3,905.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry
Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 21 Mar 2026

COE Category: C - Goods Vehicle & Bus

COE Period(Years): 10

PQP Paid: \$33,560.00

COE Rebate Amount: \$30,403.00

Total Rebate Amount: \$30,403.00

The information contained herein is correct as at 27 Feb 2017

OK

Land Transport Authority

Please read through the Privacy Statement, Terms of Use and Disclaimer.

Please do not use the **Back** or **Forward** buttons on your browser as this may alter the results of the transactions.

Best viewed with IE 8.0 SP3 and above. 1024 X 768 resolution

Copyright © 2017 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#) | [Rate this e-Service](#)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	13/02/2017 12:57
Date Of Accident	13/02/2017 08:45
Exact Location Of Accident	JUNCTION TUAS SOUTH AVE 5 AND TUAS SOUTH AVE 8
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	XE6006J
Insured/Policyholder	
Name Of Registered Owner	PAN OCEAN INTERNATIONAL PTE LTD
Co Reg No	199004645C
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	Office-62663750

Vehicle Particulars

Manufacturer	MITSUBISHI
Model	FP51SDR3VDEA-12.0 D (M)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	No
If No, Please state action to be taken	Third Party
Vehicle Category	Commercial Vehicle

Insurance Company

Name of Insurance Company	MSIG Insurance (Singapore) Pte. Ltd.
Type Of Coverage	Comprehensive
Fleet Policy	No
Policy Number	A28712860MKC
Cover Note Number	

Driver

Name of Driver	HAN ZHAOHUI
Passport No/FIN	G8351765X
Date Of Birth	31/05/1973
Occupation	Outdoor
Date Of Driving Pass	21/01/2009
Driving Experience	8 Years And 0 Months
Gender	Male
Mobile Number	(Local) +65-98077618
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address

Postcode

Was driver an employee of the Insured's Company No

If No, Relationship of the Driver with the Insured Other - AUTHORISED DRIVER

Vehicle Registration Number of Driver's Own Vehicle -

-

-

Insurance Company of Driver's Own Vehicle -

-

-

General Information of the Accident

Type Of Accident Collision- Chain Collision

Weather Conditions Clear

Road Surface Dry

Other Information

Was any foreign vehicle involved in this accident? No

Was any body injured in the Accident? No

Was any other material or property damaged? Yes

I have been approached by unknown person(s) soliciting/offering accident claims assistance. No

Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? No

If Yes, Please state which Police Station

Was notice of intended Prosecution given? No

If Yes, against whom?

Circumstances of Accident

ON THE ABOVE MENTIONED DATE AND TIME, MY VEHICLE WAS STOPPED AND STATIONARY AT THE TRAFFIC JUNCTION OF TUAS SOUTH AVE 5, AWAITING TRAFFIC LIGHT TO TURN GREEN. SUDDENLY, THERE WAS A VEHICLE 'B' (GBE1185T) TRAVELLING FROM THE OPPOSITE DIRECTION OF ME AND ANOTHER VEHICLE 'C' (SHC8425U) FROM TUAS SOUTH AVE 8 HAS COLLIDED ONTO EACH OTHER. AFTER THE IMPACT, VEHICLE 'B' WAS TOPPLED AND HIT ONTO MY VEHICLE FRONT RIGHT PORTION. NO ONE WAS INJURED.

Attachment(s)

Are accident photos available for attachment? Yes

Was there any video captured by Car Camera? No

Was there any audio recorded? No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBE1185T

Vehicle Make/Model/Colour

Details Of Properties

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SHC8425U

Vehicle Make/Model/Colour

Details Of Properties

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and


(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



Witnessed by Reporting Centre Personnel

A. XE60063
B. G66 11857
C. SH684354

Sketch Plan #2

Describe Circumstances of the Accident

As per report.

Declaration

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date &
Time

13:00
HAN ZHANG HUI 13/2/17
Driver's Signature (if driver is not the policyholder) / Date
& Time

Witnessed by Reporting Centre
Personnel

17-02-13:14:00

1 / 1



MSIG

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, # 21-01, SGX Centre 2, Singapore 068807
Tel +65 6827 7886, Fax +65 6827 7800
Co. Reg. No. 200412212G GST Reg. No. 20-0412212G

Certificate of Insurance

ROAD TRANSPORT ACT 1967 (MALAYSIA)
THE MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (FEDERATION OF MALAYSIA)
THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP. 189 OF THE REVISED EDITION)
(REPUBLIC OF SINGAPORE)
THE MOTOR VEHICLES (THIRD-PARTY RISK AND COMPENSATION) RULES, 1995 EDITION (REPUBLIC OF SINGAPORE)
OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF.

Form M. 2. 300
Goods Carrying Vehicle - Sch 1

COMMERCIAL VEHICLE
Comprehensive

Certificate No. A 28712860 MKC

Excess: SGD3,000

1. Index Mark and Registration Number of Vehicle
XK6096J

2. Name of Policyholder
Pan Ocean International Pte Ltd

3. Effective Date of the Commencement of Insurance for the purposes of the Act
22/02/2016

4. Date of Expiry of Insurance
21/02/2017

5. Persons or Classes of Persons entitled to drive*

Any other person provided he is driving on the Policyholder's order or with the Policyholder's permission.

* Provided that the person driving is permitted in accordance with the licensing or other laws or laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to use*

Use in connection with the Policyholder's business.
Use for the carriage of passengers (other than for hire or reward) in connection with the Policyholder's business.
Use for social domestic and pleasure purposes.
The Policy does not cover
(1) Use for hire or reward or for racing pace-making reliability trial or speed-testing.
(2) Use whilst drawing a trailer except the towing of any one disabled mechanically propelled vehicle.

* Limitations rendered inoperative by Section 5 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1967 (Malaysia), are not to be included under these headings.


This Certificate is not transferable to a new owner of the vehicle. If for any reason the Policy is terminated during its currency, the Certificate must be returned to the insurer within 7 days of the termination or if the Certificate has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189).

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1967 (Malaysia) or any Amendment, Act or Acts passed in substitution thereof.

MSIG Insurance (Singapore) Pte. Ltd.
Approved Insurers

for Chief Executive Officer

Sketch Plan #4



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo




Accident Photo



Accident Photo



Accident Photo




Accident Photo




Accident Photo



Accident Photo



Accident Photo





GOLDBELL ENGINEERING

Industrial Vehicles.
20,000 Served. And Counting.

GOLDBELL ENGINEERING PTE LTD

10 Tuas Avenue 18 Singapore 638894

Tel: +65 6861 0007 Fax: +65 6861 3676 (Sales)

Fax: +65 6863 0425 (Service) +65 6862 1347 (Parts)

Website: www.goldbell.com.sg

Co. Reg. No.: 198003963G

DATE : 17/02/2017

TO : PAN OCEAN INTERNATIONAL P/L

ATTN : MS. IVY

OFFICE / MOBILE : 6266-3320

EMAIL ADDRESS : -

FROM : GOLDBELL ENGINEERING P/L

ATTN : MR WILLIAM GO

OFFICE / MOBILE : 6864-0637 / 9755-7336

FAX NO. : 6863-0425

VEHICLE NO. : XE6006J

MODEL NO. : MITSUBISHI FP51SDR3VDEA

CHASSIS NO. : FP51SDA20027

ENGINE NO. : OM457319642

REG. DATE : 22/03/2016

REF. NO. : GBE/SVC/SALES-4179/170217

D.O.A. : 13/02/2017

POLICY NO. : -

CLAIM TYPE : OD CLAIM - MSIG

WORKSHOP : 10 TUAS AVE 18

S/N	PART NO.	DESCRIPTION	QUANTITY	PRICE
1	MK704681	FRONT PANEL	1	\$ 5,625.86 R
2	MK487575	FRONT PANEL TOP WEATHERSTRIP	1	\$ 150.20 X
3	MK615044	FRONT PANEL SIDE WEATHERSTRIP	2	\$ 103.94 X
4	MK548405	"FUSO" MARK	1	\$ 320.88 new
5	MK702798	FRONT PILLAR RHS	1	\$ 1,870.89 Bt
6	MC977768	FRONT CORNER PANEL RHS	1	\$ 1,087.51 CA
7	MK614682	FRONT CORNER PANEL SEAL OUTER RHS	1	\$ 65.99 new
8	MK547619	FRONT CORNER PANEL SEAL INNER RHS	1	\$ 27.45 new
9	MK547612	FRONT CORNER PANEL BRACKET RHS	1	\$ 35.62 new
10	MK547616	FRONT CORNER PANEL BRACKET RHS	1	\$ 116.76 new
11	MK549686	FRONT CORNER PANEL SIDE BRACKET RHS	1	\$ 170.34 new
12	MK547800	FRONT CORNER PANEL SEAL LOWER RHS	1	\$ 87.21 new
13	MC977678	FRONT BUMPER	1	\$ 2,259.31 DE
14	MK614407	FRONT BUMPER STAY RHS	1	\$ 169.07 R
15	MK675520	FRONT BUMPER SIDE GARNISH RHS	1	\$ 140.29 DE
16	MK614603	FRONT BUMPER STEP GARNISH	1	\$ 217.26 cut
17	MK674628	FRONT BUMPER AIR GUIDE DUCT RHS	1	\$ 96.70 DE
18	MC979981	FRONT BUMPER TOP COVER CENTRE	1	\$ 273.12 ?
19	MK549903	FRONT BUMPER TOP COVER REINFORCEMENT	1	\$ 884.79 ?
20	MC979983	FRONT BUMPER TOP COVER RHS	1	\$ 193.04 DE
21	MK549906	FRONT BUMPER TOP COVER REINFORCEMENT	1	\$ 226.06 Bt
22	MK548577	HEADLAMP RHS	1	\$ 1,286.45 new
23	MK549822	HEADLAMP BEZEL RHS	1	\$ 210.48 new
24	MK580189	HEADLAMP BRACKET RHS	1	\$ 947.63 Bt
25	MK545720	FOGLAMP RHS	1	\$ 293.25 new
26	MK549826	FOGLAMP BEZEL RHS	1	\$ 186.05 CA
27	MK486318	FRONT TURN SIGNAL LAMP RHS	1	\$ 211.91 CA
28	MK705213	FRONT DOOR RHS	1	\$ 4,626.16 new
29	MC992100	FRONT DOOR HINGE RHS	2	\$ 379.62 Bt
30	MC963828	FRONT DOOR GLASS RUNCHANNEL RHS - photo?	1	\$ 585.36 ?
31	MC935116	FRONT DOOR WEATHERSTRIP RHS	1	\$ 534.01 new
32	MK580090	FRONT DOOR WEATHERSTRIP INNER RHS	1	\$ 356.74 new
33	MC937210	FRONT DOOR CHECK RHS	1	\$ 128.88 Bt
34	MC935065	FRONT DOOR REGULATOR RHS 3 photo?	1	\$ 276.16 ?
35	MC935067	FRONT DOOR REGULATOR MOTOR RHS	1	\$ 410.64 ?
36	MC935080	FRONT DOOR RAIL LOWER RHS	1	\$ 216.52 ?
37	MK488599	FRONT DOOR LATCH & ACTUATOR RHS	1	\$ 900.45 Bt
38	MK580506	FRONT DOOR TRIM BOARD RHS	1	\$ 1,598.99 ?

bizSAFE
S T R



Certificate No: AJA/B101/Q1243

Certificate No: AJA/B101/Q1243



GOLDBELL ENGINEERING

Industrial Vehicles.
20,000 Served. And Counting.

39	MC935038	FRONT DOOR INNER FILM RHS	1	\$	37.26	new
40	MH022009	FRONT DOOR TRIM BOARD PROTECTOR RHS	2	\$	20.06	new
41	MK546944	FRONT DOOR SIDE SIGNAL LAMP RHS	1	\$	81.53	new
42	MC992680	FRONT SIDE SILL PANEL RHS	1	\$	2,227.43	new
43	MC976678	FRONT SIDE FENDER RHS	1	\$	1,241.66	new
44	MC935719	FRONT SIDE FENDER GARNISH RHS	1	\$	223.34	new
45	MC936273	FRONT SIDE FENDER SEAL RHS	1	\$	24.53	new
46	MC968233	FRONT SIDE FENDER SIDE BRACKET RHS	1	\$	257.84	new
47	MC936687	FRONT SIDE FENDER REAR BRACKET RHS	1	\$	240.76	new
48	MK674742	FRONT STEP GARNISH UPPER RHS	1	\$	744.59	new
49	MC968229	FRONT STEP GARNISH UPPER BRACKET RHS	1	\$	254.70	new
50	MC932175	FRONT STEP PANEL UPPER RHS	1	\$	331.55	new
51	MC968226	FRONT STEP PANEL MIDDLE RHS	1	\$	294.32	new
52	MK676240	FRONT STEP GARNISH WALL RHS	1	\$	324.55	new
53	MC978910	FRONT STEP GARNISH LOWER RHS	1	\$	159.15	new
54	MC937840	FRONT STEP PANEL LOWER RHS	1	\$	331.55	new
55	MC937837	FRONT STEP GARNISH LOWER COVER RHS	1	\$	237.97	new
56	MC962458	FRONT STEP SUPPORT LOWER RHS	1	\$	41.36	new
57	MC937901	FRONT STEP BRACKET LOWER RHS	1	\$	906.60	new
58	MK549797	FRONT STEP BRACKET LOWER RHS	1	\$	906.60	new
59	MC855877	FRONT STEP GARNISH REFLECTOR RHS	1	\$	37.35	new
60	MC857068	FRONT STEP GARNISH REFLECTOR NUT RHS	1	\$	2.95	new
61	MK710147	REAR QUARTTER PANEL OUTER RHS	1	\$	1,944.43	new
62	MC992139	REAR QUARTTER PANEL INNER RHS	1	\$	832.52	new
63	MC967608	REAR QUARTTER PANEL GLASS SEAL RHS	1	\$	131.77	new
64	MK456774	FRONT MUDGUARD RHS	1	\$	586.98	new
65	MK674378	FRONT WHEELHOUSING LINER RHS	1	\$	368.10	new
66	MC936773	FRONT WHEELHOUSING LINER APRON SHIELD RHS	1	\$	182.12	new
67	MC968207	FRONT WHEELHOUSING LINER APRON SHIELD RHS	1	\$	115.02	new
68	MC968210	FRONT WHEELHOUSING LINER APRON SHIELD RHS	1	\$	107.16	new
69	MC962290	REAR VIEW MIRROR LOWER COVER RHS	1	\$	38.53	new
70	MK565174	FRONT PILLAR TRIM RHS	1	\$	183.74	new
71	ML272435	REAR QUARTER PANEL TRIM RHS	1	\$	741.00	new
72	MK565310	DASHBOARD	1	\$	3,536.73	new
73	MK565376	DASHBOARD CORNER RHS	1	\$	57.17	new
74	MK565373	DASHBOARD RHS	1	\$	307.21	new
75	MK565379	DASHBOARD INNER RHS	1	\$	379.70	new
76	MC934332	FRONT WINDSCREEN WEATHERSTRIP	1	\$	728.97	new
77	MK566997	SCUFF PLATE RHS	1	\$	164.17	new

SUB-TOTAL :	\$	46,604.56
LESS 25% :	\$	11,651.14
BALANCE :	\$	34,953.42

SPECIAL-NETT ITEMS

1	COMPANY LOGO	1	\$	600.00	new
2	SEALANT	3	\$	120.00	new

PARTS TOTAL :	\$	35,673.42
---------------	----	-----------



Certificate No: AIA(S)101243

Certificate No: AIA(S)101244



GOLDBELL ENGINEERING

Industrial Vehicles.
20,000 Served. And Counting.

LABOUR CHARGES

1 TO TOW VEHICLE FROM ACCIDENT SCENE.	\$ 250.00 ✓
2 TO REMOVE & REFIT DAMAGED PARTS, CUT, WELD, PANEL BEAT, STRAIGHTEN & REALIGN, ETC. <i>6000 4200</i>	\$ 5,400.00
3 TO CHECK FOR & RECTIFY WIRING FAULTS, ETC. TO CARRY OUT DIAGNOSTICS CHECK.	\$ 280.00 ✓
4 TO REMOVE & REFIX FRONT WINDSCREEN.	\$ 350.00 ✓
5 TO REMOVE & REFIX DASHBOARD ASSY, INNER TRIMS & CARPETS. <i>1200</i>	\$ 1,400.00
6 TO REMOVE & REFIX QUARTER PANEL GLASS	\$ 120.00 ✓
7 TO REMOVE & REFIX FRONT DOOR COMPARTMENT.	\$ 250.00 ✓
8 TO PUTTY, CLEAN, SPRAY PAINT & POLISH, ETC. <i>2800</i>	\$ 3,150.00
9 SUNDRIES <i>80</i>	\$ 150.00

LABOUR TOTAL : \$ 11,350.00

GRAND TOTAL : \$ 47,023.42

PREPARED BY : WILLIAM GO

DATE / TIME : 24/02/17 @ 1530

SURVEYOR : *Revan 1Hp 9000068*

MOBILE NO. : 90000068

OFFICE FAX NO. :

EMAIL ADDRESS :

27/2/17.

51107 61

REPAIR TYPE : PART-BY-PART / LUMP SUM

RE-SURVEY : BEFORE PAINT / AFTER PAINT

NO. OF DAYS : 12 days

REMARKS :

EXCESS : 3000

REVERT



Certificate No: AJA(S)01Q1243

Certificate No: AJA(S)004



GOLDBELL ENGINEERING

GOLDBELL ENGINEERING PTE LTD

10 Tuas Avenue 18 Singapore 638894

Tel: +65 6861 0007 Fax: +65 6861 3678 (Sales)

Fax: +65 6863 0425 (Service) +65 6862 1347 (Parts)

Website: www.goldbell.com.sg

SUPPLEMENTARY ESTIMATE

Industrial Vehicles
DATE: 27/08/2016
20,000 Served And Counting.

TO : PAN OCEAN INTERNATIONAL P/L
ATTN : MS. IVY
OFFICE / MOBILE : 6266-3320
FAX NO. : -

FROM : GOLDBELL ENGINEERING PL
ATTN : MR. WILLIAM GO
OFFICE / MOBILE : 6864-0637 / 9755-7336
FAX NO. : 6863-0425

VEHICLE NO. : XE6006J
MODEL NO. : MITSUBISHI FP51SDR3VDEA
CHASSIS NO. : FP51SDA20027
ENGINE NO. : OM457319642

REF. NO. : GBE/SVC/SALES-4179/170217

D.O.A. : 13/02/2017

POLICY NO. : -

CLAIM TYPE : OD CLAIM - MSIG

WORKSHOP : 10 TUAS AVE 18

S/N	PART NO.	DESCRIPTION	QUANTITY	PRICE
1	ML260691	STEERING SHAFT	1	\$ 2,717.08
2	MK472316	STEERING COLUMN DUST COVER	1	\$ 85.15
3	MK590004	STEERING SHAFT BRACKET	1	\$ 296.69
4	MC057480	STEERING SHAFT BRACKET BOLT	2	\$ 49.24
5	MK380368	BRAKE VALVE SETTING BOARD	1	\$ 69.70
6	MK583270	AIR OUTLET TEMPERATURE SENSOR	1	\$ 52.16
7	MK541611	COMBINATION CLOCK SPRING SWITCH	1	\$ 1,117.58
8	MC938833	HEEL PAD	1	\$ 44.68
SUB-TOTAL :				\$ 4,432.28
LESS 25% :				\$ 1,108.07
PARTS TOTAL :				\$ 3,324.20

LABOUR CHARGES

1 TO REMOVE & REFIX STEERING SHAFT ASSY.

\$ ~~480.00~~ 900

2 TO REMOVE & REFIX COMBINATION CLOCK SPRING SWITCH.

\$ ~~280.00~~ 200

LABOUR TOTAL : \$ 760.00

GRAND TOTAL : \$ 4,084.20

PREPARED BY : WILLIAM GO

DATE / TIME : _____

SURVEYOR : _____

MOBILE NO. : _____

OFFICE FAX NO. : _____

EMAIL ADDRESS : _____





GOLDBELL ENGINEERING

Industrial Vehicles.
20,000 Served. And Counting.

GOLDBELL ENGINEERING PTE LTD

10 Tuas Avenue 18 Singapore 638894

Tel: +65 6861 0007 Fax: +65 6861 3676 (Sales)

Fax: +65 6863 0425 (Service) +65 6862 1347 (Parts)

Website: www.goldbell.com.sg

Co. Reg. No.: 198003963G

DATE : 17/02/2017

TO : PAN OCEAN INTERNATIONAL P/L

ATTN : MS. IVY

OFFICE / MOBILE : 6266-3320

EMAIL ADDRESS : -

FROM : GOLDBELL ENGINEERING P/L

ATTN : MR WILLIAM GO

OFFICE / MOBILE : 6864-0637 / 9755-7336

FAX NO. : 6863-0425

VEHICLE NO. : XE6006J

MODEL NO. : MITSUBISHI FP51SDR3VDEA

CHASSIS NO. : FP51SDA20027

ENGINE NO. : OM457319642

REG. DATE : 22/03/2016

REF. NO. : GBE/SVC/SALES-4179/170217

D.O.A. : 13/02/2017

POLICY NO. : -

CLAIM TYPE : OD CLAIM - MSIG

WORKSHOP : 10 TUAS AVE 18

S/N	PART NO.	DESCRIPTION	QUANTITY	PRICE
1	MK704681	FRONT PANEL	1	\$ 5,625.86 <i>RL ✓</i>
2	MK487575	FRONT PANEL TOP WEATHERSTRIP	1	\$ 150.20 <i>X ✓</i>
3	MK615044	FRONT PANEL SIDE WEATHERSTRIP	2	\$ 103.94 <i>X ✓</i>
4	MK548405	"FUSO" MARK	1	\$ 320.88 <i>RL ✓</i>
5	MK702798	FRONT PILLAR RHS	1	\$ 1,870.89 <i>RL ✓</i>
6	MC977768	FRONT CORNER PANEL RHS	1	\$ 1,087.51 <i>GM ✓</i>
7	MK614682	FRONT CORNER PANEL SEAL OUTER RHS	1	\$ 65.99 <i>RL ✓</i>
8	MK547619	FRONT CORNER PANEL SEAL INNER RHS	1	\$ 27.45 <i>RL ✓</i>
9	MK547612	FRONT CORNER PANEL BRACKET RHS	1	\$ 35.62 <i>RL ✓</i>
10	MK547616	FRONT CORNER PANEL BRACKET RHS	1	\$ 116.78 <i>RL ✓</i>
11	MK549686	FRONT CORNER PANEL SIDE BRACKET RHS	1	\$ 170.39 <i>RL ✓</i>
12	MK547800	FRONT CORNER PANEL SEAL LOWER RHS	1	\$ 87.21 <i>RL ✓</i>
13	MC977678	FRONT BUMPER	1	\$ 2,259.31 <i>DE ✓</i>
14	MK614407	FRONT BUMPER STAY RHS	1	\$ 169.07 <i>RL ✓</i>
15	MK675520	FRONT BUMPER SIDE GARNISH RHS	1	\$ 140.29 <i>DE ✓</i>
16	MK614603	FRONT BUMPER STEP GARNISH	1	\$ 217.26 <i>RL ✓</i>
17	MK674628	FRONT BUMPER AIR GUIDE DUCT RHS	1	\$ 96.70 <i>DE ✓</i>
18	MC979981	FRONT BUMPER TOP COVER CENTRE	1	\$ 278.12 <i>?</i>
19	MK549903	FRONT BUMPER TOP COVER REINFORCEMENT	1	\$ 884.79 <i>?</i>
20	MC979983	FRONT BUMPER TOP COVER RHS	1	\$ 193.04 <i>DE ✓</i>
21	MK549906	FRONT BUMPER TOP COVER REINFORCEMENT	1	\$ 226.06 <i>RL ✓</i>
22	MK548577	HEADLAMP RHS	1	\$ 1,286.45 <i>RL ✓</i>
23	MK549822	HEADLAMP BEZEL RHS	1	\$ 210.48 <i>RL ✓</i>
24	MK580189	HEADLAMP BRACKET RHS	1	\$ 947.63 <i>RL ✓</i>
25	MK545720	FOGLAMP RHS	1	\$ 293.25 <i>RL ✓</i>
26	MK549826	FOGLAMP BEZEL RHS	1	\$ 186.05 <i>RL ✓</i>
27	MK486318	FRONT TURN SIGNAL LAMP RHS	1	\$ 211.91 <i>RL ✓</i>
28	MK705213	FRONT DOOR RHS	1	\$ 4,626.16 <i>RL ✓</i>
29	MC992100	FRONT DOOR HINGE RHS	2	\$ 379.62 <i>RL ✓</i>
30	MC963828	FRONT DOOR GLASS RUNCHANNEL RHS	1	\$ 585.36 <i>RL ✓</i>
31	MC935116	FRONT DOOR WEATHERSTRIP RHS	1	\$ 534.01 <i>RL ✓</i>
32	MK580090	FRONT DOOR WEATHERSTRIP INNER RHS	1	\$ 356.74 <i>RL ✓</i>
33	MC937210	FRONT DOOR CHECK RHS	1	\$ 128.88 <i>RL ✓</i>
34	MC935065	FRONT DOOR REGULATOR RHS	1	\$ 276.16 <i>RL ✓</i>
35	MC935067	FRONT DOOR REGULATOR MOTOR RHS	1	\$ 410.64 <i>RL ✓</i>
36	MC935086	FRONT DOOR RAIL LOWER RHS	1	\$ 216.52 <i>?</i>
37	MK488599	FRONT DOOR LATCH & ACTUATOR RHS	1	\$ 900.45 <i>RL ✓</i>
38	MK580500	FRONT DOOR TRIM BOARD RHS	1	\$ 1,598.99 <i>?</i>

bizSAFE
STAR



Certificate No: AJA(E)11Q1243

Certificate No: AJA(E)11Q1244



GOLDBELL ENGINEERING

Industrial Vehicles.
20,000 Served. And Counting.

39	MC935038	FRONT DOOR INNER FILM RHS	1	\$	37.26	new
40	MH022009	FRONT DOOR TRIM BOARD PROTECTOR RHS	2	\$	20.06	new
41	MK546944	FRONT DOOR SIDE SIGNAL LAMP RHS	1	\$	81.53	CAH
42	MC992680	FRONT SIDE SILL PANEL RHS	1	\$	2,227.43	PE
43	MC976678	FRONT SIDE FENDER RHS	1	\$	1,241.68	PE
44	MC935719	FRONT SIDE FENDER GARNISH RHS	1	\$	223.34	DE
45	MC936273	FRONT SIDE FENDER SEAL RHS	1	\$	24.53	new
46	MC968233	FRONT SIDE FENDER SIDE BRACKET RHS	1	\$	257.84	PT
47	MC936687	FRONT SIDE FENDER REAR BRACKET RHS	1	\$	240.76	PT
48	MK674742	FRONT STEP GARNISH UPPER RHS	1	\$	744.59	cal
49	MC968229	FRONT STEP GARNISH UPPER BRACKET RHS	1	\$	254.70	new
50	MC932475	FRONT STEP PANEL UPPER RHS	1	\$	331.55	?
51	MC968226	FRONT STEP PANEL MIDDLE RHS	1	\$	294.32	?
52	MK676240	FRONT STEP GARNISH WALL RHS	1	\$	324.55	CAH
53	MC978910	FRONT STEP GARNISH LOWER RHS	1	\$	159.15	CAH
54	MC937840	FRONT STEP PANEL LOWER RHS	1	\$	331.55	CAH
55	MC937837	FRONT STEP GARNISH LOWER COVER RHS	1	\$	237.97	DE
56	MC962458	FRONT STEP SUPPORT LOWER RHS	1	\$	41.36	new
57	MC937901	FRONT STEP BRACKET LOWER RHS	1	\$	906.60	DE
58	MK549797	FRONT STEP BRACKET LOWER RHS	1	\$	906.60	PT
59	MC855877	FRONT STEP GARNISH REFLECTOR RHS	1	\$	37.35	new
60	MC857068	FRONT STEP GARNISH REFLECTOR NUT RHS	1	\$	2.95	new
61	MK710147	REAR QUARTTER PANEL OUTER RHS	1	\$	1,944.43	new
62	MC992439	REAR QUARTTER PANEL INNER RHS	1	\$	832.52	?
63	MC967608	REAR QUARTTER PANEL GLASS SEAL RHS	1	\$	131.77	new
64	MK456774	FRONT MUDGUARD RHS	1	\$	586.98	X
65	MK674378	FRONT WHEELHOUSING LINER RHS	1	\$	368.10	DE
66	MC936773	FRONT WHEELHOUSING LINER APRON SHIELD RHS	1	\$	182.12	DE
67	MC968207	FRONT WHEELHOUSING LINER APRON SHIELD RHS	1	\$	115.02	DE
68	MC968210	FRONT WHEELHOUSING LINER APRON SHIELD RHS	1	\$	107.16	DE
69	MC962290	REAR VIEW MIRROR LOWER COVER RHS	1	\$	38.53	new
70	MK565174	FRONT PILLAR TRIM RHS	1	\$	183.74	?
71	ML272435	REAR QUARTER PANEL TRIM RHS	1	\$	741.00	DE
72	MK565310	DASHBOARD	1	\$	3,536.73	?
73	MK565376	DASHBOARD CORNER RHS	1	\$	57.17	?
74	MK565373	DASHBOARD RHS	1	\$	307.21	?
75	MK565379	DASHBOARD INNER RHS	1	\$	379.70	?
76	MC934332	FRONT WINDSCREEN WEATHERSTRIP	1	\$	728.97	new
77	MK566997	SCUFF PLATE RHS	1	\$	164.17	new

SUB-TOTAL : 38720.21 \$ 46,604.56
LESS 25% : - 9680.05 \$ 11,651.14
BALANCE : 29040.16 \$ 34,953.42

SPECIAL-NETT ITEMS

1	COMPANY LOGO
2	SEALANT

PARTS TOTAL : 29760.16 \$ 35,673.42

bizSAFE
S T A R



Certificate No: AJA(010101243

Sancti new No: AJA(010101243



GOLDBELL ENGINEERING

Industrial Vehicles,
20,000 Served. And Counting.

LABOUR CHARGES

1 TO TOW VEHICLE FROM ACCIDENT SCENE.	\$ 250.00 ✓
2 TO REMOVE & REFIT DAMAGED PARTS, CUT, WELD, PANEL BEAT, STRAIGHTEN & REALIGN, ETC.	4200 4800 \$ 5,400.00
3 TO CHECK FOR & RECTIFY WIRING FAULTS, ETC. TO CARRY OUT DIAGNOSTICS CHECK	\$ 280.00 ✓
4 TO REMOVE & REFIX FRONT WINDSCREEN.	\$ 350.00 ✓
5 TO REMOVE & REFIX DASHBOARD ASSY, INNER TRIMS & CARPETS.	1200 \$ 1,400.00
6 TO REMOVE & REFIX QUARTER PANEL GLASS	\$ 120.00 ✓
7 TO REMOVE & REFIX FRONT DOOR COMPARTMENT.	\$ 250.00 ✓
8 TO PUTTY, CLEAN, SPRAY PAINT & POLISH, ETC.	2800 \$ 3,150.00
9 SUNDRIES	80 \$ 150.00
LABOUR TOTAL :	16130.00 \$ 11,350.00
GRAND TOTAL :	\$ 47,023.42

PREPARED BY : WILLIAM GO

DATE / TIME : 24/02/17 @ 1530

SURVEYOR : REPAIR 1HP 900W068

MOBILE NO. : 90010068

OFFICE FAX NO. :

EMAIL ADDRESS :

REPAIR TYPE : PART-BY-PART / LUMP SUM

RE-SURVEY : BEFORE PAINT / AFTER PAINT

NO. OF DAYS : 12 days

REMARKS :

EXCESS : 3000

REVERT

P: 29760.16
L: 10130.00
Supp 4084.20
\$43974.36

bizSAFE
STARS



Certificate No: AJA(9)01/01243

Cert No: AJA(9)01/01243

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	23 Feb 2017		24 Feb 2017 11:01 Edit Adj Rpt	S\$42,015.11 Edit Estimates	S\$42,015.11 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS
[Created by insurer]

Insured:	PAN OCEAN INTERNATIONAL PTE LTD, Co. Reg. No.: 199004645C		
Vehicle Reg. No.:	XE6006J	Date of Loss:	13/02/2017 08:00 - :59 [10 Months and 22 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 505605	Policy/Cover Note No.:	A28712860MKC (Comprehensive) Coverage: 22/03/2016 - 21/03/2017
		Excess:	S\$3,000.00
Repairer:	Goldbell Engineering Pte Ltd (Tuas) 29, Tanjong Penjuru, 609026 West Coast - Tel: 6864 0695		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Vimmala D/O Raja Singam - 65942471]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 26/03/2017]		
Driver/Custodian:	HAN ZHAOHUI (43 / Maie), NRIC: G8351765X, Tel: +6598077618		
Adj Asg. Remarks:	Please revert. Vehicle is in workshop now. Please survey by today		

ASSOCIATED MAIL RECEIVED
[View All](#)
[Compose Case Mail](#)

- MSIG_SG (30/04/2018): **XE6006J (505605)**
- MSIG_SG (14/02/2018): **Alert - Adj Mandate Approved (S\$42015.11) - XE6006J - Claim Handler: Vimmala D/O...**
- MSIG_SG (01/12/2017): **Alert - Adj Mandate Maintained - XE6006J - Claim Handler: Vimmala D/O Raja Singa...**
- MSIG_SG (30/11/2017): **Alert - Adj Mandate Maintained - XE6006J - Claim Handler: Vimmala D/O Raja Singa...**
- MSIG_SG (29/11/2017): **XE6006J (505605)**
- MSIG_SG (27/02/2017): **Alert - Adj Mandate Approved (S\$40353.19) - XE6006J - Claim Handler: Vimmala D/O...**

ALL ASSOCIATED TASKS
[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*XE6006J (505605)
OD
Feb 13 2017 8:00AM
[PAN OCEAN INTERNATIONAL PTE LTD]
Goldbell Engineering Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	27/02/17 14:50	Adjuster Immediate Advice	 Load HTM	☐
2	28/11/17 14:04	Adjuster Immediate Advice	 Load HTM	☐
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	27/02/17 14:11	General View	 Load JPG	☒
2	27/02/17 14:11	General View	 Load JPG	☒
3	27/02/17 14:11	General View	 Load JPG	☒
4	27/02/17 14:11	General View	 Load JPG	☒
5	27/02/17 14:11	General View	 Load JPG	☒
6	27/02/17 14:11	General View	 Load JPG	☒
7	27/02/17 14:11	General View	 Load JPG	☒
8	27/02/17 14:11	General View	 Load JPG	☒
9	27/02/17 14:11	General View	 Load JPG	☒
10	27/02/17 14:11	General View	 Load JPG	☒
11	27/02/17 14:11	General View	 Load JPG	☒
12	27/02/17 14:11	General View	 Load JPG	☒
13	27/02/17 14:11	General View	 Load JPG	☒
14	27/02/17 14:11	General View	 Load JPG	☒
15	27/02/17 14:11	General View	 Load JPG	☒
16	27/02/17 14:11	General View	 Load JPG	☒
17	27/02/17 14:11	General View	 Load JPG	☒
18	27/02/17 14:11	General View	 Load JPG	☒
19	27/02/17 14:11	General View	 Load JPG	☒
20	27/02/17 14:11	General View	 Load JPG	☒
21	27/02/17 14:11	General View	 Load JPG	☒
22	27/02/17 14:11	General View	 Load JPG	☒
23	27/02/17 14:11	General View	 Load JPG	☒
24	27/02/17 14:11	General View	 Load JPG	☒
25	27/02/17 14:11	General View	 Load JPG	☒
26	27/02/17 14:11	General View	 Load JPG	☒
27	27/02/17 14:11	General View	 Load JPG	☒
28	27/02/17 14:11	General View	 Load JPG	☒
29	27/02/17 14:11	General View	 Load JPG	☒
30	27/02/17 14:11	General View	 Load JPG	☒
31	27/02/17 14:11	General View	 Load JPG	☒
32	27/02/17 14:11	General View	 Load JPG	☒
33	27/02/17 14:11	General View	 Load JPG	☒
34	27/02/17 14:11	General View	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
35	27/02/17 14:11	General View	 Load JPG	☒
36	27/02/17 14:11	General View	 Load JPG	☒
37	27/02/17 14:11	General View	 Load JPG	☒
38	27/02/17 14:11	General View	 Load JPG	☒
39	27/02/17 14:11	General View	 Load JPG	☒
40	27/02/17 14:11	General View	 Load JPG	☒
41	27/02/17 14:11	General View	 Load JPG	☒
42	27/02/17 14:11	General View	 Load JPG	☒
43	27/02/17 14:11	General View	 Load JPG	☒
44	27/02/17 14:11	General View	 Load JPG	☒
45	27/02/17 14:11	General View	 Load JPG	☒
46	27/02/17 14:11	General View	 Load JPG	☒
47	27/02/17 14:11	General View	 Load JPG	☒
48	27/02/17 14:11	General View	 Load JPG	☒
49	27/02/17 14:11	General View	 Load JPG	☒
50	27/02/17 14:11	General View	 Load JPG	☒
51	27/02/17 14:11	General View	 Load JPG	☒
52	27/02/17 14:11	General View	 Load JPG	☒
53	27/02/17 14:11	General View	 Load JPG	☒
54	27/02/17 14:11	General View	 Load JPG	☒
55	27/02/17 14:11	General View	 Load JPG	☒
56	27/02/17 14:11	General View	 Load JPG	☒
57	27/02/17 14:11	General View	 Load JPG	☒
58	27/02/17 14:11	General View	 Load JPG	☒
59	27/02/17 14:11	General View	 Load JPG	☒
60	27/02/17 14:11	General View	 Load JPG	☒
61	27/02/17 14:11	General View	 Load JPG	☒
62	27/02/17 14:11	General View	 Load JPG	☒
63	27/02/17 14:11	General View	 Load JPG	☒
64	27/02/17 14:11	General View	 Load JPG	☒
65	27/02/17 14:11	General View	 Load JPG	☒
66	27/02/17 14:11	General View	 Load JPG	☒
67	27/02/17 14:11	General View	 Load JPG	☒
68	27/02/17 14:11	General View	 Load JPG	☒
69	27/02/17 14:11	General View	 Load JPG	☒
70	27/02/17 14:11	General View	 Load JPG	☒
71	27/02/17 14:11	General View	 Load JPG	☒
72	27/02/17 14:11	General View	 Load JPG	☒
73	27/02/17 14:11	General View	 Load JPG	☒
74	27/02/17 14:11	General View	 Load JPG	☒
75	27/02/17 14:11	General View	 Load JPG	☒
76	30/11/17 09:33	Reinspection Photo	 Load JPG	☒
77	30/11/17 09:33	Reinspection Photo	 Load JPG	☒
78	30/11/17 09:33	Reinspection Photo	 Load JPG	☒
79	30/11/17 09:33	Reinspection Photo	 Load JPG	☒
80	30/11/17 09:33	Reinspection Photo	 Load JPG	☒
81	30/11/17 09:33	Reinspection Photo	 Load JPG	☒
82	30/11/17 09:33	Reinspection Photo	 Load JPG	☒
83	30/11/17 09:33	Reinspection Photo	 Load JPG	☒
84	30/11/17 09:33	Reinspection Photo	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
85	30/11/17 09:33	Reinspection Photo	 Load JPG	☒
86	30/11/17 09:33	Reinspection Photo	 Load JPG	☒
87	30/11/17 09:33	Reinspection Photo	 Load JPG	☒
88	30/11/17 09:33	Reinspection Photo	 Load JPG	☒
89	30/11/17 09:33	Reinspection Photo	 Load JPG	☒
90	30/11/17 09:33	Reinspection Photo	 Load JPG	☒
91	30/11/17 09:33	Reinspection Photo	 Load JPG	☒
92	08/01/18 17:44	Reinspection Photo	 Load JPG	☒
93	08/01/18 17:44	Reinspection Photo	 Load JPG	☒
94	08/01/18 17:44	Reinspection Photo	 Load JPG	☒
95	07/05/18 12:11	Reinspection Photo	 Load JPG	☒
96	07/05/18 12:11	Reinspection Photo	 Load JPG	☒
97	07/05/18 12:11	Reinspection Photo	 Load JPG	☒
98	07/05/18 12:11	Reinspection Photo	 Load JPG	☒
99	07/05/18 12:11	Reinspection Photo	 Load JPG	☒
100	07/05/18 12:12	Reinspection Photo	 Load JPG	☒
101	07/05/18 12:12	Reinspection Photo	 Load JPG	☒
102	07/05/18 12:12	Reinspection Photo	 Load JPG	☒
103	07/05/18 12:12	Reinspection Photo	 Load JPG	☒
104	07/05/18 12:12	Reinspection Photo	 Load JPG	☒
105	07/05/18 12:12	Reinspection Photo	 Load JPG	☒
106	07/05/18 12:12	Reinspection Photo	 Load JPG	☒
107	07/05/18 12:12	Reinspection Photo	 Load JPG	☒
108	07/05/18 12:12	Reinspection Photo	 Load JPG	☒
109	07/05/18 12:12	Reinspection Photo	 Load JPG	☒
110	07/05/18 12:12	Reinspection Photo	 Load JPG	☒
111	07/05/18 12:12	Reinspection Photo	 Load JPG	☒
112	07/05/18 12:12	Reinspection Photo	 Load JPG	☒
113	07/05/18 12:12	Reinspection Photo	 Load JPG	☒
114	07/05/18 12:12	Reinspection Photo	 Load JPG	☒
115	07/05/18 12:12	Reinspection Photo	 Load JPG	☒
116	07/05/18 12:12	Reinspection Photo	 Load JPG	☒
117	07/05/18 12:12	Reinspection Photo	 Load JPG	☒
118	07/05/18 12:12	Reinspection Photo	 Load JPG	☒
119	07/05/18 12:12	Reinspection Photo	 Load JPG	☒
120	07/05/18 12:12	Reinspection Photo	 Load JPG	☒
121	07/05/18 12:12	Reinspection Photo	 Load JPG	☒
122	07/05/18 12:12	Reinspection Photo	 Load JPG	☒
123	07/05/18 12:12	Reinspection Photo	 Load JPG	☒
124	07/05/18 12:12	Reinspection Photo	 Load JPG	☒
125	07/05/18 12:12	Reinspection Photo	 Load JPG	☒
126	07/05/18 12:12	Reinspection Photo	 Load JPG	☒
127	07/05/18 12:12	Reinspection Photo	 Load JPG	☒
128	07/05/18 12:12	Reinspection Photo	 Load JPG	☒
129	07/05/18 12:12	Reinspection Photo	 Load JPG	☒
130	07/05/18 12:12	Reinspection Photo	 Load JPG	☒
131	07/05/18 12:12	Reinspection Photo	 Load JPG	☒
132	07/05/18 12:12	Reinspection Photo	 Load JPG	☒
133	07/05/18 12:12	Reinspection Photo	 Load JPG	☒
134	07/05/18 12:12	Reinspection Photo	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
135	07/05/18 12:12	Reinspection Photo	 Load JPG	☒
136	07/05/18 12:12	Reinspection Photo	 Load JPG	☒
137	07/05/18 12:12	Reinspection Photo	 Load JPG	☒
138	07/05/18 12:13	Reinspection Photo	 Load JPG	☒
139	07/05/18 12:13	Reinspection Photo	 Load JPG	☒
140	07/05/18 12:13	Reinspection Photo	 Load JPG	☒
141	07/05/18 12:13	Reinspection Photo	 Load JPG	☒
142	07/05/18 12:13	Reinspection Photo	 Load JPG	☒
143	07/05/18 12:13	Reinspection Photo	 Load JPG	☒
144	07/05/18 12:13	Reinspection Photo	 Load JPG	☒
145	07/05/18 12:13	Reinspection Photo	 Load JPG	☒
146	07/05/18 12:13	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	24/02/17 09:48	Estimate repair from Goldbell engineering	 Load PDF	
2	24/02/17 09:52	Email from Goldbell Engineering to arrange for survey	 Load PDF	
3	24/02/17 09:59	Enquire Rebate details	 Load PDF	
4	30/04/18 16:36	Signed DV	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	29/11/17 09:07	REVISED ESTIMATE	 Load PDF	
2	29/11/17 09:07	SUPPLEMENTARY LIST	 Load PDF	
3	08/05/18 10:02	COLOUR PHOTO	 Load PDF	

Linked Accident Report Documents

Assessment Reports			1 per page	☒
No	Finalized On	Goldbell Engineering Pte Ltd (Tuas)	Thumbnail	Print
1	13/02/17 13:39	Accident Statement	 Load HTM	
2	23/02/17 14:03	Addendum Sheet	 Load TIF	
3	23/02/17 14:03	Accident Statement Addm. #1	 Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	Goldbell Engineering Pte Ltd (Tuas)	Thumbnail	Print
1	13/02/17 13:38	Accident Photo	 Load JPG	☒
2	13/02/17 13:38	Accident Photo	 Load JPG	☒
3	13/02/17 13:38	Accident Photo	 Load JPG	☒
4	13/02/17 13:38	Accident Photo	 Load JPG	☒
5	13/02/17 13:38	Accident Photo	 Load JPG	☒
6	13/02/17 13:38	Accident Photo	 Load JPG	☒
7	13/02/17 13:38	Accident Photo	 Load JPG	☒
8	13/02/17 13:38	Accident Photo	 Load JPG	☒
9	13/02/17 13:38	Accident Photo	 Load JPG	☒
10	13/02/17 13:38	Accident Photo	 Load JPG	☒
11	13/02/17 13:38	Accident Photo	 Load JPG	☒
12	13/02/17 13:38	Accident Photo	 Load JPG	☒
13	13/02/17 13:38	Accident Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Goldbell Engineering Pte Ltd (Tuas)	Thumbnail	Print
1	13/02/17 13:36	Sketch Plan	 Load TIF	
2	13/02/17 13:36	Sketch Plan #2	 Load TIF	
3	13/02/17 13:36	Sketch Plan #3	 Load TIF	

Assessment Reports			1 per page	☒
No	Finalized On	Goldbell Engineering Pte Ltd (Tuas)	Thumbnail	Print
4	13/02/17 13:36	Sketch Plan #4	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
Show Remarks To: ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/MSG17003854/R1QBE2

Date: 08/05/2018

REFERENCE

Insured/Claimant: PAN OCEAN INTERNATIONAL PTE LTD

Policy No: A28712860MKC

Date of Loss: 13/02/2017

Nature of Claim: OD

Claim No: 505605

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: XE6006J

Make & Model: MITSUBISHI FP51SDR3VDEA, 12.0 D (M)

Engine No: OM457319642

Reg. Date: 22/03/2016 (Man. Year: 2015)

Chassis No: FP51SDA20027

Colour: Brown

Odometer: 0 km

Engine Capacity: 11967 cc

Market Value/New Car Price: S\$130,000.00

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 295/80 R22.5

Rear Tyre Size: 295/80 R22.5 (D)

Front Left Side: Bridgestone 8 mm

Rear Left Side: Bridgestone 8/8 mm

Front Right Side: Bridgestone 8 mm

Rear Right Side: Bridgestone 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	39,147.61	31,965.11	7,182.50	18.35
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,960.00	10,050.00	1,910.00	15.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	51,107.61	42,015.11	9,092.50	17.79
- Excess (S\$)	3,000.00	3,000.00	0.00	0.00
(S\$)	48,107.61	39,015.11	9,092.50	18.90
+ GST 7.00/7.00% (S\$)	3,367.53	2,731.06	636.47	18.90
Nett Amount (S\$)	51,475.14	41,746.17	9,728.97	18.90

INSPECTION

Date of Assignment: 24/02/2017

Date Inspected: 24/02/2017 Inspected At:

Goldbell Engineering Pte Ltd (Tuas)
10, Tuas Avenue 18
Singapore 638894

Estimated Period of Repair: 12.0 days

Adjuster: MOHD RASUL

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 08 May 2018)	
Parts:	N/A	MITSUBISHI FP51SDR3VDEA 12.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for XE6006J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT PANEL	Bent	5,625.86 FL	*5,625.86 FL
2	1	*FRONT PANEL TOP WEATHERSTRIP	Necessary	150.20 FL	*150.20 FL
3	2	*FRONT PANEL SIDE WEATHERSTRIP	Necessary	103.94 FL	*103.94 FL
4	1	*FUSO MARK	Necessary	320.88 FL	*320.88 FL
5	1	*FRONT PILLAR RHS	Bent	1,870.89 FL	*1,870.89 FL
6	1	*FRONT CORNER PANEL RHS	Cracked	1,087.51 FL	*1,087.51 FL
7	1	*FRONT CORNER PANEL SEAL OUTER RHS	Necessary	65.99 FL	*65.99 FL
8	1	*FRONT CORNER PANEL SEAL INNER RHS	Necessary	27.45 FL	*27.45 FL
9	1	*FRONT CORNER PANEL BRACKET RHS	Necessary	35.62 FL	*35.62 FL
10	1	*FRONT CORNER PANEL BRACKET RHS	Necessary	116.76 FL	*116.76 FL
11	1	*FRONT CORNER PANEL SIDE BRACKET RHS	Necessary	170.34 FL	*170.34 FL
12	1	*FRONT CORNER PANEL SEAL LOWER RHS	Necessary	87.21 FL	*87.21 FL
13	1	*FRONT BUMPER	Deformed	2,259.31 FL	*2,259.31 FL
14	1	*FRONT BUMPER STAY RHS	Bent	169.07 FL	*169.07 FL
15	1	*FRONT BUMPER SIDE GARNISH RHS	Deformed	140.29 FL	*140.29 FL
16	1	*FRONT BUMPER STEP GARNISH	Cut	217.26 FL	*217.26 FL
17	1	*FRONT BUMPER AIR GUIDE DUCT RHS	Deformed	96.70 FL	*96.70 FL
18	1	*FRONT BUMPER TOP COVER CENTRE	Serviceable	273.12 FL	*- FL
19	1	*FRONT BUMPER TOP COVER REINFORCEMENT	Serviceable	884.79 FL	*- FL
20	1	*FRONT BUMPER TOP COVER RHS	Deformed	193.04 FL	*193.04 FL
21	1	*FRONT BUMPER TOP COVER REINFORCEMET	Bent	226.06 FL	*226.06 FL
22	1	*HEADLAMP RHS	Broken	1,286.45 FL	*1,286.45 FL
23	1	*HEADLAMP BEZEL RHS	Broken	210.48 FL	*210.48 FL
24	1	*HEADLAMP BRACKET RHS	Bent	947.63 FL	*947.63 FL
25	1	*FOGLAMP RHS	Broken	293.25 FL	*293.25 FL
26	1	*FOGLAMP BEZEL RHS	Cracked	186.05 FL	*186.05 FL
27	1	*FRONT TURN SIGNAL LAMP RHS	Cracked	211.91 FL	*211.91 FL
28	1	*FRONT DOOR RHS	Buckled	4,626.16 FL	*4,626.16 FL
29	2	*FRONT DOOR HINGE RHS	Bent	379.62 FL	*379.62 FL
30	1	*FRONT DOOR GLASS RUNCHANNEL RHS	Not Working	585.36 FL	*585.36 FL
31	1	*FRONT DOOR WEATHERSTRIP RHS	Necessary	534.01 FL	*534.01 FL
32	1	*FRONT DOOR WEATHERSTRIP INNER RHS	Necessary	356.74 FL	*356.74 FL
33	1	*FRONT DOOR CHECK RHS	Bent	128.88 FL	*128.88 FL
34	1	*FRONT DOOR REGULATOR RHS	Bent	276.16 FL	*276.16 FL
35	1	*FRONT DOOR REGULATOR MOTOR RHS	Not Working	410.64 FL	*410.64 FL
36	1	*FRONT DOOR RAIL LOWER RHS	Serviceable	216.52 FL	*- FL
37	1	*FRONT DOOR LATCH & ACTUATOR RHS	Bent	900.45 FL	*900.45 FL
38	1	*FRONT DOOR TRIM BOARD RHS	Serviceable	1,598.99 FL	*- FL
39	1	*FRONT DOOR INNER FILM RHS	Necessary	37.26 FL	*37.26 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	2		*FRONT DOOR TRIM BOARD PROTECTOR RHS	Necessary	20.06 FL	*20.06 FL
41	1		*FRONT DOOR SIDE SIGNAL LAMP RHS	Cracked	81.53 FL	*81.53 FL
42	1		*FRONT SIDE SILL PANEL RHS	Bent	2,227.43 FL	*2,227.43 FL
43	1		*FRONT SIDE FENDER RHS	Deformed	1,241.66 FL	*1,241.66 FL
44	1		*FRONT SIDE FENDER GARNISH RHS	Deformed	223.34 FL	*223.34 FL
45	1		*FRONT SIDE FENDER SEAL RHS	Necessary	24.53 FL	*24.53 FL
46	1		*FRONT SIDE FENDER SIDE BRACKET RHS	Bent	257.84 FL	*257.84 FL
47	1		*FRONT SIDE FENDER REAR BRACKET RHS	Bent	240.76 FL	*240.76 FL
48	1		*FRONT STEP GARNISH UPPER RHS	Cut	744.59 FL	*744.59 FL
49	1		*FRONT STEP GARNISH UPPER BRACKET RHS	Bent	254.70 FL	*254.70 FL
50	1		*FRONT STEP PANEL UPPER RHS	Serviceable	331.55 FL	*- FL
51	1		*FRONT STEP PANEL MIDDLE RHS	Serviceable	294.32 FL	*- FL
52	1		*FRONT STEP GARNISH WALL RHS	Cracked	324.55 FL	*324.55 FL
53	1		*FRONT STEP GARNISH LOWER RHS	Cracked	159.15 FL	*159.15 FL
54	1		*FRONT STEP PANEL LOWER RHS	Cracked	331.55 FL	*331.55 FL
55	1		*FRONT STEP GARNISH LOWER COVER RHS	Deformed	237.97 FL	*237.97 FL
56	1		*FRONT STEP SUPPORT LOWER RHS	Necessary	41.36 FL	*41.36 FL
57	1		*FRONT STEP BRACKET LOWER RHS	Bent	906.60 FL	*906.60 FL
58	1		*FRONT STEP BRACKET LOWER RHS	Bent	906.60 FL	*906.60 FL
59	1		*FRONT STEP GARNISH REFLECTOR RHS	Missing	37.35 FL	*37.35 FL
60	1		*FRONT STEP GARNISH REFLECTOR NUT RHS	Necessary	2.95 FL	*2.95 FL
61	1		*REAR QUARTER PANEL OUTER RHS	Buckled	1,944.43 FL	*1,944.43 FL
62	1		*REAR QUARTER PANEL INNER RHS	Serviceable	832.52 FL	*- FL
63	1		*REAR QUARTER PANEL GLASS SEAL RHS	Necessary	131.77 FL	*131.77 FL
64	1		*FRONT MUDGUARD RHS	Serviceable	586.98 FL	*- FL
65	1		*FRONT WHEELHOUSING LINER RHS	Deformed	368.10 FL	*368.10 FL
66	1		*FRONT WHEELHOUSING LINER APRON SHIELD RHS	Deformed	182.12 FL	*182.12 FL
67	1		*FRONT WHEELHOUSING LINER APRON SHIELD RHS	Deformed	115.02 FL	*115.02 FL
68	1		*FRONT WHEELHOUSING LINER APRON SHIELD RHS	Deformed	107.16 FL	*107.16 FL
69	1		*REAR VIEW MIRROR LOWER COVER RHS	Missing	38.53 FL	*38.53 FL
70	1		*FRONT PILLAR TRIM RHS	Serviceable	183.74 FL	*- FL
71	1		*REAR QUARTER PANEL TRIM RHS	Deformed	741.00 FL	*741.00 FL
72	1		*DASHBOARD	Serviceable	3,536.73 FL	*- FL
73	1		*DASHBOARD CORNER RHS	Serviceable	57.17 FL	*- FL
74	1		*DASHBOARD RHS	Serviceable	307.21 FL	*- FL
75	1		*DASHBOARD INNER RHS	Serviceable	379.70 FL	*- FL
76	1		*FRONT WINDSCREEN WEATHERSTRIP	Necessary	728.97 FL	*728.97 FL
77	1		*SCUFF PLATE RHS	Deformed	164.17 FL	*164.17 FL
78	1		*COMPANY LOGO	Necessary	600.00 FS	*600.00 FS
79	3		*SEALANT	Necessary	120.00 FS	*120.00 FS
80	1		*SUNDRIES	Necessary	150.00 FS	*80.00 FS
81	1		*STEERING SHAFT	Bent	2,717.06 FL	*2,717.06 FL
82	1		*STEERING COLUMN DUST COVER	Cracked	85.15 FL	*85.15 FL
83	1		*STEERING SHAFT BRACKET	Bent	296.69 FL	*296.69 FL
84	2		*STEERING SHAFT BRACKET BOLT	Necessary	49.24 FL	*49.24 FL
85	1		*BRAKE VALVE SETTING BOARD	Bent	69.70 FL	*69.70 FL
86	1		*AIR OUTLET TEMPERATURE SENSOR	Not Working	52.16 FL	*52.16 FL
87	1		*COMBINATION CLOCK SPRING SWITCH	Not Working	1,117.58 FL	*1,117.58 FL
88	1		*HEEL PAD	Torn	44.68 FL	*44.68 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) **51,906.82** **42,353.48**
 - List Item Discount on L Items 25.00/25.00% (\$\$) **12,759.21** **10,388.37**

Total Parts (\$\$) 39,147.61 31,965.11

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO TOW VEHICLE FROM ACCIDENT SCENE	New	250.00	250.00
2	TO REMOVE & REFIT DAMAGED PARTS, CUT, WELD, PANEL BEAT, STRAIGHTEN & REALIGN, ETC	New	5,400.00	4,200.00
3	TO CHECK FOR & RECTIFY WIRING FAULTS, ETC. TO CARRY OUT DIAGNOSTICS CHECK	New	280.00	280.00
4	TO REMOVE & REFIX FRONT WINDSCREEN	New	350.00	350.00
5	TO REMOVE & REFIX DASHBOARD ASSY, INNER TRIMS & CARPETS	New	1,400.00	1,200.00
6	TO REMOVE & REFIX QUARTER PANEL GLASS	New	120.00	120.00
7	TO REMOVE & REFIX FRONT DOOR COMPARTMENT	New	250.00	250.00
8	TO PUTTY, CLEAN, SPRAY PAINT & POLISH, ETC	New	3,150.00	2,800.00
9	TO REMOVE & REFIX STEERING SHAFT ASSY	New	480.00	400.00
10	TO REMOVE & REFIX COMBINATION CLOCK SPRING SWITCH	New	280.00	200.00
Gross Labour Cost (\$\$)			11,960.00	10,050.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >