

ASS. REC. BY:

REF: CSMSC17003882/Rlg/32

Special Instruction:

Surveyor
Mee Men

Rasul

ASSIGNMENT (Office)

From (Person):

Kwok Woon Choo

of

MSCG

Date/Time:

24/2/2017 3:02pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKW6474A

Insured:

at Workshop m/s

Hitachi Capital

Tel:

6833 8282

of

8 Fauch Wc Yang Road

Policy No:

MSD/VPCP/16-002215-00

Claim No:

MSC 16/17-000316

Sum Insured:

Excess:

\$ 1,500.00

Make of Veh:

(Client's Record)

D.O.A 22/1/2017

CA / REV

/ REP. / REV 24 HRS

H.O.D Endorsement:

Date/Time:

24/2/2017 3:07pm

Person Contacted:

Grant

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SKW6474A-2

24/2/17 @ 10.50am revert to Woon Choo via Mee Men.

24/2/17 @ 1.34pm Siew Wei informed C/A via Mee Men.

24/2/17 @ 5.48pm Informed Mr Cheng C/A to BK1 \$1500 by email.

24/2/17 @ 1.43pm 2nd revert to Woon Choo via Mee Men. (Supplementary).

25/2/17 @ 8.56am Siew Wei informed C/A at \$16710.35 via Mee Men.

10/01/11/13
ASS. REC. BY: *Ronan*

REF:

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: **SKW 6474A**
at Workshop m/s: **Hitachi Capim**
of: **8, Fourth Lok Yuen**
Insured: **MSH / 00**

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: **1500**

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value

153K

IDAC Accident Report: _____ Consistent? Yes or No

GIA / PR Seen: _____ Consistent? Yes or No

Est. Repairs: **12** days Res: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / ☒ REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: **SKW 6474A** Yr Regn: **2015 / NOV**
Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or

Make: **TOYOTA VEH PART 2-5** c.c. **2498**

Colour: **BLACK** A/C: Insured / Std / NI / NA

Sp. Reading: **90052** T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: **STNGF 30H 208002862**

Gen. Cond: Good / ☒ Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / ☒ S/Rim / STD A/Rim or

Tyre Size: F: **235/50R18**

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal: **6** mm R/Bal: **6** mm

L/Bal: **6** mm L/Bal: **6** mm

D.O.A: **23/02/17** D.O.I: **24/02/17**

Survey held at: **HITACHI CAPIM**

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

FRONT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

25/5/18 @ 10:57am confirmed with Jamesoh final fig \$16710.35, 12 days.
(Red \$6679.80, 28%)

Rasul

where with wire harness photo.

RECEIVED 26 JUN 2018

(photos 0141, 0142, 0143)

(photo all had already upload)

Date/Time: File Pass to?

☐

: Preli. Report

Days Of Repair: **12**

Resurvey No. of Trip: **1**

Survey Fee

Transportation

Date/Time: File Return to?

☐

: Final Report

Add Fee:

☐

Site Insp (\$

) \$ + RS \$

☐

Interview (\$

) Photos

☐

Tech. Invs (\$

) Others

☐

Weekend (\$

)

Report Format: **MEMO**

Lump Sum / I.B.I.: (\$ **16710.35**)

TOTAL

311



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (SINGAPORE) PTE LTD			Ref : CS/MSG17003882/R1qh3	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581			Date : 24-02-2017	
			Code : MSG	
1. Policy Particulars :- OWN DAMAGE				
Insured Veh.		Veh. Inspected		SKW 6474A
Policy No.	MSD/VPCP/16-002215-00	Coverage (\$)	0.00	
Claim No.	MSC/V/17-000316	Excess (\$)	1,500.00	
Assign From	MERIMEN (KWOK WOON CHOO)	Assign Date	24/02/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer		Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	23/02/2017	Inspection Date	24/02/2017	
Survey held at	HITACHI CAPITAL (S) PTE LTD JUN TAIYO SERVICE CENTRE NO. 8 FOURTH LOK YANG ROAD SINGAPORE 629705			
5a. Remarks				
A) THE MARKET VALUE IS S\$----- (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.				

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rot	Adj Submitted	Ins Path'd	Status
Main	24 Feb 2017 Sendback Est	24 Feb 2017 10:15 S\$16,968.40	24 Feb 2017 15:02 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured:	HITACHI CAPITAL AISIA PACIFIC PTE LTD , Co. Reg. No.: 199400399N								
Vehicle Reg. No.:	SKW6474A	Date of Loss:	23/02/2017 06:00 - :59						
Claim Type:	OD / MSC/V/17-000316	Policy/Cover Note No.:	MSD/VPCP/16-002215-00 (Comprehensive) Coverage: 14/10/2016 - 13/10/2017						
		Excess:	S\$1,500.00						
Repairer:	Hitachi Capital Asia Pacific Pte. Ltd (HQ) No 8 Fourth Lok Yang Road, 629705 Pioneer - Tel: 64663022								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Kwok Woon Choo - 6643 1330]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 25/02/2017]								
Driver/Custodian:	CHOW KERR CHUEN (ZHOU KEQUAN) (31 / Male), NRIC: S8511081J, Tel: +6598325234								
Adj. Asg. Remarks:	TO REVERT								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Friday, 25 May 2018 10:57 AM
To: 'Jamilah, Binte MohdKassim'; SUR; Admin A; assignments; Taufikh (LKKAUTO); Rasul (LKKAUTO); Guo Qiang (LKKAUTO); Asher Sng (LKKAUTO); Vic (LKKAUTO)
Cc: Kevin, MJ Leong
Subject: RE: LKK OUTSTANDING CASE FINALISE (BY GRANT CHONG) - URGENT

Dear Jamilah,

SKW 6474A (DOA: 23/02/2017) – Confirm final fig \$16,710.35 before excess \$1,500.00 & GST and 12 repair days.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Jamilah, Binte MohdKassim [mailto:jamilahbegum@hcspl.com.sg]
Sent: Monday, 30 April 2018 12:42 PM
To: SUR <sur@lkkauto.com>; Admin A <admin-a@lkkauto.com>; Admin-D (LKKAUTO) <admin-d@lkkauto.com>; Taufikh (LKKAUTO) <Taufikh@lkkauto.com>; Rasul (LKKAUTO) <Rasul@lkkauto.com>; Guo Qiang (LKKAUTO) <GuoQiang@lkkauto.com>; Denise Tay (LKKAUTO) <denisetay@lkkauto.com>; Asher Sng (LKKAUTO) <AsherSng@lkkauto.com>; Vic (LKKAUTO) <vicalpeh@lkkauto.com>; Jas Khine (LKKAUTO) <jaskhine@lkkauto.com>; Janice Lee (LKKAUTO) <JaniceLee@lkkauto.com>; Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Cc: Kevin, MJ Leong <kevinleong@hcspl.com.sg>
Subject: RE: LKK OUTSTANDING CASE FINALISE (BY GRANT CHONG) - URGENT

Dear All,

Good Afternoon.

Please take note Grant has resigned.

Only 3 cases closed since (in red).

Appreciate your immediate action to close the balance cases before Mid May 2018.

Thank you & regards,

Jamilah

Admin Assistant

Auto Servicing

Total Vehicle Solutions Department

Hitachi Capital Asia Pacific Pte. Ltd.

Jun Taiyo Service Centre (Automobile Leasing & Workshop)

8 Fourth Lok Yang Road Singapore 629705

t: 6833 6265

e: jamilahbegum@hcspl.com.sg

w: www.hitachi-capital.com.sg

HITACHI
Inspire the Next

Claim Audit

AUDIT TRAIL					By
No.	On	Audit	Remarks		
1	24 Feb 2017 09:31	Clim Veh Model Changed	(204073) TOYOTA VELLFIRE 2.5 (A).		[R] Grant Chong Kean Yap
2	24 Feb 2017 09:31	Clim Created	Reg No: SKW6474A. Policy No: MSD/VPCP/16-002215-00, Acct Date: 2017/02/23. Claim Type: OD. Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ). Workshop: Hitachi Capital Asia Pacific Pte. Ltd (HQ). Created from SAS: MJT117025065		[R] Grant Chong Kean Yap
3	24 Feb 2017 10:15	Clim Submitted	16968.40.		[R] Grant Chong Kean Yap
4	24 Feb 2017 11:53	Adj Co Assigned	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor): a if c		[I] Lui Siew Wei
5	24 Feb 2017 11:53	Adj Next Rpt Changed	Next Rpt: Im. Advice. Due Date: 2017/02/25		[I] Lui Siew Wei
6	24 Feb 2017 11:53	Adj Mandate Set	Approved: 25000.00. Reinsp: Adj decides.		[I] Lui Siew Wei
7	24 Feb 2017 11:53	Clim Registration Modified	Excess: -> 1500.00.		[I] Lui Siew Wei
8	24 Feb 2017 13:40	Assignment 1st Accessed			[A] Ho Pei Fang
9	24 Feb 2017 15:01	Adj Assignment Cancelled	IHS APPT FULL		[I] Kwok Woon Choo
10	24 Feb 2017 15:01	Adj Est Details Deleted	Deleting Est Details For Cancelling Adjuster Assignment		[I] Kwok Woon Choo
11	24 Feb 2017 15:02	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ): TO REVERT		[I] Kwok Woon Choo
12	24 Feb 2017 15:02	Adj Next Rpt Changed	Next Rpt: Im. Advice. Due Date: 2017/02/25		[I] Kwok Woon Choo
13	24 Feb 2017 15:02	Adj Mandate Set	Approved: 25000.00. Reinsp: Adj decides.		[I] Kwok Woon Choo
14	24 Feb 2017 15:03	Assignment 1st Accessed			[A] Ashley Chong Chin Yan
15	24 Feb 2017 15:14	Adj Adjuster Assigned	[None] -> MOHD RASUL		[A] Ashley Chong Chin Yan
16	27 Feb 2017 10:47	Adj Rpt Initiated			[A] SHIAU CHAN
17	27 Feb 2017 10:49	Adj Im. Advice Submitted	Next Rpt: Final Rpt. Due Date: 2017/03/26		[A] SHIAU CHAN
18	27 Feb 2017 10:49	Adj Next Rpt Changed	Next Rpt: Final Rpt. Due Date: 2017/03/26		[A] SHIAU CHAN
19	27 Feb 2017 10:50	Adj Mandate Request	Cur. Req: 10346.30: DAMAGES CONSISTENT. REPAIR COST ECONOMICAL.		[A] SHIAU CHAN
20	27 Feb 2017 13:39	Adj Next Rpt Changed	Next Rpt: Final Rpt. Due Date: 2017/03/26. Mandate Remarks: a if c; check items to be confirmed		[I] Lui Siew Wei
21	27 Feb 2017 13:39	Adj Mandate Set	Approved: 9909.60: a if c; check items to be confirmed		[I] Lui Siew Wei
22	20 Jul 2017 10:45	Clim Supp Created (S:618789)			[R] Grant Chong Kean Yap
23	20 Jul 2017 16:34	Clim Submitted (S:618789)	6371.75.		[R] Grant Chong Kean Yap
24	20 Jul 2017 16:34	Adj Co Assigned (S:618789)	LKK Auto Consultants Pte Ltd (HQ):		[I] Merimen Administrator
25	21 Jul 2017 09:43	Supp Combined (S:618789)			[A] SHIAU CHAN
26	24 May 2018 13:41	Adj Im. Advice Submitted	Next Rpt: Final Rpt. Due Date: 2017/03/26		[A] SHIAU CHAN
27	24 May 2018 13:43	Adj Mandate Request	Cur. Req: 16710.35: DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. KINDLY AP PROVE ON SUPPLEMENTARY.		[A] SHIAU CHAN
28	25 May 2018 08:56	Adj Next Rpt Changed	Next Rpt: Final Rpt. Due Date: 2017/03/26. Mandate Remarks: a if c		[I] Lui Siew Wei
29	25 May 2018 08:56	Adj Mandate Set	Approved: 16710.35: a if c		[I] Lui Siew Wei

Date From



Date To



Audit Type None

Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1390900	24/02/2017 09:31	Motor	Hitachi Capital Asia Pacific Pte.	Hitachi Capital Asia Pacific Pte.	SKW6474A		XX.XX

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Kwok Woon Choo

Date: 24 May 2018

Preliminary Advice

Vehicle No	: SKW6474A	Accident Date	: 23/02/2017
Make	: TOYOTA VELLFIRE	Policy No.	: MSD/VPCP/16-002215-00
Assignment Date	: 24/02/2017	Excess	: S\$1,500.00
Date of Inspection	: 24/02/2017	Est. Duration of Repair	: 12.00
Inspection At	: HITACHI CAPITAL ASIA PACIFIC PTE. LTD (HQ) NO 8 FOURTH LOK YANG ROAD SINGAPORE 629705		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	23,340.15	(ESTIMATE \$16,968.40 + SUPPLEMENTARY \$6,371.75)
Revised Amount	:S\$	16,710.35	(INCLUSIVE OF SUPPLEMENTARY)
Check Items (Estimated)	:S\$	0.00	
Total	:S\$	16,710.35	
Lump Sum Repair	:S\$		

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	153,000.00
COE / PARF Rebate	:S\$	95,723.00
Salvage Value	:S\$	
Margin for Repair	:S\$	57,277.00

Remarks

(X) The vehicle is economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis. KINDLY APPROVE ON SUPPLEMENTARY.

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Monday, 27 February, 2017 5:48 PM
To: Chong Kean Yap
Cc: SUR
Subject: VEHICLE SKW 6474A DOA: 23/02/2017

Dear Mr Chong,

As instructed by our client MSIG Insurance Company, please proceed to repair the insured vehicle SKW 6474A (excess \$1,500.00).

If there are any check items or supplementary items please inform our office's Assignment Team at : 6741 8434 to arrange our surveyor for inspection.

Any supplementary items are subjected to further approval from our client.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewse@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

SKW6474A (MSC/V/17-000316)
OD
Feb 23 2017 6:00AM
[HITACHI CAPITAL AISIA PACIFIC PTE LTD]
Hitachi Capital Asia Pacific Pte. Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From MSIG Insurance (Singapore) Pte. Ltd. (MSIG_SG), sent on 27/02/2017 13:39 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$9909.60) - SKW6474A - Claim Handler: Kwok Woon Choo

Approved:9909.60:a if c; check items to be confirmed

DOCUMENTS SUMMARY

There are no documents.

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Kwok Woon Choo

Date: 27 Feb 2017

Preliminary Advice

Vehicle No	: SKW6474A	Accident Date	: 23/02/2017
Make	: TOYOTA VELLFIRE	Policy No.	: MSD/VPCP/16-002215-00
Assignment Date	: 24/02/2017	Excess	: S\$1,500.00
Date of Inspection	: 24/02/2017	Est. Duration of Repair	: 12.00
Inspection At	: HITACHI CAPITAL ASIA PACIFIC PTE. LTD (HQ) NO 8 FOURTH LOK YANG ROAD SINGAPORE 629705		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	16,968.40
Revised Amount	:S\$	9,909.60
Check Items (Estimated)	:S\$	436.70
Total	:S\$	10,346.30

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	153,000.00
COE / PARF Rebate	:S\$	95,723.00
Salvage Value	:S\$	
Margin for Repair	:S\$	57,277.00

Remarks

(X) The vehicle is economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis. WE HAVE NOT AUTHORISE REPAIR.

Text size + -

Enquire PARF/COE Rebate for Registered Vehicle**Vehicle Owner Particulars**

Owner ID Type: Company

Owner ID: 0399N

Vehicle Details

Vehicle No.: SKW6474A

Vehicle to be Exported: No

Intended De-registration
Date: 27 Feb 2017

Vehicle Make: TOYOTA

Vehicle Model: VELLFIRE 2.5 CVT S/R

Primary Colour: Black

Manufacturing Year: 2015

Engine No.: 2ARH640669

Chassis No.: JTNGF3DH208002862

Maximum Power Output: 134.0 kW (179 bhp)

Open Market Value: \$45,427.00

Original Registration
Date: 09 Nov 2015

First Registration Date: 09 Nov 2015

Transfer Count: 0

Actual ARF Paid: \$55,598.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry
Date: 08 Nov 2025

PARF Rebate Amount: \$41,698.00

Intended COE Rebate Details

COE Expiry Date: 08 Nov 2025

COE Category: B - Car (above 1600cc or 97kW (130bhp))

COE Period(Years): 10

QP Paid: \$62,101.00

COE Rebate Amount: \$54,025.00

Total Rebate Amount: \$95,723.00

The information contained herein is correct as at 27 Feb 2017

OK

Land Transport Authority

Please read through the Privacy Statement, Terms of Use and Disclaimer.

Please do not use the **Back** or **Forward** buttons on your browser as this may alter the results of the transactions.

Best viewed with IE 6.0 SP3 and above, 1024 X 768 resolution

Copyright © 2017 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#) | [Rate this e-Service](#)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	23/02/2017 10:20
Date Of Accident	23/02/2017 06:45
Exact Location Of Accident	PIE(TUAS) TOH TUCK/BUKIT BATOK EXIT
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKW6474A
Insured/Policyholder	
Name Of Registered Owner	HITACHI CAPITAL AISIA PACIFIC PTE LTD
Co Reg No	199400399N
Email Address	JUNTAIYO@HCSPL.COM.SG
Mobile Phone No	
Alternative Phone No	Office-84663022

Vehicle Particulars

Manufacturer	TOYOTA
Model	VELLFIRE-2.5 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? Yes

If No, Please state action to be taken

Vehicle Category	Private Car
------------------	-------------

Insurance Company

Name of Insurance Company	MSIG Insurance (Singapore) Pte. Ltd.
Type Of Coverage	Comprehensive
Fleet Policy	Yes
Policy Number	MSD/VPCP/16-002215-00
Cover Note Number	

Driver

Name of Driver	CHOW KERR CHUEN (ZHOU KEQUAN)
NRIC No	S8511081J
Date Of Birth	17/04/1985
Occupation	Outdoor
Date Of Driving Pass	01/12/2003
Driving Experience	13 Years And 2 Months
Gender	Male
Mobile Number	(Local) +65-98325234
Fax Number	
Contact Number	
Email Address	KERRCHUEN@GMAIL.COM

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

(Signature)



Policyholder's Signature / Date & Time

(Signature)

23/2/2017 0913

Driver's Signature (if driver is not the policyholder) / Date & Time

(Signature)

Witnessed by Reporting Centre Personnel

Sketch Plan



PIE (TUAS)



A: 5KW6474A
B: PA1904R

Describe Circumstances of the Accident

I was exiting PIE (Bukit Batak East Ave 3) at about 0645.
The road condition was dry and I was trying to filter to the extreme left. I could not stop / filter on time because a car from the left was exiting at a fast speed. I could not stop in time and hit the passenger bus at the rear ~~or~~ left.

Declaration

We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time



Driver's Signature (If driver is not the policyholder) / Date & Time

23/2/2017 0913



Witnessed by Reporting Centre Personnel

INSURER: **MSIG Insurance (Singapore) Pte. Ltd. (HQ)**
PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	MSD/VPCP/16-002215-00	Date of Loss:	23/02/2017
Vehicle Reg. No.:	SKW6474A	Driveable?	
Driver Age/Info:	31 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	HITACHI CAPITAL AISIA PACIFIC PTE LTD		
Driver:	CHOW KERR CHUEN (ZHOU KEQUAN)		

Make/Model:	TOYOTA VELLFIRE, 2.5 (A)	Vehicle Reg. Date:	09/11/2015
Vehicle Colour:	BLACK		
Engine No:	2ARH640669	Chassis No:	JTNGF3DH208002862
Odometer:	30000 KM		

Paint Type:	
Total Loss?	NO
Est. Duration of Repair (day)	10

Description of Accident/Loss: PLEASE REFER TO THE ATTACHED.

Present Location: HITACHI CAPITAL ASIA PACIFIC PTE. LTD (HQ)

COST OF CLAIMS	Amount
Parts	12,128.40
Miscellaneous Items	0.00
Labour	4,840.00
Paintwork Labour	0.00
Towing	0.00
Calculated Gross Total (S\$)	16,968.40
- Excess (S\$)	1,500.00
(S\$)	15,468.40
+ GST 7.00% (S\$)	1,082.79
Nett Amount (S\$)	16,551.19

 This claim is handled by: **GRANT CHONG**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 24 Feb 2017)

Parts: M1-MPV TOYOTA VELLFIRE 2.5 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Hitachi Capital Asia Pacific Pte. Ltd/SKW6474A/24/02/2017 10:15

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Front bumper	0.00	0.00	*210.00 FDE
2	10		*Front bumper clips	0.00	0.00	*15.00 FDE
3	2		*Front bumper side retainer LH/RH	0.00	0.00	*70.00 FDE
4	2		*Front tow cover	0.00	0.00	*30.00 FDE
5	2		*Headlamp LH/RH	0.00	0.00	*2,200.00 FDE
6	1		*Front bumper sponge (damage due to impact, bot RH was pushed inwards to left side)	0.00	0.00	*55.00 FDE
7	1		*Front bumper center lower grille	0.00	0.00	*80.00 FDE
8	1		*Front grille with chrome moulding	0.00	0.00	*430.00 FDE
9	1		*Front grille logo	0.00	0.00	*40.00 FDE
10	6		*Front grille clips	0.00	0.00	*9.00 FDE
11	2		*Front parking sensor original LH/RH	0.00	0.00	*270.00 FDE
12	2		*Front parking sensor original holder LH/RH	0.00	0.00	*20.00 FDE
13	1		*Front fog lamp	0.00	0.00	*90.00 FDE
14	2		*Front fog lamp cover LH-XSVC	0.00	0.00	*90.00 FDE
15	1		*Front reinforcement with bracket	0.00	0.00	*160.00 FDE
16	1		*Brace panel	0.00	0.00	*35.00 FDE
17	2		*Horn	0.00	0.00	*100.00 FDE
18	2		*Support panel LH/RH	0.00	0.00	*240.00 FDE
19	1		*Support panel lower member	0.00	0.00	*95.00 FDE
20	1		*Support panel top	0.00	0.00	*200.00 FDE
21	1		*Support panel top garnish	0.00	0.00	*120.00 FDE
22	8		*Support panel top garnish clips	0.00	0.00	*12.00 FDE
23	1		*Bonnet	0.00	0.00	*230.00 FDE
24	2		*Bonnet hinge	0.00	0.00	*50.00 FDE
25	1		*Bonnet chrome moulding	0.00	0.00	*190.00 FDE
26	1		*Bonnet lock	0.00	0.00	*60.00 FDE
27	2		*Bonnet stopper	0.00	0.00	*40.00 FDE
28	1		*Bonnet stand holder	0.00	0.00	*25.00 FDE
29	1		*Bonnet insulator	0.00	0.00	*55.00 FDE
30	8		*Bonnet insulator clips	0.00	0.00	*12.00 FDE
31	2		*Front fender LH/RH	0.00	0.00	*600.00 FDE
32	2		*Front fender shield LH/RH	0.00	0.00	*220.00 FDE
33	20		*Front fender shield clips	0.00	0.00	*30.00 FDE
34	1		*Aircon condensor	0.00	0.00	*500.00 FDE
35	1		*Air Duct	0.00	0.00	
36	1		*Radiator	0.00	0.00	*540.00 FDE
37	2		*Radiator bottom bush	0.00	0.00	*24.00 FDE
38	2		*Radiator original coolant	0.00	0.00	*42.00 FDE
39	1		*Aircon fan cowling	0.00	0.00	*95.00 FDE
40	1		*Aircon fan blade	0.00	0.00	*80.00 FDE
41	1		*Aircon fan motor	0.00	0.00	*150.00 FDE
42	1		*Radiator fan cowling top	0.00	0.00	*70.00 FDE

Hitachi Capital Asia Pacific Pte. Ltd/SKW6474A/24/02/2017 10:15. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
43	1		*Radiator fan blade	0.00	0.00	*70.00 F X
44	1		*Radiator fan motor	0.00	0.00	*300.00 F X
45	1		*Radiator top hose	0.00	0.00	*30.00 F X
46	1		*Radiator bottom hose	0.00	0.00	*30.00 F X
47	1		*Driver door	0.00	0.00	*650.00 F R
48	2		*Driver door sticker	0.00	0.00	*70.00 F X
49	1		*Wiper garnish set	0.00	0.00	*210.00 F DE
50	2		*Wiper garnish cover top LH/RH - LH - X suc	0.00	0.00	*110.00 F DE RH
51	10		*Wiper garnish clips	0.00	0.00	*15.00 F DE
52	1		*Radiator spare tank	0.00	0.00	*120.00 F X
53	1		*A pillar RH	0.00	0.00	
			Repair			
54	1		*Front windscreen with moulding	0.00	0.00	*850.00 F DE
55	1		*Windscreen sealant	0	0.00	*45.00 FS DE
56	1		*Front number plate with casing	0	0.00	*45.00 FS X suc
57	1		*Support lower garnish cover	0.00	0.00	*55.00 F X suc
58	1		*Wiper tank	0.00	0.00	*60.00 F DE
59	1		*Wiper tank motor	0.00	0.00	*200.00 F X suc
60	1		*Air resonator box	0.00	0.00	*120.00 F X suc
61	2		*Radiator side garnish LH/RH top	0.00	0.00	*80.00 F X suc
62	2		*Headlamp center cover LH/RH - LH - X suc	0.00	0.00	*130.00 F DE RH
63	1		*Front fender RH bracket	0.00	0.00	*30.00 F DE
64	1		*Front fender inner panel RH	0.00	0.00	*320.00 F suc

F=Franchise part, S=SpcNett

Sub Total (S\$) 11,034.00
+ Margin on L,N Items 10.00% (S\$) 1,094.40

Total Parts (S\$) 12,128.40

Hitachi Capital Asia Pacific Pte. Ltd/SKW6474A/24/02/2017 10:15. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	Panel beat, cut, weld, re-align & replace damaged parts of affected area	New	2,000.00 ¹³⁰⁰
2	Putty, blend and paint affected area	New ¹⁴⁰⁰	1,800.00 ¹²⁰⁰
3	Check Wiring, re-align headlamps and ensure proper function	New	80.00 ³⁰
4	Refill compressor oil, vacuum and refill aircond gas	New	180.00 ¹⁰⁰
5	Remove & reinstall bumper sensors	New	120.00 ⁶⁰
6	Conduct four wheel alignment / side slip test	New	180.00 ⁸⁰
7	Remove & re-install Front Windscreen	New	180.00 ¹²⁰
8	Transfer door lock & mechanism to new door	New	120.00 ^{60 X 2}
9	Diagnostic Check & Reset	New	180.00 ⁸⁰
Gross Labour Cost (S\$)			4,840.00

Hitachi Capital Asia Pacific Pte. Ltd/SKW6474A/24/02/2017 10:15. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

© Hitachi Capital Asia Pacific Pte. Ltd. (Main Office) Co. Reg. No. 199400399N

111 Somerset Road #11-05 Singapore 238164 Tel: (65) 6734 1222 Fax : 6734 8835

www.hitachi-capital.com.sg

Jun Taiyo Service Centre (Automobile Leasing & Workshop)

8 Fourth Lok Yang Road Singapore 629705 Tel: (65) 6466 3022 Fax: (65) 6896 6591

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Pasue

Hp 90010068

12 days

P/P

24/02/17 @ 1800

Resurvey 64 part

EMERS: 1500

REVERT


 27/2/17

HITACHI
 Inspire the Next

(SUPPLEMENTARY)

INSURER: **MSIG Insurance (Singapore) Pte. Ltd. (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	MSD/VPCP/16-002215-00	Date of Loss:	23/02/2017
Vehicle Reg. No.:	SKW6474A	Driveable?	
Driver Age/Info:	31 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	HITACHI CAPITAL AISIA PACIFIC PTE LTD		
Driver:	CHOW KERR CHUEN (ZHOU KEQUAN)		

Make/Model:	TOYOTA VELLFIRE, 2.5 (A)	Vehicle Reg. Date:	09/11/2015
Vehicle Colour:	BLACK		
Engine No:	2ARH640669	Chassis No:	JTNGF3DH208002862
Odometer:	90052 KM		

Paint Type:

Total Loss? **NO**

Est. Duration of Repair (day) 10

Description of Accident/Loss: PLEASE REFER TO THE ATTACHED.

Present Location: HITACHI CAPITAL ASIA PACIFIC PTE. LTD (HQ)

COST OF CLAIMS	Amount
Parts	6,371.75
Miscellaneous Items	0.00
Labour	0.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	6,371.75
+ GST 7.00% (S\$)	446.02
Nett Amount (S\$)	6,817.77
+ Previous Estimates (S\$)	16,551.19
Claim Total (S\$)	23,368.96

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 20 Jul 2017)
 Parts: M1-MPV TOYOTA VELLFIRE 2.5 (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Hitachi Capital Asia Pacific Pte. Ltd/SKW6474A/20/07/2017 16:34
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	10		*Front cowling clips	0.00	0.00	*15.00 F	acc/
2	1		*Front fender protector RH	0.00	0.00	*65.00 F	bro/
3	1		*Front fender quarter glass RH	0.00	0.00	*95.00 F	bro/
4	1		*Front windscreen moulding RH	0.00	0.00	*60.00 F	acc/
5	1		*Aircon liquid pipe	0.00	0.00	*280.00 F	BT/
6	1		*Front fog lamp RH	0.00	0.00	*120.00 F	CR/
7	1		*Headlamp ballast RH	0.00	0.00	*280.00 F	AW/
8	1		*Fuse box top cover RH	0.00	0.00	*35.00 F	car/
9	1		*Wiper washer inlet neck	0.00	0.00	*25.00 F	DE/
10	1		*Wiper garnish shield RH	0.00	0.00	*30.00 F	DE/
11	1		*Wire harness	0.00	0.00	*3,800.00 F	cut/
12	1		*Wiper panel lower sponge	0.00	0.00	*150.00 F	cut/
13	1		*Aircon discharge pipe	0.00	0.00	*180.00 F	BT/
14	1		*Wiper linkage	0.00	0.00	*200.00 F	BT/
15	1		*Wiper panel	0.00	0.00	*400.00 F	DE/
16	1		*Wiper tank motor rear hose	0.00	0.00	*10.00 F	cut/
17	1		*Wiper tank motor front hose	0.00	0.00	*10.00 F	cut/
18	2		*Wiper panel lower sponge clip	0.00	0.00	*6.00 F	acc/
19	3		*Wiper hose joint	0.00	0.00	*18.00 F	cut/
20	9		*Support top garnish clips	0.00	0.00	*13.50 F	acc/

F=Franchise part.

Sub Total (S\$)	5,792.50
+ Margin on L,N Items 10.00% (S\$)	579.25
Total Parts (S\$)	6,371.75

Hitachi Capital Asia Pacific Pte. Ltd/SKW6474A/20/07/2017 16:34. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 24 Feb 2017)
 Parts: M1-MPV TOYOTA VELLFIRE 2.5 (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Hitachi Capital Asia Pacific Pte. Ltd/SKW6474A/24/02/2017 10:15
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Front bumper	0.00	0.00	*210.00 F PE ✓
2	10		*Front bumper clips	0.00	0.00	*15.00 F RA ✓
3	21		*Front bumper side retainer LH/RH	0.00	0.00	*35.70 F RA ✓
4	2		*Front tow cover	0.00	0.00	*30.00 F X ✓
5	2		*Headlamp LH/RH	0.00	0.00	*2,200.00 F RA ✓
6	1		*Front bumper sponge	0.00	0.00	*55.00 F X ✓
7	1		*Front bumper center lower grille	0.00	0.00	*80.00 F X ✓
8	1		*Front grille with chrome moulding	0.00	0.00	*430.00 F RA ✓
9	1		*Front grille logo	0.00	0.00	*40.00 F RA ✓
10	6		*Front grille clips	0.00	0.00	*9.00 F RA ✓
11	21pc		*Front parking sensor original LH/RH	0.00	0.00	*135.270.00 F RA ✓
12	21pc		*Front parking sensor original holder LH/RH	0.00	0.00	*10.20.00 F RA ✓
13	1		*Front fog lamp RH	0.00	0.00	*110.00 F RA ✓
14	21pc		*Front fog lamp cover LH-X RH only ✓	0.00	0.00	*45.80.00 F RA ✓
15	1		*Front reinforcement with bracket	0.00	0.00	*180.00 F X ✓
16	1		*Brace panel	0.00	0.00	*35.00 F X ✓
17	2		*Horn	0.00	0.00	*100.00 F X ✓
18	21pc		*Support panel LH/RH	0.00	0.00	*120.240.00 F RA ✓
19	1		*Support panel lower member	0.00	0.00	*85.00 F X ✓
20	1		*Support panel top	0.00	0.00	*190.280.00 F RA ✓
21	1		*Support panel top garnish	0.00	0.00	*105.120.00 F RA ✓
22	8		*Support panel top garnish clips	0.00	0.00	*12.00 F X ✓
23	1		*Bonnet	0.00	0.00	*230.00 F RA ✓
24	2		*Bonnet hinge	0.00	0.00	*50.00 F RA ✓
25	1		*Bonnet chrome moulding	0.00	0.00	*180.00 F RA ✓
26	1		*Bonnet lock	0.00	0.00	*80.00 F RA ✓
27	2		*Bonnet stopper 10x2	0.00	0.00	*20.40.00 F RA ✓
28	1		*Bonnet stand holder	0.00	0.00	*25.00 F X ✓
29	1		*Bonnet insulator	0.00	0.00	*55.00 F RA ✓
30	8		*Bonnet insulator clips	0.00	0.00	*12.00 F RA ✓
31	21		*Front fender LH/RH / LH-Repair	0.00	0.00	*300.600.00 F RA ✓
32	21		*Front fender shield LH/RH	0.00	0.00	*110.220.00 F RA ✓
33	20		*Front fender shield clips	0.00	0.00	*30.00 F RA ✓
34	1		*Aircon condensor	0.00	0.00	*500.00 F X ✓
35	1		*Air Duct	0.00	0.00	
36	1		*Radiator	0.00	0.00	*540.00 F X ✓
37	2		*Radiator bottom bush	0.00	0.00	*24.00 F X ✓
38	2		*Radiator original coolant	0.00	0.00	*42.00 F X ✓
39	1		*Aircon fan cowling	0.00	0.00	*95.00 F X ✓
40	1		*Aircon fan blade	0.00	0.00	*80.00 F X ✓
41	1		*Aircon fan motor	0.00	0.00	*150.00 F X ✓
42	1		*Radiator fan cowling top	0.00	0.00	*70.00 F X ✓

Hitachi Capital Asia Pacific Pte. Ltd/SKW6474A/24/02/2017 10:15. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
43	1		*Radiator fan blade	0.00	0.00	*70.00 F X
44	1		*Radiator fan motor	0.00	0.00	*300.00 F X
45	1		*Radiator top hose	0.00	0.00	*30.00 F X
46	1		*Radiator bottom hose	0.00	0.00	*30.00 F X
47	1		*Driver door	0.00	0.00	*850.00 F RX
48	2		*Driver door sticker	0.00	0.00	*70.00 F X
49	1		*Wiper garnish set	0.00	0.00	*210.00 F DEL
50	1		*Wiper garnish cover top LH/RH - LH-X	0.00	0.00	*110.00 F DEL
51	10		*Wiper garnish clips	0.00	0.00	*15.00 F DEL
52	1		*Radiator spare tank	0.00	0.00	*120.00 F X
53	1		*A pillar RH	0.00	0.00	
			Repair			
54	1		*Front windscreen with moulding	0.00	0.00	*850.00 F DEL
55	1		*Windscreen sealant	0	0.00	*45.00 FS DEL
56	1		*Front number plate with casing	0	0.00	*45.00 FS X
57	1		*Support lower garnish cover	0.00	0.00	*55.00 F X
58	1		*Wiper tank	0.00	0.00	*60.00 F DEL
59	1		*Wiper tank motor	0.00	0.00	*200.00 F X
60	1		*Air resonator box	0.00	0.00	*120.00 F X
61	2		*Radiator side garnish LH/RH top	0.00	0.00	*80.00 F X
62	2		*Headlamp center cover LH/RH - LH-X RH	0.00	0.00	*130.00 F DEL
63	1		*Front fender RH bracket	0.00	0.00	*30.00 F DEL
64	1		*Front fender inner panel RH	0.00	0.00	*320.00 F DEL

F=Franchise part. S=Spec/Vel.

Sub Total (S\$) 11,034.00
+ Margin on L,N Items 10.00% (S\$) 1,094.40

Total Parts (S\$) 12,128.40

Hitachi Capital Asia Pacific Pte. Ltd/SKW6474A/24/02/2017 10:15. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Supplementary Item \$ 5792.50 + 10% = \$ 6371.75

parts \$ 6476 + 10% = \$ 7123.60

Stnelt \$ 45

labour \$ 3170

Total P/P \$ 16710.35 @ 12 days

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	Panel beat, cut, weld, re-align & replace damaged parts of affected area	New	2,000.00 1300 ✓
2	Putty, blend and paint affected area	New 1400	1,800.00 1200 ✓
3	Check Wiring, re-align headlamps and ensure proper function	New	80.00 30 ✓
4	Refill compressor oil, vacuum and refill aircond gas	New	180.00 100 ✓
5	Remove & reinstall bumper sensors	New	120.00 60 ✓
6	Conduct four wheel alignment / side slip test	New	180.00 80 ✓
7	Remove & re-install Front Windscreen	New	180.00 120 ✓
8	Transfer door lock & mechanism to new door	New	120.00 60 X
9	Diagnostic Check & Reset	New	180.00 80 ✓
Gross Labour Cost (S\$)			4,840.00

Hitachi Capital Asia Pacific Pte. Ltd/SKW6474A/24/02/2017 10:15. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

© Hitachi Capital Asia Pacific Pte. Ltd. (Main Office) Co. Reg. No. 199400399N

111 Somerset Road #11-05 Singapore 238184 Tel: (65) 6734 1222 Fax: 6734 8835
www.hitachi-capital.com.sg

Jun Taiyo Service Centre (Automobile Leasing & Workshop)
8 Fourth Lok Yang Road Singapore 629705 Tel: (65) 6486 3022 Fax: (65) 6896 6591

Issue
Hp 90010068
12 days
P/P
24/02/17 @ 1800
Resins & paint
EXCESS: 1500
RESET



合興汽車零件私人有限公司

HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403

TEL: 6291 2827 FAX: 6296 4390

A/C: 6291 1886 FAX: 6291 7717

Co. Reg. No: 200310923R GST Reg. No: 20-0310923-R

TAX INVOICE

V/S: HITACHI CAPITAL ASIA PACIFIC PTE LTD

8 FOURTH LOK YANG ROAD

SINGAPORE 629705

VELL FIRE

GRANI

NO: DLI9185955

PAGE: 1

DATE: 27/02/2017

A/C CODE: LDHC008

TERMS: CR

VEH NO: SKW6474A

Part No	Description	Location	Qty	Unit Price	Amount
				SIN	SIN
1 T52119-58947	FR BUMPER (R.N)	DB2G	1	210.00	210.00
2 T52161-0K040	CLIP BUMPER	DU1AD10-10	10	1.50	15.00
3 T52115-58070	FR BUMPER REINFORCER RH	DU1AD30-5	1	35.00	35.00
4 T81145-58430	HEADLAMP (R.N)	DB1A	1	1,100.00	1,100.00
5 T53401-58290	FR GRILLE	DB1LL	1	430.00	430.00
6 T75301-58300	FR LOGO	DB1A51-60	1	40.00	40.00
7 T52161-0K040	CLIP GRILLE	DU1AD10-10	6	1.50	9.00
8 T89341-58080-CO	SENSOR PRT RH	DB1A3-2	1	135.00	135.00
9 T89348-12020	SENSOR HOOD PRT RH	DB1A3	1	40.00	40.00
10 T81210-48050	FOG LAMP ASSY RH	DB1A3	1	110.00	110.00
11 T52030-58130	FOG LAMP LAMP RH	DB1A3	1	45.00	45.00
12 T58202-58050	SUPPORT PATTEN RH	DB1A3	1	120.00	120.00
T53301-58060	BONNET	DB2G	1	230.00	230.00
14 T53410-58060	HOOD HINGE RH	DU1AD19-4	1	25.00	25.00
15 T53420-58080	BONNET HINGE LH	DU1AD21-4	1	25.00	25.00
16 T75770-58080	HOOD MOULDING CHROME	DU1U13	1	190.00	190.00
17 T53510-58090	BONNET LOCK	DU1B33	1	60.00	60.00
18 T90541-15024	BONNET STOPPER	DD1A42-5	2	10.00	20.00
19 T53341-58060	HOOD INSULATOR	DB2DD5	1	55.00	55.00
20 T90467-09050	CLIP INSULATOR	DD1A53-6	8	1.50	12.00
21 T53801-58070	FENDER IR RH	DB1B39	1	300.00	300.00
22 T53805-58070	FENDER IR LH	DB1B39	1	110.00	110.00

Print / LSK / 27/02/2017 0:58

Inspector	General Manager Approval	Depl Manager Approval	Applica
Nuraida 24 MAR 2017 HCAP		H.C. Poon 24 MAR 2017 HCAP	K.Y. Chong 24 MAR 2017 HCAP



合興汽車零件私人有限公司 HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403

TEL: 8291 2827 FAX: 8296 4390

A/C: 8291 1886 FAX: 8291 7717

Co. Reg. No: 200310923R GST Reg. No: 20-0310923-R

TAX INVOICE

M/S: HITACHI CAPITAL ASIA PACIFIC PTE.LTD

NO: DLI9185935

PAGE: 2

Part No	Description	Location	Qty	Unit Price	Amount	
				SIN	SIN	
23	T90467-07214	CLIP COWLING	DD8	20	1.50	30.00
24	T55708-58090	WIPER COWLING	DUIF7-2V	1	210.00	210.00
25	T90467-07216	CLIP WIPER COWLING	DD1A168	10	1.50	15.00
26	T85315-58030	WINDSHIELD WASHER JAR	DUIAB16-2	1	60.00	60.00
(	T33181-58060-A0	HEADLAMP GARNISH RH	DUIAB24-1	1	65.00	65.00
--	T53835-58050	FENDER BRACE FR RH	DUIAS3-79	1	30.00	30.00
29	T53701-58070	FRT WHEEL HYLSE RH	DB2	1	320.00	320.00
TOTAL QUANTITY			79	TOTAL	SIN 4,016.00	
				ADD GST @ 7%	281.12	
				GRAND TOTAL	SIN 4,297.12	

O/R: 91748

YIP TO ON 829100252 24 MAR 2001 9/5/17
-# 224.70

Inspector	General Manager Approval	Dept Manager Approval	Applicant
 Nuraida 24 MAR 2001 HCAP		 H.C. on 24 MAR 2001 HCAP	 K.Y. Chong 24 MAR 2001 HCAP

Print / LSK / 237/20170-6214-4-11

SALESMAN: LSK

This document is computer generated. No signature required.

GOODS SOLD ARE NOT RETURNABLE

GOODS RECEIVED BY

L. SPONGES

E. & O. F.
COPY 1000
P. 117

S. S. S. S.



合興汽車零件私人有限公司

HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403

TEL: 6291 2827 FAX: 6296 4390

A/C: 6291 1886 FAX: 6291 7717

Co. Reg. No: 200310923R GST Reg. No: 20-0310923-R

TAX INVOICE

M/S: HITACHI CAPITAL ASIA PACIFIC PTE.LTD

8 FOURTH LOK YANG ROAD

SINGAPORE 629705

VILLFIRE

GRANT

NO: DLJ9185961

PAGE: 1

DATE: 27/02/2017

A/C CODE: LDHC008

TERMS: CR

VEH NO: SKW6474A

Part No	Description	Location	Qty	Unit Price	Amount
1	T55783-58030	WIPER GRILLE FOR RH	1	SIN 55.00	SIN 55.00
TOTAL QUANTITY:			1	TOTAL	SIN 55.00
				ADD GST @ 7%	3.85
				GRAND TOTAL	SIN 58.85

O/R: 91748

Inspector	General Manager Approval	Dept Manager Approval	Applic
Nuralida 24 MAR 2017 HCAP		H.C. Poon 24 MAR 2017 HCAP	K.Y. Chong 24 MAR 2017 HCAP

Printed LSK / 27/2/2017 10:24:13 AM

SALESMAN: LSK

This document is computer generated. No signature required.

GOODS SOLD ARE NOT RETURNABLE

GOODS RECEIVED BY ()

E & O E



合興汽車零件私人有限公司 HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403

TEL: 6291 2827 FAX: 6296 4390

A/C: 6291 1886 FAX: 6291 7717

Co. Reg. No: 200310923R GST Reg. No: 20-0310923-R

M/S: HITACHI CAPITAL ASIA PACIFIC PTE.LTD

8 FOURTH LOK YANG ROAD

SINGAPORE 629705

VELLFIRE

GRANT

TAX INVOICE

NO: DL19186039

PAGE: 1

DATE: 28/02/2017

A/C CODE: LDHC008

TERMS: CR

VEH NO: SKW6474A

Part No	Description	Location	Qty	Unit Price	Amount
				SIN	SIN
✓ T81185-58430	HEADLAMP UNIT RH	DDS	1	1,100.00	1,100.00
✓ T52611-58040	FR ABSORBER	DBIE49	1	55.00	55.00
✓ T53112-58150	LWR GRILLE	DU2H1	1	80.00	80.00
TOTAL QUANTITY			3	TOTAL	SIN 1,235.00
				ADD GST @ 7%	86.45
				GRAND TOTAL	SIN 1,321.45

O/R: 91748

Inspector	General Manager Approval	Dept Manager Approval	Applic

Print / LSK / 28/2/2017 5:00:54 PM

SALESMAN: LSK

This document is computer generated. No signature required.

GOODS SOLD ARE NOT RETURNABLE

GOODS RECEIVED BY

E & O E



合興汽車零件私人有限公司

HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403
TOYOTA / LEXUS / MITSUBISHI / FORD / WINDSCREEN / CHEVROLET /
DAIHATSU / KIA / SUZUKI / HONDA
TEL: 6291 2827 FAX: 6296 4380
A/C: 6291 1888 FAX: 6291 7717

Co. Reg. No: 200310923R GST Reg. No: 20-0310923-R

TAX INVOICE

M/S: HITACHI CAPITAL ASIA PACIFIC PTE.LTD

8 FOURTH LOK YANG ROAD

SINGAPORE 629705

VELLFIRE

GRANT

NO: DLI9186133

PAGE: 1

DATE: 02/03/2017

A/C CODE: LDHC008

TERMS: CR

VEH NO: SKW6474A

Part No	Description	Location	Qty	Unit Price	Amount
				SIN	SIN
① T85211-58020	FRT WIPER ARM RH	DDS	1	80.00	80.00
2 T53440-58050	BONNET STAND	DDS	1	25.00	25.00
TOTAL QUANTITY:			2	TOTAL	SIN 105.00
				ADD GST @ 7%	7.35
				GRAND TOTAL	SIN 112.35

62-91748

* refer to CN- DEN9010267 dated 16/3/17
- \$185.60


Rock

Inspector	General Manager Approval	Dept Manager Approval	Applic
Nuraida 24 MAR 2017 HCAP		H.C. Poon 24 MAR 2017 HCAP	K.Y. Chong 24 MAR 2017 HCAP

Print / LSK / 2/3/2017 3:15:25 PM

SALESMAN: LSK

This document is computer generated. No signature required.



GOODS SOLD ARE NOT RETURNABLE

[Handwritten signature]



合興汽車零件私人有限公司

HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403

TEL: 6291 2827 FAX: 6296 4390

A/C: 6291 1886 FAX: 6291 7717

Co. Reg. No: 200310923R GST Reg. No: 20-0310923-R

M/S: HITACHI CAPITAL ASIA PACIFIC PTE.LTD

8 FOURTH LOK YANG ROAD

SINGAPORE 629705

VELLFIRE

GRANT

TAX INVOICE

NO: DLI9186130

PAGE: 1

DATE: 02/03/2017

A/C CODE: LDHC008

TERMS: CR

VEH NO: SKW6474A

Part No	Description	Location	Qty	Unit Price	Amount
				SIN	SIN
Our D/O No: DDO9019369					
1 T90467-07214	CLIP COWLING	DDS	10	1.50	15.00
2 T76901-58040-A0	FR RH FENDER PROTECTOR	DU1AB46-2	1	65.00	65.00
3 T62110-58040	QTR GLASS FR RH	DD2L10	1	95.00	95.00
4 T75551-58030	FRT W/S MOULDING RH	DU1AET	1	60.00	60.00
5 T88710-58180	AIRCON LIQUID PIPE	DD1F20	1	280.00	280.00
6 T81220-48050	FOGLAMP ASSY LH	DBAA9	1	120.00	120.00
7 T53205-58070	CENTRE SUPPORT PANEL UPP	DBIH42	1	190.00	190.00
8 T81107-58340	BALLAST RH	DD2K2-1	1	280.00	280.00
9 T82662-58230	FUSE BOX RH TOP CVR	DU1A142	1	35.00	35.00
10 T85319-58030	WASHER INLET NECK	DU1AB12-1	1	25.00	25.00
11 T53806-58090	FENDER LINER FR LH	DDS	1	100.00	100.00
TOTAL QUANTITY:			20	TOTAL	SIN 1,265.00
				ADD GST @ 7%	88.55
				GRAND TOTAL	SIN 1,353.55

O/R: 91748

Inspector	General Manager Approval	Dept Manager Approval	Applic
Nuraida 24 MAR 2017 HCAP		H.C. Oon 24 MAR 2017 HCAP	K.Y. Cheng 24 MAR 2017 HCAP

Print / LSK / 20170302 3:02 PM

SALESMAN: LSK

-This document is computer generated. No signature required.



GOODS SOLD ARE NOT RETURNABLE

GOODS RECEIVED BY

E. & O. E.





合興汽車零件私人有限公司 HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403

TEL: 6291 2827 FAX: 6296 4390

A/C: 6291 1886 FAX: 6291 7717

Co. Reg. No: 200310923R GST Reg. No: 20-0310923-R

TAX INVOICE

M/S: HITACHI CAPITAL ASIA PACIFIC PTE.LTD

8 FOURTH LOK YANG ROAD

SINGAPORE 629705

VELLFIRE

GRANT

NO: DLI9186156

PAGE: 1

DATE: 03/03/2017

A/C CODE: LDHC008

TERMS: CR

2699

VEH NO: SKW6474A

Part No	Description	Location	Qty	Unit Price	Amount
1	T55753-58010	WIPER GARNISH SHIELD RH	1	30.00	30.00
TOTAL QUANTITY:			1	TOTAL	SIN 30.00
				ADD GST @ 7%	2.10
				GRAND TOTAL	<u>SIN 32.10</u>

O/R: 91748

Inspector	General Manager Approval	Dept Manager Approval	Applic

Print / LSK / 3/3/2017 10:22:15 AM

SALESMAN: LSK

This document is computer generated. No signature required.

GOODS SOLD ARE NOT RETURNABLE

Ter2

GOODS RECEIVED BY

E. & O. E.
CHEVROLET
PARTS





合興汽車零件私人有限公司

HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403
TOYOTA / LEXUS / MITSUBISHI / FORD / WINDSCREEN / CHEVROLET /
DAIHATSU / KIA / SUZUKI / HONDA
TEL: 8291 2627 FAX: 8296 4390
A/C: 8291 1856 FAX: 8291 7717

Co. Reg. No: 200310923R GST Reg. No: 20-0310923-R

TAX INVOICE

M/S: HITACHI CAPITAL ASIA PACIFIC PTE.LTD

8 FOURTH LOK YANG ROAD

SINGAPORE 629705

VELLFIRE

GRANT

NO: DLD19186378

PAGE: 1

DATE: 08/03/2017


A/C CODE: LDHC008

TERMS: CR

VEH NO: SKW6474A

Part No	Description	Location	Qty	Unit Price	Amount
1 T52119-58948	FR BUMPER (V,X)	DB2G	1	210.00	210.00
TOTAL QUANTITY:			1	TOTAL	SIN 210.00
				ADD GST @ 7%	14.70
				GRAND TOTAL	<u>SIN 224.70</u>

O/R: 91748



Inspector	General Manager Approval	Dept Manager Approval	Applic
Nuralda 24 MAR 2017 HCAP		H.C. Poon 21 MAR 2017 HCAP	K.Y. Chong 24 MAR 2017 HCAP

Reprint: LSK / 9/3/2017 11:39:46 AM

SALESMAN: LSK

This document is computer generated. No signature required.

GOODS SOLD ARE NOT RETURNABLE



合興汽車零件私人有限公司

HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 208403
TOYOTA / LEXUS / MITSUBISHI / FORD / WINDSCREEN / CHEVROLET /
DAIHATSU / KIA / SUZUKI / HONDA
TEL: 6291 2827 FAX: 6296 4390
A/C: 6291 1886 FAX: 6291 7717

Co. Reg. No: 200310923R GST Reg. No: 20-0310923-R

TAX INVOICE

M/S: HITACHI CAPITAL ASIA PACIFIC PTE.LTD

8 FOURTH LOK YANG ROAD

SINGAPORE 629705
SKW6474A VELLFIRE
GRANT

NO: DLD187355
PAGE: 1
DATE: 05/04/2017
A/C CODE: LDHC008
TERMS: CR

Part No	Description	Location	Qty	Unit Price	Amount
				SIN	SIN
Our D/O No: DDO9019568					
1 T82111-58591	HARDNESS WIRE	DDS	1	3,800.00	3,800.00
2 T55224-58030	WIPER PANEL LOWER SPONGE	DDS	1	150.00	150.00
3 T82741-58030	FUSE BOX CENTER	DDS	1	90.00	90.00
4 T82662-58030	FUSE BOX LOWER	DDS	1	60.00	60.00
5 T88711-58130	DISCHARGE PIPE	DDS	1	180.00	180.00
6 T85150-58030	WIPER LINKAGE	DDS	1	200.00	200.00
7 T55701-58113	WIPER PANEL	DDS	1	400.00	400.00
8 T90099-62129	WASHER TANK MOTOR REAR HOSE	DDS	1	10.00	10.00
9 T90099-33080	WASHER TANK MOTOR FRONT HOSE	DDS	1	10.00	10.00
10 T90467-06197	WIPER PANEL LOWER SPONGE CLIP	DDS	2	3.00	6.00

TOTAL QUANTITY: 11 TOTAL SIN 4,906.00
ADD GST @ 7% 343.42
GRAND TOTAL: SIN 5,249.42

Refer to credit note Dcn9010341
dated 22/4/17 - \$160.50

O/R: 01748
MR TECK

General
Manager
Approval

Dept
Manager
Approval


Applied

06 APR 2017

Print / LSK / 5/4/2017 10:12 PM
SALESMAN: LSK

This document is computer generated. No signature required.

GOODS SOLD ARE NOT RETURNABLE





合興汽車零件私人有限公司

HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 78 DUNLOP STREET, SINGAPORE 209403
TOYOTA / LEXUS / MITSUBISHI / FORD / WINDSCREEN / CHEVROLET /
DAIHATSU / KIA / SUZUKI / HONDA
TEL: 6291 2827 FAX: 6296 4390
A/C: 6291 1666 FAX: 6291 7717

Co. Reg. No: 220310923R GST Reg. No: 20-0310923-R

TAX INVOICE

M/S: HITACHI CAPITAL ASIA PACIFIC PTE.LTD

8 FOURTH LOK YANG ROAD

SINGAPORE 629705

VELLFIRE

GRANT

NO: DLI9187488

PAGE: 1

DATE: 10/04/2017

A/C CODE: LDHC008

TERMS: CR

VEH NO: SKW6474A

Part No	Description	Location	Qty	Unit Price	Amount
1 T85349-89122	WIPER HOSE JOINT	EDS	3	SIN 6.00	SIN 18.00
TOTAL QUANTITY			3	TOTAL	SIN 18.00
				ADD GST @ 7%	1.26
				GRAND TOTAL	SIN 19.26

O/R: 11748
MR TECK

Inspector	General Manager Approval	Dept. Manager Approval	Applic

HITACHI CAPITAL ASIA PACIFIC PTE LTD
10 APR 2017

Print / LSK / 10/4/2017 12:34:22 PM

SALESMAN: LSK

This document is computer generated. No signature required.

GOODS SOLD ARE NOT RETURNABLE

Handwritten signature





合興汽車玻璃私人有限公司

HE XING AUTO GLASS PTE LTD

MAIN OFFICE: No. 78 DUNLOP STREET, SINGAPORE 209403
CAR WINDSCREEN DIV. No 26 CUFF RD. S 209738
TEL : 6298 3113 FAX : 6298 3002
A/C : 6291 1886 FAX : 6291 7717
Co. Reg. No: 200310036C GST Reg. No: 20-0310938-C

TAX INVOICE

M/S : HITACHI CAPITAL ASIA PACIFIC PTE.LTD

8 FOURTH LOK YANG ROAD

SINGAPORE 629705

TOYOTA VELLFIRE (SKW 6474A)

AM TECK

NO: GLI8123518
DATE: 10/04/2017
A/C CODE: LDHC008
TERMS: CR
P/O NO: SKW 6474A

Part No	Description	Location	Qty	Unit Price	Amount
WT56101-58480	W/S GLASS		1	SIN 850.00	SIN 850.00
TOTAL QUANTITY				TOTAL	SIN 850.00
				ADD GST @ 7%	59.50
				GRAND TOTAL	SIN 909.50

汽车挡风镜

OR 91748

Inspector	Material Approval	Dep. Manager Approval	Admin

Print / SENG / 10/04/2017 2:21:57 PM

SALESMAN: SENG

This document is computer generated. No signature required.


GOODS SOLD ARE NOT RETURNABLE.

Back Glass

Door Glass

E. & O. E.

GOODS RECEIVED BY: Glass



合興汽車零件私人有限公司

HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403

TEL: 6291 2827 FAX: 6296 4390

A/C: 6291 1886 FAX: 6291 7717

Co. Reg. No: 200310923R GST Reg. No: 20-0310923-R

91

M/S: HITACHI CAPITAL ASIA PACIFIC PTE LTD

8 FOURTH LOK YANG ROAD

SINGAPORE 629705

VEILFIRE

GRANT

TAX INVOICE

NO: DLI9187705

PAGE 1

DATE 17/04/2017

A/C CODE LDHC008

TERMS CR

VEH NO SKW6474A

Part No	Description	Location	Qty	Unit Price	Amount
1	753106-5809U	SUPPORT TOP COVER	1	105.00	105.00
2	190467-07217	CLIP TOP GARNISH	6	1.50	9.00
TOTAL					SIN 114.00
ADD GST @ 7%					8.00
GRAND TOTAL					SIN 122.00

O/R: 91749
MR TECK

Inspector	General Manager	Deputy Manager	Applicator

Print / LSK 7/17/4/2017 4:18:33 PM

SALESMAN LSK

This document is computer generated. No signature required.

GOODS SOLD ARE NOT RETURNABLE



...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	24 Feb 2017 Sendback Est	24 Feb 2017 10:15 \$16,968.40	24 Feb 2017 15:02 Edit Adj Rpt	\$16,710.35 Edit Estimates	\$16,710.35 View Rpt		Pending for Survey Report Cancel Case
Supp #1	20 Jul 2017 10:45	20 Jul 2017 16:34 \$6,371.75	20 Jul 2017 16:34			(Combined)	Combined with Main Uncombine Suppl.

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:	HITACHI CAPITAL AISA PACIFIC PTE LTD, Co. Reg. No.: 199400399N		
Vehicle Reg. No.:	SKW6474A	Date of Loss:	23/02/2017 06:00 - :59 [15 Months and 14 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / MSC/V/17-000316	Policy/Cover Note No.:	MSD/VPCP/16-002215-00 (Comprehensive) Coverage: 14/10/2016 - 13/10/2017
		Excess:	\$1,500.00
Repairer:	Hitachi Capital Asia Pacific Pte. Ltd (HQ) No 8 Fourth Lok Yang Road, 629705 Pioneer - Tel: 64663022		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Kwok Woon Choo - 6643 1330]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 26/03/2017]		
Driver/Custodian:	CHOW KERR CHUEN (ZHOU KEQUAN) (31 / Male), NRIC: S85110813, Tel: +6598325234		
Adj Asg. Remarks:	TO REVERT		

ASSOCIATED MAIL RECEIVED
[View All](#)
[Compose Case Mail](#)

- MSIG_SG (25/05/2018): Alert - Adj Mandate Approved (\$16710.35) - SKW6474A - Claim Handler: Kwok Woon ...
- MSIG_SG (27/02/2017): Alert - Adj Mandate Approved (\$9909.60) - SKW6474A - Claim Handler: Kwok Woon C...

ALL ASSOCIATED TASKS
[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SKW6474A (MSC/V/17-000316)
OD
Feb 23 2017 6:00AM
[HITACHI CAPITAL AISA PACIFIC PTE LTD]
Hitachi Capital Asia Pacific Pte. Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View View in Browser

Assessment Reports				1 per page	☒
No	Finalized On	Hitachi Capital Asia Pacific Pte. Ltd (HQ)		Thumbnail	Print
1	23/02/17 18:36	Accident Statement		Load HTM	
2	24/02/17 10:15	Repairer Estimates		Load HTM	
3	20/07/17 16:34	Repairer Estimates Suppl. #1		Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	27/02/17 10:49	Adjuster Immediate Advice		Load HTM	
2	24/05/18 13:41	Adjuster Immediate Advice		Load HTM	

Photos/Images				3 per page	☒
No	Finalized On	Hitachi Capital Asia Pacific Pte. Ltd (HQ)		Thumbnail	Print
1	23/02/17 18:33	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
2	23/02/17 18:33	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
3	23/02/17 18:33	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
4	23/02/17 18:33	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
5	23/02/17 18:33	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
6	23/02/17 18:33	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
7	23/02/17 18:33	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
8	23/02/17 18:33	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
9	23/02/17 18:33	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
10	23/02/17 18:33	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
11	23/02/17 18:33	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
12	23/02/17 18:33	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
13	23/02/17 18:33	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
14	23/02/17 18:33	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	27/02/17 10:52	General View		Load JPG	☒
2	27/02/17 10:52	General View		Load JPG	☒
3	27/02/17 10:52	General View		Load JPG	☒
4	27/02/17 10:52	General View		Load JPG	☒
5	27/02/17 10:52	General View		Load JPG	☒
6	27/02/17 10:52	General View		Load JPG	☒
7	27/02/17 10:52	General View		Load JPG	☒
8	27/02/17 10:52	General View		Load JPG	☒
9	27/02/17 10:52	General View		Load JPG	☒
10	27/02/17 10:52	General View		Load JPG	☒
11	27/02/17 10:52	General View		Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Hitachi Capital Asia Pacific Pte. Ltd (HQ)	Thumbnail	Print
12	27/02/17 10:52	General View	 Load JPG	☒
13	27/02/17 10:52	General View	 Load JPG	☒
14	27/02/17 10:52	General View	 Load JPG	☒
15	27/02/17 10:52	General View	 Load JPG	☒
16	27/02/17 10:52	General View	 Load JPG	☒
17	27/02/17 10:52	General View	 Load JPG	☒
18	27/02/17 10:52	General View	 Load JPG	☒
19	27/02/17 10:52	General View	 Load JPG	☒
20	27/02/17 10:52	General View	 Load JPG	☒
21	27/02/17 10:52	General View	 Load JPG	☒
22	27/02/17 10:52	General View	 Load JPG	☒
23	27/02/17 10:52	General View	 Load JPG	☒
24	27/02/17 10:52	General View	 Load JPG	☒
25	27/02/17 10:52	General View	 Load JPG	☒
26	27/02/17 10:52	General View	 Load JPG	☒
27	27/02/17 10:52	General View	 Load JPG	☒
28	27/02/17 10:52	General View	 Load JPG	☒
29	27/02/17 10:52	General View	 Load JPG	☒
30	27/02/17 10:52	General View	 Load JPG	☒
31	27/02/17 10:52	General View	 Load JPG	☒
32	27/02/17 10:52	General View	 Load JPG	☒
33	27/02/17 10:52	General View	 Load JPG	☒
34	27/02/17 10:52	General View	 Load JPG	☒
35	27/02/17 10:52	General View	 Load JPG	☒
36	27/02/17 10:52	General View	 Load JPG	☒
37	27/02/17 10:52	General View	 Load JPG	☒
38	27/02/17 10:52	General View	 Load JPG	☒
39	27/02/17 10:52	General View	 Load JPG	☒
40	27/02/17 10:52	General View	 Load JPG	☒
41	27/02/17 10:52	General View	 Load JPG	☒
42	27/02/17 10:52	General View	 Load JPG	☒
43	27/02/17 10:52	General View	 Load JPG	☒
44	27/02/17 10:52	General View	 Load JPG	☒
45	27/02/17 10:52	General View	 Load JPG	☒
46	27/02/17 10:52	General View	 Load JPG	☒
47	27/02/17 10:52	General View	 Load JPG	☒
48	27/02/17 10:52	General View	 Load JPG	☒
49	27/02/17 10:52	General View	 Load JPG	☒
50	27/02/17 10:52	General View	 Load JPG	☒
51	27/02/17 10:52	General View	 Load JPG	☒
52	27/02/17 10:52	General View	 Load JPG	☒
53	27/02/17 10:52	General View	 Load JPG	☒
54	27/02/17 10:52	General View	 Load JPG	☒
55	27/02/17 10:52	General View	 Load JPG	☒
56	27/02/17 10:52	General View	 Load JPG	☒
57	27/02/17 10:52	General View	 Load JPG	☒
58	27/02/17 10:52	General View	 Load JPG	☒
59	27/02/17 10:52	General View	 Load JPG	☒
60	27/02/17 10:52	General View	 Load JPG	☒
61	27/02/17 10:52	General View	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Hitachi Capital Asia Pacific Pte. Ltd (HQ)	Thumbnail	Print
62	27/02/17 10:52	General View	 Load JPG	☒
63	27/02/17 10:52	General View	 Load JPG	☒
64	27/02/17 10:52	General View	 Load JPG	☒
65	27/02/17 10:52	General View	 Load JPG	☒
66	27/02/17 10:52	General View	 Load JPG	☒
67	27/02/17 10:52	General View	 Load JPG	☒
68	27/02/17 10:52	General View	 Load JPG	☒
69	27/02/17 10:52	General View	 Load JPG	☒
70	27/02/17 10:52	General View	 Load JPG	☒
71	27/02/17 10:52	General View	 Load JPG	☒
72	27/02/17 10:52	General View	 Load JPG	☒
73	27/02/17 10:52	General View	 Load JPG	☒
74	27/02/17 10:52	General View	 Load JPG	☒
75	27/02/17 10:52	General View	 Load JPG	☒
76	27/02/17 10:52	General View	 Load JPG	☒
77	24/05/18 13:32	Reinspection Photo	 Load JPG	☒
78	24/05/18 13:32	Reinspection Photo	 Load JPG	☒
79	24/05/18 13:32	Reinspection Photo	 Load JPG	☒
80	24/05/18 13:32	Reinspection Photo	 Load JPG	☒
81	24/05/18 13:32	Reinspection Photo	 Load JPG	☒
82	24/05/18 13:32	Reinspection Photo	 Load JPG	☒
83	24/05/18 13:32	Reinspection Photo	 Load JPG	☒
84	24/05/18 13:32	Reinspection Photo	 Load JPG	☒
85	24/05/18 13:32	Reinspection Photo	 Load JPG	☒
86	24/05/18 13:32	Reinspection Photo	 Load JPG	☒
87	24/05/18 13:32	Reinspection Photo	 Load JPG	☒
88	24/05/18 13:32	Reinspection Photo	 Load JPG	☒
89	24/05/18 13:32	Reinspection Photo	 Load JPG	☒
90	24/05/18 13:32	Reinspection Photo	 Load JPG	☒
91	24/05/18 13:32	Reinspection Photo	 Load JPG	☒
92	24/05/18 13:32	Reinspection Photo	 Load JPG	☒
93	24/05/18 13:32	Reinspection Photo	 Load JPG	☒
94	24/05/18 13:32	Reinspection Photo	 Load JPG	☒
95	24/05/18 13:32	Reinspection Photo	 Load JPG	☒
96	24/05/18 13:32	Reinspection Photo	 Load JPG	☒
97	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
98	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
99	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
100	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
101	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
102	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
103	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
104	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
105	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
106	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
107	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
108	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
109	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
110	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
111	26/06/18 12:05	Reinspection Photo	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Hitachi Capital Asia Pacific Pte. Ltd (HQ)	Thumbnail	Print
112	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
113	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
114	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
115	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
116	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
117	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
118	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
119	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
120	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
121	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
122	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
123	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
124	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
125	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
126	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
127	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
128	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
129	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
130	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
131	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
132	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
133	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
134	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
135	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
136	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
137	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
138	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
139	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
140	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
141	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
142	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
143	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
144	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
145	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
146	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
147	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
148	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
149	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
150	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
151	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
152	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
153	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
154	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
155	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
156	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
157	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
158	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
159	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
160	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
161	26/06/18 12:05	Reinspection Photo	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Hitachi Capital Asia Pacific Pte. Ltd (HQ)	Thumbnail	Print
162	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
163	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
164	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
165	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
166	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
167	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
168	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
169	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
170	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
171	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
172	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
173	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
174	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
175	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
176	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
177	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
178	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
179	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
180	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
181	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
182	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
183	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
184	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
185	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
186	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
187	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
188	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
189	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
190	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
191	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
192	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
193	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
194	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
195	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
196	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
197	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
198	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
199	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
200	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
201	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
202	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
203	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
204	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
205	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
206	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
207	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
208	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
209	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
210	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
211	26/06/18 12:05	Reinspection Photo	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Hitachi Capital Asia Pacific Pte. Ltd (HQ)	Thumbnail	Print
212	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
213	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
214	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
215	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
216	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
217	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
218	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
219	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
220	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
221	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
222	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
223	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
224	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
225	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
226	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
227	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
228	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
229	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
230	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
231	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
232	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
233	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
234	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
235	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
236	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
237	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
238	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
239	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
240	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
241	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
242	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
243	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
244	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
245	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
246	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
247	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
248	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
249	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
250	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
251	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
252	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
253	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
254	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
255	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
256	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
257	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
258	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
259	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
260	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
261	26/06/18 12:05	Reinspection Photo	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Hitachi Capital Asia Pacific Pte. Ltd (HQ)	Thumbnail	Print
262	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
263	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
264	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
265	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
266	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
267	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
268	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
269	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
270	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
271	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
272	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
273	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
274	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
275	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
276	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
277	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
278	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
279	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
280	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
281	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
282	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
283	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
284	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
285	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
286	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
287	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
288	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
289	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
290	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
291	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
292	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
293	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
294	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
295	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
296	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
297	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
298	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
299	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
300	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
301	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
302	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
303	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
304	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
305	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
306	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
307	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
308	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
309	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
310	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
311	26/06/18 12:05	Reinspection Photo	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Hitachi Capital Asia Pacific Pte. Ltd (HQ)	Thumbnail	Print
312	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
313	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
314	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
315	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
316	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
317	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
318	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
319	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
320	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
321	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
322	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
323	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
324	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
325	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
326	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
327	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
328	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
329	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
330	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
331	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
332	26/06/18 12:05	Reinspection Photo	 Load JPG	☒
333	26/06/18 12:06	Reinspection Photo	 Load JPG	☒
334	26/06/18 12:06	Reinspection Photo	 Load JPG	☒
335	26/06/18 12:06	Reinspection Photo	 Load JPG	☒
336	26/06/18 12:06	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Hitachi Capital Asia Pacific Pte. Ltd (HQ)	Thumbnail	Print
1	23/02/17 17:34	Sketch Plan [Linked Accident Report Documents]	 Load TIF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	24/05/18 13:34	SUPPLEMENTARY LIST	 Load PDF	
2	24/05/18 13:42	REVISED ESTIMATE	 Load PDF	
3	24/05/18 15:59	PARTS INVOICE	 Load PDF	

Linked Accident Report Documents

Assessment Reports			1 per page	☒
No	Finalized On	Hitachi Capital Asia Pacific Pte. Ltd (HQ)	Thumbnail	Print
1	23/02/17 18:36	Accident Statement	 Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	Hitachi Capital Asia Pacific Pte. Ltd (HQ)	Thumbnail	Print
1	23/02/17 18:33	Accident Photo	 Load JPG	☒
2	23/02/17 18:33	Accident Photo	 Load JPG	☒
3	23/02/17 18:33	Accident Photo	 Load JPG	☒
4	23/02/17 18:33	Accident Photo	 Load JPG	☒
5	23/02/17 18:33	Accident Photo	 Load JPG	☒
6	23/02/17 18:33	Accident Photo	 Load JPG	☒
7	23/02/17 18:33	Accident Photo	 Load JPG	☒
8	23/02/17 18:33	Accident Photo	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Hitachi Capital Asia Pacific Pte. Ltd (HQ)	Thumbnail	Print
9	23/02/17 18:33	Accident Photo	 Load JPG	☒
10	23/02/17 18:33	Accident Photo	 Load JPG	☒
11	23/02/17 18:33	Accident Photo	 Load JPG	☒
12	23/02/17 18:33	Accident Photo	 Load JPG	☒
13	23/02/17 18:33	Accident Photo	 Load JPG	☒
14	23/02/17 18:33	Accident Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Hitachi Capital Asia Pacific Pte. Ltd (HQ)	Thumbnail	Print
1	23/02/17 17:34	Sketch Plan	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Repairer ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/MSG17003882/R1QH3E2

Date: 03/07/2018

REFERENCE

Insured/Claimant:	HITACHI CAPITAL AISIA PACIFIC PTE LTD	Policy No:	MSD/VPCP/16-002215-00	Claim No:	MSCV/17-000316
Date of Loss:	23/02/2017	Nature of Claim:	OD		

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKW6474A	Engine No:	2ARH640669
Make & Model:	TOYOTA VELLFIRE, 2.5 (A)	Chassis No:	JTNGF3DH208002862
Reg. Date:	09/11/2015 (Man. Year: 2015)	Odometer:	90052 km
Colour:	Black		
Engine Capacity:	2494 cc		
Market Value/New Car Price:	S\$153,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/50 R18	Rear Tyre Size:	235/50 R18
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,500.15	13,540.35	4,959.80	26.81
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,840.00	3,170.00	1,670.00	34.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	23,340.15	16,710.35	6,629.80	28.41
- Excess (S\$)	1,500.00	1,500.00	0.00	0.00
(S\$)	21,840.15	15,210.35	6,629.80	30.36
+ GST 7.00/7.00% (S\$)	1,528.81	1,064.72	464.09	30.36
Nett Amount (S\$)	23,368.96	16,275.07	7,093.89	30.36

INSPECTION

Date of Assignment:	24/02/2017 Present Location:	Hitachi Capital Asia Pacific Pte. Ltd (HQ)
Date Inspected:	24/02/2017 Inspected At:	No 8 Fourth Lok Yang Road Singapore 629705
Estimated Period of Repair:	12.0 days	

Adjuster: MOHD RASUL

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 03 Jul 2018)
Parts: M1-MPV	TOYOTA VELLFIRE 2.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKW6474A)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Front bumper	Deformed	210.00 F	*210.00 F
2	10		*Front bumper clips	Necessary	15.00 F	*15.00 F
3	1		*Front bumper side retainer LH/RH	O/S Cracked	70.00 F	*35.00 F
4	2		*Front tow cover	Serviceable	30.00 F	*- F
5	2		*Headlamp LH/RH	Broken	2,200.00 F	*2,200.00 F
6	1		*Front bumper sponge	Cracked	55.00 F	*55.00 F
7	1		*Front bumper center lower grille	Cracked	80.00 F	*80.00 F
8	1		*Front grille with chrome moulding	Cracked	430.00 F	*430.00 F
9	1		*Front grille logo	Necessary	40.00 F	*40.00 F
10	6		*Front grille clips	Necessary	9.00 F	*9.00 F
11	1		*Front parking sensor original LH/RH	N/SServiceable/O/SNotWorking	270.00 F	*135.00 F
12	1		*Front parking sensor original holder LH/RH	N/SNotNecessary/O/SNecessary	20.00 F	*10.00 F
13	1		*Front fog lamp	Cracked	-	*110.00 F
14	1		*Front fog lamp cover	N/S Serviceable/O/S Missing	90.00 F	*45.00 F
15	1		*Front reinforcement with bracket	Serviceable	160.00 F	*- F
16	1		*Brace panel	Serviceable	35.00 F	*- F
17	2		*Horn	Serviceable	100.00 F	*- F
18	1		*Support panel LH/RH	N/S Serviceable / O/S Bent	240.00 F	*120.00 F
19	1		*Support panel lower member	Serviceable	95.00 F	*- F
20	1		*Support panel top	Bent	200.00 F	*190.00 F
21	1		*Support panel top garnish	Deformed	120.00 F	*105.00 F
22	8		*Support panel top garnish clips	Not Necessary	12.00 F	*- F
23	1		*Bonnet	Bent	230.00 F	*230.00 F
24	2		*Bonnet hinge	Bent	50.00 F	*50.00 F
25	1		*Bonnet chrome moulding	Cracked	190.00 F	*190.00 F
26	1		*Bonnet lock	Bent	60.00 F	*60.00 F
27	1		*Bonnet stopper	Necessary	40.00 F	*20.00 F
28	1		*Bonnet stand holder	Necessary	25.00 F	*25.00 F
29	1		*Bonnet insulator	Deformed	55.00 F	*55.00 F
30	8		*Bonnet insulator clips	Necessary	12.00 F	*12.00 F
31	1		*Front fender LH/RH	O/S Buckled/N/S Repair	600.00 F	*300.00 F
32	1		*Front fender shield LH/RH	O/S Torn	220.00 F	*110.00 F
33	20		*Front fender shield clips	Necessary	30.00 F	*30.00 F
34	1		*Aircon condensor	Serviceable	500.00 F	*- F
35	1		*Air Duct (NPA)	Serviceable	-	*- F
36	1		*Radiator	Serviceable	540.00 F	*- F
37	2		*Radiator bottom bush	Serviceable	24.00 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
38	2		*Radiator original coolant	Serviceable	42.00 F	*- F
39	1		*Aircon fan cowling	Serviceable	95.00 F	*- F
40	1		*Aircon fan blade	Serviceable	80.00 F	*- F
41	1		*Aircon fan motor	Serviceable	150.00 F	*- F
42	1		*Radiator fan cowling top	Serviceable	70.00 F	*- F
43	1		*Radiator fan blade	Serviceable	70.00 F	*- F
44	1		*Radiator fan motor	Serviceable	300.00 F	*- F
45	1		*Radiator top hose	Serviceable	30.00 F	*- F
46	1		*Radiator bottom hose	Serviceable	30.00 F	*- F
47	1		*Driver door	Repair	650.00 F	*- F
48	2		*Driver door sticker	Serviceable	70.00 F	*- F
49	1		*Wiper garnish set	Deformed	210.00 F	*210.00 F
50	1		*Wiper garnish cover top LH/RH	N/S Serviceable / O/S Deformed	110.00 F	*55.00 F
51	10		*Wiper garnish clips	Necessary	15.00 F	*15.00 F
52	1		*Radiator spare tank	Serviceable	120.00 F	*- F
53	1		*A pillar RH (NPA)	Repair	-	-
54	1		*Front windscreen with moulding	Necessary	850.00 F	*850.00 F
55	1		*Windscreen sealant	Necessary	45.00 FS	*45.00 FS
56	1		*Front number plate with casing	Serviceable	45.00 FS	*- FS
57	1		*Support lower garnish cover	Serviceable	55.00 F	*- F
58	1		*Wiper tank	Deformed	60.00 F	*60.00 F
59	1		*Wiper tank motor	Serviceable	200.00 F	*- F
60	1		*Air resonator box	Serviceable	120.00 F	*- F
61	1		*Radiator side garnish LH/RH top	Serviceable	80.00 F	*- F
62	1		*Headlamp center cover LH/RH	N/S Serviceable / O/S Broken	130.00 F	*65.00 F
63	1		*Front fender RH bracket	Necessary	30.00 F	*30.00 F
64	1		*Front fender inner panel RH	Buckled	320.00 F	*320.00 F
Supplementary #1						
65	10		*Front cowling clips	Necessary	15.00 F	*15.00 F
66	1		*Front fender protector RH	Broken	65.00 F	*65.00 F
67	1		*Front fender quarter glass RH	Broken	95.00 F	*95.00 F
68	1		*Front windscreen moulding RH	Necessary	60.00 F	*60.00 F
69	1		*Aircon liquid pipe	Bent	280.00 F	*280.00 F
70	1		*Front fog lamp RH	Cracked	120.00 F	*120.00 F
71	1		*Headlamp ballast RH	Not Working	280.00 F	*280.00 F
72	1		*Fuse box top cover RH	Cracked	35.00 F	*35.00 F
73	1		*Wiper washer inlet neck	Deformed	25.00 F	*25.00 F
74	1		*Wiper garnish shield RH	Deformed	30.00 F	*30.00 F
75	1		*Wire hardness	Cut	3,800.00 F	*3,800.00 F
76	1		*Wiper panel lower sponge	Cut	150.00 F	*150.00 F
77	1		*Aircon discharge pipe	Bent	180.00 F	*180.00 F
78	1		*Wiper linkage	Bent	200.00 F	*200.00 F
79	1		*Wiper panel	Deformed	400.00 F	*400.00 F
80	1		*Wiper tank motor rear hose	Cut	10.00 F	*10.00 F
81	1		*Wiper tank motor front hose	Cut	10.00 F	*10.00 F
82	2		*Wiper panel lower sponge clip	Necessary	6.00 F	*6.00 F
83	3		*Wiper hose joint	Cut	18.00 F	*18.00 F
84	9		*Support top garnish clips	Necessary	13.50 F	*13.50 F

F=Franchise part. S=SpcNett.

Sub Total (S\$) 16,826.50 12,313.50
+ Margin on L,N Items 10.00/10.00% (S\$) 1,673.65 1,226.85

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Total Parts (S\$)					18,500.15	13,540.35

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	Panel beat, cut, weld, re-align & replace damaged parts of affected area	New	2,000.00	1,300.00
2	Putty, blend and paint affected area	New	1,800.00	1,400.00
3	Check Wiring, re-align headlamps and ensure proper function	New	80.00	30.00
4	Refill compressor oil, vacuum and refill aircond gas	New	180.00	100.00
5	Remove & reinstall bumper sensors	New	120.00	60.00
6	Conduct four wheel alignment / side slip test	New	180.00	80.00
7	Remove & re-install Front Windscreen	New	180.00	120.00
8	Transfer door lock & mechanism to new door	New	120.00	0.00
9	Diagnostic Check & Reset	New	180.00	80.00
Gross Labour Cost (S\$)			4,840.00	3,170.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >