

RELIANCE SURVEYORS PTE LTD

Licensed Appraisers. Marine & Engineering Consultants. Cargo Surveyors & Superintendents.
Insurance Surveyors/Adjusters. Container Inspectors. Pre-Risk Surveyors & Consultants.

AUTOMOBILE INSPECTION REPORT

To : M/s Bock's Trading & Bus Transport Service
15 Jalan Rabu
Singapore 577031

Date : 15/05/2014
Your Ref : ---
Our Ref : TP/RS/116560/14

Reference

Assignment Requested by : Mr. Tan
Date of Accident : 28/03/2014
Date of Survey Request : 28/04/2014
Date of Survey : 28/04/2014
Place of Inspection : No. 18 Sungei Kadut Way

Policy Particulars

Type of claims : Third Party
Policy No : ---
Claims No : ---
Sum Insured : ---
Excess Clause : ---

Particulars of Vehicle

Regn. No : PA 428 E
Make & Model : Nissan JP251LSNEC
Yr of Manufacture/Regn : 1998
Engine No : FEB122605C
Chassis No : JP251LSN00246
Class : Pte Hire

Colour : Multi-colour
Mileage : 817200 KM
Radio/Hifi : Fitted
Air conditioner : Fitted
Seat Belt : Fitted
Modification : None

Static Test

Handbrake : Working
Footbrake : Working
Steering : Working

Tyre Size/Condition

Front o/s : B/stone 11R22.5, 80%
Front n/s : -----ditto-----
Rear o/s : -----ditto-----
Rear n/s : -----ditto-----
Wheel Rim : Standard

The above percentages represent the remaining estimated life of the tyre threads

General Description of Damage

Details of damage – refer to attached appendix 'A' & photographs

APPRAISEMENT

The repair estimated bill submitted by M/s Liannex Corporation (S) Pte Ltd (S\$14,220.00) has been checked/scrutinized thoroughly by us against the actual damage found on the said vehicle and only the badly/beyond items are recommended for replacement (Refer APPENDIX A for details). In this respect, we opined the total repair cost of **S\$9,970.00 net.** (lump sum, excluding GST) to be fair and reasonable.

Without prejudice, the repairer has agreed to our recommendation to effect repairs to the owner's satisfaction and roadworthy condition.

In accordance to your instruction, we have not authorized repair.

The estimated normal period of repair shall not exceed twelve (12) working days.

RELIANCE SURVEYORS PTE LTD

APPENDIX A

Date : 15/05/2014
Our Ref : TP/RS/116560/14
Vehicle No : PA 428 E

Name of Workshop : Liannex Corporation (S) Pte Ltd
Address : No. 18 Sungei Kadut Way , Singapore 728789 , P.I.C. : Miss Alice Ng

QTY	DESCRIPTION	REMARKS/CONDITION	REPAIRER ESTIMATE	OUR RECOMMENDATION
1	Rear o/s side corner panel	Torn/Scored	\$ 1,300.00	\$ 1,300.00
1	Rear o/s side inspection door	Distorted	\$ 2,100.00	\$ 2,100.00
1	Rear o/s side inspection door lock	Bent	\$ 110.00	\$ 110.00
1	Rear o/s side vertical panel	Distorted	\$ 220.00	\$ 220.00
1	Rear o/s fender	Distorted	\$ 2,900.00	\$ 2,900.00
1	Rear o/s wheel arch protector	Cut/Scored	\$ 480.00	\$ 480.00
1	Rear o/s luggage door lock	Distorted	\$ 2,300.00	\$ 2,300.00
1	Rear o/s luggage door lock	Bent	\$ 110.00	\$ 110.00
			<hr/>	<hr/>
			\$ 9,520.00	\$ 9,520.00
Less 10% trade discount			-----	\$ 952.00
			<hr/>	<hr/>
Total parts costs			\$ 9,520.00	\$ 8,568.00
<u>Labour charges :-</u>				
a.	To putty and spray painting on rear bumper , rear o/s corner panel , rear o/s vertical panel , rear inspection door , rear o/s luggage door , rear o/s fender and all affected accident parts including design painting on same. (multi-colour)		\$ 2,600.00	\$ 2,200.00
b.	To knock/straighten all necessary parts including repairing and changing of all damaged parts and align same.		\$ 2,100.00	\$ 1,700.00
			<hr/>	<hr/>
Total repair cost			\$ 14,220.00	\$ 12,468.00

LUMP SUM REPAIR :- S\$9,970.00 net (our recommendation)


Alternatively , the subject vehicle could be repaired satisfactorily for a lump sum not exceeding S\$9,970.00 net.

Remarks:

This survey has been carried out to the best of our knowledge and ability and "WITHOUT PREJUDICE" to any party concerned.

Enclosures : 16 pcs of photographs showing the damaged are attached to the original copy of report.

RELIANCE SURVEYORS PTE LTD


DAVID LIANG
AMIMI , CAE , AIAME
DIRECTOR