

ASS. REC. BY:

REF:

CS/CT117005331/714 b52

Special Instruction:

Survivor:

Taufik

ASSIGNMENT (Office)

From (Person):

Joan Tea

of

CT

Date/Time: 16/03/2017 5:59pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKN 3330Z

Insured:

YN 8294X

at Workshop m/s

Performance Motor

Tel:

6319 0174

of

303 Alexandra Road

Policy No:

DMCVSN3056341600

Claim No:

SNM170 01539 002/4

Sum Insured:

Excess:

Make of Veh:

D.O.A. 13/03/2017

(Client's Record)

CA / REV / REP. / REV 24 HRS '08'

27.03.2017

H.O.D. Endorsement:

Date/Time: 16/03/2017 5:59pm

Person Contacted:

Caroline

Vehicle IN/OUT

| Date/Time | Action/Instruction (✓) Estimate | Intitran |
|-----------|---------------------------------|----------|
|           | SKN 3330Z - X                   |          |
|           | YN 8294X - X                    |          |
|           |                                 |          |
|           |                                 |          |
|           |                                 |          |
|           |                                 |          |
|           |                                 |          |

08/11/13

REF:

CT 1

Surveyor: T. Anglin  
Mellman

# ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

|     |     |
|-----|-----|
|     |     |
| N/S | O/S |
|     |     |

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS OK

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: In Person

Veh No: SKN 33302 Yr Regn: 2014, April

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: BMW 640i Green Spent 2979  
E.C.

Colour: Red A/C: Insured / Std / NI / NA

Sp. Reading: 32959 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: WBA 64020300212020

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 275/30/19

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front \_\_\_\_\_ Rear \_\_\_\_\_

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. \_\_\_\_\_ D.O.I. 5/4/17 @ 1300

Survey held at PML Alexander

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

| Date / Time | Action / Instruction                            |
|-------------|---|
|             | Part by Part \$20,194.65 (Red: 11923.350 : 87%) |
|             | RECEIVED 30 NOV 2017                            |
|             | <u>30/11/2017</u>                               |

Date/Time, File Pass to?

☐ : Preli. Report

1) 30/11 Typist

☒ : Final Report

Date/Time, File Return to?

2) \_\_\_\_\_

Days Of Repair: 14

Resurvey No. of Trip: 1

Survey Fee: 250

Transportation: \_\_\_\_\_

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)

☐ : Interview (\$ \_\_\_\_\_)

☐ : Tech. Invs (\$ \_\_\_\_\_)

☐ : Weekend (\$ \_\_\_\_\_)

) \$ + RS. \$ \_\_\_\_\_

) Photos

) Others

TOTAL

Report Format : TP

Lump Sum / I.B.I: (\$) 20194.65




# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile   |  |                 |                           |   |
|---|--|-----------------|---------------------------|---|
| CHINA TAIPING INSURANCE (S) PTE LTD   |  |                 | Ref : CS/CTI17005331/T1tb |   |
| 3 ANSON ROAD #16-00<br>SPRINGLEAF TOWERS SINGAPORE 079909   |  |                 | Date : 16-03-2017         |  |
|   |  |                 | Code : CTI                |   |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>   |  |                 |                           |   |
| Insured Veh.  | YN 8294X   | Veh. Inspected  | SKN 3330Z                 |   |
| Policy No.  | DMCVSN3056541600   | Coverage (\$)   | 0.00                      |   |
| Claim No.   | SNM17D01539C02/4   | Excess (\$)     | 0.00                      |   |
| Assign From   | MERIMEN (JASON TEA)  | Assign Date     | 16/03/2017                |   |
| <b>2. Vehicle Particulars &amp; Condition</b>   |  |                 |                           |   |
| Make & Model  |  | c.c             | 0                         |   |
| Engine No.  | HIDDEN   | Year of Reg.    |                           |   |
| Chassis No.   |  | Colour          |                           |   |
| Odometer  | -  | Steering        |                           |   |
| Brakes  |  | Modification    |                           |   |
| General   |  |                 |                           |   |
| <b>3. Conditions of Tyres</b>   |  |                 |                           |   |
|   | Size   | Make            | Balance                   |   |
| R/H Front Tyre  |  |                 | mm                        |   |
| L/H Front Tyre  |  |                 | mm                        |   |
| R/H Rear Tyre   |  |                 | mm                        |   |
| L/H Rear Tyre   |  |                 | mm                        |   |
| <b>4. Description of Damages</b>  |  |                 |                           |   |
|   |  |                 |                           |   |
| <b>5. General Information</b>   |  |                 |                           |   |
| Accident Date   | 13/03/2017   | Inspection Date |                           |   |
| Survey held at  | PERFORMANCE MOTORS LTD<br>303 ALEXANDRA ROAD<br>SINGAPORE 159941 |                 |                           |   |
| <b>5a. Remarks</b>  |  |                 |                           |   |
| A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.<br>B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |  |                 |                           |   |

## ...CLAIM SUBFOLDER...(New Assignment)

## CLAIM SUBFOLDER TRACKING

| Case | Notified    | Est Submitted | Adj Assigned                                   | Adj Rpt | Adj Submitted | Ins Auth'd | Status   |
|------|-------------|---------------|--|---------|---------------|------------|--|
| Main | 16 Mar 2017 |               | 16 Mar 2017<br>17:29<br><a href="#">Assign</a> |         |               |            | <b>New Assignment</b><br><a href="#">Cancel Case</a> |

|                      |                           |                               |                           |                          |
|----------------------|---------------------------|-------------------------------|---------------------------|--------------------------|
| <a href="#">Main</a> | <a href="#">Reference</a> | <a href="#">Claim Details</a> | <a href="#">Documents</a> | <a href="#">Show All</a> |
|----------------------|---------------------------|-------------------------------|---------------------------|--------------------------|

CLAIM SUBFOLDER DETAILS

[Created by insurer]

|                             |   |                        |                        |
|-----------------------------|---|------------------------|------------------------|
| Insured:                    | WINDOW WORLD PTE LTD  |                        |                        |
| Main Claimant:              | JENNIFER HO CHUEY FOONG   |                        |                        |
| Vehicle Reg. No.:           | SKN3330Z  | Date of Loss:          | 13/03/2017 00:00 - :59 |
| Claim Type:                 | TP / SNM17D01539C02/4   | Policy/Cover Note No.: | DMCVSN3056541600       |
| Vehicle Reg. No. (Insured): | YN8294X   | Policy No. (Claimant): |                        |
|                             |   | Excess:                | S\$0.00                |
| Repairer:                   | Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174 |                        |                        |
| Handling Insurer:           | China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jason Tea - 63896171]                           |                        |                        |
| Adjuster:                   | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 27/03/2017]   |                        |                        |
| Adj Asg. Remarks:           | TO SURVEY TP VEHICLE AND VERIFY DAMAGE CONSISTENCY, WE CAN AGREE TO DIRECT SETTLEMENT IF ALL IN ORDER.                              |                        |                        |

[View All](#)
[Compose Case Mail](#)

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

| Due Date    | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
|-------------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|
| No results. |          |      |            |         |         |             |              |            |       |

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

|                            |                            |
|----------------------------|----------------------------|
| Date Of Report             | 13/03/2017 17:45           |
| Date Of Accident           | 13/03/2017 12:15           |
| Exact Location Of Accident | 12 CARDIFF GROVE S(558879) |
| Country/State of Loss      | Singapore                  |

### DETAILS OF OWN VEHICLE

|                             |                         |
|-----------------------------|-------------------------|
| Vehicle Registration Number | SKN3330Z                |
| <b>Insured/Policyholder</b> |                         |
| Name Of Registered Owner    | JENNIFER HO CHUEY FOONG |
| NRIC No                     | S1649724Z               |
| Email Address               | JENHO99@GMAIL.COM       |
| Mobile Phone No             | (LOCAL) +65-96323932    |
| Alternative Phone No        | Others-97886318         |

### Vehicle Particulars

|  |              |
|--|--------------|
| Manufacturer   | BMW          |
| Model  | 640i         |
| Exact Purpose for which vehicle was being used at time of accident           | NORMAL USAGE |
| Are you claiming under your own insurance policy for repair to your vehicle? | No           |
| If No, Please state action to be taken                                       | Third Party  |
| Vehicle Category   | Private Car  |

### Insurance Company

|                           |                       |
|---------------------------|-----------------------|
| Name of Insurance Company | AXA Insurance Pte Ltd |
| Type Of Coverage          | Comprehensive         |
| Fleet Policy              | No                    |
| Policy Number             | NOT AVAILABLE         |
| Cover Note Number         |                       |

### Driver

|                      |                         |
|----------------------|-------------------------|
| Name of Driver       | JENNIFER HO CHUEY FOONG |
| NRIC No              | S1649724Z               |
| Date Of Birth        | 30/03/1964              |
| Occupation           | Indoor                  |
| Date Of Driving Pass | 06/01/1988              |
| Driving Experience   | 29 Years And 2 Months   |
| Gender               | Female                  |
| Mobile Number        | (Local) +65-96323932    |
| Fax Number           |                         |
| Contact Number       | Others-97886318         |
| EMAIL Address        | JENHO99@GMAIL.COM       |

Address

\* Postcode

Was driver an employee of the Insured's Company No

If No, Relationship of the Driver with the Insured Owner

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

#### General Information of the Accident

Type Of Accident Unknown - REFER TO SKETCH

Weather Conditions Clear

Road Surface Dry

#### Other Information

Was any foreign vehicle involved in this accident? No

Was any body injured in the Accident? No

Was any other material or property damaged? Yes

I have been approached by unknown person(s) soliciting/offering accident claims assistance. No

Number of Passengers (Including Driver) 0

#### Details of Police Action

Was the accident reported to the police? No

If Yes, Please state which Police Station

Was notice of intended Prosecution given? No

If Yes, against whom?

#### Circumstances of Accident

REFER TO ATTACH.

#### Attachment(s)

Are accident photos available for attachment? Yes

Was there any video captured by Car Camera? No

Was there any audio recorded? No

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number YN8294X

Vehicle Make/Model/Colour LORRY WHITE HINO 300

Details Of Properties

Name of Driver YAP KOK VAI

NRIC/Passport Number

Contact Number 90303397

Address

Postcode

Insurance Company Name China Taiping Insurance (Singapore) Pte. Ltd.

Nature Of Damage

No. Of Passenger (Including Driver)

#### Details of Witness

Name

Phone Number

Email Address

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or


(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and


(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

  
Policyholder's Signature / Date & Time

  
Driver's Signature (if driver is not the policyholder) / Date & Time

  
Witnessed by Reporting Centre Personnel

Sketch Plan





## Describe Circumstances of the Accident

On 13<sup>th</sup> MARCH 2017, at about 12:14pm, a neighbour rang the door bell to inform my maid someone had driven a van into my car SK0330Z. The ~~lorry~~ driver apologised and he asked that he claimed against his insurance. He drives a white lorry YN 8294X HINO 300. The damage is on the rear end of the car at the passenger side.

## Declaration

We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel



## Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Tel. 63190888 (AfterSales)  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190528 (AfterSales)  
63190533/530 (Motorrad)  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

## ESTIMATE

15 MAR 2017

Estimate No. : b1 41944  
Date Estimated : 15/03/2017  
Prepared By : Inthiran A/L Thurasamy

Page No. : 1 of 2

- ESTIMATE REPAIR FOR -  
Jennifer Ho Chuey Foong  
12 Cardiff Grove

Singapore 558879

- ACCOUNT - 40000  
Cash Sales - Service  
Singapore

| REGN. NO. | CHASSIS NO. | REGN. DATE | MODEL    | MILEAGE |
|-----------|-------------|------------|----------|---------|
| SKN3330Z  | DZ12020     | 23/04/2014 | 640iA GC | 0       |

## DESCRIPTION

To replace rear left fender, bumper and attachments including knock out dent area cause by accident.

Painting rear left fender, bumper, tail panel, trunk floor, roof frame and 'c' pillar.

To replace rear windscreen including to conduct water leak test.

To install rear windscreen 3M Solar Film.

To remove and install rear hat hat-tray, rear seat, carpet and roof top lining to facilitate the cutting of the rear fender.

To remove and install rear boot compartment carpet and garnish to facilitate repairs.

To reconnect electrical components and wirings at the rear section include conducting checks for proper function. (Remarks: For cutting panel)

To remove old PDC assembly, replace damaged parts and reconnect to new bumper include conducting checks for proper function.

To carry out body cavity preservation.

Sundries.

## VALUE

5950 6,800.00

3684 3683 4,093.00

649.00

531.00

742 873.00

231 230 271.00

451 300 354.00

150 177.00

451 531.00

150 150.00

Total Labour 1: 14,429.00

## DESCRIPTION

PLASTIC NUT FOR COARSE THREADED PIN  
REAR LH SIDE PANEL

| QTY | PRIC     |
|-----|----------|
| 6   | 0.80     |
| 1   | 2,379.90 |

## VALUE

4.80

2,379.90

## Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



383, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Tel. 63190888 (AfterSales)  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190528 (AfterSales)  
63190533/530 (Motorrad)  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

## ESTIMATE

Estimate No. : b1 41944  
Date Estimated : 15/03/2017  
Prepared By : Inthiran A/L Thurasamy

Page No. : 2 of 2

| REGN. NO. | CHASSIS NO. | REGN. DATE | MODEL    | MILEAGE |
|-----------|-------------|------------|----------|---------|
| SKN3330Z  | DZ12020     | 23/04/2014 | 640iA GC | 0       |

## DESCRIPTION

QTY PRIC VALUE

|  |    |          |          |
|--|----|----------|----------|
| Plate                                  | 1  | 48.00    | 48.00    |
| Plate                                  | 1  | 48.00    | 48.00    |
| Mount rear left                        | 1  | 141.65   | 141.65   |
| RR BUMPER (PDC)                        | 1  | 1,690.65 | 1,690.65 |
| PLASTIC NUT                            | 4  | 0.85     | 3.40     |
| REAR W/SCREEN                          | 1  | 1,053.80 | 1,053.80 |
| BUMP STOP                              | 10 | 3.25     | 32.50    |
| REAR LIGHT IN THE SIDE PANEL LH        | 1  | 611.80   | 611.80   |
| DECOUPLING RING PDC TORQUE CONVERTE    | 4  | 4.95     | 19.80    |
| Ultraschallw                           | 1  | 363.05   | 363.05   |
| CAVITY PROTECTION WAX REMOVER 500ML    | 1  | 18.45    | 18.45    |
| BLIND RIVET AVIBVLB                    | 17 | 0.55     | 9.35     |
| SCREW (SF PLUS M5X15)                  | 3  | 0.55     | 1.65     |
| (DG/SL) BODY ADHESIVE K5B (195ML)      | 1  | 281.55   | 281.55   |
| PUNCH RIVET N5                         | 14 | 0.55     | 7.70     |
| PUNCH RIVET N4                         | 18 | 0.55     | 9.90     |
| (DG) BODYWORK ADHESIVE K5A (50ML)      | 1  | 118.35   | 118.35   |
| (DG) CLEANER R1 (100ML)                | 1  | 23.85    | 23.85    |
| (DG) CLEANER R1 (100ML)                | 1  | 23.85    | 23.85    |
| (DG/SL) W/SCREEN SEALANT (COLD 1 HOUR) | 2  | 131.55   | 263.10   |
| (DG/SL) GLASS PRIMER 30ML (VP206)      | 1  | 27.85    | 27.85    |
| (S/L) SEAM SEAL 300ML                  | 1  | 33.80    | 33.80    |

Total Parts 7,216.75

Claims CD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. 5/4/17 01300 Claim No.  
Excess \$  
Surveyor's Name Tanjahn Sign  
Surveyor's Tel 97495749 Authorised Yes / No  
A/L Name Only Time  
Surveyor's Email tanjahn@lkkamp.com  
No. of Working Days Recommended 14 days

Total Parts 7,216.75

Surveyor of the following:

- Survey before/after spray painting.
- Apply damaged part(s) during resurvey.
- Prices are subject to confirmation.
- Third party survey is on a "Without Prejudice" basis.
- Modification(s) is allowed.
- Temporary item(s) must be resurveyed.
- Subject to final approval from Insurance.

Notated by Repairer

Notated

Notated

21645.75

22123.15

|                |   |           |
|----------------|---|-----------|
| Labour 1       | : | 14,429.00 |
| Parts          | : | 7,216.75  |
| Labour 2       | : | 0.00      |
| Excess         | : | 0.00      |
| Total GST @ 7% | : | 1,515.20  |
| Grand Total    | : | 23,160.95 |

\*\* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY \*\*

\*\* GST AMOUNT SUBJECT TO CHANGE \*\*

21873.40

22350.80

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



## FINAL REPORT

Estimate No. : b1 41944  
Date Estimated : 15/03/2017  
Prepared By : Inthiran A/L Thurasamy

Page No. :

REPAIR FOR -  
Jennifer Ho Chuey Foong  
12 Cardiff Grove

- ACCOUNT - 135  
China Taiping Insurance (S) Pte Ltd  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

Singapore 558879

| REGN. NO.  | CHASSIS NO.    | REGN. DATE | MODEL    | M LEASE  |
|--|----------------|------------|----------|----------|
| SKN3330Z   | DZ12020        | 23/04/2014 | 640iA GC | 0        |
| DESCRIPTION  | ORIGINAL PRICE | DISC. %    | NETT     |          |
| * To replace rear bumper and attachments, rear LH fender include making good the tail end panel, trunk floor plate, LH roof frame, LH 'C' pillar and knocking out dents caused by the accident | 5950.00        |            | 5,950.00 |          |
| To spray paint rear LH fender, rear bumper, tail end panel, trunk floor plate, LH roof frame and LH 'C' pillar   | 3684.00        |            | 3,684.00 |          |
| To replace rear windscreen include conducting water leak tests   | 649.00         |            | 649.00   |          |
| To install rear windscreen solar 3M solar film   | 531.00         |            | 531.00   |          |
| To remove and install rear hat-tray, rear seat, carpet and roof top lining to facilitate repairs   | 742.00         |            | 742.00   |          |
| To remove and install rear boot compartment carpet and garnish to facilitate repairs.  | 231.00         |            | 231.00   |          |
| * To reconnect electrical components and wirings at the rear section include replace rear LH light in side panel and conducting checks for proper function (For cut panel)                     | 451.00         |            | 451.00   |          |
| To remove old PDC assembly, replace damaged parts and reconnect to new bumper include conducting checks for proper function.   | 150.00         |            | 150.00   |          |
| To carry out body cavity preservation for rear LH fender (For cut panel)   | 451.00         |            | 451.00   |          |
| # To remove and install fuse box at the rear section to facilitate repairs   | 451.00         |            | 451.00   | (A)      |
| Sundries   | 150.00         |            | 150.00   |          |
| DESCRIPTION  | UNIT PRICE     | QTY        | DISC. %  | NETT     |
| PLASTIC NUT FOR COARSE THREADED PIN  | 0.80           | 6.00       |          | 4.80     |
| REAR LH SIDE PANEL   | 2,379.90       | 1.00       |          | 2,379.90 |
| # EXPANDING NUT *  | 1.10           | 2.00       |          | 2.20 (A) |
| REAR BUMPER PANEL PRIMED (M)   | 1,811.40       | 1.00       |          | 1,811.40 |

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



## FINAL REPORT

|  |          |       |          |
|--|----------|-------|----------|
| PLASTIC NUT                            | 0.85     | 4.00  | 3.40     |
| # W/SCREEN RUBBER BUFFER *             | 1.60     | 10.00 | 16.00    |
| REAR W/SCREEN                          | 1,053.80 | 1.00  | 1,053.80 |
| BUMP STOP                              | 3.25     | 10.00 | 32.50    |
| # CLIP, BOTTOM PART *                  | 1.60     | 4.00  | 6.40     |
| REAR LIGHT IN THE SIDE PANEL LH        | 611.80   | 1.00  | 611.80   |
| # SNAP LOCKING COUPLING *              | 0.90     | 2.00  | 1.80     |
| DECOUPLING RING PDC TORQUE CONVERTE    | 4.95     | 4.00  | 19.80    |
| BLIND RIVET AVIBVLB                    | 0.55     | 20.00 | 11.00    |
| SCREW (SF PLUS M5X15)                  | 0.55     | 10.00 | 5.50     |
| (DG/SL) BODY ADHESIVE K5B (195ML)      | 281.55   | 1.00  | 281.55   |
| PUNCH RIVET N5                         | 0.55     | 20.00 | 11.00    |
| PUNCH RIVET N4                         | 0.55     | 20.00 | 11.00    |
| (DG) BODYWORK ADHESIVE K5A (50ML)      | 118.35   | 1.00  | 118.35   |
| (DG) CLEANER R1 (100ML)                | 23.85    | 2.00  | 47.70    |
| (DG/SL) W/SCREEN SEALANT (COLD 1 HOUR) | 131.55   | 2.00  | 263.10   |
| (DG/SL) GLASS PRIMER 30ML (VP206)      | 27.85    | 1.00  | 27.85    |
| (S/L) SEAM SEAL 300ML                  | 33.80    | 1.00  | 33.80    |

### # SUPPLEMENTARY ITEMS

|                                 |           |
|---------------------------------|-----------|
| Total Labour :                  | 13,440.00 |
| Total Parts :                   | 6,754.65  |
| Total Labour & Parts :          | 20,194.65 |
| Deduction for Excess :          | 0.00      |
| Total Repair Costs less Excess: | 20,194.65 |
| GST @7%:                        | 1,413.63  |
| Grand Total :                   | 21,608.28 |

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



## SUPPLEMENTARY

Estimate No. : b1 41944  
Date Estimated : 15/03/2017  
Prepared By : Inthiran A/L Thurasamy

Page No. :

REPAIR FOR -  
Jennifer Ho Chuey Foong  
12 Cardiff Grove

- ACCOUNT - 135  
China Taiping Insurance (S) Pte Ltd  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

Singapore 558879

| REGN. NO. | CHASSIS NO. | REGN. DATE | MODEL    | M LEAGE |
|-----------|-------------|------------|----------|---------|
| SKN3330Z  | DZ12020     | 23/04/2014 | 640iA GC | 0       |

| DESCRIPTION  | ORIGINAL PRICE | DISC. % | NETT   |
|--|----------------|---------|--------|
| # To remove and install fuse box at the rear section to facilitate repairs | 451.00         |         | 451.00 |

| DESCRIPTION                | UNIT PRICE | QTY   | DISC. % | NETT  |
|----------------------------|------------|-------|---------|-------|
| # EXPANDING NUT *          | 1.10       | 2.00  |         | 2.20  |
| # W/SCREEN RUBBER BUFFER * | 1.60       | 10.00 |         | 16.00 |
| # CLIP, BOTTOM PART *      | 1.60       | 4.00  |         | 6.40  |
| # SNAP LOCKING COUPLING *  | 0.90       | 2.00  |         | 1.80  |

|                        |        |
|------------------------|--------|
| Total Labour :         | 451.00 |
| Total Parts :          | 26.40  |
| Total Labour & Parts : | 477.40 |

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

| CLAIM SUBFOLDER TRACKING |             |               |  |   |   |             |   |
|--------------------------|-------------|---------------|--|---|---|-------------|---|
| Case                     | Notified    | Est Submitted | Adj Assigned   | Adj Rpt   | Adj Submitted                                   | Ins Auth'ed | Status  |
| Main                     | 16 Mar 2017 |               | 16 Mar 2017<br>17:29<br><a href="#">Edit Adj Rpt</a> | <b>S\$20,194.65</b><br><a href="#">Edit Estimates</a> | <b>S\$20,194.65</b><br><a href="#">View Rpt</a> |             | <b>Pending for Survey Report</b><br><a href="#">Cancel Case</a> |

|      |           |               |           |          |
|------|-----------|---------------|-----------|----------|
| Main | Reference | Claim Details | Documents | Show All |
|------|-----------|---------------|-----------|----------|

CLAIM SUBFOLDER DETAILS

[Created by insurer]

|                             |   |                        |                        |
|-----------------------------|---|------------------------|------------------------|
| Insured:                    | WINDOW WORLD PTE LTD, Co. Reg. No.: -   |                        |                        |
| Main Claimant:              | JENNIFER HO CHUEY FOONG   |                        |                        |
| Vehicle Reg. No.:           | SKN3330Z  | Date of Loss:          | 13/03/2017 00:00 - :59 |
| Claim Type:                 | TP / SNM17D01539C02/4   | Policy/Cover Note No.: | DMCVSN3056541600       |
| Vehicle Reg. No. (Insured): | YN8294X   | Policy No. (Claimant): |                        |
|                             |   | Excess:                | S\$0.00                |
| Repairer:                   | Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174 |                        |                        |
| Handling Insurer:           | China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jason Tea - 63896171]                           |                        |                        |
| Adjuster:                   | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH] ... [Final Rpt due 27/03/2017]                     |                        |                        |
| Adj Asg. Remarks:           | TO SURVEY TP VEHICLE AND VERIFY DAMAGE CONSISTENCY, WE CAN AGREE TO DIRECT SETTLEMENT IF ALL IN ORDER.                              |                        |                        |

ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.

ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

| Due Date    | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
|-------------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|
| No results. |          |      |            |         |         |             |              |            |       |

## Claim Documents

**\*SKN3330Z (SNM17D01539C02/4)**  
**[YN8294X]**

TP

**JENNIFER HO CHUEY FOONG**

**Mar 13 2017 12:00AM**

**[WINDOW WORLD PTE LTD]**

**Performance Motors Limited**

| <a href="#">Upload Documents</a> |                 | <a href="#">Upload Photos</a>                      | <a href="#">Compose New Letter</a> | <b>View</b> <a href="#">Use Viewer</a> |                                     |
|----------------------------------|-----------------|--|------------------------------------|--|-------------------------------------|
| Photos/Images                    |                 |  |                                    | 3 per page                             | <input checked="" type="checkbox"/> |
| No                               | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ)                  | Thumbnail                          | Print                                  |                                     |
| 1                                | 30/11/17 11:18  | General View                                       | Load JPG                           | <input checked="" type="checkbox"/>    |                                     |
| 2                                | 30/11/17 11:18  | General View                                       | Load JPG                           | <input checked="" type="checkbox"/>    |                                     |
| 3                                | 30/11/17 11:18  | General View                                       | Load JPG                           | <input checked="" type="checkbox"/>    |                                     |
| 4                                | 30/11/17 11:18  | General View                                       | Load JPG                           | <input checked="" type="checkbox"/>    |                                     |
| 5                                | 30/11/17 11:18  | General View                                       | Load JPG                           | <input checked="" type="checkbox"/>    |                                     |
| 6                                | 30/11/17 11:18  | General View                                       | Load JPG                           | <input checked="" type="checkbox"/>    |                                     |
| 7                                | 30/11/17 11:18  | General View                                       | Load JPG                           | <input checked="" type="checkbox"/>    |                                     |
| 8                                | 30/11/17 11:18  | General View                                       | Load JPG                           | <input checked="" type="checkbox"/>    |                                     |
| 9                                | 30/11/17 11:18  | General View                                       | Load JPG                           | <input checked="" type="checkbox"/>    |                                     |
| 10                               | 30/11/17 11:18  | General View                                       | Load JPG                           | <input checked="" type="checkbox"/>    |                                     |
| 11                               | 30/11/17 11:18  | General View                                       | Load JPG                           | <input checked="" type="checkbox"/>    |                                     |
| 12                               | 30/11/17 11:18  | General View                                       | Load JPG                           | <input checked="" type="checkbox"/>    |                                     |
| 13                               | 30/11/17 11:18  | General View                                       | Load JPG                           | <input checked="" type="checkbox"/>    |                                     |
| 14                               | 30/11/17 11:18  | General View                                       | Load JPG                           | <input checked="" type="checkbox"/>    |                                     |
| 15                               | 30/11/17 11:18  | General View                                       | Load JPG                           | <input checked="" type="checkbox"/>    |                                     |
| 16                               | 30/11/17 11:18  | General View                                       | Load JPG                           | <input checked="" type="checkbox"/>    |                                     |
| 17                               | 30/11/17 11:18  | General View                                       | Load JPG                           | <input checked="" type="checkbox"/>    |                                     |
| 18                               | 30/11/17 11:18  | General View                                       | Load JPG                           | <input checked="" type="checkbox"/>    |                                     |
| 19                               | 30/11/17 11:18  | General View                                       | Load JPG                           | <input checked="" type="checkbox"/>    |                                     |
| 20                               | 30/11/17 11:18  | General View                                       | Load JPG                           | <input checked="" type="checkbox"/>    |                                     |
| 21                               | 30/11/17 11:18  | Reinspection Photo                                 | Load JPG                           | <input checked="" type="checkbox"/>    |                                     |
| 22                               | 30/11/17 11:18  | Reinspection Photo                                 | Load JPG                           | <input checked="" type="checkbox"/>    |                                     |
| 23                               | 30/11/17 11:18  | Reinspection Photo                                 | Load JPG                           | <input checked="" type="checkbox"/>    |                                     |
| 24                               | 30/11/17 11:18  | Reinspection Photo                                 | Load JPG                           | <input checked="" type="checkbox"/>    |                                     |
| 25                               | 30/11/17 11:18  | Reinspection Photo                                 | Load JPG                           | <input checked="" type="checkbox"/>    |                                     |
| 26                               | 30/11/17 11:18  | Reinspection Photo                                 | Load JPG                           | <input checked="" type="checkbox"/>    |                                     |
| 27                               | 30/11/17 11:18  | Reinspection Photo                                 | Load JPG                           | <input checked="" type="checkbox"/>    |                                     |
| Documentation                    |                 |  |                                    | 1 per page                             | <input checked="" type="checkbox"/> |
| No                               | Finalized On    | China Taiping Insurance (Singapore) Pte. Ltd. (HQ) | Thumbnail                          | Print                                  |                                     |
| 1                                | 16/03/17 17:33  | OTHER - EMAIL                                      | Load PDF                           |  |                                     |
| 2                                | 16/03/17 17:33  | OTHER - ESTIMATE                                   | Load TIF                           |  |                                     |
| 3                                | 16/03/17 17:33  | OTHER - INSURED SAS                                | Load PDF                           |  |                                     |
| 4                                | 16/03/17 17:34  | OTHER - INSD SAS                                   | Load PDF                           |  |                                     |
| No                               | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ)                  | Thumbnail                          | Print                                  |                                     |
| 1                                | 12/12/17 11:01  | SUPPLEMENTARY                                      | Load PDF                           |  |                                     |

## Documents Checklist

|  |
|--|
| <a href="#">Reset</a> <a href="#">Save</a> <a href="#">Print</a>           |
| <b>DOCUMENTS CHECKLIST</b><br>There are no document checklists configured. |
| Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)                  |



Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

## LKK Auto Consultants Pte Ltd (Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT117005331/T1TBS2

Date: 12/12/2017

## REFERENCE

|                       |   |                      |                  |
|-----------------------|---|----------------------|------------------|
| Handling Insurer:     | China Taiping Insurance (Singapore) Pte. Ltd. | Policy No:           | DMCVSN3056541600 |
| Claimant Vehicle No : | SKN3330Z                                      | Insured Vehicle No : | YN8294X          |
| Date of Loss:         | 13/03/2017                                    | Nature of Claim:     | TP               |
|                       |   | Claim No:            | SNM17D01539C02/4 |

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

|                             |                              |             |                   |
|-----------------------------|------------------------------|-------------|-------------------|
| Reg No:                     | SKN3330Z                     | Engine No:  | 06178610N55B30A   |
| Make & Model:               | BMW 640I, 3.0 (A)            | Chassis No: | WBA6A02030DZ12020 |
| Reg. Date:                  | 23/04/2014 (Man. Year: 2013) | Odometer:   | 32959 km          |
| Colour:                     | Red                          |             |                   |
| Engine Capacity:            | 2979 cc                      |             |                   |
| Market Value/New Car Price: | N/A                          |             |                   |
| Sum Insured (S\$):          | Market Value/New Car Price   |             |                   |

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |      |                         |     |                          |     |
|--------------------------|------|-------------------------|-----|--------------------------|-----|
| General Condition:       | Good | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes  | Engine Modification:    | No  | Pre-accident Condition:  |     |

## CONDITION OF TYRES

|                   |               |                  |               |
|-------------------|---------------|------------------|---------------|
| Front Tyre Size:  | 275/30 R19    | Rear Tyre Size:  | 275/30 R19    |
| Front Left Side:  | Michelin 6 mm | Rear Left Side:  | Michelin 6 mm |
| Front Right Side: | Michelin 6 mm | Rear Right Side: | Michelin 6 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS                | Repairer's       | Adjuster's       | Difference      | Diff %      |
|-------------------------------|------------------|------------------|-----------------|-------------|
| Parts                         | 7,523.80         | 6,904.65         | 619.15          | 8.23        |
| Miscellaneous Items           | 0.00             | 0.00             | 0.00            |             |
| Labour                        | 14,827.00        | 13,290.00        | 1,537.00        | 10.37       |
| Paintwork Labour              | 0.00             | 0.00             | 0.00            |             |
| Towing                        | 0.00             | 0.00             | 0.00            |             |
| <b>Gross Total (S\$)</b>      | <b>22,350.80</b> | <b>20,194.65</b> | <b>2,156.15</b> | <b>9.65</b> |
| <b>+ GST 7.00/7.00% (S\$)</b> | <b>1,564.56</b>  | <b>1,413.63</b>  | <b>150.93</b>   | <b>9.65</b> |
| <b>Nett Amount (S\$)</b>      | <b>23,915.36</b> | <b>21,608.28</b> | <b>2,307.08</b> | <b>9.65</b> |

## INSPECTION

Date of Assignment: 16/03/2017

Date Inspected: 05/04/2017 Inspected At:

Performance Motors Limited  
(Alexandra)  
303 Alexandra Road, Sime Darby  
Performance Centre  
Singapore 159941

Estimated Period of Repair: 14.0 days

Adjuster: MOHD TAUFIKH

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

## Reference

|  |  |
|--|--|
| <b>Part Source:</b> MRM-SG                                   | Version: 1.0 (Last Synchronised: 12 Dec 2017)  |
| <b>Parts:</b> 143  | BMW 640I 3.0 (A) (Catalogue:Merimen Singapore 1.0)   |
| <b>Labour:</b> Repairer's                                    | (Price-denominated Standard List)  |
| <b>Print Code:</b> (Unsubmitted, no print-code for SKN3330Z) |  |
| <b>Validity:</b>   | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |
| <b>Further Info:</b>   | Items/values not in reference catalogue are prefixed with an asterisk *.   |

## Recommended Parts

| No. | Qty | Part No. Particulars                    | Condition     | Repairer's  | Amount       |
|-----|-----|---|---------------|-------------|--------------|
| 1   | 6   | *PLASTIC NUT FOR COARSE THREADED PIN    | Necessary     | 4.80 FS     | *4.80 FS     |
| 2   | 1   | *REAR LH SIDE PANEL                     | Dented        | 2,379.90 FS | *2,379.90 FS |
| 3   | 1   | *PLATE                                  | Not Necessary | 48.00 FS    | *- FS        |
| 4   | 1   | *PLATE                                  | Not Necessary | 48.00 FS    | *- FS        |
| 5   | 1   | *MOUNT REAR LEFT                        | Not Necessary | 141.65 FS   | *- FS        |
| 6   | 1   | *RR BUMPER (PDC)                        | Deformed      | 1,811.40 FS | *1,811.40 FS |
| 7   | 4   | *PLASTIC NUT                            | Necessary     | 3.40 FS     | *3.40 FS     |
| 8   | 1   | *REAR W/SCREEN                          | Necessary     | 1,053.80 FS | *1,053.80 FS |
| 9   | 10  | *BUMP STOP                              | Necessary     | 32.50 FS    | *32.50 FS    |
| 10  | 1   | *REAR LIGHT IN THE SIDE PANEL LH        | Cracked       | 611.80 FS   | *611.80 FS   |
| 11  | 4   | *DECOUPLING RING PDC TORQUE CONVERTE    | Necessary     | 19.80 FS    | *19.80 FS    |
| 12  | 1   | *ULTRASCHALLW                           | Not Necessary | 363.05 FS   | *- FS        |
| 13  | 1   | *CAVITY PROTECTION WAX REMOVER 500ML    | Not Necessary | 18.45 FS    | *- FS        |
| 14  | 1   | *BLIND RIVET AVIBVLB                    | Necessary     | 11.00 FS    | *11.00 FS    |
|     |     | 17pcs                                   |               |             |              |
| 15  | 1   | *SCREW (SF PLUS M5X15)                  | Necessary     | 5.50 FS     | *5.50 FS     |
|     |     | 3pcs                                    |               |             |              |
| 16  | 1   | *(DG/SL) BODY ADHESIVE K5B (195ML)      | Necessary     | 281.55 FS   | *281.55 FS   |
| 17  | 1   | *PUNCH RIVET N5                         | Necessary     | 11.00 FS    | *11.00 FS    |
|     |     | 14pcs                                   |               |             |              |
| 18  | 1   | *PUNCH RIVET N4                         | Necessary     | 11.00 FS    | *11.00 FS    |
|     |     | 18pcs                                   |               |             |              |
| 19  | 1   | *(DG) BODYWORK ADHESIVE K5A (50ML)      | Necessary     | 118.35 FS   | *118.35 FS   |
| 20  | 1   | *(DG) CLEANER R1 (100ML) }              | Necessary     | 23.85 FS    | *47.70 FS    |
| 21  | 1   | *(DG) CLEANER R1 (100ML) }              |               | 23.85 FS    | *- FS        |
| 22  | 2   | *(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR) | Necessary     | 263.10 FS   | *263.10 FS   |
| 23  | 1   | *(DG/SL) GLASS PRIMER 30ML (VP206)      | Necessary     | 27.85 FS    | *27.85 FS    |
| 24  | 1   | *(S/L) SEAM SEAL 300ML                  | Necessary     | 33.80 FS    | *33.80 FS    |
| 25  | 1   | *SUNDRIES                               | Necessary     | 150.00 FS   | *150.00 FS   |
| 26  | 2   | *EXPANDING NUT                          | Necessary     | 2.20 FS     | *2.20 FS     |
| 27  | 10  | *W/SCREEN RUBBER BUFFER                 | Necessary     | 16.00 FS    | *16.00 FS    |
| 28  | 2   | *SNAP LOCKING COUPLING                  | Necessary     | 1.80 FS     | *1.80 FS     |
| 29  | 4   | *CLIP, BOTTOM PART                      | Necessary     | 6.40 FS     | *6.40 FS     |

F=Franchise part. S=SpcNett.

|                           |                 |                 |
|---------------------------|-----------------|-----------------|
| <b>Total Parts (\$\$)</b> | <b>7,523.80</b> | <b>6,904.65</b> |
|---------------------------|-----------------|-----------------|

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                              | Particulars  | Lab.Type | Repairer's       | Amount           |
|---------------------------------|--|----------|------------------|------------------|
| <b>Labour Items</b>             |  |          |                  |                  |
| 1                               | TO REPLACE REAR LEFT FENDER, BUMPER AND ATTACHMENTS INCLUDING KNOCK OUT DENT AREA CAUSE BY ACCIDENT.   | New      | 6,800.00         | 5,950.00         |
| 2                               | PAINTING REAR LEFT FENDER, BUMPER, TAIL, PANEL, TRUNK FLOOR, ROOF FRAME AND C PILLAR.  | New      | 4,093.00         | 3,684.00         |
| 3                               | TO REPLACE REAR WINDSCREEN INCLUDING TO CONDUCT WATER LEAK TEST.   | New      | 649.00           | 649.00           |
| 4                               | TO INSTALL REAR WINDSCREEN 3M SOLAR FILM.  | New      | 531.00           | 531.00           |
| 5                               | TO REMOVE AND INSTALL REAR HAT HAT-TRAY, REAR SEAT, CARPET AND ROOF TOP LINING TO FACILITATE THE CUTTING OF THE REAR FENDER.                   | New      | 873.00           | 742.00           |
| 6                               | TO REMOVE AND INSTALL REAR BOOT COMPARTMENT CARPET AND GARNISH TO FACILITATE REPAIRS.  | New      | 271.00           | 231.00           |
| 7                               | TO RECONNECT ELECTRICAL COMPONENTS AND WIRINGS AT THE REAR SECTION INCLUDE CONDUCTING CHECKS FOR PROPER FUNCTION. (REMARKS: FOR CUTTING PANEL) | New      | 451.00           | 451.00           |
| 8                               | TO REMOVE OLD PDC ASSEMBLY, REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDE CONDUCTING CHECKS FOR PROPER FUNCTION.                   | New      | 177.00           | 150.00           |
| 9                               | TO CARRY OUT BODY CAVITY PRESERVATION.   | New      | 531.00           | 451.00           |
| 10                              | TO REMOVE AND INSTALL FUSE BOX AT THE REAR SECTION TO FACILITATE REPAIRS.  | New      | 451.00           | 451.00           |
| <b>Gross Labour Cost (\$\$)</b> |  |          | <b>14,827.00</b> | <b>13,290.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >