



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC6/AXA17008873/Kpa3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811
ATTN:STACEY

Date : 16-09-2020



Code : AXA2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJG 227H	Veh. Inspected	SDU 6118Y
Policy No.	P0546387	Coverage (\$)	0.00
Claim No.	C0300867	Excess (\$)	0.00
Assign From		Assign Date	02/03/2014

2. Vehicle Particulars & Condition

Make & Model	VOLKSWAGEN JETTA	c.c	1390
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	WVWZZZ1KZ9U020100	Colour	WHITE
Odometer	30692	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/55 R16	LASSA	8 mm
L/H Front Tyre	205/55 R16	LASSA	8 mm
R/H Rear Tyre	205/55 R16	LASSA	8 mm
L/H Rear Tyre	205/55 R16	LASSA	8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	21/02/2014	Inspection Date	02/03/2014
Survey held at	K KIM HIN AUTOMOTIVE PTE LTD BLK 34 SIN MING DRIVE, #01-114, SINGAPORE 575708		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------