

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AXA17008968/DPA3Q2

Date: 23/06/2020

REFERENCE

Handling Insurer: AXA Insurance Pte Ltd

Policy No:

GA162058

Claimant

Vehicle No : SKR4264D

Insured Vehicle No :

SJD3266R

Date of Loss: 04/05/2017

Nature of Claim:

TP

Claim No: C0432746

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKR4264D**

Make & Model: VOLKSWAGEN SCIROCCO, 1.4 TSI (A)

Engine No: CAV150067

Reg. Date: 11/05/2010 (Man. Year: 2010)

Chassis No: WVWZZZ13ZAV427979

Colour: White

Odometer: 141563 km

Engine Capacity: 1390 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/40R18

Rear Tyre Size:

235/40R18

Front Left Side: Pirelli 5 mm

Rear Left Side:

Pirelli 5 mm

Front Right Side: Pirelli 5 mm

Rear Right Side:

Pirelli 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	97,951.39	33,568.15	64,383.24	65.73
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,140.00	3,900.00	7,240.00	64.99
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	109,091.39	37,468.15	71,623.24	65.65
Approved Total (Overridden) (S\$)		30,000.00		
(S\$)	109,091.39	30,000.00	79,091.39	72.50
+ GST 7.00/7.00% (S\$)	7,636.40	2,100.00	5,536.40	72.50
Nett Amount (S\$)	116,727.79	32,100.00	84,627.79	72.50
+ Car Rental (25.0 x S\$100.00/day) (S\$)		2,500.00		
Nett Liability (S\$)		34,600.00		
Global Sum Settlement (S\$)		32,460.00		

INSPECTION

Date of Assignment: 08/05/2017

Date Inspected: 08/05/2017 Inspected At:

Teamwork Garage Pte Ltd (HQ)

53 Ubi Ave 1 #01-24, Paya Ubi

Industrial Park

Singapore 408934

Estimated Period of Repair: 20.0 days

Adjuster: BRYAN TANI**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 29 Nov 2019)
Parts:	144	VOLKSWAGEN SCIROCCO 1.4 TSI (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKR4264D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER (CONSISTENT)	Buckled	1,575.07 FL	*1,122.30 FL
2	1		*REAR BUMPER REFLECTOR (CONSISTENT)	N/S Broken /O/S Not Necessary	167.24 FL	*83.62 FL
3	2		*REAR BUMPER NUMBER PLATE LAMP (CONSISTENT)	Not Necessary	69.20 FL	*- FL
4	4		*REAR REVERSE SENSOR (CONSISTENT)	Damaged	1,017.09 FS	*350.00 FS
5	1		*REAR BUMPER REINFORCEMENT (CONSISTENT)	Dented	711.05 FL	*632.30 FL
6	2		*REAR BUMPER SIDE BRACKET (CONSISTENT)	Serviceable	121.40 FL	*- FL
7	1		*FRONT BUMPER BRACKET (CONSISTENT)	Serviceable	115.40 FL	*- FL
8	1		*REAR EXHAUST ASSY (CONSISTENT)	Dented	2,100.18 FL	*1,458.30 FL
9	1		*REAR EXHAUST HEAT SHIELD (CONSISTENT)	Serviceable	154.03 FL	*- FL
10	2		*REAR EXHAUST MOUNTING (CONSISTENT)	Serviceable	30.00 FL	*- FL
11	1		*END PANEL (CONSISTENT)	Dented	1,826.45 FL	*930.20 FL
12	1		*END PANEL GARNISH (CONSISTENT)	Bent	265.70 FL	*265.70 FL
13	1		*REAR FLOOR PANEL (CONSISTENT)	Repair	1,276.96 FL	*- FL
14	1		*REAR FLOOR PANEL TOP COVER (CONSISTENT)	Serviceable	389.98 FL	*- FL
15	1		*REAR RH FENDER (CONSISTENT)	Not Necessary	2,039.03 FL	*- FL
16	1		*REAR LH FENDER (CONSISTENT)	Not Necessary	2,039.03 FL	*- FL
17	2		*REAR FENDER INNER TRIM (CONSISTENT)	Not Necessary	439.88 FL	*- FL
18	1		*REAR LH QUARTER GLASS WITH MOULDING (CONSISTENT)	Not Necessary	608.05 FL	*- FL
19	1		*REAR RH QUARTER GLASS WITH MOULDING (CONSISTENT)	Not Necessary	608.05 FL	*- FL
20	1		*REAR TAILGATE (CONSISTENT)	Dented	2,220.38 FL	*1,607.00 FL
21	1		*TAILGATE LOGO (CONSISTENT)	Necessary	105.46 FL	*105.46 FL
22	1		*TAILGATE WEATHERSTRIP (CONSISTENT)	Deformed	378.20 FL	*378.20 FL
23	1		*REAR TAILGATE INNER TRIM BOARD LOWER (CONSISTENT)	Not Necessary	284.22 FL	*- FL
24	1		*REAR TAILGATE GLASS WITH MOULDING (CONSISTENT)	Non original	928.97 FL	*- FL
25	1		*REAR WIPER MOTOR (CONSISTENT)	Not Necessary	571.55 FL	*- FL
26	1		*REAR WIPER BLADE (CONSISTENT)	Not Necessary	74.60 FL	*- FL
27	1		*REAR WIPER ARM (CONSISTENT)	Not Necessary	93.50 FL	*- FL
28	1		*REAR TAILGATE LOCK (CONSISTENT)	Damaged	278.05 FL	*278.05 FL
29	1		*REAR LOCK CATCH (CONSISTENT)	Repair	98.47 FL	*- FL
30	2			Not Necessary	60.80 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
			*REAR TAILGATE RUBBER STOPPER (CONSISTENT)			
31	2		*REAR TAILGATE DAMPER (CONSISTENT)	Not Necessary	283.86 FL	*- FL
32	2		*REAR TAILGATE HINGE (CONSISTENT)	Not Necessary	247.94 FL	*- FL
33	2		*REAR TAILLAMP (CONSISTENT)	Cracked	869.10 FL	*869.10 FL
34	1		*FRONT BUMPER (CONSISTENT)	Torn	1,575.30 FL	*1,298.85 FL
35	2		*FRONT BUMPER FOG LAMP (CONSISTENT)	Not Necessary	450.68 FL	*- FL
36	1		*FRONT FOG LAMP GARNISH (CONSISTENT)	O/S MtgBroken/N/SNot Necessary	378.92 FL	*189.46 FL
37	2		*FRONT SIDE LAMP (CONSISTENT)	Not Necessary	288.58 FL	*- FL
38	1		*FRONT BUMPER LOWER GRILLE (CONSISTENT)	Serviceable	362.85 FL	*- FL
39	1		*FRONT BUMPER TOW COVER (CONSISTENT)	Not Necessary	40.25 FL	*- FL
40	1		*FRONT BUMPER RETAINER (CONSISTENT)	O/S Broken / N/S Not Necessary	70.40 FL	*35.20 FL
41	1		*FRONT BUMPER REINFORCEMENT (CONSISTENT)	Bent	760.26 FL	*661.10 FL
42	1		*FRONT GRILLE ASSY (CONSISTENT)	Broken	632.38 FL	*632.38 FL
43	1		*FRONT LH FENDER (CONSISTENT)	Not Necessary	739.63 FL	*- FL
44	1		*FRONT RH FENDER (CONSISTENT)	Dented	739.63 FL	*739.63 FL
45	1		*FRONT LH FENDER INNER SHIELD (CONSISTENT)	Not Necessary	115.40 FL	*- FL
46	1		*FRONT RH FENDER INNER SHIELD (CONSISTENT)	Not Necessary	115.40 FL	*- FL
47	1		*FRONT LH HEADLAMP (CONSISTENT)	Cracked	1,706.37 FL	*1,706.37 FL
48	1		*FRONT LH HEADLAMP CONTROL UNIT (CONSISTENT)	Damaged	1,209.40 FL	*1,209.40 FL
49	1		*FRONT RH HEADLAMP (CONSISTENT)	Broken / Distorted	1,706.37 FL	*1,706.37 FL
50	1		*FRONT RH HEADLAMP CONTROL UNIT (CONSISTENT)	Broken / Distorted	1,209.40 FL	*1,209.40 FL
51	1		*FRONT LH HEADLAMP TOP PANEL (CONSISTENT)	Bent	120.77 FL	*120.77 FL
52	1		*FRONT RH HEADLAMP TOP PANEL (CONSISTENT)	Bent	120.77 FL	*120.77 FL
53	1		*FRONT SUPPORT PANEL (CONSISTENT)	Bent	1,311.54 FL	*1,140.45 FL
54	1		*FRONT SUPPORT PANEL TOP GARNISH (CONSISTENT)	Broken	234.75 FL	*234.75 FL
55	1		*AIR DUCT ASSY (CONSISTENT)	Broken	185.00 FL	*185.00 FL
56	1		*INTERCOOLER (CONSISTENT)	Punctured	1,037.57 FL	*1,037.57 FL
57	1		*RADIATOR (CONSISTENT)	Punctured	918.10 FL	*918.10 FL
58	1		*AIRCON CONDENSER (CONSISTENT)	Punctured	831.32 FL	*831.32 FL
59	1		*AIRCON LOW PRESSURE PIPE (CONSISTENT)	Bent	929.74 FL	*929.74 FL
60	1		*AIRCON CONDENSER SIDE GARNISH (CONSISTENT)	Broken	84.72 FL	*84.72 FL
61	1		*ELECTRIC FAN (BIG) WITH MOTOR (CONSISTENT)	Damaged	644.30 FL	*644.30 FL
62	1		*ELECTRIC FAN (SMALL) WITH MOTOR (CONSISTENT)	Damaged	744.14 FL	*744.14 FL
63	1		*ELECTRIC FAN COWLING (CONSISTENT)	Damaged / Broken	311.03 FL	*311.03 FL
64	1		*FRONT BONNET (CONSISTENT)	Buckled	1,399.54 FL	*1,199.55 FL
65	1		*FRONT BONNET LOGO (CONSISTENT)	Necessary	131.05 FL	*131.05 FL
66	2		*FRONT BONNET HINGE (CONSISTENT)	Bent	193.90 FL	*193.90 FL
67	1		*FRONT BONNET LOCK (CONSISTENT)	Damaged	204.97 FL	*204.97 FL
68	1		*FRONT BONNET INSULATOR (CONSISTENT)	Bent	388.75 FL	*388.75 FL
69	1		*FRONT BONNET LOCK CATCH (CONSISTENT)	Not Necessary	104.60 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
70	1		*AIRBAG CONTROL UNIT (CONSISTENT)	Not Necessary	1,772.20 FL	*- FL
71	1		*FRONT DRIVER AIRBAG (CONSISTENT)	Not Necessary	4,190.40 FL	*- FL
72	1		*FRONT PASSENGER AIRBAG (CONSISTENT)	Not Necessary	3,980.45 FL	*- FL
73	1		*CRASH SENSOR (CONSISTENT)	Not Necessary	904.40 FL	*- FL
74	1		*FRONT LH SEAT BELT (CONSISTENT)	Not Necessary	860.50 FL	*- FL
75	1		*FRONT RH SEAT BELT (CONSISTENT)	Not Necessary	860.65 FL	*- FL
76	1		*DASHBOARD ASSY (CONSISTENT)	Not Necessary	4,490.05 FL	*- FL
77	1		*FRONT WINDSCREEN (CONSISTENT)	Not Necessary	1,043.50 FL	*- FL
78	2		*FRONT WHEELHOUSE (CONSISTENT)	Not Necessary	1,904.56 FL	*- FL
79	1		*COVER INTAKE MANIFOLD (CONSISTENT)	Not Necessary	290.40 FL	*- FL
80	1		*GUIDE FUNNEL (CONSISTENT)	Not Necessary	90.30 FL	*- FL
81	1		*VENT HOSE (CONSISTENT)	Not Necessary	110.40 FL	*- FL
82	1		*CONNECTING HOSE (CONSISTENT)	Not Necessary	139.43 FL	*- FL
83	1		*CONTROL LINE (CONSISTENT)	Not Necessary	119.30 FL	*- FL
84	1		*CYLINDER HEAD COVER (CONSISTENT)	Not Necessary	372.10 FL	*- FL
85	1		*OIL DIPSTICKER (CONSISTENT)	Not Necessary	55.20 FL	*- FL
86	1		*COOLANT PUMP (CONSISTENT)	Not Necessary	1,093.10 FL	*- FL
87	1		*OILCOOLER (CONSISTENT)	Not Necessary	917.34 FL	*- FL
88	1		*EXHAUST GAS TURBO CHARGER (CONSISTENT)	Not Necessary	1,540.40 FL	*- FL
89	1		*COOLER HOUSING (CONSISTENT)	Not Necessary	900.20 FL	*- FL
90	1		*INTAKE MANIFOLD (CONSISTENT)	Not Necessary	1,375.30 FL	*- FL
91	1		*RESERVOIR WIPER (CONSISTENT)	Deformed	117.32 FL	*117.32 FL
92	1		*COOLANT HOSE UPPER (CONSISTENT)	Not Necessary	90.30 FL	*- FL
93	1		*COOLANT HOSE LOWER (CONSISTENT)	Not Necessary	73.57 FL	*- FL
94	1		*GEAR OIL COOLER (CONSISTENT)	Not Necessary	901.45 FL	*- FL
95	1		*COOLANT PIPE (CONSISTENT)	Not Necessary	110.54 FL	*- FL
96	1		*COOLANT EXPANSION TANK (CONSISTENT)	Not Necessary	291.40 FL	*- FL
97	1		*PREESRE PIPE (CONSISTENT)	Not Necessary	310.40 FL	*- FL
98	1		*ENGINE MOUNTING RH (CONSISTENT)	Bent	495.60 FL	*495.60 FL
99	1		*GEARBOX MOUNTING LH (CONSISTENT)	Bent	590.20 FL	*590.20 FL
100	1		*TRIM FOR BATTERY LH (CONSISTENT)	Not Necessary	110.00 FL	*- FL
101	1		*TRIM FOR BATTERY RH (CONSISTENT)	Not Necessary	110.00 FL	*- FL
102	1		*BATERY CONSOLE (CONSISTENT)	Not Necessary	114.50 FL	*- FL
103	1		*BATERY INSULATOR (CONSISTENT)	Not Necessary	90.00 FL	*- FL
104	1		*BATERY BRACKET (CONSISTENT)	Not Necessary	119.00 FL	*- FL
105	1		*ECU CONTROL UNIT (CONSISTENT)	Not Necessary	5,120.40 FL	*- FL
106	1		*CONTOL UNIT BRACKET (CONSISTENT)	Not Necessary	220.50 FL	*- FL
107	1		*AIR DUCT UPPER (CONSISTENT)	Not Necessary	140.54 FL	*- FL
108	1		*AIR DUCT LOWER (CONSISTENT)	Not Necessary	159.30 FL	*- FL
109	1		*FRONT NUMBER PLATE (CONSISTENT)	Broken	80.00 FS	*45.00 FS
110	1		*SET FRONT BUMPER CLIP (CONSISTENT)	Necessary	30.00 FS	*20.00 FS
111	1		*SET FRONT FENDER INNER SHIELD CLIP (CONSISTENT)	Not Necessary	30.00 FS	*- FS
112	1		*REAR NUMBER PLATE (CONSISTENT)	Bent	80.00 FS	*45.00 FS
113	1		*SET REAR BUMPER CLIP (CONSISTENT)	Necessary	30.00 FS	*20.00 FS
114	1		*SET REAR FENDER INNER TRIM CLIP (CONSISTENT)	Not Necessary	20.00 FS	*- FS
115	1		*SET REAR TAILGATE INNER TRIM CLIP (CONSISTENT)	Not Necessary	20.00 FS	*- FS
116	1		*JOINT SEALANT (CONSISTENT)	Necessary	150.00 FS	*40.00 FS
117	1		*WINDSCREEN SEALANT (CONSISTENT)	Necessary	150.00 FS	*40.00 FS
118	1		*BOT COOLANT (CONSISTENT)	Necessary	60.00 FS	*40.00 FS
119	1		*GEARBOX (CONSISTENT)	Housing Broken	25,000.00 FS	*8,000.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
F=Franchise part. S=SpcNett. L=ListItemDisc.						
					Sub Total (S\$)	105,871.87
					- List Item Discount on L Items 10.00/10.00% (S\$)	7,920.48
						36,342.39
						2,774.24
					Total Parts (S\$)	97,951.39
						33,568.15

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	CHECK FRONT ,REAR WIRING AND LIGHTING SYSTEM	New	90.00	30.00
2	REMOVE,RENEW CONDENSER AND TOP UP GAS	New	200.00	120.00
3	REMOVE,RENEW RADIATOR AND TOP UP COOLANT	New	200.00	50.00
4	REMOVE AND RENEW FRONT DASHBOARD	New	500.00	0.00
5	DIAGNOIS CHECK AND CLEAR FAULT CODE (GEARBOX)	New	500.00	250.00
6	REMOVE,RENEW AIRBAG ASSY AND CLEAR FAULT CODE	New	500.00	0.00
7	REMOVE AND RENEW REAR REVERSE SENSOR	New	150.00	60.00
8	REMOVE,REFIT REAR LINING ,TRIM AND GARNISH	New	200.00	120.00
9	REMOVE AND RENEW REAR EXHAUST ASSY	New	150.00	60.00
10	REMOVE AND REFIT FUEL TANK	New	150.00	0.00
11	REMOVE AND RENEW REAR WINDSCREEN	New	150.00	120.00
12	TRANSFER PARTS ,ATTACHMENT FROM OLD TAILGATE TO NEW	New	200.00	60.00
13	PANEL BEATING ON AFFECTED AREAS	New	4,500.00	1,400.00
14	SPRAY PAINTING ON AFFECTED AREAS	New	2,800.00	1,200.00
15	APPLY ANTI RUST ON AFFECTED AREAS	New	200.00	80.00
16	TOWING SERVICE	New	150.00	0.00
17	REMOVE AND RENEW TRANSMISSION OIL & ASSY	New	500.00	350.00
Gross Labour Cost (\$\$)			11,140.00	3,900.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >