



TeamWork Garage Pte Ltd
53 Ubi Avenue 1 #01-23/24 Spore 408934
Paya Ubi Industrial Park
Tel : 6844 2475
E-mail : claims@teamworkgarage.com
ROC: 201015366H

AXA Insurance
8 Shenton Way
#24-01 AXA Tower
Singapore 068811

3RD PARTY CLAIM ESTIMATION

Vehicle number	SKR4264D
Make / Model	VOLKSWAGEN / SCIROCCO
Chassis number	WVWZZZ13ZAV427979
Accident date	04 May 2017
Reference	

Qty	Particulars	Unit Price - SGD \$	
<u>PARTS REPLACEMENT - LIST ITEMS</u>			
1	REAR BUMPER <i>Bnc</i>	1575.07 ✓	1122.30
2	REAR BUMPER REFLECTOR <i>N/S broken (dislodged) O/S NH</i>	167.24 ✓	83.62
2	REAR BUMPER NUMBER PLATE LAMP <i>NH</i>	69.20 X	
4	REAR REVERSE SENSOR <i>Down</i>	1130.10 ✓	350 SH
1	REAR BUMPER REINFORCEMENT <i>Dental</i>	711.05 ✓	632.30
2	REAR BUMPER SIDE BRACKET <i>SVC</i>	121.40 X	
1	REAR BUMPER BRACKET <i>SVC</i>	115.40 X	
1	REAR EXHAUST ASSY <i>Dental</i>	2100.18 ✓	1458.30
1	REAR EXHAUST HEAT SHIELD <i>SVC</i>	154.03 X	
2	REAR EXHAUST MOUNTING <i>SVC</i>	30.00 X	
1	END PANEL <i>Dental</i>	1826.45 ✓	930.20
1	END PANEL GARNISH <i>Wt</i>	265.70 ✓	
1	REAR FLOOR PANEL <i>renu</i>	1276.96 X	
1	REAR FLOOR PANEL TOP COVER <i>SVC</i>	389.98 X	
1	REAR RH FENDER <i>NH</i>	2039.03 X	
1	REAR LH FENDER <i>NH</i>	2039.03 X	
2	REAR FENDER INNER TRIM <i>NH</i>	439.88 X	
1	REAR LH QUARTER GLASS WITH MOULDING <i>NH</i>	608.05 X	
1	REAR RH QUARTER GLASS WITH MOULDING <i>NH</i>	608.05 X	
1	REAR TAILGATE <i>Dental</i>	2220.38 ✓	1607.00
1	TAILGATE LOGO <i>Hec</i>	105.46 ✓	
1	TAILGATE WEATHERSTRIP <i>deformed</i>	378.20 ✓	
1	REAR TAILGATE INNER TRIM BOARD LOWER <i>NH</i>	284.22 X	
1	REAR TAILGATE GLASS WITH MOULDING <i>NH</i>	928.97 X	
1	REAR WIPER MOTOR <i>NH</i>	571.55 X	
1	REAR WIPER BLADE <i>NH</i>	74.60 X	
1	REAR WIPER ARM <i>NH</i>	93.50 X	
1	REAR TAILGATE LOCK <i>Down</i>	278.05 ✓	
1	REAR LOCK CATCH <i>renu</i>	98.47 X	
2	REAR TAILGATE RUBBER STOPPER <i>NH</i>	60.80 X	
2	REAR TAILGATE DAMPER <i>NH</i>	283.86 X	
2	REAR TAILGATE HINGE <i>NH</i>	247.94 X	
2	REAR TAILLAMP <i>crack</i>	869.10 ✓	
1	FRONT BUMPER <i>torn</i>	1575.30 ✓	1298.85
2	FRONT BUMPER FOG LAMP <i>NH</i>	450.68 X	

9029.08

2	FRONT FOG LAMP GARNISH o/s windy broken N/S NH	378.92	✓	189.46
2	FRONT SIDE LAMP NH	288.58	X	
1	FRONT BUMPER LOWER GRILLE S/L	362.85	X	
1	FRONT BUMPER TOW COVER NH	40.25	X	
2	FRONT BUMPER RETAINER o/s broken N/S NH	70.40	✓	35.20
1	FRONT BUMPER REINFORCEMENT St	760.26	✓	661.10
1	FRONT GRILLE ASSY broken	632.38	✓	
1	FRONT LH FENDER NH	739.63	X	
1	FRONT RH FENDER Dented	739.63	✓	
1	FRONT LH FENDER INNER SHIELD NH	115.40	X	
1	FRONT RH FENDER INNER SHIELD NH	115.40	X	
1	FRONT LH HEADLAMP crack	1706.37	✓	
1	FRONT LH HEADLAMP CONTROL UNIT Done	1209.40	✓	
1	FRONT RH HEADLAMP broken / dislodged	1706.37	✓	
1	FRONT RH HEADLAMP CONTROL UNIT broken / dislodged	1209.40	✓	
1	FRONT LH HEADLAMP TOP PANEL St	120.77	✓	
1	FRONT RH HEADLAMP TOP PANEL St	120.77	✓	
1	FRONT SUPPORT PANEL St	1344.54	✓	1140.45
1	FRONT SUPPORT PANEL TOP GARNISH broken	234.75	✓	
1	AIR DUCT ASSY broken	185.00	✓	
1	INTERCOOLER punctured	1037.57	✓	
1	RADIATOR punctured	918.10	✓	
1	AIRCON CONDENSER punctured	831.32	✓	
1	AIRCON LOW PRESSURE PIPE St	929.74	✓	
1	AIRCON CONDENSER SIDE GARNISH broken	84.72	✓	
1	ELECTRIC FAN (BIG) WITH MOTOR Done	644.30	✓	
1	ELECTRIC FAN (SMALL) WITH MOTOR Done	744.14	✓	
1	ELECTRIC FAN COWLING Done / broken	311.03	✓	
1	FRONT BONNET Bnc	1399.54	✓	1199.55
1	FRONT BONNET LOGO Hcl	131.05	✓	
2	FRONT BONNET HINGE St	193.90	✓	
1	FRONT BONNET LOCK Done	204.97	✓	
1	FRONT BONNET INSULATOR St	388.75	✓	
1	FRONT BONNET LOCK CATCH NH	104.60	X	
1	AIRBAG CONTROL UNIT NH	1772.20	X	
1	FRONT DRIVER AIRBAG NH	4190.40	X	
1	FRONT PASSENGER AIRBAG NH	3980.45	X	
1	CRASH SENSOR NH	904.40	X	
1	FRONT LH SEAT BELT NH	860.50	X	
1	FRONT RH SEAT BELT NH	860.65	X	
1	DAHBOARD ASSY NH	4490.05	X	
1	FRONT WINDSCREEN NH	1043.50	X	
2	FRONT WHEELHOUSE NH	1904.56	X	
1	COVER INTAKE MANIFOLD NH	290.40	X	
1	GUIDE FUNNEL NH	90.30	X	
1	VENT HOSE NH	110.40	X	
1	CONNECTING HOSE NH	139.43	X	
1	CONTROL LINE NH	119.30	X	
1	CYLINDER HEAD COVER NH	372.10	X	

17610.19

1	OIL DIPSTICKER <i>NH</i>	55.20	X
1	COOLANT PUMP <i>NH</i>	1093.10	X
1	OILCOOLER <i>NH</i>	917.34	X
1	EXHAUST GAS TURBO CHARGER <i>NH</i>	1540.40	X
1	COOLER HOUSING <i>NH</i>	900.20	X
1	INTAKE MANIFOLD <i>NH</i>	1375.30	X
1	RESERVOIR <i>wiper deformed</i>	117.32	✓
1	COOLANT HOSE UPPER <i>NH</i>	90.30	X
1	COOLANT HOSE LOWER <i>NH</i>	73.57	X
1	GEAR OIL COOLER <i>NH</i>	901.45	X
1	COOLANT PIPE <i>NH</i>	110.54	X
1	COOLANT EXPANSION TANK <i>NH</i>	291.40	X
1	PREESRE PIPE <i>NH</i>	310.40	X
1	ENGINE MOUNTING RH <i>✓</i>	495.60	✓
1	GEARBOX MOUNTING LH <i>✓</i>	590.20	✓
1	TRIM FOR BATTERY LH <i>NH</i>	110.00	X
1	TRIM FOR BATTERY RH <i>NH</i>	110.00	X
1	BATERY CONSOLE <i>NH</i>	114.50	X
1	BATERY INSULATOR <i>NH</i>	90.00	X
1	BATTERY BRACKET <i>NH</i>	119.00	X
1	ECU CONTROL UNIT <i>NH</i>	5120.40	✓
1	CONTOL UNIT BRACKET <i>NH</i>	220.50	X
1	AIR DUCT UPPER <i>NH</i>	140.54	X
1	AIR DUCT LOWER <i>NH</i>	159.30	X
		80334.88	
		8033.48	
		72301.40	
		72301.40	
1	FRONT NUMBER PLATE <i>broken</i>	80.00 45/-	
1 SET	FRONT BUMPER CLIP <i>Nec</i>	30.00 20/-	
1 SET	FRONT FENDER INNER SHIELD CLIP <i>NH</i>	30.00	X
1	REAR NUMBER PLATE <i>✓</i>	80.00 45/-	
1 SET	REAR BUMPER CLIP <i>Nec</i>	30.00 20/-	
1 SET	REAR FENDER INNER TIRM CLIP <i>NH</i>	20.00	X
1 SET	REA TAILGATE INNER TRIM CLIP <i>NH</i>	20.00	X
1	JOINT SEALANT <i>Nec</i>	150.00 40/-	
1	WINDSCREEN SEALANT <i>Nec</i>	150.00 40/-	
1 BOT	COOLANT <i>Nec</i>	60.00 40/-	
		400.00	
		72701.40	
		72701.40	
1	CHECK FRONT, REAR WIRING AND LIGHTNING SYSTEM	90.00 30/-	
2	REMOVE, RENEW CONDENSER AND TOP UP GAS	200.00 120/-	
3	REMOVE, RENEW RADIATOR AND TOP UP COOLANT	200.00 50/-	

1203.12

27842.39
25058.15

Less 10 %
Subtotal

PARTS REPLACEMENT - SPECIAL NETT ITEMS

Balance B/F

600.00

Subtotal

Balance C/F

LABOUR AND MISCELLANEOUS CHARGES

Balance B/F

4	REMOVE AND RENEW FRONT DSAHBOARD	500.00 NW
5	DIAGNOIS CHECK AND CLEAR FAULT CODE (gearbox)	500.00 250/-
6	REMOVE, RENEW AIRBAG ASSY AND CLEAR FAULT CODE	500.00 NW
7	REMOVE AND RENEW REAR REVERSE SENSOR	150.00 60/-
8	REMOVE, REFIT REAR LINING, TRIM AND GANRISH	200.00 120/-
9	REMOVE AND RENEW REAR EXHAUST ASSY	150.00 60/-
10	REMOVE AND REFIT FUEL TANK	150.00 NW
11	REMOVE AND RENEW REAR WINDSCREEN	150.00 120/-
12	TRANSFER PARTS, ATTACHMENT FROM OLD TAILGATE TO NEW	200.00 60/-
13	PANEL BEATING ON AFFECTED AREAS	4500.00 1400/-
14	SPRAY PAINTING ON AFFECTED AREAS	2800.00 1200/-
15	APPLY ANTI RUST ON AFFECTED AREAS	200.00 80/-
16	TOWING SERVICE	150.00 NW
Subtotal		10640.00
Grand total		83341.40

08/05/2017 @ 1145hr

N/A Antenna

2/Smr 20 days.

2KK Auto

(Signature)
ryan

(Signature)
Chris MV

29208.15

Supp 8350.00

37558.15

1/s 30000/-

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



TeamWork Garage Pte Ltd
53 Ubi Avenue 1 #01-23/24 Spore 408934
Paya Ubi Industrial Park
Tel : 6844 2475
E-mail : claims@teamworkgarage.com
ROC: 201015366H
SUPPLEMENTARY

AXA Insurance
8 Shenton Way
#24-01 AXA Tower
Singapore 068811

Vehicle number	SKR4264D
Make / Model	VOLKSWAGEN / SCIROCCO
Chassis number	WVWZZZ13ZAV427979
Accident date	04 May 2017
Reference	1705-16

Qty	Particulars	Unit Price - SGD \$
<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1	GEARBOX housing broken	25000.00 8000.00 SN
		25000.00
	Less 10 %	2500.00
	Subtotal	22500.00
<u>LABOUR AND MISCELLANEOUS CHARGES</u>		
1	REMOVE AND RENEW TRANSMISSION OIL & ASSY	500.00 350.00
	Subtotal	500.00
	Grand total	23000.00

8350.00



09/05/2017.

LKK Auto

