

You cannot authorize this offer because

**The claim amount exceeds your approval limit [S\$9,658.08 -> S\$8,000.00].
File to be authorized by your superior.**

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI17009296/GRBS2

Date: 08/01/2018

REFERENCE

Insured/Claimant:	KIRALY AUTOMOBILE PTE LTD	Policy No:	DMHCSN1713551700	Claim No:	SNM17D02751C01
Date of Loss:	08/05/2017	Nature of Claim:	OD		

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLL1466C	Engine No:	LEB5928532
Make & Model:	HONDA VEZEL, 1.5 HYBRID X (A)	Chassis No:	RU31228520
Reg. Date:	15/02/2017 (Man. Year: 2016)	Odometer:	13827 km
Colour:	Silver		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	S\$108,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,327.80	7,497.00	2,830.80	27.41
Miscellaneous Items	277.00	277.00	0.00	0.00
Labour	2,031.89	1,884.08	147.81	7.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,636.69	9,658.08	2,978.61	23.57
- Excess (S\$)	1,000.00	1,000.00	0.00	0.00
(S\$)	11,636.69	8,658.08	2,978.61	25.60
+ GST 7.00/7.00% (S\$)	814.57	606.07	208.50	25.60
Nett Amount (S\$)	12,451.26	9,264.15	3,187.11	25.60

INSPECTION

Date of Assignment:	12/05/2017	Present Location:	Car City Auto Centre Pte Ltd (HQ)
Date Inspected:	15/05/2017	Inspected At:	Car City Auto Centre Pte Ltd (HQ) Blk 9006 #01-198, Tampines Street 93 Singapore 528840
Estimated Period of Repair:	8.0 days		

Adjuster: XING GUO QIANG

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 08 Jan 2018)
Parts:	M1-SUV	HONDA VEZEL 1.5 HYBRID X (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLL1466C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1	NA	*BONNET (WCP)	Bent	430.00 F	*430.00 F
2	1	NA	*BONNET INSULATION (WCP)	Torn	85.00 F	*85.00 F
3	1	NA	*BONNET LOCK (WCP)	Bent	85.00 F	*85.00 F
4	1	NA	*COMPR/EVAP TUBE (WCP)	Not Necessary	160.00 F	*- F
5	1	NA	*COND/COMPRESSOR HOSE (WCP)	Not Necessary	160.00 F	*- F
6	1	NA	*COND/EVAPORATOR PIPE (WCP)	Not Necessary	130.00 F	*- F
7	1	NA	*CONDENSER (WCP)	Bent	380.00 F	*380.00 F
8	1	NA	*EXPANSION TANK (WCP)	Not Necessary	50.00 F	*- F
9	1	NA	*F/FENDER EMBLEM LH (WCP)	Necessary	28.00 F	*28.00 F
10	1	NA	*F/FENDER EMBLEM RH (WCP)	Necessary	28.00 F	*28.00 F
11	1	NA	*FILLER PIPE (WCP)	Not Necessary	50.00 F	*- F
12	1	NA	*FILLER TUBE HOSE (WCP)	Not Necessary	25.00 F	*- F
13	1	NA	*FILTER INLET HOSE (WCP)	Not Necessary	48.00 F	*- F
14	1	NA	*FILTER INTAKE PIPE (WCP)	Not Necessary	36.00 F	*- F
15	1	NA	*FRONT BUMPER (WCP)	Torn	530.00 F	*530.00 F
16	1	NA	*FRONT LOWER BUMPER (WCP)	Not Necessary	270.00 F	*- F
17	1	NA	*FRONT PANEL CPL (WCP)	Buckled	390.00 F	*390.00 F
18	1	NA	*FRT BUMPER CLAMP KIT 22pcs (WCP)	Necessary	44.00 F	*44.00 F
19	1	NA	*FRT BUMPER SUPPORT (WCP)	Bent	230.00 F	*230.00 F
20	1	NA	*FRT GRILL LOW CHROME (WCP)	Cracked	75.00 F	*75.00 F
21	1	NA	*FRT TOWING EYE COVER (WCP)	Not Necessary	18.00 F	*- F
22	1	NA	*GRILLE (WCP)	Cracked	320.00 F	*320.00 F
23	1	NA	*GRILLE BADGE (WCP)	Necessary	23.00 F	*23.00 F
24	1	NA	*L/BONNET HINGE (WCP)	Bent	42.00 F	*42.00 F
25	1	NA	*L/BONNET SEAL (WCP)	Necessary	28.00 F	*28.00 F
26	1	NA	*L/BONNET SEAL (WCP)	Necessary	21.00 F	*21.00 F
27	1	NA	*L/BUMPER CORNER BRKT (WCP)	Necessary	32.00 F	*32.00 F
28	1	NA	*L/COWL PANEL GRILLE (WCP)	Not Necessary	56.00 F	*- F
29	1	NA	*L/F AIR DUCT (WCP)	Not Necessary	28.00 F	*- F
30	1	NA	*L/F BONNET STOP (WCP)	Necessary	16.00 F	*16.00 F
31	1	NA	*L/F FOG LAMP (WCP)	Not Necessary	180.00 F	*- F
32	1	NA	*L/F HEADLAMP CPL (WCP)	Cracked	950.00 F	*950.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
33	1	NA	*L/F MOULDING (WCP)	Deformed	18.00 F	*18.00 F
34	1	NA	*L/F UPP BUMPER BRKT (WCP)	Cracked	18.00 F	*18.00 F
35	1	NA	*L/F WHEELHOUSE COVER (WCP)	Not Necessary	76.00 F	*- F
36	1	NA	*L/F WING (WCP)	Buckled	270.00 F	*270.00 F
37	5	NA	*L/F WING CLAMP KIT (WCP)	Necessary	18.00 F	*28.00 F
38	1	NA	*L/FAN MOTOR (WCP)	Not Necessary	260.00 F	*- F
39	1	NA	*L/FAN SHROUD (WCP)	Not Necessary	90.00 F	*- F
40	1	NA	*L/FOG LAMP BRACKET (WCP)	Not Necessary	24.00 F	*- F
41	1	NA	*L/FOG LAMP COVER (WCP)	Deformed	27.00 F	*27.00 F
42	1	NA	*L/RAD-GRILLE BRACKET (WCP)	Necessary	21.00 F	*21.00 F
43	1	NA	*L/RADIATOR FAN (WCP)	Not Necessary	60.00 F	*- F
44	1	NA	*L/WING MOULDING (WCP)	Necessary	65.00 F	*65.00 F
45	1	NA	*LEFT BONNET STOP (WCP)	Necessary	12.00 F	*12.00 F
46	1	NA	*LOWER FRONT GRILLE (WCP)	Deformed	65.00 F	*65.00 F
47	1	NA	*MINIFOLD AIR HOSE (WCP)	Broken	35.00 F	*35.00 F
48	1	NA	*R/BONNET HINGE (WCP)	Bent	42.00 F	*42.00 F
49	1	NA	*R/BONNET SEAL (WCP)	Necessary	21.00 F	*21.00 F
50	1	NA	*R/BOONET SEAL (WCP)	Necessary	28.00 F	*28.00 F
51	1	NA	*R/BUMPER CORNER BRKT (WCP)	Necessary	32.00 F	*32.00 F
52	1	NA	*R/COWL PANEL GRILLE (WCP)	Not Necessary	56.00 F	*- F
53	1	NA	*R/F AIR DUCT (WCP)	Not Necessary	28.00 F	*- F
54	1	NA	*R/F BONNET STOP (WCP)	Necessary	16.00 F	*16.00 F
55	1	NA	*R/F FOG LAMP (WCP)	Not Necessary	180.00 F	*- F
56	1	NA	*R/F HEADLAMP CPL (WCP)	Cracked	950.00 F	*950.00 F
57	1	NA	*R/F MOULDING (WCP)	Deformed	18.00 F	*18.00 F
58	1	NA	*R/F UPP BUMPER BRKT (WCP)	Cracked	18.00 F	*18.00 F
59	1	NA	*R/F WHEELHOUSE COVER (WCP)	Not Necessary	76.00 F	*- F
60	1	NA	*R/F WING (WCP)	Buckled	270.00 F	*270.00 F
61	5	NA	*R/F WING CLAMP KIT (WCP)	Necessary	18.00 F	*28.00 F
62	1	NA	*R/FAN MOTOR (WCP)	Not Necessary	250.00 F	*- F
63	1	NA	*R/FAN SHROUD (WCP)	Not Necessary	80.00 F	*- F
64	1	NA	*R/FOG LAMP BRACKET (WCP)	Not Necessary	24.00 F	*- F
65	1	NA	*R/FOG LAMP COVER (WCP)	Not Necessary	27.00 F	*- F
66	1	NA	*R/RAD-GRILLE BRACKET (WCP)	Necessary	170.00 F	*21.00 F
67	1	NA	*R/RADIATOR FAN (WCP)	Not Necessary	60.00 F	*- F
68	1	NA	*R/WING MOULDING (WCP)	Not Necessary	65.00 F	*- F
69	1	NA	*RAD GRILLE BRACKET (WCP)	Necessary	32.00 F	*32.00 F
70	1	NA	*RAD GRILLE COVER (WCP)	Deformed	350.00 F	*350.00 F
71	1	NA	*RADIATOR (WCP)	Bent	860.00 F	*860.00 F
72	1	NA	*RIGHT BONNET STOP (WCP)	Necessary	12.00 F	*12.00 F
73	1	NA	*UP/CVR RADIAT GRILLE (WCP)	Cracked	60.00 F	*60.00 F
Report was unsubmitted during this print-out.						

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
<u>Supplementary #1</u>						
74	1		*FILLER NEXK (WCP)	Deformed	26.00 F	*26.00 F
75	1		*WASHER RESERVOIR (WCP)	Deformed	60.00 F	*60.00 F
					Sub Total (S\$)	7,140.00
					+ Margin on L,N Items 5.00/5.00% (S\$)	357.00
					Total Parts (S\$)	7,497.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	AIR-CON GAS (NECESSARY)	50.00	50.00
2	1	ANTI-FREEZE COOLANT (NECESSARY)	40.00	40.00
3	1	AUDATEX FEE	42.00	42.00
4	1	NUMBER PLATE (CRACKED)	25.00	25.00
5	1	NUMBER PLATE HOLDER (CUT)	20.00	20.00
6	1	SUNDRY PARTS (NECESSARY)	100.00	100.00
Sub Total (S\$)			277.00	277.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	Total Paint Labour	New	653.20	598.00
2	Total Paint Materials	New	334.49	310.88
3	Total Panel/Mechanical Labour	New	1,044.20	975.20
Gross Labour Cost (S\$)			2,031.89	1,884.08

Report was unsubmitted during this print-out.

< END OF ESTIMATES >