

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

 AIG Asia Pacific Insurance Pte. Ltd.
 AIG Building, 78 Shenton Way #07-16
 Singapore 079120

 Our File No: CC3/AIG17011740/GVBE2 /
 Date: 26/01/2018 /

REFERENCE

 Insured/Claimant: CHEOK ENG KWEE / Policy No: 2100387895 /
 Date of Loss: 13/06/2017 / Nature of Claim: OD / Claim No: 5329994918SG /

DESCRIPTION & IDENTIFICATION OF VEHICLE

 Reg No: SKP7079M /
 Make & Model: AUDI A3 SPORTBACK, 1.4 TFSI (A) Engine No: CXS203932 /
 Reg. Date: 30/09/2014 (Man. Year: 2014) Chassis No: WAUZZZ8V3EA194216 /
 Colour: Grey / Odometer: 47894 km /
 Engine Capacity: 1395 cc
 Market Value/New Car Price: S\$96,000.00 /
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

 General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

 Front Tyre Size: 205/55 R16 / Rear Tyre Size: 205/55 R16 /
 Front Left Side: Continental 6 mm / Rear Left Side: Continental 6 mm /
 Front Right Side: Continental 6 mm / Rear Right Side: Continental 6 mm /

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,384.40	5,607.36	3,777.04	40.25
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,932.00	3,782.00	2,150.00	36.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,316.40 /	9,389.36 /	5,927.04	38.70
- Excess (S\$)	600.00 /	600.00 /	0.00	0.00
(S\$)	14,716.40	8,789.36	5,927.04	40.28
+ GST 7.00/7.00% (S\$)	1,030.15 /	615.26 /	414.89	40.27
Nett Amount (S\$)	15,746.55	9,404.62	6,341.93	40.28

INSPECTION

 Date of Assignment: 19/06/2017
 Date Inspected: 16/06/2017 Inspected At: Premium Automobiles Pte Ltd (HQ) /
 55 Ubi Road 1
 Singapore 408699 /
 Estimated Period of Repair: 5.0 days /

Adjuster: XING GUO QIANG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed /	✓ 1,546.00 FS	*1,236.80 FS
2	1		*FRONT BUMPER GUIDE SECTION - LH	Bent /	✓ 51.00 FS	*40.80 FS
3	1		*FRONT AIR GUIDE GRILLE - LH	Necessary /	✓ 90.00 FS	*71.92 FS
4	1		*FRONT FENDER - LH	Buckled /	✓ 708.00 FS	*566.00 FS
5	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary /	✓ 56.00 FS	*- FS
6	1		*FRONT FENDER BRACKET - LH / REAR	Necessary /	✓ 23.00 FS	*18.16 FS
7	1		*FRONT FENDER BRACKET - LH	Necessary /	✓ 40.00 FS	*31.60 FS
8	✓ 8		*POP RIVET	Necessary /	✓ 23.00 FS	*17.92 FS
9	1		*FRONT FENDER CLOSING ELEMENT	Bent /	✓ 52.00 FS	*40.96 FS
10	1		*FRONT FENDER BRACE	Bent /	✓ 81.00 FS	*64.80 FS
11	1		*WHEEL HOUSING LINER - LH	Deformed /	✓ 146.00 FS	*116.80 FS
12	1		*SEALING WASHER	Not Necessary /	✓ 24.00 FS	*- FS
13	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Necessary /	✓ 75.00 FS	*59.44 FS
14	1		*GAS DISCHARGE HEADLIGHT - LH	Cracked /	✓ 1,708.00 FS	*1,366.40 FS
15	1		*HEADLIGHT WASHER LIFT CYLINDER - LH	Damaged /	✓ 160.00 FS	*127.60 FS
16	1		*BONNET	Repair /	✓ 2,372.00 FS	*- FS
17	1		*EDGE PROTECTION - FRONT	Not Necessary /	✓ 23.00 FS	*- FS
18	1		*SUNDRIES	Necessary /	✓ 400.00 FS	*61.76 FS
19	1		*WASH WATER RESERVOIR	Distorted /	✓ 138.40 FS	*138.40 FS
20	1		*WATER RESERVOIR SEAL & BUNGS	Not Necessary /	✓ 20.00 FS	*- FS
21	1		*SIGNAL HORN - LH	Broken /	✓ 138.40 FS	*138.40 FS
22	1		*LHS HEADLIGHT BALLAST	Not Working /	✓ 801.60 FS	*801.60 FS
23	1		*LHS HEADLAMP POWER MODULE	Not Working /	✓ 393.20 FS	*393.20 FS
24	1		*LHS HEADLAMP BULB	Not Working /	✓ 314.80 FS	*314.80 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) **9,384.40** **5,607.36**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER AND BONNET	New	2,400.00	1,700.00
3	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
4	TO REPAIR FRONTAL HORN WIRING HARNESS	New	280.00	280.00
5	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER, HEADLIGHT AND BONNET. RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS, REINSTALL ALL PARTS REMOVED	New	2,700.00	1,250.00
Gross Labour Cost (S\$)			5,932.00	3,782.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >