

...CLAIM SUBFOLDER...(Pending for Survey Report)

BI

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	23 Jun 2017		29 Jun 2017 09:47 Edit Adj Rpt	S\$42,256.32 Edit Estimates	S\$42,256.32 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All																																			
CLAIM SUBFOLDER DETAILS [Created by insurer] <table style="width: 100%;"> <tr> <td style="width: 15%;">Insured:</td> <td colspan="4">TAN, KUAN KHER, ID: S7319109B</td> </tr> <tr> <td>Vehicle Reg. No.:</td> <td>SKR1200H</td> <td>Date of Loss:</td> <td colspan="2">15/06/2017 09:00 - :59 [43 Months and 1 Days From LTA Reg Date (Man Yr)]</td> </tr> <tr> <td>Claim Type:</td> <td>OD / C0439064</td> <td>Policy/Cover Note No.:</td> <td colspan="2">P1685108 (Comprehensive)</td> </tr> <tr> <td></td> <td></td> <td>Excess:</td> <td colspan="2">S\$2,500.00</td> </tr> <tr> <td>Repairer:</td> <td colspan="4">Hiap Lek Automobile Trading () Blk 14 #01-19 Sector B, Sin Ming Industrial Est, 575658 Sin Ming - Tel:</td> </tr> <tr> <td>Handling Insurer:</td> <td colspan="4">AXA Insurance Pte Ltd (HQ) - Tel: 6880 4888 ... [Handled by Kitty Teo - 6880 4602]</td> </tr> <tr> <td>Adjuster:</td> <td colspan="4">LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 10/07/2017]</td> </tr> </table>					Insured:	TAN, KUAN KHER, ID: S7319109B				Vehicle Reg. No.:	SKR1200H	Date of Loss:	15/06/2017 09:00 - :59 [43 Months and 1 Days From LTA Reg Date (Man Yr)]		Claim Type:	OD / C0439064	Policy/Cover Note No.:	P1685108 (Comprehensive)				Excess:	S\$2,500.00		Repairer:	Hiap Lek Automobile Trading () Blk 14 #01-19 Sector B, Sin Ming Industrial Est, 575658 Sin Ming - Tel:				Handling Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6880 4888 ... [Handled by Kitty Teo - 6880 4602]				Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 10/07/2017]			
Insured:	TAN, KUAN KHER, ID: S7319109B																																						
Vehicle Reg. No.:	SKR1200H	Date of Loss:	15/06/2017 09:00 - :59 [43 Months and 1 Days From LTA Reg Date (Man Yr)]																																				
Claim Type:	OD / C0439064	Policy/Cover Note No.:	P1685108 (Comprehensive)																																				
		Excess:	S\$2,500.00																																				
Repairer:	Hiap Lek Automobile Trading () Blk 14 #01-19 Sector B, Sin Ming Industrial Est, 575658 Sin Ming - Tel:																																						
Handling Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6880 4888 ... [Handled by Kitty Teo - 6880 4602]																																						
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 10/07/2017]																																						
ASSOCIATED MAIL RECEIVED View All Compose Case Mail - AXA_SG (28/05/2020): Alert - Adj Mandate Approved (S\$42256.32) - SKR1200H - Claim Handler: Kitty Teo - AXA_SG (26/05/2020): Alert - Adj Mandate Approved (S\$42026.32) - SKR1200H - Claim Handler: Kitty Teo - AXA_SG (10/04/2019): Please advise on supplementary urgently - AXA_SG (10/04/2019): Re: NOTIFICATION OF MANDATE REQUEST - C0439064/SKR1200H - AXA_SG (31/10/2018): REPAIR BILL? - AXA_SG (27/09/2018): Re: URGENT REMINDER - Status - AXA_SG (28/06/2018): URGENT REMINDER - Status - AXA_SG (11/11/2017): Status - AXA_SG (11/11/2017): Status - AXA_SG (11/07/2017): Alert - Adj Mandate Approved (S\$53000.00) - SKR1200H - Claim Handler: Kitty Teo - AXA_SG (10/07/2017): Please proceed to authorise																																							
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete <table style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th>Due Date</th> <th>Priority</th> <th>Type</th> <th>Task Group</th> <th>Subject</th> <th>Handler</th> <th>Assigned By</th> <th>Completed On</th> <th>Created On</th> <th>Done?</th> </tr> </thead> <tbody> <tr> <td colspan="10">No results.</td> </tr> </tbody> </table>					Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?	No results.																								
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?																														
No results.																																							

Claim Documents

***SKR1200H (C0439064)**
OD
Jun 15 2017 9:00AM
[TAN, KUAN KHER]
Hiap Lek Automobile Trading

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[Upload Video](#)
[Upload Audio](#)

View
[View in Browser](#) ▼

Assessment Reports

1 per page ▼ ☒

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	29/06/17 16:19	Adjuster Immediate Advice		Load HTM	
2	28/11/18 12:00	Adjuster Immediate Advice		Load HTM	
3	22/07/19 17:10	Adjuster Immediate Advice		Load HTM	

Photos/Images

3 per page ▼ ☒

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	30/06/17 09:07	General View		Load JPG	☒
2	30/06/17 09:07	General View		Load JPG	☒
3	30/06/17 09:07	General View		Load JPG	☒
4	30/06/17 09:07	General View		Load JPG	☒
5	30/06/17 09:07	General View		Load JPG	☒
6	30/06/17 09:07	General View		Load JPG	☒
7	30/06/17 09:07	General View		Load JPG	☒
8	30/06/17 09:07	General View		Load JPG	☒
9	30/06/17 09:07	General View		Load JPG	☒
10	30/06/17 09:07	General View		Load JPG	☒
11	30/06/17 09:07	General View		Load JPG	☒
12	30/06/17 09:07	General View		Load JPG	☒
13	30/06/17 09:07	General View		Load JPG	☒
14	30/06/17 09:07	General View		Load JPG	☒
15	30/06/17 09:07	General View		Load JPG	☒
16	30/06/17 09:07	General View		Load JPG	☒
17	30/06/17 09:07	General View		Load JPG	☒
18	30/06/17 09:07	General View		Load JPG	☒
19	30/06/17 09:07	General View		Load JPG	☒
20	30/06/17 09:07	General View		Load JPG	☒
21	30/06/17 09:07	General View		Load JPG	☒
22	30/06/17 09:07	General View		Load JPG	☒
23	30/06/17 09:07	General View		Load JPG	☒
24	30/06/17 09:07	General View		Load JPG	☒
25	30/06/17 09:07	General View		Load JPG	☒
26	30/06/17 09:07	General View		Load JPG	☒
27	30/06/17 09:07	General View		Load JPG	☒
28	30/06/17 09:07	General View		Load JPG	☒
29	30/06/17 09:07	General View		Load JPG	☒
30	30/06/17 09:07	General View		Load JPG	☒
31	30/06/17 09:07	General View		Load JPG	☒
32	30/06/17 09:07	General View		Load JPG	☒
33	30/06/17 09:07	General View		Load JPG	☒
34	30/06/17 09:07	General View		Load JPG	☒
35	30/06/17 09:07	General View		Load JPG	☒
36	28/11/18 12:08	Reinspection Photo		Load PDF	
37	22/07/19 17:11	Reinspection Photo		Load PDF	

Assessment Reports				1 per page	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
Documentation				1 per page	
No	Finalized On	AXA Insurance Pte Ltd (HQ)		Thumbnail	Print
1	23/06/17 17:25	EMAIL_ABS		Load PDF	
2	29/06/17 09:34	ESTIMATE		Load PDF	
3	29/06/17 09:38	GIA REPORT		Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	29/06/17 16:24	estimate		Load PDF	
2	10/04/19 17:10	SUPPLMANTARY		Load PDF	
3	25/07/19 10:37	estimate		Load PDF	
4	28/05/20 10:32	TOWING INVOICE		Load PDF	
5	29/05/20 11:43	DISCHARGE VOUCHER		Load PDF	
6	29/05/20 11:43	WORKSHOP INVOICE		Load PDF	
7	29/05/20 11:54	PART INVOICE (1)		Load PDF	
8	29/05/20 11:54	PART INVOICE (2)		Load PDF	
9	29/05/20 11:54	PART INVOICE (3)		Load PDF	
10	29/05/20 11:54	PART INVOICE (4)		Load PDF	
11	29/05/20 11:54	PART INVOICE (5)		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To:

☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AXA Insurance Pte Ltd
8 Shenton Way #24-01, AXA Tower
Singapore 068811

Our File No: CS/AXA17012572/KTBS2**Date:** 29/05/2020**REFERENCE**

Insured/Claimant:	TAN, KUAN KHER	Policy No:	P1685108	
Date of Loss:	15/06/2017	Nature of Claim:	OD	Claim No: C0439064

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKR1200H		
Make & Model:	JAGUAR F-TYPE, 3.0 (A)	Engine No:	13072405131306PS
Reg. Date:	14/11/2013 (Man. Year: 2013)	Chassis No:	SAJAC65G5E8K06753
Colour:	White	Odometer:	13695 km
Engine Capacity:	2995 cc		
Market Value/New Car Price:	S\$260,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	255/35ZR20	Rear Tyre Size:	295/30ZR20
Front Left Side:	Pirelli 8 mm	Rear Left Side:	Pirelli 8 mm
Front Right Side:	Pirelli 8 mm	Rear Right Side:	Pirelli 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	73,743.78	38,736.32	35,007.46	47.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,480.00	3,520.00	4,960.00	58.49
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	82,223.78	42,256.32	39,967.46	48.61
- Excess (S\$)	2,500.00	2,500.00	0.00	0.00
Nett Amount (S\$)	79,723.78	39,756.32	39,967.46	50.13

INSPECTION

Date of Assignment:	29/06/2017	
Date Inspected:	29/06/2017	Inspected At: 160 SIN MING DRIVE #05-17 Singapore 575722
Estimated Period of Repair:	12.0 days	Repairer: Hiap Lek Automobile Trading

Adjuster: KENNETH KONG**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 29 May 2020)
Parts:	143	JAGUAR F-TYPE 3.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKR1200H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BONNET (CONSISTENT) (WCP)	Bent	2,600.00 F	*2,600.00 F
2	2		*FRT BONNET LOCK RH/LH (CONSISTENT) (WCP)	Distorted	280.00 F	*- F
3	2		*FRT BONNET HINGE RH/LH (CONSISTENT) (WCP)	Distorted	180.00 F	*180.00 F
4	1		*FRT BONNET CATCH (CONSISTENT) (WCP)	Repair	8.00 F	*- F
5	1		*FRT BONNET RELEASE HANDLE (CONSISTENT) (WCP)	Serviceable	12.00 F	*- F
6	2		*FRT BONNET SEAL RH/LH (CONSISTENT) (WCP)	Serviceable	184.00 F	*- F
7	1		*FRT BUMPER (CONSISTENT) (WCP)	Torn	1,900.00 F	*1,900.00 F
8	10		*FRT BUMPER CLIPS (CONSISTENT) (WCP)		18.00 F	*18.00 F
9	20		*FRT BUMPER BLIND RIVET (CONSISTENT) (WCP)	Necessary	70.00 F	*70.00 F
10	1		*FRT LOWER BUMPER GRILLE INSERT (CONSISTENT) (WCP)	Cracked	320.00 F	*320.00 F
11	1		*FRT BUMPER LOWER SPOILER (CONSISTENT) (WCP)	Distorted / Dented	640.00 F	*640.00 F
12	1		*FRT BUMPER LH LOWER SPOILER TRIM (CONSISTENT) (WCP)	Cracked	40.00 F	*40.00 F
13	2		*FRT LOWER SPOILER TRIM RH / LH (CONSISTENT) (WCP)	Distorted	90.00 F	*90.00 F
14	1		*FRT BUMPER GRILLE TRIM RH (BLACK) (CONSISTENT) (WCP)	Missing	140.00 F	*140.00 F
15	1		*FRT BUMPER GRILLE TRIM LH (BLACK) (CONSISTENT) (WCP)	Cracked	160.00 F	*160.00 F
16	1		*FRT BUMPER LOWER SPOILER TRIM LH (CONSISTENT) (WCP)	Serviceable	80.00 F	*- F
17	2		*FRT BUMPER CARRIER TOP SUPPORT (CONSISTENT) (WCP)	Necessary 1pc Only	260.00 F	*33.00 F
18	1		*FRT RADIATOR GRILLE UPPER (CONSISTENT) (WCP)	Cracked	350.00 F	*150.00 F
19	1		*FRT RADIATOR GRILLE CENTRE (CONSISTENT) (WCP)	Cracked	150.00 F	*150.00 F
20	1		*FRT RADIATOR GRILLE LOWER (CONSISTENT) (WCP)	Cracked	150.00 F	*150.00 F
21	1		*FRT RADIATOR GRILLE SURROUND CHROME (CONSISTENT) (WCP)	Cracked	240.00 F	*240.00 F
22	1		*FRT RADIATOR GRILLE BADGE (CONSISTENT) (WCP)	Cracked	38.00 F	*38.00 F
23	1		*SMALL MESH-GRILLE (CONSISTENT) (WCP)	Cracked	805.00 F	*805.00 F
24	1		*FRT JAGUAR -RAD BADGE (CONSISTENT) (WCP)	Necessary	100.00 F	*100.00 F
25	1		*FRT S BADGE (CONSISTENT) (WCP)	Missing	140.00 F	*140.00 F
26	1		*KABELBAUM (CONSISTENT) (WCP)	Necessary	470.00 F	*470.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
27	2		*FRT RADIATOR GRILLE REINFORCEMENT (CONSISTENT) (WCP)	Repair	28.00 F	*- F
28	1		*FRT RADIATOR SUPPORT BRACKET LH (CONSISTENT) (WCP)	Distorted	35.00 F	*35.00 F
29	1		*FRT BUMPER RH VENT GRILLE INNER (CONSISTENT) (WCP)	Serviceable	310.00 F	*- F
30	1		*FRT BUMPER RH VENT GRILLE OUTER (CONSISTENT) (WCP)	Serviceable	270.00 F	*- F
31	1		*FRT BUMPER LH VENT GRILLE INNER (CONSISTENT) (WCP)	Serviceable	310.00 F	*- F
32	1		*FRT BUMPER LH VENT GRILLE OUTER (CONSISTENT) (WCP)	Serviceable	270.00 F	*- F
33	1		*FRT BUMPER SPONGE (CONSISTENT) (WCP)	Serviceable	650.00 F	*- F
34	1		*FRT BUMPER CENTRE SPONGE (CONSISTENT) (WCP)	Cracked	62.00 F	*62.00 F
35	2		*FRT BUMPER SMALL FOAM RH/LH (CONSISTENT) (WCP)	Cracked	70.00 F	*70.00 F
36	2		*FRT HEADWASH CAP RH/LH (CONSISTENT) (WCP)	Missing / Dented	48.00 F	*48.00 F
37	2		*FRT HEADWASH BRACKET RH/LH (CONSISTENT) (WCP)	Distorted	120.00 F	*120.00 F
38	10		*FRT GRILLE CLIPS (CONSISTENT) (WCP)	Necessary	10.00 F	*10.00 F
39	1		*FRT BUMPER UNDERTRAY (CONSISTENT) (WCP)	Cracked	270.00 F	*270.00 F
40	1		*FRT ENGINE UNDERTRAY (CONSISTENT) (WCP)	Cracked	400.00 F	*400.00 F
41	1		*FRT ENGINE UNDERTRAY AIR DUCT (CONSISTENT) (WCP)	Cracked	70.00 F	*70.00 F
42	2		*FRT BUMPER SIDE RETAINER (CONSISTENT) (WCP)	Distorted	140.00 F	*140.00 F
43	2		*FRT BUMPER BRACKET RH/LH (CONSISTENT) (WCP)	Bent	15.00 F	*15.00 F
44	2		*FRT BUMPER NOOZLE RH/LH (CONSISTENT) (WCP)	Serviceable	900.00 F	*- F
45	2		*FRT BUMPER SIDE TOP DEFLECTOR (CONSISTENT) (WCP)	Distorted	72.00 F	*62.00 F
46	2		*FRT BUMPER SIDE LOWER DEFLECTOR (CONSISTENT) (WCP)	Cracked	50.00 F	*50.00 F
47	1		*FRT HEADWASH NOZZLE RH (CONSISTENT) (WCP)	Missing	200.00 F	*200.00 F
48	2		*FRT NOOZLE BRACKET RH/LH (CONSISTENT) (WCP)	Serviceable	240.00 F	*- F
49	1		*FRT NOOZLE COVER (CONSISTENT) (WCP)	Serviceable	160.00 F	*- F
50	1		*FRT TOWING COVER (CONSISTENT) (WCP)	Missing	68.00 F	*60.00 F
51	1		*FRT BUMPER HARNESS (CONSISTENT) (WCP)	Torn	178.00 F	*178.00 F
52	1		*FRT WIPER ARM COVER RH (WCP) (CONSISTENT)	Missing	6.50 F	*6.50 F
53	1		*FRT WIPER ARM CAP (CONSISTENT) (WCP)	Serviceable	15.00 F	*- F
54	4		*FRT PARKING SENSORS (CONSISTENT) (WCP)	Shorted	480.00 F	*480.00 F
55	4		*FRT PARKING SENSOR BOLT (CONSISTENT) (WCP)	Necessary	10.00 F	*10.00 F
56	4		*FRT BUMPER IMPACT SENSOR (CONSISTENT) (WCP)	Shorted	580.00 F	*580.00 F
57	1		*FRT PARKING SENSOR HARNESS W/O DELOYABLE BONNET (CONSISTENT) (WCP)	Torn	590.00 F	*590.00 F
58	1		*FRT PARKING SENSOR HARNES W/DEPLOYABLE BONNET (CONSISTENT) (WCP)	Serviceable	230.00 F	*- F
59	4		*FRT PARKING SENSOR SEAL (CONSISTENT) (WCP)	Necessary	30.00 F	*30.00 F
60	4		*FRT HARNESS (CONSISTENT) (WCP)	Repair	1,100.00 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
61	2		*FRT HEADLAMP RH/LH (CONSISTENT) (WCP)	O/s Broken / N/s Mtg Cracked	3,700.00 F	*3,700.00 F
62	2		*FRT HID XENON HEADLIGHT RH/LH (CONSISTENT) (WCP)	Serviceable	700.00 F	*- F
63	2		*FRT HEAD LAMP BALLAST RH/LH (WCP) (CONSISTENT)	Serviceable	1,820.00 F	*- F
64	2		*FRT HEAD LAMP BRACKET RH/LH (CONSISTENT) (WCP)	O/s Bent / N/s Distorted	144.00 F	*144.00 F
65	1		*FRT HEADLAMP JET LH (CONSISTENT) (WCP)	Missing	200.00 F	*200.00 F
66	1		*FRT FENDER RH SUPPORT (CONSISTENT) (WCP)	Bent	206.00 F	*206.00 F
67	2		*FRT FENDER GARNISH CHROME RH/LH (CONSISTENT) (WCP)	Serviceable	600.00 F	*- F
68	1		*FRT WHEEL INNER SHIELD PANEL RH/LH (CONSISTENT) (WCP)	O/s Cracked	300.00 F	*150.00 F
69	2		*FRT DEFLECTOR SHIELD RH/LH (CONSISTENT) (WCP)	Serviceable	80.00 F	*- F
70	1		*FRT RE-INFORCEMENT (CONSISTENT) (WCP)	Bent	450.00 F	*450.00 F
71	2		*FRT RE-INFORCEMENT BRACKET (CONSISTENT) (WCP)	Punctured	820.00 F	*820.00 F
72	1		*FRT ENGINE RADIATOR (WCP)	Cracked	420.00 F	*420.00 F
73	2		*FRT ENGINE RADIATOR DEFLECTOR RH/LH (CONSISTENT) (WCP)	Cracked	66.00 F	*66.00 F
74	1		*FRT ENGINE RADIATOR TOP COVER (CONSISTENT) (WCP)	Cracked	69.00 F	*69.00 F
75	1		*FRT ENGINE RADIATOR BOTTOM COVER (CONSISTENT) (WCP)	Cracked	97.00 F	*97.00 F
76	1		*FRT AUX RADIATOR (CONSISTENT) (WCP)	Bent / Punctured	880.00 F	*880.00 F
77	1		*FRT INTERCOOLER (CONSISTENT) (WCP)	Bent / Punctured	720.00 F	*720.00 F
78	1		*FRT INTERCOOLER INLET PIPE (WCP)	Serviceable	72.00 F	*- F
79	1		*FRT INTERCOOLER TO PUMP PIPE (WCP) (CONSISTENT)	Serviceable	40.00 F	*- F
80	1		*FRT INTERCOOLER HOSE (CONSISTENT) (WCP)	Serviceable	64.00 F	*- F
81	1		*FRT UPPER INTAKE TUBE RH (CONSISTENT) (WCP)	Serviceable	240.00 F	*- F
82	1		*FRT LOWER INTAKE TUBE RH (CONSISTENT) (WCP)	Serviceable	340.00 F	*- F
83	1		*FRT UPPER T-SHAPE INTAKE TUBE (CONSISTENT) (WCP)	Serviceable	344.00 F	*- F
84	1		*FRT ENGINE FUEL BOX (CONSISTENT) (WCP)	Serviceable	460.00 F	*- F
85	1		*FRT ENGINE FUEL BOX BRACKET (CONSISTENT) (WCP)	Repair	210.00 F	*- F
86	1		*FRT AIR FILTER (CONSISTENT) (WCP)	Serviceable	3,424.00 F	*- F
87	1		*FRT AIRBOX RH (CONSISTENT) (WCP)	Cracked	1,600.00 F	*1,600.00 F
88	2		*FRT MAIN FUEL BOX MAIN RH/LH (CONSISTENT) (WCP)	Serviceable	5,800.00 F	*- F
89	1		*FRT LOWER AIR DEFLECTOR RH (CONSISTENT) (WCP)	Serviceable	40.00 F	*- F
90	1		*FRT RIM RH (CONSISTENT) (WCP)	Serviceable	1,500.00 F	*- F
91	1		*FRT TYRE RH (CONSISTENT) (WCP)	Serviceable	650.00 F	*- F
92	2		*FRT BONNET AIR BAG SENSOR RH/LH (CONSISTENT) (WCP)	Serviceable	2,600.00 F	*- F
93	1		*AIR BAG CONTROL UNIT RH (CONSISTENT) (WCP)	Serviceable	3,450.00 F	*- F
94	2		*FRT BUMPER AIRBAG SENSOR (CONSISTENT) (WCP)	Necessary	72.00 F	*72.00 F
95	1		*SAFETY BELT RH (CONSISTENT) (WCP)	Jammed	385.00 F	*385.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
96	1		*SAFETY BELT LH (CONSISTENT) (WCP)	Serviceable	830.00 F	*- F
97	1		*FRT UPPER ARM RH (CONSISTENT) (WCP)	Serviceable	660.00 F	*- F
98	2		*FRT LOWER ARM COOL DUCT RH/LH (CONSISTENT) (WCP)	Dented	138.00 F	*138.00 F
99	1		*FRT LOWER ARM (CONSISTENT) (WCP)	Bent	195.00 F	*195.00 F
100	1		*FRT LOWER REAR ARM RH (CONSISTENT) (WCP)	Distorted	175.00 F	*175.00 F
101	1		*FRT STABILIZER ARM RH (CONSISTENT) (WCP)	Serviceable	325.00 F	*- F
102	2		*FRT ARM AIR DUCT RH/LH (CONSISTENT) (WCP)	Dented	164.00 F	*164.00 F
103	1		*FRT KNUCKLE RH (CONSISTENT) (WCP)	Bent	310.00 F	*310.00 F
104	1		*FRT SHOCK ABSORBER RH (CONSISTENT) (WCP)	Bent	860.00 F	*860.00 F
105	1		*FRT SHOCK ABSORBER BOOT RH (CONSISTENT) (WCP)	Distorted	72.00 F	*72.00 F
106	1		*FRT BEARING RH (CONSISTENT) (WCP)	Necessary	430.00 F	*430.00 F
107	1		*FRT CROSS MEMBER (CONSISTENT) (WCP)	Bent	3,000.00 F	*3,000.00 F
108	1		*STEERING RACK AND PINION (CONSISTENT) (WCP)	Bent	3,260.00 F	*3,260.00 F
109	1		*STEERING TIE ROD (CONSISTENT) (WCP)	Buckled	148.00 F	*148.00 F
110	1		*FRT STEERING TIE ROD RH (CONSISTENT) (WCP)	Bent	230.00 F	*230.00 F
111	1		*FRT STEERING BOOT COVER RH (CONSISTENT) (WCP)	Necessary	55.00 F	*55.00 F
112	1		*NUMBER PLATE BASE (CONSISTENT) (WCP)	Missing	188.00 F	*188.00 F
113	1		*START STOP FUSEBOX (CONSISTENT) (WCP)	Dented	1,200.00 F	*1,200.00 F
114	1		*START STOP FUSEBOX BRACKET (CONSISTENT) (WCP)	Distorted	95.00 F	*95.00 F
115	1		*START STOP BATTERIE (CONSISTENT) (WCP)	Dented	300.00 F	*300.00 F
116	1		*START STOP SUPPORT BRACKET (CONSISTENT) (WCP)	Buckled	100.00 F	*100.00 F
117	1		*CARRIER TOP SUPPORT (CONSISTENT) (WCP)	Distorted	210.00 F	*210.00 F
118	1		*COOLANT (CONSISTENT) (WCP)	Necessary	20.00 F	*20.00 F
119	1		*INNER BOOT CLAMP (CONSISTENT) (WCP)	Buckled	20.00 F	*20.00 F
120	1		*PARTS GST 7%		4,407.23 FS	*2,314.87 FS
121	1		*NUMBER PLATE AND HOUSING (CONSISTENT)	Bent	80.00 FS	*45.00 FS

F=Franchise part. S=SpcNett.

Sub Total (\$)	67,447.73	35,429.37
+ Margin on L,N Items 10.00/10.00% (\$)	6,296.05	3,306.95
Total Parts (\$)	73,743.78	38,736.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECKING WIRING AND FOCUS HEADLAMPS AND BUMPER FOG LAMP.	New	250.00	50.00
2	TO STRAIGHTEN AND PANEL BEATING FRONT SUPPORT PANEL INNER. TO CUT / WELD FRONT PANEL. TO REMOVE AND RE-FIT FRONT PARTS.	New	2,500.00	1,000.00
3	TO REMOVE AND RE-FIT FRONT RH SIDE UNDERCARRIAGES, RACK AND PINION CROSS MEMBER.	New	800.00	400.00
4	TO CONDUCT ELECTRONIC WHEEL ALIGNMENT TESTS.	New	200.00	120.00
5	TO PUTTY, RE-SPRAY PAINTING ON FRONT AFFECTED PORTION, FRONT RH/LH FENDERS, FRONT REINFORCEMENT AND POLISH AFFECTED AREAS.	New	4,000.00	1,600.00
6	TO CHECK AND RECTIFY WIRING SYSTEM.	New	400.00	120.00
7	TO RUST PROOF AFFECTED AREAS.	New	90.00	0.00
8	TOWING CHARGES 2 TRIPS.	New	240.00	230.00
Gross Labour Cost (\$\$)			8,480.00	3,520.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >