

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CT117012600/R1TH3E2

Date: 28/05/2018

REFERENCE

Insured/Claimant:	TEIW GUAT CHOO	Policy No:	DMPCSN3017881705
Date of Loss:	27/06/2017	Nature of Claim:	OD
		Claim No:	SNM17D03777C01

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGG8111R		
Make & Model:	BMW 520I, 2.0 (A)	Engine No:	A020I354N46B20BE
Reg. Date:	20/04/2009 (Man. Year: 2008)	Chassis No:	WBANT12040CX29937
Colour:	Blue	Odometer:	189761 km
Engine Capacity:	1995 cc		
Market Value/New Car Price:	S\$44,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/50 R17	Rear Tyre Size:	225/50 R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,685.50	2,913.02	5,772.48	66.46
Miscellaneous Items	564.90	0.00	564.90	100.00
Labour	1,024.32	536.11	488.21	47.66
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,274.72	3,449.13	6,825.59	66.43
Approved Total (Overridden) (S\$)		2,750.00		
(S\$)	10,274.72	2,750.00	7,524.72	73.24
+ GST 0.00/7.00% (S\$)	0.00	192.50	-192.50	
Nett Amount (S\$)	10,274.72	2,942.50	7,332.22	71.36

INSPECTION

Date of Assignment:	03/07/2017 Present Location:	Cheng Auto Bodyworks (HQ)
Date Inspected:	29/06/2017 Inspected At:	1 Soon Lee Street, #06-41, Pioneer Centre
		Singapore 627605
Estimated Period of Repair:	4.0 days	

Adjuster: MOHD RASUL

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 May 2018)
Parts:	143	BMW 520I 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGG8111R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1	NA	*AIR GUIDE TRIM (WCP)	Serviceable	140.00 F	*- F
2	1	NA	*BONNET (WCP)	Bent	1,500.00 F	*1,500.00 F
3	1	NA	*BONNET SPRING (WCP)	Serviceable	40.00 F	*- F
4	1	NA	*FRONT BUMPER COVER (WCP)	Repair	900.00 F	*- F
5	1	NA	*FRONT BUMPER SUPPORT (WCP)	Serviceable	450.00 F	*- F
6	1	NA	*FRT BUMPER GRILLE (WCP)	Serviceable	55.00 F	*- F
7	1	NA	*FRT BUMPER MNTG KIT (WCP)	Serviceable	15.00 F	*- F
8	1	NA	*GRILLE BADGE (WCP)	Serviceable	65.00 F	*- F
9	1	NA	*L/BONNET HINGE (WCP)	Serviceable	75.00 F	*- F
10	1	NA	*L/F BONNET STRUT (WCP)	Serviceable	60.00 F	*- F
11	1	NA	*L/F BUMPER BRACKET (WCP)	Serviceable	25.00 F	*- F
12	1	NA	*L/F GRILLE (WCP)	Serviceable	120.00 F	*- F
13	1	NA	*L/F WIPER ARM (WCP)	Serviceable	80.00 F	*- F
14	1	NA	*LEFT HEADLAMP ASSY (WCP)	Serviceable	1,250.00 F	*- F
15	1	NA	*R/BONNET HINGE (WCP)	Serviceable	75.00 F	*- F
16	1	NA	*R/BONNET LOCK (WCP)	Serviceable	120.00 F	*- F
17	1	NA	*R/F BONNET STRUT (WCP)	Serviceable	60.00 F	*- F
18	1	NA	*R/F BUMPER BRACKET (WCP)	Serviceable	25.00 F	*- F
19	1	NA	*R/F GRILLE (WCP)	Serviceable	120.00 F	*- F
20	1	NA	*R/F WING (WCP)	Serviceable	400.00 F	*- F
21	1	NA	*R/F WIPER ARM (WCP)	Serviceable	180.00 F	*- F
22	1	NA	*R/FRONT SCREEN MLDG (WCP)	Necessary	35.00 F	*35.00 F
23	1	NA	*RAIN-/LIGHT SENSOR (WCP)	Serviceable	90.00 F	*- F
24	1	NA		Serviceable	1,250.00 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
			*RIGHT HEADLAMP ASSY (WCP)			
25	1	NA	*SOUND INSULATION (WCP)	Serviceable	190.00 F	*- F
26	1	NA	*SPECIALIST AUDATEX FEES		42.00 FS	*42.00 FS
27	1	NA	*SPECIALIST FRT NO. PLATE	Bent	45.00 FS	*45.00 FS
28	1	NA	*SPECIALIST WINDSCREEN SEALANT	Necessary	25.00 FS	*25.00 FS
29	1	NA	*SUNDRY PARTS	Necessary	100.00 FS	*100.00 FS
30	1	NA	*WINDSCREEN (WCP)	Cracked	750.00 F	*750.00 F
Supplementary #1						
31	1		*Windscreen Bond Kit (WCP)	Necessary	-	*131.55 F
32	1		*Cleaner R1 frt scrn (WCP)	Necessary	-	*47.25 F
33	10		*Front screen clip (WCP)	Necessary	-	*16.50 F
34	1		*Info label airbag (WCP)	Serviceable	-	*- F
35	4		*Windscreen buffer (WCP)	Necessary	-	*6.40 F
36	2		*Windscreen buffer (WCP)	Necessary	-	*2.90 F
37	1		*Front screen cover (WCP)	Serviceable	-	*- F
38	1		*Lwr windscreen seal (WCP)	Necessary	-	*82.80 F
39	1		*Anti-misting sensor (WCP)	Serviceable	-	*- F
					Sub Total (\$\$)	8,282.00
					+ Margin on L,N Items 5.00/5.00% (\$\$)	403.50
					Total Parts (\$\$)	8,685.50
						2,913.02

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	GST 7%	564.90	0.00
Sub Total (\$\$)			564.90	0.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	Total Paint Labour	New	317.40	184.00
2	Total Paint Materials	New	223.92	125.94
3	Total Panel/Mechanical Labour	New	483.00	226.17
Gross Labour Cost (\$\$)			1,024.32	536.11

Report was unsubmitted during this print-out.

< END OF ESTIMATES >