

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC3/AIG17012744/KDS3Q2

**Date:** 13/05/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	100773997
<b>Claimant</b>		
<b>Vehicle No :</b> SHB7547M	<b>Insured Vehicle No :</b>	GY8856E
Date of Loss: 22/06/2017	Nature of Claim: TP	Claim No: 6166846012SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHB7547M		
Make & Model:	CHEVROLET EPICA, 2.0 (A)	Engine No:	HIDDEN
Reg. Date:	01/03/2012 (Man. Year: 2012)	Chassis No:	KL1LA69RJBB091501
Colour:	Red/White	Odometer:	579319 km
Engine Capacity:	1991 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Giti 3 mm	Rear Left Side:	Linglong 8 mm
Front Right Side:	Giti 3 mm	Rear Right Side:	Linglong 8 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	14,733.92	845.10	13,888.82	94.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,720.00	430.00	6,290.00	93.60
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>21,453.92</b>	<b>1,275.10</b>	<b>20,178.82</b>	<b>94.06</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,000.00</b>		
<b>(S\$)</b>	21,453.92	1,000.00	20,453.92	95.34
<b>+ GST 7.00/7.00% (S\$)</b>	1,501.77	70.00	1,431.77	95.34
<b>Nett Amount (S\$)</b>	<b>22,955.69</b>	<b>1,070.00</b>	<b>21,885.69</b>	<b>95.34</b>
<b>+ Loss of Use (3.0 x S\$50.00/day) (S\$)</b>		150.00		
<b>+ Car Rental (3.0 x S\$75.25/day) (S\$)</b>		225.75		
<b>(S\$)</b>		1,445.75		
<b>Liabie Amount (50.00%) (S\$)</b>		<b>722.88</b>		
<b>+ Doc/Search Fee (S\$)</b>		6.00		
<b>Nett Liability (S\$)</b>		<b>728.88</b>		
<b>Global Sum Settlement (S\$)</b>		<b>720.00</b>		

### INSPECTION

Date of Assignment: 29/06/2017

Date Inspected: 29/06/2017 Inspected At:

Trans-cab Auto Services Pte Ltd (Ang  
Mo Kio)  
2, Ang Mo Kio Street 63  
Singapore 569111

Estimated Period of Repair: 2.0 days

---

**Adjuster:** KENNETH KONG

**Manager:** CHAN JIA LE

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER LH	Repair	837.60 FL	*-FL
2	1		*FRONT FENDER LINER LH	Serviceable	47.00 FL	*-FL
3	1		*FRONT DOOR LH	Repair	1,133.00 FL	*-FL
4	1		*FRONT DOOR OUTER MOULDING LH	Serviceable	220.00 FL	*-FL
5	1		*FRONT DOOR OUTER HANDLE LH	Serviceable	125.00 FL	*-FL
6	1		*FRONT DOOR HANDLE SUPPORT LH	Serviceable	3.00 FL	*-FL
7	1		*FRONT DOOR OUTER HANDLE INNER SEAL LH	Serviceable	89.15 FL	*-FL
8	1		*FRONT DOOR OUTER KEY LOCK LH	Serviceable	25.00 FL	*-FL
9	1		*FRONT DOOR HINGE UPPER LH	Repair	65.00 FL	*-FL
10	1		*FRONT DOOR HINGE LOWER LH	Repair	65.00 FL	*-FL
11	1		*FRONT DOOR INNER LOCK LH	Serviceable	586.00 FL	*-FL
12	1		*FRONT DOOR INNER LOCK LATCH LH	Serviceable	206.00 FL	*-FL
13	1		*FRONT DOOR CHECK /ARRESTOR LH	Serviceable	67.50 FL	*-FL
14	1		*FRONT DOOR WEATHERSTRIP LH	Serviceable	138.79 FL	*-FL
15	1		*FRONT DOOR GLASS CHANNEL WEATHERSTRIP LH	Serviceable	160.00 FL	*-FL
16	1		*FRONT DOOR INNER TRIM BOARD LH	Serviceable	455.69 FL	*-FL
17	1		*FRONT DOOR WINDOW GLASS LH	Serviceable	456.12 FL	*-FL
18	1		*FRONT DOOR POWER WINDOW MOTOR (MASTER) LH	Serviceable	284.97 FL	*-FL
19	1		*FRONT DOOR POWER WINDOW MOTOR SWITCH	Serviceable	145.00 FL	*-FL
20	1		*FRONT DOOR WINDOW REGULATOR GEAR LH	Serviceable	84.58 FL	*-FL
21	1		*FRONT SIDE VIEW MIRROR LH	Mtg Distorted	939.00 FL	*939.00 FL
22	1		*SIDE ROCKER PANEL GARNISH LH	Serviceable	236.40 FL	*-FL
23	1		*SIDE ROCKER PANEL OUTER LH	Repair	433.26 FL	*-FL
24	1		*CENTRE PILLAR OUTER LH	Repair	446.00 FL	*-FL
25	1		*CENTRE PILLAR INNER LH	Repair	460.00 FL	*-FL
26	1		*REAR DOOR LH	Repair	1,133.00 FL	*-FL
27	1		*REAR DOOR INNER LOCK LH	Serviceable	425.00 FL	*-FL
28	1		*REAR DOOR CHECK /ARRESTOR LH	Serviceable	65.00 FL	*-FL
29	1		*REAR DOOR LOCK STRIKER /LATCH LH	Serviceable	120.00 FL	*-FL
30	1		*REAR DOOR OUTER WEATHERSTRIP MOULDING LH	Serviceable	85.00 FL	*-FL
31	1		*REAR DOOR OUTER HANDLE LH	Serviceable	60.00 FL	*-FL
32	1		*REAR DOOR OUTER HANDLE -RUBBER SEAL LH	Serviceable	25.00 FL	*-FL
33	1		*REAR DOOR INNER OPENING HANDLE LH	Serviceable	45.50 FL	*-FL
34	1		*REAR DOOR INNER TRIM BOARD LH	Serviceable	455.69 FL	*-FL
35	1		*REAR DOOR KICKING PLATE /STEP GARNISH LH	Serviceable	63.25 FL	*-FL
36	1		*REAR DOOR WINDOW GLASS CHANNEL WEATHERSTRIP LH	Serviceable	143.25 FL	*-FL
37	1		*REAR DOOR WINDOW GLASS CHANNEL HOLDER LH	Serviceable	205.60 FL	*-FL
38	1		*REAR DOOR CHANNEL WEATHERSTRIP /FELT LH	Serviceable	89.50 FL	*-FL
39	1		*REAR DOOR INTERIOR LIGHT SWITCH LH	Serviceable	139.20 FL	*-FL
40	1		*REAR DOOR POWER WINDOW MOTOR (MASTER) LH	Serviceable	274.97 FL	*-FL
41	1		*REAR DOOR REGULATOR GEAR LH	Serviceable	55.30 FL	*-FL
42	1		*REAR DOOR REGULATOR HANDLE LH	Serviceable	65.30 FL	*-FL
43	1		*REAR FENDER LH	Repair	1,145.00 FL	*-FL
44	1		*REAR FENDER INNER COWLING LH	Serviceable	76.60 FL	*-FL
45	1		*REAR TAIL LAMP LH	Serviceable	479.30 FL	*-FL
46	1		*REAR BUMPER	Serviceable	1,202.00 FL	*-FL
47	1		*REAR BUMPER SIDE RETAINER LH	Serviceable	68.76 FL	*-FL
48	1		*REAR BUMPER REFLECTOR LH	Serviceable	119.74 FL	*-FL
49	1		*SET FRONT FENDER LINER CLIP	Not Necessary	30.00 FS	*-FS
50	1		*SET REAR BUMPER PARKING SENSOR	Serviceable	300.00 FS	*-FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
51	1		*SET REAR BUMPER FASTENER CLIP	Not Necessary	30.00 FS	*- FS
52	1		*SET REAR FENDER LINER CLIP	Not Necessary	30.00 FS	*- FS
53	1		*DOOR STICKER TRANS-CAB	Not Necessary	80.00 FS	*- FS
54	1		*DOOR STICKER 6555-3333	Not Necessary	80.00 FS	*- FS
55	1		*SET SIDE ROCKER PANEL GARNISH CLIP LH	Not Necessary	60.00 FS	*- FS
56	1		*FRONT TYRE LH	Serviceable	360.00 FS	*- FS
57	1		*FRONT WHEEL RIM LH	Serviceable	254.00 FS	*- FS
58	1		*HUB CUP RIM FRONT LH	Serviceable	35.00 FS	*- FS
59	1		*REAR TYRE LH	Serviceable	360.00 FS	*- FS
60	1		*REAR WHEEL RIM LH	Serviceable	254.00 FS	*- FS
61	1		*HUB CUP RIM RR LH	Serviceable	35.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>16,159.02</b>	<b>939.00</b>
<b>- List Item Discount on L Items 10.00/10.00% (S\$)</b>	1,425.10	93.90
<b>Total Parts (S\$)</b>	<b>14,733.92</b>	<b>845.10</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	2,800.00	150.00
2	TO RUST PROOFING OF THE AFFECTED AREAS	New	220.00	0.00
3	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING	New	170.00	0.00
4	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	2,800.00	260.00
5	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
6	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
7	TO TRANSFER OF DOOR FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
8	TO TRANSFER OF FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>6,720.00</b>	<b>430.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >