



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SH 8536B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	L PRIG4 COVER FRONT BUMPER	REPLACED	367.87	367.87
1	L PRIG4 LAMP ASSY FOG RH	REPLACED	207.97	207.97
1	L PRIG4 UNIT ASSY HEADLAMP	SERVICEABLE	2,535.22	-
			3,111.06	575.84
	<u>LABOUR</u>			
	PANEL BEATING.		200.00	200.00
	SPRAY PAINT ON AFFECTED AREA.		180.00	180.00
	CHECK ALL LIGHTING.		20.00	20.00
			400.00	400.00
	GRAND TOTAL		3,511.06	975.84
	RECOMMENDED COST OF REPAIRS			975.84

Report Ref No. CS/CTI17013796/M1rbs2

MA CHIN FOOK

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.