

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG17013850/UPA3Q2
Date: 20/04/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100509519-00000
Claimant Vehicle No :	SLP4194X	Insured Vehicle No :	SLN8403C
Date of Loss:	16/07/2017	Nature of Claim:	TP
		Claim No:	5068756335SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLP4194X	Engine No:	2NRX146473
Make & Model:	TOYOTA VIOS, 1.5 E (A)	Chassis No:	MHFB29F3202009980
Reg. Date:	05/06/2017 (Man. Year: 2017)	Odometer:	2222 km
Colour:	Silver		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/50 R16	Rear Tyre Size:	195/50 R16
Front Left Side:	Bridgestone 9 mm	Rear Left Side:	Bridgestone 9 mm
Front Right Side:	Bridgestone 9 mm	Rear Right Side:	Bridgestone 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,841.70	658.62	1,183.08	64.24
Miscellaneous Items	0.00	0.00	0.00	
Labour	880.00	700.00	180.00	20.45
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,721.70	1,358.62	1,363.08	50.08
+ GST 7.00/7.00% (S\$)	190.52	95.10	95.42	50.08
Nett Amount (S\$)	2,912.22	1,453.72	1,458.50	50.08
+ Loss of Use (2.0 x S\$50.00/day) (S\$)		100.00		
+ Doc/Search Fee (S\$)		5.35		
Nett Liability (S\$)		1,559.07		
Global Sum Settlement (S\$)		1,470.00		

INSPECTION

Date of Assignment:	18/07/2017	
Date Inspected:	18/07/2017 Inspected At:	Stytech Auto Pte Ltd (HQ) 2 Kaki Bukit Ave 2 #02-30, Kaki Bukit Autohub Singapore 417921
Estimated Period of Repair:	2.0 days	

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented / Deformed	581.50 F	*581.50 FL
2	1		*SET REAR BUMPER CLIPS	Necessary	30.00 F	*30.00 FL
3	2		*REAR BUMPER RETAINERS	Not Necessary	264.20 F	*- FL
4	1		*REAR BUMPER REINFORCEMENT FRAME	Repair	374.50 F	*- FL
5	1		*SET REAR PANEL INNER GARNISH CLIPS	Not Necessary	20.00 F	*- FL
6	1		*REAR BOOTLID INNER LOCK	Not Necessary	371.50 F	*- FL
7	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	200.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	1,841.70	811.50
- List Item Discount on L Items 0.00/25.00% (S\$)	0.00	152.88
Total Parts (S\$)	1,841.70	658.62

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	20.00
2	TO SPRAY ANTI RUST PROOFING	New	50.00	0.00
3	PANEL BEATING	New	300.00	280.00
4	TO PUTTY & SPRAY PAINTING	New	480.00	400.00
			Gross Labour Cost (\$\$)	700.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >