

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III17013931/GGA3Q2

Date: 15/05/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0016
Claimant		
Vehicle No : SFG9990A	Insured Vehicle No :	SH7873J
Date of Loss: 14/07/2017	Nature of Claim: TP	Claim No: MCT17070480

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SFG9990A	Engine No:	B369I219N46B20BD
Make & Model:	BMW 320I, 2.0 (A)	Chassis No:	WBAVG76020NL65975
Reg. Date:	26/11/2008 (Man. Year: 2008)	Odometer:	158648 km
Colour:	White		
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/40 R18	Rear Tyre Size:	235/40 R18
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,687.00	2,855.06	4,831.94	62.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,350.00	1,520.00	1,830.00	54.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	11,037.00	4,375.06	6,661.94	60.36
Approved Total (Overridden) (\$\$)		3,500.00		
(\$\$)	11,037.00	3,500.00	7,537.00	68.29
+ GST 7.00/7.00% (\$\$)	772.59	245.00	527.59	68.29
Nett Amount (\$\$)	11,809.59	3,745.00	8,064.59	68.29
+ Car Rental (5.0 x \$110.00/day) (\$\$)		550.00		
Nett Liability (\$\$)		4,295.00		

INSPECTION

Date of Assignment:	18/07/2017	
Date Inspected:	18/07/2017 Inspected At:	160 SIN MING DRIVE #05-08 SIN MING AUTOCITY SINGAPORE 575722
		Repairer: Kum Chew Motor Workshop (HQ)
Estimated Period of Repair:	4.0 days	

Adjuster: XING GUO QIANG**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 03 May 2020)
Parts:	143	BMW 320I 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SFG9990A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR LID	Bent	1,129.00 F	*1,129.00 FL
2	1		*REAR LID LOCK	Not Necessary	93.00 F	*- FL
3	2		*REAR LID HINGE	Not Necessary	154.00 F	*- FL
4	1		*REAR LID CATCH	Not Necessary	55.00 F	*- FL
5	1		*REAR LID RUBBER	Twisted	81.00 F	*81.00 FL
6	2		*REAR LID REFLECTOR	Not Necessary	384.00 F	*- FL
7	1		*REAR LID EMBLEM	Necessary	68.00 F	*68.00 FL
8	1		*REAR LID 320I EMBLEM	Not Necessary	62.00 F	*- FL
9	1		*REAR LID BMW EMBLEM	Not Necessary	68.00 F	*- FL
10	2		*REAR LAMP	Not Necessary	560.00 F	*- FL
11	1		*REAR END PANEL	Not Necessary	810.00 F	*- FL
12	1		*REAR END PANEL INNER GARNISH	Not Necessary	79.00 F	*- FL
13	1		*REAR BUMPER	Deformed	1,090.00 F	*1,090.00 FL
14	1		*REAR BUMPER REINFORCEMENT	Not Necessary	414.00 F	*- FL
15	2		*REAR BUMPER RETAINER	Deformed	112.00 F	*84.40 FL
16	2		*REAR BUMPER BRACKET	Not Necessary	64.00 F	*- FL
17	1		*REAR BUMPER LOWER COVER	Not Necessary	62.00 F	*- FL
18	1		*REAR BUMPER BRACKET -CENTRE	Cracked	31.00 F	*31.00 FL
19	2		*REAR FENDER DUST COVER	Not Necessary	274.00 F	*- FL
20	2		*REAR LID SUSPENSION	Not Necessary	204.00 F	*- FL
21	4		*REVERSE SENSOR	Damaged	928.00 FS	*200.00 FS
22	1		*REAR BUMPER LOWER LIP	Cracked	880.00 FS	*400.00 FS
23	1		*REAR BUMPER LOWER LIP SEAL	Damaged	85.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,687.00	3,103.40
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	248.34
Total Parts (\$\$)	7,687.00	2,855.06

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO PULL KNOCK ON ACCIDENT PORTION & CHANGE ABOVE PART	New	1,200.00	600.00
2	TO SPRAY & PAINT ON ACCIDENT PORTION	New	1,500.00	800.00
3	TO ANTI-RUST REAR AFFECTED AREAS	New	200.00	0.00
4	TO CHECK WIRING FUNCTIONS	New	150.00	30.00
5	TO DISMANTLE & REFIX REVERSE SENSOR	New	120.00	40.00
6	TO DISMANTLE & REFIX REAR BUMPER LOWER LIP	New	180.00	50.00
Gross Labour Cost (\$\$)			3,350.00	1,520.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >