

ASS. RFC. BY:

REF: CS/TC17014110/R116072

Special Instruction:

Survivor:

Rasul

ASSIGNMENT (Office)

From (Person): LWS Sithara of FCL

Date/Time: 20072017 530pm

Estimated Cost: Bill to:

OD / TP AWS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKR 6201Y

Insured: SHA 93728

at Workshop m/s Perfurmanu

Tel: 6319 0174

of 303 Alexandra Road

Policy No:

Claim No:

D17007049MF64

Sum Insured:

Excess:

Make of Veh:

D.O.A.

15072017

(Client's Record)

CA / REV / REP. / REV 24 HRS 'DS'

24.07.2017

H.O.D. Endorsement:

Date/Time: 20072017 534pm

Person Contacted:

Caroline

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate	Inthiran
	SKR 6201Y - X	
	SHA 93728 - CS/TC17014132 / R116072	DIA: 120617
	Part by part \$11,621.40 (red: 7821.90 : 40%)	

Signature: *[Signature]*

REF: FC1

59440

ASSIGNMENT

From: _____ Date: 24/12/17
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SKR 62014
 at Workshop m/s: Perfurman
 of: 303 Alexandra Rd
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: Intrivan

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS '13'

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKR 62014 Yr Regn: 2015 / FGB
 Type: M / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: B.M.W 218i c.c. 1499
 Colour: GRN A/C: Insured / Std / NI / NA
 Sp. Reading: 35763 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: WBA 2A32050V 250665
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 205/60R16
 R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front Rear
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 15/07/17 D.O.I. 24/07/17
 Survey held at Perfurman
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 18 DEC 2017

Date/Time. File Pass to?

☐ : Preli. Report
☒ : Final Report

Days Of Repair: 7

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

Photos

Others

TOTAL

Add Fee:

☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

Report Format : TP

Lump Sum / B.I. (\$ 11,681.40)

9x15-135
170 + 135
50
50
61
466



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI17014110/R1tb

36 ROBINSON ROAD

#16-01 CITY HOUSESINGAPORE 068877

Date : 20-07-2017



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 9372S	Veh. Inspected	SKR 6201Y
Policy No.		Coverage (\$)	0.00
Claim No.	D17007049MFSH	Excess (\$)	0.00
Assign From	CWS (SITHARA)	Assign Date	20/07/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	15/07/2017	Inspection Date
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941	

5a. Remarks

--

MOTOR SURVEY ASSIGNMENT

Date	18-07-2017	Our Ref No. D17007049MFSH
Accident Date	15-07-2017	Claim Type. Third Party
Insured Vehicle	SHA9372S	Third Party Vehicle. SKR6201Y
Survey Location	303 ALEXANDRA ROAD SIME DARBY PERFORMANCE CENTRE	
Contact Person.	CAROLINE	
Contact No.	63190174/ 0	Fax No. 64794601
Survey Type	DIRECT SETTLEMENT:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PERFORMANCE MOTORS LIMITED	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SITHARA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/225862)



PRI Documents



Close X

PRI Header Details

Claim No	D17007049MFSH	Policy No	D-15072702MFSH	Claimant S.No & Name	1 & PEI LIMITE
Workshop Name	PERFORMANCE MOTORS LIMITED (Contact Person : CAROLINE)	Survey Location & Contact Details	303 ALEXANDRA ROAD SIME DARBY PERFORM Mobile: 0 , Phone: 63190174 , Fax: 6479460 EmailId: PML-PBSP@SIMEDARBY.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	DIRECT SETTLEMENT:		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHA9372S	TP Vehicle No	SKR621
PRI Recieved Date	20-07-2017 05:04:08 PM	Surveyor Appointed Date	20-07-2017 05:30:01 PM	Surveyor Accept Date	20-07-

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	20-07-2017	Upload Survey Report *:	
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make ▾	Model	Please Select Model ▾	Year	Select
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

Upload Multiple Documents

File Name

Action

Surveyor Job Remarks

Performance Motors Limited

A member of the Sime Darby Group.
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63448773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159941
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

20 JUL 2017

Estimate No. : b1 43488
Date Estimated : 20/07/2017
Prepared By : Inthiran A/L Thurasamy

Page No. : 1 of 2

- ESTIMATE REPAIR FOR -
Michelle Anne Ng Chai Ping
159 Hougang Street 11
#10-25

singapore 530159

- ACCOUNT - 303
First Capital Insurance Ltd
36 Robinson Road
#16-01 City House
Singapore 068877

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKR6201Y	VZ50665	26/02/2015	218iA AT	0

DESCRIPTION

To replace rear bumper, tailgate, tail panel and attachments including knock out dent area cause by accident.

Painting rear bumper, tailgate, tail panel and trunk floor.

To remove and install boot compartment carpet and garnish to facilitate repairs.

To remove and install rear windscreen glass including conduct water leak tests.

To reconnect electrical components and wirings at the rear section including conduct checks for proper function.

To transfer lock mechanism from old to new bootlid including conduct checks on new bootlid central locking system for proper function.

To replace bootlid smart opener control unit, top and bottom sensor lines including program and conduct checks for proper function.

To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function.

To carry out body cavity preservation.
(Per panel).

To carry out body cavity preservation.
(For cut panel).

Sundries.

VALUE

2550 5,525.00

4250 7X11

2399-2877 3,197.00

230 271.00

230 271.00

300 649.00

150 354.00

451 531.00

561 661.00

561 661.00

150 177.00

150 177.00

150 177.00

150 177.00

150 177.00

150 177.00

150 177.00

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Claim No. _____

Date & Time 24/07/17 12:00

Surveyor's Name [Signature]

Surveyor's Tel 90010068

Authorised Yes / No

Time _____

EE / RV PARTS PHOTO BY SURVEYOR YES / NO

Surveyor's E-mail _____

No. of Working Days Recommend 7 days

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

115, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 43488
Date Estimated : 20/07/2017
Prepared By : Inthiran A/L Thurasamy

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKR6201Y	VZ50665	26/02/2015	218iA AT	0

Total Labour 1: 12,164.00

DESCRIPTION

QTY PRIC VALUE

TRUNK LID	1	1,146.30	BA 1,146.30
TAIL PANEL	1	299.60	R 299.60
REAR BUMPER PANEL PRIMED (PDC)	1	942.75	DE 942.75
RR BUMPER LH SIDE GUIDE	1	46.65	? 46.65
RR BUMPER RH SIDE GUIDE	1	46.65	? 46.65
REAR BUMPER CARRIER	1	413.45	? 413.45
SUPPORT	1	36.40	CRA 36.40
RR BUMPER LH INNER SIDE GUIDE	1	57.15	CRA 57.15
RR BUMPER RH INNER SIDE GUIDE	1	57.15	CRA 57.15
SET MOUNTS PDC SENSOR REAR	1	62.50	ne 62.50
LETTERING 218 I	1	61.05	ne 61.05
GROMMET	2	0.75	ne 1.50
BADGE (BMW)	1	67.80	ne 67.80
LOCK TRUNK LID	1	196.65	? 196.65
BUMP STOP	10	3.25	? 32.50
REAR FLAP TOWING EYE PRIMED	1	27.10	? 27.10
CONTROL UNIT SMART OPENER	1	457.45	X 457.45
RR LH LIGHT IN THE TRUNK LID	1	239.85	X 239.85
RR RH LIGHT IN THE TRUNK LID	1	239.85	X 239.85
RR LH LIGHT IN THE SIDE PANEL	1	342.60	X 342.60
RR RH LIGHT IN THE SIDE PANEL	1	342.60	X 342.60
DECOUPLING RING PDC TORQUE CONVERTER	4	4.95	ne 19.80
Ultrasonic s	13	374.60	1123.80 ne 1,498.40
BLIND RIVET AVIBVLB	19	0.55	5.50 11.00 ne 10.45
SCREW (SF PLUS M5X15)	5	0.55	5.50 ne 2.75
(DG/SL) BODY ADHESIVE K5B (195ML)	1	281.55	ne 281.55
PUNCH RIVET N4	19	0.55	ne 10.45
(DG) CLEANER R1 (100ML)	1	23.85	47.70 ne 23.85
(DG) CLEANER R1 (100ML)	1	23.85	ne 23.85
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	2	131.55	ne 263.10
(DG/SL) GLASS PRIMER 30ML (VP206)	1	27.85	ne 27.85

Total Parts : 7,279.60

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Labour 1	:	12,164.00
Parts	:	7,279.60
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	1,361.05
Grand Total	:	20,804.65

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

19503-30

19514-95

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : b1 43488
Date Estimated : 20/07/2017
Prepared By : Inthiran A/L Thurasamy

Page No. :

REPAIR FOR -

Michelle Anne Ng Chai Ping
159 Hougang Street 11
#10-25

singapore 530159

- ACCOUNT - 303

First Capital Insurance Ltd
36 Robinson Road
#16-01 City House
Singapore 068877

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEASE
SKR6201Y	VZ50665	26/02/2015	218iA AT	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
To replace rear bumper and attachments, boot lid and attachments include making good the tail end panel and knocking out dents caused by the accident	2550.00		2,550.00	
To spray paint rear bumper, boot lid and tail end panel	2399.00		2,399.00	
To remove and install boot compartment carpet and garnish to facilitate repairs	230.00		230.00	
To remove and install rear windscreen glass to facilitate repairs include conducting water leak tests.	649.00		649.00	
To reconnect electrical components and wirings at the rear section including conduct checks for proper function.	150.00		150.00	
To transfer lock mechanism from old to new boot lid including conduct checks on new boot lid central locking system for proper function.	451.00		451.00	
To remove and install boot lid smart opener assembly to facilitate repairs include programming and conducting checks for proper function	561.00		561.00	
To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function.	150.00		150.00	
To carry out body cavity preservation. (Per panel).	100.00		100.00	
Sundries.	150.00		150.00	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
BLIND RIVET NUT M6	2.60	3.00		7.80
TRUNK LID	1,146.30	1.00		1,146.30
REAR BUMPER PANEL PRIMED (PDC)	942.75	1.00		942.75
# EXPANDING NUT *	1.00	2.00		2.00

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559N. GST Reg. No. M2-0020081-X



SUPPLEMENTARY

Estimate No. : b1 43488
Date Estimated : 20/07/2017
Prepared By : Inthiran A/L Thurasamy

Page No. :

REPAIR FOR -
Michelle Anne Ng Chai Ping
159 Hougang Street 11
#10-25

- ACCOUNT - 303
First Capital Insurance Ltd
36 Robinson Road
#16-01 City House
Singapore 068877

singapore 530159

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEAGE
SKR6201Y	VZ50665	26/02/2015	218iA AT	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# EXPANDING NUT *	1.00	2.00		2.00
# REAR BUMPER HEAT INSULATOR *	57.70	1.00		57.70

Total Labour :	0.00
Total Parts :	59.70
Total Labour & Parts :	59.70

3(A) new
PA ✓

Performance Motors Limited

A member of the Sims Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



FINAL REPORT

SUPPORT	36.40	1.00	36.40
RR BUMPER LH INNER SIDE GUIDE	57.15	1.00	57.15
RR BUMPER RH INNER SIDE GUIDE	57.15	1.00	57.15
SET MOUNTS PDC SENSOR REAR	62.50	1.00	62.50
LETTERING 218 I	61.05	1.00	61.05
GROMMET	0.75	2.00	1.50
BADGE (BMW)	67.80	1.00	67.80
# REAR BUMPER HEAT INSULATOR *	57.70	1.00	57.70
DECOUPING RING PDC TORQUE CONVERTER	4.95	4.00	19.80
ULTRASONIC SENSOR PLATINSILVER (WCO	374.60	3.00	1,123.80
BLIND RIVET AVIBVLB	0.55	20.00	11.00
SCREW (SF PLUS M5X15)	0.55	10.00	5.50
(DG/SL) BODY ADHESIVE K5B (195ML)	281.55	1.00	281.55
PUNCH RIVET N4	0.55	20.00	11.00
(DG) CLEANER R1 (100ML)	23.85	2.00	47.70
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	131.55	2.00	263.10
(DG/SL) GLASS PRIMER 30ML (VP206)	27.85	1.00	27.85

SUPPLEMENTARY ITEMS

Total Labour :	7,390.00
Total Parts :	4,291.40
Total Labour & Parts :	11,681.40
Deduction for Excess :	0.00
Total Repair Costs less Excess:	11,681.40
GST @7%:	817.70
Grand Total :	12,499.10



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI17014110/R1tbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 20-12-2017	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 9372S	Veh. Inspected	SKR 6201Y	
Policy No.	D-15072702MFSH	Coverage (\$)	0.00	
Claim No.	D17007049MFSH	Excess (\$)	0.00	
Assign From	SITHARA	Assign Date	20/07/2017	
2. Vehicle Particulars & Condition				
Make & Model	B.M.W 218i	c.c	1499	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	WBA2A32050VZ50665	Colour	GREY	
Odometer	35763	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	GOODYEAR	6 mm	
L/H Front Tyre	205/60 R16	GOODYEAR	6 mm	
R/H Rear Tyre	205/60 R16	GOODYEAR	6 mm	
L/H Rear Tyre	205/60 R16	GOODYEAR	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	15/07/2017	Inspection Date	24/07/2017	
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKR 6201Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	TRUNK LID (SN)	BENT	1,146.30	1,146.30
1	TAIL PANEL (SN)	SERVICEABLE	299.60	-
1	REAR BUMPER PANEL PRIMED (PDC)(SN)	DEFORMED	942.75	942.75
1	RR BUMPER LH SIDE GUIDE (SN)	SERVICEABLE	46.65	-
1	RR BUMPER RH SIDE GUIDE (SN)	SERVICEABLE	46.65	-
1	REAR BUMPER CARRIER (SN)	SERVICEABLE	413.45	-
1	SUPPORT (SN)	CRACKED	36.40	36.40
1	RR BUMPER LH INNER SIDE GUIDE (SN)	CRACKED	57.15	57.15
1	RR BUMPER RH INNER SIDE GUIDE (SN)	CRACKED	57.15	57.15
1	SET MOUNTS PDC SENSOR REAR (SN)	NECESSARY	62.50	62.50
1	LETTERING 218 I (SN)	NECESSARY	61.05	61.05
2	GROMMET (SN)	NECESSARY	1.50	1.50
1	BADGE (BMW)(SN)	NECESSARY	67.80	67.80
1	LOCK TRUNK LID (SN)	SERVICEABLE	196.65	-
10	BUMP STOP (SN)	SERVICEABLE	32.50	-
1	REAR FLAP TOWING EYE PRIMED (SN)	SERVICEABLE	27.10	-
1	CONTROL UNIT SMART OPENER (SN)	SERVICEABLE	457.45	-
1	RR LH LIGHT IN THE TRUNK LID (SN)	SERVICEABLE	239.85	-
1	RR RH LIGHT IN THE TRUNK LID (SN)	SERVICEABLE	239.85	-
1	RR LH LIGHT IN THE SIDE PANEL (SN)	SERVICEABLE	342.60	-
1	RR RH LIGHT IN THE SIDE PANEL (SN)	SERVICEABLE	342.60	-
4	DECOUPING RING PDC TORQUE CONVERTER (SN)	NECESSARY	19.80	19.80
4	ULTRASONIC S (SN)	NECESSARY (3 PCS ONLY)	1,498.40	1,123.80
19	BLIND RIVET AVIBVLB (SN)	NECESSARY	11.00	11.00
5	SCREW (SF PLUS M5X15)(SN)	NECESSARY	5.50	5.50
1	(DG/SL) BODY ADHESIVE K5B (195ML)(SN)	NECESSARY	281.55	281.55
19	PUNCH RIVET N4 (SN)	NECESSARY	11.00	11.00
1	(DG) CLEANER R1 (100ML)(SN)	NECESSARY	23.85	23.85
1	(DG) CLEANER R1 (100ML)(SN)	NECESSARY	23.85	23.85
2	(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)(SN)	NECESSARY	263.10	263.10

Report Ref No. CS/FCI17014110/R1tbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	(DG/SL) GLASS PRIMER 30ML (VP206)(SN)	NECESSARY	27.85	27.85
1	SUNDRIES (SN)	NECESSARY	150.00	150.00
3	BLIND RIVET NUT M6 (ADDITIONAL)(SN)	NECESSARY	7.80	7.80
2	EXPANDING NUT (ADDITIONAL)(SN)	NECESSARY	2.00	2.00
1	REAR BUMPER HEAT INSULATOR (ADDITIONAL)(SN)	BENT	57.70	57.70
			7,500.95	4,441.40
	LABOUR			
	TO REPLACE REAR BUMPER, TAILGATE TAIL PANEL AND ATTACHMENTS INCLUDING KNOCK OUT DENT AREA CAUSED BY ACCIDENT.		5,525.00	2,550.00
	PAINTING REAR BUMPER, TAILGATE, TAIL PANEL AND TRUNK FLOOR.		3,197.00	2,399.00
	TO REMOVE AND INSTALL BOOT COMPARTMENT CARPET AND GARNISH TO FACILITATE REPAIRS.		271.00	230.00
	TO REMOVE AND INSTALL REAR WINDSCREEN GLASS INCLUDING CONDUCT WATER LEAK TEST.		649.00	649.00
	TO RECONNECT ELECTRICAL COMPONENTS AND WIRINGS AT THE REAR SECTION INCLUDING CONDUCT CHECKS FOR PROPER FUNCTION.		354.00	150.00
	TO TRANSFER LOCK MECHANISM FROM OLD TO NEW BOOTLID INCLUDING CONDUCT CHECKS ON NEW BOOTLID CENTRAL LOCKING SYSTEM FOR PROPER FUNCTION.		531.00	451.00
	TO REPLACE BOOTLID SMART OPENER CONTROL UNIT, TOP AND BOTTOM SENSOR LINES INCLUDING PROGRAM AND CONDUCT CHECKS FOR PROPER FUNCTION.		661.00	561.00
	TO REMOVE OLD PDC ASSEMBLY, REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECKS FOR PROPER FUNCTION.		177.00	150.00
	TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL).		118.00	100.00
	TO CARRY OUT BODY CAVITY PRESERVATION (FOR CUT PANEL).	NOT NECESSARY	531.00	-
			12,014.00	7,240.00
	GRAND TOTAL		19,514.95	11,681.40
	RECOMMENDED COST OF REPAIRS			11,681.40

Report Ref No. CS/FCI17014110/R1tbn2



Report Ref No. CS/FCI17014110/R1tbn2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.