



REF

CG/CTU4014543 / 110622

Special Instructions:

Surveyor

Tawfik

ASSIGNMENT (Office)

Menmen

From (Person):

Irene Tay

of

CI

Date/Time:

28072017 1:26pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

EK 16M

Insured:

SKT 8906Z

at Workshop m/s

Cheng Auto

Tel:

6631 0702

of

5 Soon Lee St #01-62

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

D.O.A. 22072017

(Client's Record)

CA / REV / REP. / REV 24 HRS wpi

H.O.D. Endorsement:

Date/Time:

28072017 1:37pm

Person Contacted:

Michael

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	EK 16M - x
	SKT 8906Z - x
	Confirm \$12,260.14, 10 days
	Red: \$7091.44, 37%

Toufik

REF:

CT

ASSIGNMENT

From: Date:
Estimated Cost:
OO / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value: 8/148K (Toufik)

IDAC Accident Report Consistent? Yes or No

GIA / PR Seen Consistent? Yes or No

Est. Repairs: days Res: Yes or No

Lum Sum % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date Person Contacted

Vehicle: IN / OUT

Veh No: EK16M

Yr Regn 20/6 March.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make Toyota Alphard

cc 2493

Colour white.

A/C Insured / Std / NI / NA

Sp Reading 36021

T Radio: Insured / Std / NI / NA

Eng No:

C No:

Gen Cond Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod Nil / S/Rim / STD A/Rim or

Tyre Size F:

235/50R18

R:

BS DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R Bal

R Bal

L Bal

L Bal

D.O.A.

D.O.I.

Survey held at

Des. of Damages (Prt) Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

MV: \$178K, LTA: \$72,858.00, NV: \$105,142.00

Resurvey 1/8/17

RECEIVED 30 MAY 2018

Date/Time File Pass to?



Prel. Report

1: Trip 1st



Final Report

Date/Time File Return to?

2:

Report Format:

TP

Lump Sum / I.B.I: (\$ 12,249.64)

Days Of Repair: 10

Resurvey No. of Trip: 1

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Survey Fee:

Transportation

) \$ + RS \$

) Photo

) Others

TOTAL

250

250



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CS/CTI17014573/T1rb		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 28-07-2017		
		Code : CTI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKT 8906Z	Veh. Inspected	EK 16M	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From	MERIMEN (IRENE TAY)	Assign Date	28/07/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	22/07/2017	Inspection Date	28/07/2017	
Survey held at	CHENG AUTO BODYWORKS 1 SOON LEE STREET #06-41 PIONEER CENTRE SINGAPORE 627605			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

TP / CT 1
3.11.11
P/P

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	24/07/2017 11:40
Date Of Accident	22/07/2017 12:00
Exact Location Of Accident	AFTER JUNCTION- UPPER SERANGOON RD/HOUGANG ST 21
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	EK16M
Insured/Policyholder	
Name Of Registered Owner	LOW KWEE HONG (LIU GUIHONG)
NRIC No	S7912509A
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97310223
Alternative Phone No	OFFICE-97310223

Vehicle Particulars

Manufacturer	TOYOTA
Model	ALPHARD-2.5 (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5089247179

Cover Note Number

Driver

Name of Driver	LOW KWEE HONG (LIU GUIHONG)
NRIC No	S7912509A
Date Of Birth	20/04/1979
Occupation	INDOOR
Date Of Driving Pass	30/06/1998
Driving Experience	19 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97310223
Fax Number	
Contact Number	OFFICE-97310223
Email Address	NOEMAIL

CHENG AUTO BODYWORKS
5 Soon Lee Street #01-62
Pioneer Point
Singapore
627607

Claim Reference:
Assessment Number: GR000076
Version: CHENGABS/1
Date Calculated: 25/07/2017 11:04

Full Report - V1
Registration: EK16M
Printed: 25/07/2017 18:04

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	Cheng Auto Admin 2	Date of Incident:	22/07/2017
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	China Taiping Insurance (S) Pt	Repairs Authorised:	TBA
Claim Reference:		Estimated Repair Time:	
Policy Number:	5089247179	Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:	True	Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle

Manufacturer:	TOYOTA
Model:	Previa
Sub Model:	GL
Model Sheet Number:	Y92 05
Registration:	EK16M
Registration Month:	March
Registration Year:	2016
VIN Number:	
Manufacture Year:	2015
Odometer:	Not Known
Colour:	
Engine Number:	
Fuel Level:	%

Model Specs

FROM 01/2010	PARK CONTROL SENSOR
2.4 LTR 117/125 KW	TWO COAT METALLIC

Taigluh 97495749
WP
22/7/17 @ 1445.
Resuming before paint
10 days
Sur @ kkauto.com

Vehicle Condition

Vehicle Status

Pre-Accident Condition:	Severity of Impact:
Steering:	Vehicle Status on Inspection:
Brakes Pedal Travel:	Date of Inspection:
Place of Inspection:	25/07/2017
Pre-Accident Damage:	
Tyres Condition:	
Tread Depth LHF:	Tread Depth RHF:
Tread Depth LHR:	Tread Depth RHR:
Damage Areas:	Direction of Impact:

CHENG AUTO BODYWORKS

Claim Reference:

Assessment Number: GR000076


Version: CHENGABS/1

Date Calculated: 25/07/2017 11:04

Full Report - V1

Registration: EK16M

Printed: 25/07/2017 18:04

**Addresses****Cost Summary**

Total Labour	\$1,881.40
Total Paint/Material	\$244.29
Total Parts	\$15,528.89
Total of Additional Costs	\$1,697.00
Excess:	TBA
Grand Total Exc GST:	\$19,351.58
0 % GST:	\$0.00
Grand Total Inc GST:	\$19,351.58

Repair Information**LABOUR**

Time Basis 10 WU = 1 HR. Price/CL 1 = \$46.00/HR
Price/Dent = \$46.00/HR

Repair /**Guide Number Repair Details**

		WU	Cost Price (\$)
NO NUMBER	ADJUST HEADLAMP	2.0	9.20
B010)	R + R FRONT BUMPER	5.0	23.00
	NOT INCLUDED: RADIATOR GRILLE R + R		
B020)	RENEW FRONT BUMPER (REMOVED)	6.0	27.60
	INCLUDES: REQUIRED ATTACHED PARTS		
	REMOVE AND REFIT		
	NOT INCLUDED: PARKING HELP SENSOR		
	REMOVE AND REFIT		
B020	R + R FRONT OUTER PARKING AID SENSOR/S	1.0	4.60
NO NUMBER	R + R FRONT BUMPER ATTACHED PARTS	2.0	9.20
750011	R + R RADIATOR BADGE	3.0	13.80
	INCLUDES: R + R RADIATOR GRILLE		
B010)	R + R FRONT BUMPER REINFORCEMENT	2.0	9.20
B040)	R + R LEFT HEADLAMP	1.0	4.60
	(BUMPER REMOVED)		
	DOES NOT INCLUDE: ADJUST HEADLAMP		
B020)	RENEW FRONT BUMPER REINFORCEMENT	1.0	4.60
B040)	R + R HEADLAMPS	1.0	4.60
B040)	R + R RIGHT HEADLAMP	1.0	4.60
	(BUMPER REMOVED)		
	DOES NOT INCLUDE: ADJUST HEADLAMP		
B290)	RENEW REAR END PANEL CPL	32.0	147.20
B390	RENEW TAILGATE	20.0	92.00
	INCLUDES: R + R AND ALIGN TAILGATE,		
	CONVERT ATTACHED PARTS, RENEW IF		
	NECESSARY		

CHENG AUTO BODYWORKS

Claim Reference:

Assessment Number: GR000076

Version: CHENGABS/1

Date Calculated: 25/07/2017 11:04

Full Report - V1

Registration: EK16M

Printed: 25/07/2017 18:04

NO NUMBER	R + R REFLECTOR	2.0	9.20
B400	R + R L/TAILGATE HINGE	1.0	4.60
B400	R + R RIGHT TAILGATE HINGE	1.0	4.60
G040	R + R REAR SCREEN	23.0	105.80
B410	R + R REAR BUMPER	4.0	18.40
B420)	RENEW REAR BUMPER (REMOVED)	1.0	4.60
	INCLUDES: REQUIRED ATTACHED PARTS		
	REMOVE AND REFIT		
	NOT INCLUDED: PARKING HELP SENSOR		
	REMOVE AND REFIT		
NO NUMBER	R + R REAR PARKING AID SENSORS ADD/WORK	2.0	9.20
B407	R + R LEFT TAILLAMP	1.0	4.60
NO NUMBER	RENEW L/BUMPER IMPACT DAMPER	2.0	9.20
NO NUMBER	RENEW R/BUMPER IMPACT DAMPER	2.0	9.20
B407	R + R RIGHT TAILLAMP	1.0	4.60
642101	R + R TAILGATE SEAL	2.0	9.20
642371)	R + R REAR LOCK STRIKER PLATE	1.0	4.60
743921	R + R END PANEL TRIM	2.0	9.20
NO NUMBER	R + R LUGGAGE COMPARTMENT COVER	1.0	4.60
NO NUMBER	DETACH + REFIT REAR FLOOR CARPET	3.0	13.80
M010	R + R CONDENSER	22.0	101.20
M010	DRAIN AIR CONDITIONING	7.0	32.20

LABOUR COST

Total Work Units

155.0

Corrosion Protection External Labour

0.0HRS

0.00

Corrosion Protection Internal Labour

0.0HRS

0.00

Sub Total

15.5HRS

\$713.00

Paint Labour

25.4HRS

\$1,168.40

Total Labour

40.9HRS

\$1,881.40

PAINT WORK

Guide Number Description

Time Basis 10 WU = 1 HR. Price = \$46.00/HR

WU

Cost Price (\$)

	- TWO COAT METALLIC		
420	FRONT BUMPER SUPPORTSURFACE PAINT	5.0	
2741	REAR PANEL NEW PART PAINTING	16.0	
2931	BOOTLID/TAILGATE NEW PART PAINTING	18.0	
283	FRONT BUMPER NEW PART PAINT K1R	13.0	
410	GRILLE NEW PART PAINT K1R	3.0	
2583	REAR BUMPER NEW PART PAINT K1R	11.0	
3485	L/R LOWER SIDE PANELSURFACE PAINT	6.0	
3486	R/R LOWER SIDE PANELSURFACE PAINT	6.0	
1000	RR RH FEND CVR NEW PART PAINT	10.0*	
1000	RR LH FEND CVR NEW PART PAINT	10.0*	
1000	SURFACE PAINTING NEW PART PAINT	130.0*	

LABOUR COST - PAINT

TIME(PAINT)

228.0

Preparation Main Work Metal

21.0

Preparation Comp. Work Plastic

5.0

Preparation Work Multi Layer Paint

0.0

Total Work Units (10WU/HR)

254.0

Total Paintwork Labour

25.4HRS

\$1,168.40

CHENG AUTO BODYWORKS

Claim Reference:

Assessment Number: GR000076

Version: CHENGABS/1

Date Calculated: 25/07/2017 11:04

Full Report - V1

Registration: EK16M

Printed: 25/07/2017 18:04

MATERIAL COST - PAINT

New Part Painting
New Part Painting - Plastic K1R
Surface-/Blend Paint
Material-Const Main Work Metal
Material-Const Comp. Work Plastic
Total Excluding Pearlescent Uplift
Pearlescent Uplift @ 0.0%
Total Paint Material Cost

Cost Price
\$70.20
\$116.61
\$30.38
\$18.10
\$9.00
\$244.29
\$0.00
\$244.29

PARTS

Guide No.	Qty	Description	Part Number	Supplier	Price Valid: 01/06/2015	Bet.	Price (\$)
258	1	FRT NO PLATE REINF	KNPLD	NO PLATE GARNISH	0%	int	128.00*
283	1	FRONT BUMPER	52119 28977		0%	de	900.00*
297	1	LWR RADIATOR GRILLE	53112 28110	BUMPER LWR GRILLE	0%	ch	95.00*
299	1	L/FOG LAMP COVER	81482 28260	FOGLAMP INSERT	0%	?	120.00*
300	1	R/FOG LAMP COVER	81481 28260		0%	?	120.00*
319	1	L/F OUT BUMPER BRKT	52116 28170	BUMPER RETAINER	0%	na	45.00*
320	1	R/F BUMPER OUT BRKT	52115 28070		0%	na	45.00*
333	1	FRT BUMPER ABSORBER	52611 28081	FRT SPONGE	0%	?	50.00*
350	1	FRT BUMPER CLAMP KIT	USE SINGLE PARTS		0%	na	20.00*
410	1	GRILLE	53101 28472A0	CENTRE GRILLE	0%	gry	550.00*
420	1	FRONT BUMPER SUPPORT	52021 28221	FRT REINFORCEMENT	0%	?	250.00*
431	1	GRILLE BADGE	75301 28151	EMBLEM GRILLE	0%	na	180.00*
561	1	LEFT HEADLAMP ASSY	81170 28C11		0%	X nh	1,600.00*
562	1	RIGHT HEADLAMP ASSY	81130 28C11		0%	704	1,600.00*
647	1	L/F FOG LAMP	81220 0D042		0%	X nh	220.00*
648	1	R/F FOG LAMP	81210 0D042		0%	X nh	220.00*
2583	1	REAR BUMPER	52159 28915		0%	de	900.00*
2619	1	L/R BUMPER BRACKET	52156 28050		0%	na	65.00*
2620	1	R/R BUMPER BRACKET	52155 28080		0%	na	65.00*
2623	1	L/R INN BUMPER BRKT	52155 28090	REAR BUMPER RETAINER	0%	na	65.00*
2624	1	R/R INN BUMPER BRKT	52156 28060		0%	na	65.00*
2641	1	L/R IMPACT DAMPER	52616 28010	TAILGATE ABSORBABLE	0%	X nh	175.00*
2642	1	R/R IMPACT DAMPER	52615 28040		0%	X nh	175.00*
2650	1	RR BUMPER CLAMP KIT	USE SINGLE PARTS		0%	na	20.00*
2741	1	REAR PANEL	58307 28110	END PANEL	0%	bl	450.00*
2931	1	BOOTLID/TAILGATE	67005 28C90		0%	bl	1,050.00*
2944	1	BOOT/TAILGATE SEAL	67881 28120	TAILGATE RUBBER	0%	na	190.00*
2953	1	L/R HINGE	68810 02020	TAILGATE HINGE	0%	Ry	45.00*
2954	1	R/R HINGE	68810 02020		0%	Ry	45.00*
2973	1	LOCKING PLATE	69430 28050	TAILGATE LOCK CATCH	0%	X nh	45.00*
2975	1	BOOT/TAILGATE LOCK	69350 02080	TAILGATE LOCK ASSY	0%	bl	400.00*
3015	1	REAR BADGE	90975 02064	TOYOTA EMBLEM	0%	na	55.00*
3020	1	BADGE PREVIA	75441 28720	ALPHARD EMBLEM	0%	na	55.00*
3151	1	HEATED REAR SCREEN	68105 28680	REAR WINDSCREEN	0%	X nh	650.00*
3160	1	REAR SCREEN BOND KIT	PZ491-00C1131		0%	na	38.18
3281	1	L/R OUTER LAMP	81561 28503		0%	na	360.00*
3282	1	R/R OUTER LAMP	81551 28503		0%	na	360.00*
3283	1	L/R INNER LAMP	81591 28262	REFLECTOR LAMP	0%	X nh	360.00*
3284	1	R/R INNER LAMP	81581 28262		0%	X nh	360.00*
3287	1	REAR REFLECTOR	76801 28401	TAILGATE LOCK COVER	0%	X nh	350.00*
3413	1	L/R REFLECTOR	81920 13022	BUMPER REFLECTION	0%	X nh	40.00*

Audatex System Using Manufacturer Times

CHENG AUTO BODYWORKS

Claim Reference:

Assessment Number: GR000076

Version: CHENGABS/1

Date Calculated: 25/07/2017 11:04

Full Report - V1

Registration: EK16M

Printed: 25/07/2017 18:04

3414	1	R/R REFLECTOR	81910 13022	0%	2mm	40.00*
4465	1	✓ CONDENSER ✓	88460 42100	0%	2mm	750.00*
1000	1	RR RH FEND CVR	Renew	0%	Rx	314.00*
1000	1	RR LH FEND CVR	Renew	0%	de	314.00*/
1000	1	TAILGATE SNS	Renew	0%	2mm	80.00*
1000	1	TAILGATE TRIM BRD	Renew	0%	de	550.00*/
1000	1	END PANEL SNSR	Renew	0%	de	120.00*/
f: OEM Parts			Sub Total			\$14,694.18
g: Original			Mark Up From Cost	(5 %)	?	\$734.71
h: Secondhand			Sundry Parts	(Fixed)		\$100.00
p: Parallel			Total Parts			\$15,528.89
x: Exchange						

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Description		Betterment	Price
FRT PARKING	SPECIALIST	0%	\$800.00
SNSRX4			
REAR PARKING	SPECIALIST		\$800.00
SNSRX4 2			
AUDATEX FEES	SPECIALIST	0%	\$42.00
WINDSCREEN	SPECIALIST		\$25.00
SEALANT			
COOLANT	SPECIALIST	0%	\$30.00
Total Extras			\$1,697.00

Final Calculation

Total Parts		
Labour		\$15,528.89
Total Panel/Mechanical	\$713.00	648.60
Total Paintwork	\$1,168.40	1122.40
Total Labour		\$1,881.40
Additional Costs		
Corr Prot Materials External	\$0.00	
Corr Prot Materials Internal	\$0.00	
Cost of Specialist	\$1,697.00	
Total of Additional Costs		\$1,697.00
Total Paint/Material Costs		\$244.29
Grand Total Excludes GST		\$19,351.58
GST @ 0 %		\$0.00
Grand Total Includes GST		\$19,351.58

Assessment Notes

Claim Reference:
Assessment Number: GR000076
Version: LKKAUTOC/11
Date Calculated: 24/05/2018 03:23

Full Report - V1
Registration: EK16M
Printed: 24/05/2018 10:28

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	LKK AUTO	Date of Incident:	22/07/2017
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	China Taiping Insurance (S) Pt	Repairs Authorised:	TBA
Claim Reference:		Estimated Repair Time:	
Policy Number:	5089247179	Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:	True	Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle

Manufacturer:	TOYOTA
Model:	Previa
Sub Model:	GL
Model Sheet Number:	Y92 05
Registration:	EK16M
Registration Month:	March
Registration Year:	2016
VIN Number:	
Manufacture Year:	2015
Odometer:	Not Known
Colour:	
Engine Number:	
Fuel Level:	%



Model Specs

FROM 01/2010	PARK CONTROL SENSOR
2.4 LTR 117/125 KW	TWO COAT METALLIC

Vehicle Condition

Vehicle Status

Pre-Accident Condition:	Severity of Impact:	
Steering:	Vehicle Status on Inspection:	
Brakes Pedal Travel:	Date of Inspection:	25/07/2017
Place of Inspection:		
Pre-Accident Damage:		
Tyres Condition:		
Tread Depth LHF:	Tread Depth RHF:	
Tread Depth LHR:	Tread Depth RHR:	
Damage Areas:	Direction of Impact:	

**Addresses****Cost Summary**

Total Labour	\$1,771.00
Total Paint/Material	\$244.29
Total Parts	\$9,767.35
Total of Additional Costs	\$467.00
Excess:	TBA
Grand Total Exc GST:	\$12,249.64
0 % GST:	\$0.00
Grand Total Inc GST:	\$12,249.64

Repair Information**LABOUR**

Time Basis 10 WU = 1 HR. Price/CL 1 = \$46.00/HR
Price/Dent = \$46.00/HR

Repair / Guide Number	Repair Details	WU	Cost Price (\$)
NO NUMBER	ADJUST HEADLAMP	2.0	9.20
B010)	R + R FRONT BUMPER	5.0	23.00
	NOT INCLUDED: RADIATOR GRILLE R + R		
B020)	RENEW FRONT BUMPER (REMOVED)	6.0	27.60
	INCLUDES: REQUIRED ATTACHED PARTS		
	REMOVE AND REFIT		
	NOT INCLUDED: PARKING HELP SENSOR		
	REMOVE AND REFIT		
B020	R + R FRONT OUTER PARKING AID SENSOR/S	1.0	4.60
NO NUMBER	R + R FRONT BUMPER ATTACHED PARTS	2.0	9.20
750011	R + R RADIATOR BADGE	3.0	13.80
	INCLUDES: R + R RADIATOR GRILLE		
B010)	R + R FRONT BUMPER REINFORCEMENT	2.0	9.20
B020)	RENEW FRONT BUMPER REINFORCEMENT	1.0	4.60
B040)	R + R HEADLAMPS	1.0	4.60
B040)	R + R RIGHT HEADLAMP	1.0	4.60
	(BUMPER REMOVED)		
	DOES NOT INCLUDE: ADJUST HEADLAMP		
B290)	RENEW REAR END PANEL CPL	32.0	147.20
B390	RENEW TAILGATE	20.0	92.00
	INCLUDES: R + R AND ALIGN TAILGATE,		
	CONVERT ATTACHED PARTS, RENEW IF		
	NECESSARY		
G040	R + R REAR SCREEN	23.0	105.80
B410	R + R REAR BUMPER	4.0	18.40
B420)	RENEW REAR BUMPER (REMOVED)	1.0	4.60
	INCLUDES: REQUIRED ATTACHED PARTS		
	REMOVE AND REFIT		

Claim Reference:

Full Report - V1

Assessment Number: GR000076

Registration: EK16M

Version: LKKAUTOC/11

Printed: 24/05/2018 10:28

Date Calculated: 24/05/2018 03:23

NOT INCLUDED: PARKING HELP SENSOR REMOVE AND REFIT			
NO NUMBER	R + R REAR PARKING AID SENSORS ADD/WORK	2.0	9.20
642101	R + R TAILGATE SEAL	2.0	9.20
NO NUMBER	R + R LUGGAGE COMPARTMENT COVER	1.0	4.60
NO NUMBER	DETACH + REFIT REAR FLOOR CARPET	3.0	13.80
M010	R + R CONDENSER	22.0	101.20
M010	DRAIN AIR CONDITIONING	7.0	32.20
LABOUR COST			
Total Work Units		141.0	
Corrosion Protection External Labour		0.0HRS	0.00
Corrosion Protection Internal Labour		0.0HRS	0.00
Sub Total		14.1HRS	\$648.60
Paint Labour		24.4HRS	\$1,122.40
Total Labour		38.5HRS	\$1,771.00

PAINT WORK		Time Basis 10 WU = 1 HR. Price = \$46.00/HR	
Guide Number	Description	WU	Cost Price (\$)
- TWO COAT METALLIC			
420	FRONT BUMPER SUPPORTSURFACE PAINT	5.0	
2741	REAR PANEL NEW PART PAINTING	16.0	
2931	BOOTLID/TAILGATE NEW PART PAINTING	18.0	
283	FRONT BUMPER NEW PART PAINT K1R	13.0	
410	GRILLE NEW PART PAINT K1R	3.0	
2583	REAR BUMPER NEW PART PAINT K1R	11.0	
3485	L/R LOWER SIDE PANELSURFACE PAINT	6.0	
3486	R/R LOWER SIDE PANELSURFACE PAINT	6.0	
1000	RR LH FEND CVR NEW PART PAINT	10.0*	
1000	SURFACE PAINTING NEW PART PAINT	130.0*	
LABOUR COST - PAINT			
TIME(PAINT)		218.0	
Preparation Main Work Metal		21.0	
Preparation Comp. Work Plastic		5.0	
Preparation Work Multi Layer Paint		0.0	
Total Work Units (10WU/HR)		244.0	
Total Paintwork Labour		24.4HRS	\$1,122.40
MATERIAL COST - PAINT			
New Part Painting			\$70.20
New Part Painting - Plastic K1R			\$116.61
Surface-/Blend Paint			\$30.38
Material-Const Main Work Metal			\$18.10
Material-Const Comp. Work Plastic			\$9.00
Total Excluding Pearlescent Uplift			\$244.29
Pearlescent Uplift @ 0.0%			\$0.00
Total Paint Material Cost			\$244.29

PARTS

				Price Valid: 01/06/2015	
Guide No.	Qty	Description	Part Number	Supplier	Price (\$)
3020	1	BADGE PREVIA	75441 28720		0% 55.00*
2975	1	BOOT/TAILGATE LOCK	69350 02080		0% 400.00*
2944	1	BOOT/TAILGATE SEAL	67881 28120		0% 190.00*

2931	1	BOOTLID/TAILGATE	67005 28C90	0%	1,050.00*
4465	1	CONDENSER	88460 42100	0%	750.00*
1000	1	END PANEL SNSR	Renew	0%	120.00*
283	1	FRONT BUMPER	52119 28977	0%	900.00*
420	1	FRONT BUMPER SUPPORT	52021 28221	0%	250.00*
333	1	FRT BUMPER ABSORBER	52611 28081	0%	50.00*
350	1	FRT BUMPER CLAMP KIT	USE SINGLE PARTS	0%	20.00*
258	1	FRT NO PLATE REINF	KNPL0	0%	128.00*
410	1	GRILLE	53101 28472A0	0%	550.00*
431	1	GRILLE BADGE	75301 28151	0%	180.00*
319	1	L/F OUT BUMPER BRKT	52116 28170	0%	45.00*
299	1	L/FOG LAMP COVER	81482 28260	0%	110.00*
2619	1	L/R BUMPER BRACKET	52156 28050	0%	65.00*
2623	1	L/R INN BUMPER BRKT	52155 28090	0%	65.00*
3169	1	L/SPACER	64819 28020	0%	0.00F
3167	1	LEFT RETAINER	64828 28030	0%	0.00F
297	1	LWR RADIATOR GRILLE	53112 28110	0%	95.00*
320	1	R/F BUMPER OUT BRKT	52115 28070	0%	45.00*
300	1	R/FOG LAMP COVER	81481 28260	0%	120.00*
2620	1	R/R BUMPER BRACKET	52155 28080	0%	65.00*
2624	1	R/R INN BUMPER BRKT	52156 28060	0%	65.00*
3170	1	R/SPACER	64818 28020	0%	0.00F
3015	1	REAR BADGE	90975 02064	0%	55.00*
2583	1	REAR BUMPER	52159 28915	0%	900.00*
2741	1	REAR PANEL	58307 28110	0%	450.00*
3160	1	REAR SCREEN BOND KIT	PZ491 00C1131	0%	0.00F
562	1	RIGHT HEADLAMP ASSY	81130 28C11	0%	1,600.00*
3168	1	RIGHT RETAINER	64827 28040	0%	0.00F
2650	1	RR BUMPER CLAMP KIT	USE SINGLE PARTS	0%	20.00*
1000	1	RR LH FEND CVR	Renew	0%	314.00*
1000	1	TAILGATE TRIM BRD	Renew	0%	550.00*
f: OEM Parts				Saving	\$65.32
g: Original				Sub Total	\$9,207.00
h: Secondhand				Mark Up From Cost (5 %)	\$460.35
p: Parallel				Sundry Parts (Fixed)	\$100.00
x: Exchange				Total Parts	\$9,767.35

THIS ASSESSMENT CONTAINS UNPRICED PARTS
NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Description	Betterment	Price
REAR PARKING SPECIALIST	0%	\$400.00
SNSRX2		
AUDATEX FEES SPECIALIST		\$42.00
WINDSCREEN SPECIALIST	0%	\$25.00
SEALANT		
Total Extras		\$467.00

Final Calculation

Total Parts	\$9,767.35
Labour	
Total Panel/Mechanical	\$648.60
Total Paintwork	\$1,122.40
Total Labour	\$1,771.00

Claim Reference:

Full Report - V1

Assessment Number: GR000076

Registration: EK16M

Version: LKKAUTOC/11

Printed: 24/05/2018 10:28

Date Calculated: 24/05/2018 03:23

Additional Costs

Corr Prot Materials External	\$0.00
Corr Prot Materials Internal	\$0.00
Cost of Specialist	\$467.00

Total of Additional Costs	\$467.00
----------------------------------	-----------------

Total Paint/Material Costs	\$244.29
-----------------------------------	-----------------

Grand Total Excludes GST	\$12,249.64
---------------------------------	--------------------

GST @ 0 %	\$0.00
-----------	--------

Grand Total Includes GST	\$12,249.64
---------------------------------	--------------------

Assessment Notes

CHENG AUTO BODYWORKS
5 Soon Lee Street #01-62
Pioneer Point
Singapore
627607

Claim Reference:
Assessment Number: GR000076
Version: CHENGABS/1
Date Calculated: 25/07/2017 11:04

Full Report - V1
Registration: EK16M
Printed: 25/07/2017 18:04

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	Cheng Auto Admin 2	Date of Incident:	22/07/2017
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	China Taiping Insurance (S) Pt	Repairs Authorised:	TBA
Claim Reference:		Estimated Repair Time:	
Policy Number:	5089247179	Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:	True	Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle

Manufacturer:	TOYOTA
Model:	Previa
Sub Model:	GL
Model Sheet Number:	Y92 05
Registration:	EK16M
Registration Month:	March
Registration Year:	2016
VIN Number:	
Manufacture Year:	2015
Odometer:	Not Known
Colour:	
Engine Number:	
Fuel Level:	%

Model Specs

FROM 01/2010	PARK CONTROL SENSOR
2.4 LTR 117/125 KW	TWO COAT METALLIC

Tan Jiah 97495749
'WP'
22/7/17 @ 1445
Resurvey before paint
10 days
Sur @ kkauto.com

Vehicle Condition

Vehicle Status

Pre-Accident Condition:	Severity of Impact:
Steering:	Vehicle Status on Inspection:
Brakes Pedal Travel:	Date of Inspection: 25/07/2017
Place of Inspection:	
Pre-Accident Damage:	
Tyres Condition:	Tread Depth RHF:
Tread Depth LHF:	Tread Depth RHR:
Tread Depth LHR:	Direction of Impact:
Damage Areas:	

Audatex System Using Manufacturer Times

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

PAGE 1 OF 5

Acknowledged by Repairer

Signature:

Date:

CHENG AUTO BODYWORKS

Claim Reference:

Assessment Number: GR000076

Version: CHENGABS/1

Date Calculated: 25/07/2017 11:04

Full Report - V1

Registration: EK16M

Printed: 25/07/2017 18:04

3414	1	R/R REFLECTOR	81910 13022	0%	?	40.00*
4465	1	CONDENSER	88460 42100	0%	?	750.00*
1000	1	RR RH FEND CVR	Renew REAR FENDER CAB COVER	0%	Rx	314.00*
1000	1	RR LH FEND CVR	Renew	0%	de	314.00*
1000	1	TAILGATE SNS	Renew TAILGATE OUTER LOCK SENSOR	0%	de	80.00*
1000	1	TAILGATE TRIM BRD	Renew TAILGATE TRIM COVER BOARD	0%	de	550.00*
1000	1	END PANEL SNSR	Renew REAR END PANEL SENSOR	0%	de	120.00*
f: OEM Parts			Sub Total			\$14,694.18
g: Original			Mark Up From Cost	(5 %)		\$734.71
h: Secondhand			Sundry Parts	(Fixed)		\$100.00
p: Parallel			Total Parts			\$15,528.89
x: Exchange						

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Description		Betterment	Price
FRT PARKING	SPECIALIST	0%	?
SNSRX4			\$800.00
REAR PARKING	SPECIALIST		400
SNSRX4 2			\$800.00
AUDATEX FEES	SPECIALIST	0%	\$42.00
WINDSCREEN	SPECIALIST		\$25.00
SEALANT			
COOLANT	SPECIALIST	0%	?
			\$30.00
Total Extras			\$1,697.00

Final Calculation

Total Parts		\$15,528.89
Labour		
Total Panel/Mechanical	\$713.00	
Total Paintwork	\$1,168.40	
Total Labour		\$1,881.40
Additional Costs		
Corr Prot Materials External	\$0.00	
Corr Prot Materials Internal	\$0.00	
Cost of Specialist	\$1,697.00	
Total of Additional Costs		\$1,697.00
Total Paint/Material Costs		\$244.29
Grand Total Excludes GST		\$19,351.58
GST @ 0 %		\$0.00
Grand Total Includes GST		\$19,351.58

Assessment Notes

Cheng Auto Bodyworks (Co.Reg.No:53315238X)

5 Soon Lee Street, #01-62, Pioneer Centre

Singapore 627607

Tel: 6631 0707 Fax: 6316 2431 Email: chengauto@tlsgroup.com.sg

TP INSURER: China Taiping Insurance (Singapore) Pte. Ltd. (HQ)
TAN SU GAN

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	22/07/2017
Vehicle Reg. No.:	EK16M	Driveable?	
Party At Fault:	UNKNOWN		
Make/Model:	TOYOTA ALPHARD, 2.5 (A)	Vehicle Reg. Date:	29/03/2016
Vehicle Colour:	WHITE	Chassis No:	AGH300018350
Engine No:	2ARH566278		
Odometer:	10000 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	10		
Present Location:	CHENG AUTO BODYWORKS (HQ)		

COST OF CLAIMS	Amount
Parts	17,185.80
Miscellaneous Items	1,025.92
Labour	2,125.69
Paintwork Labour	0.00
Towing	0.00
Nett Amount (S\$)	20,337.41

This claim is handled by: MURUGESAN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 25 Jul 2017)

Parts: M1-MPV TOYOTA ALPHARD 2.5 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Cheng Auto Bodyworks/EK16M/25/07/2017 18:32

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1	NA	*BADGE PREVIA <i>rec</i>	0.00	0.00	*55.00 F
2	1	NA	*BOOT/TAILGATE LOCK <i>st</i>	0.00	0.00	*400.00 F
3	1	NA	*BOOT/TAILGATE SEAL <i>rec</i>	0.00	0.00	*190.00 F
4	1	NA	*BOOTLID/TAILGATE <i>st</i>	0.00	0.00	*1,050.00 F
5	1	NA	*CONDENSER <i>st</i>	0.00	0.00	*750.00 F
6	1	NA	*END PANEL SNSR <i>dis</i>	0.00	0.00	*120.00 F
7	1	NA	*FRONT BUMPER <i>de</i>	0.00	0.00	*900.00 F
8	1	NA	*FRONT BUMPER SUPPORT <i>st</i>	0.00	0.00	*250.00 F
9	1	NA	*FRT BUMPER ABSORBER <i>deformed</i>	0.00	0.00	*50.00 F
10	1	NA	*FRT BUMPER CLAMP KIT <i>rec</i>	0.00	0.00	*20.00 F
11	1	NA	*FRT NO PLATE REINF <i>cut</i>	0.00	0.00	*128.00 F
12	1	NA	*GRILLE <i>rec</i>	0.00	0.00	*550.00 F
13	1	NA	*GRILLE BADGE <i>rec</i>	0.00	0.00	*180.00 F
14	1	NA	*HEATED REAR SCREEN <i>nn</i>	0.00	0.00	*650.00 F
15	1	NA	*L/F FOG LAMP <i>nn</i>	0.00	0.00	*220.00 F
16	1	NA	*L/F OUT BUMPER BRKT <i>rec</i>	0.00	0.00	*45.00 F
17	1	NA	*L/FOG LAMP COVER <i>deformed</i>	0.00	0.00	*120.00 F
18	1	NA	*L/R BUMPER BRACKET <i>rec</i>	0.00	0.00	*65.00 F
19	1	NA	*L/R HINGE <i>st</i>	0.00	0.00	*45.00 F
20	1	NA	*L/R IMPACT DAMPER <i>nn</i>	0.00	0.00	*175.00 F
21	1	NA	*L/R INN BUMPER BRKT <i>rec</i>	0.00	0.00	*65.00 F
22	1	NA	*L/R INNER LAMP <i>nn</i>	0.00	0.00	*360.00 F
23	1	NA	*L/R OUTER LAMP <i>nn</i>	0.00	0.00	*360.00 F
24	1	NA	*L/R REFLECTOR <i>nn</i>	0.00	0.00	*40.00 F
25	1	NA	*LEFT HEADLAMP ASSY <i>nn</i>	0.00	0.00	*1,600.00 F
26	1	NA	*LOCKING PLATE <i>nn</i>	0.00	0.00	*45.00 F
27	1	NA	*LWR RADIATOR GRILLE <i>cut</i>	0.00	0.00	*95.00 F
28	1	NA	*R/F BUMPER OUT BRKT <i>rec</i>	0.00	0.00	*45.00 F
29	1	NA	*R/F FOG LAMP <i>nn</i>	0.00	0.00	*220.00 F
30	1	NA	*R/FOG LAMP COVER <i>deformed</i>	0.00	0.00	*120.00 F
31	1	NA	*R/R BUMPER BRACKET <i>rec</i>	0.00	0.00	*65.00 F
32	1	NA	*R/R HINGE <i>st</i>	0.00	0.00	*45.00 F
33	1	NA	*R/R IMPACT DAMPER <i>nn</i>	0.00	0.00	*175.00 F

Cheng Auto Bodyworks/EK16M/25/07/2017 18:32. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
34	1	NA	*R/R INN BUMPER BRKT <i>rec</i>	0.00	0.00	*65.00 F
35	1	NA	*R/R INNER LAMP <i>nn</i>	0.00	0.00	*360.00 F
36	1	NA	*R/R OUTER LAMP <i>nn</i>	0.00	0.00	*360.00 F
37	1	NA	*R/R REFLECTOR <i>nn</i>	0.00	0.00	*40.00 F
38	1	NA	*REAR BADGE <i>rec</i>	0.00	0.00	*55.00 F
39	1	NA	*REAR BUMPER <i>de</i>	0.00	0.00	*900.00 F
40	1	NA	*REAR PANEL <i>st</i>	0.00	0.00	*450.00 F
41	1	NA	*REAR REFLECTOR <i>nn</i>	0.00	0.00	*350.00 F
42	1	NA	*RIGHT HEADLAMP ASSY <i>nt</i>	0.00	0.00	*1,600.00 F
43	1	NA	*RR BUMPER CLAMP KIT <i>rec</i>	0.00	0.00	*20.00 F
44	1	NA	*RR LH FEND CVR <i>de</i>	0.00	0.00	*314.00 F
45	1	NA	*RR RH FEND CVR <i>k</i>	0.00	0.00	*314.00 F
46	1	NA	*SPECIALIST AUDATEX FEES	0	0.00	*42.00 FS
47	1	NA	*SPECIALIST COOLANT <i>nn</i>	0	0.00	*30.00 FS
48	1	NA	*SPECIALIST FRT PARKING SNSRX4 <i>nn</i>	0	0.00	*800.00 FS
49	1	NA	*SPECIALIST REAR PARKING SNSRX4 <i>2 rec</i>	0	0.00	*800.00 FS
50	1	NA	*SPECIALIST WINDSCREEN SEALANT <i>rec</i>	0	0.00	*25.00 FS
51	1	NA	*SUNDRY PARTS <i>rec</i>	0	0.00	*100.00 FS
52	1	NA	*TAILGATE SNS <i>nn</i>	0.00	0.00	*80.00 F
53	1	NA	*TAILGATE TRIM BRD <i>de</i>	0.00	0.00	*550.00 F

F=Franchise part. S=SpcNett.

Sub Total (S\$)	16,453.00
+ Margin on L,N Items 5.00% (S\$)	732.80
Total Parts (S\$)	17,185.80

Cheng Auto Bodyworks/EK16M/25/07/2017 18:32. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	GST 7%	1,025.92
Sub Total (S\$)			<u>1,025.92</u>

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	Total Paint Labour	New	1122.40 1,168.40
2	Total Paint Materials	New	✓ 244.29
3	Total Panel/Mechanical Labour	New	695.60 713.00
Gross Labour Cost (S\$)			<u>2,125.69</u>

Cheng Auto Bodyworks/EK16M/25/07/2017 18:32. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710

TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M



Wiper blades: NWB (Nippon Wiper blades), Siliper (Made in Korea),
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

CHENG AUTO BODYWORKS
5 SOON LEE STREET #01-62, PIONEER POINT

627607

TEL: 6631 0707 FAX: 6316 2431 / 6476 6372

ATTN: WESLEY LAI 86667775

TAX INVOICE : AR201708-00333
DATE : 01/08/2017
CUSTOMER ID : CHE016
VEH REG. NO. : EK16M
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR : S\$

SQ STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1. T52164-58050-A0 VELL-AGH30	RR TOWING COVER LH Z	PA PL2-K1-06V	1	15.00	15.00

[Handwritten signature]

SUB-TOTAL : 15.00
ADD GST 7.00 % 1.05

E & OE

TOTAL AMOUNT S\$: 16.05

[P] 01/08/2017 10:21:40AM

Goods Sold are not refundable for Cash

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

[B] 01/08/2017 10:18:09AM

JAE Auto Pte. Ltd.

Sales Executive: HAN

This is computer generated document.
No signature is required.



ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date



日美汽車私人有限公司 JAE AUTO PTE LTD

Bik 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

CHENG AUTO BODYWORKS
5 SOON LEE STREET #01-62, PIONEER POINT

627607

TEL: 6631 0707 FAX: 6316 2431 / 6476 6372

ATTN: WESLEY LAI 86667775

WIPER BLADE
Dept Direct: 6417 8791 / 8745 9038



Dept Direct: 6417 8791

Dept Direct: 6417 8791

Dept Direct: 6417 8791

Dept Direct: 6417 8791

Wiper blade: NWS (Nippon Wiper blade, Bilster (Made in Korea))
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

TAX INVOICE : AR201707-17242
DATE : 28/07/2017
CUSTOMER ID : CHE016
VEH REG. NO. : EK16M
TERMS : 30 days
PO NO. :
PAGE NO. : Page 2 of 2
CURR : S\$

SQ STOCKID	DESCRIPTION	Stk Loc	QTY	U/PRICE	AMOUNT
8. T52156-58030 VELL-AGH30	RR BUMPER S/RETAINER LH	PA 2623 PL2-K1-05A	1	65.00	65.00
9. T58307-58070 VELL-AGH30	END PANEL	PA 2741 PL2-P1-04B	1	450.00	450.00
10. T75403-58030 VELL-AGH30	RR BOOT LOGO	PA 3015 PL2-D1-08G	1	55.00	55.00
11. T75441-58070 ALPHD-AGH30	RR BOOT "ALPHARD" EMBLEM	PA 3020 PL2-J1-08G	1	55.00	55.00
12. T88460-58040 VELL-AGH30	A/C CONDENSER	PA 4465 PL2-A1-030	1	750.00	750.00

SUB-TOTAL : 2,158.00
ADD GST 7.00 % 151.06

E. & O.E

TOTAL AMOUNT S\$: 2,309.06

[P] 28/07/2017 9:57:00AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

[E] 28/07/2017 9:26:38AM

JAE Auto Pte. Ltd.

Sales Executive: HAN

This is computer generated document.

No signature is required.



ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date



日美汽車私人有限公司 JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 406710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

CHENG AUTO BODYWORKS
5 SOON LEE STREET #01-62, PIONEER POINT

627607
TEL : 6631 0707 FAX : 6316 2431 / 6476 6372
ATTN : WESLEY LAI 86667775

THUNDERBOLT BLADE
Dept Direct: 6417 9791 / 9740 9900



Dept Direct: 6417 9790

Dept Direct: 6417 9790

Dept Direct: 6417 9790

Dept Direct: 6417 9790

Wiper Blade: NISSAN (Nippon Wiper blade), Silver (Made in Korea),
Forch (Made in Germany)

Spark Plug: NGK (NGK Spark Plug made in Japan)

TAX INVOICE : AR201707-17279
DATE : 28/07/2017
CUSTOMER ID : CHH016
VEH REG. NO. : FK16M
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR. : S\$

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1	T53112-58140 ALPHD-AGH30	FRT BUMPER LWR GRILLE	U1 297 L2-C13-C	1	95.00	95.00
2	T52115-58060 ALPHD-AGH30	FRT BUMPER S/RRTAINER RH	U1 320 SUPPLIER	1	45.00	45.00
3	T53101-58260 ALPHD-AGH30	RAD GRILLE	U1 410 SUPPLIER	1	550.00	550.00
4	T67750-58090-C0 VELL-AGH30	RR BOOT INNER TRIM	U1 1000 SUPPLIER	1	550.00	550.00
5	T89997-30100 NSP170 ZVW50 ZYX10	ANTENNA,ELECTRICAL KEY	U1 1000 SUPPLIER	1	120.00	120.00

SUB-TOTAL : 1,360.00
ADD GST 7.00 % 95.20

E & O E

TOTAL AMOUNT S\$: 1,455.20

[P] 28/07/2017 10:07:49AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

[B] 28/07/2017 9:48:38AM

JAE Auto Pte. Ltd.

Sales Executive : HAN

This is computer generated document.

No signature is required.



* AR201707-17279 *

ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date



日美汽車私人有限公司 JAE AUTO PTE LTD

Bik 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450816 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

CHENG AUTO BODYWORKS
5 SOON LEE STREET #01-62, PIONEER POINT

627607

TEL: 6631 0707 FAX: 6316 2431 / 6476 6372
ATTN: WESLEY LAI 86667775



Wiper blade: NWS (Nippon Wiper blade), Silper (Made in Korea),
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

TAX INVOICE : AR201707-17243
DATE : 28/07/2017
CUSTOMER ID : CHE016
VEH REG. NO. : EK16M
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 2
CURR : S\$

SQ STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1. T52119-58470-A0 ALPHD-AGH30	FRT BUMPER	SG J4-1	283	1	900.00 900.00
2. T52159-58190-A0 ALPHD-AGH30	RR BUMPER S	SG Q4-6	2583	1	900.00 900.00
3. T52155-58060 VELL-AGH30	RR BUMPER S/SUPPORT RH	SG F2-1B	2620	1	65.00 65.00
4. T67005-58150 VELL-AGH30	RR BOOT	SG SG-58	2931	1	1050.00 1,050.00
5. T67881-58040 VELL-AGH30	RR BOOT RUBBER	SG T2-17	2944	1	190.00 190.00
6. T81145-58370/1 ALPHD-AGH30	HEAD LAMP RH	SG L2-4	562	1	1600.00 1,600.00
7. T69350-58030 VELL-AGH30	RR BOOT LOCK	SG H2-1B	2975	1	400.00 400.00

CONTINUE NEXT PAGE

[P] 28/07/2017 9:57:49AM

Goods Sold are not refundable for Cash

Interest Rate of 1.3% per month will be imposed on OverDue Account(s).

ORIGINAL

[E] 28/07/2017 9:26:49AM



日美汽車私人有限公司

JAE AUTO PTE LTD

Bik 3018 UBI ROAD 1 #01-121 SINGAPORE 408710

TEL: 67453833 FAX: 67454442, 67450618 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS
Dept Direct: 6417 8701 / 6418 9020



Dept Direct: 6417 8704

Dept Direct: 6417 8706

Dept Direct: 6417 8708

Dept Direct: 6417 8710

Wiper blades: NWB (Nippon Wiper blades), Gilper (Made in Korea),
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

CHENG AUTO BODYWORKS
5 SOON LEE STREET #01-62, PIONEER POINT

627607

TEL: 6631 0707 FAX: 6316 2431 / 6476 6372

ATTN: WESLEY LAI 86667775

TAX INVOICE : AR201707-17243
DATE : 28/07/2017
CUSTOMER ID : CHE016
VEH REG. NO. : EK16M
TERMS : 30 days
PO NO. :
PAGE NO. : Page 2 of 2
CURR : S\$

SQ STOCKID	DESCRIPTION	Stk Loc	QTY	U/PRICE	AMOUNT
8. T52166-58030-A0 VELL-AGH30	RR BUMPER UPP COVER LH	SG JI-10	1000	1	314.00

SUB-TOTAL : 5,419.00
ADD GST 7.00 % 379.33

E & OE

TOTAL AMOUNT S\$: 5,798.33

[P] 28/07/2017 9:57:49AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

[E] 28/07/2017 9:26:49AM

JAE Auto Pte. Ltd.

Sales Executive: HAN

This is computer generated document.
No signature is required.



AR201707-17243

ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date



日美汽車私人有限公司 JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

OST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

CHENG AUTO BODYWORKS

5 SOON LEE STREET #01-62, PIONEER POINT

627607

TEL: 6631 0707 FAX: 6316 2431 / 6476 6372

ATTN: WESLEY LAI 86667775

WINDSHIELD GLASS
Dept Direct: 6417 5701 / 6745 2606



Dept Direct: 6417 5704

Dept Direct: 6417 5705

Dept Direct: 6417 5706

Dept Direct: 6417 5707

Wiper blade: NWS (Japan Wiper blade), Silper (Made in Korea),
Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

TAX INVOICE : AR201707-17242

DATE : 28/07/2017

CUSTOMER ID : CHE016

VEH REG. NO. : EK16M

TERMS : 30 days

PO NO. :

PAGE NO. : Page 1 of 2

CURR : S\$

SQ	STOCKID	DESCRIPTION	StdLoc	QTY	U/PRICE	AMOUNT
1.	T53105-58010 ALPHD-AGH30	FRT BUMPER CTR GARNISH	PA PL2-A1-06A	258 1	128.00	128.00
2.	T52116-58060 ALPHD-AGH30	FRT BUMPER S/RETAINER LH	PA PL2-G1-06D	319 1	45.00	45.00
3.	T52611-58040 VELL-AGH30	FRT BUMPER SPONGE	PA PL2-G1-030	333 1	50.00	50.00
4.	T52021-58030 VELL-AGH30	FRT BUMPER REINFORCEMENT	PA PL2-P1-09B	420 1	250.00	250.00
5.	T75301-58200 ALPHD-AGH30	RAD GRILLE LOGO	PA PL2-H1-04F	431 1	180.00	180.00
6.	T52156-58040 VELL-AGH30	RR BUMPER S/SUPPORT LH	PA PL2-K1-03M	2619 1	65.00	65.00
7.	T52155-58050 VELL-AGH30	RR BUMPER S/BRKT RH	PA PL2-K1-03M	2624 1	65.00	65.00

CONTINUE NEXT PAGE

[P] 28/07/2017 9:56:59AM

Goods Sold are not refundable for Cash

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

ORIGINAL

[E] 28/07/2017 9:26:38AM



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

CHENG AUTO BODYWORKS

5 SOON LEE STREET #01-62, PIONEER POINT

627607

TEL: 6631 0707 FAX: 6316 2431 / 6476 6372

ATTN: WESLEY LAI 86667775



Wiper blade: NWD (Nippon Wiper blade), Siliper (Made in Korea),
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

TAX INVOICE : AR201707-18200
DATE : 29/07/2017
CUSTOMER ID : CHE016
VEH REG. NO. : EK16M
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR : S\$

SO STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1. T52040-58120 ALPHD-AGH30	FOG LAMP COVER LH	PA 299 PL2-K1-04I	1	120.00	120.00
2. T52030-58120 ALPHD-AGH30	FOG LAMP COVER RH	PA 300 PL2-K1-03M	1	120.00	120.00

SUB-TOTAL : 240.00
ADD GST 7.00 % 16.80

E & OE

TOTAL AMOUNT S\$: 256.80

[P] 29/07/2017 11:32:19AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

[E] 29/07/2017 11:31:23AM

JAE Auto Pte. Ltd.

Sales Executive: HAN

This is computer generated document.
No signature is required.



ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date



日美汽車私人有限公司

JAE AUTO PTE LTD

Bik 3018 UBI ROAD 1 #01-121 SINGAPORE 408710

TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO: M2-0110201-3 CO. REG. NO: 199307741M

CHENG AUTO BODYWORKS

5 SOON LEE STREET #01-62, PIONEER POINT

627607

TEL: 6631 0707 FAX: 6316 2431 / 6476 6372

ATTN: WESLEY LAI 86667775

WIPER BLADE
Dept Direct: 6417 8701 / 6416 9030



Dept Direct: 6417 8706

Dept Direct: 6417 9196

Dept Direct: 6417 9736

Dept Direct: 6417 9719

Wiper blade: NWS (Nippon Wiper blade), Sliper (Made in Korea),
Forch (Made in Germany)

Spark plug: Nippon Chem, NGK (Made in Japan)

TAX INVOICE : AR201708-00400

DATE : 01/08/2017

CUSTOMER ID : CHE016

VEH REG. NO. : EK16M

TERMS : 30 days

PO NO. :

PAGE NO. : Page 1 of 1

CURR : S\$

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	UPRICE	AMOUNT
1.	T89341-58050-A0 VELL-AGH30	BUMPER SENSOR	SG misc Z2-1F	2	200.00	400.00

Handwritten signature

SUB-TOTAL : 400.00
ADD GST 7.00 % 28.00

E & OE

TOTAL AMOUNT S\$: 428.00

[P] 01/08/2017 10:54:37AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

[E] 01/08/2017 10:53:50AM

JAE Auto Pte. Ltd.

Sales Executive: HAN

This is computer generated document.

No signature is required.



ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	25 Jul 2017 Sendback Est	25 Jul 2017 18:32 S\$20,337.41	28 Jul 2017 13:26 Edit Adj Rpt	S\$12,260.14 Edit Estimates	S\$12,260.14 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS			
Insured:	TAN SU GAN, Co. Reg. No.: S6834878A		
Main Claimant:	LOW KWEE HONG		
Vehicle Reg. No.:	EK16M	Date of Loss:	22/07/2017 00:00 - :59 [15 Months and 23 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM17D04371C02	Policy/Cover Note No.:	DMHCSN1715791700
Vehicle Reg. No. (Insured):	SKT8906Z	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Cheng Auto Bodyworks (HQ) 5 Soon Lee Street #01-62 Pioneer Point, 627607 Pioneer - Tel: 6631 0707		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 08/08/2017]		
Adj Asg. Remarks:	PLEASE ASSIST TO SURVEY AND REVERT WITH YOUR RECOMMENDATION		

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
There are no mail for this case.		

ALL ASSOCIATED TASKS										View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

Claim Documents

EK16M (SNM17D04371C02)
[SKT8906Z]
TP
LOW KWEE HONG
Jul 22 2017 12:00AM
[TAN SU GAN]
Cheng Auto Bodyworks

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	☒
No	Finalized On	Cheng Auto Bodyworks (HQ)	Thumbnail	Print
1	25/07/17 18:32	Repairer Estimates	 Load HTM	☒
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	24/05/18 12:49	General View	 Load JPG	☒
2	24/05/18 12:49	General View	 Load JPG	☒
3	24/05/18 12:49	General View	 Load JPG	☒
4	24/05/18 12:50	General View	 Load JPG	☒
5	24/05/18 12:50	General View	 Load JPG	☒
6	24/05/18 12:50	General View	 Load JPG	☒
7	24/05/18 12:50	General View	 Load JPG	☒
8	24/05/18 12:50	General View	 Load JPG	☒
9	24/05/18 12:50	General View	 Load JPG	☒
10	24/05/18 12:50	General View	 Load JPG	☒
11	24/05/18 12:50	General View	 Load JPG	☒
12	24/05/18 12:50	General View	 Load JPG	☒
13	24/05/18 12:50	General View	 Load JPG	☒
14	24/05/18 12:50	General View	 Load JPG	☒
15	24/05/18 12:50	General View	 Load JPG	☒
16	24/05/18 12:50	General View	 Load JPG	☒
17	24/05/18 12:50	General View	 Load JPG	☒
18	24/05/18 12:50	General View	 Load JPG	☒
19	24/05/18 12:50	General View	 Load JPG	☒
20	24/05/18 12:50	General View	 Load JPG	☒
21	24/05/18 12:50	General View	 Load JPG	☒
22	24/05/18 12:50	General View	 Load JPG	☒
23	24/05/18 12:50	General View	 Load JPG	☒
24	24/05/18 12:50	General View	 Load JPG	☒
25	24/05/18 12:50	General View	 Load JPG	☒
26	24/05/18 12:50	General View	 Load JPG	☒
27	24/05/18 12:50	General View	 Load JPG	☒
28	24/05/18 12:50	General View	 Load JPG	☒
29	24/05/18 12:50	General View	 Load JPG	☒
30	24/05/18 12:50	General View	 Load JPG	☒
31	24/05/18 12:50	General View	 Load JPG	☒
32	24/05/18 12:50	General View	 Load JPG	☒
33	24/05/18 12:50	General View	 Load JPG	☒
34	24/05/18 12:50	General View	 Load JPG	☒

Assessment Reports			1 per page	☒
No.	Finalized On	Cheng Auto Bodyworks (HQ)	Thumbnail	Print
				☒
35	24/05/18 12:50	General View		☒
36	24/05/18 12:50	General View		☒
37	24/05/18 12:50	General View		☒
38	24/05/18 12:50	General View		☒
39	24/05/18 12:50	General View		☒
40	24/05/18 12:50	General View		☒
41	24/05/18 12:50	General View		☒
42	24/05/18 12:50	General View		☒
43	24/05/18 12:50	General View		☒
44	24/05/18 12:50	General View		☒
45	24/05/18 12:50	General View		☒
46	24/05/18 12:50	General View		☒
47	24/05/18 12:50	General View		☒
48	24/05/18 12:50	General View		☒
49	24/05/18 12:50	General View		☒
50	24/05/18 12:50	General View		☒
51	24/05/18 12:50	General View		☒
52	24/05/18 12:50	General View		☒
53	24/05/18 12:50	General View		☒
54	24/05/18 12:50	General View		☒
55	24/05/18 12:50	General View		☒
56	24/05/18 12:50	General View		☒
57	24/05/18 12:50	General View		☒
58	24/05/18 12:50	General View		☒
59	24/05/18 12:50	General View		☒
60	24/05/18 12:50	General View		☒
61	24/05/18 12:50	General View		☒
62	24/05/18 12:50	General View		☒
63	24/05/18 12:50	General View		☒
64	24/05/18 12:50	General View		☒
65	24/05/18 12:50	General View		☒
66	24/05/18 12:50	General View		☒
67	24/05/18 12:50	General View		☒
68	24/05/18 12:50	General View		☒
69	24/05/18 12:50	General View		☒
70	24/05/18 12:50	General View		☒
71	24/05/18 12:50	General View		☒
72	24/05/18 12:51	Reinspection Photo		☒
73	24/05/18 12:51	Reinspection Photo		☒
74	24/05/18 12:51	Reinspection Photo		☒
75	24/05/18 12:51	Reinspection Photo		☒
76	24/05/18 12:51	Reinspection Photo		☒
77	24/05/18 12:51	Reinspection Photo		☒
78	24/05/18 12:51	Reinspection Photo		☒
79	24/05/18 12:51	Reinspection Photo		☒
80	24/05/18 12:51	Reinspection Photo		☒
81	24/05/18 12:51	Reinspection Photo		☒
82	24/05/18 12:51	Reinspection Photo		☒
83	24/05/18 12:51	Reinspection Photo		☒

Assessment Reports			1 per page	☒
No	Finalized On	Cheng Auto Bodyworks (HQ)	Thumbnail	Print
84	24/05/18 12:51	Reinspection Photo	 Load JPG	☒
85	24/05/18 12:51	Reinspection Photo	 Load JPG	☒
86	24/05/18 12:51	Reinspection Photo	 Load JPG	☒
87	24/05/18 12:51	Reinspection Photo	 Load JPG	☒
88	24/05/18 12:51	Reinspection Photo	 Load JPG	☒
89	24/05/18 12:51	Reinspection Photo	 Load JPG	☒
90	24/05/18 12:51	Reinspection Photo	 Load JPG	☒
91	24/05/18 12:51	Reinspection Photo	 Load JPG	☒
92	24/05/18 12:51	Reinspection Photo	 Load JPG	☒
93	24/05/18 12:51	Reinspection Photo	 Load JPG	☒
94	24/05/18 12:51	Reinspection Photo	 Load JPG	☒
95	24/05/18 12:51	Reinspection Photo	 Load JPG	☒
96	24/05/18 12:51	Reinspection Photo	 Load JPG	☒
97	24/05/18 12:51	Reinspection Photo	 Load JPG	☒
98	24/05/18 12:51	Reinspection Photo	 Load JPG	☒
99	24/05/18 12:51	Reinspection Photo	 Load JPG	☒
100	24/05/18 12:51	Reinspection Photo	 Load JPG	☒
101	24/05/18 12:51	Reinspection Photo	 Load JPG	☒
102	24/05/18 12:51	Reinspection Photo	 Load JPG	☒
103	24/05/18 12:51	Reinspection Photo	 Load JPG	☒
104	24/05/18 12:51	Reinspection Photo	 Load JPG	☒
105	24/05/18 12:51	Reinspection Photo	 Load JPG	☒
106	24/05/18 12:51	Reinspection Photo	 Load JPG	☒
107	24/05/18 12:51	Reinspection Photo	 Load JPG	☒
108	24/05/18 12:51	Reinspection Photo	 Load JPG	☒
109	24/05/18 12:51	Reinspection Photo	 Load JPG	☒
110	24/05/18 12:51	Reinspection Photo	 Load JPG	☒
111	24/05/18 12:51	Reinspection Photo	 Load JPG	☒
112	24/05/18 12:51	Reinspection Photo	 Load JPG	☒
113	24/05/18 12:51	Reinspection Photo	 Load JPG	☒
114	24/05/18 12:51	Reinspection Photo	 Load JPG	☒
115	24/05/18 12:51	Reinspection Photo	 Load JPG	☒
116	24/05/18 12:51	Reinspection Photo	 Load JPG	☒
117	24/05/18 12:51	Reinspection Photo	 Load JPG	☒
118	24/05/18 12:51	Reinspection Photo	 Load JPG	☒
119	24/05/18 12:51	Reinspection Photo	 Load JPG	☒
120	24/05/18 12:51	Reinspection Photo	 Load JPG	☒
121	24/05/18 12:51	Reinspection Photo	 Load JPG	☒
122	24/05/18 12:51	Reinspection Photo	 Load JPG	☒
123	24/05/18 12:51	Reinspection Photo	 Load JPG	☒
124	24/05/18 12:51	Reinspection Photo	 Load JPG	☒
125	24/05/18 12:51	Reinspection Photo	 Load JPG	☒
126	24/05/18 12:51	Reinspection Photo	 Load JPG	☒
127	24/05/18 12:51	Reinspection Photo	 Load JPG	☒
128	24/05/18 12:51	Reinspection Photo	 Load JPG	☒
129	24/05/18 12:51	Reinspection Photo	 Load JPG	☒
130	24/05/18 12:51	Reinspection Photo	 Load JPG	☒
131	24/05/18 12:51	Reinspection Photo	 Load JPG	☒
132	24/05/18 12:51	Reinspection Photo	 Load JPG	☒
133	24/05/18 12:51	Reinspection Photo	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Cheng Auto Bodyworks (HQ)	Thumbnail	Print
134	24/05/18 12:51	Reinspection Photo	 Load JPG	☒
135	24/05/18 12:51	Reinspection Photo	 Load JPG	☒
136	24/05/18 12:51	Reinspection Photo	 Load JPG	☒
137	24/05/18 12:51	Reinspection Photo	 Load JPG	☒
138	24/05/18 12:51	Reinspection Photo	 Load JPG	☒
139	24/05/18 12:51	Reinspection Photo	 Load JPG	☒
140	24/05/18 12:51	Reinspection Photo	 Load JPG	☒
141	24/05/18 12:51	Reinspection Photo	 Load JPG	☒
142	24/05/18 12:51	Reinspection Photo	 Load JPG	☒
143	24/05/18 12:51	Reinspection Photo	 Load JPG	☒
144	24/05/18 12:51	Reinspection Photo	 Load JPG	☒
145	24/05/18 12:51	Reinspection Photo	 Load JPG	☒
146	24/05/18 12:52	Reinspection Photo	 Load JPG	☒
147	24/05/18 12:52	Reinspection Photo	 Load JPG	☒
148	24/05/18 12:52	Reinspection Photo	 Load JPG	☒
149	24/05/18 12:52	Reinspection Photo	 Load JPG	☒
150	24/05/18 12:52	Reinspection Photo	 Load JPG	☒
151	24/05/18 12:52	Reinspection Photo	 Load JPG	☒
152	24/05/18 12:52	Reinspection Photo	 Load JPG	☒
153	24/05/18 12:52	Reinspection Photo	 Load JPG	☒
154	24/05/18 12:52	Reinspection Photo	 Load JPG	☒
155	24/05/18 12:52	Reinspection Photo	 Load JPG	☒
156	24/05/18 12:52	Reinspection Photo	 Load JPG	☒
157	24/05/18 12:52	Reinspection Photo	 Load JPG	☒
158	24/05/18 12:52	Reinspection Photo	 Load JPG	☒
159	24/05/18 12:52	Reinspection Photo	 Load JPG	☒
160	24/05/18 12:52	Reinspection Photo	 Load JPG	☒
161	24/05/18 12:52	Reinspection Photo	 Load JPG	☒
162	24/05/18 12:52	Reinspection Photo	 Load JPG	☒
163	24/05/18 12:52	Reinspection Photo	 Load JPG	☒
164	24/05/18 12:52	Reinspection Photo	 Load JPG	☒
165	24/05/18 12:52	Reinspection Photo	 Load JPG	☒
166	24/05/18 12:52	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	05/06/18 12:01	Parts Invoice	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)				
Show Remarks To: ☐ Repairer ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI17014573/T1RBE2

Date: 05/06/2018

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMHCSN1715791700

Claimant Vehicle
No: EK16MInsured Vehicle
No: SKT8906Z

Date of Loss: 22/07/2017

Nature of Claim: TP

Claim
No: SNM17D04371C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: EK16M

Make & Model: TOYOTA ALPHARD, 2.5 (A)

Engine No: 2ARH566278

Reg. Date: 29/03/2016 (Man. Year: 2015)

Chassis No: AGH300018350

Colour: White

Odometer: 36021 km

Engine Capacity: 2493 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/50 R18

Rear Tyre Size: 235/50 R18

Front Left Side: Dunlop 6 mm

Rear Left Side: Dunlop 6 mm

Front Right Side: Dunlop 6 mm

Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,185.80	10,244.85	6,940.95	40.39
Miscellaneous Items	1,025.92	0.00	1,025.92	100.00
Labour	2,125.69	2,015.29	110.40	5.19
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	20,337.41	12,260.14	8,077.27	39.72
+ GST 0.00/7.00% (S\$)	0.00	858.21	-858.21	
Nett Amount (S\$)	20,337.41	13,118.35	7,219.06	35.50

INSPECTION

Date of Assignment: 28/07/2017 Present Location:

Cheng Auto Bodyworks (HQ)

Date Inspected: 27/07/2017 Inspected At:

5 Soon Lee Street #01-62 Pioneer Point
Singapore 627607

Estimated Period of Repair: 10.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

MARKET VALUE: \$178,000.00(EST)-LTA REIMBURSEMENT VALUE: \$72,858.00=NETT VALUE: \$105,142.00

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 Jun 2018)
Parts:	M1-MPV	TOYOTA ALPHARD 2.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for EK16M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1	NA	*BADGE PREVIA (WCP)	Necessary	55.00 F	*55.00 F
2	1	NA	*BOOT/TAILGATE LOCK (WCP)	Bent	400.00 F	*400.00 F
3	1	NA	*BOOT/TAILGATE SEAL (WCP)	Necessary	190.00 F	*190.00 F
4	1	NA	*BOOTLID/TAILGATE (WCP)	Bent	1,050.00 F	*1,050.00 F
5	1	NA	*CONDENSER (WCP)	Bent	750.00 F	*750.00 F
6	1	NA	*END PANEL SNSR (WCP)	Distorted	120.00 F	*120.00 F
7	1	NA	*FRONT BUMPER (WCP)	Deformed	900.00 F	*900.00 F
8	1	NA	*FRONT BUMPER SUPPORT (WCP)	Bent	250.00 F	*250.00 F
9	1	NA	*FRT BUMPER ABSORBER (WCP)	Deformed	50.00 F	*50.00 F
10	1	NA	*FRT BUMPER CLAMP KIT (WCP)	Necessary	20.00 F	*20.00 F
11	1	NA	*FRT NO PLATE REINF (WCP)	Cut	128.00 F	*128.00 F
12	1	NA	*GRILLE (WCP)	Cracked	550.00 F	*550.00 F
13	1	NA	*GRILLE BADGE (WCP)	Necessary	180.00 F	*180.00 F
14	1	NA	*HEATED REAR SCREEN (WCP)	Not Necessary	650.00 F	*- F
15	1	NA	*L/F FOG LAMP (WCP)	Not Necessary	220.00 F	*- F
16	1	NA	*L/F OUT BUMPER BRKT (WCP)	Necessary	45.00 F	*45.00 F
17	1	NA	*L/FOG LAMP COVER (WCP)	Deformed	120.00 F	*120.00 F
18	1	NA	*L/R BUMPER BRACKET (WCP)	Necessary	65.00 F	*65.00 F
19	1	NA	*L/R HINGE (WCP)	Repair	45.00 F	*- F
20	1	NA	*L/R IMPACT DAMPER (WCP)	Not Necessary	175.00 F	*- F
21	1	NA	*L/R INN BUMPER BRKT (WCP)	Necessary	65.00 F	*65.00 F
22	1	NA	*L/R INNER LAMP (WCP)	Not Necessary	360.00 F	*- F
23	1	NA	*L/R OUTER LAMP (WCP)	Not Necessary	360.00 F	*- F
24	1	NA		Not Necessary	40.00 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
			*L/R REFLECTOR (WCP)			
25	1	NA	*LEFT HEADLAMP ASSY (WCP)	Not Necessary	1,600.00 F	*- F
26	1	NA	*LOCKING PLATE (WCP)	Not Necessary	45.00 F	*- F
27	1	NA	*LWR RADIATOR GRILLE (WCP)	Cut	95.00 F	*95.00 F
28	1	NA	*R/F BUMPER OUT BRKT (WCP)	Necessary	45.00 F	*45.00 F
29	1	NA	*R/F FOG LAMP (WCP)	Not Necessary	220.00 F	*- F
30	1	NA	*R/FOG LAMP COVER (WCP)	Deformed	120.00 F	*120.00 F
31	1	NA	*R/R BUMPER BRACKET (WCP)	Necessary	65.00 F	*65.00 F
32	1	NA	*R/R HINGE (WCP)	Repair	45.00 F	*- F
33	1	NA	*R/R IMPACT DAMPER (WCP)	Not Necessary	175.00 F	*- F
34	1	NA	*R/R INN BUMPER BRKT (WCP)	Necessary	65.00 F	*65.00 F
35	1	NA	*R/R INNER LAMP (WCP)	Not Necessary	360.00 F	*- F
36	1	NA	*R/R OUTER LAMP (WCP)	Not Necessary	360.00 F	*- F
37	1	NA	*R/R REFLECTOR (WCP)	Not Necessary	40.00 F	*- F
38	1	NA	*REAR BADGE (WCP)	Necessary	55.00 F	*55.00 F
39	1	NA	*REAR BUMPER (WCP)	Deformed	900.00 F	*900.00 F
40	1	NA	*REAR PANEL (WCP)	Bent	450.00 F	*450.00 F
41	1	NA	*REAR REFLECTOR (WCP)	Not Necessary	350.00 F	*- F
42	1	NA	*RIGHT HEADLAMP ASSY (WCP)	Cut	1,600.00 F	*1,600.00 F
43	1	NA	*RR BUMPER CLAMP KIT (WCP)	Necessary	20.00 F	*20.00 F
44	1	NA	*RR LH FEND CVR (WCP)	Deformed	314.00 F	*314.00 F
45	1	NA	*RR RH FEND CVR (WCP)	Repair	314.00 F	*- F
46	1	NA	*SPECIALIST AUDATEX FEES		42.00 FS	*42.00 FS
47	1	NA	*SPECIALIST COOLANT	Not Necessary	30.00 FS	*- FS
48	1	NA	*SPECIALIST FRT PARKING SNSRX4	Not Necessary	800.00 FS	*- FS
49	1	NA	*SPECIALIST REAR PARKING SNSRX4	Necessary-2 pcs only	800.00 FS	*400.00 FS
50	1	NA	*SPECIALIST WINDSCREEN SEALANT	Necessary	25.00 FS	*25.00 FS
51	1	NA	*SUNDRY PARTS	Necessary	100.00 FS	*100.00 FS
52	1	NA	*TAILGATE SNS (WCP)	Not Necessary	80.00 F	*- F
53	1	NA	*TAILGATE TRIM BRD (WCP)	Deformed	550.00 F	*550.00 F

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	16,453.00	9,784.00
+ Margin on L,N Items 5.00/5.00% (\$\$)	732.80	460.85
Total Parts (\$\$)	17,185.80	10,244.85

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	GST 7%	1,025.92	0.00
Sub Total (S\$)			1,025.92	0.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	Total Paint Labour	New	1,168.40	1,122.40
2	Total Paint Materials	New	244.29	244.29
3	Total Panel/Mechanical Labour	New	713.00	648.60
Gross Labour Cost (S\$)			2,125.69	2,015.29

Report was unsubmitted during this print-out.

< END OF ESTIMATES >