ASS. REC. BY:	REF: CS/N	71tb	y Special Instruction:	:
Sorvator: Tal	Assic	GNMENT (Office)		
From (Person):	Irene Tan . of	msth	Date/Time:	28072017 357pm
Estimated Cost:		Bill to:		
OD-(UD)/WS+TPR	ES / OD RES / EVA / INV /	MV / CS		
To Inspect Vehicle No	SKO '	16518 I	nsured: SLC	9492X
at Workshop m/s			Tel: 6272 38	\$92
of	15 Fan Yong Ri	od		
Policy No:	128 9781 43 mp	Claim No:	524302.	
Sum Insured:		Excess:		
Make of Veh: (Client's Record)			D.O.A.	7207 2017
CA / REV / REP.	/ REV 24 HRS (Mp)	7 9 FOCFUIE	Morning H.O.D. Endo	orsement:
Date/Time: 1807)	OF Upm Person Cont	acted: Elic	Vehicle (N)	OUT
Date/Time Action	a/Instruction (✓) Es	finate		
CKN	1871. x		· · · · · · · · · · · · · · · · · · ·	·····
Sic	911-1 x x			
			··	

72/03/2002

Sirvaulir Tauth REF: MSLA	•
mumun A	SSIGNMENT
2.50	Veh No: SKQ48216. Yr Regn: 2014, Dec.
	Type: M.Qar / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Estimated Cost:	Truck / Trailer or
OD/TP) WS/TP RES/OD RES/EVA/INV/MV	
To Inspect Vehicle No: SKQ 48118	Make: 79 ypta Vios. G c.c 1497- Colour Salvar A/C: Insured / Std / NI / NA
at Workshop m/s Movu	
of 15 Fan Yong Road	Sp.Reading (QS) 15. T/Radio: Insured / Std / NI / NA
Insured:	Eng/No:
Policy No.	C/No: MHFBT9FSX BLO 22322
Claims No.	Gen. Cond: Godd / Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inforder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil / S/Rim / STD A/Rim or
morning	Tyre Size: F: /85/60/7/5
(Policy Condition)	R: ~ ~ ~
Remark: The veh had commenced its N/S O	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO/YOKO or ConfirmAc
Bal. or Market Value: 4 75 K	Front Rear
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. 6 mm R/Bal. 6 mm
GIA / PR Seen: Consistent? : Yes or No	L/Bal. 6 mm L/Bal. 6 mm
Est. Repairs: days Res.: Yes or No	D.O.A. D.O.J. 31/7/12 3/19
Lum Sum: % 3 Val.: Yes or No	Survey held at Mova Fan Joney
CA / REV / REP. / 24 HRS	Des. of Damages: Fpt / Rear / O/S / N/S / U/C / Rooftop or
Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction	
Q 1612	······································
(Reg	3604.25 (18°1.)
	hus to
	652/2kg/1
	نا ن غ
Data Cine Cia Decembra	Dave Of Bonaire 15
Date/Time, File Pass to? : Prelli. Report	Days Of Repail.
1) 203 WMST Final Report	Resurvey No. of Trip: Survey Fee: 300
Date/Time, File Return to? 2) Add I	Transportation: Site Insp (\$)S+RSSI
2) Add i	
TD	: Interview (\$) Photos
Report Format:	:Tech. Invs (\$) Others
Lump Sum / 1.8.1) (\$ 16,124)	:Weekend (\$) .
	TOTAL 210



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Granding	Affiliated to Federation Internation		, , , , , , , , , , , , , , , , , , , ,	
MSIC	SINSURANCE (SI	NGAPORE) PTE LTD	Ref : CS/MSG1701461	1/T1tb	
	AFFLES QUAY 01 HONG LEONG	BLDG SINGAPORE 048581	Date: 28-07-2017 Code: MSG		
17.		Policy Particulars	;- THIRD PARTY CLAIM		
	Insured Veh.	SLC 9492X	Veh. Inspected	SKQ 4821B	
	Policy No.	A28978143TMP	Coverage (\$)	0.00	
•	Claim No.	524302	Excess (\$)	0.00	
	Assign From	MERIMEN (IRENE TAN)	Assign Date	28/07/2017	
2		Vehicle Parti	culars & Condition	"""说" "于特 说的执道	
	Make & Model		c.c	0	
	Engine No.	HIDDEN	Year of Reg.		
	Chassis No.		Colour		
	Odometer	-	Steering		
	Brakes		Modification		
	General				
3.	A CONTRACTOR OF THE STATE OF TH	Condit	ons of Tyres		
		Size	Make	Balance	
	R/H Front Tyre			mm	
	L/H Front Tyre			mm	
	R/H Rear Tyre			mm	
<u>্বর জেলি</u> ন সাধ্য	L/H Rear Tyre	a trong of the section of the sectio	The state of the s	mm	
. Alerti		v _{el} Descripti	on of Damages	and the state of t	
5. 🗼	l Segina ko	নান্য নান্ত Genera	l Information		
	Accident Date	22/07/2017	Inspection Date	31/07/2017	
	Survey held at	MOVA AUTOMOTIVE PTE LTD			
		15 FAN YONG ROAD SINGAPORE 629792			
5a(La Testa de la Constantina del Constantina de la	R	emarks 🚉 🎎 👢 👢		
		ON WAS CONDUCTED ON A"WIT			

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	24 Jul 2017		28 Jul 2017 15:57 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All	
CLAIM SUBFOLDER D	ETAILS		[Created by insurer]		
Insured:	LEO VALENTINE @LI HAN BIN, I	D: S8124764A, Tel: +658228074	2, Email: leovalentine242	2@gmail.com	
Main Clalmant:	LEE CHEY, ID: S0226433A				
Vehicle Reg. No.:	SKQ4821B	Date of Loss:	22/07/2017 15:00 - :59		
Claim Type:	TP / 524302	Policy/Cover Note No.:	A28978143TMP (Third Pa Coverage: 21/06/2017 -		
Vehicle Reg. No. (Insured):	SLC9492X	Policy No. (Claimant):			
		Excess:			
Repairer:	Mova Automotive Pte Ltd (HQ) Blo	ock 1008 Bukit Merah Lane 3 #01-	04/06/08/94, 159722 Bukit	Merah - Tel:	
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 [Handled by Irene Tan Gek Ing - 6594 2541]				
Adjuster:	LKK Auto Consultants Pte Ltd (HC) - Tel: 6256-3561 [Imm.Ad	vice due 29/07/2017)		
Driver/Custodian (Insured):	LEO VALENTINE @LI HAN BIN (35 / N				
ASSOCIATED MAIL R	ECEIVED		View All Com	pose Case Mail	
ASSOCIATED MAIL R			View All Com	pose Case Mail	
There are no mail for this	s case.		View All Com	pose Case Mail	
There are no mail for this	s case.	View All Search T			
There are no mail for this	s case.			Complete	

Text size +

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Singapore NRIC

Owner ID:

6433A

Vehicle Details

Vehicle No.:

SKQ4821B

Vehicle to be Exported:

Intended De-registration

01 Aug 2017

Vehicle Make:

TOYOTA

Vehicle Model:

VIOS G GRADE AUTO

Primary Colour:

Silver

Manufacturing Year:

2014

Engine No.:

1NZZ079334

Chassis No.:

MHFBT9F3X06022322

Maximum Power Output:

80.0 kW (107 bhp)

Open Market Value:

\$15,154.00

Original Registration Date: 01 Dec 2014

First Registration Date:

01 Dec 2014

Transfer Count:

Actual ARF Paid:

\$10,154.00

Intended PARF Rebate Details

PARF Eligibility:

PARF Eligibility Expiry Date: 30 Nov 2024

PARF Rebate Amount:

\$7,615.00

Intended COE Rebate Details

COE Expiry Date:

30 Nov 2024

COE Category:

A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years):

10

QP Paid:

\$64,600.00

COE Rebate Amount:

\$47,355.00

Total Rebate Amount:

\$54,970.00

The information contained herein is correct as at 01 Aug 2017

OK

Land Transport Authority

Please read through the Privacy Statement, Terms of Use and Disclaimer. Please do not use the Back or Forward buttons on your browser as this may alter the results of the transactions. Best viewed with IE 6.0 SP3 and above. 1024 X 768 resolution Copyright © 2017 LTA | Privacy Statement | Terms of Use | Disclaimer | Rate the Website | Rate this e-Service Last updated on 30 Jul 2017 at 12:58 AM

8/1/17, 9:03 AN

MMOV17096685 / Mova Automotive Pte Ltd - Bukit Merah ENTRY DATE & TIME: 22/07/2017 16:43

TP MS1G.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

aforesaid.		
	ACCIDENT STATEMENT	
Date Of Report	22/07/2017 16:43	
Date Of Accident	22/07/2017 15:15	
Exact Location Of Accident	BOON LAY WAY	
Country/State of Loss	SINGAPORE	
	DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SKQ4821B	
Insured/Policyholder		
Name Of Registered Owner	LEE CHEY	
NRIC No	S0226433A	
Email Address	LEECHEVAO@GMAIL COM	

Email AddressLEECHEY49@GMAIL.COMMobile Phone No(LOCAL) +65-91052196Alternative Phone NoHOME-NOPHONE

Alternative Priorie No. HowL-NOPHONE

Vehicle Particulars

Manufacturer TOYOTA

Model VIOS-1.5 G (A)

Exact Purpose for which vehicle was being used at

time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

NO

If No, Please state action to be taken THIRD PARTY
Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company AIG ASIA PACIFIC INSURANCE PTE. LTD.

Type Of Coverage COMPREHENSIVE

Fleet Policy NO

Policy Number 2100394515-02000

Cover Note Number

Driver

Name of Driver LEE CHEY
NRIC No S0226433A
Date Of Birth 08/07/1949
Occupation INDOOR
Date Of Driving Pass 06/05/1968

Driving Experience 49 YEARS AND 2 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-91052196

Fax Number

Contact Number HOME-NOPHONE

EMail Address LEECHEY49@GMAIL.COM

Address

Postcode

Was driver an employee of the Insured's Company NO

OWNER If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

CHAIN COLLISION

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

YES

Foreign Vehicle Registration Number

JNT8237 (PRIVATE CAR)

Was any body injured in the Accident? Was any other material or property damaged? NO **YEŞ**

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

1

Details of Police Action

Was the accident reported to the police?

YES

If Yes.Please state which Police Station

Police Station Name

HONG KAH SOUTH NEIGHBOURHOOD POLICE POST

Police Station Address

ROAD: BLK 510 JURONG WEST STREET 52, POSTCODE: 640510,

COUNTRY: SINGAPORE

Police Station Contact

TEL NO: 1800-5648999 - FAX NO: 66655797

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?

Was there any video captured by Car Camera?

Was there any audio recorded?

YES

YES

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

Vehicle Make/Model/Colour

Details Of Properties

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

SLC9492X

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

Vehicle Make/Model/Colour

Details Of Properties

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

JNT8237

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Formmust be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims:
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & 1 Driver's Signature (If driver is not the policyholder) / Date

В

Sketch Plan $V' \mid 16.0V \mid 1$

Witnessed by Reporting Centre Personnel

A: 5KQ4821B B: 5LC9492X

C JNT 8237

Sketch Plan Pg. 2

Describe Circumstances of the Accident	LICENSE PLATE NUMBER: SKQ 482/R
ACCIDENT DATE: 22-7-2017	CONTACT NUMBER: 9 / 05 2/9%
ACCIDENT TIME: 3.15 pm	EMAIL: /eechey 49 @ guail.com
ACCIDENT TIME: 3.15 pm LOCATION: BOON LAY WAY	
REFER TO POLICE LEPORT	
NOTE: PLEASE NOTE THAT YOUR INSURER N	MAY HAVE 14 DAYS TIME FRAME FOR YOU TO SUBMIT
1	AIM UNDER YOUR OWN POLICY.
	OLICY FOR MORE INFORMATION.
Please state:	OBIOT TOLEMOND INTOLKRATION.
	() Claim OD/TP at other workshop () Reporting Only
	, repeating one
Declaration	
MANA de alegan Alegan area de de alegan area de de alegan area de de alegan area	
IWe declare the foregoing particulars are true in every respect	PIE
1111111111111	
1/1/W [*] /	
N/ V° -	AVOIT
Delicularidada Signatura / Data 2	
Policyholder's Signature / Date & Driver's Signature (If driv	er is not the policyholder) / Date Witnessed by Reporting Centre Personnel
22/11/1011	. www.printer
Time VIII WIT & Time **Time** **T	
1100	





1 of 4

Report No. T/20170722/2143

Police Station Of Origin: Hong Kah South NPP 510 Jurong West Street 52 #01-90 SINGAPORE 640510 Tei No: 1800-5648999

REPORT OF	A TRAFFIC	ACCIDENT		Station Diary No.		
Date/Time Report Made: 22/07/2017 19:53			Vide Report No.:	33		
THE SECTION	esser and other		Paddross:			
Name of I LEE CHE	nformant:		APT BLK 257 BOON LAY DRI 640257	VE #02-501 SINGAPORE		
ID Type / ID No.: NRIC NO / S0226433A			Contact No.: Home/Office:	Mobile: 91052196		
Nationality: SINGAPORE CITIZEN			Email:			
Sex: Male	Age: 68	Date of Birth: 08/07/1949	Type of Informant: Driver	The state of Name of N		
Race:		<u> </u>	Language: English	Institution / School Name:		
Occupation:			Driving Licence Information: Class: 3	Date of Expiry:		
INSUKA	いしに べいに	W I				

Type of Accident:	Non-injury Foreign Vehicle	Drink Drive: No	Date/Time of Accident: 22/07/2017 15:15	Type of Location: Straight Road
Location: Along Road BOON LAY V		ON		Road Speed Limit
Weather: Clear		Road Surface:		Traffic Volume:
Traffic Flow: One Way		Traffic Control: Traffic Light - Wo	orking	Moderate
Type of Colli	sion: cle Against - Parked Ve	hicle		Anyone conveyed by ambulance:

			动物动物 经净效益			
JNT8237	Car		2.24.22.22.22.24.22.2		Slightly Damaged	0 ,
SKQ4821B	Саг	TOYOTA	VIOS G GRADE AUTO	Silver	Seriously Damaged	0
SLC9492X	Car		AUIU		Seriously Damaged	0

2

なが、大場の表とは過ぎる

• :

i

•





Police Station Of Origin: Hong Kah South NPP 510 Jurong West Street 52 #01-90 SINGAPORE 640510 Tel No: 1800-5648999

2 of 4 Report No. T/20170722/2143

CONTINUATION OF REPORT

- 1						
i			Professional Company of the Company			
- 1				The state of the s		
			A GO C. AND PROCESS OF THE PROPERTY OF THE PARTY OF THE P	ber einem mir eine ber ber ber ber ber ber ber ber ber be	and the second s	433
						#25Jd
	The state of the s					
						-
	CKU3/02/43	4 4 4 4 4 4			and the second of the second o	`,
- 1	UNICHOZ 125	I AIG ANIA PACIE	IC INSURANCE PTE		Company of the control of the contro	
)	IN IMPOUNDABLE PIE	! 71/N/304516	01/12/2018 30/11/20	
		1177		W (4000013)	- LUHTZ//ZDAK AN/44/204	17 !
1		I LIU.		1 .		11
	a commendation of the said			1	1	- 1
		·			1 .	- 1
						,

		L			<u> </u>
		25 C. C. S. S.	Self Sec.	$a_{i,j}(\gamma)$	Program entre program de la companya
Any Pedestrian	Involved: No				A CONTRACTOR OF THE PARTY OF TH
No. of Padestria	ins Injured: NIL	Use of Pe	destria	n Cros	sing: NA
Name					
. Name	LEE SHIOW THING		ID No		920107-01-6360
Related Vehicle	JNT8237 (Car)		-		
	(Gai)		Conta	ct No.	+60164415595
Hospital/Clinic	NIL	· · · · · · · · · · · · · · · · · · ·	Class	of	Class: NIL
			Drivin		Date of Explry: NIL
	,		Licena		Dear of Expay, 1412
Data Taratana			Explry		
Date Treatment	NIL	Date Disc	harge	NIL	<u> </u>
IVU. OF Days gran	ited Medical Leave NIL	Degree of	Injury :	NIL	
Name		S. M. M. M.	A. 1.		(1) (1) (1) (1) (1) (1) (1) (1) (1) (1)
Mana	LEE CHEY	· · · · · · · · · · · · · · · · · · ·	ID No.		S0226433A
Related Vehicle	SKQ4821B (Car)		Contac		0400040
			CONTRA	CE NAO.	91052196
Hospital/Clinic	NIL		Class	0/	Class: 3
	f .		Driving	,	Date of Expiry: NIL
			Licenc	e&	and or Expery. Isin
Date Treatment			Explry	Date	
No of Dave eres	NIL	Date Disci	rarge	NIL	· · · · · · · · · · · · · · · · · · ·
to or pays grain	ted Medical Leave NIL	Degree of	Injury	NIL	
Vame					
Active	LEO VALENTINE OLI HAN BIN		ID No.	1	S8124784A
Related Vehicle	SI COLONY (S				
ICIDION ACINCIA	SLC9492X (Car)	1	Contac	t No.	82280742
tospital/Clinic	NIL		Class		Class: 3
		i	Driving	1	Date of Expiry: NIL
	•	1	Licence		Date of Exhity: MIL
Date Treatment	NIL I	<u></u>	Expiry I		***
		Date Disch	arge		
TO A STANKE	ed Medical Leave NIL	Degree of I	nlury	NIL	







3 01 4

Report No. T/20170722/2143

CONTINUATION OF REPORT

Brief Details.

On 22/07/2017, at about 1515hrs, I was traveling along Boon Lay Way, towards Boon Lay MRT station, I met into an incident with (V1: JNT8237) and (V2: SLC9492X). It was a three lane road and I was traveling along the center lane, lane 2. As I was nearing a traffic light that was near Canadian International School along Boon Lay Way, I slowly came to a stopped as it was red light and there were around four vehicle ahead of me including V1. After stopping for around 30 seconds, suddenly I felt a huge impact from the rear of my vehicle. The impact causes my vehicle to moved forward and my front of my vehicle collided into V1's rear. After the collision, I came out of my car and realized that actually V2's front have collided onto my vehicle's rear. V2's driver then checked with me whether did I sustained any injuries and also checked with V1's driver, no one sustained any injuries during this incident. I then exchanged particulars with V2's and V1's driver. After exchanging of particulars, I then shifted my vehicle to the road shoulder and wait for my tow to arrive.

This is the first time such incident have happened. I do have an in-built camera in my vehicle and it was on recording mode during the incident. No Police or ambulance attended to the incident, no government property was damaged and no one sustained any injuries from this incident.

ţ

弘明 其職五為以其事 沙

į





Police Station Of Origin: Hong Kah South NPP 510 Jurong West Street 52 #01-90 SINGAPORE 640510 Tel No: 1800-5648999

4 of 4) Report No. T/201707222143/

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

FA+

IMPORTANT: Please attach a copy of your vehicle's insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: J / LIM JIA WEI, NICHOLAS	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time; 22/07/2017 19:53
Officer In Charge Of Case: TP / AEIT / Staff Sgt TANG SIEW PING Contact No.: 65476430	Classification Of Case:
Authentication Stamp	





Main Office Move Buildin No. 22, Jaian Kilang Singaporo 15941 Tel: (65) 6476 333 Fax: (65) 6271 589

www.move.com.s

Estimate

25/07/2017

MSIG INSURANCE (S) PTE LTD (SGX CENTRE) 16, RAFFLES QUAY #24-01 HONG LEONG BUILDING SINGAPORE 048581.

Page #

- SKQ4821B Veh#

Veh Model :- TOYOTA VIOS 1.5G

CK416139 Estimale# :-

Claim#

ACC. Date :- 22/07/17

Terms :- C.O.D Days

Workshop Depi Block 1006 Bukit Merah Lane (#01-04/06/08/9 Singapore 15972

Tel : (65) 6272 389 Fax : (65) 6270 831

Co. Reg. 1989040334 GST Reg. M2-0088864-

Attention: XA013

No.	Description	Qty	U.Price Amounts S\$
	LIST ITEMS :		
1,	FRONT BUMPER	1 PC	480.00 Le 480.00.
2.	FRONT BUMPER SIDE RETAINER	2 PC	67,00 44 134.00
3.	FRONT BUMPER LOWER GRILLE	1 PC	280.00 de 280.00
4.	FRONT BUMPER TOWING COVER	1 PC	55.00 mg 55.00
5.	FRONT BUMPER CHROME MOULDING	2 PC	68.00 ant 136.00
6.	FRONT BUMPER TOP CHROME MOULDING	1 PC	395.00 cm 395.00
7.	FRONT BUMPER REINFORCEMENT	1 PC	390.00 8 7 390.00
8.	FRONT BUMPER LOWER GRILLE MOULDING	1 PC	150.00 Aut 150.00
9.	FRONT BUMPER CLIPS	20 PC	5.00 My 100.00
э. 10.	HEADLAMP	20 PC	890.000 1,780.00
11.	HEADLAMP BRACKET	2 PC	67.00 di 3 134.00
12.	BONNET	1 PC	895,00 1/ 895.00
		10 PC	5,00 2 50.00
13.	INSULATOR CLIPS SUPPORT TOP COVER	10 PC	250.00 34 250.00
14.	FRONT BRACE PANEL	1 PC	146.00 6t 146.00
15.			85.00 Age 85.00
16.	FRONT BUMPER LOGO	1 PC	510,00 de 510,00
17.	REAR BUMPER	1 PC	50.00 may 100.00
18.	REAR BUMPER SIDE RETAINER	2 PC	48.00 Ne / 96.00
19.	REAR BUMPER INNER RETAINER	2 PC	190,00 mis 380.00
20.	REAR BUMPER REFLECTOR LAMP	2 PC	
21.	REAR PARKING SENSOR ASSY		350.00 mis/ 350.00 350.00 350.00
22.	REAR REINFORCEMENT	1 PC	
23.	RER BUMPER CLIPS	20 PC	
24.	BOOT LID	1 PC	1,663.00 bt 1,663.00 95.00 bt 95.00
25.	BOOT LID LOCK	1 PC	71.0
26,	BOOT LID HINGE	2 PC	60.00 //6 120,00
27.	BOOT LID GARNISH	1 PC	165.00 CM 165.00 95,00 7490.00
28.	BOOT LID NUMBER PLATE LAMP	2 PC	4. /
29.	BOOT LID LOGO	1 PC	M/
30.	BOOT LID (VIOS) EMBLEM	1 PC	30,00
31.	BOOT LID (G) EMBLEM	1 PC	
32 .	BOOT LID INNER TRIM	1 PC	375.00 de 375.00
33.	TAILLAMP	2 PC	248.00 00 498.00
34.	TAILLAMP PANEL	2 PC	160.00 bt 320.00
35.	TAILLAMP CLIPS	4 PC	15.00 ~4 60.00
36.	TAILLAMP GASKET	2 PC	30,00 00 60.00
37.	REAR FENDER LH-HVIRH-RY	2 PC	997.00 997 1,994.00
38.	REAR FENDER AIR VENT LA LEVIRHARY	2 PC	110.00 Kny 220.00-
39.	REAR FENDER INNER SHIELD	2 PC	60.00 mec 120.00
40.	INNER TRIM CLIPS	20 PC	5.00 de 100.00
41.	END PANEL GARNISH	1 PC	235.00 bt 235.00
42.	END PANEL ASSY	1 PC	695.00 695.00
43.	SPARE TYRE BOARD	1 PC	230.00 de 230.00
44.	SPARE TYRE LH SPONGE	1 PC	210.00 2 210.00
45.	SPARE TYRE RH SPONGE	1 PC	210.00 de 210.00
46.	FLOOR PANEL ASSY	1 PC	690.00
47.	REAR TRUCK LID WEATHERSTRIP	1 PC	190.00 كرنبك 190.00
48.	REAR WINDSCREEN MOULDING REAR FENDER INNER TRIM ALH_ AL , RH - 10 / RH - 10	1 PC	100.00 ملعب 100.00
49,	REAR FENDER INNER TRIM HALLAN RH - PULL	2 PC	395.00 790.00
50.	REAR EXHAUST HEAT SHIELD	1 PC	100.00
51.	REAR CHASSISMEMBER RH	1 PC	450.00 £∞ 450.00





Estimate

Attention: XA013

25/07/2017

MSIG INSURANCE (S) PTE LTD (SGX CENTRE) 16, RAFFLES QUAY #24-01 HONG LEONG BUILDING SINGAPORE 048581.

Page #

:- 1

128878

Veh#

:- SKQ4821B

Veh Model: TOYOTA VIOS 1.5G

Estimate# :- CK416139

Claim#

ACC, Date :- 22/07/17

Terms

:- C.O.D Days

Remarks

Main Office: Mova Building No. 22, Jalan Kilang Singapore 159419 Tel : (65) 6476 3333 Fax : (65) 6271 5891

www.move.com.sc Workshop Dept Block 1008

Bukit Merah Lano 3 #01-04/06/08/94 Singapore 159722

Tel: (65) 6272 3892 Fax: (65) 6270 8314

Co. Reg. 1989040330 G\$T Reg. M2-0088864-4

No.	Description	Qt	y	U.Price	Amounts S\$
	LIST TOTAL SS 25% DISCOUNT SS Supplementary LH rew door rubber \$215				17,414.00
	25% DISCOUNT SS Supplements				-4,353,50
	·				13,060.50
	SPECIAL NET ITEMS :			_	
1.	REAR WINDSCREEN SEALANT	1	PC	40.00	10.00
2.	FRONT NUMBER PLATE	1	PC	50.00	be 50.00
3.	REAR NUMBER PLATE	1	PC	50.00	b+ 50.00
4.	RADIATOR COOLANT	1	PĊ	30.00	Nee- 30.00
5 .	REAR CAMERA	1	PC	200,00	215/200,00
	SPECIAL NET TOTAL S\$				370.00

LABOUR:

TO INSPECT FRONT AND REAR LIGHTING WATER AND **LEAKAGE TEST**

TO REMOVE AND INSTALL REAR WINDSCREEN

TO REMOVE AND INSTALL REAR GARNISHES, CARPET, ROOF LINING AND ETC IN ORDER TO CUT OFF PANEL

TO REMOVE AND INSTALL REAR UNDERCARRIAGE IN ORDER TO CUT OFF FLOOR PARTS AND STRAIGHTEN REAR CHASSIS MEMBER

TO REMOVE AND STRAIGHTEN REAR EXHAUST

TO REMOVE AND INSTALL FUEL TANK

TO SET VEHICLE ON CHASSIS BENCH IN ORDER TO CUT OFF DAMAGED PANEL AND STRAIGHTEN

TO REMOVE AND INSTALL REAR PARKING SENSOR AND REPROGRAM AFTER REPLACE

TO REMOVE AND INSTALL A/C CONDENSER AND RADIATOR IN ORDER TO STRAIGHTEN FRONT SUPPORT PANEL

TO CUT OFF END PANEL, FLOOR PANEL, L/R REAR FENDER, CHASSISMEMBER REAR RH, STRAIGHTEN FRONT SUPPORT PANEL, ETC AND RENEW DAMAGED **PARTS**

TO APPLY BODY JOINT SEALANT ON CUTTING AREA

TO APPLY RUST PROOF ON AFFECTED AREA

60.00 -120.00

40.

lov 200.00

12007 250.00

> CO. 80.00 50

80.00

or photo. 300.00 <

> 30. 150.00

124X 140.00

2000

2,600.00

80.00

200.00





Estimate

25/07/2017

MSIG INSURANCE (S) PTE LTD (SGX CENTRE) 16, RAFFLES QUAY #24-01 HONG LEONG BUILDING SINGAPORE 048581.

Attention:- XA013

Page #

128878

Veh#

\$KQ4821B

Veh Model :- TOYOTA VIOS 1.5G

Estimate# :-

CK416139

Claim#

ACC. Date ;- 22/07/17

Terms

C.O.D Days

Remarks

Main Office: Mova Building

No. 22, Jalan Kilang Singapore 15941 Tol: (65) 6476 3333 Fax: (65) 6271 5891 www.mova.com.sc

Workshop Dept: **Block 1008** Bukit Merah Lane 3 #01-04/06/08/94 Singapore 159722

Tel: (65) 6272 3892 Fex: (65) 6270 8314

Co. Rog. 198904033C GST Reg. M2-0088864-2

No. Description Qty

U.Price Amounts \$\$

TO SPRAY PAINT ON REPLACED, REPAIRED AREA

TOWING CHARGE TO FAN YOONG

LABOUR TOTAL SS

/600 1.800.00

55,00

6,115.00

E. & O.E

NON-TAX AMOUNT S

AMOUNT S\$

19,545.50

GST @ 7 %

1,368,19

AMOUNT DUE S\$

20,913.69

19706.75

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged partis, during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "W-thout Prejudice" basis

Customer's Signature/Co. Stamp MOVA AUTOMOTIVE PTE LTD

- No illegal modification(s) is allowed.
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

31/7/17 @ 1525 Repurray before paint

gure (Kleanto wom.





Main Offic∈

Main Office Move Buildin No. 22, Jalan Kilant Singapora 15941 Tel: (65) 6476 333 Fax: (65) 6271 589 www.mova.com.s

Workshop Depi Block 100(Bukit Merah Lane (#01-04/05/05/ Singapore 15972

Tel: (65) 6272 389 Fax: (65) 6270 831

Co. Reg. 198904033i GST Reg. M2-0088864-

Estimate

25/07/2017

MSIG INSURANCE (S) PTE LTD (SGX CENTRE) 16, RAFFLES QUAY #24-01 HONG LEONG BUILDING

SINGAPORE 048581.

Attention: XA013

Page #

Veh# :- SKQ4821B

Veh Model :- TOYOTA VIOS 1.5G

Estimate# :- CK416139

Claim #

ACC. Date :- 22/07/17

:- C.O.D Days Terms

Remarks

٥.	Description	Qty	U.Price Amounts S\$
******	LIST ITEMS :		<i>J</i>
1.	FRONT BUMPER	1 PC	480.00 Le 480.00
2.	FRONT BUMPER SIDE RETAINER	2 PC	67,00 Let 134.00
3.	FRONT BUMPER LOWER GRILLE	1 PC	280.00 M - 280.00
4.	FRONT BUMPER TOWING COVER	1 PC	55,00 mg/ 55,00
5.	FRONT BUMPER CHROME MOULDING	2 PC	58.00 int 136.00
6.	FRONT BUMPER TOP CHROME MOULDING	1 PC	395.00 / 📈 / 395.00
7,	FRONT BUMPER REINFORCEMENT	1 PC	390.00 7 390.00
8.	FRONT BUMPER LOWER GRILLE MOULDING	1 PC	150.00
9.		20 PC	5.00 104/ 100.00
10.	HEADLAMP - CICLO Z	2 PC	890.00 w 1,780.00
11.	HEADLAMP BRACKET - MERICO	2 PC	67.00 du 5. 134.00
12.	BONNET	1 PC	895,00 H 895.00
13.	INSULATOR CLIPS	10 PC	5.00 14 - 50.00
14.	SUPPORT TOP COVER - COVER	1 PC	250.00 20 250.00
15.	FRONT BRACE PANEL Pant	1 PC	146.00 Bt 146.00
16.	FRONT BUMPER LOGO	1 PC	85.00 Aug 85.00
17.	REAR BUMPER	1 PC	510.00 de - 510.00
18.	REAR BUMPER SIDE RETAINER	2 PC	100.00 🖊 عد 50.00
19.	REAR BUMPER INNER RETAINER	2 PC	48.00 🛷 🥕 96.00
20.	REAR BUMPER REFLECTOR LAMP	2 PC	190,00 m/3 380,00
21.	REAR PARKING SENSOR ASSY	1 PC	350.00 mis 350.00
22.	REAR REINFORCEMENT	1 PC	350.00 bt 350.00 2 5
23.	RER BUMPER CLIPS	20 PC	5.00 by: / 100.00
24.	BOOT LID	1 PC	1,663,00 bl / 1,663.00
25.	BOOT LID LOCK Por /	1 PC	95.00 bl 95.00
26.	BOOT LID HINGE	2 PC	60.00 TH 120.00
27.	BOOT LID GARNISH BOOT LID NUMBER PLATE LAMP — OROCC	1 PC	165.00 cm 165.00
28.	BOOT LID NUMBER PLATE LAMP ——CICLO	2 PC	95.00 0 5 190.00
29.	BOOT LID LOGO	1 PC	85.00 85.00
30.	BOOT LID (VIOS) EMBLEM	1 PC	50.00 50.00
31.	BOOT LID (G) EMBLEM	1 PC	55.00 55.00
32.	BOOT LID INNER TRIM	1 PC	375.00 de 375.00
33.	TAILLAMP	2 PC	248.00 00 498.00
34.	TAILLAMP PANEL	2 PC	160.00 bt 320.00
35.	TAILLAMP CLIPS	4 PC	15.00 me 60.00
36.	TAILLAMP GASKET	2 PC	30,00 NO 60,00
37.	REAR FENDER : H-bt/RH-RY	2 PC	997.00 4,994.00
-38		2PC	110:00 7 220:00- x 1
39.	REAR FENDER INNER SHIELD	2 PC	60.00 new 120.00
40,	INNER TRIM CLIPS	20 PC	100.00 رجابہ 5.00
41.	END PANEL GARNISH	1 PC	235.00 bt 235.00
42.	END PANEL GARNISH END PANEL ASSY SPARE TYRE BOARD	1 PC	695.00 de 🗲 — 695.00
43.	SPARE TYRE BOARD	1 PC	230.00 de - 230.00
44.	SPARE TYRE LH SPONGE	1 PC	210.00 4 210.00
45.	SPARE TYRE RH SPONGE	1 PC	210.00 1 210.00
46.	FLOOR PANEL ASSY PARTY	1 PO	690.00 690.00
47.	REAR TRUCK LID WEATHERSTRIP	1 PC	190.00 tuil 190.00
48.	REAR WINDSCREEN MOULDING	1 PC	100.00 ماوس 100.00
49.	REAR TRUCK LID WEATHERSTRIP REAR WINDSCREEN MOULDING REAR FENDER INNER TRIM REAR EXHAUST-HEAT-SHIELD	2 PC	395.00 790.00
50 -	REAR EXHAUST-HEAT-SHIELD	1P6	100.00 7 100.00 X
	REAR CHASSISMEMBER RH	1 PG	450:00 -£∞ -450.00 x •





Estimate

25/07/2017

MSIG INSURANCE (S) PTE LTD (SGX CENTRE) 16, RAFFLES QUAY #24-01 HONG LEONG BUILDING

SINGAPORE 048581.

Page #

128878

Veh#

SKQ4821B

Veh Model :-

Supplementary Parta. Over rubber = # 215.00 (New)

TOYOTA VIOS 1.5G

Estimate# :-

CK416139

Claim #

22/07/17 ACC, Date :-

Terms

C.O.D Days

Remarks :-

Main Office Mova Building No. 22, Jalan Kilang Singapore 159419 Tel: (65) 6476 3333 Fax: (65) 6271 5891 www.move.com.sc

> Workshop Dept Block 1008 Bukit Marah Lang 3 #01-04/06/08/94 Singapore 159722

Tel: (65) 6272 3892 Fax: (65) 6270 8314

Co. Reg. 1989040336 GST Reg. M2-0088864-7

Attention :- XA013

No. Description

LIST TOTAL S\$

25% DISCOUNT SS

SPECIAL NET ITEMS: REAR WINDSCREEN SEALANT

FRONT NUMBER PLATE 2.

REAR NUMBER PLATE 3.

RADIATOR COOLANT 4. REAR CAMERA -

SPECIAL NET TOTAL S\$

LABOUR :

TO INSPECT FRONT AND REAR LIGHTING WATER AND LEAKAGE TEST

TO REMOVE AND INSTALL REAR WINDSCREEN

TO REMOVE AND INSTALL REAR GARNISHES, CARPET, ROOF LINING AND ETC IN ORDER TO CUT OFF PANEL

TO REMOVE AND INSTALL REAR UNDERCARRIAGE IN ORDER TO CUT OFF FLOOR PARTS AND STRAIGHTEN REAR CHASSIS MEMBER

TO REMOVE AND STRAIGHTEN REAR EXHAUST

TO REMOVE AND INSTALL FUEL TANK

TO SET VEHICLE ON CHASSIS BENCH IN ORDER TO CUT OFF DAMAGED PANEL AND STRAIGHTEN

TO REMOVE AND INSTALL REAR PARKING SENSOR AND REPROGRAM AFTER REPLACE

TO REMOVE AND INSTALL A/C CONDENSER AND RADIATOR IN ORDER TO STRAIGHTEN FRONT SUPPORT PANEL

TO CUT OFF END PANEL, FLOOR PANEL, L/R REAR FENDER, CHASSISMEMBER REAR RH, STRAIGHTEN FRONT SUPPORT PANEL, ETC AND RENEW DAMAGED **PARTS**

TO APPLY BODY JOINT SEALANT ON CUTTING AREA

TO APPLY RUST PROOF ON AFFECTED AREA

Qty.

U.Price Amounts S\$

17.414.00

-4,353.50

13,060.50

10.00 ALI 1 PC 40.00 16- 50.0045 PC 50.00 1 50.00 44 5 1 PC 50.00 30.00 100 30.00 PC

200,00 dis/200.00 PC

40. 60.00

370.00

120.00

100 200.00

1200 XX 250,00

80.00

50 80.00 o plusto.

300.00 🗸

32, 150,00

100 120 X

140.00

2000 2,600.00

80,00

/ 00 200,00





Estimate

25/07/2017

MSIG INSURANCE (S) PTE LTD (SGX CENTRE) 16, RAFFLES QUAY #24-01 HONG LEONG BUILDING SINGAPORE 048581.

Attention :- XA013

Page # :- 1 128878

Veh # :- SKQ4821B

Veh Model :- TOYOTA VIOS 1.5G

Estimate# :- CK416139

Claim # :

ACC. Date ;- 22/07/17

Terms :- C.O.D Days

Remarks :-

Main Office: Mova Building No. 22, Jeten Kileng Singapore 159415 Tol: (65) 6476 3333 Fax: (65) 6271 5891 www.mova.com.sg

> Workshop Dept: Block 1008 Bukit Merah Lane 3 #01-04/08/08/94 Singapore 159722

Tel: (65) 6272 3892 Fax: (65) 6270 8374 Co. Reg. 1989040336

Co. Rog. 198904033© GST Reg. M2-0088864-2

No.	Description	Qty	U,Price Amounts S\$
	TO SPRAY PAINT ON REPLACED, REPAIRED AREA		1600 1,800,00
	TOWING CHARGE TO FAN YOONG		55,00
	LABOUR TOTAL SS		6,115.00
			LC-4700 45

E. & O.E

NON-TAX AMOUNT S
AMOUNT S\$
GST @ 7 %

19,545.50 1,368.19

4460

AMOUNT DUE SS

20,913.69

Customer's Signature/Co. Stamp MOVA AUTOMOTIVE PTE LTD

15072 P-14,957 15072 P-15,172 11304 P-11,379 360 S/N-360.00 4460 PC-1,700:00 4460 11,124 \$\frac{1}{4}\left[6,439]

Temple 97495749

WP

31/7/17 @ 1525

Recovery before paint
15 days.

sur @ Mando wm.

Merimen e-Claims Page 1 of 1

...CLAIM SUBFOLDER...(Pending for Survey Report)

LAIM SUBFOLDER TRACKING								
Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status		
24 Jul 2017		28 Jul 2017 15:57	1-4,	S\$16,124.00 View Rpt		Pending for Survey Report Cancel Case		
V	otified	otified Est Submitted	otified Est Submitted Adj Assigned 28 Jul 2017	otified	otified Est Submitted Adj Assigned Adj Rpt Adj Submitted 4 Jul 2017 28 Jul 2017 15:57 \$\$16,124.00 \$\$16,124.00 In Folit Estimates View Rpt View Rpt	otified Est Submitted Adj Assigned Adj Rpt Adj Submitted Ins Auth'ed 4 Jul 2017 28 Jul 2017 15:57 \$\$16,124.00 \$\$16,124.00 View Rpt		

Main	Reference	Claim Details	Documents	Show All
CLAIM SUBFOLDER DETA			[Created by ins	urer]
Insured:	LEO VALENTINE @LI HAN BIN, leovalentine2422@gmail.com	ID: S8124764A, Tel: +658	2280742, Email:	
Main Claimant:	LEE CHEY, ID: S0226433A			
Vehicle Reg. No.:	SKQ4821B	Date of Loss:	22/07/2017 15:00) - :59
Claim Type:	TP / 524302	Policy/Cover Note No.:	A28978143TMP (T Coverage: 21/06/	
Vehicle Reg. No. (Insured):	SLC9492X	Policy No. (Claimant):		
		Excess:		
Repairer:	Mova Automotive Pte Ltd (HQ) B Tel:	lock 1008 Bukit Merah Lane 3	#01-04/06/08/94, 1597	22 Bukit Merah -
Handling Insurer:	MSIG Insurance (Singapore) Pte 6594 2541]	. Ltd. (HQ) - Tel: +65 6827	7888 [Handled by Ire	ne Tan Gek Ing -
Adjuster:	LKK Auto Consultants Pte Ltd (He due 29/07/2017]	Q) - Tel: 6256-3561 [Hand	dled by MOHD RASUL]	. [Imm.Advice
Driver/Custodian (Insured):	LEO VALENTINE @LI HAN BIN (35 /	Male), NRIC: S8124764A,	Tel: +6582280742	,
ASSOCIATED MAIL RECEI	VED		View All	
ASSOCIATED MAIL RECEI				Compose Case Mai
There are no mail for this case	e.			Compose Case Mai
		View All Se	arch Tasks Create New	

Page 1 of 6 Merimen e-Claims

Claim Documents

*SKQ4821B (524302) [SLC9492X] TP **LEE CHEY** Jul 22 2017 3:00PM [LEO VALENTINE @LI HAN BIN] Mova Automotive Pte Ltd

- Op	load Documents U	oload Photos Comp	ose New Letter	<u> </u>		View in Bro	,
Ass	essment Reports				1 pe	erpage 🔻	\square
No	Finalized On	MSIG Insurance (S		. Ltd. (HQ)		Thumbnail	Print
1	26/07/17 10:39	Accident Statemen From:SC - Reg. No: SLC9		O VALENTINE @LI HAN BIN	0	Load HTM	
Pho	tos/Images				3 pe	er page 🔻	7
No	, <u> </u>	LKK Auto Consulta	nts Pte Ltd (H	Q)		Thumbnail	Print
1	26/03/18 14:29	Reinspection Photo)		0	Load JPG	☑
2	26/03/18 14:29	Reinspection Photo)		0	Load JPG	✓
3	26/03/18 14:29	Reinspection Photo	9		0	Load JPG	$\overline{\mathbf{Z}}$
4	26/03/18 14:29	Reinspection Photo	a	****	0	Load JPG	4
 5	26/03/18 14:29	Reinspection Photo)		a	Load JPG	Z
6	26/03/18 14:29	Reinspection Photo)		0	Load JPG	V
7	26/03/18 14:29	Reinspection Photo			0	Load JPG	V
8	26/03/18 14:29	Reinspection Photo	•	- 111	0	Load JPG	V
9	26/03/18 14:29	Reinspection Photo	D		Ð	Load JPG	Ø
10	26/03/18 14:29	Reinspection Photo	D		0	Load JPG	\Box
11	26/03/18 14:29	Reinspection Photo)		0	Load JPG	\square
12	26/03/18 14:29	Reinspection Photo)	,	0	Load JPG	Ø
13	26/03/18 14:29	Reinspection Photo)		0	Load JPG	\square
14	26/03/18 14:29	Reinspection Photo)		0	Load JPG	☑
15	26/03/18 14:29	Reinspection Photo	0		0	Load JPG	V
16	26/03/18 14:29	Reinspection Photo	3		0	Load JPG	Y
17	26/03/18 14:29	Reinspection Photo	D		0	Load JPG	\mathbf{Z}
18	26/03/18 14:29	Reinspection Photo	D		0	Load JPG	Z
19	26/03/18 14:29	Reinspection Photo	Ò		0	Load JPG	☑
20	26/03/18 14:29	Reinspection Photo	D		0	Load JPG	☑
21	26/03/18 14:29	Reinspection Photo	0	1000000	0	Load JPG	\Box
22	26/03/18 14:29	Reinspection Photo	9		0	Load JPG	Z
23	26/03/18 14:29	Reinspection Photo	0		6	Load JPG	4
24	26/03/18 14:29	Reinspection Photo	0		0	Load JPG	$\overline{\mathbf{A}}$
25	26/03/18 14:29	Reinspection Photo	0		6	Load JPG	\mathbf{A}
26	26/03/18 14:29	Reinspection Photo	0		O	Load JPG	\square
27	26/03/18 14:29	Reinspection Photo	9		0	Load JPG	V
28	26/03/18 14:29	Reinspection Photo	3		Ō	Load JPG	3
29	26/03/18 14:29	Reinspection Photo	0		0	Load JPG	4
30	26/03/18 14:29	Reinspection Photo	D		0	Load JPG	Z
31	26/03/18 14:29	Reinspection Photo	n		6	Load JPG	S

34	26/03/18 14:29				☑
34		Reinspection Photo	0	Load JPG	2
	26/03/18 14:29	Reinspection Photo	0	Load JPG	<u></u>
,	26/03/18 14:29	Reinspection Photo	0	Load JPG	V
36	26/03/18 14:29	Reinspection Photo	0	Load JPG	Ø
37	26/03/18 14:29	Reinspection Photo	ō	Load JPG	Z
 	26/03/18 14:29	Reinspection Photo	Ö	Load JPG	2
	26/03/18 14:29	Reinspection Photo	ŏ	Load JPG	\square
 	26/03/18 14:29	Reinspection Photo	0	Load JPG	₩.
	26/03/18 14:29	Reinspection Photo	0	Load JPG	
	26/03/18 14:29	Reinspection Photo	0	Load JPG	V
	26/03/18 14:29	Reinspection Photo	0	Load JPG	3
43			0	Load JPG	\square
 	26/03/18 14:29	Reinspection Photo	0		Z
45	26/03/18 14:29	Reinspection Photo	1=1	Load JPG	
-	26/03/18 14:29	Reinspection Photo	0	Load JPG	2
	26/03/18 14:29	Reinspection Photo	0	Load JPG	Z
	26/03/18 14:29	Reinspection Photo	0	Load JPG	Z
	26/03/18 14:29	Reinspection Photo	0	Load JPG	Z
	26/03/18 14:29	Reinspection Photo	0	Load JPG	V
51	26/03/18 14:29	Reinspection Photo	0	Load JPG	2
	26/03/18 14:29	Reinspection Photo	0	Load JPG	<u> </u>
53	26/03/18 14:29	Reinspection Photo	0	Load JPG	<u> </u>
54	26/03/18 14:29	Reinspection Photo	0	Load JPG	\square
55	26/03/18 14:29	Reinspection Photo	0	Load JPG	☑
56	26/03/18 14:29	Reinspection Photo	0	Load JPG	\square
57	26/03/18 14:29	Reinspection Photo	0	Load JPG	☑
58	26/03/18 14:29	Reinspection Photo	0	Load JPG	Z
59	26/03/18 14:29	Reinspection Photo	0	Load JPG	☑
60	26/03/18 14:29	Reinspection Photo	0	Load JPG	2
61	26/03/18 14:29	Reinspection Photo	0	Load JPG	☑
62	26/03/18 14:29	Reinspection Photo	0	Load JPG	\square
63	26/03/18 14:29	Reinspection Photo	0	Load JPG	2
64	26/03/18 14:29	Reinspection Photo	0	Load JPG	\square
65	26/03/18 14:29	Reinspection Photo	0	Load JPG	☑
66	26/03/18 14:29	Reinspection Photo	0	Load JPG	$\overline{\mathbf{Z}}$
67	26/03/18 14:29	Reinspection Photo	0	Load JPG	✓
68	26/03/18 14:29	Reinspection Photo	0	Load JPG	☑
69	26/03/18 14:29	Reinspection Photo	0	Load JPG	V
70	26/03/18 14:29	Reinspection Photo	0	Load JPG	V
71	26/03/18 14:29	Reinspection Photo	0	Load JPG	Ø
72	26/03/18 14:29	Reinspection Photo	0	Load JPG	☑
73	26/03/18 14:29	Reinspection Photo	0	Load JPG	☑
74	26/03/18 14:29	Reinspection Photo	0	Load JPG	☑
75	26/03/18 14:29	Reinspection Photo	0	Load JPG	Ø
76	26/03/18 14:29	Reinspection Photo	0	Load JPG	☑
77	26/03/18 14:29	Reinspection Photo	0	Load JPG	V
78	26/03/18 14:29	Reinspection Photo	0	Load JPG	☑
79	26/03/18 14:29	Reinspection Photo	0	Load JPG	☑
80	26/03/18 14:29	Reinspection Photo	0	Load JPG	\square
81	26/03/18 14:29	Reinspection Photo	0	Load JPG	Ø

82	26/03/18 14:29	Reinspection Photo	0	Load JPG	\mathbf{V}
83	26/03/18 14:29	Reinspection Photo	0	Load JPG	$ \mathbf{Z} $
84	26/03/18 14:29	Reinspection Photo	0	Load JPG	7
85	26/03/18 14:29	Reinspection Photo	0	Load JPG	\Box
86	26/03/18 14:29	Reinspection Photo	0	Load JPG	☑
87	26/03/18 14:29	Reinspection Photo	0	Load JPG	☑
88	26/03/18 14:29	Reinspection Photo	0	Load JPG	✓
89	26/03/18 14:29	Reinspection Photo	0	Load JPG	\Box
90	26/03/18 14:29	Reinspection Photo	0	Load JPG	▼
91	26/03/18 14:29	Reinspection Photo	0	Load JPG	\square
92	26/03/18 14:29	Reinspection Photo	0	Load JPG	☑
93	26/03/18 14:29	Reinspection Photo	0	Load JPG	lacksquare
94	26/03/18 14:29	Reinspection Photo	0	Load JPG	\mathbf{Z}
95	26/03/18 14:29	Reinspection Photo	0	Load JPG	☑
96	26/03/18 14:29	Reinspection Photo	0	Load JPG	\Box
97	26/03/18 14:29	Reinspection Photo	0	Load JPG	\mathbf{Z}
98	26/03/18 14:29	Reinspection Photo	0	Load JPG	\Box
99	26/03/18 14:29	Reinspection Photo	0	Load JPG	Ø
100	26/03/18 14:29	Reinspection Photo	0	Load JPG	$oldsymbol{\square}$
101	26/03/18 14:29	Reinspection Photo	0	Load JPG	\square
102	26/03/18 14:29	Reinspection Photo	0	Load JPG	\square
103	26/03/18 14:29	Reinspection Photo	0	Load JPG	Ø
104	26/03/18 14:29	Reinspection Photo	0	Load JPG	\Box
105	26/03/18 14:29	Reinspection Photo	0	Load JPG	\square
106	26/03/18 14:29	Reinspection Photo	0	Load JPG	\square
107	26/03/18 14:29	Reinspection Photo	0	Load JPG	\square
108	26/03/18 14:29	Reinspection Photo	0	Load JPG	\square
109	26/03/18 14:29	Reinspection Photo	0	Load JPG	\square
110	26/03/18 14:34	General View	0	Load JPG	\square
111	26/03/18 14:34	General View	6	Load JPG	\square
112	26/03/18 14:34	General View	0	Load JPG	\square
113	26/03/18 14:34	General View	0	Load JPG	\square
114	26/03/18 14:34	General View	0	Load JPG	$\overline{\mathbf{Q}}$
115	26/03/18 14:34	General View	0	Load JPG	\square
116	26/03/18 14:34	General View	0	Load JPG	
117	26/03/18 14:34	General View	0	Load JPG	\square
118	26/03/18 14:34	General View	0	Load JPG	☑
119	26/03/18 14:34	General View	0	Load JPG	\square
120	26/03/18 14:34	General View	0	Load JPG	☑
121	26/03/18 14:34	General View	0	Load JPG	\square
122	26/03/18 14:34	General View	0	Load JPG	<u> </u>
123	26/03/18 14:34	General View	0	Load JPG	\square
124	26/03/18 14:34	General View	0	Load JPG	Z
125	26/03/18 14:34	General View	0	Load JPG	Ø
126	26/03/18 14:34	General View	0	Load JPG	<u> </u>
127	26/03/18 14:34	General View	0	Load JPG	
128	26/03/18 14:34	General View	0	Load JPG	
129	26/03/18 14:34	General View	0	Load JPG	V
130	26/03/18 14:34	General View	0	Load JPG	
131	26/03/18 14:34	General View	0	Load JPG	V

132	26/03/18 14:34	General View		Load JPG	☑
-	26/03/18 14:34	General View	0	Load JPG	☑
134	26/03/18 14:34	General View	0	Load JPG	<u>_</u>
135	26/03/18 14:34	General View	0	Load JPG	Z
136	26/03/18 14:34	General View	0	Load JPG	Z
137	26/03/18 14:34	General View	0	Load JPG	Z
138	26/03/18 14:34	General View	0	Load JPG	2
139	26/03/18 14:34	General View	ō	Load JPG	<u></u>
	26/03/18 14:34	General View	Ø	Load JPG	V
141	26/03/18 14:34	General View	0	Load JPG	☑
142	26/03/18 14:34	General View	0	Load JPG	V
143	26/03/18 14:34	General View	Ō	Load JPG	<u> </u>
144	26/03/18 14:34	General View	0	Load JPG	<u></u>
145	26/03/18 14:34	General View	0	Load JPG	\overline{Z}
146	26/03/18 14:34	General View	0	Load JPG	<u></u>
147	26/03/18 14:34	General View	0	Load JPG	\mathbf{Z}
148	26/03/18 14:34	General View	0	Load JPG	<u> </u>
149	26/03/18 14:34	General View	0	Load JPG	Z
\vdash	26/03/18 14:34	General View	0	Load JPG	<u> </u>
151	26/03/18 14:34	General View	0	Load JPG	Z
 	26/03/18 14:34	General View	O	Load JPG	2
153	26/03/18 14:34	General View	ō	Load JPG	Z
-	26/03/18 14:34	General View	Ö	Load JPG	7
<u> </u>	26/03/18 14:34	General View	0	Load JPG	
156	26/03/18 14:34	General View	0	Load JPG	<u> </u>
	26/03/18 14:34	General View	0	Load JPG	Z
-	26/03/18 14:34	General View	0	Load JPG	☑
159	26/03/18 14:34	General View	ō	Load JPG	<u> </u>
160	26/03/18 14:34	General View	0	Load JPG	<u></u>
-	26/03/18 14:34	General View	0	Load JPG	Z
162	26/03/18 14:34	General View	0	Load JPG	Z
	26/03/18 14:34	General View	O	Load JPG	<u>-</u>
<u> </u>	26/03/18 14:34	General View	0	Load JPG	<u></u>
 	26/03/18 14:34	General View	0	Load JPG	<u> </u>
	26/03/18 14:34	General View	O	Load JPG	$\overline{\mathbf{Z}}$
167	26/03/18 14:34	General View	0	Load JPG	<u> </u>
	26/03/18 14:34	General View	O	Load JPG	<u>-</u>
169		General View	0	Load JPG	\sqrt{2}
170	26/03/18 14:34	General View	0	Load JPG	<u> </u>
171	26/03/18 14:34	General View	ō	Load JPG	<u> </u>
-	26/03/18 14:34	General View	0	Load JPG	<u> </u>
	26/03/18 14:34	General View	0	Load JPG	4
	26/03/18 14:34	General View	0	Load JPG	☑
<u> </u>	26/03/18 14:34	General View	0	Load JPG	<u>√</u>
 	26/03/18 14:34	General View	O	Load JPG	<u>-</u>
	26/03/18 14:34	General View	0	Load JPG	<u> </u>
	26/03/18 14:34	General View	0	Load JPG	<u>-</u>
ļ	26/03/18 14:34	General View	0	Load JPG	V
-	26/03/18 14:34	General View	0	Load JPG	Ø
ļ	26/03/18 14:34	General View	0	Load JPG	V
	-1 - 1 - 1 - 1 - 1 - 1				-

Merimen e-Claims Page 5 of 6

182	26/03/18 14:34	General View	Load JPG	☑
183	26/03/18 14:34	General View	Load JPG	Z
184	26/03/18 14:34	General View	Load JPG	4
185	26/03/18 14:34	General View	Load JPG	☑
186	26/03/18 14:34	General View	Load JPG	4
187	26/03/18 14:34	General View		Z
188	26/03/18 14:34	General View		☑
189	26/03/18 14:34	General View		\square
	26/03/18 14:34	General View		☑
191	26/03/18 14:34	General View		Z
192	26/03/18 14:34	General View		<u>-</u>
193	26/03/18 14:34	General View		<u> </u>
194	26/03/18 14:34	General View		Ø
195	26/03/18 14:34	General View		Ø
196	26/03/18 14:34	General View		Z
197	26/03/18 14:34	General View		A
198	26/03/18 14:34	General View		Ø
199	26/03/18 14:34	General View		☑
	26/03/18 14:34	General View		Z
201	26/03/18 14:34	General View		3
	26/03/18 14:34	General View		<u> </u>
203	26/03/18 14:34	General View		☑ ☑
204	26/03/18 14:34	General View		Z
205	26/03/18 14:34	General View		<u> </u>
206	26/03/18 14:34	General View		₩ W
207		General View		☑
}	26/03/18 14:34	General View		$\overline{\mathbf{Z}}$
<u> </u>	26/03/18 14:34	General View		∀
209	26/03/18 14:34	General View		\square
210		General View		₹
211	26/03/18 14:34			☑
212	26/03/18 14:34			V
	26/03/18 14:34			
h	26/03/18 14:34		-	A
215	26/03/18 14:34	General View	Loau JPG) IZI
Doc	umentation	1	per page 🔻	4
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	26/07/17 10:34	Estimate	Load PDF	
2	26/07/17 10:34	PRI	Load PDF	
3	26/07/17 10:35	SKQ4821B GIA Rpt	Load PDF	<u></u>

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pto	Ltd (HQ)			
	^			
	~			

Page 6 of 6

Merimen e-Claims

Show Remarks 1	o: Handling Insurer		
	ate unless you show it to other parties.		

Adjuster Report Page 1 of 5

LKK Auto Consultants Pte Ltd (Co.Reg. No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS/MSG17014611/R1TBE2

Date:

28/03/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No:

A28978143TMP

Claimant Vehicle

SKQ4821B

Insured Vehicle No:

SLC9492X

No: Date of Loss:

22/07/2017

Nature of Claim:

TP

Claim No: 524302

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SKQ4821B

Make & Model:

TOYOTA VIOS, 1.5 G (A)

Engine No:

1NZZ079334

Reg. Date: Colour: 01/12/2014 (Man. Year: 2014)

Chassis No: Odometer: MHFBT9F3X06022322 68873 km

Engine Capacity:

Silver 1497 cc

ne Capacity: 1493

Market Value/New Car Price:

N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Engine Modification:

Yes Footbrake (Serviceable):

Pre-accident Condition:

Yes

Handbrake (Serviceable):

CONDITION OF TYRES

185/60 R15

Rear Tyre Size:

No

185/60 R15

Front Tyre Size: Front Left Side:

Continental 6 mm

Rear Left Side:

Continental 6 mm

Front Right Side:

Continental 6 mm

Rear Right Side:

Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,591.75	11,664.00	1,927.75	14.18
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,115.00	4,460.00	1,655.00	27.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	19,706.75	16,124.00	3,582.75	18.18
+ GST 7.00/7.00% (S\$)	1,379.47	1,128.68	250.79	18.18
Nett Amount (S\$)	21,086.22	17,252.68	3,833.54	18.18

INSPECTION

Date of Assignment:

28/07/2017

Date Inspected:

31/07/2017

Inspected At:

Mova Automotive Pte Ltd (HQ)

15 FAN YONG ROAD SINGAPORE 629792

Estimated Period of Repair:

15.0 days

Adjuster: MOHD RASUL

•

Manager: DENISE TAY KWEE CHENG

Page 2 of 5 Adjuster Report NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded. https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=gen_... 28/3/2018

Page 3 of 5 Adjuster Report

REPAIR DETAILS

Reference

Part Source: MRM-SG

Version: 1.0 (Last Synchronised: 28 Mar 2018)

Parts:

143

TOYOTA VIOS 1.5 G (A) (Catalogue:Merimen Singapore 1.0)

Labour:

Repairer's

(Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKQ4821B)

Validity:

These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.		Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER	Deformed	480.00 FL	*480.00 FL
2	2	*FRONT BUMPER SIDE RETAINER	Necessary	134.00 FL	*134.00 FL
3	1	*FRONT BUMPER LOWER GRILLE	Deformed	280.00 FL	*280.00 FL
4	1	*FRONT BUMPER TOWING COVER	Missing	55.00 FL	*55.00 FL
5	2	*FRONT BUMPER CHROME MOULDING	Cut	136.00 FL	*136.00 FL
6	1	*FRONT BUMPER TOP CHROME MOULDING	Cracked	395.00 FL	*395.00 FL
7	1	*FRONT BUMPER REINFORCEMENT	Bent	390.00 FL	*390.00 FL
8	1	*FRONT BUMPER LOWER GRILLE MOULDING	Cut	150.00 FL	*150.00 FL
9	20	*FRONT BUMPER CLIPS	Necessary	100.00 FL	*100.00 FL
10	2	*HEADLAMP	Cracked	1,780.00 FL	*1,780.00 FL
11	2	*HEADLAMP BRACKET	Distorted	134.00 FL	*134.00 FL
12	1	*BONNET	Bent	895.00 FL	*895.00 FL
13	10	*INSULATOR CLIPS	Necessary	50.00 FL	*50.00 FL
14	1	*SUPPORT TOP COVER	Deformed	250.00 FL	*250.00 FL
15	1	*FRONT BRACE PANEL	Bent	146.00 FL	*146.00 FL
16	1	*FRONT BUMPER LOGO	Necessary	85.00 FL	*85.00 FL
17	1	*REAR BUMPER	Deformed	510.00 FL	*510.00 FL
18	2	*REAR BUMPER SIDE RETAINER	Necessary	100.00 FL	*100.00 FL
19	2	*REAR BUMPER INNER RETAINER	Necessary	96.00 FL	*96.00 FL
20	2	*REAR BUMPER REFLECTOR LAMP	Missing	380.00 FL	*380.00 FL
21	1	*REAR PARKING SENSOR ASSY	Missing	350.00 FL	*250.00 FL
22	1	*REAR REINFORCEMENT	Bent	350.00 FL	*350.00 FL
23	20	*REAR BUMPER CLIPS	Necessary	100.00 FL	*100.00 FL
24	1	*BOOT LID	Bent	1,663.00 FL	*1,663.00 FL
25	1	*BOOT LID LOCK	Bent	95.00 FL	*95.00 FL
26	2	*BOOT LID HINGE	Bent	120.00 FL	*120.00 FL
27	1	*BOOT LID GARNISH	Cracked	165.00 FL	*165.00 FL
28	2	*BOOT LID NUMBER PLATE LAMP	Distorted	190.00 FL	*190.00 FL
29	1	*BOOT LID LOGO	Necessary	85.00 FL	*85.00 FL
30	1	*BOOT LID (VIOS) EMBLEM	Necessary	50.00 FL	*50.00 FL
31	1	*BOOT LID (G) EMBLEM	Deformed	55.00 FL	*55.00 FL
32	1	*BOOT LID INNER TRIM	Deformed	375.00 FL	*375.00 FL
33	2	*TAILLAMP	Cracked	496.00 FL	*496.00 FL
34	2	*TAILLAMP PANEL	Bent	320.00 FL	*320.00 FL
35	4	*TAILLAMP CLIPS	Necessary	60.00 FL	*60.00 FL
36	2	*TAILLAMP GASKET	Necessary	60.00 FL	*60.00 FL
37	1	*REAR FENDER	N/S Bent / O/S Repair	1,994.00 FL	*997.00 FL
38	2	*REAR FENDER AIR VENT	Not Necessary	220.00 FL	*-FL
39	2	*REAR FENDER INNER SHIELD	Necessary	120.00 FL	*120.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	20		*INNER TRIM CLIPS	Deformed	100.00 FL	*100.00 FL
41	1		*END PANEL GARNISH	Bent	235.00 FL	*235.00 FL
42	1		*END PANEL ASSY	Bent	695.00 FL	*695.00 FL
43	1		*SPARE TYRE BOARD	Deformed	230.00 FL	*230.00 FL
44	1		*SPARE TYRE LH SPONGE	Deformed	210.00 FL	*210.00 FL
45	1		*SPARE TYRE RH SPONGE	Deformed	210.00 FL	*210.00 FL
46	1		*FLOOR PANEL ASSY	Repair	690.00 FL	*-FL
47	1		*REAR TRUNK LID WEATHERSTRIP	Twisted	190.00 FL	*190.00 FL
48	1		*REAR WINDSCREEN MOULDING	Deformed	100.00 FL	*100.00 FL
49	2		*REAR FENDER INNER TRIM	Deformed	790.00 FL	*790.00 FL
50	1		*REAR EXHAUST HEAT SHIELD	Not Necessary	100.00 FL	*-FL
51	1		*REAR CHASSISMEMBER RH	Repair	450.00 FL	*- FL
52	1		*LH REAR DOOR RUBBER	Necessary	215.00 FL	*215.00 FL
53	1		*REAR WINDSCREEN SEALANT	Necessary	40.00 FS	*40.00 FS
54	1		*FRONT NUMBER PLATE	Bent	50.00 FS	*45.00 FS
55	1		*REAR NUMBER PLATE	Bent	50.00 FS	*45.00 FS
56	1		*RADIATOR COOLANT	Necessary	30.00 FS	*30.00 FS
57	1		*REAR CAMERA	Distorted	200.00 FS	*200.00 FS
F=Fra	inchise	part. S=SpcN	Nett. L=ListItemDisc.			
				Sub Total (S\$)	*	15,432.00
			- List Item Discount o	n L Items 25.00/25.00% (S\$)	4,407.25	3,768.00
				Total Parts (S\$)	13,591.75	11,664.00
			Report was unsubmitted di	uina thia print out		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

Particulars	Lab.Type	Repairer's	Amount
our Items	***	 	
TO INSPECT FRONT AND REAR LIGHTING WATER AND LEAKAGE TEST	New	60.00	40.00
TO REMOVE AND INSTALL REAR WINDSCREEN	New	120.00	120.00
TO REMOVE AND INSTALL REAR GARNISHES, CARPET, ROOF LINING AND ETC IN ORDER TO CUT OFF PANEL	New	200.00	100.00
TO REMOVE AND INSTALL REAR UNDERCARRIAGE IN ORDER TO CUT OFF FLOOR PARTS AND STRAIGHTEN REAR CHASSIS MEMBER	New	250.00	0.00
TO REMOVE AND STRAIGHTEN REAR EXHAUST	New	80.00	60.00
TO REMOVE AND INSTALL FUEL TANK	New	80.00	50.00
TO SET VEHICLE ON CHASSIS BENCH IN ORDER TO CUT OFF DAMAGED PANEL AND STRAIGHTEN	New	300.00	300.00
TO REMOVE AND INSTALL REAR PARKING SENSOR AND REPROGRAM AFTER REPLACE	New	150.00	30.00
TO REMOVE AND INSTALL A/C CONDENSER AND RADIATOR IN ORDER TO STRAIGHTEN FRONT SUPPORT PANEL	New	140.00	0.00
·		2,600.00	2,000.00
TO APPLY BODY JOINT SEALANT ON CUTTING AREA	New	80.00	60.00
TO APPLY RUST PROOF ON AFFECTED AREA	New	200.00	100.00
TO SPRAY PAINT ON REPLACED, REPAIRED AREA	New	1,800.00	1,600.00
TOWING CHARGE TO FAN YOONG	New	55.00	0.00
Gross Labou	r Cost (S\$)	6,115.00	4,460.00
	TO INSPECT FRONT AND REAR LIGHTING WATER AND LEAKAGE TEST TO REMOVE AND INSTALL REAR WINDSCREEN TO REMOVE AND INSTALL REAR GARNISHES, CARPET, ROOF LINING AND ETC IN ORDER TO CUT OFF PANEL TO REMOVE AND INSTALL REAR UNDERCARRIAGE IN ORDER TO CUT OFF FLOOR PARTS AND STRAIGHTEN REAR CHASSIS MEMBER TO REMOVE AND STRAIGHTEN REAR EXHAUST TO REMOVE AND INSTALL FUEL TANK TO SET VEHICLE ON CHASSIS BENCH IN ORDER TO CUT OFF DAMAGED PANEL AND STRAIGHTEN TO REMOVE AND INSTALL REAR PARKING SENSOR AND REPROGRAM AFTER REPLACE TO REMOVE AND INSTALL A/C CONDENSER AND RADIATOR IN ORDER TO STRAIGHTEN FRONT SUPPORT PANEL TO CUT OFF END PANEL, FLOOR PANEL, L/R REAR FENDER CHASSISMEMBER REAR RH, STRAIGHTEN FRONT SUPPORT PANEL, ETC AND RENEW DAMAGED PARTS TO APPLY BODY JOINT SEALANT ON CUTTING AREA TO APPLY RUST PROOF ON AFFECTED AREA TO SPRAY PAINT ON REPLACED, REPAIRED AREA TO WING CHARGE TO FAN YOONG	TO INSPECT FRONT AND REAR LIGHTING WATER AND NEW LEAKAGE TEST TO REMOVE AND INSTALL REAR WINDSCREEN NEW TO REMOVE AND INSTALL REAR GARNISHES, CARPET, NEW ROOF LINING AND ETC IN ORDER TO CUT OFF PANEL TO REMOVE AND INSTALL REAR UNDERCARRIAGE IN NEW ORDER TO CUT OFF FLOOR PARTS AND STRAIGHTEN REAR CHASSIS MEMBER TO REMOVE AND STRAIGHTEN REAR EXHAUST NEW TO REMOVE AND INSTALL FUEL TANK NEW OFF DAMAGED PANEL AND STRAIGHTEN TO REMOVE AND INSTALL REAR PARKING SENSOR AND NEW REPROGRAM AFTER REPLACE TO REMOVE AND INSTALL A/C CONDENSER AND RADIATOR NEW IN ORDER TO STRAIGHTEN FRONT SUPPORT PANEL TO CUT OFF END PANEL, FLOOR PANEL, L/R REAR FENDER, NEW CHASSISMEMBER REAR RH, STRAIGHTEN FRONT SUPPORT PANEL, ETC AND RENEW DAMAGED PARTS TO APPLY BODY JOINT SEALANT ON CUTTING AREA NEW TO APPLY RUST PROOF ON AFFECTED AREA NEW TO SPRAY PAINT ON REPLACED, REPAIRED AREA	TO INSPECT FRONT AND REAR LIGHTING WATER AND LEAKAGE TEST TO REMOVE AND INSTALL REAR WINDSCREEN TO REMOVE AND INSTALL REAR GARNISHES, CARPET, ROOF LINING AND ETC IN ORDER TO CUT OFF PANEL TO REMOVE AND INSTALL REAR UNDERCARRIAGE IN ORDER TO CUT OFF FLOOR PARTS AND STRAIGHTEN REAR CHASSIS MEMBER TO REMOVE AND STRAIGHTEN REAR EXHAUST TO REMOVE AND INSTALL FUEL TANK TO REMOVE AND INSTALL FUEL TANK New 80.00 TO SET VEHICLE ON CHASSIS BENCH IN ORDER TO CUT OFF DAMAGED PANEL AND STRAIGHTEN TO REMOVE AND INSTALL REAR PARKING SENSOR AND NEW 150.00 REPROGRAM AFTER REPLACE TO REMOVE AND INSTALL A/C CONDENSER AND RADIATOR IN ORDER TO STRAIGHTEN FRONT SUPPORT PANEL TO CUT OFF END PANEL, FLOOR PANEL, L/R REAR FENDER, CHASSISMEMBER REAR RH, STRAIGHTEN FRONT SUPPORT PANEL, ETC AND RENEW DAMAGED PARTS TO APPLY BODY JOINT SEALANT ON CUTTING AREA NEW 2,600.00 TO SPRAY PAINT ON REPLACED, REPAIRED AREA NEW 1,800.00 TO SPRAY PAINT ON REPLACED, REPAIRED AREA NEW 55.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >