

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III17014736/UGA3Q2

Date: 07/07/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : GZ7619A	Insured Vehicle No :	SH9092H
Date of Loss: 27/06/2017	Nature of Claim: TP	Claim No: MCT17060953

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GZ7619A		
Make & Model:	NISSAN LAFESTA, 2.0 (A)	Engine No:	4D56LC3461
Reg. Date:	29/08/2006 (Man. Year: 2006)	Chassis No:	JMAJNP15V6A001526
Colour:	White	Odometer:	292258 km
Engine Capacity:	2477 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185 R14	Rear Tyre Size:	185 R14
Front Left Side:	Linglong 6 mm	Rear Left Side:	Linglong 6 mm
Front Right Side:	Linglong 6 mm	Rear Right Side:	Linglong 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,646.00	0.00	1,646.00	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,850.00	450.00	1,400.00	75.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$)	3,496.00	450.00	3,046.00	87.13
+ Loss of Use (3.0 x S\$60.00/day) (\$)		180.00		
		(S\$)	630.00	
Liable Amount (50.00%) (\$)		315.00		
+ Doc/Search Fee (\$)		5.35		
Nett Liability (\$)		320.35		
Global Sum Settlement (\$)		320.00		

INSPECTION

Date of Assignment: 31/07/2017

Date Inspected: 31/07/2017 Inspected At:

LIU'S BROTHER AUTO
ENGINEERING WORKSHOP
1 KAKI BUKIT AVENUE 6 #01-01
AUTOBAY @ KAKI BUKIT
SINGAPORE 417883

Estimated Period of Repair: 2.0 days

Adjuster: MARCUS CHUA**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 07 Nov 2017)
Parts:	M1-MPV	NISSAN LAFESTA 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GZ7619A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER (DENTED)	Not Consistent With The Impact	453.00 F	*- FL
2	1		*REAR BUMPER SIDE LH	Repair	235.00 F	*- FL
3	1		*REAR BUMPER SIDE BRACKET	Not Necessary	196.00 F	*- FL
4	2		*REAR BUMPER REFLECTOR	Not Necessary	292.00 F	*- FL
5	1		*REAR TAIL LAMP LH	Not Necessary	220.00 FS	*- FS
6	1		*REAR CORPORATEADVERTISEMENT STICKER	Not Necessary	250.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	1,646.00	0.00
- List Item Discount on L Items 0.00/10.00% (S\$)	0.00	0.00
Total Parts (S\$)	1,646.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOR FOR PANEL BEATING ,CUT,WELD ,STRAIGHTEN & REPLACING PARTS ETCS	New	1,000.00	250.00
2	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED AREAS	New	800.00	200.00
3	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION	New	50.00	0.00
Gross Labour Cost (\$\$)			1,850.00	450.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >