

ASS. REC. BY:

REF:

CS/FCL17015688/Altbn2

Special Instruction:

Surveyor

ASSIGNMENT (Office)

From (Person):

WS Lurene Jew

of

FCL

Date/Time:

12082017 11:41am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKV 790G

Insured:

CHA 8519T

at Workshop m/s

Wearings

Tel:

81261237

of

249 Alexandra Road

Policy No:

Claim No:

D17007783MFSH

Sum Insured:

Excess:

D.O.A.

07082017

Make of Veh:

(Client's Record)

CA / REV / REP. / REV 24 HRS 1wpi

H.O.D. Endorsement:

Date/Time:

14082017 10:42am

Person Contacted:

Paul

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SKV 790G - X

CHA 8519T - CS / FCL16019415 / Kvb2

DUA: 071016

Part by Part \$3471.18 (Red 2823.85144%)

Simzyur

Ram

REF:

14214

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SKV 7906
 at Workshop m/s Wearnes
 of _____
 Insured: TCI MP
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKV 7906 Yr Regn: 2015 / Aug
 Type: C / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Volvo S60 C.C. 1969
 Colour: Red A/C: Insured / Std / NI / NA
 Sp. Reading: 59088 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: 4V1FS46L0G2398035
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 235/45 ZR17
 R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or CONTINENTAL

Front _____ mm Rear _____ mm
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 07/08/17 D.O.I. 07/08/17

Survey held at Wearnes
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
REAR N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 10 JAN 2018

Date/Time, File Pass to?

1) Not Typist

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I: (\$ 3471.18)

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech. Invs (\$)
☐ Weekend (\$)

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

TOTAL

145
50
50
18
263



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI17015688/R1tb

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 14-08-2017



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 8519T	Veh. Inspected	SKV 790G
Policy No.		Coverage (\$)	0.00
Claim No.	D17007783MFSH	Excess (\$)	0.00
Assign From	CWS (LURENE JAW)	Assign Date	12/08/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	07/08/2017	Inspection Date
Survey held at	WEARNES AUTOMOTIVE PTE LTD 249 ALEXANDRA ROAD SINGAPORE 159935	

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C
GST Reg. No. M2-0001676-9

MOTOR SURVEY ASSIGNMENT

Date	11-08-2017	Our Ref No. D17007783MFSH
Accident Date	07-08-2017	Claim Type. Third Party
Insured Vehicle	SHA8519T	Third Party Vehicle. SKV790G
Survey Location	BODY AND PAINT DEPT 249 ALEXANDRA ROAD	
Contact Person.	PAUL ONG	
Contact No.	64304899/ 81261237	Fax No. 0
Survey Type	WITHOUT PREJUDICE: ACCIDENT NOT REPORTED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	WEARNES AUTOMOTIVE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	LURENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/226773)



PRI Documents



Close X

PRI Header Details

Claim No	D17007783MFSH	Policy No	D-15072702MFSH	Claimant S.No & Name	1 & WE LTD
Workshop Name	WEARNES AUTOMOTIVE PTE LTD (Contact Person : PAUL ONG)	Survey Location & Contact Details	BODY AND PAINT DEPT 249 ALEXANDRA ROAD Mobile: 81261237 , Phone: 64304899 , Fax: EmailId: PAUL.ONG@WEARNES.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: ACCIDENT NOT REPORT		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHA8519T	TP Vehicle No	SKV791
PRI Recieved Date	11-08-2017 03:18:51 PM	Surveyor Appointed Date	12-08-2017 11:41:28 AM	Surveyor Accept Date	14-08-

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	14-08-2017	Upload Survey Report *:	
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

Upload Multiple Documents	
File Name	Action

Surveyor Job Remarks

As Auto Consultant, hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

SERVICE ESTIMATE

82120 Signature: 000001 SL: SERVICE SALES - PC
 Ms Suliah Binte Mungin
 Blk 44 Sims Drive
 #03-171

Singapore 380044

Closed by : Paul Ong Qing Yong
 Svc Consultant :
 Remarks : Ms Suliah Binte Mung

GST Reg.No: M28920628X
 Inv.No. . : B&P 0 Page 1
 Inv.date. : 10/08/2017
 WIP No. . : 12792 26094
 Veh.In/Out:
 *Tel.No. . : Mobile: 90915558
 Reg.No. . : SKV790G
 Reg.date . : 28/08/2015
 Mileage .. : 0
 Chassis No: YV1FS40LDG2398035

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
-------	-------------	----------	-------	-------	-----	--------	---

802	TO REPLACE REAR BUMPER, SENSOR, ETC	0	1600.00	0		1,600.00 S 800	
800	TO PUTTY SPRAY PAINT ON REAR BUMPER, ETC	0	1400.00	0		1,400.00 S 700	
280	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	0	450.00	0		450.00 S	
	BUMPER SPOILER REAR	1.0 EA	486.40			486.40 S ? xsm	
	PROTECTING PLATE REA	1.0 EA	178.10			178.10 S see	
	PARK ASSIST REAR SV6	1.0 EA	811.30			811.30 S ? xsm	160.29
	BUMPER INSTALLING MT	1.0 EA	83.40			83.40 S see	75.06

Rasm
 Hp 90010068

3 days

07/11/17

Labour Total	3,450.00	Gross Total.	5,009.20
Parts Total	1,559.20	Net.....	5,009.20
Package Total	0.00	GST @ 7.0%	350.64
		Total.....	5,359.85
		Paid.....	0.00
		Please Pay..	5,359.85

GST: S=StdRated; O=OutOfScope; Z=ZeroRated

6295-03

SERVICE ESTIMATE

0 - F00003 SL: FIRST CAPITAL INSURANCE LTD
 FIRST CAPITAL INSURANCE LTD GST Reg.No:M28920628X
 36 ROBINSON ROAD Inv.No. . : B&P 0 Page 1
 #16-01, CITY HOUSE Inv.date. : 13/11/2017
 SINGAPORE WIP No. . : 26094
 Singapore 068877 Veh.In/Out: 07/11/2017 10/11/2017

Closed by : Paul Ong Qing Yong
 Svc Consultant : ACC
 Remarks : Ms Suliah Binte Mung

*Tel.No. . :
 Reg.No. . : SKV790G
 Reg.date . : 28/08/2015
 Mileage .. : 59,087
 Chassis No: YV1FS40LDG2398035

Op.No	Description	Mech	Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE REAR BUMPER	0		800.00	0		800.00	S
800	TO PUTTY SPRAYPAINT ON	0		700.00	0		700.00	S
REAR BUMPER								
280	TO CHECK WIRING INCLUDE	0		450.00	0		450.00	S
RESETTING OF ALL ELECTRICAL								
MODULES								
	PROTECTING PLATE REA ^①	1.0	EA	178.10	10		160.29	S
	BUMPER INSTALLING MT ^②	1.0	EA	83.40	10		75.06	S
	BUMPER COVER REAR S6	1.0	EA	1428.70	10		1,285.83	Sent <i>PK</i>

Gross Total. 3,471.18

Labour Total 1,950.00
 Parts Total 1,521.18
 Package Total 0.00

Net..... 3,471.18
 GST @ 7.0% 242.98
 Total..... 3,714.16
 Paid..... 0.00
 Please Pay.. 3,714.16

GST: S=StdRated; O=OutOfScope; Z=ZeroRated

sup

SERVICE ESTIMATE

0 - F00003 SL: FIRST CAPITAL INSURANCE LTD
 FIRST CAPITAL INSURANCE LTD GST Reg.No:M28920628X
 36 ROBINSON ROAD Inv.No. . : B&P 0 Page 1
 #16-01, CITY HOUSE Inv.date. : 13/11/2017
 SINGAPORE WIP No. . : 26094
 Singapore 068877 Veh.In/Out: 07/11/2017 10/11/2017
 *Tel.No. . :
 Reg.No. . : SKV790G
 Closed by : Paul Ong Qing Yong Reg.date . : 28/08/2015
 Svc Consultant : ACC Mileage ... : 59,087
 Remarks : Ms Suliah Binte Mung Chassis No: YV1FS40LDG2398035

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
-------	-------------	----------	-------	-------	-----	--------	---

	BUMPER COVER REAR S6	1.0 EA	1428.70	10		1,285.83	S DE
--	----------------------	--------	---------	----	--	----------	------

Labour Total	0.00
Parts Total	1,285.83
Package Total	0.00

Gross Total.	1,285.83
Net.....	1,285.83
GST @ 7.0%	90.01
Total.....	1,375.84
Paid.....	0.00
Please Pay..	1,375.84

GST: S=StdRated; O=OutOfScope; Z=ZeroRated



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI17015688/R1tbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 17-01-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 8519T	Veh. Inspected	SKV 790G	
Policy No.	D-15072702MFSH	Coverage (\$)	0.00	
Claim No.	D17007783MFSH	Excess (\$)	0.00	
Assign From	LURENE	Assign Date	12/08/2017	
2. Vehicle Particulars & Condition				
Make & Model	VOLVO S60	c.c	1969	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	YV1FS40LDG2398035	Colour	RED	
Odometer	59088	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	235/45 ZR17	CONTINENTAL	6 mm	
L/H Front Tyre	235/45 ZR17	CONTINENTAL	6 mm	
R/H Rear Tyre	235/45 ZR17	CONTINENTAL	6 mm	
L/H Rear Tyre	235/45 ZR17	CONTINENTAL	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	07/08/2017	Inspection Date	07/11/2017	
Survey held at	WEARNES AUTOMOTIVE PTE LTD 249 ALEXANDRA ROAD SINGAPORE 159935			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKV 790G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BUMPER SPOILER REAR (SN)	SERVICEABLE	486.40	-
1	PROTECTING PLATE REA (SN)	SCRATCHED	178.10	160.29
1	PARK ASSIST REAR SV6 (SN)	SERVICEABLE	811.30	-
1	BUMPER INSTALLING MT (SN)	NECESSARY	83.40	75.06
1	BUMPER COVER REAR S6 (ADDITIONAL)(SN)	DEFORMED	1,285.83	1,285.83
			2,845.03	1,521.18
LABOUR				
	TO REPLACE REAR BUMPER,SENSOR,ETC.		1,600.00	800.00
	TO PUTTY SPRAY PAINT ON REAR BUMPER,ETC.		1,400.00	700.00
	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES.		450.00	450.00
			3,450.00	1,950.00
GRAND TOTAL			6,295.03	3,471.18
RECOMMENDED COST OF REPAIRS				3,471.18

Report Ref No. CS/FC117015688/R1tbn2

MOHAMMED RASUL BIN MOHD YUNUS
Automotive Assessor

ADRIAN LING WAI PING
B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.