

ASS. REC. BY:

REF: CS / CTL 17016163 / Titled

Special Instruction:

Supplier:

Tashik

ASSIGNMENT (Office)

Mariman

From (Person): Chong Boon Sen of CTIDate/Time: 21082017 @ 17:11

Estimated Cost:

Bill to:

(OD) TE / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: YN 7881H

Insured:

at Workshop m/s Sng Ah Tee Motor & Panel ServiceTel: 6268 6183of Blk 3 Pioneer Road North #01-18Policy No: DMCVSN3036551700Claim No: SNM17D04232 C01

Sum Insured:

Excess: S\$550.00

Make of Veh:

(Client's Record)

D.O.A. 17072017 @ 13:00

CA (REV) REP. / REV 24 HRS

21082017 anytime

H.O.D. Endorsement:

Date/Time: 21082017Person Contacted: Samantha

Vehicle (IN) OUT

Date/Time

Action/Instruction (✓) Estimate

YN 7881H - X23/8/17 @ 4:02pm Report to Boon Sen via Messenger. (unip sum back).25/8/17 @ 15:49 authorize repair at25/8/17 @ 4:06pm inform samantha authorize repair excess \$550/-
not more than \$55k.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD			Ref : CS/CTI17016163/T1tb	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909			Date : 21-08-2017	
			Code : CTI	
1. Policy Particulars :- OWN DAMAGE				
Insured Veh.		Veh. Inspected		YN 7881H
Policy No. DMCVSN3036551700		Coverage (\$)		0.00
Claim No. SNM17D042323C01		Excess (\$)		550.00
Assign From MERIMEN (CHONG BOONN SEN)		Assign Date		21/08/2017
2. Vehicle Particulars & Condition				
Make & Model		c.c		0
Engine No. HIDDEN		Year of Reg.		
Chassis No.		Colour		
Odometer -		Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date 17/08/2017		Inspection Date 22/08/2017		
Survey held at SNG AH TEE MOTOR & PANEL SERVICE PTE LTD BLK 3, PIONEER ROAD NORTH, #01-18 SINGAPORE 628457.				
5a. Remarks				
A) THE MARKET VALUE IS S\$----- (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.				

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	17 Aug 2017 Sendback Est	17 Aug 2017 18:12 S\$59,171.30	21 Aug 2017 17:11 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

Insured:	FELICITY ENGINEERING PTE LTD, Co. Reg. No.: 199701363W		
Vehicle Reg. No.:	YN7881H	Date of Loss:	17/07/2017 13:00 - :59
Claim Type:	OD / SNM17D04232C01	Policy/Cover Note No.:	DMCVSN3036551700 (Comprehensive)
		Excess:	S\$550.00
Repairer:	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer) Blk 3 Pioneer Road North, #01-18, 628457 Pioneer - Tel: 6268 6183		
Handling Insurers:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 30/08/2017]		
Driver/Custodian:	MUTHUSAMY UKKIRAPANDI (33 / Male), NRIC: G6459017R, Tel: +6586864016		
Adj Asg. Remarks:	SURVEY REVERT, AND ECONOMICAL TO REPAIR.		

ASSOCIATED MAIL RECEIVED
[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS
[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Friday, 7 December 2018 1:45 PM
To: 'Sharon Sng'; SUR; Taufikh (LKKAUTO)
Subject: RE: YN7881H - FINALISE (URGENT)

Dear Sharon,

Confirm \$37,200, 24days

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Sharon Sng <sharon@sngahtee.com>
Sent: Tuesday, 4 December 2018 3:02 PM
To: SUR <sur@lkkauto.com>; Taufikh (LKKAUTO) <Taufikh@lkkauto.com>
Subject: FW: YN7881H - FINALISE (URGENT)

2nd REMINDER

From: Sharon Sng <sharon@sngahtee.com>
Sent: Monday, October 29, 2018 4:48 PM
To: 'SUR' <sur@lkkauto.com>
Subject: FW: YN7881H - FINALISE (URGENT)

REMINDER

From: Sharon Sng <sharon@sngahtee.com>
Sent: Tuesday, July 10, 2018 6:05 PM
To: 'Taufikh (LKK Auto)' <taufikh@lkkauto.com>; 'SUR' <sur@lkkauto.com>
Subject: YN7881H - FINALISE (URGENT)

Best Regards

Sharon Sng

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD | BLK 3 PIONEER ROAD NORTH #01-18 SINGAPORE 628457
TEL: 62686183 (4LINES) | FAX: 62681429 | Find us at <http://www.sngahtee.com>



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	18/07/2017 11:51
Date Of Accident	17/07/2017 13:30
Exact Location Of Accident	TANAH MERAH COAST ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	YN7881H
Insured/Policyholder	
Name Of Registered Owner	FELICITY ENGINEERING PTE LTD
Co Reg No	199701363W
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-63857157

Vehicle Particulars

Manufacturer	HINO
Model	XZU710R-HKFMS3-4.0 D (M)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	COMMERCIAL VEHICLE
------------------	--------------------

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMCVSN3036551700
Cover Note Number	

Driver

Name of Driver	MUTHUSAMY UKKIRAPANDI
Passport No/FIN	G6459017R
Date Of Birth	05/05/1984
Occupation	OUTDOOR
Date Of Driving Pass	13/07/2016
Driving Experience	1 YEAR AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-86864016
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address
Postcode
Was driver an employee of the Insured's Company YES
If No, Relationship of the Driver with the Insured
Vehicle Registration Number of Driver's Own Vehicle -
Vehicle -
Insurance Company of Driver's Own Vehicle -
-

General Information of the Accident

Type Of Accident HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Was any body injured in the Accident? YES
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 0

Details of Police Action

Was the accident reported to the police? YES
If Yes, Please state which Police Station
Police Station Name TAMPINES NEIGHBOURHOOD POLICE CENTRE
Police Station Address ROAD: 6 TAMPINES AVE 4 , POSTCODE: 529682 , COUNTRY: SINGAPORE
Police Station Contact TEL NO: 1800-5871999 - FAX NO: 65871699
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

AS PER POLICE REPORT NO: T/20170717/2144

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number XD8845X
Vehicle Make/Model/Colour
Details Of Properties
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

Details of Witness

Name
Phone Number

Email Address

DETAILS OF INJURED PERSON 1

Name

Approximate Age

Injuries Sustain

Injured person in which vehicle? XD8845X

Were seat belts worn?

Was injured conveyed to hospital by ambulance?

Address

Postcode

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of thereport being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA) I understand, acknowledge, agree and consent that :
 (a) My insurer , my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 (ii) investigating the accident and/or my claims;
 (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involvedisclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
 (collectively the "Purposes")
 (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

I AM AWARE THAT MY INSURER MAY HAVE A 14 DAYS TIMEFRAME FOR ME TO SUBMIT AN OWN DAMAGE CLAIM UNDER MY OWN POLICY. I WILL CHECK MY POLICY FOR MORE DETAILS.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



Sketch Plan Pg. 2

Describe Circumstances of the Accident

As per police report No. 7/20170717/2144.

Declaration

We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time

Mukesh Patel

Driver's Signature (If driver is not the policyholder) / Date & Time

- ☐ Claim own policy
- ☒ Claim third party
- ☐ Claim OD / TP at other workshop
- ☐ For record purpose

Policy No.

Insurer

Chinat

Veh. No. YN76514

Witnessed by Reporting Centre Personnel



**SINGAPORE
POLICE FORCE**



T/20170717/2144

1 of 3

Police Station Of Origin:
Tampines N.P.C
6 Tampines Avenue 4 SINGAPORE 529682
Tel No: 1800-5871999

Report No. T/20170717/2144

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 17/07/2017 20:04		Vide Report No.: G/20170717/0063		Station Diary No.: 134
Informant's Particulars				
Name of Informant: MUTHUSAMY UKKIRAPANDI		Address: APT BLK 364 CLEMENTI AVENUE 2 #10-449 CLEMENTI SPRING SINGAPORE 120364		
ID Type / ID No.: FIN NO / G6459017R		Contact No.: Home/Office: Mobile: 86864016		
Nationality: INDIAN		Email:		
Sex: Male	Age: 33	Date of Birth: 05/05/1984	Type of Informant: Driver	
Race: Indian		Language:	Institution / School Name:	
Occupation: PROJECT SUPERVISOR		Driving Licence Information: Class: 2B,3,4 Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 17/07/2017 13:30	Type of Location: Straight Road
Location: Along Road 1 TANAH MERAH COAST ROAD towards Changi Aviation Park				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: No Traffic	
Type of Collision: Moving Vehicle Against - Parked Vehicle			Anyone conveyed by ambulance: No	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
XD8845X	Lorry				Seriously Damaged	2
YN7881H	Lorry				Seriously Damaged	0

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20170717/2144

2 of 3

Police Station Of Origin:
Tampines N.P.C
6 Tampines Avenue 4 SINGAPORE 529682
Tel No: 1800-5871999

Report No. T/20170717/2144

CONTINUATION OF REPORT

Driver			
Name	MUTHUSAMY UKKIRAPANDI	ID No.	G6459017R
Related Vehicle	YN7881H (Lorry)	Contact No.	86864016
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 2B,3,4 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 17/7/17 at around 1330hrs, I parked my vehicle along Tanah Merah Coast Road towards Aviation Park. It was on the bicycle lane. My workers and I were cutting grass at the open field beside the road, when a sudden the mentioned vehicle (XD8845X) came and bang my stationary vehicle from the rear.

Immediately I called for the police and just before the arrival of the ambulance, SCDF and the police the driver called for a friend to pick the female passenger up. I did not managed to get any of their particulars as everything happened fast. He was then later conveyed via the ambulance.

I am lodging this report to seek assistance on an insurance claim for my company (Felicity Engineering Pte Ltd) vehicle. Other than the driver no one else was injured or required any medical attention.



**SINGAPORE
POLICE FORCE**



T/20170717/2144

Police Station Of Origin:
Tampines N.P.C
6 Tampines Avenue 4 SINGAPORE 529682
Tel No: 1800-5871999

3 of 3

Report No. T/20170717/2144

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: G / TAY AI PENG, DIANA	Signature Of Informant: Hussein Rafandi
Signature Of Interpreter: Not applicable	Date/Time: 17/07/2017 20:04
Officer in Charge Of Case: TP / GIT / Sr Staff Sgt MOHAMMAD ABDILLAH BIN PALIL Contact No.: 65476246	Classification Of Case:
Authentication Stamp NP168	

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 1363W

Vehicle Details

Vehicle No.: YN7881H

Vehicle to be
Exported: No

Intended De-
registration Date: 31 Jul 2017

Vehicle Make: HINO

Vehicle Model: HINO XZU710R-HKFMS3

Primary Colour: White

Manufacturing
Year: 2014

Engine No.: N04CUS20488

Chassis No.: JHHUCS3H90K011621

Maximum Power
Output: -

Open Market
Value: \$26,981.00

Original
Registration
Date: 30 Apr 2015

First Registration
Date: 30 Apr 2015

Transfer Count: 0

Actual ARF Paid: \$1,350.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility
Expiry Date: -

PARF Rebate
Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 29 Apr 2025

COE Category: C - Goods Vehicle & Bus

COE
Period(Years): 10

PQP Paid: \$26,449.00

COE Rebate
Amount: \$20,490.00

**Total Rebate
Amount: \$20,490.00**

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Chong Boon Sen

Date: 23 Aug 2017

Preliminary Advice

Vehicle No	: YN7881H	Accident Date	: 17/07/2017
Make	: HINO XZU710R-HKFMS3	Policy No.	: DMCVSN3036551700
Assignment Date	: 21/08/2017	Excess	: S\$550.00
Date of Inspection	: 22/08/2017	Est. Duration of Repair	: 24.00
Inspection At	: SNG AH TEE MOTOR & PANEL SERVICE PTE LTD (PIONEER) BLK 3 PIONEER ROAD NORTH, #01-18 SINGAPORE 628457		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion, o/s body, undercarriage & rooftop and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	59,171.30
Revised Amount	:S\$	38,518.30
Check Items (Estimated)	:S\$	19,643.00
Total	:S\$	58,161.30
 Lump Sum Repair	:S\$	 46,500.00 (Estimate)

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	80,000.00
COE / PARF Rebate	:S\$	20,490.00
Salvage Value	:S\$	
Margin for Repair	:S\$	59,510.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : THE VEHICLE REPAIR ON LUMP SUM BASIS.
WE HAVE NOT AUTHORISE REPAIR.

Text size + -

Enquire PARF/COE Rebate for Registered Vehicle**Vehicle Owner Particulars**

Owner ID Type: Company

Owner ID: 1363W

Vehicle Details

Vehicle No.: YN7881H

Vehicle to be Exported: No

Intended De-registration
Date: 23 Aug 2017

Vehicle Make: HINO

Vehicle Model: HINO XZU710R-HKFMS3

Primary Colour: White

Manufacturing Year: 2014

Engine No.: N04CUS20488

Chassis No.: JHHUCS3H90K011621

Maximum Power
Output: -

Open Market Value: \$26,981.00

Original Registration
Date: 30 Apr 2015

First Registration Date: 30 Apr 2015

Transfer Count: 0

Actual ARF Paid: \$1,350.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry
Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 29 Apr 2025

COE Category: C - Goods Vehicle & Bus

COE Period(Years): 10

PQP Paid: \$26,449.00

COE Rebate Amount: \$20,321.00

Total Rebate Amount: \$20,321.00

The information contained herein is correct as at 23 Aug 2017



Please read through the Privacy Statement, Terms of Use and Disclaimer.

Please do not use the **Back** or **Forward** buttons on your browser as this may alter the results of the transactions.

Best viewed with IE 8.0 SP3 and above, 1024 X 768 resolution

Copyright © 2017 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#) | [Rate this e-Service](#)

Last updated on 20 Aug 2017 at 12:36 AM

SGCARMART
APP DOWNLOAD

All

Car Make or Model

Search

MYCARFORUM
MARKETPLACE

Buy / Sell Parts & Accessories

[click here to visit now!](#)

Username / Email Add

password

[Sign Up New Account](#)
[Forgot Password](#)

Post an Advertisement
 Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

Classic Promo! Best Deal! Fast Selling! Hurry Down Now!



Flexible Loan, Trade In And
 Welcome 100% Deposit Return
 For Unachieved Loan!
 Classic Credit. [Contact](#)



Browse by Category

Sort by Date Posted

20 results/page

2 vehicles

HINO XZ

Advanced Search

Name	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	HINO XZ	Any	Any	Any	Any	Any	Any	Available
	Hino XZU710R	-	N/A	29-Feb-2016	4,009 cc	34,000 km	Truck	Available
Fuel Type: Diesel Almost New Hino XZU710R 10 Feet Euro 5 Truck. Well Maintained By 1 Owner Only. Very Low Mileage. Immaculate Condition. 5 Years Service Warranty By Borneo Motors. Actual 11 Footer, Fast Call Now Before...								SINGLE OWNER
Posted: 15-Jul-2017 Tags: 2016 Hino XZU710R, Hino XZU710R, Hino, XZU710R, Used Hino								Details
	Hino XZU710R	\$49,800	\$10,670 /yr	23-Apr-2012	4,009 cc	-	Truck	Available
Fuel Type: Diesel Stormy Weather Or Recession? No Problem By Investing In This 15 Footer For Transporting Your Workers And With Hood Plus Canvas To Keep Goods Dry. See Is Believing, Call Our Friendly Sales Person Today...								Details
Posted: 19-Jun-2017 Tags: 2012 Hino XZU710R, Hino XZU710R, Hino, XZU710R, Used Hino								

Save this search criteria, to get email alerts whenever a match is found.

For old advertisements, view [Expired ads](#)

20 results/page

sgCarMart is the number one car classified for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to CDE cars & OPC cars. You can also buy from a car auction, look up car items, low mileage cars, car brands, carpark rates & car insurance. Find buy used HINO XZ, HINO XZ Singapore, used HINO XZ Singapore, used HINO XZ, used vehicles Singapore or even buy used HINO XZ Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, massage services, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & CDE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

- Home
- New Car
- Used Car
- Sell Car
- Motoring Directory
- Products Guide
- Article
- Forum
- Tool & Tip

- About Us
- Careers
- Contact Us
- Sitemap

© 2004-2017 sgCarMart. All rights reserved.

- Terms of Service
- Privacy Policy
- Personal Data Protection Statement

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Friday, 25 August, 2017 4:06 PM
To: 'SAMANTHA TAN'; Taufikh (LKKAuto)
Cc: 'Sharon Sng'; 'Darren Sng'
Subject: RE: YN 7881H repair limit

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **YN 7881H (Excess \$550/-). LIMIT AT \$55K LUMP SUM**

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: SAMANTHA TAN [mailto:sam@sngahtee.com]
Sent: Wednesday, 23 August, 2017 9:04 AM
To: Taufikh (LKKAuto) <Taufikh@lkkauto.com>
Cc: 'Sharon Sng' <sharon@sngahtee.com>; 'Darren Sng' <darren@sngahtee.com>; Denise Tay (LKKAuto) <denisetay@lkkauto.com>
Subject: RE: YN 7881H repair limit

Hi Taufikh,

We accept the repair limit \$55K.

Thank you.

Best Regards

Samantha Tan | sam@sngahtee.com

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD | BLK 3 PIONEER ROAD NORTH #01-18 SINGAPORE 628457
TEL: 62686183 (4LINES) | FAX: 62681429 | Find us at <http://www.sngahtee.com>



From: Taufikh (LKK Auto) [mailto:taufikh@lkkauto.com]
Sent: Tuesday, 22 August 2017 7:56 PM
To: 'ADMIN SNGAHTEE' <admin@sngahtee.com>
Cc: 'Sharon Sng' <sharon@sngahtee.com>; 'Darren Sng' <darren@sngahtee.com>; 'Denise Tay (LKKAuto)'

View Received Message

This mail is associated with :

YN7881H (SNM17D04232C01)

OD

Jul 17 2017 1:00PM

[FELICITY ENGINEERING PTE LTD]

Sng Ah Tee Motor & Panel Service Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From China Taiping Insurance (Singapore) Pte. Ltd. (HQ) (CHINA_TAIPING), sent on 25/08/2017 15:49 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$46500.00) - YN7881H - Claim Handler: Chong Boon Sen

Approved:46500.00:LUMP SUM of \$46,500 before Excess

DOCUMENTS SUMMARY

There are no documents.

Sng Ah Tee Motor & Panel Service Pte Ltd (Co.Reg.No:200810440N)

Blk 3 Pioneer Road North, #01-18

Singapore 628457

Tel: 6268 6183 Fax: 6268 1429 Email: sngahtee@singnet.com.sg; darren@sngahtee.com; janice@sngahtee.com

INSURER: China Taiping Insurance (Singapore) Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	DMCVSN3036551700	Date of Loss:	17/07/2017
Vehicle Reg. No.:	YN7881H	Driveable?	
Driver Age/Info:	33 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	YES	Third Party Involved?	YES
Insured/Claimant:	FELICITY ENGINEERING PTE LTD		
Driver:	MUTHUSAMY UKKIRAPANDI		
Make/Model:	HINO XZU710R-HKFMS3, 4.0 D (M)	Vehicle Reg. Date:	30/04/2015
Vehicle Colour:	WHITE		
Engine No:	N04CUS20488	Chassis No:	JHHUCS3H90K011621
Odometer:	5 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	35		
Description of Accident/Loss	AS PER POLICE REPORT NO: T/20170717/2144		
Present Location:	SNG AH TEE MOTOR & PANEL SERVICE PTE LTD (PIONEER)		

Tanfuhi 97495749
 Lumpsum!
 Resurvey after 24 days after paint.
 Ex \$550
 Revert.
 22/8/17. sw@lkhanda.com

COST OF CLAIMS

	Amount
Parts	52,981.30
Miscellaneous Items	0.00
Labour	6,190.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	59,171.30
+ GST 7.00% (\$\$)	4,141.99
Nett Amount (\$\$)	63,313.29

This claim is handled by: JANICE CHANG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

63313.29

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 17 Aug 2017)

Parts: N/A HINO XZU710R-HKFS3 4.0 D (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for YN7881H)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT BUMPER <i>del ✓</i>	0.00	0.00	*950.00 F ✓
2	2		*FRT BUMPER SIDE BRACKET <i>LH-X^{an} RH-bt</i>	0.00	0.00	*560.00 F <i>280</i>
3	1		*FRT FOGLAMP(RH) <i>mis</i>	0.00	0.00	*275.00 F ✓
4	1		*FRT FOGLAMP HOLDER(RH) <i>dis</i>	0.00	0.00	*50.00 F ✓
5	2		*FRT HEADLAMP <i>LH-X^{an} RH-one</i>	0.00	0.00	*2,200.00 F <i>1100</i>
6	1		*FRT GRILLE <i>mis</i>	0.00	0.00	*575.00 F ✓
7	10		*FRT GRILLE CLIPS <i>del</i>	0.00	0.00	*30.00 F ✓
8	1		*FRT GRILLE EMBLEM <i>del</i>	0.00	0.00	*68.00 F ✓
9	1		*FRT CORNER PANEL(RH) <i>mis</i>	0.00	0.00	*550.00 F ✓
10	1		*FRT CORNER PANEL SEAL(RH) <i>del</i>	0.00	0.00	*30.00 F ✓
11	1		*SIDE MIRROR ARM(RH) <i>bt</i>	0.00	0.00	*255.00 F ✓
12	1		*SIDE MIRROR ARM ROUND CAP(RH) <i>mis</i>	0.00	0.00	*12.00 F ✓
13	1		*SIDE MIRROR(RH) <i>one</i>	0.00	0.00	*28.00 F ✓
14	1		*SIDE MIRROR ARM TOP SEAL(RH) <i>mis</i>	0.00	0.00	*25.00 F ✓
15	1		*SIDE MIRROR ARM (LH) <i>bt</i>	0.00	0.00	*265.00 F ✓
16	1		*SIDE MIRROR(LH)(ROUND) <i>mis</i>	0.00	0.00	*15.00 F ✓
17	1		*SIDE MIRROR(LH) <i>del</i>	0.00	0.00	*30.00 F ✓
18	1		*FRT WINDSCREEN WITH MOULDING <i>new</i>	0.00	0.00	*1,350.00 F ✓
19	1		*FRT WINDSCREEN SEALANT <i>del</i>	0	0.00	*40.00 FS ✓
20	1		*ERP BRACKET <i>del</i>	0	0.00	*26.00 FS ✓
21	1		*FRT ROOF TOP LAMP(RH) <i>mis</i>	0.00	0.00	*140.00 F ✓
22	1		*FRT ROOF ANTENNA <i>bt</i>	0.00	0.00	*95.00 F ✓
23	1		*FRT ROOF TOP PANEL SIDE (RH) <i>bt</i>	0.00	0.00	*400.00 F ✓
24	1		*FRT ROOF TOP PANEL AT REAR <i>bt</i>	0.00	0.00	*470.00 F ✓
25	1		*FRT CABIN ROOF LINING <i>del</i>	0.00	0.00	*300.00 F ✓
26	1		*FRT CABIN REAR GLASS MOULDING <i>del</i>	0.00	0.00	*80.00 F ✓
27	1		*FRT CABIN REAR PANEL <i>bt</i>	0.00	0.00	*850.00 F ✓
28	1		*FRT CABIN REAR SUPPORT <i>bt</i>	0.00	0.00	*1,050.00 F ✓
29	2		*FRT CABIN REAR LOCK <i>X^{an}</i>	0.00	0.00	*600.00 F X
30	1		*FRT CABIN REAR LOCK LATCH(LH) <i>X^{an}</i>	0.00	0.00	*105.00 F X
31	2		*FRT CABIN REAR LOCK HOOK <i>X^{an}</i>	0.00	0.00	*110.00 F X
32	2		*FRT CABIN REAR LOCK HOOK PLATE <i>X^{an}</i>	0.00	0.00	*240.00 F X
33	2		*FRT CABIN REAR MOUNTING BUSH <i>X^{an}</i>	0.00	0.00	*160.00 F X
34	1		*FRT WHEEL ARCH PANEL(RH) <i>del</i>	0.00	0.00	*370.00 F ✓
35	1		*FRT WHEEL ARCH PANEL RR RUBBER SEAL(RH) <i>del</i>	0.00	0.00	*40.00 F ✓
36	1		*ROCKER PANEL(RH) <i>bt</i>	0.00	0.00	*355.00 F ✓
37	1		*ROCKER PANEL SCUFF PLATE(RH) <i>del</i>	0.00	0.00	*150.00 F ✓
38	1		*FRT TYRE REAR MUDGUARD(RH) <i>del</i>	0.00	0.00	*200.00 F ✓
39	1		*FRT DOOR(RH) <i>bt</i>	0.00	0.00	*1,100.00 F ✓
40	2		*FRT DOOR HINGE(RH) <i>X^{an}</i>	0.00	0.00	*280.00 F X
41	1		*FRT DOOR CHECKER(RH) <i>X^{an}</i>	0.00	0.00	*85.00 F X
42	1		*FRT DOOR GLASS RUN CHANNEL(RH) <i>mis</i>	0.00	0.00	*150.00 F ✓
43	1		*FRT DOOR GLASS INNER MOULDING <i>del</i>	0.00	0.00	*60.00 F ✓
44	1		*FRT DOOR GLASS OUTER MOULDING <i>del</i>	0.00	0.00	*65.00 F ✓
45	1		*FRT DOOR GLASS REGULATOR <i>bt</i>	0.00	0.00	*200.00 F ✓
46	1		*FRT DOOR GLASS REGULATOR MOTOR <i>X^{an}</i>	0.00	0.00	*245.00 F X
47	1		*FRT DOOR OUTER HANDLE <i>one</i>	0.00	0.00	*60.00 F ✓

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
48	1		*FRT DOOR 616 STICKER <i>del</i>	0.00	0.00	*70.00 F
49	1		*FRT DOOR EURO 5 STICKER <i>del</i>	0.00	0.00	*45.00 F
50	1		*FRT DOOR INNER TRIMBOARD(RH) <i>del</i>	0.00	0.00	*460.00 F
51	1		*FRT DOOR WEATHERSTRIPE(RH) <i>del</i>	0.00	0.00	*165.00 F
52	1		*FRT DOOR LOCK(RH) <i>del</i>	0.00	0.00	*200.00 F
53	1		*FRT DOOR SEAL @ FRT <i>del</i>	0.00	0.00	*60.00 F
54	1		*FRT DOOR LOWER GARNISH(RH) <i>del</i>	0.00	0.00	*100.00 F
55	1		*FRT DOOR LAMP(RH) <i>del</i>	0.00	0.00	*70.00 F
56	1		*FRT STEP GARNISH(RH) <i>del</i>	0.00	0.00	*360.00 F
57	1		*REAR DOOR PILLAR(RH) <i>del</i>	0.00	0.00	*980.00 F
58	1		*DASHBOARD ASSY <i>del</i>	0.00	0.00	*550.00 F
59	1		*DASHBOARD SIDE COVER LOWER(RH) <i>del</i>	0.00	0.00	*170.00 F
60	1		*DASHBOARD SIDE COVER TOP <i>del</i>	0.00	0.00	*300.00 F
61	1		*DASHBOARD GLOVE BOX <i>del</i>	0.00	0.00	*340.00 F
62	1		*DASHBOARD SPEAKER COVER(RH) <i>del</i>	0.00	0.00	*100.00 F
63	1		*DASHBOARD BRAKE TANK OUTER COVER(RH) <i>del</i>	0.00	0.00	*100.00 F
64	1		*DASHBOARD RADIO OUTER TRIM <i>del</i>	0.00	0.00	*250.00 F
65	1		*FRT DOOR PILLAR HANDLE NUT COVER RH <i>del</i>	0.00	0.00	*5.00 F
66	1		*DASHBOARD CUP HOLDER RH <i>del</i>	0.00	0.00	*160.00 F
67	1		*DASHBOARD SPEEDOMETER OUTER TRIM <i>del</i>	0.00	0.00	*168.00 F
68	1		*AIR CON BLOWER COOLING COIL ASSY <i>del</i>	0.00	0.00	*1,650.00 F
69	1		*HEATER COOLING COIL ASSY <i>del</i>	0.00	0.00	*550.00 F
70	1		*AIR INTAKE DUCT <i>del</i>	0.00	0.00	*350.00 F
71	1		*AIR INTAKE HOSE <i>del</i>	0.00	0.00	*100.00 F
72	1		*AIR CLEANER BOX ASSY <i>del</i>	0.00	0.00	*400.00 F
73	1		*AIR CLEANER BOX AIR FLOW HOSE <i>del</i>	0.00	0.00	*120.00 F
74	1		*FRT RIM RH <i>del</i>	0	0.00	*200.00 FS
75	1		*FRT TYRE RH <i>del</i>	0	0.00	*180.00 FS
76	1		*FRT SHOCK ABSORBER RH <i>del</i>	0.00	0.00	*280.00 F
77	1		*FRT KNUCKLE ARM RH <i>del</i>	0.00	0.00	*600.00 F
78	1		*FRT WHEEL HUB RH <i>del</i>	0.00	0.00	*125.00 F
79	1		*FRT WHEEL HUB BEARING RH <i>del</i>	0.00	0.00	*100.00 F
80	1		*FRT AXLE <i>del</i>	0.00	0.00	*2,200.00 F
81	1		*FRT EXHAUST PIPE <i>del</i>	0.00	0.00	*550.00 F
82	1		*ERG COOLER REAR HEAT SHIELD COVER <i>del</i> TYPE: EGR COOLER REAR HEAT SHIELD COVER	0.00	0.00	*195.00 F
83	2		*ENGINE MOUNTING @ FRT <i>del</i>	0.00	0.00	*260.00 F
84	2		*GEAR BOX MOUNTING <i>del</i>	0.00	0.00	*200.00 F
85	1		*REAR NUMBER PLATE <i>del</i>	0	0.00	*15.00 FS
86	2		*REAR NUMBER PLATE LAMP <i>del</i>	0.00	0.00	*80.00 F
87	1		*REAR NUMBER PLATE BRACKET <i>del</i>	0.00	0.00	*85.00 F
88	2		*REAR TAIL LAMP <i>del</i>	0.00	0.00	*320.00 F
89	2		*REAR TAIL LAMP PANEL <i>del</i>	0.00	0.00	*240.00 F
90	1		*REAR BUMPER <i>del</i>	0	0.00	*350.00 FS
91	2		*REAR BUMPER SIDE BRACKET <i>del</i>	0	0.00	*360.00 FS
92	1		*REAR CHASSIS FRAME END CROSSMEMBER <i>del</i>	0	0.00	*180.00 FS
93	1		*REAR SPARE TYRE RIM <i>del</i>	0.00	0.00	*180.00 F
94	1		*REAR SPARE TYRE <i>del</i>	0	0.00	*200.00 FS
95	1		*REAR SPARE TYRE BRACKET <i>del</i>	0.00	0.00	*250.00 F
96	1		*REAR SPARE TYRE SUPPORT PANEL <i>del</i>	0.00	0.00	*480.00 F
97	1		*REAR WOODEN DECK ASSY <i>del</i>	0.00	0.00	*6,500.00 F
98	1		*REAR WOODEN STEP PANEL <i>del</i>	0	0.00	*100.00 FS
99	2		*REAR CHASSIS FRAME TOP BEAM <i>del</i>	0	0.00	*1,600.00 FS
100	11		*REAR CHASSIS FRAME WOODEN CROSSMEMBER BEAM <i>del</i>	0	0.00	*3,080.00 FS
101	6		*REAR CHASSIS FRAME U BOLT SET <i>del</i>	0	0.00	*360.00 FS
102	1		*REAR TAILGATE 60KM/H STICKER <i>del</i>	0	0.00	*10.00 FS
103	1		*REAR TAILGATE PAX STICKER <i>del</i>	0	0.00	*10.00 FS
104	1		*REAR DECK FRT WOODEN RAILING <i>del</i>	0.00	0.00	*350.00 F
105	2		*REAR DECK SIDE WOODEN RAILING LH <i>del</i>	0.00	0.00	*700.00 F
106	2		*REAR DECK SIDE WOODEN RAILING RH <i>del</i>	0.00	0.00	*700.00 F
107	2		*REAR RIM <i>del</i>	0	0.00	*360.00 FS

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
108	2		*REAR TYRE <i>LH-RH packed</i>	0	0.00	*400.00 FS <i>200</i>
109	1		*REAR WHEEL SHAFT(RH) <i>X</i>	0.00	0.00	*850.00 F <i>X</i>
110	2		*REAR WHEEL HUB <i>X</i>	0.00	0.00	*2,100.00 F <i>X</i>
111	2		*REAR WHEEL HUB BEARING <i>Ran</i>	0.00	0.00	*130.00 F <i>X</i>
112	1		*REAR SHOCKABSORBER(RH) <i>X</i>	0	0.00	*270.00 FS <i>X</i>
113	1		*REAR DIFFERENTIAL PROPELLER SHAFT <i>X</i>	0.00	0.00	*1,800.00 F <i>X</i>
114	2		*REAR MUDGUARD <i>de</i>	0.00	0.00	*700.00 F <i>X</i>
115	2		*REAR MUDGUARD LOWER MUD FLAP <i>mis</i>	0.00	0.00	*60.00 F <i>X</i>

F=Franchise part. S=SpcNett.

Sub Total (S\$)	50,827.00
+ Margin on L,N Items 5.00% (S\$)	2,154.30
Total Parts (S\$)	52,981.30

Report was unsubmitted during this print-out.
Generated using **Merimen e-Claims IEAS**

Estimates on Miscellaneous Items

* There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO LIFT UP REAR DECK	New 300	400.00 ✓
2	TO KNOCK FRT PANEL,FRT DOOR PILLAR(RH),ROOF TOP PANEL,WELD,REMOVE & FIX ABOVE PARTS	New 1200	1,500.00 ✓
3	TO SPRAY PAINTING ON FRT BUMPER,FRT DOOR PILLAR(RH),FRT DOOR(RH),ROOF TOP PANEL,FRT CABIN REAR PANEL,FRT WHEEL ARCH PANEL(RH),ROCKER PANEL(RH),REAR BUMPER,REAR CHASSIS & AFFECTED AREA	New 1500	1,800.00 ✓
4	TO KNOCK,WELD,JACK,STRAIGHTEN CHASSIS FRAME	New 800	1,300.00 ✓
5	TO CHECK WIRING,FOCUS HEADLAMP	New ✓	20.00 ✓
6	TO REMOVE & REFIT DOOR TRIM,DOOR GLASS,WINDOW REGULATOR	New 40	60.00 ✓
7	TO REMOVE & REFIT FRT CABIN REAR GLASS	New ✓	100.00 ✓
8	TO REMOVE & REFIT INNER SEAT & UPHOLSTERY TO ASSIST WORK LOAD	New 60	100.00 ✓
9	TO REMOVE & REFIT ROOF LINING, INNER TRIM TO ASSIST WORK LOAD	New 60	80.00 ✓
10	TO REMOVE & REFIT EXHAUST SYSTEM TO ASSIST WORK LOAD	New 100	150.00 ✓
11	TO REMOVE & REFIT UNDERCARRIAGE TO ASSIST WORK LOAD	New 300	400.00 ✓
12	TO DO WHEEL ALIGNMENT	New ✓	80.00 ✓
13	TO APPLY ANTI RUST COATING	New 120	200.00 ✓
Gross Labour Cost (S\$)			6,190.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 17 Aug 2017)
 Parts: N/A HINO XZU710R-HKFMS3 4.0 D (M) (Model not available in database)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: (Unsubmitted, no print-code for YN7881H)
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT BUMPER <i>del ✓</i>	0.00	0.00	*950.00 F/
2	2		*FRT BUMPER SIDE BRACKET <i>LH-?, RH-bt ✓</i>	0.00	0.00	*560.00 F/ <i>200 ✓</i>
3	1		*FRT FOGLAMP(RH) <i>mis ✓</i>	0.00	0.00	*275.00 F/
4	1		*FRT FOGLAMP HOLDER(RH) <i>del ✓</i>	0.00	0.00	*50.00 F/
5	2		*FRT HEADLAMP <i>LH-?, RH-cue ✓</i>	0.00	0.00	*2,200.00 F/ <i>1100 ✓</i>
6	1		*FRT GRILLE <i>mis ✓</i>	0.00	0.00	*575.00 F/
7	10		*FRT GRILLE CLIPS <i>ne ✓</i>	0.00	0.00	*30.00 F/
8	1		*FRT GRILLE EMBLEM <i>ne ✓</i>	0.00	0.00	*68.00 F/
9	1		*FRT CORNER PANEL(RH) <i>mis ✓</i>	0.00	0.00	*550.00 F/
10	1		*FRT CORNER PANEL SEAL(RH) <i>ne ✓</i>	0.00	0.00	*30.00 F/
11	1		*SIDE MIRROR ARM(RH) <i>bt ✓</i>	0.00	0.00	*255.00 F/
12	1		*SIDE MIRROR ARM ROUND CAP(RH) <i>mis ✓</i>	0.00	0.00	*12.00 F/
13	1		*SIDE MIRROR(RH) <i>cue ✓</i>	0.00	0.00	*28.00 F/
14	1		*SIDE MIRROR ARM TOP SEAL(RH) <i>mis ✓</i>	0.00	0.00	*25.00 F/
15	1		*SIDE MIRROR ARM (LH) <i>bt ✓</i>	0.00	0.00	*265.00 F/
16	1		*SIDE MIRROR(LH)(ROUND) <i>mis ✓</i>	0.00	0.00	*15.00 F/
17	1		*SIDE MIRROR(LH) <i>cut ✓</i>	0.00	0.00	*30.00 F/
18	1		*FRT WINDSCREEN WITH MOULDING <i>ne ✓</i>	0.00	0.00	*1,350.00 F/
19	1		*FRT WINDSCREEN SEALANT <i>ne ✓</i>	0	0.00	*40.00 FS
20	1		*ERP BRACKET <i>ne ✓</i>	0	0.00	*26.00 FS
21	1		*FRT ROOF TOP LAMP(RH) <i>mis ✓</i>	0.00	0.00	*140.00 F/
22	1		*FRT ROOF ANTENNA <i>bt ✓</i>	0.00	0.00	*95.00 F/
23	1		*FRT ROOF TOP PANEL SIDE (RH) <i>bt ✓</i>	0.00	0.00	*400.00 F/
24	1		*FRT ROOF TOP PANEL AT REAR <i>bt ✓</i>	0.00	0.00	*470.00 F/
25	1		*FRT CABIN ROOF LINING <i>del ✓</i>	0.00	0.00	*300.00 F/
26	1		*FRT CABIN REAR GLASS MOULDING <i>ne ✓</i>	0.00	0.00	*80.00 F/
27	1		*FRT CABIN REAR PANEL <i>bt ✓</i>	0.00	0.00	*850.00 F/
28	1		*FRT CABIN REAR SUPPORT <i>bt ✓</i>	0.00	0.00	*1,050.00 F/
29	2		*FRT CABIN REAR LOCK <i>?</i>	0.00	0.00	*600.00 F/
30	1		*FRT CABIN REAR LOCK LATCH(LH) <i>?</i>	0.00	0.00	*105.00 F/
31	2		*FRT CABIN REAR LOCK HOOK <i>?</i>	0.00	0.00	*110.00 F/
32	2		*FRT CABIN REAR LOCK HOOK PLATE <i>?</i>	0.00	0.00	*240.00 F/
33	2		*FRT CABIN REAR MOUNTING BUSH <i>?</i>	0.00	0.00	*160.00 F/
34	1		*FRT WHEEL ARCH PANEL(RH) <i>del ✓</i>	0.00	0.00	*370.00 F/
35	1		*FRT WHEEL ARCH PANEL RR RUBBER SEAL(RH) <i>del ✓</i>	0.00	0.00	*40.00 F/
36	1		*ROCKER PANEL(RH) <i>bt ✓</i>	0.00	0.00	*355.00 F/
37	1		*ROCKER PANEL SCUFF PLATE(RH) <i>?</i>	0.00	0.00	*150.00 F/ <i>photo</i>
38	1		*FRT TYRE REAR MUDGUARD(RH)	0.00	0.00	*200.00 F/
39	1		*FRT DOOR(RH) <i>bt ✓</i>	0.00	0.00	*1,100.00 F/
40	2		*FRT DOOR HINGE(RH) <i>?</i>	0.00	0.00	*280.00 F/
41	1		*FRT DOOR CHECKER(RH) <i>?</i>	0.00	0.00	*85.00 F/
42	1		*FRT DOOR GLASS RUN CHANNEL(RH) <i>mis ✓</i>	0.00	0.00	*150.00 F/
43	1		*FRT DOOR GLASS INNER MOULDING <i>?</i>	0.00	0.00	*60.00 F/ <i>photo</i>
44	1		*FRT DOOR GLASS OUTER MOULDING <i>?</i>	0.00	0.00	*65.00 F/ <i>photo</i>
45	1		*FRT DOOR GLASS REGULATOR <i>?</i>	0.00	0.00	*200.00 F/ <i>photo</i>
46	1		*FRT DOOR GLASS REGULATOR MOTOR <i>?</i>	0.00	0.00	*245.00 F/
47	1		*FRT DOOR OUTER HANDLE <i>cue ✓</i>	0.00	0.00	*60.00 F/

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
48	1		*FRT DOOR 616 STICKER <i>ht</i>	0.00	0.00	*70.00 F/
49	1		*FRT DOOR EURO 5 STICKER <i>rec</i>	0.00	0.00	*45.00 F/
50	1		*FRT DOOR INNER TRIMBOARD(RH)	0.00	0.00	*460.00 F/
51	1		*FRT DOOR WEATHERSTRIPE(RH) <i>ht</i>	0.00	0.00	*165.00 F/
52	1		*FRT DOOR LOCK(RH) <i>ht</i>	0.00	0.00	*200.00 F/
53	1		*FRT DOOR SEAL @ FRT <i>ht</i>	0.00	0.00	*60.00 F/
54	1		*FRT DOOR LOWER GARNISH(RH) <i>ht</i>	0.00	0.00	*100.00 F/
55	1		*FRT DOOR LAMP(RH) <i>over</i>	0.00	0.00	*70.00 F/
56	1		*FRT STEP GARNISH(RH) <i>cut</i>	0.00	0.00	*360.00 F/
57	1		*REAR DOOR PILLAR(RH) <i>ht</i>	0.00	0.00	*980.00 F/
58	1		*DASHBOARD ASSY <i>dis</i>	0.00	0.00	*550.00 F/
59	1		*DASHBOARD SIDE COVER LOWER(RH) ?	0.00	0.00	*170.00 FX
60	1		*DASHBOARD SIDE COVER TOP ?	0.00	0.00	*300.00 FX
61	1		*DASHBOARD GLOVE BOX <i>di</i>	0.00	0.00	*340.00 F/
62	1		*DASHBOARD SPEAKER COVER(RH) <i>di</i>	0.00	0.00	*100.00 F/
63	1		*DASHBOARD BRAKE TANK OUTER COVER(RH)	0.00	0.00	*100.00 F/
64	1		*DASHBOARD RADIO OUTER TRIM <i>over</i>	0.00	0.00	*250.00 F/
65	1		*FRT DOOR PILLAR HANDLE NUT COVER RH <i>dis</i>	0.00	0.00	*5.00 F/
66	1		*DASHBOARD CUP HOLDER RH ?	0.00	0.00	*160.00 FX
67	1		*DASHBOARD SPEEDOMETER OUTER TRIM <i>dis</i>	0.00	0.00	*168.00 F/
68	1		*AIR CON BLOWER COOLING COIL ASSY ?	0.00	0.00	*1,650.00 F/ <i>photo</i>
69	1		*HEATER COOLING COIL ASSY ?	0.00	0.00	*550.00 FX
70	1		*AIR INTAKE DUCT <i>di</i>	0.00	0.00	*350.00 F/
71	1		*AIR INTAKE HOSE <i>di</i>	0.00	0.00	*100.00 F/
72	1		*AIR CLEANER BOX ASSY <i>over</i>	0.00	0.00	*400.00 F/
73	1		*AIR CLEANER BOX AIR FLOW HOSE <i>di</i>	0.00	0.00	*120.00 F/
74	1		*FRT RIM RH ?	0	0.00	*200.00 FS <i>photo</i>
75	1		*FRT TYRE RH <i>punctured</i>	0	0.00	*180.00 FS
76	1		*FRT SHOCK ABSORBER RH ?	0.00	0.00	*280.00 FX
77	1		*FRT KNUCKLE ARM RH ?	0.00	0.00	*600.00 FX
78	1		*FRT WHEEL HUB RH ?	0.00	0.00	*125.00 FX
79	1		*FRT WHEEL HUB BEARING RH ?	0.00	0.00	*100.00 FX
80	1		*FRT AXLE ?	0.00	0.00	*2,200.00 FX
81	1		*FRT EXHAUST PIPE ?	0.00	0.00	*550.00 FX
82	1		*ERG COOLER REAR HEAT SHIELD COVER ? TYPO: EGR COOLER REAR HEAT SHIELD COVER	0.00	0.00	*195.00 F/ <i>photo</i>
83	2		*ENGINE MOUNTING @ FRT ?	0.00	0.00	*260.00 FX
84	2		*GEAR BOX MOUNTING ?	0.00	0.00	*200.00 FX
85	1		*REAR NUMBER PLATE <i>ht</i>	0	0.00	*15.00 FS
86	2		*REAR NUMBER PLATE LAMP <i>dis</i>	0.00	0.00	*80.00 F/
87	1		*REAR NUMBER PLATE BRACKET <i>ht</i>	0.00	0.00	*85.00 F/
88	2		*REAR TAIL LAMP <i>over</i>	0.00	0.00	*320.00 F/
89	2		*REAR TAIL LAMP PANEL <i>ht</i>	0.00	0.00	*240.00 F/
90	1		*REAR BUMPER <i>ht</i>	0	0.00	*350.00 FS
91	2		*REAR BUMPER SIDE BRACKET <i>ht</i>	0	0.00	*360.00 FS
92	1		*REAR CHASSIS FRAME END CROSSMEMBER <i>ht</i>	0	0.00	*180.00 FS
93	1		*REAR SPARE TYRE RIM <i>mis</i>	0.00	0.00	*180.00 F/
94	1		*REAR SPARE TYRE <i>mis</i>	0	0.00	*200.00 FS
95	1		*REAR SPARE TYRE BRACKET <i>ht</i>	0.00	0.00	*250.00 F/
96	1		*REAR SPARE TYRE SUPPORT PANEL <i>ht</i>	0.00	0.00	*480.00 F/
97	1		*REAR WOODEN DECK ASSY <i>over</i>	0.00	0.00	*6,500.00 F/
98	1		*REAR WOODEN STEP PANEL <i>over</i>	0	0.00	*100.00 FS
99	2		*REAR CHASSIS FRAME TOP BEAM <i>ht</i>	0	0.00	*1,600.00 FS
100	11		*REAR CHASSIS FRAME WOODEN CROSSMEMBER BEAM <i>over</i>	0	0.00	*3,080.00 FS
101	6		*REAR CHASSIS FRAME U BOLT SET <i>ht</i>	0	0.00	*360.00 FS
102	1		*REAR TAILGATE 60KM/H STICKER <i>over</i>	0	0.00	*10.00 FS
103	1		*REAR TAILGATE PAX STICKER <i>ht</i>	0	0.00	*10.00 FS
104	1		*REAR DECK FRT WOODEN RAILING <i>over</i>	0.00	0.00	*350.00 F/
105	2		*REAR DECK SIDE WOODEN RAILING LH <i>mis</i>	0.00	0.00	*700.00 F/
106	2		*REAR DECK SIDE WOODEN RAILING RH <i>mis</i>	0.00	0.00	*700.00 F/
107	2		*REAR RIM LH-? , RH- <i>ht</i>	0	0.00	(p)*380.00 FS <i>photo</i>

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
108	2		*REAR TYRE LH-? RH <i>punctured</i>	0	0.00	(Lp)*400.00 FS <i>200</i>
109	1		*REAR WHEEL SHAFT(RH) ?	0.00	0.00	*850.00 FX
110	2		*REAR WHEEL HUB ?	0.00	0.00	*2,100.00 FX
111	2		*REAR WHEEL HUB BEARING ?	0.00	0.00	*130.00 FX
112	1		*REAR SHOCKABSORBER(RH) ?	0	0.00	*270.00 FSX
113	1		*REAR DIFFERENTIAL PROPELLER SHAFT ?	0.00	0.00	*1,800.00 FX
114	2		*REAR MUDGUARD <i>de</i>	0.00	0.00	*700.00 F/
115	2		*REAR MUDGUARD LOWER MUD FLAP <i>mis</i>	0.00	0.00	*60.00 F/

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	<i>\$29181.00</i>	50,827.00
+ Margin on L,N Items 5.00% (\$\$)	<i>add 5% = \$30640.05</i>	2,154.30
Total Parts (\$\$)	<i>Swell \$7091.00</i>	52,981.30

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

SUPPLEMENTARY.

- AIR CLEANER BOX BRACKET \$95. *b1* ✓
- FRT CABIN BRACKET \$1250.00 *b7* ✓
- FRT WINDSCREEN MOUNTING (RH) \$60.00. *de* ✓
- RE DECK RANOA ASSY \$2000.00. *swell mis* ✓
- DIESEL RETURN HOSE \$120. *b1* ✓
- CABIN TILT SENSOR \$325.00 *dis* ✓

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO LIFT UP REAR DECK	New 300	400.00
2	TO KNOCK FRT PANEL,FRT DOOR PILLAR(RH),ROOF TOP PANEL,WELD,REMOVE & FIX ABOVE PARTS	New 1200	1,500.00
3	TO SPRAY PAINTING ON FRT BUMPER,FRT DOOR PILLAR(RH),FRT DOOR(RH),ROOF TOP PANEL,FRT CABIN REAR PANEL,FRT WHEEL ARCH PANEL(RH),ROCKER PANEL(RH),REAR BUMPER,REAR CHASSIS & AFFECTED AREA	New 1500	1,800.00
4	TO KNOCK,WELD,JACK,STRAIGHTEN CHASSIS FRAME <i>(rear chassis) photo ?</i>	New 800	1,300.00 ✓
5	TO CHECK WIRING,FOCUS HEADLAMP	New	20.00
6	TO REMOVE & REFIT DOOR TRIM,DOOR GLASS,WINDOW REGULATOR	New 40	60.00
7	TO REMOVE & REFIT FRT CABIN REAR GLASS	New	100.00
8	TO REMOVE & REFIT INNER SEAT & UPHOLSTERY TO ASSIST WORK LOAD	New 60	100.00
9	TO REMOVE & REFIT ROOF LINING, INNER TRIM TO ASSIST WORK LOAD	New 60	80.00
10	TO REMOVE & REFIT EXHAUST SYSTEM TO ASSIST WORK LOAD	New 100	150.00
11	TO REMOVE & REFIT UNDERCARRIAGE TO ASSIST WORK LOAD	New 300	400.00
12	TO DO WHEEL ALIGNMENT	New	80.00
13	TO APPLY ANTI RUST COATING	New 120	200.00
Gross Labour Cost (\$\$) 4680			6,190.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

total: \$46553.55
less 2% = \$37242.80
x \$37200 45
Before 5000 \$5500
OK? Plus Perent - shaw
limit \$55k. 10/17/2018

REPAIR DETAILS

Supplementary

Reference

Part Source: (Last Synchronised: 09 May 2018)

Parts: N/A HINO XZU710R-HKFMS3 4.0 D (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for YN7881H)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*AIR CLEANER BOX BRACKET	0.00	0.00	95.00 F
2	1		*FRT CABIN BRACKET	0.00	0.00	1,250.00 F
3	1		*FRT WINDSCREEN INNER TRIM (RH)	0.00	0.00	60.00 F
4	1		*REAR DECK CANOPY ASSY	0	0.00	2,200.00 FS
5	1		*DIESEL RETURN HOSE	0.00	0.00	120.00 F
6	1		*CABIN TILT SENSOR	0.00	0.00	325.00 F

F=Franchise part, S=Spclt.

Sub Total (S\$)	4,050.00
+ Margin on L,N Items 5.00% (S\$)	92.50
Total Parts (S\$)	4,142.50

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	17 Aug 2017 Sendback Est	17 Aug 2017 18:12 \$559,171.30	21 Aug 2017 17:11 Edit Adj Rpt	\$537,200.00 Edit Estimates	\$537,200.00 View Rpt		Pending for Survey Report Cancel Case
Supp #1	09 May 2018 14:17	09 May 2018 14:58 \$54,142.50	09 May 2018 14:58			(Combined)	Combined with Main Uncombine Suppl.

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:	FELICITY ENGINEERING PTE LTD, Co. Reg. No.: 199701363W		
Vehicle Reg. No.:	YN7881H	Date of Loss:	17/07/2017 13:00 - :59 [26 Months and 17 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / SNM17D04232C01	Policy/Cover Note No.:	DMCVSN3036551700 (Comprehensive)
		Excess:	\$5550.00
Repairer:	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer) Blk 3 Pioneer Road North, #01-18, 628457 Pioneer - Tel: 6268 6183		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 30/08/2017]		
Driver/Custodian:	MUTHUSAMY UKKIRAPANDI (33 / Male), NRIC: G6459017R, Tel: +6586864016		
Adj Asg. Remarks:	SURVEY REVERT, AND ECONOMICAL TO REPAIR.		

ASSOCIATED MAIL RECEIVED
[View All](#)
[Compose Case Mail](#)

- CHINA_TAIPING (25/08/2017): Alert - Adj Mandate Approved (\$546500.00) - YN7881H - Claim Handler: Chong Boon ...

ALL ASSOCIATED TASKS
[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

YN7881H (SNM17D04232C01)
OD
Jul 17 2017 1:00PM
[FELICITY ENGINEERING PTE LTD]
Sng Ah Tee Motor & Panel Service Pte Ltd

Upload Documents

Upload Photos

Compose New Letter

View

View in Browser

Assessment Reports

1 per page

No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)		Thumbnail	Print
1	18/07/17 14:39	Accident Statement		Load HTM	
2	17/08/17 10:35	Addendum Sheet		Load TIF	
3	17/08/17 10:36	Accident Statement Addm. #1		Load HTM	
4	17/08/17 18:12	Repairer Estimates		Load HTM	
5	09/05/18 14:58	Repairer Estimates Suppl. #1		Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	23/08/17 15:46	Adjuster Immediate Advice		Load HTM	

Photos/Images

3 per page

No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)		Thumbnail	Print
1	18/07/17 14:34	Accident Photo [Linked Accident Report Documents]		Load JPG	
2	18/07/17 14:34	Accident Photo [Linked Accident Report Documents]		Load JPG	
3	18/07/17 14:34	Accident Photo [Linked Accident Report Documents]		Load JPG	
4	18/07/17 14:34	Accident Photo [Linked Accident Report Documents]		Load JPG	
5	18/07/17 14:34	Accident Photo [Linked Accident Report Documents]		Load JPG	
6	18/07/17 14:34	Accident Photo [Linked Accident Report Documents]		Load JPG	
7	18/07/17 14:34	Accident Photo [Linked Accident Report Documents]		Load JPG	
8	18/07/17 14:34	Accident Photo [Linked Accident Report Documents]		Load JPG	
9	18/07/17 14:34	Accident Photo [Linked Accident Report Documents]		Load JPG	
10	18/07/17 14:34	Accident Photo [Linked Accident Report Documents]		Load JPG	
11	18/07/17 14:34	Accident Photo [Linked Accident Report Documents]		Load JPG	
12	18/07/17 14:34	Accident Photo [Linked Accident Report Documents]		Load JPG	
13	18/07/17 14:34	Accident Photo [Linked Accident Report Documents]		Load JPG	
14	18/07/17 14:34	Accident Photo [Linked Accident Report Documents]		Load JPG	
15	18/07/17 14:34	Accident Photo [Linked Accident Report Documents]		Load JPG	
16	18/07/17 14:34	Accident Photo [Linked Accident Report Documents]		Load JPG	
17	18/07/17 14:34	Accident Photo [Linked Accident Report Documents]		Load JPG	
18	18/07/17 14:34	Accident Photo [Linked Accident Report Documents]		Load JPG	
19	18/07/17 14:34	Accident Photo [Linked Accident Report Documents]		Load JPG	
20	18/07/17 14:34	Accident Photo [Linked Accident Report Documents]		Load JPG	
21	18/07/17 14:34	Accident Photo [Linked Accident Report Documents]		Load JPG	
22	18/07/17 14:34	Accident Photo [Linked Accident Report Documents]		Load JPG	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print

Assessment Reports			1 per page	☒
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	23/08/17 15:50	General View	 Load JPG	☒
2	23/08/17 15:50	General View	 Load JPG	☒
3	23/08/17 15:50	General View	 Load JPG	☒
4	23/08/17 15:50	General View	 Load JPG	☒
5	23/08/17 15:50	General View	 Load JPG	☒
6	23/08/17 15:50	General View	 Load JPG	☒
7	23/08/17 15:50	General View	 Load JPG	☒
8	23/08/17 15:50	General View	 Load JPG	☒
9	23/08/17 15:50	General View	 Load JPG	☒
10	23/08/17 15:50	General View	 Load JPG	☒
11	23/08/17 15:50	General View	 Load JPG	☒
12	23/08/17 15:50	General View	 Load JPG	☒
13	23/08/17 15:50	General View	 Load JPG	☒
14	23/08/17 15:50	General View	 Load JPG	☒
15	23/08/17 15:50	General View	 Load JPG	☒
16	23/08/17 15:50	General View	 Load JPG	☒
17	23/08/17 15:50	General View	 Load JPG	☒
18	23/08/17 15:50	General View	 Load JPG	☒
19	23/08/17 15:50	General View	 Load JPG	☒
20	23/08/17 15:50	General View	 Load JPG	☒
21	23/08/17 15:50	General View	 Load JPG	☒
22	23/08/17 15:50	General View	 Load JPG	☒
23	23/08/17 15:50	General View	 Load JPG	☒
24	23/08/17 15:50	General View	 Load JPG	☒
25	23/08/17 15:50	General View	 Load JPG	☒
26	23/08/17 15:50	General View	 Load JPG	☒
27	23/08/17 15:50	General View	 Load JPG	☒
28	23/08/17 15:50	General View	 Load JPG	☒
29	23/08/17 15:50	General View	 Load JPG	☒
30	23/08/17 15:50	General View	 Load JPG	☒
31	23/08/17 15:50	General View	 Load JPG	☒
32	23/08/17 15:50	General View	 Load JPG	☒
33	23/08/17 15:50	General View	 Load JPG	☒
34	23/08/17 15:50	General View	 Load JPG	☒
35	23/08/17 15:50	General View	 Load JPG	☒
36	23/08/17 15:50	General View	 Load JPG	☒
37	23/08/17 15:50	General View	 Load JPG	☒
38	23/08/17 15:50	General View	 Load JPG	☒
39	23/08/17 15:50	General View	 Load JPG	☒
40	23/08/17 15:50	General View	 Load JPG	☒
41	23/08/17 15:50	General View	 Load JPG	☒
42	23/08/17 15:50	General View	 Load JPG	☒
43	23/08/17 15:50	General View	 Load JPG	☒
44	23/08/17 15:50	General View	 Load JPG	☒
45	23/08/17 15:50	General View	 Load JPG	☒
46	23/08/17 15:50	General View	 Load JPG	☒
47	23/08/17 15:50	General View	 Load JPG	☒
48	23/08/17 15:50	General View	 Load JPG	☒
49	23/08/17 15:50	General View	 Load JPG	☒
50	23/08/17 15:50	General View	 Load JPG	☒

Assessment Reports				1 per page	☒
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)		Thumbnail	Print
51	23/08/17 15:50	General View		Load JPG	☒
52	23/08/17 15:50	General View		Load JPG	☒
53	23/08/17 15:50	General View		Load JPG	☒
54	23/08/17 15:50	General View		Load JPG	☒
55	23/08/17 15:50	General View		Load JPG	☒
56	23/08/17 15:50	General View		Load JPG	☒
57	23/08/17 15:50	General View		Load JPG	☒
58	23/08/17 15:50	General View		Load JPG	☒
59	23/08/17 15:50	General View		Load JPG	☒
60	23/08/17 15:50	General View		Load JPG	☒
61	23/08/17 15:50	General View		Load JPG	☒
62	23/08/17 15:50	General View		Load JPG	☒
63	23/08/17 15:50	General View		Load JPG	☒
64	23/08/17 15:50	General View		Load JPG	☒
65	23/08/17 15:50	General View		Load JPG	☒
66	23/08/17 15:50	General View		Load JPG	☒
67	23/08/17 15:50	General View		Load JPG	☒
68	23/08/17 15:50	General View		Load JPG	☒
69	23/08/17 15:50	General View		Load JPG	☒
70	23/08/17 15:50	General View		Load JPG	☒
71	23/08/17 15:50	General View		Load JPG	☒
72	23/08/17 15:50	General View		Load JPG	☒
73	23/08/17 15:50	General View		Load JPG	☒
74	23/08/17 15:50	General View		Load JPG	☒
75	23/08/17 15:50	General View		Load JPG	☒
76	23/08/17 15:50	General View		Load JPG	☒
77	23/08/17 15:50	General View		Load JPG	☒
78	23/08/17 15:50	General View		Load JPG	☒
79	23/08/17 15:50	General View		Load JPG	☒
80	23/08/17 15:50	General View		Load JPG	☒
81	23/08/17 15:50	General View		Load JPG	☒
82	23/08/17 15:50	General View		Load JPG	☒
83	23/08/17 15:50	General View		Load JPG	☒
84	23/08/17 15:50	General View		Load JPG	☒
85	23/08/17 15:50	General View		Load JPG	☒
86	23/08/17 15:50	General View		Load JPG	☒
87	23/08/17 15:50	General View		Load JPG	☒
88	23/08/17 15:50	General View		Load JPG	☒
89	23/08/17 15:50	General View		Load JPG	☒
90	23/08/17 15:50	General View		Load JPG	☒
91	23/08/17 15:50	General View		Load JPG	☒
92	23/08/17 15:50	General View		Load JPG	☒
93	23/08/17 15:50	General View		Load JPG	☒
94	23/08/17 15:50	General View		Load JPG	☒
95	23/08/17 15:50	General View		Load JPG	☒
96	23/08/17 15:50	General View		Load JPG	☒
97	23/08/17 15:50	General View		Load JPG	☒
98	23/08/17 15:50	General View		Load JPG	☒
99	23/08/17 15:50	General View		Load JPG	☒
100	23/08/17 15:50	General View		Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
101	23/08/17 15:50	General View	 Load JPG	☒
102	23/08/17 15:50	General View	 Load JPG	☒
103	23/08/17 15:50	General View	 Load JPG	☒
104	23/08/17 15:50	General View	 Load JPG	☒
105	23/08/17 15:50	General View	 Load JPG	☒
106	23/08/17 15:50	General View	 Load JPG	☒
107	23/08/17 15:50	General View	 Load JPG	☒
108	23/08/17 15:50	General View	 Load JPG	☒
109	23/08/17 15:50	General View	 Load JPG	☒
110	23/08/17 15:50	General View	 Load JPG	☒
111	23/08/17 15:50	General View	 Load JPG	☒
112	23/08/17 15:50	General View	 Load JPG	☒
113	23/08/17 15:50	General View	 Load JPG	☒
114	23/08/17 15:50	General View	 Load JPG	☒
115	23/08/17 15:50	General View	 Load JPG	☒
116	23/08/17 15:50	General View	 Load JPG	☒
117	23/08/17 15:50	General View	 Load JPG	☒
118	23/08/17 15:50	General View	 Load JPG	☒
119	23/08/17 15:50	General View	 Load JPG	☒
120	23/08/17 15:50	General View	 Load JPG	☒
121	23/08/17 15:50	General View	 Load JPG	☒
122	23/08/17 15:50	General View	 Load JPG	☒
123	23/08/17 15:50	General View	 Load JPG	☒
124	23/08/17 15:50	General View	 Load JPG	☒
125	23/08/17 15:50	General View	 Load JPG	☒
126	23/08/17 15:50	General View	 Load JPG	☒
127	23/08/17 15:50	General View	 Load JPG	☒
128	23/08/17 15:50	General View	 Load JPG	☒
129	23/08/17 15:50	General View	 Load JPG	☒
130	23/08/17 15:50	General View	 Load JPG	☒
131	23/08/17 15:50	General View	 Load JPG	☒
132	23/08/17 15:50	General View	 Load JPG	☒
133	23/08/17 15:50	General View	 Load JPG	☒
134	23/08/17 15:50	General View	 Load JPG	☒
135	23/08/17 15:50	General View	 Load JPG	☒
136	23/08/17 15:50	General View	 Load JPG	☒
137	23/08/17 15:50	General View	 Load JPG	☒
138	23/08/17 15:50	General View	 Load JPG	☒
139	23/08/17 15:50	General View	 Load JPG	☒
140	23/08/17 15:50	General View	 Load JPG	☒
141	23/08/17 15:50	General View	 Load JPG	☒
142	23/08/17 15:50	General View	 Load JPG	☒
143	23/08/17 15:50	General View	 Load JPG	☒
144	23/08/17 15:50	General View	 Load JPG	☒
145	23/08/17 15:50	General View	 Load JPG	☒
146	23/08/17 15:50	General View	 Load JPG	☒
147	23/08/17 15:50	General View	 Load JPG	☒
148	23/08/17 15:50	General View	 Load JPG	☒
149	23/08/17 15:50	General View	 Load JPG	☒
150	23/08/17 15:50	General View	 Load JPG	☒

Assessment Reports			1 per page	☒
No.	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
151	23/08/17 15:50	General View	 Load JPG	☒
152	23/08/17 15:50	General View	 Load JPG	☒
153	23/08/17 15:50	General View	 Load JPG	☒
154	23/08/17 15:50	General View	 Load JPG	☒
155	23/08/17 15:50	General View	 Load JPG	☒
156	23/08/17 15:50	General View	 Load JPG	☒
157	23/08/17 15:50	General View	 Load JPG	☒
158	23/08/17 15:50	General View	 Load JPG	☒
159	23/08/17 15:50	General View	 Load JPG	☒
160	23/08/17 15:50	General View	 Load JPG	☒
161	23/08/17 15:50	General View	 Load JPG	☒
162	23/08/17 15:50	General View	 Load JPG	☒
163	23/08/17 15:50	General View	 Load JPG	☒
164	23/08/17 15:50	General View	 Load JPG	☒
165	23/08/17 15:50	General View	 Load JPG	☒
166	23/08/17 15:50	General View	 Load JPG	☒
167	23/08/17 15:50	General View	 Load JPG	☒
168	23/08/17 15:50	General View	 Load JPG	☒
169	23/08/17 15:50	General View	 Load JPG	☒
170	23/08/17 15:50	General View	 Load JPG	☒
171	23/08/17 15:50	General View	 Load JPG	☒
172	23/08/17 15:50	General View	 Load JPG	☒
173	23/08/17 15:50	General View	 Load JPG	☒
174	23/08/17 15:50	General View	 Load JPG	☒
175	23/08/17 15:50	General View	 Load JPG	☒
176	23/08/17 15:50	General View	 Load JPG	☒
177	23/08/17 15:50	General View	 Load JPG	☒
178	23/08/17 15:50	General View	 Load JPG	☒
179	23/08/17 15:50	General View	 Load JPG	☒
180	23/08/17 15:50	General View	 Load JPG	☒
181	23/08/17 15:50	General View	 Load JPG	☒
182	23/08/17 15:50	General View	 Load JPG	☒
183	23/08/17 15:50	General View	 Load JPG	☒
184	23/08/17 15:50	General View	 Load JPG	☒
185	07/12/18 14:45	Reinspection Photo	 Load JPG	☒
186	07/12/18 14:45	Reinspection Photo	 Load JPG	☒
187	07/12/18 14:45	Reinspection Photo	 Load JPG	☒
188	07/12/18 14:45	Reinspection Photo	 Load JPG	☒
189	07/12/18 14:45	Reinspection Photo	 Load JPG	☒
190	07/12/18 14:45	Reinspection Photo	 Load JPG	☒
191	07/12/18 14:45	Reinspection Photo	 Load JPG	☒
192	07/12/18 14:45	Reinspection Photo	 Load JPG	☒
193	07/12/18 14:45	Reinspection Photo	 Load JPG	☒
194	07/12/18 14:45	Reinspection Photo	 Load JPG	☒
195	07/12/18 14:45	Reinspection Photo	 Load JPG	☒
196	07/12/18 14:45	Reinspection Photo	 Load JPG	☒
197	07/12/18 14:45	Reinspection Photo	 Load JPG	☒
198	07/12/18 14:45	Reinspection Photo	 Load JPG	☒
199	07/12/18 14:45	Reinspection Photo	 Load JPG	☒
200	07/12/18 14:45	Reinspection Photo	 Load JPG	☒

Assessment Reports				1 per page	☒
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print	
201	07/12/18 14:45	Reinspection Photo	 Load JPG	☒	
202	07/12/18 14:45	Reinspection Photo	 Load JPG	☒	
203	07/12/18 14:45	Reinspection Photo	 Load JPG	☒	
204	07/12/18 14:45	Reinspection Photo	 Load JPG	☒	
205	07/12/18 14:45	Reinspection Photo	 Load JPG	☒	
206	07/12/18 14:45	Reinspection Photo	 Load JPG	☒	
207	07/12/18 14:45	Reinspection Photo	 Load JPG	☒	
208	07/12/18 14:45	Reinspection Photo	 Load JPG	☒	
209	07/12/18 14:45	Reinspection Photo	 Load JPG	☒	
210	07/12/18 14:45	Reinspection Photo	 Load JPG	☒	
211	07/12/18 14:45	Reinspection Photo	 Load JPG	☒	
212	07/12/18 14:45	Reinspection Photo	 Load JPG	☒	
213	07/12/18 14:45	Reinspection Photo	 Load JPG	☒	
214	07/12/18 14:45	Reinspection Photo	 Load JPG	☒	
215	07/12/18 14:45	Reinspection Photo	 Load JPG	☒	
216	07/12/18 14:45	Reinspection Photo	 Load JPG	☒	
Documentation				1 per page	☒
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print	
1	18/07/17 14:38	CI,IC,DL [Linked Accident Report Documents]	 Load TIF		
2	18/07/17 14:38	POLICE REPORT [Linked Accident Report Documents]	 Load TIF		
3	18/07/17 14:39	Sketch Plan [Linked Accident Report Documents]	 Load TIF		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	12/12/18 12:47	Supplementary	 Load PDF		

Linked Accident Report Documents

Assessment Reports				1 per page	☒
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print	
1	18/07/17 14:39	Accident Statement	 Load HTM		
2	17/08/17 10:35	Addendum Sheet	 Load TIF		
3	17/08/17 10:36	Accident Statement Addm. #1	 Load HTM		
Photos/Images				3 per page	☒
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print	
1	18/07/17 14:34	Accident Photo	 Load JPG	☒	
2	18/07/17 14:34	Accident Photo	 Load JPG	☒	
3	18/07/17 14:34	Accident Photo	 Load JPG	☒	
4	18/07/17 14:34	Accident Photo	 Load JPG	☒	
5	18/07/17 14:34	Accident Photo	 Load JPG	☒	
6	18/07/17 14:34	Accident Photo	 Load JPG	☒	
7	18/07/17 14:34	Accident Photo	 Load JPG	☒	
8	18/07/17 14:34	Accident Photo	 Load JPG	☒	
9	18/07/17 14:34	Accident Photo	 Load JPG	☒	
10	18/07/17 14:34	Accident Photo	 Load JPG	☒	
11	18/07/17 14:34	Accident Photo	 Load JPG	☒	
12	18/07/17 14:34	Accident Photo	 Load JPG	☒	
13	18/07/17 14:34	Accident Photo	 Load JPG	☒	
14	18/07/17 14:34	Accident Photo	 Load JPG	☒	
15	18/07/17 14:34	Accident Photo	 Load JPG		

Assessment Reports			1 per page	☒
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
				☒
16	18/07/17 14:34	Accident Photo	 Load JPG	☒
17	18/07/17 14:34	Accident Photo	 Load JPG	☒
18	18/07/17 14:34	Accident Photo	 Load JPG	☒
19	18/07/17 14:34	Accident Photo	 Load JPG	☒
20	18/07/17 14:34	Accident Photo	 Load JPG	☒
21	18/07/17 14:34	Accident Photo	 Load JPG	☒
22	18/07/17 14:34	Accident Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	18/07/17 14:38	CI,IC,DL	 Load TIF	
2	18/07/17 14:38	POLICE REPORT	 Load TIF	
3	18/07/17 14:39	Sketch Plan	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Repairer ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd

(Co.Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CT117016163/T1TBE2

Date: 12/12/2018

REFERENCE

Insured/Claimant: FELICITY ENGINEERING PTE LTD Policy No: DMCVSN3036551700

Date of Loss: 17/07/2017

Nature of Claim: OD

Claim No: SNM17D04232C01

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	YN7881H	Engine No:	N04CUS20488
Make & Model:	HINO XZU710R-HKFMS3, 4.0 D (M)	Chassis No:	JHHUCS3H90K011621
Reg. Date:	30/04/2015 (Man. Year: 2014)	Odometer:	0 km
Colour:	White		
Engine Capacity:	4009 cc		
Market Value/New Car Price:	S\$80,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	7.00 /R16	Rear Tyre Size:	7.00 /R16 (D)
Front Left Side:	Bridgestone 7 mm	Rear Left Side:	Bridgestone 7/7 mm
Front Right Side:	Bridgestone 7 mm	Rear Right Side:	Bridgestone 7/7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	57,123.80	42,214.80	14,909.00	26.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,190.00	4,680.00	1,510.00	24.39
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	63,313.80	46,894.80	16,419.00	25.93
Approved Total (Overridden) (S\$)		37,200.00		
- Excess (S\$)	0.00	550.00	-550.00	
(S\$)	63,313.80	36,650.00	26,663.80	42.11
+ GST 7.00/7.00% (S\$)	4,431.97	2,565.50	1,866.47	42.11
Nett Amount (S\$)	67,745.77	39,215.50	28,530.27	42.11

INSPECTION

Date of Assignment:	21/08/2017 Present Location:	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)
Date Inspected:	22/08/2017 Inspected At:	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer) Blk 3 Pioneer Road North, #01-18 Singapore 628457
Estimated Period of Repair:	24.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 12 Dec 2018)	
Parts:	N/A	HINO XZU710R-HKFMS3 4.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YN7881H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER (WCP)	Deformed	950.00 F	*950.00 F
2	1		*FRT BUMPER SIDE BRACKET (WCP)	N/S Not Necessary/O/S Bent	560.00 F	*280.00 F
3	1		*FRT FOGLAMP(RH) (WCP)	Missing	275.00 F	*275.00 F
4	1		*FRT FOGLAMP HOLDER(RH) (WCP)	Distorted	50.00 F	*50.00 F
5	1		*FRT HEADLAMP (WCP)	N/S Not Necessary/O/S Cracked	2,200.00 F	*1,100.00 F
6	1		*FRT GRILLE (WCP)	Missing	575.00 F	*575.00 F
7	10		*FRT GRILLE CLIPS (WCP)	Necessary	30.00 F	*30.00 F
8	1		*FRT GRILLE EMBLEM (WCP)	Necessary	68.00 F	*68.00 F
9	1		*FRT CORNER PANEL(RH) (WCP)	Missing	550.00 F	*550.00 F
10	1		*FRT CORNER PANEL SEAL(RH) (WCP)	Necessary	30.00 F	*30.00 F
11	1		*SIDE MIRROR ARM(RH) (WCP)	Bent	255.00 F	*255.00 F
12	1		*SIDE MIRROR ARM ROUND CAP(RH) (WCP)	Missing	12.00 F	*12.00 F
13	1		*SIDE MIRROR(RH) (WCP)	Cracked	28.00 F	*28.00 F
14	1		*SIDE MIRROR ARM TOP SEAL(RH) (WCP)	Missing	25.00 F	*25.00 F
15	1		*SIDE MIRROR ARM (LH) (WCP)	Bent	265.00 F	*265.00 F
16	1		*SIDE MIRROR(LH)(ROUND) (WCP)	Missing	15.00 F	*15.00 F
17	1		*SIDE MIRROR(LH) (WCP)	Cut	30.00 F	*30.00 F
18	1		*FRT WINDSCREEN WITH MOULDING (WCP)	Necessary	1,350.00 F	*1,350.00 F
19	1		*FRT WINDSCREEN SEALANT	Necessary	40.00 FS	*40.00 FS
20	1		*ERP BRACKET	Necessary	26.00 FS	*26.00 FS
21	1		*FRT ROOF TOP LAMP(RH) (WCP)	Missing	140.00 F	*140.00 F
22	1		*FRT ROOF ANTENNA (WCP)	Bent	95.00 F	*95.00 F
23	1		*FRT ROOF TOP PANEL SIDE (RH) (WCP)	Buckled	400.00 F	*400.00 F
24	1			Bent	470.00 F	*470.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
			*FRT ROOF TOP PANEL AT REAR (WCP)			
25	1		*FRT CABIN ROOF LINING (WCP)	Deformed	300.00 F	*300.00 F
26	1		*FRT CABIN REAR GLASS MOULDING (WCP)	Necessary	80.00 F	*80.00 F
27	1		*FRT CABIN REAR PANEL (WCP)	Bent	850.00 F	*850.00 F
28	1		*FRT CABIN REAR SUPPORT (WCP)	Bent	1,050.00 F	*1,050.00 F
29	2		*FRT CABIN REAR LOCK (WCP)	Not Necessary	600.00 F	*- F
30	1		*FRT CABIN REAR LOCK LATCH(LH) (WCP)	Not Necessary	105.00 F	*- F
31	2		*FRT CABIN REAR LOCK HOOK (WCP)	Not Necessary	110.00 F	*- F
32	2		*FRT CABIN REAR LOCK HOOK PLATE (WCP)	Not Necessary	240.00 F	*- F
33	2		*FRT CABIN REAR MOUNTING BUSH (WCP)	Not Necessary	160.00 F	*- F
34	1		*FRT WHEEL ARCH PANEL(RH) (WCP)	Deformed	370.00 F	*370.00 F
35	1		*FRT WHEEL ARCH PANEL RR RUBBER SEAL(RH) (WCP)	Deformed	40.00 F	*40.00 F
36	1		*ROCKER PANEL(RH) (WCP)	Buckled	355.00 F	*355.00 F
37	1		*ROCKER PANEL SCUFF PLATE(RH) (WCP)	Deformed	150.00 F	*150.00 F
38	1		*FRT TYRE REAR MUDGUARD(RH) (WCP)	Deformed	200.00 F	*200.00 F
39	1		*FRT DOOR(RH) (WCP)	Bent	1,100.00 F	*1,100.00 F
40	2		*FRT DOOR HINGE(RH) (WCP)	Not Necessary	280.00 F	*- F
41	1		*FRT DOOR CHECKER(RH) (WCP)	Not Necessary	85.00 F	*- F
42	1		*FRT DOOR GLASS RUN CHANNEL(RH) (WCP)	Missing	150.00 F	*150.00 F
43	1		*FRT DOOR GLASS INNER MOULDING (WCP)	Deformed	60.00 F	*60.00 F
44	1		*FRT DOOR GLASS OUTER MOULDING (WCP)	Deformed	65.00 F	*65.00 F
45	1		*FRT DOOR GLASS REGULATOR (WCP)	Bent	200.00 F	*200.00 F
46	1		*FRT DOOR GLASS REGULATOR MOTOR (WCP)	Not Necessary	245.00 F	*- F
47	1		*FRT DOOR OUTER HANDLE (WCP)	Cracked	60.00 F	*60.00 F
48	1		*FRT DOOR 616 STICKER (WCP)	Necessary	70.00 F	*70.00 F
49	1		*FRT DOOR EURO 5 STICKER (WCP)	Necessary	45.00 F	*45.00 F
50	1		*FRT DOOR INNER TRIMBOARD(RH) (WCP)	Deformed	460.00 F	*460.00 F
51	1		*FRT DOOR WEATHERSTRIPE(RH) (WCP)	Necessary	165.00 F	*165.00 F
52	1		*FRT DOOR LOCK(RH) (WCP)	Jammed	200.00 F	*200.00 F
53	1		*FRT DOOR SEAL @ FRT (WCP)	Necessary	60.00 F	*60.00 F
54	1		*FRT DOOR LOWER GARNISH(RH) (WCP)	Deformed	100.00 F	*100.00 F
Report was unsubmitted during this print-out.						

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
55	1		*FRT DOOR LAMP(RH) (WCP)	Cracked	70.00 F	*70.00 F
56	1		*FRT STEP GARNISH(RH) (WCP)	Cut	360.00 F	*360.00 F
57	1		*REAR DOOR PILLAR(RH) (WCP)	Buckled	980.00 F	*980.00 F
58	1		*DASHBOARD ASSY (WCP)	Distorted	550.00 F	*550.00 F
59	1		*DASHBOARD SIDE COVER LOWER(RH) (WCP)	Not Necessary	170.00 F	*- F
60	1		*DASHBOARD SIDE COVER TOP (WCP)	Not Necessary	300.00 F	*- F
61	1		*DASHBOARD GLOVE BOX (WCP)	Deformed	340.00 F	*340.00 F
62	1		*DASHBOARD SPEAKER COVER(RH) (WCP)	Deformed	100.00 F	*100.00 F
63	1		*DASHBOARD BRAKE TANK OUTER COVER(RH) (WCP)	Deformed	100.00 F	*100.00 F
64	1		*DASHBOARD RADIO OUTER TRIM (WCP)	Cracked	250.00 F	*250.00 F
65	1		*FRT DOOR PILLAR HANDLE NUT COVER RH (WCP)	Distorted	5.00 F	*5.00 F
66	1		*DASHBOARD CUP HOLDER RH (WCP)	Not Necessary	160.00 F	*- F
67	1		*DASHBOARD SPEEDOMETER OUTER TRIM (WCP)	Distorted	168.00 F	*168.00 F
68	1		*AIR CON BLOWER COOLING COIL ASSY (WCP)	Cracked	1,650.00 F	*1,650.00 F
69	1		*HEATER COOLING COIL ASSY (WCP)	Not Necessary	550.00 F	*- F
70	1		*AIR INTAKE DUCT (WCP)	Deformed	350.00 F	*350.00 F
71	1		*AIR INTAKE HOSE (WCP)	Deformed	100.00 F	*100.00 F
72	1		*AIR CLEANER BOX ASSY (WCP)	Cracked	400.00 F	*400.00 F
73	1		*AIR CLEANER BOX AIR FLOW HOSE (WCP)	Deformed	120.00 F	*120.00 F
74	1		*FRT RIM RH	Bent	200.00 FS	*200.00 FS
75	1		*FRT TYRE RH	Punctured	180.00 FS	*180.00 FS
76	1		*FRT SHOCK ABSORBER RH (WCP)	Not Necessary	280.00 F	*- F
77	1		*FRT KNUCKLE ARM RH (WCP)	Not Necessary	600.00 F	*- F
78	1		*FRT WHEEL HUB RH (WCP)	Not Necessary	125.00 F	*- F
79	1		*FRT WHEEL HUB BEARING RH (WCP)	Not Necessary	100.00 F	*- F
80	1		*FRT AXLE (WCP)	Not Necessary	2,200.00 F	*- F
81	1		*FRT EXHAUST PIPE (WCP)	Not Necessary	550.00 F	*- F
82	1		*ERG COOLER REAR HEAT SHIELD COVER TYPO: EGR COOLER REAR HEAT SHIELD COVER (WCP)	Bent	195.00 F	*195.00 F
83	2		*ENGINE MOUNTING @ FRT (WCP)	Not Necessary	260.00 F	*- F
84	2		*GEAR BOX MOUNTING (WCP)	Not Necessary	200.00 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
85	1		*REAR NUMBER PLATE	Bent	15.00 FS	*15.00 FS
86	2		*REAR NUMBER PLATE LAMP (WCP)	Cracked	80.00 F	*80.00 F
87	1		*REAR NUMBER PLATE BRACKET (WCP)	Bent	85.00 F	*85.00 F
88	2		*REAR TAIL LAMP (WCP)	Cracked	320.00 F	*320.00 F
89	2		*REAR TAIL LAMP PANEL (WCP)	Bent	240.00 F	*240.00 F
90	1		*REAR BUMPER	Bent	350.00 FS	*350.00 FS
91	2		*REAR BUMPER SIDE BRACKET	Bent	360.00 FS	*360.00 FS
92	1		*REAR CHASSIS FRAME END CROSSMEMBER	Bent	180.00 FS	*180.00 FS
93	1		*REAR SPARE TYRE RIM (WCP)	Missing	180.00 F	*180.00 F
94	1		*REAR SPARE TYRE	Missing	200.00 FS	*200.00 FS
95	1		*REAR SPARE TYRE BRACKET (WCP)	Bent	250.00 F	*250.00 F
96	1		*REAR SPARE TYRE SUPPORT PANEL (WCP)	Bent	480.00 F	*480.00 F
97	1		*REAR WOODEN DECK ASSY (WCP)	Cracked	6,500.00 F	*6,500.00 F
98	1		*REAR WOODEN STEP PANEL	Cracked	100.00 FS	*100.00 FS
99	2		*REAR CHASSIS FRAME TOP BEAM	Bent	1,600.00 FS	*1,600.00 FS
100	11		*REAR CHASSIS FRAME WOODEN CROSSMEMBER BEAM	Cracked	3,080.00 FS	*3,080.00 FS
101	6		*REAR CHASSIS FRAME U BOLT SET	Bent	360.00 FS	*360.00 FS
102	1		*REAR TAILGATE 60KM/H STICKER	Necessary	10.00 FS	*10.00 FS
103	1		*REAR TAILGATE PAX STICKER	Necessary	10.00 FS	*10.00 FS
104	1		*REAR DECK FRT WOODEN RAILING (WCP)	Cracked	350.00 F	*350.00 F
105	2		*REAR DECK SIDE WOODEN RAILING LH (WCP)	Missing	700.00 F	*700.00 F
106	2		*REAR DECK SIDE WOODEN RAILING RH (WCP)	Missing	700.00 F	*700.00 F
107	1		*REAR RIM	N/S Not Necessary/O/SBent	360.00 FS	*180.00 FS
108	1		*REAR TYRE	N/S Not Necessary/O/SPunctured	400.00 FS	*200.00 FS
109	1		*REAR WHEEL SHAFT(RH) (WCP)	Not Necessary	850.00 F	*- F
110	2		*REAR WHEEL HUB (WCP)	Not Necessary	2,100.00 F	*- F
111	2		*REAR WHEEL HUB BEARING (WCP)	Not Necessary	130.00 F	*- F
112	1		*REAR SHOCKABSORBER(RH)	Not Necessary	270.00 FS	*- FS
113	1		*REAR DIFFERENTIAL PROPELLER SHAFT (WCP)	Not Necessary	1,800.00 F	*- F
114	2		*REAR MUDGUARD (WCP)	Deformed	700.00 F	*700.00 F
115	2		*REAR MUDGUARD LOWER MUD FLAP (WCP)	Missing	60.00 F	*60.00 F
Supplementary #1						
116	1		*AIR CLEANER BOX BRACKET (WCP)	Bent	95.00 F	*95.00 F
117	1		*FRT CABIN BRACKET (WCP)	Bent	1,250.00 F	*1,250.00 F
118	1		*FRT WINDSCREEN INNER TRIM (RH) (WCP)	Deformed	60.00 F	*60.00 F
119	1		*REAR DECK CANOPY ASSY	Missing	2,200.00 FS	*2,200.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
120	1		*DIESEL RETURN HOSE (WCP)	Bent	120.00 F	*120.00 F
121	1		*CABIN TILT SENSOR (WCP)	Distorted	325.00 F	*325.00 F

F=Franchise part. S=SpcNett.

	Sub Total (\$\$)	54,877.00	40,647.00
+ Margin on L,N Items	5.00/5.00% (\$\$)	2,246.80	1,567.80
	Total Parts (\$\$)	57,123.80	42,214.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO LIFT UP REAR DECK	New	400.00	300.00
2	TO KNOCK FRT PANEL,FRT DOOR PILLAR(RH),ROOF TOP PANEL,WELD,REMOVE & FIX ABOVE PARTS	New	1,500.00	1,200.00
3	TO SPRAY PAINTING ON FRT BUMPER,FRT DOOR PILLAR (RH),FRT DOOR(RH),ROOF TOP PANEL,FRT CABIN REAR PANEL,FRT WHEEL ARCH PANEL(RH),ROCKER PANEL (RH),REAR BUMPER,REAR CHASSIS & AFFECTED AREA	New	1,800.00	1,500.00
4	TO KNOCK,WELD,JACK,STRAIGHTEN CHASSIS FRAME	New	1,300.00	800.00
5	TO CHECK WIRING,FOCUS HEADLAMP	New	20.00	20.00
6	TO REMOVE & REFIT DOOR TRIM,DOOR GLASS,WINDOW REGULATOR	New	60.00	40.00
7	TO REMOVE & REFIT FRT CABIN REAR GLASS	New	100.00	100.00
8	TO REMOVE & REFIT INNER SEAT & UPHOLSTERY TO ASSIST WORK LOAD	New	100.00	60.00
9	TO REMOVE & REFIT ROOF LINING, INNER TRIM TO ASSIST WORK LOAD	New	80.00	60.00
10	TO REMOVE & REFIT EXHAUST SYSTEM TO ASSIST WORK LOAD	New	150.00	100.00
11	TO REMOVE & REFIT UNDERCARRIAGE TO ASSIST WORK LOAD	New	400.00	300.00
12	TO DO WHEEL ALIGNMENT	New	80.00	80.00
13	TO APPLY ANTI RUST COATING	New	200.00	120.00
Gross Labour Cost (\$\$)			6,190.00	4,680.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >