

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 166P

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BUMPER COVER REAR (CONSISTENT)	BUCKLED	1,108.46	1,108.46
1	BUMPER LOWER REAR (CONSISTENT)	SERVICEABLE	768.84	-
1	BUMPER BRACKET CTR REAR (CONSISTENT)	SERVICEABLE	113.47	-
1	BUMPER BRACKET SIDE RH REAR (CONSISTENT)	SERVICEABLE	135.97	-
1	BUMPER BRACKET CTR RH REAR (CONSISTENT)	SERVICEABLE	44.99	-
1	BUMPER REFLECTOR RH (CONSISTENT)	SERVICEABLE	43.61	-
1	BUMPER BEAM REAR (CONSISTENT)	TO REPAIR SEE LABOUR	777.52	-
1	BUMPER BEAM BRACKET RH REAR (CONSISTENT)	TO REPAIR SEE LABOUR	225.95	-
1	FENDER PANEL REAR RH (CONSISTENT)	BENT	3,299.13	3,299.13
1	WHEELARCH REAR RH (CONSISTENT)	SERVICEABLE	543.47	-
1	FENDER PANEL HOUSE PANEL REAR RH (CONSISTENT)	TO REPAIR SEE LABOUR	3,039.04	-
1	KUCKLE ARM REAR RH (CONSISTENT)	SERVICEABLE	736.67	-
1	ABSORBER REAR (CONSISTENT)	SERVICEABLE	389.75	-
1	LOWER ARM REAR RH (CONSISTENT)	SERVICEABLE	905.99	-
1	TAILLAMP PANEL RH (CONSISTENT)	SERVICEABLE	986.70	-
1	AIR VENT (CONSISTENT)	SERVICEABLE	97.29	-
1	BOOT REAR (CONSISTENT)	TO REPAIR SEE LABOUR	2,872.68	-
1	BOOT FINISHER (CONSISTENT)	SERVICEABLE	470.06	-
1	BOOT WEATHERSTRIP (CONSISTENT)	SERVICEABLE	323.05	-
1	BOOT REFLECTOR LAMP RH (CONSISTENT)	SERVICEABLE	493.35	-
1	BOOT BADGE 'RENAULT'(CONSISTENT)	NOT NECESSARY	225.36	-
1	BOOT BADGE (CONSISTENT)	NOT NECESSARY	225.36	-
1	SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL) (CONSISTENT)	TO REPAIR SEE LABOUR	2,189.88	-
1	EXHAUST REAR (CONSISTENT)	TO REPAIR SEE LABOUR	7,488.00	-
1	EXHAUST CAP REAR (CONSISTENT)	TO REPAIR SEE LABOUR	230.49	-
1	ROCKER PANEL OUTER RH (CONSISTENT)	TO REPAIR SEE LABOUR	987.49	-

Report Ref No. CC3/ASM17016220/Kps3q2



## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	DOOR PANEL REAR RH (CONSISTENT)	TO REPAIR SEE LABOUR	2,844.66	-
	LESS 10% DISCOUNT		-3,156.72	-440.76
			28,410.51	3,966.83
	SPECIAL NETT ITEMS			
1	SET PARKING AID (SN) (CONSISTENT)	SERVICEABLE	600.00	-
1	SET REAR BUMPER CLIP (SN) (CONSISTENT)	NECESSARY	66.00	66.00
1	SET BUMPER BRACKET CTR CLIP (SN) (CONSISTENT)	NECESSARY	33.00	33.00
1	SET BUMPER BRACKET SIDE CLIP RH RR (SN) (CONSISTENT)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER RH CLIP RR (SN) (CONSISTENT)	NOT NECESSARY	20.00	-
1	SET BUMPER LOWER REAR CLIP (SN) (CONSISTENT)	NOT NECESSARY	66.00	-
1	SET BUMPER BEAM BOLT (SN) (CONSISTENT)	SERVICEABLE	33.00	-
1	SET WHEELARCH CLIP REAR RH (SN) (CONSISTENT)	NOT NECESSARY	45.00	-
2	REAR WINDSCREEN SEALANT (SN) (CONSISTENT)	NECESSARY	80.00	40.00
1	REAR WINDSCREEN INNER SPONGE SEAL (SN) (CONSISTENT)	NECESSARY	150.00	30.00
1	RIM (ROUE 7J 16H 2547) RH RR (SN) (CONSISTENT)	SERVICEABLE	385.00	-
1	TYRE RH RR (SN) (CONSISTENT)	SERVICEABLE	330.00	-
1	CAP HUB RH REAR (SN) (CONSISTENT)	SERVICEABLE	35.60	-
1	DOOR STICKER '6555-3333' (SN) (CONSISTENT)	NECESSARY	80.00	60.00
1	BOOT STICKER 'TRANS-CAB' (SN) (CONSISTENT)	NOT NECESSARY	30.00	-
1	BOOT STICKER '6555-3333' (SN) (CONSISTENT)	NOT NECESSARY	30.00	-
1	EXHAUST MOUNTING REAR (SN) (CONSISTENT)	SERVICEABLE	65.50	-
1	EXHAUST BRACKET REAR (SN) (CONSISTENT)	TO REPAIR SEE LABOUR	22.22	-
			2,081.32	229.00
	LABOUR			
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION .		3,000.00	700.00

Report Ref No. CC3/ASM17016220/Kps3q2



## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF BUMPER BEAM REAR,BUMPER BEAM BRACKET RH REAR,FENDER WHEEL HOUSE PANEL REAR RH,BOOT REAR,SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL),EXHAUST REAR,EXHAUST CAP REAR,ROCKER PANEL OUTER RH,DOOR PANEL REAR RH AND EXHAUST BRACKET REAR.		2,800.00	660.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	30.00
	TO REINSTALL REAR BUMPER PARKING SENSOR .		170.00	60.00
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
	TOWING FEES.	NOT NECESSARY	120.00	-
	TO TRANSFER OF REAR FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.		380.00	100.00
	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST.		170.00	120.00
	TO REPAIR AND REALIGN REAR EXHAUST PIPE.	NOT NECESSARY	170.00	-
	TO DISMANTLE AND REFIT REAR UNDERCARRIAGE PARTS ,FINAL CHECKING AND TESTING.	NOT NECESSARY	380.00	-
			7,750.00	1,670.00
	GRAND TOTAL		38,241.83	5,865.83

RECOMMENDED COST OF REPAIRS 5,865.83

Report Ref No. CC3/ASM17016220/Kps3q2

KONG SENG CHEONG

Licensed Appraiser