

22/02/2002

ASS. REC. BY:

REF: CS/FCI17017038 /Grbn2

Special Instructions:

Surveyor: cws

AR

ASSIGNMENT (Office)

From (Person): Sitharaof FCIDate/Time: 4/9/17 1.03pm

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: FBJ 5155CInsured: SHA 00714at Workshop m/s OUR BRO'STel: 66361338of 10 kaki Bukit Rd 2 # 03-37/38

Policy No:

Claim No: D17008346 MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A. 26/08/2017

(Client's Record)

CA / REV / REP. / REV 24 HRS

'wp'

H.O.D. Endorsement:

Date/Time: 4/9/17 1.47pmPerson Contacted: SyafirahVehicle IN OUT

Date/Time	Action/Instruction (✓) Estimate
	FBJ 5155C - NS/INC17016686/K1th: D.O.A: 26/08/2017
	SHA 00714 - X

Signature: Xiel

ASSIGNMENT

From:

Date: 05/09/2017

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

FBJ 5155C

at Workshop m/s

Our Bro's

of

10 Kaka Bukit Rd 2 # 03-37

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

FBJ 5155 C

Yr Regn: 19 Dec 2013

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

KTM 390 Duke c.c 373

Colour:

orange

A/C: Insured / Std / NI / NA

Sp. Reading

500/6

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

VBKIGT407DC 215 491

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

120/70-17

R:

150/70-17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

TIM SUN

Front

Rear

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

D.O.I.

05-09-17

Survey held at

W/S

5:30pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

And

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

6/9/17

email to sithara - pending est from wksp.

09/7

Finalized \$ 3600 with Mami (Red 6253.50, 6370)

RECEIVED 0 10 2018

Date/Time, File Pass to?



Preli. Report

1)



Final Report

Date/Time, File Return to?

2)

Days Of Repair:

4

Resurvey No. of Trip:

2

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format:

TP

Lump Sum / I.B.I: (\$ 3600)

170

50

50+50

114

434

Survey Department Check List (Case Handler)

Reference No. : CS/EC117017038/Grb
Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (Catherine): Case handler to make sure all Information created by the assignment team are ACCURATE.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code	✓			
N	Assign From	✓			
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No				
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (Guo Qiang): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By:

Catherine

Case Handler

Date

9/7/18

*C: Critical *N: Non-Critical

21/05/201



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI17017038/Ggb	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 04-09-2017	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHA 0071U	Veh. Inspected	FBJ 5155C
Policy No.		Coverage (\$)	0.00
Claim No.	D17008346MFSH	Excess (\$)	0.00
Assign From	CWS (SITHARA)	Assign Date	04/09/2017
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	26/08/2017	Inspection Date	
Survey held at	OUR BRO'S WORKSHOP 10 KAKIT BUKIT ROAD 2 #03-37/38 FIRST EAST CENTRE SINGAPORE 417868		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C
GST Reg. No. M2-0001676-9

MOTOR SURVEY ASSIGNMENT

Date	29-08-2017	Our Ref No. D17008346MFSH
Accident Date	26-08-2017	Claim Type. Third Party
Insured Vehicle	SHA0071U	Third Party Vehicle. FBJ5155C
Survey Location	10 Kaki Bukit Road 2 #03-37/38 First East Centre	
Contact Person.	NUR SYAFIRAH JASNI	
Contact No.	66361338/ 0	Fax No. 66361339
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	OUR BRO'S WORKSHOP (S) PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SITHARA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/227471)



PRI Documents



Close X

PRI Header Details

Claim No	D17008346MFSH	Policy No	D-15072702MFSH	Claimant S.No & Name	1 & OUR BRO'
Workshop Name	OUR BRO'S WORKSHOP (S) PTE LTD (Contact Person : NUR SYAFIRAH JASNI)	Survey Location & Contact Details	10 Kaki Bukit Road 2 #03-37/38 First East Centre Mobile: 0 , Phone: 66361338 , Fax: 66361339 EmailId: SYAFIRAHOBW@YAHOO.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE:		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHA0071U	TP Vehicle No	FBJ5155C
PRI Recieved Date	31-08-2017 08:01:12 PM	Surveyor Appointed Date	04-09-2017 01:04:09 PM	Surveyor Accept Date	04-09-2017 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	04-09-2017	Upload Survey Report *:	Choose File
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Ai Phing (LKKAuto)

From: Ai Phing (LKKAuto)
Sent: Wednesday, 6 September, 2017 5:06 PM
To: 'Claim Workflow System'
Cc: SITHARA@FIRST-INSURANCE.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D17008346MFSH/1

Dear Sithara,

Please be informed that we have inspected the vehicle FBJ 5155C on 05-09-2017.
We are pending estimate from repairer.

Best Regards,

Ai Phing | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #01-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Monday, 4 September, 2017 1:51 PM
To: 'Claim Workflow System' <cwsmotorclaims@first-insurance.com.sg>; assignments <assignments@lkkauto.com>
Cc: SITHARA@FIRST-INSURANCE.COM.SG; SUR <sur@lkkauto.com>; assignments@lkkauto.com'
Subject: RE: SURVEY ASSESSMENT - D17008346MFSH/1

Dear Sithara,

Thank you for the Assignment.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@first-insurance.com.sg>]
Sent: Monday, 4 September, 2017 1:03 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG; SITHARA@FIRST-INSURANCE.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D17008346MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type	Singapore NRIC
Owner ID	7226C
Vehicle Details	
Vehicle No.	FBJ5155C
Vehicle to be Exported	No
Intended De-registration Date	30 Nov 2017
Vehicle Make	K.T.M.
Vehicle Model	390 DUKE
Primary Colour	White
Manufacturing Year	2013
Engine No.	390204333
Chassis No.	VBKJGJ407DC215491
Maximum Power Output	-
Open Market Value	\$6,144.00
Original Registration Date	19 Dec 2013
First Registration Date	30 Jun 2014
Transfer Count	1
Actual ARF Paid	\$922.00
Intended PARF Rebate Details	
PARF Eligibility	No
PARF Eligibility Expiry Date	-
PARF Rebate Amount	\$0.00
Intended COE Rebate Details	
COE Expiry Date	29 Jun 2024
COE Category	D - Motorcycle
COE Period(Years)	10
QP Paid	\$3,890.00
COE Rebate Amount	\$2,559.00
Total Rebate Amount	\$2,559.00

The information contained herein is correct as at 30 Nov 2017

OK



KTM 390 Duke \$11,000 14 Feb 2014 Street Bikes
 Engine Capacity: 373 Giving up riding and switching to car. Well maintained. Always parked indoor. Valve clearance done. Condition 9/10. Last service May 2017 Bike fully paid. Come with bided number *8*8 Hella horn. New Pirelli Diablo Rosso III tyre F/R May 2017. Posted: 3 Sep 2017 **★ PAID AD**

DIRECT OWNER



KTM 390 Duke \$11,800 21 Feb 2014 Street Bikes
 Engine Capacity: 373 Previous owner upgrade bike. Used for work. Decent condition. Loan/cash package available. Trade in are welcome. Interested parties are welcome to view. No test ride. Street Legal zard exhaust with cert. Posted: 8 Aug 2017 **★ PAID AD**

DEALER AD



KTM 390 Duke \$12,300 13 Jan 2015 Street Bikes
 Engine Capacity: 373 KTM 390 Duke available. Good conditions. Power parts are changed. Original parts keep as spare. Interested will be appropriated can be arranged appointment for viewing. Original spare parts available to handover with bike. Posted: 31 Aug 2017 **DIRECT OWNER**



KTM 390 Duke - 7 Oct 2013 Street Bikes
 Engine Capacity: 373 KTM 390 Duke for sale! AS Phoon is Singapore's Leading Motorcycle Dealer! Trade In. Loan Available. NO Hidden Cost. NO Agreement Fees.. NO Early Repayment Penalty. Find Us At 399 Changi Road, Singapore 419846. Posted: 4 Aug 2017 **★ PAID AD** **DEALER AD**

SOLD

Sketch Plan #0 Pg. 1

Policy Information

Page 1 of 1

Policy Information

Policy No.	5073758143-01	Policyholder Name	JAMAL BIN KAMIS	Policyholder Address	55007226C
Address	BLK 329 407-1036 FREE HOLD 2 AVENUE 3 SINGAPORE 111329				
Product Name	MOBILITYVUE INSURANCE	Plan		Group Policy Flag	0
Policy Issue Date	12/12/2016	Effective Date	01/12/2016	Expiry Date	29/11/17 23:59
Third Party Excess	0	Own Damage Excess	0	Uninsured Excess	
Additional Excess		CG Premium	0		
Outside Singapore On Excess		Outside Singapore TP Excess			
Agent	ASSURE PTE. LTD.	Agent Tel	65489119	BSY Flag	0
Co-Insurance Flag	No				
Open Policy Info					
Certificate Info					

Policyholder Mailing Address

Address 1	BLK 329 407-2536	Address 2	MOBILITYVUE/2536	Address 3	SINGAPORE 111329
Address 4		Address Type	Singapore Street	Post Code	111329
Unit No.	01-2056	Related Policy Number	02377600-01		

Insured Object: PASSENGER

Vehicle No.	FF051500	Model	ISOLAR	Color	GRY
Vehicle Type	404	Date of Registration	4/12/2016		
Chassis No.	V0001210700215498	Engine No.	05020433	Vehicle Capacity	370
No. of Seats	2	Parallel Import	0	Imported/Reimported	0
Old park car					

Coverage		Coverage Amount	Self Insured	Excess (deductible)	Maximum
Third Party, Fire & Theft	Own Damage by Fire		95,539,599.00		
Third Party, Fire & Theft	Loss or Own Damage by Theft		95,539,599.00		
Third Party, Fire & Theft	TP		45,959,899.00		
Third Party, Fire & Theft	TPPI		000,000.00		
Third Party, Fire & Theft	Third Party Fire & Theft Excess		9,455,959,899.00		
Owner Name	IC No.	Date of 1st	Driving License Reg. No.	Use	
JAMAL BIN KAMIS	55007226C	01/12/1989	57612610	Main Driver	

Endorsements

Sequence	Date of Endorsement	Endorsement Type	Endorsement Amount	Endorsement Details
[Continue] [Cancel]				



6 tampines st 73, #01-03, singapore 528825
tel: 6746 2118 fax: 6746 1148
reg no: 53058468m

Insured	:	-
Policy No.	:	-
Sum Insured	:	-
Excess	:	-
Our Reference	:	KAAS/TA/4743/5155/TP/08.17
Date	:	17 September 2017

To: Jamal Bin Kamis
c/o 10 Kaki Bukit Road 2
#03-37/38
First East Centre
Singapore 417868

VEHICLE APPRAISAL REPORT

Name of Workshop	:	Our Bro's Workshop (S) Pte Ltd
Place of inspection	:	10 kaki Bukit Road 2 #03-37/38, First East Centre, Singapore 417868
Date of Assignment	:	05 September 2017
Date of Accident	:	26 August 2017
Date of Inspection	:	05 September 2017

PARTICULARS OF INSPECTED VEHICLE

Registration No.	:	FBJ 5155C	Engine No.	:	HIDDEN FROM VIEW
Make/Model	:	KTM 390 Duke	Chassis Frame No.	:	VBKJGJ407DC215491
Year of Manufacture/Reg	:	2014	Colour	:	Orange
Class/Type	:	Motorcycle	Odometer Reading	:	50,016 KM

CONDITION OF VEHICLE DURING SURVEY (Visual & Static Check Only)

General Condition	:	Good	Undercarriage (Front)	:	Serviceable
Paintwork	:	Good	Undercarriage (Rear)	:	Serviceable
Footbrakes	:	Serviceable	Market Value	:	-
Steering	:	Serviceable	Scrap Value (PARF/OMV)	:	-

CONDITION OF TYRES ON VEHICLE

	<u>Make/Size</u>	<u>Thread Balance</u>
Front Left	TIMSUN 120 / 70 - 17	8mm
Rear Left	TIMSUN 150 / 70 - 17	8mm
Front Right	TIMSUN 120 / 70 - 17	8mm
Rear Right	TIMSUN 150 / 70 - 17	8mm

*The above is an estimate of the remaining life of the tyre thread in millimeters

The information contained in these documents may be privileged and confidential, and is intended for the exclusive use of the addressee designation. If you are not the addressee, any enclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this survey report in error, please contact us immediately by phone so that we can arrange for its return.



Our Reference
Vehicle Number

: KAAS/TA/4743/5155/TP/08.17
: FBJ 5155C

6 tampines st 73, #01-03, singapore 528825
tel: 6746 2118 fax: 6746 1148
reg no: 53058468m

APPRAISEMENT SCHEDULE




S/N	Qty	Descriptions	Comments/ Conditions	Repairer's Estimate	Revised Amount
		LIST ITEMS:-			
1	1 pc	Front fender	Deformed	\$ 210.40	\$ 210.40
2	1 pair	Front fork assy	Buckled	\$ 1,340.00	\$ 1,340.00 } NN
3	1 pc	Upper clamp	Buckled	\$ 756.10	\$ 756.10
4	1 pc	Under bracket	Broken	\$ 890.50	\$ 890.50
5	1 pc	Headlamp	Scratched	\$ 399.10	\$ 399.10
6	1 pc	Head fairing w/ windshield	Broken	\$ 231.20	\$ 231.20
7	1 pc	Handlebar	Buckled	\$ 294.70	\$ 294.70
8	1 pair	Handlebar guard w/ cover	Buckled	\$ 734.00	\$ 734.00
9	1 pair	Handlebar grip	Damaged	\$ 63.00	\$ 63.00
10	1 pair	Handlebar end	Buckled	\$ 52.50	\$ 52.50
11	1 pair	Wing mirror	Scratched	\$ 210.00	\$ 210.00
12	1 pc	LH clutch lever	Buckled	\$ 136.50	\$ 136.50
13	2 pcs	Radiator side garnish @S\$168.00	Scratched	\$ 336.00	\$ 336.00
14	1 pc	RH crankcase	Scratched	\$ 262.50	\$ 262.50
15	1 pc	LH side fairing	Deformed	\$ 157.50	\$ 157.50
16	1 pc	LH rider foot rest bracket	Buckled	\$ 152.30	\$ 152.30
17	1 pc	LH rider foot rest w/ pad	Deformed	\$ 73.50	\$ 73.50
18	1 pc	LH gear pedal	Buckled	\$ 89.20	\$ 89.20
19	1 pc	LH pillion rider foot rest bracket	Buckled	\$ 136.50	\$ 136.50
20	1 pc	LH pillion rider foot rest w/ pad	Deformed	\$ 73.50	\$ 73.50
21	1 pc	Rear handle grip	Scratched	\$ 50.00	Repair
22	1 pc	LH rear fairing	Deformed	\$ 189.00	\$ 189.00
			3801.4	\$ 6,838.00	\$ 6,788.00
		Less 10%	10% : 3421.26	\$ 6,838.00	\$ 6,788.00
		SPECIAL NETT ITEMS:-			
23	1 pc	Front wheel rim	Distorted	\$ 425.00	\$ 350 425.00
24	1 pc	Front tyre @ 50% depreciation	Scratched	\$ 360.00	\$ 100 180.00
25	1 pc	IU unit	Scratched	\$ 160.50	\$ 1 160.50
26	1 pc	Front no. plate	Buckled	\$ 60.00	\$ 15 50.00
27	1 pc	Rear no. plate	Buckled	\$ 60.00	\$ 15 50.00
28	1 set	Fairing decorative sticker	Necessary	\$ 300.00	\$ 200 300.00
				\$ 1,365.50	\$ 1,165.50
		Sub - Total		\$ 8,203.50	\$ 7,274.70

APPRAISEMENT SCHEDULE

S/N	Qty	Descriptions	Comments/ Conditions	Repairer's Estimate	Revised Amount
		B/F		\$ 8,203.50	\$ 7,274.70
		LABOUR & OTHER CHARGES:-			
1		To panel beat and renewal of all necessary damaged body parts		\$ 600.00	\$ 150 500.00
2		To check wiring and rewire		\$ 60.00	\$ NNX 50.00
3		To realign front fork		\$ 200.00	\$ 100 180.00
4		To perform body frame alignment		\$ 180.00	\$ X 150.00
5		To remove and reinstall fuel tank		\$ 120.00	\$ NNX X 90.00
6		To anti-rust		\$ 140.00	\$ X 120.00
7		To putty and spray-paint of affected areas		\$ 350.00	\$ X 300.00
				\$ 1,650.00	\$ 1,390.00
		4511.76 29%: 3600 4 Days.			
Sub - Total				\$ 9,853.50	\$ 8,664.70

ASSESSMENT SUMMARY

Damages sustained were consistent with the accident report.



(Please refer to the parts list and photographs as attached for more information)

ASSESSOR'S RECOMMENDATIONS

The estimated repair costs submitted by Messrs **Our Bro's Workshop (S) Pte Ltd** is \$ 9,853.50

We have adjusted the cost to \$ 8,664.70 and the repairer has agreed to undertake the repairs at a

Contract Lump Sum of \$ 7,350.00 to a acceptable quality and standards.

However, we have not given authorization and instruction to the repairer to proceed with the repairs.

The repairs should be completed within a reasonable period of **6** working days.

96 photographs were taken at the time of static inspection.

This report is strictly done in a **Without Prejudice Basis**.

We are reverting the matter to you a decision.

We enclose herewith our Invoice No. **4743** for our services rendered and
we thank you for engaging our services.

Kelvin Automotive Appraising Services



KELVIN TEO

Licensed Automotive Appraiser

Nitec in Automotive Technology

Dip MS

MSAAA

NOTE : This revised estimate was from a visual inspection. Should there be any discrepancy or unseen items not listed in this survey, kindly notify the company within Seven (7) days from the date hereof. Otherwise this revised amount shall be treated as valid.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI17017038/Grbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 10-07-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 71U	Veh. Inspected	FBJ 5155C	
Policy No.	D-15072702MFSH	Coverage (\$)	0.00	
Claim No.	D17008346MFSH	Excess (\$)	0.00	
Assign From	SITHARA	Assign Date	04/09/2017	
2. Vehicle Particulars & Condition				
Make & Model	K.T.M 390 DUKE	c.c	373	
Engine No.	HIDDEN	Year of Reg.	2013	
Chassis No.	VBKJGJ407DC215491	Colour	ORANGE	
Odometer	50016	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	120/70-17	TIMSUN	4 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	150/70-17	TIMSUN	4 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION,O/S AND N/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	26/08/2017	Inspection Date	05/09/2017	
Survey held at	OUR BRO'S WORKSHOP 10 KAKIT BUKIT ROAD 2 #03-37/38 FIRST EAST CENTRE SINGAPORE 417868			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBJ 5155C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT FENDER	DEFORMED	210.40	210.40
1	PAIR FRONT FORK ASSY	NOT NECESSARY	1,340.00	-
1	UPPER CLAMP	NOT NECESSARY	756.10	-
1	UNDER BRACKET	NOT NECESSARY	890.50	-
1	HEADLAMP	SCRATCHED	399.10	399.10
1	HEAD FAIRING W/WINDSHIELD	BROKEN	231.20	231.20
1	HANDLEBAR	BUCKLED	294.70	294.70
1	PAIR HANDLEBAR GUARD W/COVER	BUCKLED	734.00	734.00
1	PAIR HANDLEBAR GRIP	DAMAGED	63.00	63.00
1	PAIR HANDLEBAR END	BUCKLED	52.50	52.50
1	PAIR WING MIRROR	SCRATCHED	210.00	210.00
1	LH CLUTCH LEVER	BUCKLED	136.50	136.50
2	RADIATOR SIDE GARNISH @\$168.00	SCRATCHED	336.00	336.00
1	RH CRANKCASE	SCRATCHED	262.50	262.50
1	LH SIDE FAIRING	DEFORMED	157.50	157.50
1	LH RIDER FOOT REST BRACKET	BUCKLED	152.30	152.30
1	LH RIDER FOOT REST W/PAD	DEFORMED	73.50	73.50
1	LH GEAR PEDAL	BUCKLED	89.20	89.20
1	LH PILLION RIDER FOOT REST BRACKET	BUCKLED	136.50	136.50
1	LH PILLION RIDER FOOT REST W/PAD	DEFORMED	73.50	73.50
1	REAR HANDLE GRIP	TO REPAIR SEE LABOUR	50.00	-
1	LH REAR FAIRING	DEFORMED	189.00	189.00
	LESS 10% DISCOUNT		-	-380.14
			6,838.00	3,421.26
SPECIAL NETT ITEMS				
1	FRONT WHEEL RIM (SN)	DISTORTED	425.00	350.00
1	FRONT TYRE (SN)	SCRATCHED	360.00	100.00
1	IU UNIT (SN)	SCRATCHED	160.50	160.50
1	FRONT NO PLATE (SN)	BUCKLED	60.00	15.00
1	REAR NO PLATE (SN)	BUCKLED	60.00	15.00

Report Ref No. CS/FCI17017038/Grbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET FAIRING DECORATIVE STICKER (SN)	NECESSARY	300.00	200.00
			1,365.50	840.50
	LABOUR			
	TO PANEL BEAT AND RENEWAL OF ALL NECESSARY DAMAGED BODY PARTS.INCLUSIVE OF THE REPAIR OF REAR HANDLE GRIP.		600.00	150.00
	TO CHECK WIRING AND REWIRE.	NOT NECESSARY	60.00	-
	TO REALIGN FRONT FORK.		200.00	100.00
	TO PERFORM BODY FRAME ALIGNMENT.	NOT NECESSARY	180.00	-
	TO REMOVE AND REINSTALL FUEL TANK.	NOT NECESSARY	120.00	-
	TO ANTI-RUST.	NOT NECESSARY	140.00	-
	TO PUTTY AND SPRAY-PAINT OF AFFECTED AREAS.	NOT NECESSARY	350.00	-
			1,650.00	250.00
	GRAND TOTAL		9,853.50	4,511.76
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,600.00

Report Ref No. CS/FCI17017038/Grbn2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.