

22/03/2002

ASS. REC. BY:

REF:

CS/MSG17017088/RIGB 9/1

Special Instruction:

SURVJOY:  
MUMEN

RCAU

ASSIGNMENT (Office)

From (Person):

Catherine Thua

of

MSLI

Date/Time:

04/09/2017 5:20pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SDL 282S

Insured:

SKZ 5425H

at Workshop m/s

Performance

Tel:

6319 474

of

303 Alexandra Road

Policy No:

28875516QMY

Claim No:

528142

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

08/09/2017

CA / REV / REP. / REV 24 HRS WP

12-09-2017

H.O.D. Endorsement:

Date/Time:

04/09/2017 5:44pm

Person Contacted:

Caroline

Vehicle IN / OUT

Date/Time	Action/Instruction ( ✓ ) Estimate	Thua.
	SDL 282S - X	
	SKZ 5425H - X	
13/9/17 @	4.41m revised to Catherine Thua via Mumen.	
05/11/18 @	Rain Repair finished with Caroline final fig \$29676.65, 15 days.	
	(Ref # 7710.85, 21%)	

Rasul

REF:


60924

## ASSIGNMENT

From \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost \_\_\_\_\_  
 OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No. **SDL 282S**  
 at Workshop mis **PERFORMANCE**  
 of \_\_\_\_\_  
 Insured: **MSK**  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record) \_\_\_\_\_  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
 repair at the time of inspection.



Bal. or Market Value: **205K**  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: **15** days Res: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Date / Time Action / Instruction

Veh No: **SDL 282S** Yr Regn: **2013 July**  
 Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: **B.M.W 640 I Gran Coupe** c.c. **2979**  
 Colour: **BLACK** A/C: Insured / Std / NI / NA  
 Sp. Reading: **57776** T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: **WBA6A0200UDZ11598**  
 Gen. Cond: Good / ☒ Fair / Poor / Burnt  
 Steering: ☒ In order / Jammed / Leaked / Burnt or  
 Brake: ☒ In order / Jammed / Leaked / Burnt or  
 Modi: Nil / ☒ S/Rim / STD A/Rim or  
 Tyre Size F: **245/40R19**  
 R: **1**  
 BS / ☒ DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or \_\_\_\_\_  
 Front: \_\_\_\_\_ Rear: \_\_\_\_\_  
 R/Bal: **6** mm R/Bal: **6** mm  
 L/Bal: **6** mm L/Bal: **6** mm  
 D.O.A. **03/07/17** D.O.I. **13/09/17**  
 Survey held at: **PERFORMANCE**  
 Des. of Damages: Frt / Rear / O/S / ☒ N/S / U/C / Rooftop or  
**N/S**  
 The U/C / Chassis frame / Body Structure affected due to collision.

*[Signature]*  
 5/7/2018

RECEIVED 06 JUL 2018

Date/Time. File Pass to?

1) *05/7/2018*

Date/Time. File Return to?

2)

☐ : Preli. Report  
☐ : Final Report

Days Of Repair: **15**Resurvey No. of Trip: **1**

Survey Fee:

Transportation:

) \_\_\_\$ + RS \_\_\_\$

) Photos

) Others

)

TOTAL

Report Format :

Lump Sum / I.B.I. (\$) **29616.65**Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG17017088/R1qb

16 RAFFLES QUAY

#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 04-09-2017



Code : MSG

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKZ 5425H	Veh. Inspected	SDL 282S
Policy No.	28875516QMY	Coverage (\$)	0.00
Claim No.	528443	Excess (\$)	0.00
Assign From	MERIMEN (CATHERINE THIA)	Assign Date	04/09/2017

## 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	03/09/2017	Inspection Date	04/09/2017
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

## Shiau Chan (LKKAuto)

---

**From:** Rasul (LKKAuto)  
**Sent:** Thursday, 5 July 2018 9:00 AM  
**To:** PBSP  
**Cc:** SUR  
**Subject:** RE: FINAL REPORT / SDL2825

Hi Caroline,

Finalised amount of \$ 29,626.65 / 15 days P/P is confirmed

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933) Save the Earth. Print only when necessary.

-----Original Message-----

From: PBSP [mailto:pml-pbsp@simedarby.com.sg]

Sent: Wednesday, 11 April, 2018 12:27 PM

To: Rasul (LKKAuto); SUR

Subject: FINAL REPORT / SDL2825

Dear Rasul

We refer to the above and attached Final Report.

Please confirm COR as follows:

Total Labour : 15,049.00

Total Parts : 14,577.65

Total Labour & Parts : 29,626.65

Repair days: 15

Thank you.

Regards,

Caroline

C/o Performance Motors Limited - Body and Paint

303 Alexandra Road Singapore 159941

DID: 6319 0174 Fax: 6479 4601

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

**Note: This document has not been finalised.**

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Catherine Thia Shi Yi

Date: 13 Sep 2017

### Preliminary Advice

Insured Vehicle No	: SKZ5425H	Accident Date	: 03/09/2017
TP Vehicle No	: SDL282S	Assignment Date	: 04/09/2017
Make	: BMW 640i	Est. Duration of Repair	: 15.00
Date of Inspection	: 12/09/2017		
Inspection At	: PERFORMANCE MOTORS LIMITED (ALEXANDRA) 303 ALEXANDRA ROAD, SIME DARBY PERFORMANCE CENTRE SINGAPORE 159941		

### Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s body and portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	34,310.40
Revised Amount	:S\$	23,061.00
Check Items (Estimated)	:S\$	7,448.40
Total	:S\$	30,509.40

Lump Sum Repair	:S\$	
-----------------	------	--

### **Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

### Remarks

- ( ) The vehicle is economical/not economical for repair.
- ( X ) The above survey was conducted on a 'without prejudice' basis.

Text size + -

**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC

Owner ID: 0092H

**Vehicle Details**

Vehicle No.: SDL282S

Vehicle to be Exported: No

Intended De-registration Date: 13 Sep 2017

Vehicle Make: B.M.W.

Vehicle Model: 640i GRAN COUPE 4DR SR LED DSC NAV HUD

Primary Colour: Black

Manufacturing Year: 2013

Engine No.: 08208469N55B30A

Chassis No.: WBA6A02000DZ11598

Maximum Power Output: 235.0 kW (315 bhp)

Open Market Value: \$85,009.00

Original Registration Date: 22 Jul 2013

First Registration Date: 22 Jul 2013

Transfer Count: 0

Actual ARF Paid: \$125,017.00

**Intended PARF Rebate Details**

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 21 Jul 2023

PARF Rebate Amount: \$93,762.00

**Intended COE Rebate Details**

COE Expiry Date: 21 Jul 2023

COE Category: B - Car (1601cc &amp; above)

COE Period(Years): 10

QP Paid: \$76,389.00

COE Rebate Amount: \$44,724.00

**Total Rebate Amount: \$138,486.00**

205,000  
 138,486  
 -----  
 66,514

The information contained herein is correct as at 13 Sep 2017

OK

Land Transport Authority

Please read through the Privacy Statement, Terms of Use and Disclaimer.

Please do not use the **Back** or **Forward** buttons on your browser as this may alter the results of the transactions.

Best viewed with IE 8.0 SP3 and above, 1024 X 768 resolution

Copyright © 2017 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#) | [Rate this e-Service](#)  
 Last updated on 27 Aug 2017 at 01:09 AM

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	04/09/2017 10:24
Date Of Accident	03/09/2017 18:05
Exact Location Of Accident	JLN ANAK BUKIT TURNING INTO PIE CHANGI
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SDL282S
<b>Insured/Policyholder</b>	
Name Of Registered Owner	LEE KEK CHIN
NRIC No	S1450092H
Email Address	DBSACE123@GMAIL.COM
Mobile Phone No	(LOCAL) +65-97925278
Alternative Phone No	OFFICE-65345642
<b>Vehicle Particulars</b>	
Manufacturer	BMW
Model	640
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
<b>Insurance Company</b>	
Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	B27550199SMP
Cover Note Number	
<b>Driver</b>	
Name of Driver	LEE KEK CHIN
NRIC No	S1450092H
Date Of Birth	12/05/1960
Occupation	INDOOR
Date Of Driving Pass	30/05/1979
Driving Experience	38 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97925278
Fax Number	
Contact Number	OFFICE-65345642
EMail Address	DBSACE123@GMAIL.COM

Address  
 Postcode  
 Was driver an employee of the Insured's Company NO  
 If No, Relationship of the Driver with the Insured OWNER  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

#### General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR  
 Weather Conditions CLEAR  
 Road Surface DRY

#### Other Information

Was any foreign vehicle involved in this accident? NO  
 Was any body injured in the Accident? NO  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 1

#### Details of Police Action

Was the accident reported to the police? NO  
 If Yes, Please state which Police Station  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

#### Circumstances of Accident

REFER TO ATTACH.

#### Attachment(s)

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? NO  
 Was there any audio recorded? NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SKZ5425H  
 Vehicle Make/Model/Colour TOYOTA SILVER ALTIS  
 Details Of Properties  
 Name of Driver MILDRED GAN CHI HUI  
 NRIC/Passport Number S8320953D  
 Contact Number 90044729  
 Address BLK 111 CLEMENTI ST 13#12-32  
 Postcode 120111  
 Insurance Company Name MSIG INSURANCE (SINGAPORE) PTE. LTD.  
 Nature Of Damage FRONT  
 No. Of Passenger (Including Driver) 4

#### Details of Witness

Name GAN CHI XIAN  
 Phone Number 97659369  
 Email Address




**SKETCH PLAN**

**(IMPORTANT NOTICE)**


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**  
I understand, acknowledge, agree and consent that :  
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [Form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law firms/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :  
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;  
(ii) investigating the accident and/or my claims;  
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;  
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or  
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims, (collectively the "Purposes")  
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law firms/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and  
(c) my Personal Information may/are be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their law firms/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

  
Policyholder's Signature / Date & Time

  
Driver's Signature (If driver is not the policyholder) / Date & Time

  
Witnessed by Reporting Centre Personnel

Sketch Plan



# Sketch Plan Pg. 2

## Describe Circumstances of the Accident

Time around 6.32 pm  
 Road: along Jalan Anak Kuchil. on Right hand side of road turning into PIE (Changi)

A few cars were on the right lane waiting to turn into PIE Changi Airport. There were 3/4 cars ahead of me while waiting on the right lane, SK2 SYL5H, collided into my rear and part of side of car. Driver of SK2 SYL5H came out of car and apologise and we move to side road to exchange particulars.

## Declaration

We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time 8.40 am ~  
 Driver's Signature (if not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel 04/09/2017 @ 856 hrs

## Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770

380, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Tel. 63190888 (AfterSales)  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190528 (AfterSales)  
63190533/530 (Motorrad)  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

## E S T I M A T E

04 SEP 2017

Estimate No. : b1 44001  
Date Estimated : 04/09/2017  
Prepared By : Chua Kee Sin

Page No. : 1 of 3

## - ESTIMATE REPAIR FOR -

Lee Kek Chin  
56 Sunset Way

Singapore 597081

## - ACCOUNT - 40000

Cash Sales - Service  
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SDL282S	DZ11598	22/07/2013	640iA GC	0

## DESCRIPTION

Replace rear left side fender, rear left door, left front view mirror assembly, rear bumper and remove attachment etc include knock on accident dent

6800 9,350.00

Spray painting both left side door, left mirror cover, left rear fender, rear bumper and rear boot lid

4324 4,805.00

To remove and install rear hat-tray, rear seat, carpet and roof top lining to facilitate repairs.

742 873.00

To replace rear windscreen glass including conduct water leak tests.

649.00

To supply and install rear windscreen solar film.

Xnn? 531.00

To check steering geometry and conduct wheel alignment in accordance with BMW specifications. (1X).

451 531.00

To carry out body cavity preservation.  
(For cut panel).

451 531.00

To carry out body cavity preservation.  
(For cut panel).

200 531.00

To replace tyre and wheel rim including balancing. (1X).  
left rear

80 94.00

To transfer lock mechanism from old to new door including conduct checks on new door power window system for proper function. (1 door).

451 531.00

To conduct checks on all doors and bootlid central locking system for proper function.

150 177.00

To check electrical wiring systems and lightings at the rear section for proper function.

150 177.00

## Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Tel. 63190888 (AfterSales)  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190528 (AfterSales)  
63190533/530 (Motorrad)  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

## ESTIMATE

Estimate No. : b1 44001  
Date Estimated : 04/09/2017  
Prepared By : Chua Kee Sin

Page No. : 2 of 3

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SDL282S	DZ11598	22/07/2013	640iA GC	0

## DESCRIPTION

## VALUE

To supply and install rear left window glass solar film.

XAM ? 425.00

Sundries. *Nice*

150.00

Total Labour 1: 19,355.00

## DESCRIPTION

## QTY PRIC

## VALUE

PLASTIC NUT FOR COARSE THREADED PIN

6 0.80

AN AX 4.80

ALLOY RIM 8.5JX19 W SPOKE 423

1 1,340.50

1474.55 SCX 1,340.50

REAR LH SIDE PANEL

1 2,379.90

PAC 2,379.90

Plate

1 48.00

XSL 48.00

Plate

1 48.00

XSL 48.00

LEFT UPPER REAR DOOR HINGE

1 55.75

H 55.75

LEFT LOWER REAR DOOR HINGE

1 54.90

XSL 54.90

REAR LH DOOR

1 2,111.25

H 2,111.25

SET OF MOUNTS FOR PDC SENSOR RR

1 62.50

? 62.50

EXPANDING NUT

10 1.00

XSL 10.00

RR BUMPER CARRIER

1 751.70

? 751.70

RR BUMPER ADAPTER

1 67.10

? 67.10

GUIDE CENTER REAR

1 70.25

CRA 70.25

RR BUMPER (PDC)

1 1,690.65

DB 1,690.65

BMW EMBLEM

1 67.80

NE 67.80

MODEL LETTERING 640I

1 61.05

NE 61.05

PLASTIC NUT

4 0.85

SCX 3.40

LH MIRROR GLASS HEATED WIDE-ANGLE

1 739.30

SCX 739.30

LH WINGMIRROR COVER (PRIMED)

1 109.90

SCX 109.90

LH OUTSIDE MIRROR W/OUT GLASS HEATE

1 1,064.65

CRA 1,064.65

REAR DOOR BRAKE

1 99.15

XSL 99.15

REAR WINDOW GREEN (SSG)

1 1,341.20

NE 1,341.20

BUMP STOP

10 3.25

XSL 32.50

RR LH DOOR OUTER WEATHERSTRIP (CHRO

1 163.70

NE 163.70

CHANNEL SEAL INNER C-PILLAR LH

1 278.30

XSL 278.30

RR LH DOOR SIDE WINDOW FIXED (SSG)

1 400.45

XSL 400.45

RR LH DOOR WEATHERSTRIP

1 233.65

H 233.65

RR BUMPER LH HEAT INSULATOR

1 32.70

H 32.70

COVER WHEEL HOUSING REAR RH

1 162.10

CRA 162.10

(S/L) LH DOOR JOINT SEAL B PILLAR

1 79.50

NE 79.50

TRIM STRIP C-PILLAR LH

1 40.25

? 40.25

DECOUPLING RING PDC TORQUE CONVERTE

4 4.95

SUL 19.80

BUMPER PDC SENSOR (SCHWARZ)

4 231.10

? 924.40

CAVITY PROTECTION WAX REMOVER 500ML

1 18.45

NM 18.45

BLIND RIVET AVIBVLB

17 0.55

NE 9.35

SCREW (SF PLUS M5X15)

3 0.55

NE 1.65

PUNCH RIVET N5

14 0.55

NE 7.70

PUNCH RIVET N4

18 0.55

NE 9.90

(DG) BODYWORK ADHESIVE K5A (50ML)

1 118.35

NE 118.35

## Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No M2-0020081-X

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel: 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax: 64747770

285, Remping Arang Road  
East Coast Centre  
Singapore 438180  
Tel: 63190888 (AfterSales)  
Fax: 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel: 63190528 (AfterSales)  
63190533/530 (Motorrad)  
Fax: 64796601 (AfterSales)  
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

## ESTIMATE

Estimate No. : b1 44001  
Date Estimated : 04/09/2017  
Prepared By : Chua Kee Sin

Page No. : 3 of 3

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SDL282S	DZ11598	22/07/2013	640iA GC	0

## DESCRIPTION

(DG) CLEANER R1 (100ML)  
(DG) CLEANER R1 (100ML)  
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)  
(DG/SL) GLASS PRIMER 30ML (VP206)  
(S/L) SEAM SEAL 300ML

QTY	PRIC	VALUE
1	23.85	23.85
1	23.85	23.85
1	131.55	131.55
1	27.85	27.85
1	33.80	33.80

Total Parts : 14,955.40

## Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. \_\_\_\_\_ Claim No. \_\_\_\_\_  
Date & Time 12/09/17 @ 1625 Excess \$5 \_\_\_\_\_  
Surveyor's Name Rasol Sign \_\_\_\_\_  
Surveyor's Tel 90010068 Authorized Yes / No \_\_\_\_\_  
Authorized Date \_\_\_\_\_ Time \_\_\_\_\_

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No Yes / No

Surveyor's E-mail \_\_\_\_\_

No. of Working Days Recommended 15 days

## LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: \_\_\_\_\_

Date: \_\_\_\_\_

Labour 1	:	19,355.00
Parts	:	14,955.40
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	2,401.73
Grand Total	:	36,712.13

\*\* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY \*\*

\*\* PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\*

37337.50

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



## FINAL REPORT

Estimate No. : b1 44001  
Date Estimated : 04/09/2017  
Prepared By : Chua Kee Sin

Page No. :

REPAIR FOR -  
Lee Kek Chin  
56 Sunset Way

- ACCOUNT - 66  
MSIG Insurance (S) Pte Ltd  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 069807

Singapore 597081

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEAGE		
SDL282S	DZ11598	22/07/2013	640iA GC	0		
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT.			
To replace rear bumper and attachments, rear LH fender, rear LH wheel well extension, rear LH door and attachments, LH wingmirror assembly, rear LH wheel housing cover, rear LH light in side panel include making good the front LH door, boot lid and knocking out dents caused by the accident	6800.00		6,800.00			
To spray paint front/rear LH doors, LH wingmirror cover, rear LH fender, rear bumper and boot lid.	4324.00		4,324.00			
To remove and install rear hat-tray, rear seat, carpet and roof top lining to facilitate repairs.	742.00		742.00			
To replace rear windscreen glass include conducting water leak tests	649.00		649.00			
To check steering geometry and conduct wheel alignment in accordance with BMW specifications (1x)	451.00		451.00			
To carry out body cavity preservation. (For cut panel).	451.00		451.00			
To carry out body cavity preservation. (Per panel)	200.00		200.00			
To replace rear LH wheel rim include balancing (1x)	80.00		80.00			
To transfer lock mechanism from old to new door include conducting checks on new door power window system for proper function (1x)	451.00		451.00			
To conduct checks on all doors and boot lid central locking system for proper function	150.00		150.00			
To check electrical wiring systems and lightings at the rear section for proper function.	150.00		150.00			
# To replace rear LH exhaust silencer and attachments include alignment and conducting checks for leak	451.00		451.00			
Sundries.	150.00		150.00			

# Performance Motors Limited

A member of the Sims Darby Group  
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



## FINAL REPORT

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# RR SILENCER CLAMPING BUSH *	60.60	1.00		60.60
# EXHAUST TRIM CHROME *	130.55	1.00		130.55
# RR LH SILENCER *	1,201.80	1.00		1,201.80
ALLOY RIM 9JX19 W SPOKE 423	1,474.55	1.00		1,474.55
# EXTENSION FOR REAR LH WHEEL WELL *	261.55	1.00		261.55
REAR LH SIDE PANEL	2,379.90	1.00		2,379.90
LEFT UPPER REAR DOOR HINGE	55.75	1.00		55.75
REAR LH DOOR	2,111.25	1.00		2,111.25
GUIDE CENTER REAR	70.25	1.00		70.25
# MOUNT REAR LH *	141.65	1.00		141.65
RR BUMPER (PDC)	1,690.65	1.00		1,690.65
BMW EMBLEM	67.80	1.00		67.80
MODEL LETTERING 640i	61.05	1.00		61.05
PLASTIC NUT	0.85	4.00		3.40
LH MIRROR GLASS HEATED WIDE-ANGLE	739.30	1.00		739.30
LH WINGMIRROR COVER (PRIMED)	109.90	1.00		109.90
LH OUTSIDE MIRROR W/OUT GLASS HEATE	1,064.65	1.00		1,064.65
REAR WINDOW GREEN (SSG)	1,341.20	1.00		1,341.20
# GROMMET *	0.75	5.00		3.75
RR LH DOOR OUTER WEATHERSTRIP (CHRO	163.70	1.00		163.70
RR BUMPER LH HEAT INSULATOR	32.70	1.00		32.70
# TRIM DRIP RAIL LH *	52.20	1.00		52.20
# CLIP, BOTTOM PART *	1.60	3.00		4.80
# CLIP, BOTTOM PART *	1.60	1.00		1.60
COVER WHEEL HOUSING REAR RH	162.10	1.00		162.10
# CLIP ROOF FRAME STRIP *	1.65	5.00		8.25
(S/L) LH DOOR JOINT SEAL B PILLAR	79.50	1.00		79.50
# RR BUMPER LH REFLECTOR *	34.35	1.00		34.35
# REAR LIGHT IN THE SIDE PANEL LH *	646.90	1.00		646.90
# SNAP LOCKING COUPLING *	0.90	10.00		9.00
# RR BUMPER BREATHER COVERING *	19.10	1.00		19.10
BLIND RIVET AVIBVLB	0.55	20.00		11.00
SCREW (SF PLUS M5X15)	0.55	3.00		1.65
PUNCH RIVET N5	0.55	20.00		11.00
PUNCH RIVET N4	0.55	20.00		11.00
(DG) BODYWORK ADHESIVE K5A (50ML)	118.35	1.00		118.35
(DG) CLEANER R1 (100ML)	23.85	2.00		47.70
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	131.55	1.00		131.55
(DG/SL) GLASS PRIMER 30ML (VP206)	27.85	1.00		27.85
(S/L) SEAM SEAL 300ML	33.80	1.00		33.80

### # SUPPLEMENTARY ITEMS

Total Labour :	15,049.00
Total Parts :	14,577.65
Total Labour & Parts :	29,626.65
Deduction for Excess :	
Total Repair Costs less Excess:	29,626.65
GST @7%:	2,073.87
Grand Total :	31,700.52



# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



## SUPPLEMENTARY

Estimate No. : b1 44001  
Date Estimated : 04/09/2017  
Prepared By : Chua Kee Sin

Page No. :

REPAIR FOR -  
Lee Kek Chin  
56 Sunset Way

- ACCOUNT - 66  
MSIG Insurance (S) Pte Ltd  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

Singapore 597081

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE
SDL282S	DZ11598	22/07/2013	640iA GC	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
# To replace rear LH exhaust silencer and attachments include alignment and conducting checks for leak	451.00		451.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# RR SILENCER CLAMPING BUSH *	60.60	1.00		60.60 <i>na</i>
# EXHAUST TRIM CHROME *	130.55	1.00		130.55 <i>see</i>
# RR LH SILENCER *	1,201.80	1.00		1,201.80 <i>BT</i>
# EXTENSION FOR REAR LH WHEEL WELL *	261.55	1.00		261.55 <i>BT</i>
# MOUNT REAR LH *	141.65	1.00		141.65 <i>CRA</i>
# GROMMET *	0.75	5.00		3.75 <i>na</i>
# TRIM DRIP RAIL LH *	52.20	1.00		52.20 <i>na</i>
# CLIP, BOTTOM PART *	1.60	3.00		4.80 <i>na</i>
# CLIP, BOTTOM PART *	1.60	1.00		1.60 <i>na</i>
# CLIP ROOF FRAME STRIP *	1.65	5.00		8.25 <i>na</i>
# RR BUMPER LH REFLECTOR *	34.35	1.00		34.35 <i>na</i>
# REAR LIGHT IN THE SIDE PANEL LH *	646.90	1.00		646.90 <i>CH</i>
# SNAP LOCKING COUPLING *	0.90	10.00		9.00 <i>na</i>
# RR BUMPER BREATHER COVERING *	19.10	1.00		19.10 <i>CRA</i>

Total Labour :	451.00
Total Parts :	2,576.10
Total Labour & Parts :	3,027.10






































### ...CLAIM SUBFOLDER...(Pending for Survey Report)


















































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	04 Sep 2017		04 Sep 2017 17:20 <a href="#">Edit Adj Rpt</a>	<b>S\$29,626.65</b> <a href="#">Edit Estimates</a>	<b>S\$29,626.65</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by Insurer]</span>									
Insured: <b>NG BEOW KHENG</b> , ID: S1286531G									
Main Claimant: <b>LEE KEK CHIN</b> , ID: S1450092H									
Vehicle Reg. No.:	<b>SDL282S</b>	Date of Loss:	03/09/2017 00:00 - :59 [49 Months and 12 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / 528443</b>	Policy/Cover Note No.:	28875516QMY (Comprehensive) Coverage: 27/01/2017 - 26/01/2018						
Vehicle Reg. No. (Insured):	<b>SKZ5425H</b>	Policy No. (Claimant):							
		Excess:							
Repairer: <b>Performance Motors Limited (Alexandra)</b> 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174									
Handling Insurer: <b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Chhia Nyuk Pui</b> - 6594 2521]									
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MOHD RASUL</b> ] ... [Final Rpt due 04/10/2017]									
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

**\*SDL282S (528443)**  
**[SKZ5425H]**  
**TP**  
**LEE KEK CHIN**  
**Sep 3 2017 12:00AM**  
**[NG BEOW KHENG]**  
**Performance Motors Limited**

<a href="#">Upload Documents</a> <a href="#">Upload Photos</a> <a href="#">Compose New Letter</a>			<b>View</b> <a href="#">View in Browser</a>	
<b>Assessment Reports</b>			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	13/09/17 16:41	Adjuster Immediate Advice	 Load HTML	
<b>Photos/Images</b>			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	05/07/18 09:51	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
2	05/07/18 09:51	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
3	05/07/18 09:51	General View	 Load JPG	<input checked="" type="checkbox"/>
4	05/07/18 09:51	General View	 Load JPG	<input checked="" type="checkbox"/>
5	05/07/18 09:51	General View	 Load JPG	<input checked="" type="checkbox"/>
6	05/07/18 09:51	General View	 Load JPG	<input checked="" type="checkbox"/>
7	05/07/18 09:51	General View	 Load JPG	<input checked="" type="checkbox"/>
8	05/07/18 09:51	General View	 Load JPG	<input checked="" type="checkbox"/>
9	05/07/18 09:51	General View	 Load JPG	<input checked="" type="checkbox"/>
10	05/07/18 09:51	General View	 Load JPG	<input checked="" type="checkbox"/>
11	05/07/18 09:51	General View	 Load JPG	<input checked="" type="checkbox"/>
12	05/07/18 09:51	General View	 Load JPG	<input checked="" type="checkbox"/>
13	05/07/18 09:51	General View	 Load JPG	<input checked="" type="checkbox"/>
14	05/07/18 09:51	General View	 Load JPG	<input checked="" type="checkbox"/>
15	05/07/18 09:51	General View	 Load JPG	<input checked="" type="checkbox"/>
16	05/07/18 09:51	General View	 Load JPG	<input checked="" type="checkbox"/>
17	05/07/18 09:51	General View	 Load JPG	<input checked="" type="checkbox"/>
18	05/07/18 09:51	General View	 Load JPG	<input checked="" type="checkbox"/>
19	05/07/18 09:51	General View	 Load JPG	<input checked="" type="checkbox"/>
20	05/07/18 09:51	General View	 Load JPG	<input checked="" type="checkbox"/>
21	05/07/18 09:51	General View	 Load JPG	<input checked="" type="checkbox"/>
22	05/07/18 09:51	General View	 Load JPG	<input checked="" type="checkbox"/>
23	05/07/18 09:51	General View	 Load JPG	<input checked="" type="checkbox"/>
24	05/07/18 09:51	General View	 Load JPG	<input checked="" type="checkbox"/>
25	05/07/18 09:51	General View	 Load JPG	<input checked="" type="checkbox"/>
26	05/07/18 09:51	General View	 Load JPG	<input checked="" type="checkbox"/>
27	05/07/18 09:51	General View	 Load JPG	<input checked="" type="checkbox"/>
28	05/07/18 09:51	General View	 Load JPG	<input checked="" type="checkbox"/>
29	05/07/18 09:51	General View	 Load JPG	<input checked="" type="checkbox"/>
30	05/07/18 09:51	General View	 Load JPG	<input checked="" type="checkbox"/>
31	05/07/18 09:51	General View	 Load JPG	<input checked="" type="checkbox"/>
32	05/07/18 09:51	General View	 Load JPG	<input checked="" type="checkbox"/>
33	05/07/18 09:51	General View	 Load JPG	<input checked="" type="checkbox"/>
34	05/07/18 09:51	General View	 Load JPG	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	05/07/18 09:51	General View	 Load JPG	<input checked="" type="checkbox"/>
36	05/07/18 09:51	General View	 Load JPG	<input checked="" type="checkbox"/>
37	05/07/18 09:51	General View	 Load JPG	<input checked="" type="checkbox"/>
38	05/07/18 09:51	General View	 Load JPG	<input checked="" type="checkbox"/>
39	05/07/18 09:51	General View	 Load JPG	<input checked="" type="checkbox"/>
40	05/07/18 09:51	General View	 Load JPG	<input checked="" type="checkbox"/>
41	05/07/18 09:51	General View	 Load JPG	<input checked="" type="checkbox"/>
42	05/07/18 09:51	General View	 Load JPG	<input checked="" type="checkbox"/>
43	05/07/18 09:51	General View	 Load JPG	<input checked="" type="checkbox"/>
44	05/07/18 09:51	General View	 Load JPG	<input checked="" type="checkbox"/>
45	05/07/18 09:51	General View	 Load JPG	<input checked="" type="checkbox"/>
46	05/07/18 09:51	General View	 Load JPG	<input checked="" type="checkbox"/>
47	05/07/18 09:51	General View	 Load JPG	<input checked="" type="checkbox"/>
48	05/07/18 09:51	General View	 Load JPG	<input checked="" type="checkbox"/>
49	05/07/18 09:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	05/07/18 09:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	05/07/18 09:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	05/07/18 09:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	05/07/18 09:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	05/07/18 09:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	05/07/18 09:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	05/07/18 09:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	05/07/18 09:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	05/07/18 09:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	05/07/18 09:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	05/07/18 09:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	05/07/18 09:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	05/07/18 09:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	05/07/18 09:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	05/07/18 09:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	05/07/18 09:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	05/07/18 09:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	05/07/18 09:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	05/07/18 09:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	05/07/18 09:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	05/07/18 09:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	05/07/18 09:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	05/07/18 09:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	05/07/18 09:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	05/07/18 09:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	05/07/18 09:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	05/07/18 09:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	05/07/18 09:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	05/07/18 09:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	05/07/18 09:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	05/07/18 09:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
81	05/07/18 09:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
82	05/07/18 09:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
83	05/07/18 09:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
84	05/07/18 09:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
85	05/07/18 09:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
86	05/07/18 09:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
87	05/07/18 09:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
88	05/07/18 09:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	04/09/17 16:06	SDL2825 GIA RPT	 Load PDF	
2	04/09/17 16:08	Estimate	 Load JPG	<input checked="" type="checkbox"/>
3	04/09/17 17:21	Survey AGREE ON SJE, Appoint LKK as Surveyor	 Load PDF	
4	04/09/17 17:21	Request Pre-Repair Inspection	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	16/07/18 12:20	SUPPLEMENTARY PART	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To:

☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199807198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG17017088/R1QBQ2

Date: 16/07/2018

## REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 28875516QMY

Claimant Vehicle No : SDL282S

Insured Vehicle No : SKZ5425H

Date of Loss: 03/09/2017

Nature of Claim: TP

Claim No: 528443

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: **SDL282S**

Make &amp; Model: BMW 640I, 3.0 Gran Coupe (F13) (A)

Engine No: 08208469N55B30A

Reg. Date: 22/07/2013 (Man. Year: 2013)

Chassis No: WBA6A02000DZ11598

Colour: Black

Odometer: 57776 km

Engine Capacity: 2979 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 245/40 R19

Rear Tyre Size: 245/40 R19

Front Left Side: Dunlop 6 mm

Rear Left Side: Dunlop 6 mm

Front Right Side: Dunlop 6 mm

Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,821.60	14,727.65	3,093.95	17.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	19,656.00	14,899.00	4,757.00	24.20
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>37,477.60</b>	<b>29,626.65</b>	<b>7,850.95</b>	<b>20.95</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>2,623.43</b>	<b>2,073.87</b>	<b>549.56</b>	<b>20.95</b>
<b>Nett Amount (S\$)</b>	<b>40,101.03</b>	<b>31,700.52</b>	<b>8,400.51</b>	<b>20.95</b>

## INSPECTION

Date of Assignment: 04/09/2017

Date Inspected: 12/09/2017 Inspected At:

Performance Motors Limited (Alexandra)  
303 Alexandra Road, Sime Darby  
Performance Centre  
Singapore 159941

Estimated Period of Repair: 15.0 days

Adjuster: MOHD RASUL

Manager: SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b>	(Last Synchronised: 16 Jul 2018)	
<b>Parts:</b>	N/A	BMW 640i 3.0 Gran Coupe (F13) (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SDL282S)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	150.00 FS	*150.00 FS
2	6		*PLASTIC NUT FOR COARSE THREADED PIN	Not Necessary	4.80 FS	*- FS
3	1		*ALLOY RIM 8.5JX19W SPOKE 423	Scratched	1,474.55 FS	*1,474.55 FS
4	1		*REAR LH SIDE PANEL	Buckled	2,379.90 FS	*2,379.90 FS
5	1		*PLATE	Serviceable	48.00 FS	*- FS
6	1		*PLATE	Serviceable	48.00 FS	*- FS
7	1		*LEFT UPPER REAR DOOR HINGE	Bent	55.75 FS	*55.75 FS
8	1		*LEFT LOWER REAR DOOR HINGE	Serviceable	54.90 FS	*- FS
9	1		*REAR LH DOOR	Bent	2,111.25 FS	*2,111.25 FS
10	1		*SET OF MOUNTS FOR PDC SENSOR RR	Serviceable	62.50 FS	*- FS
11	10		*EXPANDING NUT	Serviceable	10.00 FS	*- FS
12	1		*RR BUMPER CARRIER	Serviceable	751.70 FS	*- FS
13	1		*RR BUMPER ADAPTER	Serviceable	67.10 FS	*- FS
14	1		*GUIDE CENTER REAR	Cracked	70.25 FS	*70.25 FS
15	1		*RR BUMPER (PDC)	Deformed	1,690.65 FS	*1,690.65 FS
16	1		*BMW EMBLEM	Necessary	67.80 FS	*67.80 FS
17	1		*MODEL LETTERING 640i	Necessary	61.05 FS	*61.05 FS
18	4		*PLASTIC NUT	Necessary	3.40 FS	*3.40 FS
19	1		*LH MIRROR GLASS HEATED WIDE-ANGLE	Scratched	739.30 FS	*739.30 FS
20	1		*LH WINGMIRROR COVER (PRIMED)	Scratched	109.90 FS	*109.90 FS
21	1		*LH OUTSIDE MIRROR W/OUT GLASS HEATE	Cracked	1,064.65 FS	*1,064.65 FS
22	1		*REAR DOOR BRAKE	Serviceable	99.15 FS	*- FS
23	1		*REAR WINDOW GREEN (SSG)	Necessary	1,341.20 FS	*1,341.20 FS
24	10		*BUMP STOP	Serviceable	32.50 FS	*- FS
25	1		*RR LH DOOR OUTER WEATHERSTRIP (CHRO)	Necessary	163.70 FS	*163.70 FS
26	1		*CHANNEL SEAL INNER C-PILLAR LH	Serviceable	278.30 FS	*- FS
27	1		*RR LH DOOR SIDE WINDOW FIXED (SSG)	Serviceable	400.45 FS	*- FS
28	1		*RR LH DOOR WEATHERSTRIP	Serviceable	233.65 FS	*- FS
29	1		*RR BUMPER LH HEAT INSULATOR	Bent	32.70 FS	*32.70 FS
30	1		*COVER WHEEL HOUSING REAR RH	Cracked	162.10 FS	*162.10 FS
31	1		*(S/L) LH DOOR JOINT SEAL B PILLAR	Necessary	79.50 FS	*79.50 FS
32	1		*TRIM STRIP C-PILLAR LH	Serviceable	40.25 FS	*- FS
33	4		*DECOUPLING RING PDC TORQUE CONVERTE	Serviceable	19.80 FS	*- FS
34	4		*BUMPER PDC SENSOR (SCHWARZ)	Serviceable	924.40 FS	*- FS
35	1		*CAVITY PROTECTION WAX REMOVED 500ML	Not Necessary	18.45 FS	*- FS
36	20		*BLIND RIVET AVIBVLB	Necessary	11.00 FS	*11.00 FS
37	3		*SCREW (SF PLUS M5X15)	Necessary	1.65 FS	*1.65 FS
38	20		*PUNCH RIVET N5	Necessary	11.00 FS	*11.00 FS
39	20		*PUNCH RIVET N4	Necessary	11.00 FS	*11.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*(DG) BODYWORK ADHESIVE K5A (50ML)	Necessary	118.35 FS	*118.35 FS
41	1		*(DG) CLEANER R1 (100ML)	Necessary	23.85 FS	*23.85 FS
42	1		*(DG) CLEANER R1 (100ML)	Necessary	23.85 FS	*23.85 FS
43	1		*(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	Necessary	131.55 FS	*131.55 FS
44	1		*(DG/SL) GLASS PRIMER 30ML (VP206)	Necessary	27.85 FS	*27.85 FS
45	1		*(S/L) SEAM SEAL 300ML	Necessary	33.80 FS	*33.80 FS
46	1		*RR SILENCER CLAMPING BUSH	Necessary	60.60 FS	*60.60 FS
47	1		*EXHAUST TRIM CHROME	Scratched	130.55 FS	*130.55 FS
48	1		*RR LH SILENCER	Bent	1,201.80 FS	*1,201.80 FS
49	1		*EXTENSION FOR REAR LH WHEEL WELL	Bent	261.55 FS	*261.55 FS
50	1		*MOUNT REAR LH	Cracked	141.65 FS	*141.65 FS
51	5		*GROMMET	Necessary	3.75 FS	*3.75 FS
52	1		*TRIM DRIP RAIL LH	Necessary	52.20 FS	*52.20 FS
53	3		*CLIP ,BOTTOM PART	Necessary	4.80 FS	*4.80 FS
54	1		*CLIP ,BOTTOM PART	Necessary	1.60 FS	*1.60 FS
55	5		*CLIP ROOF FRAME STRIP	Necessary	8.25 FS	*8.25 FS
56	1		*RR BUMPER LH REFLECTOR	Missing	34.35 FS	*34.35 FS
57	1		*REAR LIGHT IN THE SIDE PANEL LH	Cracked	646.90 FS	*646.90 FS
58	10		*SNAP LOCKING COUPLING	Necessary	9.00 FS	*9.00 FS
59	1		*RR BUMPER BREATHER COVERING	Cracked	19.10 FS	*19.10 FS
Total Parts (S\$)					17,821.60	14,727.65

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.



## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REPLACE REAR LH EXHAUST SILENCER AND ATTACHMENTS INCLUDE ALIGNMENT AND CONDUCTING CHECKS FOR LEAK	New	451.00	451.00
2	REPLACE REAR LEFT SIDE FENDER ,REAR LEFT DOOR ,LEFT FRONT VIEW MIRROR ASSEMBLY ,REAR BUMPER AND REMOVED ATTACHMENT ETC INCLUDE KNOCK ON ACCIDENT DENT	New	9,350.00	6,800.00
3	SPRAY PAINTING BOTH LEFT SIDE DOOR ,LEFT MIRROR COVER ,LEFT REAR FENDER ,REAR BUMPER AND REAR BOOT LID	New	4,805.00	4,324.00
4	TO REMOVE AND INSTALL REAR HAT-TRAY ,REAR SEAT ,CARPET AND ROOF TOP LINING TO FACILITATE REPAIRS	New	873.00	742.00
5	TO REPLACE REAR WINDSCREEN GLASS INCLUDING CONDUCT WATER LEAK TESTS	New	649.00	649.00
6	TO SUPPLY AND INSTALL REAR WINDSCREEN SOLAR FILM	New	531.00	0.00
7	TO CHECK STEERING GEOMETRY AND CONDUCT WHEEL ALIGNMENT IN ACCORDANCE WITH BMW SPECIFICATIONS	New	531.00	451.00
8	TO CARRY OUT BODY CAVITY PRESERVATION (FOR CUT PANEL)	New	531.00	451.00
9	TO CARRY OUT BODY CAVITY PRESERVATION (FOR CUT PANEL)	New	531.00	200.00
10	TO REPLACE TYRE AND WHEEL RIM INCLUDING BALANCING .LEFT REAR	New	94.00	80.00
11	TO TRANSFER LOCK MECHANISM FROM OLD TO NEW DOOR INCLUDING CONDUCT CHECKS ON NEW DOOR POWER WINDOW SYSTEM FOR PROPER FUNCTION	New	531.00	451.00
12	TO CONDUCT CHECKS ON ALL DOORS AND BOOTLID CENTROL LOCKING SYSTEM FOR PROPER FUNCTION	New	177.00	150.00
13	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR RPOPER FUNCTION	New	177.00	150.00
14	TO SUPPLY AND INSTALL REAR LEFT WINDOW GLASS SOLAR FILM	New	425.00	0.00
Gross Labour Cost (S\$)			19,656.00	14,899.00

Report was unsubmitted during this print-out.

&lt; END OF ESTIMATES &gt;