11/17/21, 2:03 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AXA17017237/KPS3Q2

17/11/2021 Date:

REFERENCE

Handling Insurer: AXA Insurance Pte Ltd Policy No: P1632127

Claimant Vehicle SHC5137X Insured Vehicle No: PA1696R No:

Date of Loss: 31/08/2017 Nature of Claim: TP Claim No: C0450900

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHC5137X

Make & Model: RENAULT LATITUDE, 2.0 L (A) Engine No: M9R8839C000642 Reg. Date: 14/01/2014 (Man. Year: 2013) Chassis No: VF1ABL15AUC275895

Colour: Metallic White/Red Odometer: 457688 km

Engine Capacity: 1995 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Engine Modification: Pre-accident Condition: Yes No

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16 Front Left Side: Rear Left Side: Linglong 8 mm Linglong 6 mm Front Right Side: Linglong 8 mm Rear Right Side: Linglong 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	25,866.56	1,335.06	24,531.50	94.84
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,060.00	155.00	9,905.00	98.46
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	35,926.56	1,490.06	34,436.50	95.85
Approved Total (Overridden) (S\$)				
(S\$)	35,926.56	1,200.00	34,726.56	96.66
+ GST 7.00/7.00% (S\$)	2,514.86	84.00	2,430.86	96.66
Nett Amount (S\$)	38,441.42	1,284.00	37,157.42	96.66
Global Su	m Settlement (S\$)	0.00		

INSPECTION

Date of Assignment: 07/09/2017

Trans-cab Auto Services Pte Ltd No 2 Ang Mo Kio Street 63 Date Inspected: 05/09/2017 Inspected At:

Singapore 569111

Estimated Period of Repair: 1.0 days

KENNETH KONG **CHEW HSIAO TONG** Adjuster: Manager:

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

11/17/21, 2:03 PM Adjuster Report

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 13 Aug 2020)

Parts: 143 RENAULT LATITUDE 2.0 L (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHC5137X)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER FRT (CONSISTENT)	Serviceable	1,259.42 FL	*- FL
2	1		*BUMPER RETAINER FRT RH (CONSISTENT)	Serviceable	151.41 FL	*- FL
3	1		*BUMPER BRACKET FRT RH (CONSISTENT)	Repair	181.75 FL	*- FL
4	1		*HEADLAMP RH (CONSISTENT)	Serviceable	1,184.43 FL	*- FL
5	1		*HEADLAMP PANEL FRT RH (CONSISTENT)	Repair	152.15 FL	*- FL
6	1		*FENDER PANEL FRT RH (CONSISTENT)	Repair	783.83 FL	*- FL
7	1		*WHEELARCH FRT RH (CONSISTENT)	Serviceable	278.84 FL	*- FL
8	1		*DOOR MIRROR RH (CONSISTENT) }	Broken	1,483.40 FL	*1,483.40 FL
9	1		*DOOR MIRROR GLASS RH (CONSISTENT) }		148.20 FL	*- FL
10	1		*DOOR MIRROR BACK COVER RH (CONSISTENT) }		218.46 FL	*- FL
11	1		*DOOR PANEL FRT RH (CONSISTENT)	Repair	2,844.66 FL	*- FL
12	1		*DOOR HINGE UPPER RH (CONSISTENT)	Repair	274.50 FL	*- FL
13	1		*DOOR HINGE LOWER RH (CONSISTENT)	Repair	300.55 FL	*- FL
14	1		*DOOR CHECK FRT RH (CONSISTENT)	Serviceable	194.77 FL	*- FL
15	1		*DOOR GRAB HANDLE FRT RH (CONSISTENT)	Serviceable	210.96 FL	*- FL
16	1		*DOOR HANDLE OUTER FRT RH (CONSISTENT)	Serviceable	258.12 FL	*- FL
17	1		*DOOR HANDLE CAP FRT RH (CONSISTENT)	Serviceable	26.44 FL	*- FL
18	1		*DOOR HANDLE SEAL FRT RH (CONSISTENT)	Serviceable	7.89 FL	*- FL
19	1		*DOOR HANDLE COVER FRT RH (CONSISTENT)	Serviceable	13.22 FL	*- FL
20	1		*DOOR HANDLE MODULE FRT RH (CONSISTENT)	Serviceable	133.60 FL	*- FL
21	1		*DOOR FINISHER FRT RH (CONSISTENT)	Serviceable	515.06 FL	*- FL
22	1		*DOOR MOULDING FRT RH (CONSISTENT)	Serviceable	176.82 FL	*- FL
23	1		*DOOR WEATHERSTRIP FRT RH (CONSISTENT)	Serviceable	474.21 FL	*- FL
24	1		*DOOR SEAL LOWER FRT RH (CONSISTENT)	Serviceable	105.18 FL	*- FL
25	1		*DOOR SEAL FRT RH (CONSISTENT)	Serviceable	68.67 FL	*- FL
26	1		*DOOR WAIST SEAL OUTER FRT RH (CONSISTENT)	Serviceable	291.27 FL	*- FL
27	1		*ROCKER PANEL OUTER RH (CONSISTENT)	Repair	987.49 FL	*- FL
28	1		*DOOR PANEL REAR RH (CONSISTENT)	Repair	2,844.66 FL	*- FL
29	1		*DOOR GUIDE REAR RH (CONSISTENT)	Serviceable	176.82 FL	*- FL
30	1		*DOOR HINGE UPPER RH (CONSISTENT)	Repair	315.74 FL	*- FL
31	1		*DOOR HINGE LOWER RH (CONSISTENT)	Repair	300.55 FL	*- FL
32	1		*DOOR CHECK REAR RH (CONSISTENT)	Serviceable	203.06 FL	*- FL
33	1		*DOOR GRAB HANDLE REAR RH (CONSISTENT)	Serviceable	210.96 FL	*- FL
34	1		*DOOR HANDLE OUTER REAR RH (CONSISTENT)	Serviceable	126.49 FL	*- FL
35	1		*DOOR HANDLE CAP REAR RH (CONSISTENT)	Serviceable	35.52 FL	*- FL
36	1		*DOOR HANDLE SEAL REAR RH (CONSISTENT)	Serviceable	7.89 FL	*- FL
37	1		*DOOR HANDLE COVER REAR RH (CONSISTENT)	Serviceable	13.22 FL	*- FL
38	1		*DOOR HANDLE MODULE REAR RH (CONSISTENT)	Serviceable	133.60 FL	*- FL
39	1		*DOOR FINISHER REAR RH (CONSISTENT)	Serviceable	423.10 FL	*- FL
40	1		*DOOR MOULDING REAR RH (CONSISTENT)	Serviceable	176.82 FL	*- FL
41	1		*DOOR WEATHERSTRIP REAR RH (CONSISTENT)	Serviceable	474.60 FL	*- FL
42	1		*DOOR SEAL REAR RH (CONSISTENT)	Serviceable	187.08 FL	*- FL
43	1		*DOOR WAIST SEAL OUTER REAR RH (CONSISTENT)	Serviceable	334.69 FL	*- FL
44	1		*TAILLAMP RH (CONSISTENT)	Serviceable	552.55 FL	*- FL
45	1		*TAILLAMP PANEL RH (CONSISTENT)	Repair	986.70 FL	*- FL
					330 C. E	

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*WHEELARCH REAR RH (CONSISTENT)	Serviceable	543.47 FL	*- FL
48	1		*BUMPER COVER REAR (CONSISTENT)	Serviceable	1,108.46 FL	*- FL
49	1		*BUMPER LOWER REAR (CONSISTENT)	Serviceable	768.84 FL	*- FL
50	1		*BUMPER BRACKET CTR REAR (CONSISTENT)	Serviceable	113.47 FL	*- FL
51	1		*BUMPER BRACKET SIDE RH REAR (CONSISTENT)	Serviceable	135.97 FL	*- FL
52	1		*BUMPER BRACKET CTR RH REAR (CONSISTENT)	Serviceable	44.99 FL	*- Fl
53	1		*BUMPER REFLECTOR RH (CONSISTENT)	Serviceable	43.61 FL	*- Fl
54	1		*SET FRONT BUMPER CLIP (CONSISTENT)	Not Necessary	66.00 FS	*- FS
55	1		*SET WHEELARCH CLIP FRT RH (CONSISTENT)	Not Necessary	66.00 FS	*- F\$
56	1		*SET WHEELARCH CLIP FRT RH (CONSISTENT)	Not Necessary	66.00 FS	*- FS
57	1		*SET RADIATOR GRILLE FRAME CLIP (CONSISTENT)	Not Necessary	52.00 FS	*- F
58	1		*SET FRAME FULL SUPPORT PANEL CLIP (CONSISTENT)	Not Necessary	70.00 FS	*- F
59	1		*CAP HUB RH FRT (CONSISTENT)	Serviceable	35.00 FS	*- F
30	1		*RIM RH FRT (CONSISTENT)	Serviceable	385.00 FS	*- F\$
61	1		*TYRE RH FRT (CONSISTENT)	Serviceable	330.00 FS	*- F\$
32	1		*CAP HUB RH FRT RR (CONSISTENT)	Serviceable	35.00 FS	*- F
33	1		*RIM RH FRT RR (CONSISTENT)	Serviceable	385.00 FS	*- F
64	1		*TYRE RH FRT RR (CONSISTENT)	Serviceable	330.00 FS	*- F
35	1		*DOOR STICKER TRANS-CAB (CONSISTENT)	Not Necessary	80.00 FS	*- F
66	1		*DOOR STICKER CLASSIC (CONSISTENT)	Not Necessary	30.00 FS	*- F
37	1		*DOOR STICKER 6555-3333 (CONSISTENT)	Not Necessary	80.00 FS	*- F\$
86	1		*SET REAR BUMPER CLIP (CONSISTENT)	Not Necessary	66.00 FS	*- F
69	1		*SET WHEELARCH CLIP RR RH (CONSISTENT)	Not Necessary	66.00 FS	*- F\$
70	1		*SET WHEELARCH CLIP RR RH (CONSISTENT)	Not Necessary	66.00 FS	*- F
=Fra	nchise	part. S=Spc	Nett. L=ListItemDisc.			
				Sub Total (S\$)	28,495.29	1,483.40
			- List Item Discount on L Items	10.00/10.00% (S\$)	2,628.73	148.34
				Total Parts (S\$)	25,866.56	1,335.06

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			
1	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New -	4,200.00	80.00
2	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	15.00
3	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	4,500.00	60.00
4	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
5	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING	New	170.00	0.00
6	TOWING FEES	New	120.00	0.00
7	TO TRANSFER OF DOOR FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
8	TO REMOVE AND REFIT FRONT W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR	New	170.00	0.00
9	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	0.00
10	TO TRANSFER OF FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
	Gross Labour Cost (S\$)		10,060.00	155.00
	Report was unsubmitted during this	print-out.		

< END OF ESTIMATES >