

SS. REC. BY

REF: CS/MSG/7017278/T146n2

Special Instruction:

Surveyor
m/mon

Taufia

ASSIGNMENT (Office)

From (Person):

Monica Chung

of

msch

Date/Time: 06092017 1105am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SDU 3331 S

Insured:

SCA 8078Z

at Workshop m/s

Wearnes

Tel:

9295 1331

of

45 Leng Kee Rd

Policy No:

827830946SMP

Claim No:

526423

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

11082017

CA / REV / REP. / REV 24 HRS w/p

06092017 @ 11am OW

Date/Time:

06092017 1033am

Person Contacted:

Chan

H.O.D. Endorsement:

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SDU 3331 S-X
	SCA 8078Z-X
	Part by Part \$6634.85 (Red: 3333.25 : 33%)

Storage: *Tan Jiah*

REF:


MSL

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

WP

Vehicle: IN / OUT

Date: _____ Person Contacted: *Chan*

Veh No: *SDU 33315* Yr Regn: *20/6/1 Sep*
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: *Land Rover Range Rover Sport* c.c. *2993*

Colour: *Maroon* A/C: Insured / Std / NI / NA

Sp. Reading: *25294* T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: *SALWA 2 KE36A 107066*

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: *255/55 R20*
 R: *255/55 R20*

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. *6* mm R/Bal. *6* mm

L/Bal. *6* mm L/Bal. *6* mm

D.O.A. _____ D.O.I. *6/9/17 @ 1120*

Survey held at *Wanman 45 King Lee Rd*

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction *9295133-1*

RECEIVED 20 APR 2010

Date/Time, File Pass to?

☐ : Preli. Report
☒ : Final Report

1) *2014 Typist*
 Date/Time, File Return to?

2)

Days Of Repair: *3*

Resurvey No. of Trip: *1*

Report Format: *TP*

Lump Sum / I.E. (\$) *6634.35*

Add Fee:

☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

Survey Fee:

Transportation:

☐ S + RS: \$

Photos

Others

TOTAL

300
10
310



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (SINGAPORE) PTE LTD			Ref : CS/MSG17017278/T1tb	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581			Date : 06-09-2017	
			Code : MSG	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SCQ 8078Z	Veh. Inspected	SDU 3331S	
Policy No.	B27830946SMP	Coverage (\$)	0.00	
Claim No.	526423	Excess (\$)	0.00	
Assign From	MERIMEN (MONICA CHUNG)	Assign Date	06/09/2017	
2. Vehicle Particulars & Condition				
Make & Model	c.c		0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	11/08/2017	Inspection Date	06/09/2017	
Survey held at	WEARNES AUTOMOTIVE PTE LTD 45 LENG KEE ROAD SINGAPORE 159103.			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							Status
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	
Main	12 Aug 2017		06 Sep 2017 10:05 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	LIM SWEE CHEANG, ID: S2500658E		
Main Claimant:	LIM KUE LAY, ID: S0545012H		
Vehicle Reg. No.:	SDU3331S	Date of Loss:	11/08/2017 11:00 - :59
Claim Type:	TP / 526423	Policy/Cover Note No.:	B27830946SMP (Comprehensive) Coverage: 26/12/2016 - 25/12/2017
Vehicle Reg. No. (Insured):	SCQ8078Z	Policy No. (Claimant):	
		Excess:	S\$1,200.00
Repairer:	Wearnes Automotive Pte Ltd (Jurong) 2 Jalan Pesawat, 619358 Jurong East - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 07/09/2017]		
Driver/Custodian (Insured):	PEH SUE LAN @ PAI SHU NAN (/ Female), NRIC: S2500659C		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

SERVICE ESTIMATE

75923 - C00001
Mr Lim Kue Lay
17 Pavilion Place

SL: SERVICE SALES - PC

GST Reg.No: M28920628X

Singapore
Singapore 658353

Inv.No. : B&P 0 Page 1

Inv.date. : 15/08/2017

WIP No. : 13701

Veh.In/Out:

*Tel.No. : Mobile: 97331433

Reg.No. : SDU3331S

Reg.date : 30/09/2016

Mileage : 0

Chassis No: SALWAZKE3GA107066

Closed by : Chan Yau Chiang

Svc Consultant :

Remarks : Mr Lim Kue Lay

Tanphun 97495749

6/9/17 @ 1120

* Resurvey new parts

tanphun @ lkkauto.com

sur @ lkkauto.com

3 days.

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount G
-------	-------------	----------	-------	-------	-----	----------

802	TO REPLACE REAR BUMPER	0	1800.00	0	1,800.00	S 1200 ✓
800	TO SPRAY PAINT REAR BUMPER AND TAILGATE	0	2500.00	0	2,500.00	S 2000 ✓
280	WIRING CHECK AND REST ALL ELEC	0	324.00	0	324.00	S res ✓
	BUMPER COVER REAR RR	1.0 EA	1782.90		1,782.90	S ? 1604.61 de ✓
	BRACKET - BUMPER MOU	1.0 EA	150.60		150.60	S res 135.54 ✓
	BRACKET - BUMPER MOU	1.0 EA	197.90		197.90	S res 178.11 ✓
	REINFORCEMENT - REAR	1.0 EA	1108.60		1,108.60	S ? x nn ✓
	BUMPER MOULDING TOW	1.0 EA	427.70		427.70	S x x nn ✓
	BUMPER INSERT REAR R	1.0 EA	389.80		389.80	S dis 350.82 ✓
	PARKING AID 90 Degre	1.0 EA	401.30		401.30	S x nn ✓
	LLR045014/BADGE 'RAN	1.0 EA	196.10		196.10	S res 176.49 ✓
	BADGE 'ROVER' REAR R	1.0 EA	183.20		183.20	S res 164.93 ✓
	BADGE OVAL REAR RR3	1.0 EA	91.20		91.20	S res 82.08 ✓
	NAME PLATE EMBLEM	1.0 EA	241.40		241.40	S res 217.26 ✓
	FOG LAMP REAR RH RRS	1.0 EA	223.40		223.40	S res 201.06 ✓

Gross Total. 10,018.10

Labour Total 4,624.00
Parts Total 5,394.10
Package Total 0.00

Net..... 10,018.10

GST @ 7.0% 701.27

Total..... 10,719.35

Paid..... 0.00

Please Pay.. 10,719.35

GST: S=StdRated; O=OutOfScope; Z=ZeroRated

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SERVICE ESTIMATE

0 - A00003 SL: MSIG INSURANCE (SINGAPORE) PTE. LTD
 MSIG INSURANCE (SINGAPORE) PTE. LTD.
 4 SHENTON WAY #21-01
 SGX CENTRE 2
 SINGAPORE 068807

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 1
 Inv.date: : 28/03/2018
 WIP No. : 13701
 Veh.In/Out: 19/05/2017 25/05/2017
 *Tel.No. : 68277888
 Reg.No. : SDU3331S
 Reg.date : 30/09/2016
 Mileage : 0
 Chassis No: SALWA2KE3GA107066

Closed by : Mandy Neo
 Svc Consultant :
 Remarks : Mr Lim Kue Lay

Op.No	Description	Mech	Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE REAR BUMPER	0		1200.00	0		1,200.00	S✓
800	TO SPRAY PAINT REAR BUMPER	0		2000.00	0		2,000.00	S✓
AND TAILGATE								
280	WIRING CHECK AND REST ALL ELEC	0		324.00	0		324.00	S✓
NOTES	NOTES- DO NOT DELETE	0		0.00	0			S
	BUMPER COVER REAR RR 1	1.0	EA	1782.90	10		1,604.61	S
	BRACKET - BUMPER MOU 2	1.0	EA	150.60	10		135.54	S
	BRACKET - BUMPER MOU 3	1.0	EA	197.90	10		178.11	S
	BUMPER INSERT REAR R 6	1.0	EA	389.80	10		350.82	S
	LLR045014/BADGE 'RAN 8	1.0	EA	196.10	10		176.49	S
	BADGE 'ROVER' REAR R 9	1.0	EA	183.20	10		164.88	S
	BADGE OVAL REAR RR3 10	1.0	EA	91.20	10		82.08	S
	NAME PLATE EMBLEM 11	1.0	EA	241.40	10		217.26	S
	FOG LAMP REAR RH RRS 12	1.0	EA	223.40	10		201.06	S

Gross Total. 6,634.85
 Net..... 6,634.85
 GST @ 7.0% 464.44
 Total..... 7,099.29
 Paid..... 0.00
 Please Pay.. 7,099.29

Labour Total 3,524.00
 Parts Total 3,110.85
 Package Total 0.00

GST: S=StdRated; O=OutOfScope; Z=ZeroRated

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG17017278/T1TBN2

Date: 20/04/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	B27830946SMP
Claimant:	SDU3331S	Insured Vehicle No :	SCQ8078Z
Vehicle No :		Nature of Claim:	TP
Date of Loss:	11/08/2017	Claim No:	526423

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDU3331S	Engine No:	1070234306DT
Make & Model:	LAND ROVER RANGE ROVER, 3.0 D TDV6 TSS (A)	Chassis No:	SALWA2KE3GA107066
Reg. Date:	30/09/2016 (Man. Year: 2016)	Odometer:	25294 km
Colour:	Maroon		
Engine Capacity:	2993 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	255/55R20	Rear Tyre Size:	255/55R20
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	5,394.10	3,110.85	2,283.25	42.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,624.00	3,524.00	1,100.00	23.79
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	10,018.10	6,634.85	3,383.25	33.77
+ GST 7.00/7.00% (S\$)	701.27	464.44	236.83	33.77
Nett Amount (S\$)	10,719.37	7,099.29	3,620.08	33.77

INSPECTION

Date of Assignment:	06/09/2017	
Date Inspected:	06/09/2017 Inspected At:	45 Leng Kee Road Singapore 159103 Repairer: Wearnes Automotive Pte Ltd
Estimated Period of Repair:	3.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 20 Apr 2018)
Parts:	N/A LAND ROVER RANGE ROVER 3.0 D TDV6 TSS (A) (Model not available in database)
Labour:	Repairer's (Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SDU3331S)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER REAR RR	Deformed	1,782.90 FS	*1,604.61 FS
2	1		*BRACKET-BUMPER MOU	Necessary	150.60 FS	*135.54 FS
3	1		*BRACKET-BUMPER MOU	Necessary	197.90 FS	*178.11 FS
4	1		*REINFORCEMENT-REAR	Not Necessary	1,108.60 FS	*- FS
5	1		*BUMPER MOULDING TOW	Not Necessary	427.70 FS	*- FS
6	1		*BUMPER INSERT REAR R	Distorted	389.80 FS	*350.82 FS
7	1		*PARKING AID 90 DEGRE	Not Necessary	401.30 FS	*- FS
8	1		*LLR045014/BADGERAN	Necessary	196.10 FS	*176.49 FS
9	1		*BADGE ROVER REAR R	Necessary	183.20 FS	*164.88 FS
10	1		*BADGE OVAL REAR RR3	Necessary	91.20 FS	*82.08 FS
11	1		*NAME PLATE EMBLEM	Necessary	241.40 FS	*217.26 FS
12	1		*FOG LAMP REAR RH RRS	Cracked	223.40 FS	*201.06 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	5,394.10	3,110.85
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPLACE REAR BUMPER	New	1,800.00	1,200.00
2	TO SPRAY PAINT REAR BUMPER AND TAILGATE	New	2,500.00	2,000.00
3	WIRING CHECK AND RESR ALL ELEC	New	324.00	324.00
Gross Labour Cost (S\$)			4,624.00	3,524.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >