

22/09/2017

ASS. REC. BY:

REF: CS/MSG17017324/Arb n2

Special Instruction:

SWEETEN Adnan

ASSIGNMENT (Office)

From (Person): Christina Wong of MSGDate/Time: 7/9/17 11:47 am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GBC 67144Insured: GBE 3567Lat Workshop m/s SM AutomotiveTel: 6747 9241of Blk C-1, Kaki Bukit Ave 6 # 01-43 417883Policy No: D28844583MKCClaim No: 528807

Sum Insured:

Excess:

Make of Veh:
(Client's Record)D.O.A 06/09/2017

CA / REV / REP. / REV 24 HRS

'wp'

H.O.D. Endorsement:

Date/Time: 7/9/17 12:06 pm Person Contacted: RaenaVehicle IN OUT

Date/Time	Action/Instruction (✓) Estimate
	GBC 67144 - NA/MSG17017303/k4 - D.O.A: 6/9/2017
	GBE 3567L - NA/MSG17017303/k4 - D.O.A: 6/9/2017
1/12/17	Sent preli through merimen
	confirm l/s \$2K, 13 days
	led: \$27,44.80, 70%.




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (SINGAPORE) PTE LTD			Ref : CS/MSG17017324/Arb	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581			Date : 07-09-2017	
			Code : MSG	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBE 3567L	Veh. Inspected	GBC 6714U	
Policy No.	D28844583MKC	Coverage (\$)	0.00	
Claim No.	528807	Excess (\$)	0.00	
Assign From	MERIMEN (CHRISTINA WONG)	Assign Date	07/09/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	06/09/2017	Inspection Date	07/09/2017	
Survey held at	SM AUTOMOTIVE BLK C, 1 KAKI BUKIT AVENUE 6 #01-43 SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	06 Sep 2017		07 Sep 2017 11:47 Assign				New Assignment Cancel Case

[Main](#)[Reference](#)[Claim Details](#)[Documents](#)[Show All](#)

CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:	GRIFFIN KINETIC PTE LTD, Co. Reg. No.: -		
Main Claimant:	CREATIVE BEVERAGE INGREDIENTS PTE LTD, Co. Reg. No.: 200312236M		
Vehicle Reg. No.:	GBC6714U	Date of Loss:	06/09/2017 08:00 - :59
Claim Type:	TP / 528807	Policy/Cover Note No.:	D28844583MKC (Comprehensive) Coverage: 02/11/2016 - 01/11/2017
Vehicle Reg. No. (Insured):	GBE3567L	Policy No. (Claimant):	
		Excess:	
Repairer:	Sm Automotive - Kaki Bukit (HQ) BLOCK C - 1, KAKI BUKIT AVE 6, #01-43, 417883 Kaki Bukit - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 08/09/2017]		
Driver/Custodian (Insured):	MUHAMMAD TAWFIQ BIN MELING (), NRIC: S8622554I, Tel: +6591924496		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Print Sent Message

This mail is associated with :

***GBC6714U (528807)**

[GBE3567L]

TP

CREATIVE BEVERAGE INGREDIENTS PTE LTD

Sep 6 2017 8:00AM

[GRIFFIN KINETIC PTE LTD]

Sm Automotive - Kaki Bukit

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 07/09/2017 17:55 PM.
To christina_wong@sg.msg-asia.com
CC sur@lkkauto.com
Subject GBC6714U (528807)

Dear Christina,

Please be informed that we have inspected the vehicle **GBC 6714U** on 07/09/2017.

We are pending for estimate from repairer.

Thank you.

Regards,
Janice

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Christina Wong

Date: 01 Dec 2017

Preliminary Advice

Insured Vehicle No	: GBE3567L	Accident Date	: 06/09/2017
TP Vehicle No	: GBC6714U	Assignment Date	: 07/09/2017
Make	: TOYOTA HIACE	Est. Duration of Repair	: 13.00
Date of Inspection	: 07/09/2017		
Inspection At	: SM AUTOMOTIVE - KAKI BUKIT (HQ) BLOCK C - 1, KAKI BUKIT AVE 6, #01-43 SINGAPORE 417883		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front and rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	39,979.80
Revised Amount	:S\$	15,052.25
Check Items (Estimated)	:S\$	0.00
Total	:S\$	15,052.25

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

MSME17118308 / SME Motor Pte Ltd - Kaki Bukit
ENTRY DATE & TIME: 08/09/2017 17:36

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	06/09/2017 17:36
Date Of Accident	06/09/2017 08:30
Exact Location Of Accident	SLE (BKE) BEFORE UPP THOMSON FLYOVER
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBC6714U
Insured/Policyholder	
Name Of Registered Owner	CREATIVE BEVERAGE INGREDIENTS PTE LTD
Co Reg No	200312236M
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-67416638
Vehicle Particulars	
Manufacturer	TOYOTA
Model	HIACE
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	TOKIO MARINE INSURANCE SINGAPORE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	17-MX003072-R03
Cover Note Number	
Driver	
Name of Driver	TANG BOON WHA
NRIC No	S1557451H
Date Of Birth	03/12/1962
Occupation	INDOOR
Date Of Driving Pass	21/12/1982
Driving Experience	34 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93853294
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address BLK 448 HOUGANG AVE 10 #11-537
 Postcode 530448
 Was driver an employee of the Insured's Company YES
 If No, Relationship of the Driver with the Insured
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident CHAIN COLLISION
 Weather Conditions DRIZZLING
 Road Surface WET

Other Information

Was any foreign vehicle involved in this accident? NO
 Was any body injured in the Accident? YES
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

I WAS TRAVELLING AONG SLE (BKE) ON THE CENTER LANE OF THREE LANES. VEHICLE IN FRONT SLOWED DOWN AND STOPPED, I FOLLOWED SUIT. SUDDENLY, I FELT AN IMPACT. VEHICLE B HIT ON THE REAR PORTION OF MY VEHICLE AND CAUSED DAMAGES. THE STRONG IMPACT CAUSED MY VEHICLE TO SURGE FORWARD AND HIT ONTO VEHICLE C. I ALIGHTED AND REALISED IT WAS A 3 CARS CHAIN COLLISION.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBE3567L
 Vehicle Make/Model/Colour
 Details Of Properties VEHICLE B
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

Details of Witness

Name
 Phone Number
 Email Address

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SJD2029R
Vehicle Make/Model/Colour
Details Of Properties VEHICLE C
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

Details of Witness

Name
Phone Number
Email Address

DETAILS OF INJURED PERSON 1

Name TANG BOON HWA
Approximate Age
Injuries Sustain
Injured person in which vehicle? GBC6714U
Were seat belts worn?
Was injured conveyed to hospital by ambulance?
Address
Postcode

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Traffic Police Department for investigation.
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

<p>SLE (3KE) Before Upper Thomson Flyover</p> <p>A: ABC6714U B: ABE3567L C: SJD2079R</p>	<p>↓</p> <p>↑</p>	
--	-------------------	--

I was travelling along LE (BKE) on the centre lane of three lanes.

Vehicle in front slowed down and stopped. I followed suit. Suddenly, I felt an impact. Vehicle B hit on the rear portion of my vehicle and caused damages.

The strong impact caused my vehicle to surge forward and hit onto vehicle C. I awoke and realised it was a three cars chain collision.

I/We declare the foregoing particulars are true in every respect.

Witnessed by Reporting
Centre Personnel

Insurance Co. : _____
Vehicle NO. : _____ Date of Accident: ____/____/____

- ☐ Reporting Only
☐ Own Damage
☐ Third Party Claim

Text size + -

Enquire PARF/COE Rebate for Registered Vehicle**Vehicle Owner Particulars**

Owner ID Type: Company

Owner ID: 2236M

Vehicle Details

Vehicle No.: GBC6714U

Vehicle to be Exported: Yes

Intended De-registration
Date: 06 Sep 2017

Vehicle Make: TOYOTA

Vehicle Model: HIACE MANUAL

Primary Colour: Silver

Manufacturing Year: 2013

Engine No.: 1KD2295660

Chassis No.: JTFHT02P000115645

Maximum Power Output: -

Open Market Value: \$25,820.00

Original Registration Date: 23 May 2013

First Registration Date: 23 May 2013

Transfer Count: 0

Actual ARF Paid: \$1,291.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry
Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 22 May 2023

COE Category: C - Goods Vehicle & Bus

COE Period(Years): 10

QP Paid: \$56,011.00

COE Rebate Amount: \$31,980.00

Total Rebate Amount: \$31,980.00

The information contained herein is correct as at 06 Sep 2017

OK

Land Transport Authority

Please read through the Privacy Statement, Terms of Use and Disclaimer.
Please do not use the **Back** or **Forward** buttons on your browser as this may alter the results of the transactions.
Best viewed with IE 6.0 SP3 and above. 1024 X 768 resolution



FREE HELP
FOR DIRECT BUYERS & SELLER
 100% FREE SETTLEMENT ON LOANS, INSURANCE & PAPERWORK



Username / Email Add

password

Connect Sign Up New Account
 Forgot Password

Post an Advertisement
 Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad Advertiser Login Ways of Selling

BMW 530Ci Cabriolet.



The Best Cabriolet Fit 4 Adults
 Comfortably. Enjoy The
 Convertible Drive.
 Direct Owner StarAd

KA-HUP

VALUE FOR MONEY
VALUE FOR TIME
A PEACE OF MIND

HOTLINE: 6741 9997 **VIEW OUR CARS**

Browse by Category ▼

Sort by Date Posted ▼

20 results/page ▼

2 vehicles

Hiace

Advanced Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Hiace		Any	Any	2013	Any	Any	Any	Available
	Toyota	Hiace	\$57,800	\$10,090 /yr	30-May-2013	2,982 cc	85,921 km	Van	Available
	Fuel Type: Diesel Cheapest In The Market! Most Reliable Japanese Big Van. Borneo Unit. Low Maintenance. Very Good Condition. Test Drive To Believe. High Loan And High Trade In Welcome. Call For Exact Location. Abwin Van Pte Ltd Posted: 06-Sep-2017 Tags: 2013 Toyota Hiace, Toyota Hiace, Toyota, Hiace, Used Toyota								
	Toyota	Hiace	\$72,800	\$11,560 /yr	24-Dec-2013	2,982 cc	-	Bus	Available
	Fuel Type: Diesel Car As Good As New, Cheapest In The Market! New 1 Year Road Tax! Urgent Sales, Owner Leaving Country! Seldom Driven, Kept At Home Always. Genuine Mileage! High Loan Available! Bring Along Your Deposit... Posted: 14-Jul-2017 Tags: 2013 Toyota Hiace, Toyota Hiace, Toyota, Hiace, Used Toyota								

Save this search criteria, to get email alerts whenever a match is found.

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view Expired ads

20 results/page

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Find buy used Hiace, Hiace Singapore, used Hiace Singapore, used Hiace, used vehicles Singapore or even buy used Hiace Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, massage services, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current, sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

- Home
- New Car
- Used Car
- Sell Car
- Motoring Directory
- Products Guide
- Article
- Forum
- Tool & Tip

- About Us
- Careers
- Contact Us
- Sitemap

© 2004-2017 sgCarMart. All rights reserved.

- Terms of Service
- Privacy Policy
- Personal Data Protection Statement

SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241 Fax: (65) 6741 7276

RCB No.: 53231488C

18/9/2017

CREATIVE BEVERAGE INGREDIENTS PTE LTD

Blk C, 1 Kaki Bukit Ave 6

01-43

Singapore 417883

7pms19.

Janice

Accident date: 06/09/2017

Estimated repair cost for vehicle no: GBC6714U TOYOTA HIACE MANUAL 3.0 '13

CHASSIS: JTFHT021000115645

S/n	Qty	Items	U/price	Amount
1	1	Front Bonnet <i>Painted</i>		\$844.60 ✓
2	2	Front Bonnet Hinge <i>2 new</i>	\$89.90	\$179.80 ✓
3	1	Front Bonnet Lock <i>1 new</i>		\$98.90 ✓
4	1	Front Bonnet Emblem Logo <i>new</i>		\$79.90 ✓
5	2	Front Head Lamp <i>cracked</i>	\$898.90	\$1,797.80 1528 ✓
6	1	Front Grille <i>cracked</i>		\$467.90 ✓
7	1	Front Bumper <i>Deformed</i>		\$458.90 ✓
8	10	Front Bumper Clip <i>new</i>	\$6.50	\$65.00 30 ✓
9	2	Front Bumper Side Retainer <i>new</i>	\$179.90	\$359.80 139 ✓
10	1	Front Bumper Number Plate <i>Best</i>		\$50.00 25(SW) ✓
11	1	Front Bumper Reinforcement <i>new</i>		\$298.90 ✓
12	1	Front Bumper Lower Reinforcement <i>Best</i>		\$229.80 ✓
13	1	Front Bumper Top Beam <i>Best</i>		\$169.90 ✓
14	2	Front Bumper Fog Lamp Cover <i>new</i>	\$69.90	\$139.80 ✓
15	1	Front Support Panel <i>new</i>		\$329.90 ✓
16	2	Front Support Panel Top Cover <i>new</i>	\$149.90	\$299.80 ✓
17	1	Front Air-Con Condenser <i>Best</i>		\$1,699.00 1431.90 ✓
18	1	Front Radiator <i>new</i>		\$2,007.90 ✓
19	1	Front Radiator Spare Tank <i>new</i>		\$515.90 ✓
20	1	Front Intercooler <i>new</i>		\$1,399.90 ✓
21	1	Front Wiper Tank <i>new</i>		\$79.90 ✓
22	1	Rear Boot Lid <i>Distorted</i>		\$1,950.90 1788.10 ✓
23	2	Rear Boot Lid Hinge <i>new</i>	\$79.90	\$159.80 ✓
24	2	Rear Boot Lid Shock Absorber <i>new</i>	\$299.20	\$598.40 ✓
25	1	Rear Boot Lid Emblem Logo <i>new</i>		\$79.90 ✓
26	1	Rear Boot Lid Toyota Hiace Sticker <i>new</i>		\$89.90 ✓
27	1	Rear Boot Lid Number Plate <i>Best</i>		\$50.00 25(SW) ✓
28	2	Rear Boot Lid Number Plate Lamp <i>new</i>	\$123.90	\$247.80 ✓
29	1	Rear Boot Lid Centre Moulding <i>Deformed</i>		\$149.90 ✓

30	4	Rear Boot Lid Lower Inner Side Clutch	1 Brgd	\$89.90	\$359.60	89.90
31	1	Rear Boot Lid Inner Lock	Drgd		\$268.70	✓
32	1	Raer Boot Lid Inner Lock Cover	Alm		\$149.90	X
33	1	Rear Boot Lid Inner Rubber	lt		\$391.90	✓
34	1	Rear Boot Lid Inner Trim Board	horn		\$469.90	195
35	10	Rear Boot Lid Inner Trim Board Clip	slm	\$6.50	\$65.00	20
36	1	Rear Boot Lid Wiper	2		\$89.90	X
37	1	Rear Boot Lid Wiper Arm	mt		\$139.90	X
38	1	Rear Boot Lid Wiper Motor	mt		\$595.90	X
39	1	Rear Boot Lid Top Side Mirror	↓		\$479.90	X
40	1	Rear Boot Lid Windscreen	Shattered		\$1251.70	✓
41	1	Rear Boot Lid Windscreen Seal	nm		\$95.00	✓
42	2	Rear Tail Lamp	LH Smashed	\$229.90	\$459.80	229.90
43	4	Rear Tail Lamp Clip	m	\$8.00	\$32.00	16
44	2	Rear Tail Lamp Panel	Dented LH	\$372.50	\$745.00	372.50
45	2	Rear Tail Lamp Inner Panel	epir	\$381.45	\$762.90	X
46	2	Rear Tail Lamp Lower Cover	LH Deformed	\$132.10	\$264.20	132.10
47	2	Rear Tail Lamp Lower Cover Side Retainer	nm	\$132.25	\$264.50	X
48	1	Rear Bumper	Deformed		\$374.80	✓
49	8	Rear Bumper Clip	nm	\$6.50	\$52.00	30
50	2	Rear Bumper Side Retainer	m	\$62.60	\$125.20	✓
51	1	Rear End Panel Outer	Dented		\$326.90	✓
52	1	Rear End Panel Inner	↓		\$994.90	681.20
53	6	Rear End Panel Top Clip	nm	\$6.50	\$39.00	X
54	1	Rear End Panel Top Moulding	3mm		\$274.45	X
55	6	Rear End Panel Top Moulding Clip	↓	\$6.50	\$39.00	X
56	1	Rear Spare Tyre Bracket	nm		\$289.90	X
57	1	Rear L/H Fender	Buckled		\$1,712.85	✓
58	1	Rear L/H Fender Air Duct	crushed		\$174.45	✓
59	1	Rear L/H Fender Inner Panel	epir		\$374.85	X
60	1	Rear L/H Fender Sliding Door Moulding	2mm		\$172.10	X
61	1	Rear L/H Fender Sliding Door Moulding Cover	Deformed		\$138.10	✓
62	1	Rear Floor Panel	epir		\$1,218.50	X
63	1	Rear Exhaust	2mm		\$791.40	X
64	1	Rear Centre Exhaust	↓		\$1,218.50	X
65	1	Reverse Sensor	Drgd		\$350	200/500
				Subtotal :-	\$29,819.80	

14125
10593.75

SP. 250

Labour charges

To remove & refit air-con condenser, radiator, fan motor
& top up gas

~~\$450.00~~ 120

To remove & refit reverse sensor

~~\$100.00~~ 50

To remove & refit rear windscreen

~~\$120.00~~ 100

Gum *new*

~~\$50.00~~ ✓

To remove & refit plywood & carpet

~~\$380.00~~ 200

To remove & refit rear & centre exhaust

~~\$380.00~~ X

To remove & refit body logo

4210

~~\$450.00~~ 280

To remove & refit roof lining

~~\$380.00~~ X

To check wiring

~~\$100.00~~ 30

Towing fee

~~\$100.00~~ X

Tuff kote

~~\$150.00~~ 80

Panel beating

~~\$4,500.00~~ 1800

Spray painting

~~\$3,000.00~~ 1500

Subtotal :- \$10,160.00

Total:- \$39,979.80

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total: 15053.75

H/S: 12K

130 days

40612.50

12K

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG17017324/ARB2

Date: 04/12/2017

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	D28844583MKC
Claimant Vehicle No :	GBC6714U	Insured Vehicle No :	GBE3567L
Date of Loss:	06/09/2017	Nature of Claim:	TP
		Claim No:	528807

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBC6714U	Engine No:	1KD2295660
Make & Model:	TOYOTA HIACE, 3.0 (A)	Chassis No:	JTFHT02P000115645
Reg. Date:	23/05/2013 (Man. Year: 2013)	Odometer:	137368 km
Colour:	Silver		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195R15C	Rear Tyre Size:	195R15C
Front Left Side:	Firestone 6 mm	Rear Left Side:	Firestone 6 mm
Front Right Side:	Firestone 6 mm	Rear Right Side:	Firestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	30,502.50	10,892.25	19,610.25	64.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,110.00	4,160.00	5,950.00	58.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	40,612.50	15,052.25	25,560.25	62.94
Approved Total (Overridden) (S\$)		12,000.00		
Nett Amount (S\$)	40,612.50	12,000.00	28,612.50	70.45

INSPECTION

Date of Assignment:	07/09/2017	
Date Inspected:	07/09/2017 Inspected At:	Sm Automotive - Kaki Bukit (HQ) BLOCK C - 1, KAKI BUKIT AVE 6, #01-43 Singapore 417883

Estimated Period of Repair: 13.0 days

Adjuster: ADRIAN LING

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 04 Dec 2017)	
Parts:	N/A	TOYOTA HIACE 3.0 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBC6714U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Dented	844.60 F	*844.60 FL
2	2		*FRONT BONNET HINGE	Not Necessary	179.80 F	*- FL
3	1		*FRONT BONNET LOCK	Not Necessary	98.90 F	*- FL
4	1		*FRONT BONNET EMBLEM LOGO	Necessary	79.90 F	*79.90 FL
5	2		*FRONT HEAD LAMP	Cracked	1,797.80 F	*1,528.00 FL
6	1		*FRONT GRILLE	Cracked	467.90 F	*467.90 FL
7	1		*FRONT BUMPER	Deformed	458.90 F	*458.90 FL
8	10		*FRONT BUMPER CLIP	Necessary	65.00 F	*30.00 FL
9	2		*FRONT BUMPER SIDE RETAINER	Necessary	359.80 F	*139.00 FL
10	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	298.90 F	*- FL
11	1		*FRONT BUMPER LOWER REINFORCEMENT	Bent	229.80 F	*229.80 FL
12	1		*FRONT BUMPER TOP BEAM	Bent	169.90 F	*169.90 FL
13	2		*FRONT BUMPER FOG LAMP COVER	Not Necessary	139.80 F	*- FL
14	1		*FRONT SUPPORT PANEL	Repair	329.90 F	*- FL
15	2		*FRONT SUPPORT PANEL TOP COVER	Not Necessary	299.80 F	*- FL
16	1		*FRONT AIR-CON CONDENSER	Bent	1,699.00 F	*1,431.90 FL
17	1		*FRONT RADIATOR	Not Necessary	2,007.90 F	*- FL
18	1		*FRONT RADIATOR SPARE TANK	Not Necessary	515.90 F	*- FL
19	1		*FRONT INTERCOOLER	Not Necessary	1,399.90 F	*- FL
20	1		*FRONT WIPER TANK	Not Necessary	79.90 F	*- FL
21	1		*REAR BOOT LID	Distorted	1,950.90 F	*1,798.10 FL
22	2		*REAR BOOT LID HINGE	Not Necessary	159.80 F	*- FL
23	2		*REAR BOOT LID SHOCK ABSORBER	Not Necessary	598.40 F	*- FL
24	1		*REAR BOOT LID EMBLEM LOGO	Necessary	79.90 F	*79.90 FL
25	1		*REAR BOOT LID TOYOTA HIACE STICKER	Necessary	89.90 F	*89.90 FL
26	2		*REAR BOOT LID NUMBER PLATE LAMP	Not Necessary	247.80 F	*- FL
27	1		*REAR BOOT LID CENTRE MOULDING	Deformed	149.90 F	*149.90 FL
28	1		*REAR BOOT LID LOWER INNER SIDE CLUTCH (4 Pcs)	Damaged (1Pc only)	359.60 F	*89.90 FL
29	1		*REAR BOOT LID INNER LOCK	Damaged	268.70 F	*268.70 FL
30	1		*REAR BOOT LID INNER LOCK COVER	Not Necessary	149.90 F	*- FL
31	1		*REAR BOOT LID INNER RUBBER	Damaged	391.90 F	*391.90 FL
32	1		*REAR BOOT LID INNER TRIM BOARD	Torn	469.90 F	*195.00 FL
33	10		*REAR BOOT LID INNER TRIM BOARD CLIP	Necessary	65.00 F	*20.00 FL
34	1		*REAR BOOT LID WIPER	Not Necessary	89.90 F	*- FL
35	1		*REAR BOOT LID WIPER ARM	Not Necessary	139.90 F	*- FL
36	1		*REAR BOOT LID WIPER MOTOR	Not Necessary	595.90 F	*- FL
37	1		*REAR BOOT LID TOP SIDE MIRROR	Not Necessary	479.90 F	*- FL
38	1		*REAR BOOT LID WINDSCREEN	Shattered	1,251.70 F	*1,251.70 FL
39	1		*REAR BOOT LID WINDSCREEN SEAL	Necessary	95.00 F	*95.00 FL
40	1		*REAR TAIL LAMP	N/s Smashed	459.80 F	*229.90 FL
41	4		*REAR TAIL LAMP CLIP	Necessary	32.00 F	*16.00 FL
42	2		*REAR TAIL LAMP INNER PANEL	Repair	762.90 F	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*REAR TAIL LAMP PANEL	N/s Dented	745.00 F	*372.50 FL
44	1		*REAR TAIL LAMP LOWER COVER	N/s Deformed	264.20 F	*131.20 FL
45	2		*REAR TAIL LAMP LOWER COVER SIDE RETAINER	Not Necessary	264.50 F	*- FL
46	1		*REAR BUMPER	Deformed	374.80 F	*374.80 FL
47	8		*REAR BUMPER CLIP	Necessary	52.00 F	*30.00 FL
48	2		*REAR BUMPER SIDE RETAINER	Necessary	125.20 F	*125.20 FL
49	1		*REAR END PANEL OUTER	Dented	326.90 F	*326.90 FL
50	1		*REAR END PANEL INNER	Dented	994.90 F	*681.20 FL
51	6		*REAR END PANEL TOP CLIP	Not Necessary	39.00 F	*- FL
52	1		*REAR END PANEL TOP MOULDING	Not Necessary	274.45 F	*- FL
53	6		*REAR END PANEL TOP MOULDING CLIP	Not Necessary	39.00 F	*- FL
54	1		*REAR SPARE TYRE BRACKET	Not Necessary	289.90 F	*- FL
55	1		*REAR L/H FENDER	Buckled	1,712.85 F	*1,712.85 FL
56	1		*REAR L/H FENDER AIR DUCT	Cracked	174.45 F	*174.45 FL
57	1		*REAR L/H FENDER INNER PANEL	Repair	374.85 F	*- FL
58	1		*REAR L/H FENDER SLIDING DOOR MOULDING	Not Necessary	172.10 F	*- FL
59	1		*REAR L/H FENDER SLIDING DOOR MOULDING COVER	Deformed	138.10 F	*138.10 FL
60	1		*REAR FLOOR PANEL	Repair	1,218.50 F	*- FL
61	1		*REAR EXHAUST	Not Necessary	791.40 F	*- FL
62	1		*REAR CENTRE EXHAUST	Not Necessary	1,218.50 F	*- FL
63	1		*REVERSE SENSOR	Damaged	350.00 FS	*200.00 FS
64	1		*FRONT NUMBER PLATE LAMP	Bent	50.00 FS	*25.00 FS
65	1		*REAR BOOT LID NUMBER PLATE	Bent	50.00 FS	*25.00 FS
66	1		*GUM	Necessary	50.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	30,502.50	14,423.00
- List Item Discount on L Items 0.00/25.00% (S\$)	0.00	3,530.75
Total Parts (S\$)	30,502.50	10,892.25

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REFIT AIR-CON CONDENSER,RADIATOR,FAN MOTOR & TOP UP GAS	New	450.00	120.00
2	TO REMOVE & REFIT REVERSE SENSOR	New	100.00	50.00
3	TO REMOVE & REFIT REAR WINDSCREEN	New	120.00	100.00
4	TO REMOVE & REFIT PLYWOOD & CARPET	New	380.00	200.00
5	TO REMOVE & REFIT REAR & CENTRE EXHAUST	New	380.00	-
6	TO REMOVE & REFIT BODY LOGO	New	450.00	280.00
7	TO REMOVE & REFIT ROOF LINNING	New	380.00	-
8	TO CHECK WIRING	New	100.00	30.00
9	TOWING FEE	New	100.00	-
10	TUFF KOTE	New	150.00	80.00
11	PANEL BEATING	New	4,500.00	1,800.00
12	SPRAY PAINTING	New	3,000.00	1,500.00
Gross Labour Cost (S\$)			10,110.00	4,160.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >