

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way #07-16  
Singapore 079120

**Our File No:** CC3/AIG17017412/ATBS2**Date:** 01/03/2018REFERENCE

Insured/Claimant:	LIEW FU TANG	Policy No:	2100508922	
Date of Loss:	04/09/2017	Nature of Claim:	OD	Claim No: 9834545525SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SLN3790S</b>	Engine No:	CYG016752
Make & Model:	AUDI A6, 1.8 TFSI S-tronic (C7) (A)	Chassis No:	WAUZZZ4G6HN043830
Reg. Date:	28/04/2017 (Man. Year: 2016)	Odometer:	8656 km
Colour:	White		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	S\$200,000.00		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/55R17	Rear Tyre Size:	225/55R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

*The above values represent the remaining tyre tread depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	13,812.60	9,600.80	4,211.80	30.49
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,572.00	2,522.00	1,050.00	29.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>17,384.60</b>	<b>12,122.80</b>	<b>5,261.80</b>	<b>30.27</b>
<b>- Excess (S\$)</b>	400.00	400.00	0.00	0.00
<b>(S\$)</b>	16,984.60	11,722.80	5,261.80	30.98
<b>+ GST 7.00/7.00% (S\$)</b>	1,188.92	820.60	368.32	30.98
<b>Nett Amount (S\$)</b>	<b>18,173.52</b>	<b>12,543.40</b>	<b>5,630.12</b>	<b>30.98</b>

INSPECTION

Date of Assignment:	08/09/2017	
Date Inspected:	08/09/2017	Inspected At: Premium Automobiles Pte Ltd (HQ) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	4.0 days	

**Adjuster:** ADRIAN LING**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,445.00 FS	*1,956.00 FS
2	1		*FRONT BUMPER GRILLE	Not Necessary	106.00 FS	*- FS
3	14		*LOCKING CLIP	Not Necessary	47.00 FS	*- FS
4	1		*FOAM FILLER	Not Necessary	193.00 FS	*- FS
5	1		*REINFORCEMENT BEAM	Not Necessary	674.00 FS	*- FS
6	1		*FRONT PARKING SENSOR OUTER	Not Necessary	208.00 FS	*- FS
7	1		*HEADLAMP MOUNTING RH	Not Necessary	100.00 FS	*- FS
8	1		*LIFT CYLINDER RH	Not Necessary	204.00 FS	*- FS
9	1		*LED HEADLAMP RH	Cracked	9,454.00 FS	*7,563.20 FS
10	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS
11	1		*TONE CHIP GUARD - RHS	Necessary	81.60 FS	*81.60 FS
Total Parts (S\$)					13,812.60	9,600.80

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	New	480.00	480.00
2	TO DISMANTLE AND RENEW FRONT BUMPER AND RHS HEADLIGHT. RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	New	1,400.00	750.00
3	TO RESPRAY FRONT BUMPER AND FRONT RH FENDER.	New	1,500.00	1,100.00
4	TO CARRY OUT DIAGNOSTIC CHECKS.	New	192.00	192.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,572.00</b>	<b>2,522.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >