Surveyor Adrian	REF-CS/EQ117017701 ASSIGNMENT	(Ofc.	
From (Person): Ya Pu L	of Ergo	Frate/Firme	13/1/12/10/10
	75'11	to	
OD/FP WS/TP RES/OD 1	RESTEVATINVIMVICS	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	
To Inspect Vehicle No:	SJW3567 Y	Insured: GBF	7532S
		da	628721
of 60 woodlands Inc	Park EH, 757705		
roncy 146	C	aim No: GB195329 /SE/	
Sum Insured:		Excess:	
Make of Veh: (Client's Record)			0/09/2017
· · · · ·	\)	401-60, 1 kajui Buluit	109 2017 Ava 6
CA / REV / REP. / REV 24	MKS 1		orsement.
Date/Time: 13/4/17 11:00	m_Person Contacted C	ther Vehicle (ID)	
Date/Time Action/Instructio			
C0000001	Y- NA 1 AIC10015518/w	1-0.0A: 5/8/2010	
- GBF95328	· X	· · · · · · · · · · · · · · · · · · ·	
	·		

, 100 11 REF:	
ASS. REC. BY: Adrian Liny	
ASS	SIGNMENT
From: Date:	Veh No: SJW 3567 Y Yr Regn: 2010 / March
Estimated Cost:	Type: M.Cary M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD / TP / WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
To Inspect Vehicle No:	Make: Paihatsy Sirion c.c 1298.
at Workshop m/s	Colour Green . A/C: Insured / Std / NI / NA
of	Sp.Reading 55092 T/Radio: Insured / Std / NI / NA
Insured:	Eng/No:
Policy No.	C/No: JDAM 301500 11050 603
Claims No.	Gen. Condi Good / Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Morde: / Jammed / Leaked / Burnt or
(Client's Record)	Brake: anorde / Jammed / Leaked / Burnt or
Make of Veh:	Modi: ND/S/Rim / STD A/Rim or
	Tyre Size: F: 175/65R14
(Policy Condition)	175/63R14
Remark: The veh had commenced its N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO/YOKO or Continents
Bal. or Market Value:	
IDAC Accident Rport: Consistent?: Yes or No	DID-I
GIA / PR Seen: Consistent?: Yes or No	
Est. Repairs: days Res.: Yes or No	D.O.A. D.O.I. 13/08/17,
Lum Sum: % 3 Val.: Yes or No	Survey held at SMRT.
	
CA / REV / REP. / 24 HRS Vehicle: IN / OUT	Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Date:Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction	- Ino ore removed trainer array continues
TP Ergo.	
U	
Confirm \$ 4.600, 9 days	
led:\$10,379.85, 687.	
1,27 17 17 17 17 17 17 17 17 17 17 17 17 17	13)
A second of the	
Date/Time, File Pass to? : Prefi. Report	Days Of Repair: 9
: Final Report	Resurvey No. of Trip: Survey Fee: 350
Date/Time, File Return to?	Transportation:
Add Fee	
TD	: Interview (\$) Photos
Report Format: TP	: Tech. Invs (\$) Others
_ump Sum / I .B.1 : (\$4&00)	: Weekend (\$)
	TOTAL 350



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

7.7 ¥		Affiliated to Federation Interna	ationale Des Experts En Automob	ile
ERO	30 INSURANCE P	TE LTD	Ref : CS/EGI17017701	/Arb
#04	EMASEK BOULEV -01 SUNTEC TOW GAPORE 038985		Date: 13-09-2017 Code: EGI	
1.		Policy Particula	rs :- THIRD PARTY CLAIM	
	Insured Veh.	GBF 9532S	Veh. Inspected	SJW 3567Y
	Policy No.		Coverage (\$)	0.00
	Claim No.		Excess (\$)	0.00
	Assign From	YEE PEI LI	Assign Date	13/09/2017
2.		Vehicle Pa	rticulars & Condition	· · · · · · · · · · · · · · · · · · ·
	Make & Model		c.c	0
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.		Colour	
	Odometer	-	Steering	
	Brakes		Modification	
	General			
3.		Conc	litions of Tyres	
-		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm
4.		Descrip	otion of Damages	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
5.	A State of the sta	Gene	ral Information	
	Accident Date	10/09/2017	Inspection Date	13/09/2017
	Survey held at	1 KAKI BUKIT AVE 6 #01-60		
	Repairer	SMRT AUTOMOTIVE SERVI	CES PTE LTD	
5a.	(Beneval)		Remarks	
	A)THE INSPECTIO	N WAS CONDUCTED ON A"V	VITHOUT PREJUDICE" BASIS.	
	R)IN ACCORDANG	CE TO YOUR INSTRUCTIONS,	WE HAVE NOT AUTHORISED	REPAIRS.

Catherine Chong (LKK Auto)

From: Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>

Sent: Wednesday, 13 September, 2017 10:10 AM

 To:
 'admin-d@lkkauto.com'

 Subject:
 OI : GBF9532S / TP : SJW3567Y/LKK / DOA : 10.09.2017

Attachments: GBF9532S - SAS.pdf; SJW3567Y - SAS.pdf; SJW3567Y - PRS FORM.pdf; SJW3567Y -

estimate.pdf; Our Ref SJW3567Y - TP CLAIMS ERGO DOA 07 Jul 2017 Your Ref GBF

9532S (236 KB)

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please assist to conduct this survey from **SMRT AUTOMOTIVE SERVICES PTE LTD**,

ADDRESS : PLEASE CONFIRM WITH ESTHER

PERSON TO CONTACT : ESTHER @ 9862 8721

ERGO OFFICER-IN-CHARGE : STEVE LIM

Note: To survey on without prejudice basis. Please advise the consistency of damages to third party vehicle that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are estimate, insured and third party SAS (note: reports not to be released to any Third Party).

Kindly acknowledge receipt of this email.

Thank you

Best Regards
Yee Pei Li
Claims Assistant (Motor)
ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985

Tel: 65 6829 9199 / DID: 65 6829 9194

Fax: 65 6829 9247 Website: www.ergo.com.sg



51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: GBF9532S/SE/pl Our Ref: CS/EGI17017701/Arb

The Motor Claims Department ERGO Insurance Pte Ltd

Without Prejudice

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO. SJW 3567Y .

Please be informed that we had conducted the inspection of the above mentioned vehicle on 13/09/2017 at the premises of M/s SMRT AUTOMOTIVE SERVICES PTE LTD and have the following to report:-

Workshop Estimate Amount	: <u>S\$ 15,179.85</u>	<u>. </u>
Revised Estimate Amount	: S\$ 6,042.00	<u> </u>
"Check" Items Amount	: <u>S\$</u>	
Market Value	: <u>S\$</u>	
LTA Reimbursement Value	: <u>S\$</u>	
Nett Value	: <u>S\$ </u>	.

Description of Damage: The vehicle sustained damages at the rear o/s portion.

rear front offside

Comments/ Present Status: Damages Consistent.

Yours faithfully

ADRIAN Automotive Assessor

ERGO

Date:	13.09.2017		Sent via Fax		
Our Reference:	GBF 9532S/SE/pl	_			-
Your Reference:	SJW 3567Y		or	<u> </u>	
rour neierence.		_	Email		
To:	SMRT AUTOMOTIVE SERVIC	ES PTE LTD		L	ChorKeng@smrt.com.sg
Pre-Repair Su	vey (PRS) Acknowledgement		18	nig offi	1
Vehicle For Inspe			11.0	$y \sim y$	<i>x</i> : <i>'</i> .
Insured's Vehicle	GBF 9532S	_	`	1, ^{(X} 62)	res.
Date Of Accident				, , , , , , , , , , , , , , , , , , ,	
We acknowledge	receipt of your request for PRS on:	 12.09.2017			
			-		
the list below an	th "State Courts Practice Directions Am	endment No.1 of	2016", do se!	ect an asse	ssor from
the list below and	d indicate your selection in the box mar	ked *.	:	*	LKK
AIS	Automobile Inspection Services Pte Ltd	l les	T		
FTA	FormTeam Consultancy Pte Ltd	LBS	L.B.S Auto Con		
	Infiniti Appraisal Service	PS	Priority Service		td
JPK	JP Knights Pte Ltd	VAC	Vicom Ltd	:5	
Your request We acknowle	t for inspection does not have your client's of the inspection does not have your client's of the inspection does not have your client's of the decident in the inspection of the accident to us of the inspection of the accident to us of the inspection of the inspec	SIA report, kindly fo will assess & rever todate.	orward a copy. t soon upon rece	eipt of estim	ate.
-		······································			
Prepared by: iignature:	te.	Pei Li	6829 91	<u>-</u>	laims@ergo.com.sg AX: 6829 9247
ssessor use only:		3441-1			
ssignment Date: ssignment Time: emarks:		Workshop use only Assessor attended Date: Time Inspector: Vehicle not availab	workshop on:		
		Norkshop Acknowl Note: Our Inspectio	edgement & Sta		

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

profession.		
	ACCIDENT STATEMENT	
Date Of Report	11/09/2017 11:51	
Date Of Accident	10/09/2017 19:15	
Exact Location Of Accident	768 WOODLAND MART CARPARK	
Country/State of Loss	SINGAPORE	

	DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SJW3567Y	

Insured/Policyholder

Name Of Registered Owner TAN TIONG YIT S7427693H NRIC No.

VAPORAIDEN@GMAIL.COM **Email Address** Mobile Phone No (LOCAL) +65-98626755 Alternative Phone No OFFICE-68841317

Vehicle Particulars

Manufacturer **DAIHATSU** SIRION-1.3 (A) Model

Exact Purpose for which vehicle was being used at PTE USED time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

THIRD PARTY

If No, Please state action to be taken Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

Type Of Coverage COMPREHENSIVE

Fleet Policy NO

DMPCSN1741951700 Policy Number

Cover Note Number

Driver

Name of Driver LOOI WAN TECK KELVIN

NRIC No S8017171D Date Of Birth 16/06/1980 Occupation **INDOOR** Date Of Driving Pass 03/02/2004

13 YEARS AND 7 MONTHS **Driving Experience**

MALE Gender

(LOCAL) +65-98768660 Mobile Number

Fax Number

Contact Number

VAPORAIDEN@GMAIL.COM **EMail Address**

Address

BLK 364 WOODLANDS AVE 5 #07-482

Postcode

730364

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

RELATIVE

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Was any body injured in the Accident?

NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

0

Details of Police Action

Was the accident reported to the police?

NO

If Yes.Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

PLEASE REFER TO ATTACHED REPORT

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

GBF9532S

Vehicle Make/Model/Colour

Details Of Properties

Name of Driver

MR GOH

NRIC/Passport Number

Contact Number

93676780

Address

Postcode

Insurance Company Name

Nature Of Damage


No. Of Passenger (Including Driver)

Details of Witness


Name

Phone Number

Email Address



Sketch Plan #2







SMRT Automotive Services Pte Ltd

60 Woodlands Industrial Park E4 Singapore 757705 Tel: 65 6362 3422 Fax: 65 6368 7420

SMRT Vehicle Repair Estimate

Group : Buses / Taxis / <u>Commercial</u>	
Reg. No. : SJW 3567Y	Ref. No. : <u>WL/SEPT2017/006</u>
Make / Model : DAIHATSU SIRION-1.3 (A)	Reg. Date :
Chassic No : JDAM301S001105063/2347952	Mileage :
Name of Driver :	Rental/Replacement Vehicle : Yes / No
Date/Time of Accident : 10/09/2017 @19:15	The damages on the vehicle are as
Surveyer is Required ? YES / NO	indicated in the following diagram :
If Yes, VICOM / LKK / AIS / Others MSIG :	
Vehicle is Towed Back ? YES / NO Date / Time :	
Accident reporting date :	
Type of Accident : Skid / Head-Rear / Head-On / Side Swipe / Others	
Special Instruction to ARC, if any :	
THIRD PARTY CLAIMS AGAINST GBF9532S (ERGO INSURANCE PTE LTD)	_
Signed : Date	:
Accident Repair Job Card No : Date Prepar	
Summary of Repair Estimates Repair Com Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges : \$ 1,500.00	
Total Spray Painting Charges : \$ 1,500.00	
Total Material Charges : \$ 11,799.85	\$ 11,799.85
Other Charges : \$ 380.00	
TOTAL : \$ 15,179.85	
Lump Sum Repair, if	fany :
No. of Repair Days : 5] days	[4] days
Signature : Prepared by:	Adjusted by:
ON No. Invoice No.	Invoice Date
QN NoInvoice No Signed : Date	Invoice Date

Ref No.:

Page (2)

Part 1 - Labour Works

Job Scope	Quotation from ARC	
TO KNOCKING , REALIGN REAR CHASIS , CUT OUT REAR FENDER /FLOOR PANEL ETC	\$1,500.00	1200
Total Labour	\$1,500.00	

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC		
SPRAY PAINTING ON SPARE TYPRE PANEL / FENDER RH BOOTLID , BUMPER	\$1,500.00	1000	-0.4
			•
Total Spray Painting & Panel Beating	\$1,500.00		

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Page (3)

Job Scope	Quotation from ARC		
REMOVE & REFIX UNDERCARRIAGE AND ALIGNMENT	\$250.00	80	
WIRING	\$50,00	30	
TOWING	\$80,00	60.	
Total Other Costs	\$380.00		

2370 17029 50

Part 4 - Spare Parts / Material Usage

Ref No.:

To be completed by Service Advisor, ARC								
Part Number	Parts Description	Qty	C	Cost Price	Discount (%)	Final Price	Repair (R) Replace (/)	Not given (X) Repair (R) Replace (/)
	REAR BUMPER Distorted	1	\$	450.00	15.00%	\$ 382.50	Replace (/)	Replace (/)
	REAR BUMPER REINFORCEMENT	1	\$	180.00	15.00%	\$ 153.00	Replace (/)	Not given (x)
	REAR BUMPER BRACKET RH 23d	1	\$	45.00	15.00%	\$ 38.25	Replace (/)	Replace (/)
	REAR BUMPER BRACKET RH	1	\$	45.00	15.00%	\$ 38.25	Not given (x)	Not given (x)
	REAR FENDER RH Southeld	1	\$	650.00	15.00%	\$ 552.50	Not given (x)	Not given (x)
	REAR FENDER INNER SHIELD tom	1	\$	85.00	15.00%	\$ 72.25	Replace (/)	Replace (/)
	REAR LAMP RH Couled	1	\$	380.00	15.00%	\$323.00	Not given (x)	Not given (x)
	TRUNKLID Deved	1	\$	650.00	15.00%	\$552.50	Not given (x)	Not given (x)
	TRUNKLID HINGES (\$65 X 2 PCS)	2	\$	130.00	15.00%	\$ 110.50	Replace (/)	Replace (/)
	TRUNKLID EMBLEM	1	\$	60.00	15.00%	\$ _ 51.00	Not given (x)	Not given (x)
	TRUNKLID EMBLEM LOGO (H)	1	\$	70.00	15.00%	\$ 59.50	Not given (x)	Not given (x)
	REAR END PANEL Berted	1	\$	480.00	15.00%	\$ 7/408.00	Replace (/)	Replace (/)
	REAR END PANEL TOP GARNISH	1	\$	180.00	15.00%	\$ 153.00	Replace (/)	Replace (/)
	BOOTLID LOCK Ken	1	\$	98.00	15.00%	\$ 83.30	Not given (x)	Not given (x)
	SPARE TYRE BOARD 74 M	1	\$	450.00	15.00%	\$ 382.50	Replace (/)	Replace (/)
	SPARE TYRE PANEL PUT	1	\$	1,250.00	15.00%	\$ 1,062.50	Not given (x)	Not given (x)
	REAR FENDER INNER GARNISH	PO1	\$	150.00	15.00%	\$ 1/127.50	Replace (/)	Replace (/)
	REAR FENDER INNER GARNISH CLIPS (\$10 X 4 PCS)	4	\$	40.00	15.00%	\$ 7 34.00		Not given (x)
	REAR WINDSCREEN Shaffered	1	\$	650.00	15.00%	\$552.50	Not given (x)	Not given (x)
	DAIHATSU EMBLEM New	1	\$	85.00	15.00%	\$ 72.25		Not given (x)
	REAR WINDSCREEN GLUM	1	\$	650.00	15.00%	\$ 552.50	Not given (x)	Not given (x)
	REAR TYRE Punched	1	\$	125.00	15.00%	\$ 106.25	Replace (/)	Replace (/)
	REAR TYRE RIM	1	\$	550.00	15.00%	\$ 467.50	Replace (/)	Replace (/)
	REAR AXLE ASSY	1	\$	1,250.00	15.00%	\$ 1,062.50	Not given (x)	Not given (x)
	REAR SHOCK ABSORBER RH	1	\$	258.00	15.00%	\$ 219.30	Not given (x)	Not given (x)
	REAR SHOCK ABSORBER MOUNTING	1	\$	120.00	15.00%	\$ 102.00	Replace (/)	Replace (/)
	WHEEL CAP could	1	\$	180.00	15.00%	\$ 60(52.00	Replace (/)	Replace (/)
ı	REAR SPRING COIL NIT NA	1	\$	450.00	15.00%	\$ > 382.50	Not given (x)	Not given (x)

Ato m	1	\$	450.00	15.00%	\$ 💉 382.50	Not all a characters (a)
112.11. 111.22.1133		<u> </u>				Not given (x) Not given (x)
REAR BRAKE DRUM ALM	1	*	450.00	15.00%	\rightarrow	Not given (x) Not given (x)
BRAKE CALIPHER NEW	1	\$	650.00	15.00%	\$ 552.50	Not given (x) Not given (x)
REAR EXHAUST ASSY THE	1	\$	650.00	15.00%	\$ 552.50	Replace (/)
REVERSE SENSOR (1 SET) Pord	2	\$_	250.00	NETT	\$ 220,250.00	Replace (/)
NO PLATE (METAL)	1	\$	25.00	NETT	\$ 25.00	Replace (/)
NO PLATE GARNISH	1	\$	25.00	NETT	\$ 25.00	Replace (/)
PANEL BODY LWER BACK	1	\$	488.00	NETT	\$ 488.00	Replace (/)
PLATE 1.3	1	\$	38.00	15.00%	\$ 32.30	Replace (/)
PANEL, WH HOUSING RH	1	\$	532.50	15.00%	\$ 532.20	Replace (/)
PANEL, QTR INNER RH	1	\$	380.00	15.00%	\$ 323.00	Replace (/)
TOTAL MATERIALS		\$ 1	3,649.50		\$ 11,799.85	
	BRAKE CALIPHER REAR EXHAUST ASSY REVERSE SENSOR (1 SET) NO PLATE (METAL) NO PLATE GARNISH PANEL BODY LWER BACK PLATE 1.3 PANEL, WH HOUSING RH PANEL, QTR INNER RH	REAR BRAKE DRUM ALM 1 BRAKE CALIPHER MIN 1 REAR EXHAUST ASSY AH M 1 REVERSE SENSOR (1 SET) Part 2 NO PLATE (METAL) XH AM 1 NO PLATE GARNISH MIN 1 PANEL BODY LWER BACK MIN 1 PANEL , WH HOUSING RH Prin 1 PANEL , QTR INNER RH 1	REAR WHEEL HUB REAR BRAKE DRUM BRAKE CALIPHER REAR EXHAUST ASSY REVERSE SENSOR (1 SET) NO PLATE (METAL) NO PLATE GARNISH PANEL BODY LWER BACK PLATE 1.3 PANEL, WH HOUSING RH PANEL, QTR INNER RH 1 \$ 1 \$ 1 \$ 1 \$ 1 \$ 1 \$ 1 \$ 1	REAR WHEEL HUB REAR BRAKE DRUM BRAKE CALIPHER REAR EXHAUST ASSY REVERSE SENSOR (1 SET) NO PLATE (METAL) NO PLATE GARNISH PANEL BODY LWER BACK PANEL, WH HOUSING RH PANEL, QTR INNER RH 1 \$ 450.00 1 \$ 650.00 2 \$ 250.00 2 \$ 250.00 1 \$ 25.00 1 \$ 488.00 1 \$ 38.00 PANEL, QTR INNER RH 1 \$ 380.00	REAR WHEEL HUB REAR BRAKE DRUM ALL M BRAKE CALIPHER BRAKE CALIPHER ALL M 1 \$ 650.00 15.00% REAR EXHAUST ASSY ALL M 1 \$ 650.00 15.00% REVERSE SENSOR (1 SET) NO PLATE (METAL) NO PLATE (METAL) NO PLATE GARNISH PANEL BODY LWER BACK 1 \$ 488.00 NETT PLATE 1.3 ALL M PANEL, WH HOUSING RH PANEL, QTR INNER RH 1 \$ 380.00 15.00% 1 \$ 380.00 15.00%	REAR BRAKE DRUM

3672 515 A7101	

Adrian him 96893735 4/5 13/09/17. 09 Days. total: 6042 HS: 48K



TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Affiliated to Federation Intern	nationale Des Experts En Autor	nobile
ERGO INSURANCE F	PTE LTD	Ref : CS/EGI170177	01/Arbe2
5 TEMASEK BOULEV #04-01 SUNTEC TOV SINGAPORE 038985		Date: 24-01-2018 Code: EGI	
14 14 12 13 14 14 15 15	Policy Particul	ars :- THIRD PARTY CLA	IM
Insured Veh.	GBF 9532S	Veh. Inspected	SJW 3567Y
Policy No.		Coverage (\$)	0.00
Claim No.	GBF9532S/SE/pl	Excess (\$)	0.00
Assign From	YEE PEI LI	Assign Date	13/09/2017
2.	Vehicle P	articulars & Condition	
Make & Model	DAIHATSU SIRION	c.c	1298
Engine No.	HIDDEN	Year of Reg.	2010
Chassis No.	JDAM301S001105063	Colour	GREEN
Odometer	55092	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. 秦汉 [1] [1] [1] [1] [1] [1]	Con	ditions of Tyres	
	Size	Make	Balance
R/H Front Tyre		CONTINENTAL	6 mm
L/H Front Tyre	175/65 R14	CONTINENTAL	6 mm
R/H Rear Tyre	175/65 R14	CONTINENTAL	6 mm
L/H Rear Tyre	175/65 R14	CONTINENTAL	6 mm
4.		ption of Damages	
DAMAGES SEE D			
5.	Gen	eral information	
Accident Date	10/09/2017	Inspection Date	13/09/2017
Survey held at	1 KAKI BUKIT AVE 6 #01-60	•	
Repairer	SMRT AUTOMOTIVE SERV		
5a.		Remarks	
	ON WAS CONDUCTED ON A" CE TO YOUR INSTRUCTIONS		
5b.	Estim	ate Days of Repair	
i i	RMAL PERIOD FOR REPAIR:	9 Working Day	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJW 3567Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted
	REPLACEMENT OF PARTS		, , , , , , , , , , , , , , , , , , ,	1
1	REAR BUMPER	DISTORTED	450.00	450.00
1	REAR BUMPER BRACKET RH	DAMAGED	45.00	45.00
1	REAR FENDER RH	BUCKLED	650.00	650.00
1	REAR FENDER INNER SHIELD	TORN	85.00	85.00
1	REAR LAMP RH	CRACKED	380.00	380.00
1	TRUNKLID	DENTED	650.00	650.00
1	TRUNKLID EMBLEM	NECESSARY	60.00	60.00
1	TRUNKLID EMBLEM LOGO (H)	NECESSARY	70.00	70.00
1	REAR END PANEL	DENTED	480.00	480.00
1	REAR FENDER INNER GARNISH	DEFORMED	150.00	150.00
4	REAR FENDER INNER GARNISH CLIPS @\$10.00	NECESSARY	40.00	40.00
1	REAR WINDSCREEN	SHATTERED	650.00	650.00
1	DAIHATSU EMBLEM	NECESSARY	85.00	85.00
1	REAR TYRE	PUNCTURE	125.00	125.00
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	180.00	
2	TRUNKLID HINGES @\$65.00	NOT NECESSARY	130.00	
1	REAR END PANEL TOP GARNISH	NOT NECESSARY	180.00	
1	BOOTLID LOCK	NOT NECESSARY	98.00	,
1	SPARE TYRE BOARD	NOT NECESSARY	450.00	
1	REAR TYRE RIM	NOT NECESSARY	550.00	
1	REAR AXLE ASSY	NOT NECESSARY	1,250.00	
1	REAR SHOCK ABSORBER RH	NOT NECESSARY	258.00	
1	REAR SHOCK ABSORBER MOUNTING	NOT NECESSARY	120.00	
1	REAR SPRING COIL	NOT NECESSARY	450.00	
1	REAR WHEEL HUB	NOT NECESSARY	450.00	
1	REAR BRAKE DRUM	NOT NECESSARY	450.00	
1	BRAKE CALIPHER	NOT NECESSARY	650.00	
1	REAR EXHAUST ASSY	NOT NECESSARY	650.00	
1	PLATE 1.3	NOT NECESSARY	38.00	
1	SPARE TYRE PANEL	TO REPAIR SEE LABOUR	1,250.00	-

Report Ref No. CS/EGI17017701/Arbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

y ∵	Description of Parts	Condition	Estimate By Workshop (\$))	
1	PANEL, WH HOUSING RH	TO REPAIR SEE LABOUR	532.50	•
1	PANEL, QTR INNER RH	TO REPAIR SEE LABOUR	380.00	
1	REAR BUMPER BRACKET RH	REPEATED	45.00	
	LESS 15% DISCOUNT			-588.00
			12,031.50	3,332.00
	SPECIAL NETT ITEMS			
1	REAR WINDSCREEN GLUM (SN)	NECESSARY	650.00	60.00
1	WHEEL CAP (SN)	CRACKED	180.00	60.00
2	SET REVERSE SENSOR (SN)	DAMAGED	250.00	220.00
1	NO PLATE (METAL) (SN)	NOT NECESSARY	25.00	
1	NO PLATE GARNISH (SN)	NOT NECESSARY	25.00	
1	PANEL BODY LWER BACK (SN)	NOT NECESSARY	488.00	
			1,618.00	340.00
	LABOUR			
F F S	TO KNOCKING, REALIGN REAR CHASSIS, CUT OUT REAR FENDER / FLOOR PANEL ETC. INCLUSIVE OF THE REPAIR OF SPARE TYRE PANEL, PANEL, WH HOUSING RH AND PANEL, QTR INNER RH.		1,500.00	1,200.00
	SPRAY PAINTING ON SPARE TYRE PANEL / FENDER RH BOOTLID, BUMPER.		1,500.00	1,000.00
	REMOVE & REFIX UNDERCARRIAGE AND ALIGNMENT.		250.00	80.00
ļ	WIRING.		50.00	30.00
ı	TOWING.		80.00	60.00
			3,380.00	2,370.00
_	GRAND TOTAL		17,029.50	6,042.00

(TO ITS PRE-ACCIDENT CONDITION)

Report Ref No. CS/EGI17017701/Arbe2



ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.