

22/03/2017

ASS. REC. BY:

REF: C03/LPC17004443/Gtb-1 Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person):

Ong Li Li

of

LPC

Date/Time:

12.09.2017

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGG 4240C

Insured:

SGW 3310C

at Workshop m/s

N-51 Automotiv

Tel:

6842 0051

of

2 Kaki Bukit Ave 2 #01-17

Policy No:

Claim No:

15/17/17/VPOB/019726

Sum Insured:

Excess:

D.O.A. 13/03/2017

Make of Veh:

(Client's Record)

06.03.2017

H.O.D. Endorsement:

CA / REV / REP. / REV 24 HRS w/p

Date/Time:

06/03/2017 10:46am

Person Contacted:

Hui Xin

Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate
	SGG 4240C - NA / MS17004556/13
	SGW 3310C - X
13/3	Resurvey.
13/3	After repair.

lump sum \$7600 - (Red: 7300 48%) 10 days

30/11 - File pass to typist.

RECEIVED 30 NOV 2017

no bill

28/11/13

AS S. REC. BY:

PRS

XBL

REF:

LPC

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s: N-51

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SG64240C Yr Regn: 21 Jan 2016Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Nissan Sylphy cc 1598Colour: white A/C Insured / Std / NI / NASp. Reading: 31495 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MANTRB3AB17-80023873Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/60 R16R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front _____ Rear _____

R/Bal. 7 mm R/Bal. 7 mmL/Bal. 7 mm L/Bal. 7 mmD.O.A. _____ D.O.I. 06-03-17Survey held at: W/S 12pmDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Submit PRS Report

Date/Time, File Pass to?

☐ : Preli. Report

1215 TYPST

☐ : Final Report

Date/Time, File Return to?

2)

Report Format: PR3-TP

Lump Sum / I.B.I: (\$ _____)

Days Of Repair: 2Resurvey No. of Trip: 2

Add Fee: ☐ Site Insp (\$ _____) ☐ S + RS \$ _____

☐ Interview (\$ _____) ☐ Photos

☐ Tech. Invs (\$ _____) ☐ Others

☐ Weekend (\$ _____)

Survey Fee:

Transportation:

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CS3/LPC17004443/Gtb-1

300 BEACH ROAD
#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 13-09-2017



Code : LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGW 3310G	Veh. Inspected	SGG 4240C
Policy No.		Coverage (\$)	0.00
Claim No.	15/17/17/VP05/019726	Excess (\$)	0.00
Assign From	ONG LI LI	Assign Date	12/09/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	03/03/2017	Inspection Date	13/09/2017
Survey held at	N-51 AUTOMOTIVE PL 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

Catherine Chong (LKK Auto)

From: ONG LI LI <llong@lonpac.com>
Sent: Tuesday, 12 September, 2017 2:44 PM
To: Catherine Chong (LKK Auto)
Cc: MT_Claim_SG; assignments@lkkauto.com
Subject: RE: SGG4240C & SGW3310G - NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 3 WORKING DAYS Our Ref: 15/17/17/VP05/019726
Attachments: 12092017143754.pdf; 12092017143022.pdf

Hi Catherine

Attached are the TP survey report & photographs (part 1) for your surveyor's comment.

Please let us know if re-inspection of the TP vehicle is required.

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

From: Catherine Chong (LKK Auto) [mailto:admin-d@lkkauto.com]
Sent: Saturday, 4 March, 2017 10:54 AM
To: GERALD POH WEE BIN
Cc: MT_Claim_SG; assignments@lkkauto.com
Subject: RE: SGG4240C & SGW3310G - NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 3 WORKING DAYS Our Ref: 15/17/17/VP05/019726

Dear Mr Gerald,

Received with thanks.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: GERALD POH WEE BIN [mailto:geraldpoh@lonpac.com]
Sent: Saturday, 4 March, 2017 10:13 AM
To: Ashley Chong (LKK Auto) <admin-d@lkkauto.com>
Cc: MT_Claim_SG <mt_claim@lonpac.com>
Subject: FW: SGG4240C & SGW3310G - NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 3 WORKING DAYS Our Ref: 15/17/17/VP05/019726

Dear Ashley,

For your necessary action.

Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd
100 Beach Road, #19-00 Shaw Tower, Singapore 189702
Tel: (65) 6250 7388 Ext.240 | Fax: (65) 6296 2706

From: Chin Hui Xin [<mailto:huixin@n51.com.sg>]

Sent: Friday, 3 March, 2017 5:25 PM

To: ERIC WOO JUN KIAT

Cc: MT_Claim_SG

Subject: Re: SGG4240C & SGW3310G - NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 3 WORKING DAYS Our Ref: 15/17/17/VP05/019726

Dear Sir/Madam,

Please see attached.

Regards,


Melody Chin

N-51 Automotive Pte Ltd

Office : 6842 0051

Fax : 6741 0510

www.n51.com.sg



On Fri, Mar 3, 2017 at 5:19 PM, ERIC WOO JUN KIAT <ericwoo@lonpac.com> wrote:

Thank you for your list of surveyors.

We regret we are not agreeable to your panel of surveyor as listed.

We shall be assigning to Xing Guo Qiang from LKK Auto Consultants Pte Ltd to conduct the survey on your client's vehicle No: SGG 4240C.

Thank you.

Best Regards,

Eric Woo

Claims Executive | Lonpac Insurance Bhd

100 Beach Road, #19-00 Shaw Tower, Singapore 189702

Tel: (65) 6250 7388 Ext.252 | Fax: (65) 6296 2706

From: Chin Hui Xin [mailto:huixin@n51.com.sg]

Sent: Friday, 3 March, 2017 5:16 PM

To: ERIC WOO JUN KIAT

Subject: Re: SGG4240C & SGW3310G - NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 3 WORKING DAYS

Dear Eric Woo,

I already by fax for you...


Regards,

Melody Chin

N-51 Automotive Pte Ltd

Office : 6842 0051

Fax : 6741 0510



On Fri, Mar 3, 2017 at 5:06 PM, ERIC WOO JUN KIAT <ericwoo@lonpac.com> wrote:

Dear Hui Xin,

Kindly refer to attached for our list of surveyors.

Thank you.

Best Regards,

Eric Woo

Claims Executive | Lonpac Insurance Bhd

100 Beach Road, #19-00 Shaw Tower, Singapore 189702

Tel: (65) 6250 7388 Ext.252 | Fax: (65) 6296 2706

From: Chin Hui Xin [<mailto:huixin@n51.com.sg>]

Sent: Friday, 3 March, 2017 3:13 PM

To: MT_Claim_SG

Subject: SGG4240C & SGW3310G - NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 3 WORKING DAYS

Dear Sir/Madam,

As per above subject,

Please refer attachment and:-

Kindly propose / provide your 10 surveyors.

Thank you...

Regards,


Melody Chin

N-51 Automotive Pte Ltd

Office : 6842 0051

Fax : 6741 0510

www.n51.com.sg



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	03/03/2017 14:57
Date Of Accident	03/03/2017 12:10
Exact Location Of Accident	PIE TWDS CHANGI B4 LORNIE RD EXIT
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGG4240C
Insured/Policyholder	
Name Of Registered Owner	TOH SENG HUAT
NRIC No	S1469260F
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96259858
Alternative Phone No	Others-96259858
Vehicle Particulars	
Manufacturer	NISSAN
Model	SYLPHY
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	No
If No, Please state action to be taken	Third Party
Vehicle Category	Private Car
Insurance Company	
Name of Insurance Company	AIG Asia Pacific Insurance Pte. Ltd.
Type Of Coverage	Comprehensive
Fleet Policy	No
Policy Number	2100448471-01000
Cover Note Number	
Driver	
Name of Driver	TOH SENG HUAT
NRIC No	S1469260F
Date Of Birth	28/10/1961
Occupation	Indoor
Date Of Driving Pass	13/09/1983
Driving Experience	33 Years And 5 Months
Gender	Male
Mobile Number	(Local) +65-96259858
Fax Number	
Contact Number	Others-96259858
Email Address	NOEMAIL

Address	BLK 301C ANCHORVALE DRIVE
	#06-37
Postcode	543301
Was driver an employee of the Insured's Company	No
If No, Relationship of the Driver with the Insured	Owner
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	Collision- Chain Collision
Weather Conditions	Clear
Road Surface	Wet

Other Information

Was any foreign vehicle involved in this accident?	No
Was any body injured in the Accident?	Yes
Was any other material or property damaged?	Yes
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	No
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	No
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	No
If Yes, against whom?	

Circumstances of Accident

PLS REFER TO THE ATTACHED STATEMENT.

Attachment(s)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Remarks/ Reasons:	WITH DRIVER
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGW3310G
Vehicle Make/Model/Colour	
Details Of Properties	
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Details of Witness

Name	
Phone Number	
Email Address	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SGJ7687L
-----------------------------	----------

Sketch Plan #2

Describe Circumstances of the Accident

I WAS TRAVELLING ON THE EXTREME RIGHT LANE OF THE CONTRA-CHANNEL BEFORE CORNER ROAD EAST.
 IT WAS A LONG I WAS LANE WAS
 WHILE TRAVELLING STRAIGHT AHEAD. AS THE VEHICLE IN FRONT BEGAN TO COMPLETE STOP I TOO APPLIED BRAKE TO COMPLETE STOP. SUDDENLY AND A FEW SECONDS I FELT A GREAT IMPACT FROM THE REAR OF MY VEHICLE AND THE IMPACT PUSHED ME FORWARD AND CAUSE ME HIT INTO THE VEHICLE IN FRONT.
 I REALIZED IT WAS A VEHICLE BEHIND (S6W 3310 G) THAT HAD HIT ME FROM THE REAR AFTER HIT INTO THE REAR OF MY VEHICLE.
 IT WAS A CHAIN INCIDENT INVOLVING 4 CARS.

VEHICLE A - S6B 9240 L
 VEHICLE B - S6W 3310 G
 VEHICLE C - S6T 7092 L
 VEHICLE D - S6B 8727 P

Declaration

We declare the foregoing particulars are true in every respect

 Policyholder's Signature - Date & Time

 Driver's Signature (if driver is not the policyholder) - Date & Time

 Witnessed by Reporting Centre Personnel

Report No: 0351-17-N51

07 August 2017

ACCIDENT VEHICLE SURVEY REPORT

Toh Seng Hunt
Blk 301C Anchorvale Drive #06-37
Singapore 543301

VEHICLE INFORMATION:

Vehicle Reg No.:	SGG4240C	Odometer:	31495km
Make & Model:	Nissan Sylphy 1.6 CVT	Colour:	White
Chassis number:	MNTBBAB17Z0023873	Date of accident:	03/03/2017
Year of Regn.:	21/01/2006	Date inspected:	06/03/2017
Repairer at:	N-51 Automotive Pte Ltd 2 Kaki Bukit Ave 2 #01-18 Kaki Bukit Auto Hub Singapore 417921	Date inspected (After Repair):	11/03/2017

STATIC CHECKS, where applicable:

Steering :	serviceable
Footbrake :	serviceable
Handbrake :	serviceable
Paintwork :	Good
General condition :	Good

TIRE CONDITION:

	<u>LH / Make</u>	<u>RH / Make</u>	<u>Size</u>
Front:	5mm/Bridgestone	5mm/Bridgestone	195/60/R15
Rear:	5mm/Bridgestone	5mm/Bridgestone	195/60/R15

POINT OF IMPACT AND DAMAGE, where applicable:

Impact on the rear and front portion.
Please see details as described in the Annex for parts and labour.

REMARKS:

We have inspected the above-mentioned vehicle on a "Without Prejudice" basis.

PAR Automotive Consultancy

Regn No. 52960974L

Thomson Rd Post Office PO Box 029 Singapore 915701. Tel : 645 31173, Fax : 645 36131.

Report No: 0351-17-N51

07 August 2017

ACCIDENT VEHICLE SURVEY REPORT

Toh Seng Huat
Blk 301C Anchorvale Drive #06-37
Singapore 543301

VEHICLE INFORMATION:

<i>Vehicle Reg No.:</i>	SGG4240C	<i>Odometer:</i>	31495km
<i>Make & Model:</i>	Nissan Sylphy 1.6 CVT	<i>Colour:</i>	White
<i>Chassis number:</i>	MNTBBAB17Z0023873	<i>Date of accident:</i>	03/03/2017
<i>Year of Regn.:</i>	21/01/2006	<i>Date inspected:</i>	06/03/2017
<i>Repairer at:</i>	N-51 Automotive Pte Ltd 2 Kaki Bukit Ave 2 #01-18 Kaki Bukit Auto Hub Singapore 417921	<i>Date inspected (After Repair):</i>	11/03/2017

RE-INSPECTION

We had carried out re-inspection during works in progress and post repair inspection on the above vehicle. Attached in Annex B are the re-inspection photos, showing the work in progress and our re-inspection to the hidden part that were damaged.

REMARKS:

We have inspected the above-mentioned vehicle on a "Without Prejudice" basis.

Parts and Labour Assessment

PARTS

Description of part	Qty	Condition	Repairer's estimate	Our adjustment
AIRCON CONDENSER AIR GUIDE CLIPS	6	necessary	39.00	39.00
AIRCON CONDENSER AIR GUIDE L/R	2	warped	393.40	393.40
FRONT BONNET WEATHERSTRIP	1	reuse	37.10	0.00
FRONT BUMPER	1	squashed	446.30	446.30
FRONT BUMPER FOGLAMP GARNISH L/R	2	fractured	128.60	128.60
FRONT BUMPER FOGLAMP L/R	2	fractured	640.00	640.00
FRONT BUMPER INNER SPONGE	1	deformed	280.70	280.70
FRONT BUMPER LOWER CENTER GRILLE	1	fractured	135.60	135.60
FRONT BUMPER LOWER LIP 'ORIGINAL'	1	deformed	1,178.70	1,178.70 XR
FRONT BUMPER NUMBER PLATE GARNISH	1	deformed	73.20	73.20
FRONT BUMPER REINFORCEMENT	1	bent	561.90	561.90
FRONT BUMPER TOW HOOK COVER	1	fractured	22.30	22.30
FRONT GRILLE	1	fractured	297.20	297.20
FRONT GRILLE CLIPS	6	necessary	39.00	39.00
FRONT HEADLAMP LOWER BRACKET L/R	2	bent	89.00	89.00
FRONT SUPPORT PANEL	1	repair	891.60	0.00
FRONT SUPPORT PANEL TOP GARNISH	1	reuse	287.20	0.00
REAR BOOTLID	1	buckled	600.50	600.50 XR
REAR BOOTLID INNER UPHOLSTERY TRIM	1	deformed	204.80	204.80 XNN
REAR BOOTLID OUTER CHROME GARNISH 'TOP'	1	fractured	148.00	148.00 XNN
REAR BOOTLID OUTER CHROME GARNISH CLIPS	1	necessary	6.50	6.50
REAR BOOTLID OUTER LOWER CHROME GARNISH	1	fractured	138.00	138.00
REAR BOOTLID REFLECTOR LAMP CLIPS L/R	4	necessary	26.00	26.00
REAR BUMPER	1	squashed	427.00	427.00
REAR BUMPER INNER SIDE SHIELD CLIPS L/R	6	necessary	39.00	39.00
REAR BUMPER INNER SPONGE 'CENTER'	1	deformed	56.00	56.00
REAR BUMPER INNER SPONGE L/R	2	deformed	135.80	135.80
REAR BUMPER LOWER LIP 'ORIGINAL'	1	deformed	810.00	810.00 XR
REAR END PANEL	1	buckled	540.90	540.90
REAR END PANEL INNER TOP GARNISH	1	fractured	204.80	204.80
REAR END PANEL INNER TOP GARNISH CLIPS	2	necessary	13.00	13.00
REAR TAILLAMP CLIPS L/R	4	necessary	26.00	26.00
REAR TAILLAMP L/R	2	fractured	387.80	387.80
SPARE TYRE PANEL INNER TOP RUBBER TRAY	1	reuse	495.00	0.00
SPARE TYRE PANEL INNER TOP SPONGE	1	deformed	191.50	191.50 XNN
SPARE TYRE PANEL INNER TOP UPHOLSTERY BOARD	1	deformed	485.00	485.00 XNN
Subtotal before discount			S\$ 10,476.40	S\$ 8,765.50
Percentage discount 30% and 30%			S\$ 3,142.92	S\$ 2,629.65
Sub-total 1			S\$ 7,333.48	S\$ 6,135.85

FRONT BONNET MECHANISM LOCK	1	bent	63.50	63.50	
FRONT BONNET RUBBER GUIDE STOPPER L/R	4	reuse	40.00	0.00	
FRONT BUMPER SIDE RETAINER L/R	2	necessary	48.00	48.00	
FRONT GRILLE 'LOGO' EMBLEM	1	necessary	64.60	64.60	
FRONT GRILLE CHROME GARNISH	1	fractured	185.00	185.00	
FRONT GRILLE TOP RETAINER L/R	2	necessary	39.00	39.00	
FRONT HEADLAMP L/R	2	fractured	1,060.40	1,060.40	
HORN	2	distortion	192.80	192.80	XNN
REAR BOOTLID 'LOGO' EMBLEM	1	necessary	55.20	55.20	
REAR BOOTLID 'PURE DRIVE XTRONIC CVT' EMBLEM	1	necessary	66.40	66.40	
REAR BOOTLID 'SIGNATURE' EMBLEM	1	necessary	78.50	78.50	
REAR BOOTLID 'SYLPHY' EMBLEM	1	necessary	66.40	66.40	
REAR BOOTLID HINGES L/R	2	repair	176.00	0.00	
REAR BOOTLID MECHANISM LOCK	1	bent	84.30	84.30	
REAR BOOTLID NUMBER PLATE LAMP L/R	2	fractured	124.00	124.00	XNN
REAR BOOTLID OUTER KEY LOCK	1	jammed	98.00	98.00	XNN
REAR BOOTLID OUTER LOCK HANDLE SWITCH	1	shorted	78.00	78.00	XNN
REAR BOOTLID REFLECTOR LAMP BACK RUBBER GASKET L/R	2	necessary	48.00	48.00	
REAR BOOTLID REFLECTOR LAMP L/R	2	fractured	321.20	321.20	
REAR BOOTLID RUBBER GUIDE STOPPER L/R	2	deformed	20.00	20.00	
REAR BOOTLID WEATHERSTRIP	1	deformed	88.00	88.00	
REAR BUMPER EXHAUST END CHROME GARNISH L/R	2	deformed	156.00	156.00	
REAR BUMPER IMPACT BRACKET L/R	2	bent	108.00	108.00	
REAR BUMPER INNER SIDE SHIELD L/R	2	reuse	48.00	0.00	
REAR BUMPER REFLECTOR L/R	2	reuse	98.00	0.00	
REAR BUMPER SIDE RETAINER L/R	2	necessary	72.20	72.20	
REAR END PANEL BOOTLID ANTENNA SENSOR	1	shorted	98.00	98.00	XNN
REAR END PANEL LOCK STRIKER	1	bent	58.20	58.20	XNN
REAR EXHAUST GASKET	1	necessary	16.00	16.00	XNN
REAR EXHAUST RUBBER MOUNTING	3	distorted	48.00	48.00	XNN
REAR EXHAUST SILENCER BOX	1	bent	795.30	795.30	XNN
REAR FENDER INNER UPHOLSTERY TRIM L/R	2	deformed	408.00	408.00	XNN
REAR TAILLAMP INNER PANEL L/R	2	repair	408.00	0.00	
Subtotal before discount			S\$ 5,311.00	S\$ 4,541.00	
Percentage discount 10% and 10%			S\$ 531.10	S\$ 454.10	
Sub-total 2			S\$ 4,779.90	S\$ 4,086.90	

FRONT BONNET INSULATOR MAT CLIPS - SET	1	reuse	30.00	0.00
FRONT BUMPER CLIPS - SET	1	necessary	30.00	30.00
FRONT BUMPER NUMBER PLATE	1	bent	25.00	25.00 <i>20</i>
FRONT BUMPER NUMBER PLATE HOLDER	1	bent	50.00	50.00 <i>25</i>
FRONT FENDER INNER SHIELD CLIPS L/R - SET	2	necessary	60.00	60.00 <i>40</i>
FRONT SUPPORT PANEL TOP GARNISH CLIPS - SET	1	necessary	30.00	30.00 <i>20</i>
RADIATOR COOLANT - BOT	1	reuse	80.00	0.00
REAR BOOTLID INNER UPHOLSTERY TRIM CLIPS - SET	1	necessary	30.00	30.00 <i>20</i>
REAR BOOTLID NUMBER PLATE	1	bent	25.00	25.00 <i>XNN</i>
REAR BOOTLID NUMBER PLATE HOLDER	1	bent	50.00	50.00 <i>XNN</i>
REAR BOOTLID REVERSE CAMERA	1	shorted	800.00	800.00 <i>XNN</i>
REAR BUMPER CLIPS - SET	1	necessary	30.00	30.00
REAR BUMPER REVERSE SENSOR - SET	1	shorted	350.00	350.00 <i>200</i>
REAR FENDER INNER UPHOLSTERY TRIM CLIPS L/R - SET	2	necessary	60.00	60.00 <i>40</i>
SPARE TYRE PANEL INNER BREAK DOWN SIGN	1	fractured	150.00	150.00 <i>XNN</i>
SPARE TYRE PANEL INNER JACKING TOOL	1	bent	180.00	180.00 <i>XNN</i>
SPARE TYRE PANEL INSULATOR MAT	1	necessary	350.00	350.00 <i>XNN</i>
Subtotal before discount			SS 2,330.00	SS 2,220.00
Sub-total 3			SS 2,330.00	SS 2,220.00
Parts-total			SS 14,443.38	SS 12,442.75

LABOUR

To remove, reinstall air con parts, vacuums, refill air con gas. (to FR)	180.00	0.00
To remove, reinstall electrical wiring harness, check lighting, resetting headlamp focussing and rewire for parking sensor.	180.00	140.00 <i>90</i>
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	140.00	60.00
To re-spray painting on the rear bootlid, rear end panel, rear fender (L/R), spare tyre panel and rear bumper.	1,500.00	1,200.00 <i>800</i>
To re-spray painting on the front bonnet, front support panel, front fender (L/R) and front bumper.	1,250.00	1,000.00 <i>700</i>
To remove and change exhaust silencer box with pipe, re-align where necessary consistent to the accident.	160.00	120.00 <i>X</i>
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	2,500.00	2,000.00 <i>1,400</i>
To mount vehicle on to Car 'O' Liner.	400.00	400.00 <i>X</i>
To apply anti-rust chemical on repaired and replaced panel.	120.00	120.00 <i>50</i>
Labour Total		SS 6,430.00 SS 5,040.00
Parts & Labour Total		SS 20,873.38 SS 17,482.75

Results of inspection of the accident vehicle are as shown above.

We have taken into consideration the age and condition of the vehicle in our recommendation.

Hence, the recommended cost of repairs based on Lump Sum repairs is : SS 14,900.00 and the recommended number of working days for the repairs is within 16 day(s).

B
B J Loi (I Eng., MIMI, AIRTE)
Automotive Appraiser

10 days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD			Ref : CS3/LPC17004443/Gtbs2-1	
300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555			Date : 01-12-2017	
			Code : LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SGW 3310G	Veh. Inspected	SGG 4240C	
Policy No.		Coverage (\$)	0.00	
Claim No.	15/17/17/VP05/019726	Excess (\$)	0.00	
Assign From	ONG LI LI	Assign Date	12/09/2017	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN SYLPHY	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	MNTBBAB17Z0023873	Colour	WHITE	
Odometer	31495	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/60R16	BRIDGESTONE	7 mm	
L/H Front Tyre	195/60R16	BRIDGESTONE	7 mm	
R/H Rear Tyre	195/60R16	BRIDGESTONE	7 mm	
L/H Rear Tyre	195/60R16	BRIDGESTONE	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	03/03/2017	Inspection Date	06/03/2017	
Survey held at	N-51 AUTOMOTIVE PL 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			10 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGG 4240C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
6	AIRCON CONDENSER AIR GUIDE CLIPS	NECESSARY	39.00	39.00
2	AIRCON CONDENSER AIR GUIDE L/R	WARPED	393.40	393.40
1	FRONT BONNET WEATHERSTRIP	REUSE	37.10	-
1	FRONT BUMPER	SQUASHED	446.30	446.30
2	FRONT BUMPER FOGLAMP GARNISH L/R	FRACTURED	128.60	128.60
2	FRONT BUMPER FOGLAMP L/R	FRACTURED	640.00	640.00
1	FRONT BUMPER INNER SPONGE	DEFORMED	280.70	280.70
1	FRONT BUMPER LOWER CENTER GRILLE	FRACTURED	135.60	135.60
1	FRONT BUMPER LOWER LIP 'ORIGINAL'	TO REPAIR SEE LABOUR	1,178.70	-
1	FRONT BUMPER NUMBER PLATE GARNISH	DEFORMED	73.20	73.20
1	FRONT BUMPER REINFORCEMENT	BENT	561.90	561.90
1	FRONT BUMPER TOW HOOK COVER	FRACTURED	22.30	22.30
1	FRONT GRILLE	FRACTURED	297.20	297.20
6	FRONT GRILLE CLIPS	NECESSARY	39.00	39.00
2	FRONT HEADLAMP LOWER BRACKET L/R	BENT	89.00	89.00
1	FRONT SUPPORT PANEL	TO REPAIR SEE LABOUR	891.60	-
1	FRONT SUPPORT PANEL TOP GARNISH	REUSE	287.20	-
1	REAR BOOTLID	TO REPAIR SEE LABOUR	600.50	-
1	REAR BOOTLID INNER UPHOLSTERY TRIM	NOT NECESSARY	204.80	-
1	REAR BOOTLID OUTER CHROME GARNISH 'TOP'	NOT NECESSARY	148.00	-
1	REAR BOOTLID OUTER CHROME GARNISH CLIPS	NECESSARY	6.50	6.50
1	REAR BOOTLID OUTER LOWER CHROME GARNISH	FRACTURED	138.00	138.00
4	REAR BOOTLID REFLECTOR LAMP CLIPS L/R	NECESSARY	26.00	26.00
1	REAR BUMPER	SQUASHED	427.00	427.00
6	REAR BUMPER INNER SIDE SHIELD CLIPS L/R	NECESSARY	39.00	39.00
1	REAR BUMPER INNER SPONGE 'CENTER'	DEFORMED	56.00	56.00
2	REAR BUMPER INNER SPONGE L/R	DEFORMED	135.80	135.80
1	REAR BUMPER LOWER LIP 'ORIGINAL'	TO REPAIR SEE LABOUR	810.00	-
1	REAR END PANEL	BUCKLED	540.90	540.90
1	REAR END PANEL INNER TOP GARNISH	FRACTURED	204.80	204.80
2	REAR END PANEL INNER TOP GARNISH CLIPS	NECESSARY	13.00	13.00

Report Ref No. CS3/LPC17004443/Gtbs2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
4	REAR TAILLAMP CLIPS L/R	NECESSARY	26.00	26.00
2	REAR TAILLAMP L/R	FRACTURED	387.80	387.80
1	SPARE TYRE PANEL INNER TOP RUBBER TRAY	REUSE	495.00	-
1	SPARE TYRE PANEL INNER TOP SPONGE	NOT NECESSARY	191.50	-
1	SPARE TYRE PANEL INNER TOP UPHOLSTERY BOARD	NOT NECESSARY	485.00	-
	LESS 30% DISCOUNT		-3,142.92	-1,544.10
			7,333.48	3,602.90
	NETT ITEMS			
1	FRONT BONNET MECHANISM LOCK (N)	BENT	63.50	63.50
4	FRONT BONNET RUBBER GUIDE STOPPER L/R (N)	REUSE	40.00	-
2	FRONT BUMPER SIDE RETAINER L/R (N)	NECESSARY	48.00	48.00
1	FRONT GRILLE 'LOGO' EMBLEM (N)	NECESSARY	64.60	64.60
1	FRONT GRILLE CHROME GARNISH (N)	FRACTURED	185.00	185.00
2	FRONT GRILLE TOP RETAINER L/R (N)	NECESSARY	39.00	39.00
2	FRONT HEADLAMP L/R (N)	FRACTURED	1,060.40	1,060.40
2	HORN (N)	NOT NECESSARY	192.80	-
1	REAR BOOTLID 'LOGO' EMBLEM (N)	NECESSARY	55.20	55.20
1	REAR BOOTLID 'PURE DRIVE XTRONIC CVT' EMBLEM (N)	NECESSARY	66.40	66.40
1	REAR BOOTLID 'SIGNATURE' EMBLEM (N)	NECESSARY	78.50	78.50
1	REAR BOOTLID 'SYLPHY' EMBLEM (N)	NECESSARY	66.40	66.40
2	REAR BOOTLID HINGES L/R (N)	TO REPAIR SEE LABOUR	176.00	-
1	REAR BOOTLID MECHANISM LOCK (N)	BENT	84.30	84.30
2	REAR BOOTLID NUMBER PLATE LAMP L/R (N)	NOT NECESSARY	124.00	-
1	REAR BOOTLID OUTER KEY LOCK (N)	NOT NECESSARY	98.00	-
1	REAR BOOTLID OUTER LOCK HANDLE SWITCH (N)	NOT NECESSARY	78.00	-
2	REAR BOOTLID REFLECTOR LAMP BACK RUBBER GASKET L/R (N)	NECESSARY	48.00	48.00
2	REAR BOOTLID REFLECTOR LAMP L/R (N)	FRACTURED	321.20	321.20
2	REAR BOOTLID RUBBER GUIDE STOPPER L/R (N)	DEFORMED	20.00	20.00
1	REAR BOOTLID WEATHERSTRIP (N)	DEFORMED	88.00	88.00
2	REAR BUMPER EXHAUST END CHROME GARNISH L/R (N)	DEFORMED	156.00	156.00
2	REAR BUMPER IMPACT BRACKET L/R (N)	BENT	108.00	108.00
2	REAR BUMPER INNER SIDE SHIELD L/R (N)	REUSE	48.00	-
2	REAR BUMPER REFLECTOR L/R (N)	REUSE	98.00	-
2	REAR BUMPER SIDE RETAINER L/R (N)	NECESSARY	72.20	72.20

Report Ref No. CS3/LPC17004443/Gtbs2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR END PANEL BOOTLID ANTENNA SENSOR (N)	NOT NECESSARY	98.00	-
1	REAR END PANEL LOCK STRIKER (N)	BENT	58.20	-
1	REAR EXHAUST GASKET (N)	NOT NECESSARY	16.00	-
3	REAR EXHAUST RUBBER MOUNTING (N)	NOT NECESSARY	48.00	-
1	REAR EXHAUST SILENCER BOX (N)	NOT NECESSARY	795.30	-
2	REAR FENDER INNER UPHOLSTERY TRIM L/R (N)	NOT NECESSARY	408.00	-
2	REAR TAILLAMP INNER PANEL L/R (N)	TO REPAIR SEE LABOUR	408.00	-
	LESS 10% DISCOUNT		-531.10	-262.47
			4,779.90	2,362.23
	SPECIAL NETT ITEMS			
1	SET FRONT BONNET INSULATOR MAT CLIPS (SN)	REUSE	30.00	-
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	30.00	30.00
1	FRONT BUMPER NUMBER PLATE (SN)	BENT	25.00	20.00
1	FRONT BUMPER NUMBER PLATE HOLDER (SN)	BENT	50.00	25.00
2	SET FRONT FENDER INNER SHIELD CLIPS L/R (SN)	NECESSARY	60.00	40.00
1	SET FRONT SUPPORT PANEL TOP GARNISH CLIPS (SN)	NECESSARY	30.00	20.00
1	BOT RADIATOR COOLANT (SN)	REUSE	80.00	-
1	SET REAR BOOTLID INNER UPHOLSTERY TRIM CLIPS (SN)	NECESSARY	30.00	20.00
1	REAR BOOTLID NUMBER PLATE (SN)	NOT NECESSARY	25.00	-
1	REAR BOOTLID NUMBER PLATE HOLDER (SN)	NOT NECESSARY	50.00	-
1	REAR BOOTLID REVERSE CAMERA (SN)	NOT NECESSARY	800.00	-
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	30.00	30.00
1	SET REAR BUMPER REVERSE SENSOR (SN)	SHORTED	350.00	200.00
2	SET REAR FENDER INNER UPHOLSTERY TRIM CLIPS L/R (SN)	NECESSARY	60.00	40.00
1	SPARE TYRE PANEL INNER BREAK DOWN SIGN (SN)	NOT NECESSARY	150.00	-
1	SPARE TYRE PANEL INNER JACKING TOOL (SN)	NOT NECESSARY	180.00	-
1	SPARE TYRE PANEL INSULATOR MAT (SN)	NECESSARY	350.00	-
			2,330.00	425.00
	LABOUR			
	TO REMOVE, REINSTALL AIR CON PARTS, VACUUMS, REFILL AIR CON GAS. (TO FR)	NOT NECESSARY	180.00	-
	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING, RESETTING HEADLAMP FOCUSING AND REWIRE FOR PARKING SENSOR.		180.00	90.00

Report Ref No. CS3/LPC17004443/Gtbs2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE, REINSTALL ROOF TOP TRIM UPHOLSTERY, CUSHION SEAT, TRIM GARNISH, TRIM LINER CARPET. (TO FR)		140.00	60.00
	TO RE-SPRAY PAINTING ON THE REAR BOOTLID, REAR END PANEL, REAR FENDER (L/R), SPARE TYRE PANEL AND REAR BUMPER.		1,500.00	800.00
	TO RE-SPRAY PAINTING ON THE FRONT BONNET, FRONT SUPPORT PANEL, FRONT FENDER (L/R) AND FRONT BUMPER.		1,250.00	700.00
	TO REMOVE AND CHANGE EXHAUST SILENCER BOX WITH PIPE, RE-ALIGN WHERE NECESSARY CONSISTENT TO THE ACCIDENT.	NOT NECESSARY	160.00	-
	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE- CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF FRONT BUMPER LOWER LIP 'ORIGINAL', FRONT SUPPORT PANEL, REAR BOOTLID, REAR BUMPER LOWER LIP 'ORIGINAL', REAR BOOTLID HINGES L/R AND REAR TAILLAMP INNER PANEL L/R.		2,500.00	1,400.00
	TO MOUNT VEHICLE ON TO CAR 'O' LINER.	NOT NECESSARY	400.00	-
	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL.		120.00	50.00
			6,430.00	3,100.00
GRAND TOTAL			20,873.38	9,490.13
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				7,600.00

Report Ref No. CS3/LPC17004443/Gtbs2-1

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.