

ASS. REC. BY:

REF: CS/FCI17017848/Atbez

Special Instruction:

SURVEY:

CWS Adrian

ASSIGNMENT (Office)

From (Person): Joannee Yong of FCI

Date/Time 15/9/17 10:37am

Estimated Cost: Bill to

OD / (TP) / WS / TP RES / OD RES / EVA / ENV / MV / CS

To Inspect Vehicle No: GBC 9451 H

Insured: SHA 7607 D

at Workshop m/s F-I Autoclinic

Tel: 92712214

of 1 Kaki Bukit Ave 6 #01-13

Policy No:

Claim No:

D1700 8791 MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record):

D.O.A. 11/9/17

CA / REV / REP. / REV 24 HRS 'wp'

H.O.D. Endorsement:

Date/Time: 15/9/17 11:10am

Person Contacted: Chris Chan

Vehicle (IN) OUT

Date/Time

Action/Instruction (✓) Estimate

GBC 9451 H - X"

SHA 7607 D - CS/FCI 16019140 / Gubm2 - D.O.A. 6/10/2016

ump Sum \$24,500, 28days. (Red: 14,244.60:22%)




**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI17017848/Atb	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 15-09-2017	
		Code : FCI2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	SHA 7607D	Veh. Inspected	GBC 9451H
Policy No.		Coverage (\$)	0.00
Claim No.	D17008791MFSH	Excess (\$)	0.00
Assign From	CWS (JOANNEY YONG)	Assign Date	15/09/2017
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
<b>4. Description of Damages</b>			
<b>5. General Information</b>			
Engine No.	HIDDEN	Accident Date	11/09/2017
		Inspection Date	15/09/2017
Survey held at	F-1 AUTOCLINIC PTE LTD 25 KAKI BUKIT ROAD 4 #05-26 SYNERGY @ KB SINGAPORE 417800		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI17017848/Atb

36 ROBINSON ROAD  
#16-01 CITY HOUSESINGAPORE 068877

Date : 15-09-2017



# First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C

GST Reg. No. M2-0001676-9

## MOTOR SURVEY ASSIGNMENT

<b>Date</b>	14-09-2017	<b>Our Ref No.</b> D17008791MFSH
<b>Accident Date</b>	11-09-2017	<b>Claim Type.</b> Third Party
<b>Insured Vehicle</b>	SHA7607D	<b>Third Party Vehicle.</b> GBC9451H
<b>Survey Location</b>	1 KAKI BUKIT AVE 6 #01-43	
<b>Contact Person.</b>	CHRIS CHAN PICK YUEN	
<b>Contact No.</b>	0/ 92712214	<b>Fax No.</b> 0
<b>Survey Type</b>	WITHOUT PREJUDICE:	
<b>Appointed Surveyor</b>	LKK AUTO CONSULTANTS PTE LTD	
<b>Contact Person</b>	NA	<b>Fax No.</b> 68416315
<b>Contact Number.</b>	NA	

## FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

### THIRD PARTY SURVEY REQUEST

<b>Cc : Workshop</b>	F-1 AUTOCLINIC PTE LTD	<b>Attention.</b> NIL
<b>Cc : TP Solicitor</b>	NA	<b>TP Solicitor Fax No.</b> NA
<b>Officer Incharge</b>	JOANNEY	

## IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/228009)



PRI Documents



Close



## PRI Header Details

<b>Claim No</b>	D17008791MFSH	<b>Policy No</b>	D-15072701MFSH	<b>Claimant S.No &amp; Name</b>	1 & F-1 AUTO
<b>Workshop Name</b>	F-1 AUTOCLINIC PTE LTD (Contact Person : CHRIS CHAN PICK YUEN)	<b>Survey Location &amp; Contact Details</b>	1 KAKI BUKIT AVE 6 #01-43 <b>Mobile:</b> 92712214 , <b>Phone:</b> 0 , <b>Fax:</b> 0 <b>EmailId:</b> CHRIS_CHANBEBE@HOTMAIL.COM		
<b>Our Surveyor</b>	LKK AUTO CONSULTANTS PTE LTD	<b>Instructions To Surveyor</b>	WITHOUT PREJUDICE:		
<b>Insured Name</b>	COMFORT TRANSPORTATION PTE LTD	<b>Insured Vehicle No</b>	SHA7607D	<b>TP Vehicle No</b>	GBC9451H
<b>PRI Recieved Date</b>	14-09-2017 03:55:02 PM	<b>Surveyor Appointed Date</b>	15-09-2017 10:37:39 AM	<b>Surveyor Accept Date</b>	15-09-2017 10:37:39 AM

## Survey Report Upload

<b>Surveyor Inspection Date *:</b>		<b>Surveyor Report Date</b>	15-09-2017	<b>Upload Survey Report *:</b>	<input type="button" value="Choose File"/>
------------------------------------	--	-----------------------------	------------	--------------------------------	--

## Vehicle Particulars

<b>Make</b>	Please Select Make ▾	<b>Model</b>	Please Select Model ▾	<b>Year</b>	Select Year ▾
<b>Chasis No</b>	<input type="text"/>	<b>Engine No</b>	<input type="text"/>	<b>Mileage</b>	<input type="text"/>
<b>Color</b>	<input type="text"/>	<b>Cubic Capacity</b>	<input type="text"/>		

## Multiple Documents Upload

<input type="button" value="Upload Multiple Documents"/>	
<b>File Name</b>	<b>Action</b>

## Surveyor Job Remarks

<b>Remarks</b>	<input type="text"/>	<input type="button" value="Save"/>
----------------	----------------------	-------------------------------------

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	12/09/2017 15:34
Date Of Accident	11/09/2017 04:00
Exact Location Of Accident	ALONG WEST COAST HIGHWAY TOWARDS WEST COAST ROAD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBC9451H
<b>Insured/Policyholder</b>	
Name Of Registered Owner	SANTA FRESH VEGETABLE SUPPLIER
Co Reg No	53035455A
Email Address	DIANAYSK@YAHOO.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-98514299
<b>Vehicle Particulars</b>	
Manufacturer	NISSAN
Model	CABSTAR 3.0 5M/T ABS 2DR 2WD EURO 5
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	REPORTING ONLY
Vehicle Category	COMMERCIAL VEHICLE
<b>Insurance Company</b>	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	CN790751
Cover Note Number	
<b>Driver</b>	
Name of Driver	NG KOK PENG DON
NRIC No	S7536738D
Date Of Birth	28/11/1975
Occupation	OUTDOOR
Date Of Driving Pass	03/08/1994
Driving Experience	23 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-92488800
Fax Number	
Contact Number	
E-Mail Address	NOEMAIL

**DETAILS OF INJURED PERSON 1**

Name	NG KOK PENG DON
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	GBC9451H
Were seat belts worn?	YES
Was injured conveyed to hospital by ambulance?	YES
Address	
Postcode	

Accident Date & Time : 11/09/2017, 4:00 am  
Accident Location : Along West Coast Highway/  
Statement :

As per police report

☒ Reporting Only  
☐ Own Damage Claim (OD)  
☐ Third Party Claim (TP)  
☐ Claim at other workshop (OD/TP)

You had been advised by the workshop that in the event that you wish to claim against your own policy (Own Damage Claim), there is a **FOURTEEN (14) days** clause whereby the claim must be made within the stipulated timeframe from the day of occurrence.

**We declare the foregoing particulars are true in every respect.**

**Policyholder's Signature / Date &  
Time**

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre  
Personnel





**SINGAPORE  
POLICE FORCE**



T/20170912/2043

Police Station Of Origin:  
Bukit Panjang N.P.C  
1 Segar Road #01-05 SINGAPORE 677738  
Tel No: 1800-8929999

2 of 3

Report No. T/20170912/2043

## CONTINUATION OF REPORT

<b>Driver</b>			
Name	NG KOK PENG DON		ID No. S7536738D
Related Vehicle	GBC9451H (Lorry)		Contact No. 92488800
Hospital/Clinic	NATIONAL UNIVERSITY HOSPITAL		Class of Driving Licence & Expiry Date Class: 2B,2A,3 Date of Expiry: NIL
Date Treatment	11/09/2017	Date Discharge	12/09/2017
No. of Days granted Medical Leave	09	Degree of Injury	Slight
<b>Driver</b>			
Name	NG THIAM CHYE		ID No. NIL
Related Vehicle	SHA7607D (Car)		Contact No. 96960211
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

**Brief Details.**

On the above mentioned date, time and location, I was involved in an accident involving my lorry and a taxi. I was travelling along West Coast Highway towards West Coast Road and was driving on the right of the 4 lanes. I were turning right into the Wholesale Centre when suddenly an impact occurred from the rear of my vehicle. Due to the impact my vehicle flip and subsequently my right tire mounted onto the curb. The vehicle flip to its original position with its front tires on the curb. My leg was also stuck to the steering wheel while my body was hanging out from the driver side window. I also discovered that my seatbelt had snapped and also the driver and passenger side windows were smashed. The front window of my lorry was also cracked.

I managed to loosen my leg from the steering wheel and subsequently fall onto the road on my back. The taxi driver also managed to get out of his vehicle however his vehicle ended onto a tree at the left part of the road. Police then arrived and told me that the left side of my head was bleeding and they assisted to call for the ambulance. Ambulance arrived and conveyed me to NUH for treatment. I was warded for a day for observation and was subsequently given 9 days of Hospitalization Leave. I suffered lacerations on both hands, left side of my head and also bruises on both legs. There is no in built CCTV in my lorry. The rear right side of my vehicle was also dislodged from my lorry. The IO in charge of this accident is IO Sufian Tel: 65476367.

# F-1 AUTOCLINIC PTE LTD

Block 25 Kaki Bukit Road 4, #05-26 Synergy @ KB Singapore 417800  
 HP: 96583371 TEL: (65) 67022915 FAX: 67022916

SANTA FRESH VEGETABLE SUPPLIER  
 BLOCK 25 KAKI BUKIT ROAD 4  
 # 08-26 SYNERGY @KB  
 Singapore 417800

14<sup>th</sup> September 2017

Accident date: 11<sup>th</sup> September 2017

Estimated repair cost for vehicle no: GBC9451H Nissan CABSTAR '14

S/n	Qty	Items	U/price	Amount	
1	2	Front Head Lamp <i>cracked</i>	\$482.00	\$964.00	✓ (N)
2	2	Front Head Lamp lower apron <i>RH cut</i>	\$76.20	\$152.40	76.20 (N)
3	1	Front windscreen <i>shattered</i>		\$943.00	✓ (N)
4	1	Front windscreen moulding <i>new</i>		\$289.40	✓ (N)
5	1	front windscreen sealant <i>new</i>		\$60.00	✓ (SN)
6	1	ERP bracket <i>new</i>		\$26.00	✓ (SN)
7	1	front windscreen pillar RH <i>dented</i>		\$584.00	✓ (L)
8	1	front windscreen pillar inner garnish RH <i>deformed</i>		\$185.40	✓ (N)
9	1	Front Grille <i>cracked</i>		\$535.60	✓ (L)
10	1	Front Grille Clips <i>new</i>		\$10.00	✓ (L)
11	1	Front Grille Emblem Logo <i>new</i>		\$55.00	✓ (N)
12	1	Front Grille CABSTAR Logo <i>new</i>		\$48.50	✓ (N)
13	1	Front Bumper <i>cut</i>		\$933.40	✓ (L)
14	2	Front Bumper Bracket <i>RH Bent</i>	\$178.40	\$356.80	178.40 (L)
15	1	Front RH corner panel <i>dented</i>		\$437.00	✓ (L)
16	1	front panel <i>Repair</i>		\$1,583.60	✓ (L)
17	1	antenna <i>cut</i>		\$157.70	✓ (N)
18	1	Front dashboard <i>deformed</i>		\$1,667.40	✓ (L)
19	1	dashboard reinforcement <i>Bent</i>		\$873.90	✓ (L)
20	1	roof panel inner trim board <i>crumpled</i>		\$1,140.70	✓ (L)
21	1	roof panel inner trim board clips <i>new</i>		\$50.00	✓ (L)
22	1	front wiper panel garnish <i>new</i>		\$437.30	✓ (L)
23	1	front RH wing mirror stay cover <i>Missing</i>		\$113.20	✓ (L)
24	1	front RH wing mirror <i>Distorted</i>		\$139.80	✓ (L)
25	1	front RH wing mirror stay <i>Distorted</i>		\$192.90	✓ (N)

G3A 1968

## Sheet1

26	1	Front RH door Signal Lamp <i>wt</i>		\$46.50	✓	(N)
27	1	Front R/H Door <i>distorted</i>		\$1,696.40	✓	(L)
28	1	Front R/H Door visor <i>cracked</i>		\$60.00	✓	(SN)
29	1	Front R/H Door Sticker <i>new</i>		\$30.00	✓	(SN)
30	1	Front R/H Door Outer Handle <i>wt</i>		\$174.10	✓	(N)
31	1	Front R/H Door quarter Garnish <i>wt</i>		\$45.90	✓	(N)
32	1	Front R/H Door Inner Trim Board <i>delnd</i>		\$755.90	✓	(L)
33	1	FRONT R/H Door INNER TRIM Board clips <i>n</i>		\$30.00	✓	(L)
34	1	front RH door glass <i>shattered</i>		\$894.40	✓	(N)
35	1	front RH door glass outer moulding <i>wt</i>		\$155.80	✓	(N)
36	1	front RH door glass regulator <i>damaged</i>		\$217.30	✓	(N)
37	1	Front R/H Door Lock <i>jammed</i>		\$167.50	✓	(N)
38	1	Front R/H door WEATHERSTRIPE <i>wt</i>		\$136.70	✓	(N)
39	1	front door frame RH <i>distorted</i>		\$785.20	✓	(L)
40	1	front step garnish RH <i>wt</i>		\$140.10	✓	(N)
41	1	front wheel guard <i>wt</i>		\$186.60	✓	(N)
42	1	front RH lower arm <i>Best</i>		\$459.90	✓	(N)
43	1	RH front shock absorber <i>Best</i>		\$271.60	✓	(N)
44	1	front knuckle arm -RH <i>damaged</i>		\$904.80	✓	(N)
45	1	RH front wheel hub c/w bearing <i>damaged</i>		\$580.80	✓	(N)
46	1	spare tyre bracket <i>Best</i>		\$244.80	✓	(N)
47	1	side gate RH <i>distorted</i>		\$2,915.10	✓	(L)
48	4	RH side gate hinge <i>Best</i>	\$53.00	\$212.00	✓	(N)
49	1	stopper bracket RH <i>Best</i>		\$131.00	✓	(L)
50	1	tail gate aluminium panel <i>wt</i>		\$650.00	✓	300 (SN)
51	2	tail gate side lock-RH <i>Best</i>		\$58.20	✓	(N)
52	1	tail gate <i>distorted</i>		\$1,688.30	✓	(L)
53	1	rear exhaust pipe <i>Best</i>		\$566.10	✓	(N)
54	1	Rear center Exhaust <i>fine new</i>		\$624.10	x	(N)
55	1	Rear Exhaust mounting		\$37.40	x	(N)
56	1	fuel tank <i>distorted</i>		\$1,225.70	✓	(L)
57	2	fuel tank fastener <i>Best</i>	\$105.40	\$210.80	✓	(N)
58	1	radiator <i>not new</i>		\$759.20	x	(N)
59	1	radiator spare tank <i>delnd</i>		\$104.20	✓	(N)
60	1	radiator fan blade <i>new</i>		\$166.10	x	(N)
61	1	radiator fan <i>casting cracked</i>		\$136.80	✓	(N)
62	1	brake fluid reservoir <i>cracked</i>		\$124.10	✓	(N)
63	1	rear shock absorber -RH <i>Best</i>		\$191.60	✓	(N)
64	1	RH rear leafspring <i>Best</i>		\$892.60	✓	(N)
65	1	rear leafspring u bolt -RH <i>Best</i>		\$85.60	✓	(N)
66	1	propeller shaft <i>old new</i>		\$1,829.60	x	(L)
67	1	rear axle carrier <i>new</i>		\$4,680.80	x	(L)
68	1	rear wheel hub -RH <i>damaged</i>		\$484.60	✓	(N)

69	1	RH rear axle shaft <i>Bent</i>	\$524.70	✓ (N)
70	1	rear shaft bearing -RH <i>N</i>	\$113.50	✓ (N)

Subtotal :- \$38,333.40

S/n	Qty	Items/S Nett	U/price	Amount	
1	1	Front tyre <i>At</i>		<del>\$250.00</del>	150 (SN)
2	1	Front rim <i>At</i>		<del>\$200.00</del>	150 (SN)
3	1	front driver seat <i>Bent</i>		<del>\$1,500.00</del>	1000 (SN)
4	1	side gate aluminium panel RH <i>At</i>		<del>\$850.00</del>	300 (SN)
5	1	side gate aluminium panel rivet <i>N</i>		<del>\$50.00</del>	✓ (SN)
6	1	side gate top railing RH <i>Bent</i>		<del>\$580.00</del>	480 (SN)
7	1	RH stopper <i>Missing</i>		<del>\$20.00</del>	✓ (SN)
8	2	rear tyre -RH <i>1 piece cut</i>	\$180.00	<del>\$360.00</del>	150 (SN)
9	1	RH rear wheel rim <i>At</i>		<del>\$200.00</del>	150 (SN)
10	1	rear RH wheel guard -front <i>Distorted</i>		<del>\$284.50</del>	✓ (L)
11	1	rear wheel guard -RH (REAR ) <i>Distorted</i>		<del>\$209.40</del>	✓ (L)
12	1	RH rear wheel mudflap <i>Distorted</i>		<del>\$58.90</del>	✓ (L)
13	1	nissan sticker <i>N</i>		<del>\$83.60</del>	✓ (N)
14	1	tail gate aluminium panel rivets <i>N</i>		<del>\$50.00</del>	✓ (SN)
15	1	70km sticker <i>N</i>		<del>\$15.00</del>	✓ (SN)
16	1	air cond condenser <i>N</i>		<del>\$669.80</del>	✓ (SN)
17	1	radiator coolant <i>N</i>		<del>\$30.00</del>	✓ (SN)
18	1	brake fluid <i>N</i>		<del>\$30.00</del>	✓ (SN)
19	1	rear deck carrier <i>Ry</i>		<del>\$6,800.00</del>	✓ (SN)

Subtotal :- \$12,241.20

Labour charges

to remove & install front windscreen	\$180.00
to Remove & install dashboard	<del>\$380.00</del> 120
remove & Refix front door fitting	<del>\$150.00</del> 80
to remove & install rear desk carrier	<del>\$400.00</del> 350
to remove & Refix rear fuel tank	<del>\$150.00</del> 80
To remove & refix front undercarriage	<del>\$350.00</del> 220
To remove & refix rear undercarriage	<del>\$500.00</del> 400

to crane up & tow vehicle	<del>\$200.00</del> 150
to repair & straighten chassis member	<del>\$2,000.00</del> 1200
to Remove & install reverse sensor	<del>\$100.00</del> 50
to underseal	<del>\$300.00</del> 150
to remove & install cabin upholstery	<del>\$380.00</del> 200
to remove & install air con condenser , radiator & to up gas	<del>\$180.00</del> 120
To check wheel alignment computer	<del>\$150.00</del> 80
TO Remove & install rear exhaust	<del>\$300.00</del> 160
To Check Wiring System	<del>\$150.00</del> 60
Panel beating	<del>\$3,800.00</del> 1500
Spray painting	<del>\$3,000.00</del> 2000

Subtotal :- \$12,670.00

Total:- \$63,244.60

list : 15000.10  
 less 30% : 10500.07  
 Nett : 12687.40  
 less 10% : 11418.66

S.N: 3051  
 Labour : 5670  
 total : 30639.73.  
 v/s 24.5K.

28 Days.

KK Auto Consultants hence notify  
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:




# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI17017848/Atbe2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 26-01-2018	
			Code : FCI2	
<b>1. Policy Particulars : THIRD PARTY CLAIM</b>				
Insured Veh.	SHA 7607D	Veh. Inspected	GBC 9451H	
Policy No.	D-15072701MFSH	Coverage (\$)	0.00	
Claim No.	D17008791MFSH	Excess (\$)	0.00	
Assign From	JOANNEY YONG	Assign Date	15/09/2017	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	NISSAN CABSTAR	c.c	2953	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	JN1SC2F24Z0855514	Colour	SILVER	
Odometer	-	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	195 R15C	MICHELIN	6 mm	
L/H Front Tyre	195 R15C	MICHELIN	6 mm	
R/H Rear Tyre	155 R12C	YOKOHAMA	6 mm	
L/H Rear Tyre	155 R12C	YOKOHAMA	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY, FRONT AND UNDERCARRIAGE PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	11/09/2017	Inspection Date	15/09/2017	
Survey held at	1 KAKI BUKIT AVE 6 #01-43			
Repairer	F-1 AUTOCLINIC PTE LTD			
<b>5a. Remarks</b>				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		28 Working Days		



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBC 9451H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	FRONT WINDSCREEN PILLAR RH	DENTED	584.00	584.00
1	FRONT GRILLE	CRACKED	535.60	535.60
1	FRONT GRILLE CLIPS	NECESSARY	10.00	10.00
1	FRONT BUMPER	CUT	933.40	933.40
2	FRONT BUMPER BRACKET @\$178.40	O/S BENT	356.80	178.40
1	FRONT RH CORNER PANEL	DENTED	437.00	437.00
1	FRONT PANEL	TO REPAIR SEE LABOUR	1,583.60	-
1	FRONT DASHBOARD	DEFORMED	1,667.40	1,667.40
1	DASHBOARD REINFORCEMENT	BENT	873.90	873.90
1	FRONT WIPER PANEL GARNISH	NOT NECESSARY	437.30	-
1	FRONT R/H DOOR	DISTORTED	1,696.40	1,696.40
1	FRONT R/H DOOR INNER TRIM BOARD	DEFORMED	755.90	755.90
1	FRONT R/H DOOR INNER TRIM BOARD CLIPS	NECESSARY	30.00	30.00
1	FRONT DOOR FRAME RH	DENTED	785.20	785.20
1	SIDE GATE RH	DENTED	2,915.10	2,915.10
1	STOPPER BRACKET RH	BENT	131.00	131.00
1	TAIL GATE	DENTED	1,688.30	1,688.30
1	FUEL TANK	DENTED	1,225.70	1,225.70
1	PROPELLER SHAFT	NOT NECESSARY	1,829.60	-
1	REAR AXLE CARRIER	NOT NECESSARY	4,680.80	-
1	REAR RH WHEEL GUARD - FRONT	DISTORTED	284.50	284.50
1	REAR WHEEL GUARD - RH (REAR)	DISTORTED	209.40	209.40
1	RH REAR WHEEL MUDFLAP	DISTORTED	58.90	58.90
	LESS 30% DISCOUNT		-	-4,500.03
			23,709.80	10,500.07
<b>NETT ITEMS</b>				
2	FRONT HEAD LAMP @\$482.00 (N)	CRACKED	964.00	964.00
2	FRONT HEAD LAMP LOWER APREN @\$76.20 (N)	O/S CUT	152.40	76.20
1	FRONT WINDSCREEN (N)	SHATTERED	943.00	943.00
1	FRONT WINDSCREEN MOULDING (N)	NECESSARY	289.40	289.40

Report Ref No. CS/FCI17017848/Atbe2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT WINDSCREEN PILLAR INNER GARNISH RH (N)	DEFORMED	185.40	185.40
1	FRONT GRILLE EMBLEM LOGO (N)	NECESSARY	55.00	55.00
1	FRONT GRILLE CABSTAR LOGO (N)	NECESSARY	48.50	48.50
1	ANTENNA (N)	CUT	157.70	157.70
1	ROOF PANEL INNER TRIM BOARD (N)	CRUMPLED	1,140.70	1,140.70
1	ROOF PANEL INNER TRIM BOARD CLIPS (N)	NECESSARY	50.00	50.00
1	FRONT RH WING MIRROR STAY COVER (N)	MISSING	113.20	113.20
1	FRONT RH WING MIRROR (N)	DISTORTED	139.80	139.80
1	FRONT RH WING MIRROR STAY (N)	DISTORTED	192.90	192.90
1	FRONT RH DOOR SIGNAL LAMP (N)	CUT	46.50	46.50
1	FRONT R/H DOOR OUTER HANDLE (N)	CUT	174.10	174.10
1	FRONT R/H DOOR QUARTER GARNISH (N)	CUT	45.90	45.90
1	FRONT RH DOOR GLASS (N)	SHATTERED	894.40	894.40
1	FRONT RH DOOR GLASS OUTER MOULDING (N)	CUT	155.80	155.80
1	FRONT RH DOOR GLASS REGULATOR (N)	DAMAGED	217.30	217.30
1	FRONT R/H DOOR LOCK (N)	JAMMED	167.50	167.50
1	FRONT R/H DOOR WEATHERSTRIP (N)	CUT	136.70	136.70
1	FRONT STEP GARNISH RH (N)	CUT	140.10	140.10
1	FRONT WHEEL GUARD (N)	CUT	186.60	186.60
1	FRONT RH LOWER ARM (N)	BENT	459.90	459.90
1	RH FRONT SHOCK ABSORBER (N)	BENT	271.60	271.60
1	FRONT KNUCKLE ARM - RH (N)	DAMAGED	904.80	904.80
1	RH FRONT WHEEL HUB C/W BEARING (N)	DAMAGED	580.80	580.80
1	SPARE TYRE BRACKET (N)	BENT	244.80	244.80
4	RH SIDE GATE HINGE @\$53.00 (N)	BENT	212.00	212.00
2	TAIL GATE SIDE LOCK - RH (N)	BENT	58.20	58.20
1	REAR EXHAUST PIPE (N)	BENT	566.10	566.10
1	REAR CENTER EXHAUST (N)	NOT NECESSARY	624.10	-
1	REAR EXHAUST MOUNTING (N)	NOT NECESSARY	37.40	-
2	FUEL TANK FASTENER @\$105.40 (N)	BENT	210.80	210.80
1	RADIATOR (N)	NOT NECESSARY	759.20	-
1	RADIATOR SPARE TANK (N)	DEFORMED	104.20	104.20
1	RADIATOR FAN BLADE (N)	NOT NECESSARY	166.10	-

Report Ref No. CS/FCI17017848/Atbe2





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop(\$)	Our Adjusted (\$)
1	RADIATOR FAB COWLING (N)	CRACKED	136.80	136.80
1	BRAKE FLUID RESERVOIR (N)	CRACKED	124.10	124.10
1	REAR SHOCK ABSORBER - RH (N)	BENT	191.60	191.60
1	RH REAR FAIRING (N)	BENT	892.60	892.60
1	REAR LEAFSPRING U BOLT - RH (N)	BENT	85.60	85.60
1	REAR WHEEL HUB - RH (N)	DAMAGED	484.60	484.60
1	RH REAR AXLE SHAFT (N)	BENT	524.70	524.70
1	REAR SHAFT BEARING - RH (N)	NECESSARY	113.50	113.50
1	NISSAN STICKER (N)	NECESSARY	83.60	83.60
	LESS 10% DISCOUNT		-	-1,277.10
			14,434.00	11,493.90
	<b>SPECIAL NETT ITEMS</b>			
1	FRONT WINDSCREEN SEALANT (SN)	NECESSARY	60.00	60.00
1	ERP BRACKET (SN)	NECESSARY	26.00	26.00
1	FRONT R/H DOOR VISOR (SN)	CRACKED	60.00	60.00
1	FRONT R/H DOOR STICKER (SN)	NECESSARY	30.00	30.00
1	TAIL GATE ALUMINIUM PANEL (SN)	CUT	650.00	300.00
1	FRONT TYRE (SN)	CUT	250.00	150.00
1	FRONT RIM (SN)	CUT	200.00	150.00
1	FRONT DRIVER SEAT (SN)	BENT	1,500.00	1,000.00
1	SIDE GATE ALUMINIUM PANEL RH (SN)	CUT	850.00	300.00
1	SIDE GATE ALUMINIUM PANEL RIVET (SN)	NECESSARY	50.00	50.00
1	SIDEGATE TOP RAILING RH (SN)	BENT	580.00	480.00
1	RH STOPPER (SN)	MISSING	20.00	20.00
2	REAR TYRE - RH @\$180.00 (SN)	CUT-1 PC ONLY	360.00	150.00
1	RH REAR WHEEL RIM (SN)	CUT	200.00	150.00
1	TAIL GATE ALUMINIUM PANEL RIVETS (SN)	NECESSARY	50.00	50.00
1	70KM STICKER (SN)	NECESSARY	15.00	15.00
1	AIR COND CONDENSER (SN)	NOT NECESSARY	669.80	-
1	RADIATOR COOLANT (SN)	NECESSARY	30.00	30.00
1	BRAKE FLUID (SN)	NECESSARY	30.00	30.00

Report Ref No. CS/FCI17017848/Atbe2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR DECK CARRIER (SN)	TO REPAIR SEE LABOUR	6,800.00	-
			12,430.80	3,051.00
	<b>LABOUR</b>			
	SPRAY PAINTING.		3,000.00	2,000.00
	TO REMOVE & INSTALL FRONT WINDSCREEN.		180.00	180.00
	TO REMOVE & INSTALL DASHBOARD.		380.00	120.00
	REMOVE & REFIX FRONT DOOR FITTING.		150.00	80.00
	TO REMOVE & INSTALL REAR DESK CARRIER.		400.00	350.00
	TO REMOVE & REFIX REAR FUEL TANK.		150.00	80.00
	TO REMOVE & REFIX FRONT UNDERCARRIAGE.		350.00	220.00
	TO REMOVE & REFIX REAR UNDERCARRIAGE.		500.00	400.00
	TO CRANE UP & TOW VEHICLE.		200.00	150.00
	TO REPAIR & STRAIGHTEN CHASSIS MEMBER.		2,000.00	1,200.00
	TO REMOVE & INSTALL REVERSE SENSOR.		100.00	50.00
	TO UNDERSEAL.		300.00	150.00
	TO REMOVE & INSTALL CABIN UPHOLSTERY.		380.00	200.00
	TO REMOVE & INSTALL AIR CON CONDENSER, RADIATOR & TOP UP GAS.		180.00	120.00
	TO CHECK WHEEL ALIGNMENT COMPUTER.		150.00	80.00
	TO REMOVE & INSTALL REAR EXHAUST.		300.00	160.00
	TO CHECK WIRING SYSTEM.		150.00	60.00
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF FRONT PANEL AND REAR DECK CARRIER.		3,800.00	1,500.00
			12,670.00	7,100.00
<b>GRAND TOTAL</b>			<b>63,244.60</b>	<b>32,144.97</b>

<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>24,500.00</b>
---	--	--	------------------

Report Ref No. CS/FCI17017848/Atbe2

MARKET VALUE: \$52,000.00 (EST)-PAPER VALUE: \$27,000.00=NETT VALUE: \$25,000.00

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report in whole or in part, does so at his or her own risk.