

ASS. REC. BY:

REF: CS/FCI17017849/R1qbn2

Special Instruction:

SUBJECT: Road ASSIGNMENT (Office)

From (Person): Karen Tan of FCI Date/Time: 15/9/17 11:23am

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD /  TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GBA 8296G Insured: SHD 3336X

at Workshop m/s C L Auto Tel: 67956125 / 90051911

of 48 Toh Guan Rd East # 02-125

Policy No: P15077701MFSH Claim No: D17008696MFSH

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 10/9/17  
(Client's Record)

CA / REV / REP. / REV 24 HRS 'DS' 18/9/17 @ 11am owner waiting  
H.O.D. Endorsement: \_\_\_\_\_

Date/Time: 15/9/17 12:00pm Person Contacted: Michael Low Vehicle  IN  OUT

Date/Time	Action/Instruction ( <input checked="" type="checkbox"/> ) Estimate
	<u>GBA 8296G-X</u>
	<u>SHD 3336X - CS/FCI17003731/K1vbn2-D.O.A: 10/2/2017</u>
	<u>US \$3850, 6 days (red \$6087.43, 6176)</u>





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI17017849/R1qb

36 ROBINSON ROAD  
#16-01 CITY HOUSESINGAPORE 068877

Date : 15-09-2017



Code : FCI2

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHD 3336X	Veh. Inspected	GBA 8269G
Policy No.		Coverage (\$)	0.00
Claim No.	D17008696MFSH	Excess (\$)	0.00
Assign From	CWS (KAREN TAN)	Assign Date	15/09/2017

## 2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	10/09/2017	Inspection Date	
Survey held at	C L AUTO PTE LTD 48 TOH GUAN ROAD EAST #02-127 ENTERPRISE HUP SINGAPORE 608586		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--



**MOTOR SURVEY ASSIGNMENT**

<b>Date</b>	12-09-2017	<b>Our Ref No.</b> D17008696MFSH
<b>Accident Date</b>	10-09-2017	<b>Claim Type.</b> Third Party
<b>Insured Vehicle</b>	SHD3336X	<b>Third Party Vehicle.</b> GBA8296G
<b>Survey Location</b>	48 TOH GUAN ROAD EAST #02-125 ENTERPRISE HUB	
<b>Contact Person.</b>	MICHAEL LOW	
<b>Contact No.</b>	67956125/ 90051911	<b>Fax No.</b> 67950920
<b>Survey Type</b>	DIRECT SETTLEMENT:	
<b>Appointed Surveyor</b>	LKK AUTO CONSULTANTS PTE LTD	
<b>Contact Person</b>	NA	<b>Fax No.</b> 68416315
<b>Contact Number.</b>	NA	

**FOR DIRECT SETTLEMENT**

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

## THIRD PARTY SURVEY REQUEST

<b>Cc : Workshop</b>	C L AUTO PTE LTD	<b>Attention.</b> NIL
<b>Cc : TP Solicitor</b>	NA	<b>TP Solicitor Fax No.</b> NA
<b>Officer Incharge</b>	KARENT	

**IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/227901)



PRI Documents



Close



## PRI Header Details

<b>Claim No</b>	D17008696MFSH	<b>Policy No</b>	D-15072701MFSH	<b>Claimant S.No &amp; Name</b>	1 & C L AUTO
<b>Workshop Name</b>	C L AUTO PTE LTD (Contact Person : MICHAEL LOW)	<b>Survey Location &amp; Contact Details</b>	48 TOH GUAN ROAD EAST #02-125 ENTERPRISE HUB <b>Mobile:</b> 90051911 , <b>Phone:</b> 67956125 , <b>Fax:</b> 67950920 <b>EmailId:</b> MICHAEL.CLAUTO.2017@GMAIL.COM		
<b>Our Surveyor</b>	LKK AUTO CONSULTANTS PTE LTD	<b>Instructions To Surveyor</b>	DIRECT SETTLEMENT:		
<b>Insured Name</b>	COMFORT TRANSPORTATION PTE LTD	<b>Insured Vehicle No</b>	SHD3336X	<b>TP Vehicle No</b>	GBA8296G
<b>PRI Recieved Date</b>	14-09-2017 02:44:46 PM	<b>Surveyor Appointed Date</b>	15-09-2017 11:23:45 AM	<b>Surveyor Accept Date</b>	15-09-2017 1

## Survey Report Upload

<b>Surveyor Inspection Date *:</b>	<input type="text"/>	<b>Surveyor Report Date</b>	15-09-2017	<b>Upload Survey Report *:</b>	<input type="button" value="Choose File"/>
------------------------------------	----------------------	-----------------------------	------------	--------------------------------	--

## Vehicle Particulars

<b>Make</b>	<input type="text" value="Please Select Make"/>	<b>Model</b>	<input type="text" value="Please Select Model"/>	<b>Year</b>	<input type="text" value="Select Year"/>
<b>Chasis No</b>	<input type="text"/>	<b>Engine No</b>	<input type="text"/>	<b>Mileage</b>	<input type="text"/>
<b>Color</b>	<input type="text"/>	<b>Cubic Capacity</b>	<input type="text"/>		

## Multiple Documents Upload

File Name

Action

## Surveyor Job Remarks

Remarks



中英汽車(私人)有限公司 シーエルオート PTE LTD

# CL AUTO PTE LTD

(ACRA No. 198800292M)

48 Toh Guan Road East, #02-125 / #02-127 Enterprise Hub, Singapore 608586

Website: www.clauto.com.sg

Email: ks@clauto.com.sg

Tel: 67956125

Fax: 67950920

M/S : UNIQUE ENTERPRISE  
1010 DOVER ROAD  
#01-29V SINGAPORE 139658

ATTN: MR. GOH

Your Ref No: GBA8296G  
Claim Type: Third Party  
Accident Date:

Estimate No: EST1700161  
Date: 12 Sep 2017  
Policy No:  
Veh Reg No: GBA8296G  
Make/Model: NISSAN URVAN PANEL  
LWB 3.0 5DR 4AT ABS  
AIRBAG  
Chassis No: JN1MG4E25Z0780385  
Engine No: ZD301522426K  
Reg. Date:  
Payment Term: COD

## Estimate Repair Cost to Vehicle No : GBA8296G

Description	Quantity	List Price	Amount
			SS
<b>Net Price:</b>			
1 FRONT LHS HEADLAMP ASSEMBLY	1 PC	521.60	7x300
2 FRONT LHS SIGNAL LAMP ASSEMBLY	1 PC	178.30	Pro
3 FRONT LHS DOOR UPPER HINGE	1 PC	62.10	Xx300
4 FRONT LHS DOOR LOWER HINGE	1 PC	62.10	7x300
5 FRONT LHS STEP GARNISH	1 PC	406.60	PCU
6 FRONT LHS STEP GARNISH CLIPS	1 SET	27.50	ne -
7 FRONT LHS DOOR WEATHERSTRIP	1 PC	121.20	ne -
8 FRONT LHS DOOR LOWER WEATHERSTRIP	1 PC	25.20	ne -
9 FRONT LHS DOOR STOPPER LINK	1 PC	58.20	X 300
10 FRONT BUMPER CLIPS	1 SET	44.00	ne -
11 FRONT WINDSCREEN MOULDING	1 PC	100.00	X 300 ny
12 FRONT WINDSCREEN SEALANT DAM	1 PC	22.80	X 300 ny
13 FRONT WINDSCREEN STOPPER	2 PC	45.60	X 300
		1,675.20	
	Less 10%	167.52	1,507.68
<b>Special Net:</b>			
14 LGV STICKER	1 PC	25.00	25 ne
15 WINDSCREEN SEALANT	2 TUBE	48.00	X ny
		73.00	73.00
<b>List Price:</b>			
16 FRONT BUMPER ASSEMBLY	1 PC	720.10	DE
17 FRONT BUMPER FOGLIGHT GARNISH	1 PC	143.10	aut -
18 FRONT LHS BUMPER SIDE BRACKET	1 PC	100.90	ne -
19 FRONT LHS BUMPER STAY	1 PC	100.90	7x300
20 FRONT LHS BUMPER LOWER RETAINER	1 PC	100.90	7x300
21 FRONT LHS CORNER PANEL	1 PC	589.10	BT
22 FRONT LHS CORNER PANEL CENTRE BRACKET	1 PC	93.60	7x300
23 FRONT LHS CORNER PANEL LOWER BRACKET	1 PC	93.60	7x300
24 FRONT LHS CORNER PANEL SEAL	1 PC	39.10	ne -
25 FRONT LHS DOOR ASSEMBLY	1 PC	1,491.80	PA
26 FRONT LHS STEP PANEL	1 PC	129.50	BT
27 FRONT LHS DOOR PILLAR OUTER PANEL	1 PC	1,274.10	R
28 FRONT LHS DOOR PILLAR INNER PANEL	1 PC	275.80	X 300



中英汽車(私人)有限公司 シーエルオート PTE LTD

# CL AUTO PTE LTD

(ACRA No. 198800292M)

48 Toh Guan Road East, #02-125 / #02-127 Enterprise Hub, Singapore 608586

Website: www.clauto.com.sg

Email: ks@clauto.com.sg

Tel: 67956125

Fax: 67950920

M/S : UNIQUE ENTERPRISE  
1010 DOVER ROAD  
#01-29V SINGAPORE 139658

ATTN: MR. GOH

Your Ref No: GBA8296G  
Claim Type: Third Party  
Accident Date:

Estimate No: EST1700161  
Date: 12 Sep 2017  
Policy No:  
Veh Reg No: GBA8296G  
Make/Model: NISSAN URVAN PANEL  
LWB 3.0 5DR 4AT ABS  
AIRBAG  
Chassis No: JN1MG4E25Z0780385  
Engine No: ZD301522426K  
Reg. Date:  
Payment Term: COD

### Estimate Repair Cost to Vehicle No : GBA8296G

Description	Quantity	List Price	Amount
		SS	SS
	3213.60	5,152.50	
	30%	1,545.75	3,606.75
	2249.52		
<b>Labour Charges:</b>			
29 TO REMOVE & REFIX FRONT WINDSCREEN	1-	200.00	X11
30 TO REMOVE & REFIX DASHBOARD, METER CLUSTER & INSTRUMENT PANEL	1-	480.00	X11
31 TO REMOVE & REFIX AIR CON COOLING COIL & BLOWER MOTOR ASSY. TO VACUUM & TOP UP AIR CON GAS	1-	380.00	X11
32 TO TRANSFER FRONT LHS DOOR LOCK, OUTSIDE MOULDING, WINDOW GLASS, WINDOW REGULATOR, WINDOW MOTOR ASSY & GLASS CHANNEL	1-	180.00	80
33 TO STRAIGHTEN FRONT FIREWALL PANEL, CUT & WELD INNER DOOR PILLAR, OUTER DOOR PILLAR & FRONT GLASS PANEL. TO REALIGN FRONT DOOR ASSY, FRONT WINDSCREEN, FRONT HEADLAMP COMBINATION & REPLACE BUMPER ASSY	1-	1,300.00	600 1840
34 TO RESPRAY PAINT FRONT BUMPER ASSY - 300	1-	380.00	250
35 TO UNDERCOAT AFFECTED PORTION	1-	250.00	60
36 TO RESPRAY PAINT FRONT DOOR INNER & OUTER - 380	1-	380.00	250
37 TO RESPRAY PAINT FRONT LHS FLOOR BOARD, WHEEL ARC, DOOR PILLAR INNER & OUTER, FRONT PANEL, FRONT HEADLAMP PANEL, LHS CORNER PANEL & FRONT WINDSCREEN PANEL - 350	1-	1,200.00	200
		4,750.00	4,750.00
		Total	SS 9,937.43

TOTAL: SINGAPORE DOLLAR NINE THOUSAND NINE HUNDRED THIRTY SEVEN AND CENTS FORTY THREE ONLY

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Rasul  
Hp 90010068 For C L Auto Pte Ltd  
6 days  
45  
18/09/17 e1110  
Resurvey after repair  
email: rasul@lkkauto.com  
6day  
722.52  
25.00  
2249.52  
1840.00  
4837.04  
20%



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI17017849/R1qbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 29-11-2017	
		Code : FCI2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	SHD 3336X	Veh. Inspected	GBA 8296G
Policy No.	D-15072701MFSH	Coverage (\$)	0.00
Claim No.	D17008696MFSH	Excess (\$)	0.00
Assign From	KARENT	Assign Date	15/09/2017
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	NISSAN URVAN PANEL 3.0	c.c	2953
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	JN1MG4E25Z0780385	Colour	WHITE
Odometer	206505	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	195 R15C	BRIDGESTONE	6 mm
L/H Front Tyre	195 R15C	BRIDGESTONE	6 mm
R/H Rear Tyre	195 R15C	BRIDGESTONE	6 mm
L/H Rear Tyre	195 R15C	BRIDGESTONE	6 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	09/09/2017	Inspection Date	18/09/2017
Survey held at	C L AUTO PTE LTD 48 TOH GUAN ROAD EAST #02-127 ENTERPRISE HUP SINGAPORE 608586		
<b>5a. Remarks</b>			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 3

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBA 8296G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	FRONT BUMPER ASSEMBLY	DEFORMED	720.10	720.10
1	FRONT BUMPER FOGLIGHT GARNISH	CUT	143.10	143.10
1	FRONT LHS BUMPER SIDE BRACKET	NECESSARY	100.90	100.90
1	FRONT LHS BUMPER STAY	SERVICEABLE	100.90	-
1	FRONT LHS BUMPER LOWER RETAINER	SERVICEABLE	100.90	-
1	FRONT LHS CORNER PANEL	BENT	589.10	589.10
1	FRONT LHS CORNER PANEL CENTRE BRACKET	SERVICEABLE	93.60	-
1	FRONT LHS CORNER PANEL LOWER BRACKET	SERVICEABLE	93.60	-
1	FRONT LHS CORNER PANEL SEAL	NECESSARY	39.10	39.10
1	FRONT LHS DOOR ASSEMBLY	BENT	1,491.80	1,491.80
1	FRONT LHS STEP PANEL	BENT	129.50	129.50
1	FRONT LHS DOOR PILLAR OUTER PANEL	TO REPAIR SEE LABOUR	1,274.10	-
1	FRONT LHS DOOR PILLAR INNER PANEL	SERVICEABLE	275.80	-
	LESS 30% DISCOUNT		-1,545.75	-964.08
			3,606.75	2,249.52
<b>NETT ITEMS</b>				
1	FRONT LHS HEADLAMP ASSEMBLY (N)	SERVICEABLE	521.60	-
1	FRONT LHS SIGNAL LAMP ASSEMBLY (N)	BROKEN	178.30	178.30
1	FRONT LHS DOOR UPPER HINGE (N)	SERVICEABLE	62.10	-
1	FRONT LHS DOOR LOWER HINGE (N)	SERVICEABLE	62.10	-
1	FRONT LHS STEP GARNISH (N)	SCRATCHED	406.60	406.60
1	SET FRONT LHS STEP GARNISH CLIPS (N)	NECESSARY	27.50	27.50
1	FRONT LHS DOOR WEATHERSTRIP (N)	NECESSARY	121.20	121.20
1	FRONT LHS DOOR LOWER WEATHERSTRIP (N)	NECESSARY	25.20	25.20
1	FRONT LHS DOOR STOPPER LINK (N)	SERVICEABLE	58.20	-
1	SET FRONT BUMPER CLIPS (N)	NECESSARY	44.00	44.00
1	FRONT WINDSCREEN MOULDING (N)	NOT NECESSARY	100.00	-
1	FRONT WINDSCREEN SEALANT DAM (N)	NOT NECESSARY	22.80	-
2	FRONT WINDSCREEN STOPPER (N)	SERVICEABLE	45.60	-

Report Ref No. CS/FCI17017849/R1qbn2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 10% DISCOUNT		-167.52	-80.28
			1,507.68	722.52
	<b>SPECIAL NETT ITEMS</b>			
1	LGV STICKER (SN)	NECESSARY	25.00	25.00
2	TUBE WINDSCREEN SEALANT (SN)	NOT NECESSARY	48.00	-
			73.00	25.00
	<b>LABOUR</b>			
	TO REMOVE & REFIX FRONT WINDSCREEN.	NOT NECESSARY	200.00	-
	TO REMOVE & REFIX DASHBOARD, METER CLUSTER & INSTRUMENT PANEL.	NOT NECESSARY	480.00	-
	TO REMOVE & REFIX AIR CON COOLING COIL & BLOWER MOTOR ASSY. TO VACUUM & TOP UP AIR CON GAS.	NOT NECESSARY	380.00	-
	TO TRANSFER FRONT LHS DOOR LOCK, OUTSIDE MOULDING, WINDOW GLASS, WINDOW REGULATOR, WINDOW MOTOR ASSY & GLASS CHANNEL.		180.00	80.00
	TO STRAIGHTEN FRONT FIREWALL PANEL, CUT & WELD INNER DOOR PILLAR, OUTER DOOR PILLAR & FRONT GLASS PANEL. TO REALIGN FRONT DOOR ASSY, FRONT WINDSCREEN, FRONT HEADLAMP COMBINATION & REPLACE BUMPER ASSY. INCLUSIVE OF THE REPAIR OF FRONT LHS DOOR PILLAR OUTER PANEL.		1,300.00	800.00
	TO RESPRAY PAINT FRONT BUMPER ASSY.		380.00	300.00
	TO UNDERCOAT AFFECTED PORTION.		250.00	60.00
	TO RESPRAY PAINT FRONT DOOR INNER & OUTER.		380.00	300.00
	TO RESPRAY PAINT FRONT LHS FLOOR BOARD, WHEEL ARC, DOOR PILLAR INNER & OUTER, FRONT PANEL, FRONT HEADLAMP PANEL, LHS CORNER PANEL & FRONT WINDSCREE PANEL.		1,200.00	300.00
	-		-	-
	-		-	-
			4,750.00	1,840.00
	<b>GRAND TOTAL</b>		<b>9,937.43</b>	<b>4,837.04</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>3,850.00</b>

Report Ref No. CS/FCI17017849/R1qbn2



Report Ref No. CS/FCI17017849/R1qbn2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.  
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.