

ASS. REC. BY:

REF:

CG/TP17017991/Cgbn2

Special Instruction:

Surveyor:

GA

ASSIGNMENT (Office)

From (Person):

Lim Siang Teck

of

Areda Adjusters

Date/Time:

18/09/2017 11:23am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHD 3853U

Insured:

Public Liability

at Workshop m/s

Comfort Delgro

Tel:

8471 6644

of

600 Sin Ming Avenue Citycab Building

Policy No:

1793533 / LST

Claim No:

AC170367

Sum Insured:

65508568 christine

Excess:

Make of Veh:

Elin 62148735

D.O.A

11-09-2017

(Client's Record)

CA / REV / REP. / REV 24 HRS WP

H.O.D. Endorsement:

Date/Time:

18/09/2017

Person Contacted:

Kelvin

Vehicle IN OUT

Date/Time	Action/Instruction (✓) Estimate	Vehicle
	SHD 3853U - 003/EQ116014753/H1pa342	Vehicle scrape
	Public Liability - x	DUA: 060876





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AREDA ADJUSTERS PL

Ref : CS/LAW17017995/Ggb

195 PEARL'S HILL TERRACE  
#02-63 SINGAPORE 168976

Date : 19-09-2017



Code : L125

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	PUBLIC LIABILITY	Veh. Inspected	SHD 3853U
Policy No.	1793533/LST	Coverage (\$)	0.00
Claim No.	AC170367	Excess (\$)	0.00
Assign From	LIM SIANG TECK	Assign Date	18/09/2017

## 2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	11/09/2017	Inspection Date	18/09/2017
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 600 SIN MING AVENUE CITYCAB BUILDING SINGAPORE 575733		

## 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
---

**Catherine Chong (LKK Auto)**

---

**From:** Lee Siang Teck <leesiangteck@areda.com.sg>  
**Sent:** Monday, 18 September, 2017 11:23 AM  
**To:** assignments@lkkauto.com  
**Cc:** Jackson Yeo  
**Subject:** Motor assessment on 3 dmaaged taxis  
**Attachments:** 1793533 Repair estimates.pdf

Our Ref : 1793533/LST

Dear Catherine

We refer to our telephone conversation this morning, 18 September 2017.

As discussed, please conduct motor survey on 3 damaged taxis (i.e. SHA 2574Y, SHD 3853U & SHC 1506R) for our Principal, India International Insurance Pte Ltd. The repair estimates is enclosed for your perusal.

Please contact Mr Kelvin Tan of Comfort Transportation Pte Ltd for the survey. His contact nos. :

Hand phone      8491 6644

DID                6550 8571

If you need any clarification, please contact the undersigned.

Thank you.

Best Regards

*Lee Siang Teck*

**Areda Adjusters Pte Ltd**  
195 Pearl's Hill Terrace, #02-63  
Singapore 168976

Tel: 6557 0258 Fax: 6557 0256

The logo for AREDA, featuring the word "AREDA" in a bold, stylized, sans-serif font. The letters are thick and have a slightly distressed or metallic appearance.

Text size + -

**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Company  
 Owner ID: 3821R

**Vehicle Details**

Vehicle No.: SHD3853U  
 Vehicle to be Exported: No  
 Intended De-registration Date: 19 Sep 2017  
 Vehicle Make: HYUNDAI  
 Vehicle Model: SONATA NF 2.0 CRDI AT ABS 2WD 4DR TURBO  
 Primary Colour: Blue  
 Manufacturing Year: 2010  
 Engine No.: D4EA8609561  
 Chassis No.: KMHET41VMAA793711  
 Maximum Power Output: 110.0 kW (147 bhp)  
 Open Market Value: \$16,276.00  
 Original Registration Date: 09 Sep 2010  
 First Registration Date: 09 Sep 2010  
 Transfer Count: 0  
 Actual ARF Paid: \$16,276.00

**Intended PARF Rebate Details**

PARF Eligibility: Yes  
 PARF Eligibility Expiry Date: 08 Sep 2018  
 PARF Rebate Amount: \$9,765.00

**Intended COE Rebate Details**

COE Expiry Date: 08 Sep 2018  
 COE Category: A - Car (1600cc & below)  
 COE Period(Years): 8  
 QP Paid: \$27,201.00  
 COE Rebate Amount: \$3,302.00

**Total Rebate Amount: \$13,067.00****Message**

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 19 Sep 2017

OK

Land Transport  Authority

Please read through the Privacy Statement, Terms of Use and Disclaimer.  
 Please do not use the **Back** or **Forward** buttons on your browser as this may alter the results of the transactions.  
 Best viewed with IE 6.0 SP3 and above. 1024 X 768 resolution  
 Copyright © 2017 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#) | [Rate this e-Service](#)  
 Last updated on 27 Aug 2017 at 01:09 AM

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE\*

VEHICLE NO : SHD 3853U

MAKE :

MODEL : HYUNDAI SONATA

LKK Auto Consultants hence notify the Repairer of the following:  
 • To resurvey before/after spray painting  
 • To display damaged part(s) during resurvey  
 • Parts prices are subject to confirmation  
 • Third party survey is on a "Without Prejudice" basis  
 • No illegal modification(s) is allowed  
 • Supplementary item(s) must be resurveyed and is subject to final approval by the Insurance Company

DATE 9/15/2017 16:03

Acknowledged by Repairer

Signature:

Qty	Parts Description/ Labour	Date	Type	Unit Price	Amount
	Bonnet / Buc				\$ 1,151.80
	Front Bumper Cover X Repair				\$ 538.80
	Front Bumper Grille (LH/RH) X NN			\$ 17.60	\$ 35.20
	Headlamp Support Panel Assy ?				\$ 1,023.00
	Headlamp (LH/RH) ?			\$ 797.90	\$ 1,595.80
	Front Fender (RH) X Repair				\$ 593.00
	Door Centre Pillar Outer (LH/RH) X Repair			\$ 1,711.70	\$ 3,423.40
	Front Windscreen Glass - UFA				\$ 1,015.00
	Front Windscreen Moulding - MC				\$ 60.00
	Front Windscreen Pillar Outer (LH/RH) X Repair			\$ 1,766.20	\$ 3,532.40
	Roof Panel / Dis				\$ 1,194.90
	Dashboard Complete ?				\$ 2,576.00
	Boot Lid / Buc				\$ 1,349.50
	Rear Windscreen Glass X NN				\$ 639.00
	Rear Windscreen Moulding X NN				\$ 60.00
	<b>SUB TOTAL</b>				<b>\$18,787.80</b>
	<b>LESS 20%</b>				<b>\$ 3,757.56</b>
	<b>DISCOUNTED TOTAL</b>				<b>\$15,030.24</b>
	Front Windscreen Sealant - MC				\$ 46.00
	Rear Windscreen Sealant X NN				\$ 46.00
					<b>\$ 92.00</b>
	<b>Labour Charge</b>				
	Panel Beating				\$ 2,500.00
	Spray Painting Charge				\$ 1,600.00
	Wiring Charge				\$ 50.00
	Tuff Kote				\$ 100.00
	Remove/Refix Cushion & Upholstery Rear				\$ 150.00
	Remove/Refix Rear Windscreen Glass				\$ 120.00
	Remove/Refix Front Windscreen Glass				\$ 120.00
	Remove/Refix Cushion & Upholstery Front				\$ 90.00
	Remove/Refix Roof Top Taxi Digital Sign				\$ 150.00
	<b>TOTAL LABOUR</b>				<b>\$ 4,880.00</b>
	<b>ESTIMATE TOTAL</b>				<b>\$20,002.24</b>

Nett  
Nett

1400  
1400  
30  
80  
60  
X  
100  
60  
?

11 Days.  
 Unpsum repair  
 After repair photos.  
 Que Qi ap - 82880282  
 18/9/17

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

INDIA INTERNATIONAL INSURANCE PL

Ref : CS/TP17017995/Ggbn2

64 CECIL STREET  
#05-02 IOB BUILDING SINGAPORE 049711  
ATTN: JACKSON YEO

Date : 30-11-2017



Code : III2

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	PUBLIC LIABILITY	Veh. Inspected	SHD 3853U
Policy No.	1793533/LST	Coverage (\$)	0.00
Claim No.	AC170367	Excess (\$)	0.00
Assign From	LEE SIANG TECK	Assign Date	18/09/2017

### 2. Vehicle Particulars & Condition

Make & Model	HYUNDAI SONATA	c.c	1991
Engine No.	HIDDEN	Year of Reg.	2010
Chassis No.	KMHET41VMAA793711	Colour	BLUE
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R16	WEST LAKE	6 mm
L/H Front Tyre	215/60 R16	WEST LAKE	6 mm
R/H Rear Tyre	215/60 R16	WEST LAKE	6 mm
L/H Rear Tyre	215/60 R16	WEST LAKE	6 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT, REAR PORTION AND ROOFTOP.  
DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	11/09/2017	Inspection Date	18/09/2017
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 600 SIN MING AVENUE CITYCAB BUILDING SINGAPORE 575733		

### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **11 Working Days**



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 3853U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	BONNET	BUCKLED	1,151.80	1,151.80
1	FRONT BUMPER COVER	TO REPAIR SEE LABOUR	538.80	-
2	FRONT BUMPER GRILLE (LH/RH) @\$17.60	NOT NECESSARY	35.20	-
1	HEADLAMP SUPPORT PANEL ASSY	* CHECK	1,023.00	-
2	HEADLAMP (LH/RH) @\$797.90	* CHECK	1,595.80	-
1	FRONT FENDER (RH)	TO REPAIR SEE LABOUR	593.00	-
2	DOOR CENTRE PILLAR OUTER (LH/RH) @\$1711.70	TO REPAIR SEE LABOUR	3,423.40	-
1	FRONT WINDSCREEN GLASS	CRACKED	1,015.00	1,015.00
1	FRONT WINDSCREEN MOULDING	NECESSARY	60.00	60.00
2	FRONT WINDSCREEN PILLAR OUTER (LH/RH) @\$1766.20	TO REPAIR SEE LABOUR	3,532.40	-
1	ROOF PANEL	DISTORTED	1,194.90	1,194.90
1	DASHBOARD COMPLETE	* CHECK	2,576.00	-
1	BOOT LID	BUCKLED	1,349.50	1,349.50
1	REAR WINDSCREEN GLASS	NOT NECESSARY	639.00	-
1	REAR WINDSCREEN MOULDING	NOT NECESSARY	60.00	-
	LESS 20% DISCOUNT		-3,757.56	-954.24
			15,030.24	3,816.96
<b><u>SPECIAL NETT ITEMS</u></b>				
1	FRONT WINDSCREEN SEALANT (SN)	NECESSARY	46.00	46.00
1	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	46.00	-
			92.00	46.00
<b><u>LABOUR</u></b>				
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF FRONT BUMPER COVER, FRONT FENDER (RH), DOOR CENTRE PILLAR OUTER (LH/RH) AND FRONT WINDSCREEN PILLAR OUTER (LH/RH).		2,500.00	1,400.00
	SPRAY PAINTING CHARGE.		1,600.00	1,400.00
	WIRING CHARGE.		50.00	30.00
	TUFF KOTE.		100.00	80.00
	REMOVE/REFIX CUSHION & UPHOLSTERY REAR.		150.00	60.00
	REMOVE/REFIX REAR WINDSCREEN GLASS.	NOT NECESSARY	120.00	-

Report Ref No. CS/TP17017995/Ggbn2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE/REFIX FRONT WINDSCREEN GLASS.	* CHECK	120.00	100.00
	REMOVE/REFIX CUSHION & UPHOLSTERY FRONT.		90.00	60.00
	REMOVE/REFIX ROOF TOP TAXI DIGITAL SIGN.		150.00	-
			4,880.00	3,130.00
<b>GRAND TOTAL</b>			<b>20,002.24</b>	<b>6,992.96</b>
<b>RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS S\$4,305.84 NETT)</b>				<b>6,992.96</b>

Report Ref No. CS/TP17017995/Ggbn2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.**

**No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.**