

ASS. REC. BY:

REF: CS/MSG17018334 / Aqbn2

Special Instruction:

SURVEYOR

Meimen

Adrian

ASSIGNMENT (Office)

From (Person):

Christine Wong

of

MSG

Date/Time

25/9/17 9:45am

Estimated Cost

Bill to

OB / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJH 2692D

Insured:

SLL875L

at Workshop m/s

Preeise Auto

Tel:

67457367

of No. 1 Kaki Bukit Ave 6, # 02-34/36 2417883

Policy No

80425909 QMX

Claim No:

530556

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A 21/09/2017

CA / REV / REP. / REV 24 HRS

'wp'

H.O.D. Endorsement

Date/Time

25/9/17 9:49am

Person Contacted

Yan Hong

Vehicle ☒ IN ☐ OUT

Date/Time

Action/Instruction

(✓) Estimate

SJH 2692D-X

SLL 875L

26/9/17 @ 11:20am Informed Christine Wong, we are pending estimate from repairer.

26/9/17 @ 2:48pm Revised to Christine Wong via Meimen.

REF: MS1G

ASSIGNMENT

From: _____ Date: 25/9/17

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SJH 2692 Dat Workshop m/s: Precise Autoof No 1 Kaki Bukit Ave 6 # 02-34/36, 417883

Insured: _____

Policy No: _____


Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal or Market Value: _____

IDAC Accident Rpt. Consistent? : Yes or No

GIA / PR Seen. Consistent? : Yes or No

Est Repairs: 10 days Res: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS wp

Date: _____ Person Contacted: _____

Vehicle IN / OUT

Date / Time Action / Instruction

TP MS1G

MV: 18K

PV: 10K

Nett: 8K

RECEIVED 03 DEC

Veh No: SJH 2692 D Yr Regn: 2008, JulyType: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Stream cc 1799Colour: Blue A/C: _____ Insured / Std / NI / NASp. Reading: 161027 T. Radio: Insured / Std / NI / NA

Eng. No: _____

C. No: RN61073569Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size F: 215/50R17R: 215/50R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Westlake

Front

Rear

R. Bal: 06 mmR. Bal: 06 mmL. Bal: 06 mmL. Bal: 06 mm

D.O.A.

D.O.I. 25/09/17

Survey held at

PreciseDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time File Pass to?

06/12/17 Turner

Date/Time File Return to?

☐ : Preli. Report
☐ : Final Report
Days Of Repair: 10Resurvey No. of Trip: 1
Add Fee: ☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech. Invs (\$)
☐ Weekend (\$)
☐ Others (\$)
☐ Others (\$)

Survey Fee

Transportation

) S + RS S

) Photos

) Others

TOTAL

300

10

310

Report Format: MPR-TPLump Sum / I.B.A. (\$) 7500



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG17018334/Aqb		
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 25-09-2017		
		Code : MSG		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLL 875L	Veh. Inspected	SJH 2692D	
Policy No.	80425909QMX	Coverage (\$)	0.00	
Claim No.	53056	Excess (\$)	0.00	
Assign From	MERIMEN (CHRISTINA WONG)	Assign Date	25/09/2017	
2. Vehicle Particulars & Condition				
Make & Model	c.c		0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	21/09/2017	Inspection Date	25/09/2017	
Survey held at	PRECISE AUTO SERVICE NO.1 KAKI BUKIT AVE 6 #02-34/36 SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Survey Department Check List (Case Handler)

Reference No.: *Cy/MSA/2018334/Agb*
 Policy Type: OD / TP / TP RES / TL / EVA

SJH 2692D

Case Handler

Typist

Admin (*Cath*): Case handler to make sure all Information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

- C Reference No.
- C Customer Code
- N Assign From
- C Assign Date
- C Veh No (Inspected)
- C Veh No (Insured)
- C D.O.A
- C Policy No
- C Claim No
- C Insurance Authorisation (CA /REV/REP)
- C Report Type
- C Weekend Charges
- N Survey held at/Repairer
- C Excess

Y-Date	N-Date	Y-Date	N-Date
☒	☒		
☒	☒		
☒	☒		
☒	☒		
☒	☒		
☒	☒		
☒	☒		
☒	☒		
☒	☒		
☒	☒		
☒	☒		
☒	☒		
☒	☒		

Surveyor (*Adrian*): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

- C Vehicle No
- C Regn Month/Year
- N Vehicle Type
- N Make & Model
- C Engine Capacity. (C.C)
- N Colour
- C Odometer. (Sp.Reading)
- C Chassis No
- N General Condition
- N Steering
- N Brake
- N Modification (Modi)
- C Tyre Size
- N Tyre Make
- C Tyre Balance
- C Date of Inspection
- N Survey held
- N Des.of Damages

☒			
☒			
☒			
☒			
☒			
☒			
☒			
☒			
☒			
☒			
☒			
☒			
☒			
☒			
☒			
☒			
☒			

(2) System - (Views/Merimen)

- C Damaged Vehicle Photographs Uploaded

☒		
-------------------------------------	--	--

(3) Workshop Estimate/Assignment Form

- N ALL Parts condition
- C Market Value for OD cases
- C Estimate Repair Cost for PRI (RSI, TMI, MSIG)
- C Days of repair
- C Finalised Amount
- C Re-inspection Cases to Finalize within 5 Days

☒		
☒		

(4) System - (Views/Merimen)

- C Resurvey photo Uploaded

☒		
-------------------------------------	--	--

Check By:

Case Handler

Date

*C: Critical *N: Non-Critical

21/05/2014

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	21 Sep 2017		25 Sep 2017 09:45 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	HUANG WENWEN, ID: S8529915H		
Main Claimant:	ONG YONG THIAM		
Vehicle Reg. No.:	SJH2692D	Date of Loss:	21/09/2017 06:00 - :59
Claim Type:	TP / 530556	Policy/Cover Note No.:	80425909QMX (Comprehensive) Coverage: 15/02/2017 - 14/02/2018
Vehicle Reg. No. (Insured):	SLL875L	Policy No. (Claimant):	
		Excess:	
Repairer:	Precise Auto Service (HQ) No 1 Kaki Bukit Ave 6, #02-34/36, 417883 Kaki Bukit - Tel: 67457367		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 26/09/2017]		
Adj Asg. Remarks:	Law firm appoint Mr Adrian Ling to survey the car		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Christina Wong

Date: 06 Dec 2017

Preliminary Advice

Insured Vehicle No	: SLL875L	Accident Date	: 21/09/2017
TP Vehicle No	: SJH2692D	Assignment Date	: 25/09/2017
Make	: HONDA STREAM	Est. Duration of Repair	: 10.00
Date of Inspection	: 25/09/2017		
Inspection At	: PRECISE AUTO SERVICE (HQ) NO 1 KAKI BUKIT AVE 6, #02-34/36 SINGAPORE 417883		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	14,859.04
Revised Amount	:S\$	9,361.52
Check Items (Estimated)	:S\$	0.00
Total	:S\$	9,361.52
Lump Sum Repair	:S\$	7,500.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

Shiau Chan (LKKAUTO)

From: Do-Not-Reply <do-not-reply@merimen.com>
Sent: Tuesday, 26 September, 2017 11:20 AM
To: do-not-reply@merimen.com
Cc: SUR
Subject: VEHICLE SJH 2692D (YOUR REF: 530556)

This mail is associated with :

***SJH2692D (530556)**

[SLL875L]

TP

ONG YONG THIAM

Sep 21 2017 6:00AM

[HUANG WENWEN]

Precise Auto Service

Dear Christina,

Please be informed that we have inspected the vehicle SJH 2692D on 25/09/2017.

We are pending for estimate from repairer.

Thanks & Regards,

Shiau Chan (Ms)
LKK Auto Consultants Pte Ltd
Tel: 6256 3561
Fax: 6256 4315

[This mail is sent from a mailer account - do not reply to this email address]

Sent by : SHIAU CHAN (LKK Auto Consultants Pte Ltd)

**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC
Owner ID: 0185Z

Vehicle Details

Vehicle No.: SJH2692D
Vehicle to be Exported: Yes
Intended De-registration Date: 25 Sep 2017
Vehicle Make: HONDA
Vehicle Model: STREAM 1.8X A
Primary Colour: Black
Manufacturing Year: 2008
Engine No.: R18A1781255
Chassis No.: RN61073569
Maximum Power Output: 103.0 kW (138 bhp)
Open Market Value: \$17,199.00
Original Registration Date: 30 Jul 2008
First Registration Date: 30 Jul 2008
Transfer Count: 2
Actual ARF Paid: \$17,199.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 29 Jul 2018
PARF Rebate Amount: \$8,599.00

Intended COE Rebate Details

COE Expiry Date: 29 Jul 2018
COE Category: B - Car (1601cc & above)
COE Period(Years): 10
QP Paid: \$14,235.00
COE Rebate Amount: \$1,201.00
Total Rebate Amount: \$9,800.00

The information contained herein is correct as at 25 Sep 2017



Honda Stream 1.8A X CNG **\$15,288** **\$10,000 /yr** **15-Jul-2008** **1,799 cc** **-** **MPV** **Available**

Trade In All Available, Interested Please Call For Viewing, Viewing By Appointment Only.

Boeki Auto & Marine

Posted: 24-Sep-2017 Tags: 2008 Honda Stream, 2008 Honda Stream, Honda Stream, Honda Stream, Honda, Stream, Stream, Used Honda

[Details](#)



Honda Stream 1.8A **\$18,888** **\$10,790 /yr** **26-Jul-2008** **1,799 cc** **135,526 km** **MPV** **Available**

With \$0 Drive Away Available Upon Approval, In House Loan Available. Do Swing By For A Test Drive.

Posted: 25-Sep-2017 Tags: 2008 Honda Stream, 2008 Honda Stream, Honda Stream, Honda Stream, Honda, Stream, Stream, Used Honda

[Details](#)



Honda Stream 1.8A **\$20,800** **\$12,270 /yr** **08-Aug-2008** **1,799 cc** **117,900 km** **MPV** **Available**

Elegant Grey MPV, Agent Unit, One Owner Only, Low Mileage Done, Low Maintenance Cost, Very Well Maintained, Drive Away With Minimum Down Payment, Flexible In-House Loan Packages Available.

Prime Motor & Leasing

Posted: 19-Sep-2017 Tags: 2008 Honda Stream, 2008 Honda Stream, Honda Stream, Honda Stream, Honda, Stream, Stream, Used Honda

[Details](#)



Honda Stream 1.8A X **\$17,000** **\$12,670 /yr** **08-Aug-2008** **1,799 cc** **-** **MPV** **A**

Well Maintained By One Owner. Pristine Condition, Great For Family Usage. Best Quality In The Market, Call Now For More Details!

Posted: 24-Aug-2017 Tags: 2008 Honda Stream, 2008 Honda Stream, Honda Stream, Honda Stream, Honda, Stream, Stream, Used Honda

[Details](#)



Honda Stream 1.8A Style Edition (OPC) **\$17,800** **\$12,120 /yr** **18-Aug-2008** **1,799 cc** **-** **MPV** **A**

Ideal For Conversion! Well Maintained! Extended Warranty Available! A Stylish MPV Comes Standard With Roomy, Practical, Versatile Interior For Your Usage And Comfort. Buy It From Us With A Peace Of Mi...

Dickson Automobile

Posted: 25-Jul-2017 Tags: 2008 Honda Stream, 2008 Honda Stream, Honda Stream, Honda Stream, Honda, Stream, Stream, Used Honda

[Details](#)



Honda Stream 1.8A **\$19,888** **\$10,640 /yr** **03-Sep-2008** **1,799 cc** **118,000 km** **MPV** **Available**

0% Downpayment Available! A Very Reliable And Sporty MPV! Well Maintained By Previous Owner! High Loan And Flexible Financing Packages!

Posted: 16-Aug-2017 Tags: 2008 Honda Stream, 2008 Honda Stream, Honda Stream, Honda Stream, Honda, Stream, Stream, Used Honda

[Details](#)



Honda Stream 1.8A X **\$22,800** **\$14,000 /yr** **19-Sep-2008** **1,799 cc** **120,000 km** **MPV** **Available**

Engine Is Excellent Conditions. PARF \$10,000, Body \$1000, Good To Renew. All Parts Replaced. Drive With No Worries. Pioneer DVD And DVD Player (Movies).

Carro

Posted: 24-Sep-2017 Tags: 2008 Honda Stream, 2008 Honda Stream, Honda Stream, Honda Stream, Honda, Stream, Stream, Used Honda

[Details](#)



Honda Stream 1.8A X **\$20,500** **\$12,120 /yr** **25-Sep-2008** **1,799 cc** **130,000 km** **MPV** **Available**

Best MPV In Town Now. Drives Smoothly And Beautifully. Powerful And Responsive Engine. Beautiful Interior And Exterior. Must View Model. Well Taken Care By Owner. Regularly Serviced And Maintained. 10...

Posted: 01-Aug-2017 Tags: 2008 Honda Stream, 2008 Honda Stream, Honda Stream, Honda Stream, Honda, Stream, Stream, Used Honda

[Details](#)



Honda Stream 1.8A **\$20,800** **\$10,560 /yr** **30-Sep-2008** **1,799 cc** **122,000 km** **MPV** **Available**

In House Loan And Trade In Available. Agent Model With 4x Disc Brakes And High OMV. Rare 1 Owner Stream. Low Mileage Of Only 13.6k Km Done Per Year! Great For COE Renewal And Short Term Drive. Spaciou...

Posted: 25-Aug-2017 Tags: 2008 Honda Stream, 2008 Honda Stream, Honda Stream, Honda Stream, Honda, Stream, Stream, Used Honda

[Details](#)



Honda Stream 1.8A X **\$24,800** **\$13,350 /yr** **03-Oct-2008** **1,799 cc** **-** **MPV** **Available**

1.99% Interest!, High Trade In, A Stylish MPV Comes With Spacious Interior For Your Comfort. Buy It From Us With A Peace Of Mind, A Company Accredited With Outstanding Awards, Professional After Sales...

Dickson Automobile

Posted: 08-Sep-2017 Tags: 2008 Honda Stream, 2008 Honda Stream, Honda Stream, Honda Stream, Honda, Stream, Stream, Used Honda

[Details](#)



Honda Stream 1.8A CNG **\$17,888** **\$10,510 /yr** **10-Oct-2008** **1,799 cc** **121,000 km** **MPV** **Available**

1 Owner Only, Regularly Serviced/Well Maintained By Previous Owner, Pristine Condition, Clean Interior, Accident Free, Viewing Kindly Call For Appointment.

Posted: 18-Sep-2017 Tags: 2008 Honda Stream, 2008 Honda Stream, Honda Stream, Honda Stream, Honda, Stream, Stream, Used Honda

[Details](#)



Honda Stream 1.8A X **\$19,800** **\$10,730 /yr** **16-Oct-2008** **1,799 cc** **-** **MPV** **Available**

\$0 Down Payment Available! Balloon Scheme Available! We Are sgCarMart Premium Dealer! Buy With No Worries! No Hidden Costs! Car In Original Condition! Low Mileage! Accident Free! In House Loan Or Bank...

88 Motor Trading

[Details](#)

PRECISE AUTO SERVICE

NO. 1 KAKI BUKIT AVE 6 #02-34/36 SINGAPORE 417883

TEL : 67457367 FAX : 68413390

CO. REG. NO. : 35766600C

GST REG. NO. : 35766600C

25-10-17

Date Of Accident : 21-09-17

OUR REF : SJH 2692D/T/17

ONG YONG THIAM

BLK 491 JURONG WEST AVE 1

#05-157

SINGAPORE 640491

Adrian

Date in/out 21/09/17 to 04/10/17

TP MS/G.

Xiao Chen

ESTIMATE BILL ON VEH. NO. : SJH 2692D

MODEL : HONDA STREAM

CHASSIS NO. : RN61073569

LIST ITEM

Tail Gate	Distorted		903.20 ✓
Tail Gate Badge	New		25.80 ✓
Tail Gate Lock	Repld		109.40 ✓
Tail Gate Lock Striker	Best		26.70 ✓
Tail Gate Weather Stripe	Cut		121.60 ✓
Tail Gate Stopper	New	2pcs @ 7.00	14.00 ✓
Tail Gate Absorber	New	2pcs @ 116.70	233.40 ✓
Tail Gate Outer Garnish	Cracked		162.80 ✓
Tail Gate Outer Garnish Clips	New	4pcs @ 4.00	16.00 ✓
Tail Gate Emblem "Stream"	New		31.60 ✓
Tail Gate Inner Trim Board	Repld		141.00 ✓
Tail Gate Inner Trim Board Clips	New	8pcs @ 4.50	36.00 ✓
Tail Gate Inner Handle Holder	New		25.00 ✓
Rear Windscreen Glass Moulding	New		45.00 ✓
Rear Windscreen Glass Inner Seal	New		28.00 ✓
Rear Windscreen Glass Clips	New	14pcs @ 5.00	70.00 ✓
Tail Lamp Assy	Cracked	2pcs @ 352.50	705.00 ✓

Tail Lamp Base Panel	Ryis	2pcs @ 145.90	291.80	✓
Tail Lamp Clips	mm	6pcs @ 3.50	21.00	✓
Rear Bumper Fascia	Debonded		600.20	✓
Rear Bumper Side Retainer	mm	2pcs @ 19.40	38.80	✓
Rear Bumper Side Attachment	mm		44.00	✓
Rear Bumper Clips	mm	10pcs @ 3.90	39.00	✓
Rear End Panel (Outer)	2 Dented		306.70	✓
Rear End Panel (Inner)			95.00	✓
Rear End Side Panel	Not mm	2pcs @ 95.00	190.00	✓
Rear End Inner Bracket	Bent	2pcs @ 65.00	130.00	✓
Rear End Side Extension Panel	Not mm	2pcs @ 24.30	48.60	✓
Rear End Panel Top Trim	Debond		116.70	✓
Rear End Panel Top Trim Clips	mm	4pcs @ 4.50	18.00	✓
Rear Number Plate Lamp	Not mm	2pcs @ 32.80	65.60	✓
Rear Floor Panel	Distorted		1,045.50	✓
Rear Floor Panel Carpet	Not mm		841.30	✓
Rear Floor Panel Board	Not mm	2pcs @ 130.00	260.00	✓
Rear Floor Panel Insulator Cloth	mm		55.00	✓
Rear Sub Chassis Frame Member	Ryis	2pcs @ 539.00	1,078.00	✓
Rear Floor Panel Board Under Garnish (Rear)	Debonded		126.50	✓
Rear Fender Inner Trim Board	Debonded	2pcs @ 197.00	394.00	✓
Rear Fender Inner Trim Board Clips	mm	16pcs @ 4.80	76.80	✓
Spare Tyre Bracket	Bent		121.60	✓
Spare Tyre Adjusting Screw	3 Bent		7.00	✓
Spare Tyre Adjusting Screw Hook			18.00	✓
Exhaust Silencer	Bent		620.00	✓
Exhaust Silencer Hook	Not mm	3pcs @ 22.00	66.00	✓

Exhaust Silencer Chorme Pipe *best*

620190 S.N. 80

4961.52

80(53)
126.70

9,536.30

20% Less Discount :

1,907.26

7,629.04

SPECIAL NETT ITEM

Rear Windscreen Glass Sealant *new*

60.00 ✓

Rear Bumper Lower Spoiler (Acc) *Disturbed*

900.00 *780*

Reverse Sensor With Control Unit *argd*

380.00 *20*

Reverse Camera (Acc) *Use New*

650.00 ✗

LABOUR CHARGE

Towing

80.00 ✗

To Check & Reconnect Snap Wiring

120.00 *30*

To Tuff Coat Affected Areas

220.00 *80*

To Remove & Refix Interior Upholstery

180.00 ✓

To Remove & Refix Reverse Sensor & Reverse Camera

280.00 *100*

To Remove & Refix Rear Windscreen Glass

180.00 *120*

To Remove & Refix Exhaust Silencer & Straighten Exhaust Center Pipe

200.00 *100*

To Respray Affected Areas

1,800.00 *1,000*

To Adjust Chassis Alignment On Car O Liner

380.00 *350*

To Renew Damaged Parts, Straighten & Repair Rear Chassis Member,
Rear Fender & Aligned All Parts

1,800.00 *1,300*

TOTAL :

14,859.04

GST 7% :

1,040.13

AMOUNT DUE :

15,899.17

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total 9361.52

L/S: 7.5K

7.5K

10 Pags

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG17018334/AQBN2

Date: 08/12/2017

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	80425909QMX
Claimant Vehicle No :	SJH2692D	Insured Vehicle No :	SLL875L
Date of Loss:	21/09/2017	Nature of Claim:	TP
		Claim No:	530556

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJH2692D	Engine No:	R18A1781255
Make & Model:	HONDA STREAM, 1.8 (A)	Chassis No:	RN61073569
Reg. Date:	30/07/2008 (Man. Year: 2008)	Odometer:	161027 km
Colour:	Black		
Engine Capacity:	1799 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/50 R17	Rear Tyre Size:	215/50 R17
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	9,619.04	6,101.52	3,517.52	36.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,240.00	3,260.00	1,980.00	37.79
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,859.04	9,361.52	5,497.52	37.00
Approved Total (Overridden) (S\$)		7,500.00		
(S\$)	14,859.04	7,500.00	7,359.04	49.53
+ GST 7.00/7.00% (S\$)	1,040.13	525.00	515.13	49.53
Nett Amount (S\$)	15,899.17	8,025.00	7,874.17	49.53

INSPECTION

Date of Assignment:	25/09/2017	
Date Inspected:	25/09/2017	Inspected At: Precise Auto Service (HQ) No 1 Kaki Bukit Ave 6, #02-34/36 Singapore 417883
Estimated Period of Repair:	10.0 days	

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 07 Dec 2017)
Parts:	M1-MPV	HONDA STREAM 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJH2692D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL GATE	Distorted	903.20 FL	*903.20 FL
2	1		*TAIL GATE BADGE	Necessary	25.80 FL	*25.80 FL
3	1		*TAIL GATE LOCK	Damaged	109.40 FL	*109.40 FL
4	1		*TAIL GATE LOCK STRIKER	Bent	26.70 FL	*26.70 FL
5	1		*TAIL GATE WEATHER STRIP	Cut	121.60 FL	*121.60 FL
6	2		*TAIL GATE STOPPER	Not Necessary	14.00 FL	-
7	2		*TAIL GATE ABSORBER	Not Necessary	233.40 FL	*- FL
8	1		*TAIL GATE OUTER GARNISH	Cracked	162.80 FL	*162.80 FL
9	4		*TAIL GATE OUTER GARNISH CLIPS	Necessary	16.00 FL	*16.00 FL
10	1		*TAIL GATE EMBLEM STREAM	Necessary	31.60 FL	*31.60 FL
11	1		*TAIL GATE INNER TRIM BOARD	Deformed	141.00 FL	*141.00 FL
12	8		*TAIL GATE INNER TRIM BOARD CLIPS	Necessary	36.00 FL	*36.00 FL
13	1		*TAIL GATE INNER HANDLE HOLDER	Not Necessary	25.00 FL	*- FL
14	1		*REAR WINDSCREEN GLASS MOULDING	Necessary	45.00 FL	*45.00 FL
15	1		*REAR WINDSCREEN GLASS INNER SEAL	Necessary	28.00 FL	*28.00 FL
16	1		*REAR WINDSCREEN GLASS CLIPS (14pcs)	Necessary	70.00 FL	*20.00 FL
17	2		*TAIL LAMP ASSY	Cracked	705.00 FL	*705.00 FL
18	2		*TAIL LAMP BASE PANEL	Repair	291.80 FL	*- FL
19	6		*TAIL LAMP CLIPS	Necessary	21.00 FL	*21.00 FL
20	1		*REAR BUMPER FASCIA	Deformed	600.20 FL	*600.20 FL
21	2		*REAR BUMPER SIDE RETAINER	Necessary	38.80 FL	*38.80 FL
22	1		*REAR BUMPER SIDE ATTACHMENT	Not Necessary	44.00 FL	*- FL
23	10		*REAR BUMPER CLIPS	Necessary	39.00 FL	*39.00 FL
24	1		*REAR END PANEL (OUTER)	Dented	306.70 FL	*306.70 FL
25	1		*REAR END PANEL (INNER)	Dented	95.00 FL	*95.00 FL
26	2		*REAR END SIDE PANEL	Not Necessary	190.00 FL	*- FL
27	2		*REAR END INNER BRACKET	Bent	130.00 FL	*130.00 FL
28	2		*REAR END SIDE EXTENSION PANEL	Not Necessary	48.60 FL	*- FL
29	1		*REAR END PANEL TOP TRIM	Deformed	116.70 FL	*116.70 FL
30	4		*REAR END PANEL TOP TRIM CLIPS	Necessary	18.00 FL	*18.00 FL
31	2		*REAR NUMBER PLATE LAMP	Not Necessary	65.60 FL	*- FL
32	1		*REAR FLOOR PANEL	Distorted	1,045.50 FL	*1,045.50 FL
33	1		*REAR FLOOR PANEL CARPET	Not Necessary	841.30 FL	*- FL
34	2		*REAR FLOOR PANEL BOARD	Not Necessary	260.00 FL	*- FL
35	1		*REAR FLOOR PANEL INSULATOR CLOTH	Necessary	55.00 FL	*55.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	2		*REAR SUB CHASSIS FRAME MEMBER	Repair	1,078.00 FL	*- FL
37	1		*REAR FLOOR PANEL BOARD UNDER GARNISH (REAR)	Deformed	126.50 FL	*126.50 FL
38	2		*REAR FENDER INNER TRIM BOARD	Deformed	394.00 FL	*394.00 FL
39	16		*REAR FENDER INNER TRIM BOARD CLIPS	Necessary	76.80 FL	*76.80 FL
40	1		*SPARE TYRE BRACKET	Bent	121.60 FL	*121.60 FL
41	1		*SPARE TYRE ADJUSTING SCREW	Bent	7.00 FL	*7.00 FL
42	1		*SPARE TYRE ADJUSTING SCREW HOOK	Bent	18.00 FL	*18.00 FL
43	1		*EXHAUST SILENCER	Bent	620.00 FL	*620.00 FL
44	3		*EXHAUST SILENCER HOOK	Not Necessary	66.00 FL	*- FL
45	1		*EXHAUST SILENCER CHROME PIPE	Bent	101.36 FS	*80.00 FS
46	1		*REAR WINDSCREEN GLASS SEALANT	Necessary	60.00 FS	*60.00 FS
47	1		*REAR BUMPER LOWER SPOILER (ACC)	Distorted	900.00 FS	*780.00 FS
48	1		*REVERSE SENSOR WITH CONTROL UNIT	Damaged	380.00 FS	*220.00 FS
49	1		*REVERSE CAMERA (ACC)	Not Necessary	650.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,500.96	7,341.90
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,881.92	1,240.38
Total Parts (\$\$)	9,619.04	6,101.52

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING.	New	80.00	0.00
2	TO CHECK & RECONNECT SNAP WIRING.	New	120.00	30.00
3	TO TUFF COAT AFFECTED AREAS.	New	220.00	80.00
4	TO REMOVE & REFIX INTERIOR UPHOLSTERY.	New	180.00	180.00
5	TO REMOVE & REFIX REVERSE SENSOR & REVERSE CAMERA.	New	280.00	100.00
6	TO REMOVE & REFIX REAR WINDSCREEN GLASS.	New	180.00	120.00
7	TO REMOVE & REFIX EXHAUST SILENCER & STRAIGHTEN EXHAUST CENTER PIPE.	New	200.00	100.00
8	TO RESPRAY AFFECTED AREAS.	New	1,800.00	1,000.00
9	TO ADJUST CHASSIS ALIGNMENT ON CAR O LINER.	New	380.00	350.00
10	TO RENEW DAMAGED PARTS, STRAIGHTEN & REPAIR REAR CHASSIS MEMBER, REAR FENDER & ALIGNED ALL PARTS.	New	1,800.00	1,300.00
Gross Labour Cost (S\$)			5,240.00	3,260.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >