

ASS. REC. BY:

REF CS/FCI/7018344/Tirbnz

Special Instruction:

Surveyor

Tawfik

ASSIGNMENT (Office)

cus

From (Person) Eilen Lee

of FCI

Date/Time 23/9/17 3:47pm

Estimated Cost

Bill to

OD / TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLS 417 P

Insured: SHC 3498 S

at Workshop m/s

SHU Fat + Auto

Tel: 62730119

of Blk 1009 # 01-90 Bukitmerah Lane 3

Policy No:

Claim No: D1700 9006 MFS #

Sum Insured

Excess:

Make of Veh:

(Client's Record)

D.O.A. 20/09/17

CA / REV / REP. / REV 24 HRS

'wp'

27.09.2017 @ 4pm - 5pm

H.O.D. Endorsement

Date/Time: 25/9/17 9:07am

Person Contacted: Pat

Vehicle IN (OUT)

Date/Time: Action/Instruction (✓) Estimate

SLS 417 P - X

SHC 3498 S - X

Sent pol to Eilen

Confirm with Pat \$3783.08, 5 days

Red - \$2675.68, 42%

Invoice
Closed

Surveyor: Tan Jia

REF: TC1

ASSIGNMENT

From: _____ Date: 27092017
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SLS 417P
 at Workshop m/s: Shu Fatt Auto
 of Blok 1009 Bukit Merah Lane 3 #01-90
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

4pm - 5pm

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS WPI

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLS 417P Yr Regn: 2017 / Sep
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Honda Vezel Hybrid C.C. 1496
 Colour: Grey A/C: Insured / Std / NI / NA
 Sp. Reading: 289 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: R4 31253187
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 215 / 60 R16
 R: 2

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Dunlop

Front 7 mm Rear 7 mm
 R/Bal. 7 mm R/Bal. 7 mm
 L/Bal. 7 mm L/Bal. 7 mm
 D.O.A. _____ D.O.I. 27/9/17

Survey held at Shu Fatt
 Des. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time . Action / Instruction

RECEIVED 6 8 2017

Date/Time, File Pass to?

1) Sign
 Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I. (\$) 3783.08

Days Of Repair: 5

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS, \$

Photos

Others

TOTAL

140
50
50
52
292



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI17018344/T1rb

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 25-09-2017



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 3498S	Veh. Inspected	SLS 417P
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	CWS (EILEEN LEE)	Assign Date	25/09/2017

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	20/09/2017	Inspection Date	
Survey held at	SHU FATT AUTO WORKS BLK 1009, BUKIT MERAH LANE 3 #01-90 SINGAPORE 159723		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C
GST Reg. No. M2-0001676-9

MOTOR SURVEY ASSIGNMENT

Date	21-09-2017	Our Ref No.	D17009006MFSH
Accident Date	20-09-2017	Claim Type.	Third Party
Insured Vehicle	SHC3498S	Third Party Vehicle.	SLS417P
Survey Location	BLK 1009 #01-90 BUKIT MERAH LANE 3		
Contact Person.	CONNIE		
Contact No.	62730119/ 0	Fax No.	62707065
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:		
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD		
Contact Person	NA	Fax No.	68416315
Contact Number.	NA		

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	SHU FATT AUTO WORKS	Attention.	NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No.	NA
Officer Incharge	EILEEN LEE		

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/228278)



PRI Documents



Close



PRI Header Details

Claim No	D17009006MFSH	Policy No	D-15072701MFSH	Claimant S.No & Name	1 & SHU FATT
Workshop Name	SHU FATT AUTO WORKS (Contact Person : CONNIE)	Survey Location & Contact Details	BLK 1009 #01-90 BUKIT MERAH LANE 3 Mobile: 0 , Phone: 62730119 , Fax: 62707065 EmailId: SHUFATT@SINGNET.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHC3498S	TP Vehicle No	SLS417P
PRI Recieved Date	22-09-2017 07:57:50 PM	Surveyor Appointed Date	23-09-2017 03:48:47 PM	Surveyor Accept Date	25-09-2017 1

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	25-09-2017	Upload Survey Report *:	Choose File
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select Year
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D17009006MFSH

Our Ref: CS/FCI17018344/T1rb

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLS 417P.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 27/9/2017 at the premises of M/s SHU FATT PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$ 6,478.76 .
Revised Estimate Amount	: S\$ 3,783.08 .
"Check" Items Amount	: S\$ - .
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

Description of Damage:

The vehicle sustained damages at the rear portion.



Yours faithfully

TAUFIKH
Automotive Assessor

Janice Lee (LKKAuto)

From: Janice Lee (LKKAuto)
Sent: Friday, December 08, 2017 4:05 PM
To: EILEENLEE@FIRST-INSURANCE.COM.SG
Subject: RE: SURVEY ASSESSMENT - D17009006MFSH/1
Attachments: SLS 417P.pdf

Dear Eileen,

Enclosed preliminary revised for **SLS 417P**

Thank you.

Best Regards,

Janice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Monday, September 25, 2017 9:23 AM
To: 'Claim Workflow System' <cwsmotorclaims@first-insurance.com.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: EILEENLEE@FIRST-INSURANCE.COM.SG
Subject: RE: SURVEY ASSESSMENT - D17009006MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@first-insurance.com.sg>]
Sent: Saturday, 23 September, 2017 3:47 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG; EILEENLEE@FIRST-INSURANCE.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D17009006MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



樹發汽車修理廠 SHU FATT AUTO WORKS

BLOCK 1009 BUKIT MERAH LANE 3 #01-90 SINGAPORE 159723 TEL: 6273 0119 FAX: 6270 7065

Our Ref: WSK/jw/SF-quo
21st September 2017
TP- 1st Capital

SLS 417P HONDA VEZEL

		SS
Spare Parts	1 Rear boot.	1200.90 <i>bt</i>
	1 Rear boot logo.	28.00 <i>ne</i>
	1 Rear boot 'Vezel' emblem.	56.20 <i>ne</i>
	1 Rear boot 'Hybrid' emblem.	68.20 <i>ne</i>
	1 Rear boot lock.	185.00 ?
	1 Rear boot rubber.	145.00 ?
	1 Rear bumper.	863.70 <i>de</i>
	1 Set rear bumper clips.	48.60 <i>ne</i>
	2 Rear bumper side retainers. @ \$36/-	72.00 <i>ne</i>
	1 Rt rear bumper reflector.	151.10 ?
	1 Rt rear fender arch garnish.	210.10 ?
	Rear fender arch garnish clips.	36.00 ?
	1 Rear windscreen wiper cover.	20.00 <i>mis</i>
	1 Rear windscreen moulding.	175.00 <i>ne</i>
	1 Rear windscreen inner seal.	42.00 Snet <i>ne</i>
	1 Rear windscreen sealant.	55.00 Snet <i>ne</i>
	1 Set rear reverse sensors.	280.00 Snet 200 <i>ne</i>

		3636.80
		Less 20% 651.96

		4288.76
Labour	To knock, straighten rear inner panel, rear lower panel, rear side panel, rear floor board, rear spare wheel base, left rear fender, rt rear fender, renew rear boot, rear support panel, rear lights, rear bumper and assembly.	850.00 <i>600</i>
	To respray damaged parts.	
	To remove rear garnishes, carpets, upholstery, fender inner covers to facilitate repairs and assembly.	900.00 <i>600</i>
	To remove, replace rear windscreen.	100.00 <i>50</i>
	To remove, replace, transfer rear boot inner lock, outer lock, motor, mouldings, rubbers, garnishes, board, wiring and assembly.	180.00 <i>120</i>
	To reseal joints, reinsulate, anti rust panels and assembly.	120.00 <i>60</i>
		40.00 <i>30</i>

		6478.76

Dunlop 215/60R16
RU3- 1253187
1786

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Tanpin 97495749
WP

27/9/17 @ 1715

5 days

Resurvey before paint
sur @ lkkard.com



樹發汽車修理廠 SHU FATT AUTO WORKS

BLOCK 1009 BUKIT MERAH LANE 3 #01-90 SINGAPORE 159723 TEL: 6273 0119 FAX: 6270 7065

Our Ref: WSK/jw/SF-quo

21st September 2017

TP- 1st Capital

SLS 417 P HONDA VEZEL

		S\$
Spare Parts	1 Rear boot.	1200.90 <i>6hr</i>
	1 Rear boot logo.	28.00 <i>new</i>
	1 Rear boot 'Vezel' emblem.	56.20 <i>new</i>
	1 Rear boot 'Hybrid' emblem.	68.20 <i>new</i>
	1 Rear boot lock.	185.00 <i>7 x nh</i>
	1 Rear boot rubber.	145.00 <i>7 x nh</i>
	1 Rear bumper.	863.70 <i>del</i>
	1 Set rear bumper clips.	48.60 <i>new</i>
	2 Rear bumper side retainers. @ \$36/-	72.00 <i>new</i>
	1 Rt rear bumper reflector.	151.10 <i>7 x nh</i>
	1 Rt rear fender arch garnish.	210.10 <i>7 x nh</i>
	Rear fender arch garnish clips.	36.00 <i>7 x nh</i>
	1 Rear windscreen wiper cover.	20.00 <i>mis</i>
	1 Rear windscreen moulding.	175.00 <i>new</i>
	1 Rear windscreen inner seal.	42.00 <i>Snet new</i>
	1 Rear windscreen sealant.	55.00 <i>Snet new</i>
	1 Set rear reverse sensors.	280.00 <i>Snet 200 new</i>
		3636.80
Less 20%		651.96
		4288.76
Labour	To knock, straighten rear inner panel, rear lower panel, rear side panel, rear floor board, rear spare wheel base, left rear fender, rt rear fender, renew rear boot, rear support panel, rear lights, rear bumper and assembly.	850.00 <i>600.</i>
	To respray damaged parts.	900.00 <i>600.</i>
	To remove rear garnishes, carpets, upholstery, fender inner covers to facilitate repairs and assembly.	100.00 <i>50.</i>
	To remove, replace rear windscreen.	180.00 <i>120.</i>
	To remove, replace, transfer rear boot inner lock, outer lock, motor, mouldings, rubbers, garnishes, board, wiring and assembly.	120.00 <i>60.</i>
	To reseal joints, reinsulate, anti rust panels and assembly.	40.00 <i>30.</i>
		3759.8
		5174.84
		5174.84
		9749.5749

Parts: 2532.60
- 20%: (506.52)
2026.08
Snet: 297.00
2323.08
Labour: 1460.00
3783.08

Dunlop 215/60R16
 RU3- 1253187
 1786

Tanpha 97495749
WP
27/9/17 @ 1715
5 days
Resuming before paint
840 @ khairudin



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI17018344/T1rbn2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 13-12-2017		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 3498S	Veh. Inspected	SLS 417P	
Policy No.	D-15072701MFSH	Coverage (\$)	0.00	
Claim No.	D17009006MFSH	Excess (\$)	0.00	
Assign From	EILEEN LEE	Assign Date	23/09/2017	
2. Vehicle Particulars & Condition				
Make & Model	HONDA VEZEL HYBRID	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	RU31253187	Colour	GREY	
Odometer	2891	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	DUNLOP	7 mm	
L/H Front Tyre	215/60 R16	DUNLOP	7 mm	
R/H Rear Tyre	215/60 R16	DUNLOP	7 mm	
L/H Rear Tyre	215/60 R16	DUNLOP	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	20/09/2017	Inspection Date	27/09/2017	
Survey held at	SHU FATT AUTO WORKS BLK 1009,BUKIT MERAH LANE 3 #01-90 SINGAPORE 159723			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLS 417P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BOOT	BENT	1,200.90	1,200.90
1	REAR BOOT LOGO	NECESSARY	28.00	28.00
1	REAR BOOT "VEZEL" EMBLEM	NECESSARY	56.20	56.20
1	REAR BOOT "HYBRID" EMBLEM	NECESSARY	68.20	68.20
1	REAR BOOT LOCK	NOT NECESSARY	185.00	-
1	REAR BOOT RUBBER	NOT NECESSARY	145.00	-
1	REAR BUMPER	DEFORMED	863.70	863.70
1	SET REAR BUMPER CLIPS	NECESSARY	48.60	48.60
2	REAR BUMPER SIDE RETAINERS @\$36.00	NECESSARY	72.00	72.00
1	RT REAR BUMPER REFLECTOR	NOT NECESSARY	151.10	-
1	RT REAR FENDER ARCH GARNISH	NOT NECESSARY	210.10	-
1	REAR FENDER ARCH GARNISH CLIPS	NOT NECESSARY	36.00	-
1	REAR WINDSCREEN WIPER COVER	MISSING	20.00	20.00
1	REAR WINDSCREEN MOULDING	NECESSARY	175.00	175.00
	LESS 20% DISCOUNT		-651.96	-506.52
			2,607.84	2,026.08
SPECIAL NETT ITEMS				
1	REAR WINDSCREEN INNER SEAL (SN)	NECESSARY	42.00	42.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	55.00	55.00
1	SET REAR REVERSE SENSORS (SN)	NOT WORKING	280.00	200.00
			377.00	297.00
LABOUR				
	TO KNOCK, STRAIGHTEN REAR INNER PANEL, REAR LOWER PANEL, REAR SIDE PANEL, REAR FLOOR BOARD, REAR SPARE WHEEL BASE, LEFT REAR FENDER, RT REAR FENDER, RENEW REAR BOOT, REAR SUPPORT PANEL, REAR LIGHTS, REAR BUMPER AND ASSEMBLY.		850.00	600.00
	TO RESPRAY DAMAGED PARTS.		900.00	600.00
	TO REMOVE REAR GARNISHES, CARPETS, UPHOLSTERY, FENDER INNER COVERS TO FACILITATE REPAIRS AND ASSEMBLY.		100.00	50.00

Report Ref No. CS/FCI17018344/T1rbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE,REPLACE REAR WINDSCREEN.		180.00	120.00
	TO REMOVE,REPLACE,TRANSFER REAR BOOT INNER LOCK,OUTER		120.00	60.00
	LOCK,MOTOR,MOULDINGS,RUBBERS,GARNISHES,BOARD,WIRING AND ASSEMBLY.			
	TO RESEAL JOINTS,REINSULATE ANTI RUST PANELS AND ASSEMBLY.		40.00	30.00
			2,190.00	1,460.00
GRAND TOTAL			5,174.84	3,783.08
RECOMMENDED COST OF REPAIRS				3,783.08

Report Ref No. CS/FCI17018344/T1rbn2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.