

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/LCR17018831/KEA3Q2

Date: 04/03/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	999995170
Claimant		
Vehicle No : SHB7671L	Insured Vehicle No :	SLF5881S
Date of Loss: 24/09/2017	Nature of Claim: TP	Claim No: 6505648840SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHB7671L		
Make & Model:	CHEVROLET EPICA, 2.0 2.0DSL AT ABS D/AB 2WD 4DR TUR (A)	Engine No:	Z20S1451814K
Reg. Date:	29/06/2012 (Man. Year: 2011)	Chassis No:	KL1LA69RJBB077878
Colour:	White/Red	Odometer:	56500 km
Engine Capacity:	1991 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Giti 6 mm	Rear Left Side:	Giti 4 mm
Front Right Side:	Giti 6 mm	Rear Right Side:	Giti 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,432.77	10,413.62	4,019.15	27.85
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,210.00	3,790.00	6,420.00	62.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	24,642.77	14,203.62	10,439.15	42.36
Approved Total (Overridden) (S\$)		11,350.00		
(S\$)	24,642.77	11,350.00	13,292.77	53.94
+ GST 7.00/7.00% (S\$)	1,724.99	794.50	930.49	53.94
Nett Amount (S\$)	26,367.76	12,144.50	14,223.26	53.94
+ Car Rental (22.0 x S\$75.25/day) (S\$)		1,655.50		
(S\$)		13,800.00		
Liabile Amount (50.00%) (S\$)		6,900.00		
+ Doc/Search Fee (S\$)		5.35		
Nett Liability (S\$)		6,905.35		

INSPECTION

Date of Assignment: 29/09/2017

Date Inspected: 29/09/2017 Inspected At:

Trans-cab Auto Services Pte Ltd
No 2 Ang Mo Kio Street 63
Singapore 569111

Estimated Period of Repair: 15.0 days

Adjuster: KENNETH KONG

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Bent	1,202.00 FL	*1,202.00 FL
2	1		*REAR BUMPER BEAM	Bent	239.94 FL	*239.94 FL
3	1		*REAR BUMPER CENTRE ABSORBER	Cracked	260.00 FL	*260.00 FL
4	1		*REAR BUMPER SIDE RETAINER RH	Cracked	68.76 FL	*68.76 FL
5	1		*REAR BUMPER SIDE RETAINER LH	Cracked	68.76 FL	*68.76 FL
6	1		*REAR BUMPER REFLECTORS RH	Broken	119.74 FL	*119.74 FL
7	1		*REAR BUMPER REFLECTORS LH	Broken	119.74 FL	*119.74 FL
8	1		*REAR BUMPER TOW HOOK COVER	Serviceable	93.00 FL	*- FL
9	1		*REAR LUGGAGE FLOOR PANEL	Bent / Buckled	973.00 FL	*973.00 FL
10	1		*REAR LUGGAGE FLOOR PANEL INSULATOR	Necessary	63.50 FL	*63.50 FL
11	1		*REAR LUGGAGE FLOOR PANEL TRIM BOARD	Serviceable	378.00 FL	*- FL
12	1		*REAR END PANEL OUTER	Bent	623.76 FL	*623.76 FL
13	1		*REAR END PANEL INNER	Bent	336.50 FL	*336.50 FL
14	1		*REAR END PANEL INNER TRIM	Distorted	263.84 FL	*263.84 FL
15	1		*BOOTLID	Bent	973.00 FL	*973.00 FL
16	1		*BOOTLID INNER TRIM BOARD	Deformed	400.00 FL	*400.00 FL
17	1		*BOOTLID INNER HANDLE	Serviceable	45.55 FL	*- FL
18	1		*BOOTLID WEATHERSTRIP (50%)	Cut	309.85 FS	*172.14 FS
19	1		*BOOTLID LOCK -TOP	Dented	466.56 FL	*466.56 FL
20	1		*BOOTLID CHEVROLET BADGE	Necessary	120.62 FL	*120.62 FL
21	1		*BOOTLID LOGO	Necessary	138.84 FL	*138.84 FL
22	1		*BOOTLID EPICA LT BADGE	Necessary	119.84 FL	*119.84 FL
23	1		*BOOTLID REFLECTOR CENTRE	Cracked	217.97 FL	*217.97 FL
24	1		*BOOTLID REFLECTOR RH	Cracked	128.40 FL	*128.40 FL
25	1		*BOOTLID REFLECTOR LH	Cracked	128.40 FL	*128.40 FL
26	1		*BOOTLID HINGE RH	Repair	120.00 FL	*- FL
27	1		*BOOTLID HINGE LH	Repair	120.00 FL	*- FL
28	1		*REAR GAS T/GATE SPRING RH	Serviceable	286.90 FL	*- FL
29	1		*REAR GAS T/GATE SPRING LH	Serviceable	286.90 FL	*- FL
30	1		*REAR TAIL LAMP RH	Mtg Cracked	479.30 FL	*479.30 FL
31	1		*REAR TAIL LAMP PANEL RH	Bent	359.00 FL	*359.00 FL
32	1		*REAR TAIL LAMP LH	Broken	479.30 FL	*479.30 FL
33	1		*REAR TAIL LAMP PANEL LH	Bent	359.00 FL	*359.00 FL
34	1		*REAR EXHAUST BOX (MUFFLER A-EXH ,RR)	Repair	1,110.00 FL	*- FL
35	1		*REAR FENDER RH	Repair	1,145.00 FL	*- FL
36	1		*REAR FENDER INNER TRIM RH	Cracked	418.44 FL	*418.44 FL
37	1		*REAR FENDER LH	Buckled	1,145.00 FL	*1,145.00 FL
38	1		*REAR FENDER INNER TRIM LH	Cracked	418.44 FL	*418.44 FL
39	1		*REAR NUMBER PLATE LAMP RH	Serviceable	25.00 FL	*- FL
40	1		*REAR NUMBER PLATE LAMP LH	Serviceable	25.00 FL	*- FL
41	1		*REAR FENDER INNER COWLING RH	Serviceable	76.60 FL	*- FL
42	1		*REAR FENDER INNER COWLING LH	Serviceable	76.60 FL	*- FL
43	1		*SET LICENCE PLATE WITH HOLDER	Dented	60.00 FS	*45.00 FS
44	1		*SET BOOTLID INNER TRIM BOARD CLIP	Necessary	40.00 FS	*40.00 FS
45	1		*SET REAR BUMPER PARKING SENSOR	Dented	300.00 FS	*300.00 FS
46	1		*SET REAR BUMPER FASTENER CLIP	Necessary	44.00 FS	*44.00 FS
47	1		*SET REAR FENDER INNER TRIM CLIP LH	Necessary	30.00 FS	*30.00 FS
48	1		*SET REAR FENDER INNER TRIM CLIP RH	Necessary	30.00 FS	*30.00 FS
49	1		*SET REAR BUMPER END DUST COVER CLIP	Not Necessary	30.00 FS	*- FS
50	1		*REAR BOOT STICKER TRANS-CAB	Necessary	30.00 FS	*30.00 FS
51	1		*REAR BOOT STICKER 6555-3333	Necessary	30.00 FS	*30.00 FS
52	1		*REAR EXHAUST MOUNTING	Serviceable	10.00 FS	*- FS
53	2		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
54	1		*REAR WINDSCREEN INNER SPONGE SEAL	Necessary	100.00 FS	*30.00 FS
55	1		*SPARE TYRE	Serviceable	180.00 FS	*- FS
56	1		*SPARE WHEEL RIM	Serviceable	126.74 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	15,880.79	11,482.79
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,448.02	1,069.17
Total Parts (\$\$)	14,432.77	10,413.62

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	4,050.00	2,000.00
2	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	150.00
4	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	4,200.00	1,200.00
5	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	60.00
6	TO TRANSFER OF END PANEL FITTINGS AND CONDUCT WATER SEEPAGE TEST	New	170.00	100.00
7	TO TRANSFER OF LUGGAGE FLOOR PANEL FITTINGS AND CONDUCT WATER SEEPAGE TEST	New	170.00	80.00
8	TO REMOVE AND REFIT REAR W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR	New	170.00	120.00
9	TO TRANSFER OF BOOT FITTINGS AND CONDUCT WATER SEEPAGE TEST	New	170.00	60.00
10	TO TRANSFER OF FENDER FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
11	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH, FITTINGS AND OTHER,TO ENABLE REPAIR	New	380.00	0.00
12	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
Gross Labour Cost (\$\$)			10,210.00	3,790.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >