



**SINGAPORE
POLICE FORCE**



T/20161126/2108

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

2 of 3

Report No. T/20161126/2108

CONTINUATION OF REPORT

Driver			
Name	LOW SWEE KUAN	ID No.	S7221970H
Related Vehicle	SKW1466G (Car)	Contact No.	93895193
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

ON THE ABOVE DATE AND TIME, I WAS IN THE EXTREME RIGHT LANE OF TWO LANES. A RED TAXI ON MY LEFT RECKLESSLY AND AGGRESSIVELY CUT INTO MY LANE, WITHOUT SIGNAL, IN FRONT OF ME, AND HIT THE FRONT LEFT SIDE OF MY CAR WHILE DOING SO. THE TAXI THEN SPED OFF AND CHANGED LANE TO THE EXTREME LEFT AND TURNED ONTO BUKIT TIMAH AND WENT OFF, HE KEPT APPLYING HIS BRAKE WHILE DOING SO. MY CAR SUFFERED SOME SCRATCHES, DENTING AND PAINT TRANSFER ON THE FRONT LEFT SIDE. I WAS NOT INJURED. THAT'S ALL.



**SINGAPORE
POLICE FORCE**



T/20161126/2108

3 of 3

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20161126/2108

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report
TP /
SARHAN SAYED HASSAN

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / HRT /
SI ZAINI BIN MOHAMED SALLEH
Contact No.: 65476206

Authentication Stamp
NP168

Signature Of Informant:

Date/Time:
26/11/2016 15:59

Classification Of Case:

Signature

Enquire Vehicle & Owner Information (Vehicle No. SHC5608D As At 26 Nov 2016 / 00:35:00)

Law Firm Search Details

Search Reason: Insurance claim in relation to traffic accident
Law Firm Case No.: N63-102326-17

Current Owner Details

Owner ID Type: Company
Owner ID: 200303878K
Owner Name: TRANS-CAB SERVICES PTE LTD
Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes
Registered Block/House No.: 2
Registered Street Name: ANG MO KIO STREET 63
Registered Unit No.: -
Registered Building Name: -
Registered Postal Code: 569111

Current Vehicle Details

Vehicle No.: SHC5608D
Make Description/Model: RENAULT / LATITUDE 2.0L DCI AUTO D/AB 4DR
Insurance Company Name: AXA INSURANCE PTE LTD



Please read through the [Privacy Statement](#), [Terms of Use](#) and [Disclaimer](#).
Please do not use the **Back** or **Forward** buttons on your browser as this may alter the results of the transactions.
Best viewed with IE 6.0 SP3 and above, 1024 X 768 resolution
Copyright © 2017 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#)
Last updated on 28 May 2017 at 12:56 AM

ONE MOTORING
 Your Fast Track To Complete Motoring

Thank you



Ng Ching Boon Eric has successfully logged out.

Your last login date and time was 31 May 2017, 14:54:30.

To return to ONE.MOTORING, please click [here](#).

For security reasons, please **CLEAR YOUR CACHE** after each session.

Session Transaction History

<u>S/No.</u>	<u>Asset Type</u>	<u>Asset ID</u>	<u>Asset Owner ID</u>	<u>Transaction Type</u>	<u>Transaction Amount(S\$)</u>	<u>Log Date/Time</u>
1	Vehicle	SHC5608D -		18.19 Enquire Veh Owner Info (Others) by Law Firm	5.35	31 May 2017 / 14:55:05

Land Transport  Authority

Please read through the Privacy Statement, Terms of Use and Disclaimer.

Please do not use the Back or Forward buttons on your browser as this may alter the results of the transactions.

Best viewed with IE 6.0 SP3 and above, 1024 X 768 resolution

Copyright © 2017 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#)

Last updated on 28 May 2017 at 12:56 AM

Land Transport Authority

Land Transport Authority
10 Sin Ming Drive
Singapore 575701

GST Registration No. : M4-0006529-2

Print Date/Time : 29 Nov 2016 / 15:23:09

Receipt Date/Time : 29 Nov 2016 / 15:23:09

Tax Invoice/Receipt

Receipt No. : ITNET-00000-161129-001184

Previous Receipt No. :

**S/N Item Description/
Business Transaction
Reference No.**

Amount Before GST (\$\$)	GST Amount (\$\$)	Amount After GST (\$\$)
--------------------------------	-------------------------	-------------------------------

Result of Insurance Enquiry - SHC5608D

As at 26 Nov 2016/00:35:00


Insurance Co: AXA INSURANCE SINGAPORE PTE LTD

1 Insurance Enquiry - SHC5608D
Enquiry Fee
20161129152230088647

	5.00	0.35	5.35
Sub-Total	5.00	0.35	5.35
Total Before Rounding	5.00	0.35	5.35
Rounding Difference			0.00
Total Amount Payable			5.35
Paid By			
xxxxxxxxxxxx2392	Credit Card: Visa/MasterCard		5.35
Total			5.35
Cash Change			0.00
Tendered Amount			5.35
Excess Refundable Amount			0.00

THANK YOU AND HAVE A NICE DAY!


Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.



Liberty Insurance Pte Ltd
Registration no.199002791D
51 Club Street
#03-00 Liberty House
Singapore 069428
Tel: (65) 6221 8611 Fax: (65) 6225 6890
Website: <http://www.libertyinsurance.com.sg>

CERTIFICATE OF INSURANCE

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

Certificate No	SD16V13469 /VPZ /R01
Form	MZ406C
Date Of Issue	17-OCT-2016
1.Index Mark and Registration No. of Vehicle:	SKW1466G
2.Chassis number of Vehicle:	MR053REH104537680
3.Name of Policyholder:	TWINCAR LEASING PTE LTD
4.Effective date of Commencement of Insurance for the purpose of the Act:	19-OCT-2016 00:00 AM
5.Date of Expiry of Insurance:	18-OCT-2017 23:59 PM
6.Persons or Classes of Persons entitled to drive*:	
Any person who is driving on the Policyholder's order or with their permission or to whom the vehicle is hired. Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle. And provided further that the Motor Vehicle is registered under the Road Traffic Act and its registration under the Road Traffic Act has not been cancelled at the time of the accident loss or damage.	
7.Limitations as to use*:	
A) Use for carriage of passengers or goods in connection with the Policyholder's business. B) Use for social, domestic, pleasure and business purposes of any person to whom the vehicle is hired. C) Use for the carriage of passengers for hire or reward under "Uber/Grabcar" by the person to whom the vehicle is hired.	
8.Policy does not cover:	
A) Use for racing, pace-making, reliability trial or speed-testing. B) Use whilst drawing a trailer except the towing (other than for reward) of any one disabled mechanically propelled vehicle.	
*Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia) are not to be included under these headings.	
I/We hereby certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).	
For and on behalf of LIBERTY INSURANCE PTE LTD Approved Insurers  _____ Authorised Signature	
For Information only:	
COVERAGE :	Comprehensive, Unlimited Windscreen, Uber/Grabcar Extension
SUM INSURED:	MARKET VALUE AT THE TIME OF LOSS
EXCESS:	Section I - Singapore S\$2000 / Outside Singapore S\$4000, Section II - Singapore S\$1500 / Outside Singapore S\$3000, Windscreen Excess S\$100
FINANCE COMPANY:	DBS BANK LTD
PRODUCER NAME:	INSURE HOUSE

PLYW-/17-OCT-16

S1_CI_T1_T3_OE_Template2-Ver1.

17-OCT-16

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 3046C

Vehicle Details

Vehicle No.: SKW1466G

Vehicle to be Exported: No

Intended De-registration Date: 29 Nov 2016

Vehicle Make: TOYOTA

Vehicle Model: COROLLA ALTIS CLASSIC 1.6 CVT

Primary Colour: Silver

Manufacturing Year: 2015

Engine No.: 1ZRX527723

Chassis No.: MR053REH104537680

Maximum Power Output: 90.0 kW (120 bhp)

Open Market Value: \$17,804.00

Original Registration Date: 19 Oct 2015

First Registration Date: 19 Oct 2015

Transfer Count: 0

Actual ARF Paid: \$17,804.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 18 Oct 2025

PARF Rebate Amount: \$13,353.00

Intended COE Rebate Details

COE Expiry Date: 18 Oct 2025

COE Category: A - Car (up to 1600cc & 97kW (130bhp))

Period(Years): 10

QP Paid: \$56,001.00

COE Rebate Amount: \$49,754.00

Total Rebate Amount: \$63,107.00

The information contained herein is correct as at 29 Nov 2016

OK

Land Transport Authority

Please read through the Privacy Statement, Terms of Use and Disclaimer.

Please do not use the **Back** or **Forward** buttons on your browser as this may alter the results of the transactions.

Best viewed with IE 6.0 SP3 and above, 1024 X 768 resolution

Copyright © 2016 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#) | [Rate this e-Service](#)

Transaction ref 20151019164316630762

The owner and vehicle particulars for Vehicle No. SKW1466G as at 19 Oct 2015 are as follows:

1.	Name	: TWINCAR LEASING PTE LTD
2.	Identification No. Type	: Company
3.	Identification No.	: 201533046C
4.	Place Of Passport Issue	: -
5.	Registered Address	: 2 KAKI BUKIT AVENUE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921
6.	Mailing Address	: -
7.	Vehicle No.	: SKW1466G
8.	Effective Date of Ownership	: 19 Oct 2015
9.	Original Registration Date	: 19 Oct 2015
10.	First Registration Date	: 19 Oct 2015
11.	Vehicle Type	: Z10 - Private Hire (Chauffeur) Motor Car
12.	Vehicle Scheme	: Normal
13.	Attachment 1	: No Attachment
14.	Attachment 2	: -
15.	Attachment 3	: -
16.	Vehicle Make	: TOYOTA
17.	Vehicle Model	: COROLLA ALTIS CLASSIC 1.6 CVT
18.	Year of Manufacture	: 2015
19.	Primary Colour	: Silver
20.	Secondary Colour	: -
21.	Passenger Capacity	: 4
22.	Chassis/Trailer Chassis No.	: MR053REH104537680 / -
23.	Propellant/Emission Standard	: Petrol / Euro IV
24.	Engine No./Motor No.	: 1ZRX527723 / -
25.	Engine Capacity(cc)/Power Rating(kW)	: 1598 / -
26.	Maximum Power Output(kW/bhp)	: 90.0 / 120
27.	Unladen Weight(kg)	: 1205
28.	Maximum Laden Weight(kg)	: 1640
29.	Open Market Value	: \$17,804.00
30.	PARF Eligibility	: Yes
31.	PARF Eligibility Expiry Date	: 18 Oct 2025
32.	Minimum PARF Benefit	: \$8,902.00
33.	IU Label No.	: -
34.	COE No.	: 2015110101000150M
35.	COE Expiry Date	: 18 Oct 2025
36.	COE Category	: A - Car (up to 1600cc & 97kW (130bhp))
37.	Quota Premium/Prevailing Quota Premium	: \$56,001.00
38.	Actual Quota Premium/PQP Paid	: \$56,001.00
39.	Actual ARF Paid	: \$17,804.00
40.	CO2 Emission(g/km)	: 151.00
41.	Actual CEVS Rebate Utilised	: -
42.	CEVS Surcharge Paid	: -
43.	Actual Green Vehicle Rebate Utilised	: -
44.	Vehicle Lifespan Expiry Date	: -
45.	Road Tax Amount	: \$297.00
46.	Road Tax Start Date	: 19 Oct 2015
47.	Road Tax End Date	: 18 Apr 2016
48.	Remarks	: This is a public service vehicle. This vehicle is eligible for PARF. To renew the COE, the Prevailing Quota Premium payable is that of Category A.

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200616038C

GST Registration No. : 200616038C

TWINCAR LEASING PTE LTD

2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB

SINGAPORE 417921

Contact : 68420051 93895193

TAX INVOICE

Date : 06/04/2017

Date in : 26/11/2016

Vehicle Num. : SKW1466G

Make/Model : TOYOTA COROLLA ALTIS CLASSIC 1.6 CVT-2015

Chassis/Eng# : MR053REH104537680/1ZRX527723

Accident Date : 26/11/2016

Claim No : CLM13791

Reference : NOV-41/2016

Policy No. : SD16V13469/VPZ/R01 (18/10/2017)

LUMP SUM REPAIR BILL

AS PER SURVEYOR REPORT

REF : 0172-17-N51 DATED 03/04/2017

BY PAR AUTOMOTIVE CONSULTANCY

Amount S\$

9,300.00

E. & O.E. Sub S\$: 9,300.00

Add GST (7 %) S\$: 651.00

Total Amount S\$: 9,951.00



for N-51 AUTOMOTIVE PTE LTD



bizSAFE₃

PAR Automotive Consultancy

Regn. No: 52986974L

Thomson Rd Post Office PO Box 029 Singapore 915701. Tel : 645 31173. Fax : 645 36131.

Report No: 0172-17-N51

03 April 2017

Twincar Leasing Pte Ltd
2 Kaki Bukit Ave 2 #01-17
Kaki Bukit Auto Hub
Singapore 417921

INVOICE No. 0172-17-N51

Vehicle No. SKW1466G

<u>S/NO</u>	<u>SERVICES RENDERED</u>	<u>Amount due</u>
1	Being accident vehicle appraisal services, transport, photographs and re-inspection (work in progress and post repair inspection).	\$782.00
Total amount payable		<u>\$782.00</u>

Kindly cross your cheque in favour of "PAR Automotive Consultancy"

We thank you in anticipation for your prompt payment.

PAR Automotive Consultancy



Report No: 0172-17-N51

03 April 2017

ACCIDENT VEHICLE SURVEY REPORT

Twincar Leasing Pte Ltd
2 Kaki Bukit Ave 2 #01-17
Kaki Bukit Auto Hub
Singapore 417921

VEHICLE INFORMATION:

Vehicle Reg No.:	SKW1466G	Odometer:	102462km
Make & Model:	Toyota Corolla Altis 1.6	Colour:	Silver
Chassis number:	MR053REH104537680	Date of accident:	26/11/2016
Year of Regn.:	19/10/2015	Date inspected:	12/12/2016
Repairer at:	N-51 Automotive Pte Ltd 2 Kaki Bukit Ave 2 #01-18 Kaki Bukit Auto Hub Singapore 417921	Date inspected (After Repair):	15/12/2016

STATIC CHECKS, where applicable:

Steering :	serviceable
Footbrake :	serviceable
Handbrake :	serviceable
Paintwork :	Good
General condition :	Good

TIRE CONDITION:

	<u>LH / Make</u>	<u>RH / Make</u>	<u>Size</u>
Front:	5mm/Dunlop	5mm/Dunlop	205/55R16
Rear:	5mm/Dunlop	5mm/Dunlop	205/55R16

POINT OF IMPACT AND DAMAGE, where applicable:

Impact on the front LH portion.
Please see details as described in the Annex for parts and labour.

REMARKS:

We have inspected the above-mentioned vehicle on a "Without Prejudice" basis.

Parts and Labour Assessment

PARTS

Description of part	Qty	Condition	Repairer's estimate	Our adjustment
FRONT BUMPER	1	abraded/fractured	561.60	561.60 ✓
FRONT BUMPER LH FOGLAMP	1	reuse ^d	295.20	0.00 ✗
FRONT BUMPER LH FOGLAMP BRACKET	1	reuse ^d	99.00	0.00 ✗
FRONT BUMPER LH FOGLAMP GARNISH	1	reuse ^d	98.60	0.00 ✗
FRONT BUMPER SIDE RETAINER L/R <i>RH Not Rpld</i>	2	necessary	264.20	264.20 <i>132.10</i>
FRONT GRILLE	1	reuse ^d	372.80	0.00 ✗
FRONT GRILLE 'LOGO' EMBLEM	1	reuse ^d	61.10	0.00 ✗
FRONT GRILLE CLIPS	6	necessary	39.00	39.00 ✗ <i>NH</i>
FRONT GRILLE OUTER CHROME GARNISH 'TOP'	1	reuse ^d	65.00	0.00 ✗
FRONT GRILLE TOP RUBBER SEAL	1	reuse ^d	32.30	0.00 ✗
FRONT LH DOOR <i>Rpld</i>	1	buckled	1,004.95	1,004.95 ✗
FRONT LH DOOR BLACK FRAME STICKER <i>Not Rpld</i>	1	necessary	46.10	46.10 ✗
FRONT LH DOOR GLASS OUTER CHROME MOULDING <i>Rpld</i>	1	necessary	131.80	131.80 ✗
FRONT LH DOOR INNER GARNISH	1	reuse ^d	93.50	0.00 ✗
FRONT LH DOOR INNER GARNISH CLIPS <i>Not Rpld</i>	3	necessary	19.50	19.50 ✗
FRONT LH DOOR INNER LOCK HANDLE	1	reuse ^d	70.40	0.00 ✗
FRONT LH DOOR INNER TRIM BOARD	1	reuse ^d	731.80	0.00 ✗
FRONT LH DOOR OUTER LOCK HANDLE	1	reuse ^d	70.40	0.00 ✗
FRONT LH DOOR OUTER LOCK HANDLE COVER	1	reuse ^d	35.00	0.00 ✗
FRONT LH DOOR OUTER LOCK HANDLE INNER GARNISH	1	reuse ^d	192.10	0.00 ✗
FRONT LH DOOR RUBBER GUIDE STOPPER <i>Not Rpld</i>	2	deformed	44.82	44.82 ✗
FRONT LH DOOR SIDE MIRROR	1	fractured	1,202.50	1,202.50 ✓
FRONT LH DOOR SIDE MIRROR COVER <i>Rpld</i>	1	abraded	122.40	122.40 ✗
FRONT LH DOOR SIDE MIRROR SIGNAL LAMP <i>3 Not Rpld</i>	1	shorted	65.90	65.90 ✗
FRONT LH DOOR WEATHERSTRIP	1	deformed	170.70	170.70 ✗
FRONT LH FENDER	1	buckled	781.20	781.20 ✓
FRONT LH FENDER 'DUAL VVT-I' EMBLEM	1	necessary	36.70	36.70 ✓
FRONT LH FENDER BRACKET	1	repair	66.70	0.00 ✗
FRONT LH FENDER INNER SHIELD <i>Not Rpld</i>	1	fractured	215.30	215.30 ✗
FRONT LH FENDER INNER SHIELD 'VERTICAL'	1	reuse ^d	126.70	0.00 ✗
FRONT LH FENDER INNER SHIELD 'VERTICAL' CLIPS	3	necessary	19.50	19.50 ✓
FRONT LH FENDER QUARTER GARNISH	1	reuse ^d	42.90	0.00 ✗
FRONT LH FENDER QUARTER GARNISH CLIPS	2	necessary	13.00	13.00 ✓
FRONT LH FENDER TOP SPONGE	1	reuse ^d	25.00	0.00 ✗
FRONT LH HEADLAMP	1	fractured	877.30	877.30 ✓
FRONT LH HEADLAMP CHROME GARNISH <i>Not Rpld</i>	1	necessary	138.90	138.90 ✗
FRONT LH HEADLAMP CLIPS	4	necessary	26.00	26.00 ✓
FRONT LH HEADLAMP LOWER BRACKET <i>Not Rpld</i>	1	bent	182.40	182.40 ✗
FRONT SUSPENSION LH ABS SENSOR <i>Not Rpld</i>	1	shorted	466.50	466.50 ✗
FRONT SUSPENSION LH DRIVE SHAFT ASSY	1	reuse ^d	1,287.60	0.00 ✗
FRONT SUSPENSION LH KNUCKLE ARM	1	distorted	516.30	516.30 ✗
FRONT SUSPENSION LH KNUCKLE ARM BEARING <i>3 Not Rpld</i>	1	dislodged	130.90	130.90 ✗

PAR Automotive Consultancy

FRONT SUSPENSION LH LOWER ARM	1 bent	602.10	602.10 x
FRONT SUSPENSION LH LOWER BALL JOINT	1 dislodged	215.80	215.80 x
FRONT SUSPENSION LH POWER STEERING RACK END	1 dislodged	189.60	189.60 x
FRONT SUSPENSION LH POWER STEERING TIE ROD	1 reused	144.20	0.00 x
FRONT SUSPENSION LH SHOCK ABSORBER	1 bent	356.90	356.90 x
FRONT SUSPENSION LH SHOCK ABSORBER TOP MOUNTING	1 necessary	180.10	180.10 x
FRONT SUSPENSION LH STABILIZER BAR LINK	1 bent	195.70	195.70 x

Subtotal before discount S\$ 12,727.97 S\$ 8,817.67

Percentage discount 25% and 25%

S\$ 3,181.99 S\$ 2,204.42

Sub-total 1 S\$ 9,545.98 S\$ 6,613.25

FRONT BUMPER CLIPS - SET	1 necessary	30.00	30.00 ✓
FRONT LH DOOR INNER TRIM BOARD CLIPS - SET	1 necessary NH	30.00	30.00 x
FRONT LH FENDER INNER SHIELD CLIPS - SET	1 necessary NH	30.00	30.00 x
FRONT WHEEL LH 15" SPORT RIM	1 abraded	780.00	780.00 ✓
FRONT WHEEL LH 205/55R15 91V TYRE	1 abraded NH	580.00	580.00 x

Subtotal before discount S\$ 1,450.00 S\$ 1,450.00

Sub-total 2 S\$ 1,450.00 S\$ 1,450.00

Parts-total S\$ 10,995.98 S\$ 8,063.25

LABOUR

To remove, reinstall electrical wiring harness, check lighting, resetting headlamp focussing and rewire for parking sensor.

180.00 60.00 40

To remove, reinstall window glass. (to FR)

120.00 100.00 x

To remove, change front suspension parts, absorber, lower arm, knuckle arm, wheel bearing, bearing hub, drive shaft, anti-roll bar, top-arm and steering rack and pinion.

550.00 450.00 x

To road test driving, check and resetting wheel alignments system.

180.00 180.00 80

To transfer door glass, regulator gear, motor, railing, channel, trim board, mechanism lock and handle.

160.00 120.00 x

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

1,250.00 1,000.00 700

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

1,500.00 880.00 400

To apply anti-rust chemical on repaired and replaced panel.

120.00 60.00 30

Labour Total S\$ 4,060.00 S\$ 2,850.00

Parts & Labour Total S\$ 15,055.98 S\$ 10,913.25

Results of inspection of the accident vehicle are as shown above.

We have taken into consideration the age and condition of the vehicle in our recommendation.

Hence, the recommended cost of repairs based on Lump Sum repairs is : S\$ 9,300.00 and the recommended number of working days for the repairs is within 8 day(s).

B J Loi (I Eng., MIMI AIRTE)
Automotive Appraiser

total: 479742

2/3: 3.8K ✓

04 days

05073

...CLAIM SUBFOLDER...(Pending for Survey Report)

Reinspection PRI Midnight/Investigation Non-Reporting

CLAIM SUBFOLDER TRACKING						
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed
Main	29 Nov 2016		30 Nov 2016 13:02 Edit Adj Rpt	S\$3,800.00 Edit Estimates	S\$3,800.00 View Rpt	
						Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	TRANS-CAB SERVICES PTE LTD, Co. Reg. No.: -			
Main Claimant:	TWINCAR LEASING PTE LTD, Co. Reg. No.: 201533046C			
Vehicle Reg. No.:	SKW1466G	Date of Loss:	26/11/2016 00:00 - :59	
Claim Type:	TP / C0410026	Policy/Cover Note No.:	P1680520 (Third Party Only)	
Vehicle Reg. No. (Insured):	SHC5608D	Policy No. (Claimant):		
		Excess:	S\$5,000.00	
Repairer:	N-51 Automotive Pte Ltd (HQ) BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB, 417921 Kaki Bukit - Tel: 68420051			
Handling Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288 ... [Handled by Vale Oh - 6880 4897]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 09/12/2016]			

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- AXA_SG (28/09/2017): Reinspection - C0410026/P1680520
- AXA_SG (08/03/2017): Re: Direct Settlement - Accident Involving SHC5608D (OI : AXA - C0410026) and SK...
- AXA_SG (20/12/2016): Direct Settlement - Accident Involving SHC5608D (OI : AXA - C0410026) and SKW146...
- AXA_SG (30/11/2016): WP / New TP Assignment - C0410026/P1680520

☐ **ALL ASSOCIATED TASKS** [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKW1466G (C0410026)
[SHC5608D]
TP
TWINCAR LEASING PTE LTD
Nov 26 2016 12:00AM
[TRANS-CAB SERVICES PTE LTD]
N-51 Automotive Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View Use Viewer		
Photos/Images						3 per page				<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)				Thumbnail				Print	
1	15/06/17 17:10	Chassis Number						Load JPG		<input checked="" type="checkbox"/>	
2	15/06/17 17:10	General View						Load JPG		<input checked="" type="checkbox"/>	
3	15/06/17 17:10	General View						Load JPG		<input checked="" type="checkbox"/>	
4	15/06/17 17:10	General View						Load JPG		<input checked="" type="checkbox"/>	
5	15/06/17 17:10	General View						Load JPG		<input checked="" type="checkbox"/>	
6	15/06/17 17:10	General View						Load JPG		<input checked="" type="checkbox"/>	
7	15/06/17 17:10	General View						Load JPG		<input checked="" type="checkbox"/>	
8	15/06/17 17:10	General View						Load JPG		<input checked="" type="checkbox"/>	
9	15/06/17 17:10	General View						Load JPG		<input checked="" type="checkbox"/>	
10	15/06/17 17:10	General View						Load JPG		<input checked="" type="checkbox"/>	
11	15/06/17 17:10	General View						Load JPG		<input checked="" type="checkbox"/>	
12	15/06/17 17:10	General View						Load JPG		<input checked="" type="checkbox"/>	
13	15/06/17 17:10	General View						Load JPG		<input checked="" type="checkbox"/>	
14	15/06/17 17:10	General View						Load JPG		<input checked="" type="checkbox"/>	
15	15/06/17 17:10	General View						Load JPG		<input checked="" type="checkbox"/>	
16	15/06/17 17:10	General View						Load JPG		<input checked="" type="checkbox"/>	
17	15/06/17 17:10	General View						Load JPG		<input checked="" type="checkbox"/>	
18	15/06/17 17:11	Reinspection Photo						Load JPG		<input checked="" type="checkbox"/>	
19	15/06/17 17:11	Reinspection Photo						Load JPG		<input checked="" type="checkbox"/>	
20	15/06/17 17:11	Reinspection Photo						Load JPG		<input checked="" type="checkbox"/>	
21	15/06/17 17:11	Reinspection Photo						Load JPG		<input checked="" type="checkbox"/>	
22	15/06/17 17:11	Reinspection Photo						Load JPG		<input checked="" type="checkbox"/>	
23	15/06/17 17:11	Reinspection Photo						Load JPG		<input checked="" type="checkbox"/>	
24	15/06/17 17:11	Reinspection Photo						Load JPG		<input checked="" type="checkbox"/>	
25	15/06/17 17:11	Reinspection Photo						Load JPG		<input checked="" type="checkbox"/>	
26	15/06/17 17:11	Reinspection Photo						Load JPG		<input checked="" type="checkbox"/>	
27	15/06/17 17:11	Reinspection Photo						Load JPG		<input checked="" type="checkbox"/>	
28	15/06/17 17:11	Reinspection Photo						Load JPG		<input checked="" type="checkbox"/>	
29	15/06/17 17:11	Reinspection Photo						Load JPG		<input checked="" type="checkbox"/>	
30	15/06/17 17:11	Reinspection Photo						Load JPG		<input checked="" type="checkbox"/>	
31	15/06/17 17:11	Reinspection Photo						Load JPG		<input checked="" type="checkbox"/>	
32	15/06/17 17:11	Reinspection Photo						Load JPG		<input checked="" type="checkbox"/>	
33	15/06/17 17:11	Reinspection Photo						Load JPG		<input checked="" type="checkbox"/>	
34	15/06/17 17:11	Reinspection Photo						Load JPG		<input checked="" type="checkbox"/>	
35	15/06/17 17:11	Reinspection Photo						Load JPG		<input checked="" type="checkbox"/>	
36	15/06/17 17:11	Reinspection Photo						Load JPG		<input checked="" type="checkbox"/>	
37	15/06/17 17:11	Reinspection Photo						Load JPG		<input checked="" type="checkbox"/>	
38	15/06/17 17:11	Reinspection Photo						Load JPG		<input checked="" type="checkbox"/>	
39	15/06/17 17:11	Reinspection Photo						Load JPG		<input checked="" type="checkbox"/>	
40	15/06/17 17:11	Reinspection Photo						Load JPG		<input checked="" type="checkbox"/>	
41	15/06/17 17:11	Reinspection Photo						Load JPG		<input checked="" type="checkbox"/>	

42	15/06/17 17:11	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
43	15/06/17 17:11	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
44	15/06/17 17:11	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
45	15/06/17 17:11	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
46	15/06/17 17:11	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
47	15/06/17 17:11	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
48	15/06/17 17:11	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
49	15/06/17 17:11	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
50	15/06/17 17:11	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
51	15/06/17 17:11	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
Documentation					
			1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	AXA Insurance Pte Ltd (HQ)		Thumbnail	Print
1	29/11/16 16:29	CO-CLAIMANT TP_ABS	1	Load PDF	
2	29/11/16 16:29	EMAIL_ABS	1	Load PDF	
3	30/11/16 11:25	EMAIL TO TP ON SURVEYOR LIST	1	Load TIF	
4	30/11/16 11:28	EMAIL TO INSURED - NON REPORTING	1	Load TIF	
5	30/11/16 13:01	EMAIL FR TP ON SJE	1	Load TIF	
6	14/02/17 16:22	INSRD SATELLITE TRACKING RECORD - INSRD NOT INVOLVING	1	Load TIF	
7	14/02/17 16:23	EMAIL FR INSRD-NOT INVOLVING	1	Load TIF	
8	06/06/17 12:29	LOD_ABS	1	Load PDF	
9	06/06/17 12:29	CO_LEGAL ACK_ABS	1	Load PDF	
10	19/06/17 16:30	INTERNAL-BI TO INSRD ON POLICE REPORT	1	Load TIF	
11	28/09/17 11:12	EMAIL TO LKK ON REINSPN	1	Load TIF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	12/12/16 17:38	TP GIA REPORT & POLICE REPORT	1	Load PDF	
2	28/06/17 10:18	EMAIL	1	Load PDF	
3	20/11/17 11:19	RE-INSPECTION PHOTOS	1	Load PDF	
4	11/12/17 10:44	PRS INVOICE	1	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; width: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AXA16022871/AYB3S2-1
 Date: 11/12/2017

REFERENCE

Handling Insurer:	AXA Insurance Pte Ltd	Policy No:	P1680520
Claimant Vehicle No :	SKW1466G	Insured Vehicle No :	SHC5608D
Date of Loss:	26/11/2016	Nature of Claim:	TP
		Claim No:	C0410026

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKW1466G	Engine No:	1ZR527723
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 CLASSIC CVT (A)	Chassis No:	MR053REH104537680
Reg. Date:	19/10/2015 (Man. Year: 2015)	Odometer:	172133 km
Colour:	Silver		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,995.98	3,547.42	7,448.56	67.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,060.00	1,250.00	2,810.00	69.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,055.98	4,797.42	10,258.56	68.14
Approved Total (Overridden) (S\$)		3,800.00		
(S\$)	15,055.98	3,800.00	11,255.98	74.76
+ GST 7.00/7.00% (S\$)	1,053.92	266.00	787.92	74.76
Nett Amount (S\$)	16,109.90	4,066.00	12,043.90	74.76

INSPECTION

Date of Assignment:	30/11/2016	
Date Inspected:	05/10/2017 Inspected At:	N-51 Automotive Pte Ltd (HQ) BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB Singapore 417921

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING

Manager: Jasmine Khine Phoo Wai

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 11 Dec 2017)	
Parts: 143	TOYOTA COROLLA ALTIS 1.6 CLASSIC CVT (A) (Catalogue:Merimen Singapore 1.0)	
Labour: Repairer's	(Price-denominated Standard List)	
Print Code: (Unsubmitted, no print-code for SKW1466G)		
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	REPLACED	561.60 FL	*561.60 FL
2	1		*FRONT BUMPER LH FOGLAMP	REUSED	295.20 FL	*- FL
3	1		*FRONT BUMPER LH FOGLAMP BRACKET	REUSED	99.00 FL	*- FL
4	1		*FRONT BUMPER LH FOGLAMP GARNISH	REUSED	98.60 FL	*- FL
5	1		*FRONT BUMPER SIDE RETAINER L/R	O/S NOT CHANGED	264.20 FL	*132.10 FL
6	1		*FRONT GRILLE	REUSED	372.80 FL	*- FL
7	1		*FRONT GRILLE LOGO EMBLEM	REUSED	61.10 FL	*- FL
8	6		*FRONT GRILLE CLIPS	NOT CHANGED	39.00 FL	*- FL
9	1		*FRONT GRILLE OUTER CHROME GARNISH TOP	REUSED	65.00 FL	*- FL
10	1		*FRONT GRILLE TOP RUBBER SEAL	REUSED	32.30 FL	*- FL
11	1		*FRONT LH DOOR	REPAIRED	1,004.95 FL	*- FL
12	1		*FRONT LH DOOR BLACK FRAME STICKER	NOT CHANGED	46.10 FL	*- FL
13	1		*FRONT LH DOOR GLASS OUTER CHROME MOULDING	NOT CHANGED	131.80 FL	*- FL
14	1		*FRONT LH DOOR INNER GARNISH	REUSED	93.50 FL	*- FL
15	3		*FRONT LH DOOR INNER GARNISH CLIPS	NOT CHANGED	19.50 FL	*- FL
16	1		*FRONT LH DOOR INNER LOCK HANDLE	REUSED	70.40 FL	*- FL
17	1		*FRONT LH DOOR INNER TRIM BOARD	REUSED	731.80 FL	*- FL
18	1		*FRONT LH DOOR OUTER LOCK HANDLE	REUSED	70.40 FL	*- FL
19	1		*FRONT LH DOOR OUTER DOOR LOCK HANDLE COVER	REUSED	35.00 FL	*- FL
20	1		*FRONT LH DOOR LOCK HANDLE INNER GARNISH	REUSED	192.10 FL	*- FL
21	2		*FRONT LH DOOR RUBBER GUIDE STOPPER	NOT CHANGED	44.82 FL	*- FL
22	1		*FRONT LH DOOR SIDE MIRROR	REPLACED	1,202.50 FL	*1,202.50 FL
23	1		*FRONT LH DOOR SIDE MIRROR COVER	REPAIRED	122.40 FL	*- FL
24	1		*FRONT LH DOOR SIDE MIRROR SIGNAL LAMP	NOT CHANGED	65.90 FL	*- FL
25	1		*FRONT LH DOOR WEATHERSTRIP	NOT CHANGED	170.70 FL	*- FL
26	1		*FRONT LH FENDER	REPLACED	781.20 FL	*781.20 FL
27	1		*FRONT LH FENDER DUAL VVT-I EMBLEM	REPLACED	36.70 FL	*36.70 FL
28	1		*FRONT LH FENDER BRACKET	REPAIRED	66.70 FL	*- FL
29	1		*FRONT LH FENDER INNER SHIELD	NOT CHANGED	215.30 FL	*- FL
30	1		*FRONT LH FENDER INNER SHIELD VERTICAL	REUSED	126.70 FL	*- FL
31	3		*FRONT LH FENDER INNER SHIELD VERTICAL CLIPS	REPLACED	19.50 FL	*19.50 FL
32	1		*FRONT LH FENDER QUARTER GARNISH	REUSED	42.90 FL	*- FL
33	2		*FRONT LH FENDER QUARTER GRANISH CLIPS	REPLACED	13.00 FL	*13.00 FL
34	1		*FRONT LH FENDER TOP SPONGE	REUSED	25.00 FL	*- FL
35	1		*FRONT LH HEADLAMP	REPLACED	877.30 FL	*877.30 FL
36	1		*FRONT LH HEADLAMP CHROME GARNISH	NOT CHARGED	138.90 FL	*- FL
37	4		*FRONT LH HEADLAMP CLIPS	REPLACED	26.00 FL	*26.00 FL
38	1		*FRONT HEADLAMP LOWER BRACKET	NOT CHANGED	182.40 FL	*- FL
39	1		*FRONT SUSOENSION LH ABS SENSOR	NOT CHANGED	466.50 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*FRONT SUSPENSION LH DRIVE SHAFT ASSY	REUSED	1,287.60 FL	*- FL
41	1		*FRONT SUSPENSION LH KNUCKLE ARM	NOT CHANGED	516.30 FL	*- FL
42	1		*FRONT SUSPENSION LH KNUCKLE ARM BEARING	NOT CHANGED	130.90 FL	*- FL
43	1		*FRONT SUSPENSION LH LOWER ARM	NOT CHANGED	602.10 FL	*- FL
44	1		*FRONT SUSPENSION LH LOWER BALL JOINT	NOT CHANGED	215.80 FL	*- FL
45	1		*FRONT SUSPENSION LH POWER STEERING RACK END	NOT CHANGED	189.60 FL	*- FL
46	1		*FRONT SUSPENSION LH POWER STEERING TIE ROD	REUSED	144.20 FL	*- FL
47	1		*FRONT SUSPENSION LH SHOCK ABSORBER	NOT CHANGED	356.90 FL	*- FL
48	1		*FRONT SUSPENSION LH SHOCK ABSORBER TOP MOUNTING	NOT CHANGED	180.10 FL	*- FL
49	1		*FRONT SUSPENSION LH STABILIZER BAR LINK	NOT CHANGED	195.70 FL	*- FL
50	1		*SET FRONT BUMPER CLIPS	REPLACED	30.00 FS	*30.00 FS
51	1		*SET FRONT LH DOOR INNER TRIM BOARD CLIPS	NOT CHANGED	30.00 FS	*- FS
52	1		*SET FRONT LH FENDER INNER SHIELD CLIPS	NOT CHANGED	30.00 FS	*- FS
53	1		*FRONT WHEEL LH 15 SPORT RIM	REPLACED	780.00 FS	*780.00 FS
54	1		*FRONT WHEEL LH 205/55R15 91V TYRE	NOT CHANGED	580.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	14,177.97	4,459.90
- List Item Discount on L Items 25.00/25.00% (\$\$)	3,181.99	912.48
Total Parts (\$\$)	10,995.98	3,547.42

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING, RESETTNG HEADLAMP FOCUSING AND REWIRE FOR PARKING SENSOR.	New	180.00	40.00
2	TO REMOVE, REINSTALL WINDOW GLASS. (TO FR)	New	120.00	0.00
3	TO REMOVE, CHANGE FRONT SUSPENSION PARTS, ABSORBER, LOWER ARM, KNUCKLE ARM, WHEEL BEARING, BEARING HUB, DRIVE SHAFT, ANTI-ROLL BAR, TOP-ARM AND STEERING RACK AND PINION.	New	550.00	0.00
4	TO ROAD TEST DRIVING, CHECK AND RESETTNG WHEEL ALIGNMENTS SYSTEM.	New	180.00	80.00
5	TO TRANSFER DOOR GLASS, REGULATOR GEAR, MOTOR, RAILING, CHANNEL, TRIM BOARD, MECHANISM LOCK AND HANDLE.	New	160.00	0.00
6	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION AND WHERE CONSISTENT TO THE ACCIDENT.	New	1,250.00	700.00
7	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT.	New	1,500.00	400.00
8	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL.	New	120.00	30.00
Gross Labour Cost (S\$)			4,060.00	1,250.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >